

BMW 3er 320d xDrive Luxury Line


Stock number:	<i>JZ32143</i>
Build year:	2016
First registration:	11/2016
Odometer reading:	255,931 km
Fuel type:	Diesel
Horsepower:	140 kW / 190 HP
Cylinder capacity:	1,995 ccm
Gear box:	Automatic
Inspection expires:	04/2025
Body type:	Combi
Total number of owners:	3
Keys:	2
Prior damage / Accident according to previous owner	No
Country of origin:	IT
Country of last registration:	-
Environmental class:	EURO 6b
COC papers:	Yes
Seats:	5
Color:	Blue (Original)
Upholstery:	Leather (Original)
Door count:	5
CO2 Emissions:	129g/km





Car location

-



0:00 / 0:35





MAIN CAR DETAILS

CAR HIGHLIGHTS / ADDITIONAL PHOTOS



General



General



General



General



General

CAR EQUIPMENT

Some content has been automatically translated.

 Heated seats	Front seat heating
 Park Distance Control	Park-Distance-Control (PDC) front and rear Rearview camera
 Power steering	Power steering Servotronic
 Hands-free system	Bluetooth hands-free with USB audio interface
 Navigation System	Professional audio-navigation system
 Airbag	Front side airbag Side airbag rear Driver side airbag / passenger side airbag Disconnectable passenger airbag Front head airbag system Rear Cranial Airbag System
 AC System	Automatic dual-zone air conditioning with automatic air circulation control
 DPF / FAP	Particulate filter
 ESP	Dynamic Stability Control (DSC)
 Immobilizer	Immobilizer
 Cruise Control	Cruise control, Active with Stop&Go function
 All wheel drive	Drive type: xDrive (All-wheel drive)
 On-board computer	On-board computer External temperature indicator
 Entertainment system	BMW Professional audio system (Radio/CD player MP3 compatible) DAB-Tuner (Digital Radio Receiver) Instrument cluster (extended scope)



Theft alarm system / security alarm

Alarm system



ABS

Anti-lock Braking System (ABS)

CAR SERVICE DETAILS

Service book details:

Digital service book

Service appointment:

Some

Last service on:

10/14/2019

Last service Mileage:

75,208 km

Drive belt change on:

-

Drive belt change Mileage:

-

Car service images 1 image



TECHNICAL INSPECTION


Date of latest technical inspection:

04/21/2023

Mileage at latest technical inspection:

202,611 km

Technical inspection images 1 image



TEST DRIVE INFORMATION

TEST DRIVE LOCATION: ON PUBLIC STREET < 80KM/H (LOWER SPEED)

NO SPECIFIC FINDINGS

CAR DATA ACCORDING TO IDENTIFICATION NUMBER (VIN)

Some content has been automatically translated.

-  Upholstery: Dakota Leather
-  Color monitor (6.5 """)
-  AUX-IN connection (AUX-IN)
-  Model update
-  Interior: Fine wood Fineline interior trim
-  Remote unlocking tailgate
-  NOx storage catalyst (BMW Blue Performance)
-  Check Control System
-  Trunk cover / Blind
-  Dynamic stop



PAINT THICKNESS NEW

Hood	220 µm
Roof	130 µm
Front fender left	261 µm
Front fender right	123 µm
Rear fender left	311 µm
Rear fender right	166 µm
Front door left	258 µm
Front door right	120 µm
Rear door left	286 µm
Rear door right	108 µm
Tailgate (Boot lid)	90 µm

CAR DAMAGE

DAMAGE AREAS

Sub-area images are merely displayed for orientation purposes and the damage summary reports the area's condition in detail. Please note that we take photos of all significant damages. Minor damage will be displayed below in the table without a corresponding image.




1/15



2/15



3/15



4/15



5/15



6/15



Deep scratch - down to primer

7/15




Deep scratch - down to primer

8/15



Surface scratch

9/15



Surface scratch

10/15



Professional repaint

11/15

No damage specific images



Surface scratch

12/15



13/15



14/15



15/15

Damage and severity

FRONT LEFT FENDER

3 SCRATCHES

Length: ≥100mm Surface scratch

1 REPAINT

Thickness: ≥250µm & <500µm Professional repaint




DAMAGE SUMMARY

The results of this car’s evaluation are summarised in the DAMAGE SUMMARY table and visualised in the DAMAGE AREAS section below.

Damage / Part	Severity
4 REPAINT Front left fender (1) Front left door (1) Rear left door (1) Rear left fender (1)	Thickness: ≥250µm & <500µm , Professional repaint
1 REPAINT Hood (1)	Thickness: ≥125µm & <250µm , Professional repaint
11-15 Hood (2) Front left fender (3) Roof (6-10)	Length: ≥100mm , Surface scratch
2 SCRATCHES Front left door (2)	Length: ≥50mm & <100mm , Surface scratch
3 SCRATCHES Front right door (3)	Length: ≥50mm & <100mm , Deep scratch - down to primer
2 SCRATCHES Front right door handle (2)	Length: <20mm , Deep scratch - down to primer
3 STONE CHIPS Front right fender (3)	Width: >3mm , Paint damage
6-10 Windscreen (6-10)	Width: ≤3mm , In driver's eyeline
1 RECONDITIONING NECESSARY Front door interior left (1)	
2 WORN OUT Steering Wheel (1) Driver seat (1)	

MAIN WHEELS DETAILS [i](#)

This section visualises the state of the car's tires, brake pad and disc condition. In the case that any rim-related damages are found on this car they will be displayed in the car damages section.



FRONT LEFT - (1/4)

Tire type

Winter

DOT

1423

Profile depth (mm)

8

Tire condition

No issues found

Rim type

Aluminium

Brake type

Disc brake

Brake pad thickness

≥ 3mm

Brake disc condition

No issues found