

Vehicle

BMW 320D A, 140KW

WBA8H91020K748989



Development code F31
Colour alpinweiss 3
Actual integration level F020-22-11-510
Start of warranty 17 June 2016

 Valid service contracts are available.

Technical campaigns

There are no Campaigns for this vehicle.

Warranty extension/VIN-based goodwill

Status	Campaign number	Description
Open	1SACC011056	Exhaust gas recirculation cooler Bx7 Local campaign number: -

Special information

There are no Campaigns for this vehicle.

Restrictions on the warranty

There are no restrictions on the warranty.

⚠ Market-specific restrictions are not currently displayed. Please check this in WDF/WXE via S-Gate.

Live Diagnosis

 There are no service solutions for Live Diagnosis.

Service contracts

Description	Issuer	Invoice from	Duration	Vehicle mileage
UC Service Inclusive for Used Cars - 3 years / 40,000 km	AG	6 Mar 2024	up to 5 Mar 2027	up to 251761 Km

Information on faults workshop/Service Consultation

There is no information on faults.

Navigation map

Note: The installed map cannot be clearly identified. Presumably one of the following maps is present in the vehicle.

Installed map	Enabling code (subscription)	Latest navigation map included in subscription	Latest navigation map subject to charge
Road Map EUROPE EVO 2016-1 (As of: 21 Jun 2023)	-	-	-
Road Map EUROPE EVO 2016-1 (As of: 21 Jun 2023)	Enabling code valid for navigation maps with release date up to 31 Dec 2099 (SWID: 00F10FFF).	Road Map EUROPE EVO 2024-2	-

Vehicle details

Vehicle type	Passenger car
Brand	BMW
Model	320D A
Body	TOUR
Vehicle identification number (last 7 digits)	K748989
Vehicle identification number (17 digits)	WBA8H91020K748989
Development code	F31
Steering	LL
Engine	B47O
Engine number	71449652
Exhaust re-treatment	EURO6, W, PI/CI, M, N1 I
Transmission	AUT
Transmission number	0347229ZRI
Head unit serial number	HB2140G7816501
Drive	HECK
Integration level, works	F020-16-03-504
Production date	14 Jun 2016
Production plant	Muenchen
Delivery date	8 Jul 2016
Delivering retailer	Fuhrpark, München, DE
National-market version	EUR
Paint code	300
Upholstery code	HAAT
Model code	8H01
Basic type	8H91

Lead type

8H01

Optional equipment

Optional equipment ex works:

01CA Selection of COP-relevant vehicles
 01CB CO2 equipment
 0216 Hydro steering-servotronic
 0230 EU-specific additional contents
 0258 Tyres with runflat properties
 02PE BMW LA wheel, M star spoke 400
 02TB Sport automatic gearbox
 02VB Tyre pressure display
 0302 Alarm system
 0322 Comfort access
 0337 M Sports package
 03AA Roof railing black
 03AC Trailer coupling
 0402 Panorama glass roof
 0420 Sun protection glazing
 0423 Floor mats velours
 0428 Warning triangle and first aid kit
 0430 Interior/outside mirror with auto dip
 0431 Interior mirror with automatic-dip
 0481 Sports seat
 0488 Lumbar support, driver and passenger
 0493 Storage compartment package
 0494 Seat heating driver/passenger
 04AE Armrest front, retractable
 04WF Alum. Hexagon accent blue matt
 0508 Park Distance Control (PDC)
 0521 Rain sensor
 0534 Automatic air conditioning
 0548 Kilometre speedo
 0552 Adaptive LED headlight
 0563 Light package
 0575 Additional 12V sockets
 05A1 LED Fog lights
 05AC High-beam assistant
 05AL Active Protection
 05DA Passenger airbag deactivation
 05DC Rear-seat headrests, folding
 05DF Active cruise control+stop&go function
 0609 Navigation system Professional
 0676 HiFi speaker system
 0698 Area-Code 2 for DVD
 06AC Intelligent emergency call
 06AE Teleservices
 06AK Connected Drive Services
 06AM Real-Time Traffic Information
 06AN Concierge Services
 06AP Remote Services
 06NS Comfort telephony w/ enhanced Smartphone
 06WA Instrument panel with extended scope
 0704 M Sports suspension
 0710 M Leather steering wheel
 0715 M Aerodynamics package
 0760 High gloss shadow line
 0775 Headlining anthracite
 07LF Modell M Sport
 07XP Navigation package Connected Drive
 0801 National version Germany
 0851 Language version German
 0879 On-board literature, German
 08KA Oil service interval 24 mths / 30,000 km
 08TH Road sign detection
 09AA Outer skin protection
 09BD Business Package
 A090 90 Ah AGM battery
 POLS Cloth cushion

Retrofitted optional equipment:

This vehicle has no retrofits.

Vehicle histories

	Date	Type	Vehicle mileage	Retailer	Overview				
—	26/11/2024	Key	229251 Km	02832	Key 10				
	 14000 03/2026	 	 14000 03/2026	 	 80000 03/2026	 	 8000 	 14000 03/2026	
—	26/11/2024	Repair	229252 Km	00027 ,	Job Job Job				
—	Job	Description: Considered as a repeat visit No Customer's own words							
	Fahrzeugüberprüfung im Rahmen der Annahm Flat rate unit I 00 52 054		Local		0 FRU				
—	Job	Description: Considered as a repeat visit No Customer's own words Seriennummer neuer AirBag: 24B0824P0197,							
	Replace driver's airbag Flat rate unit I 00 76 283				5 FRU				
	Airbag module, driver's side Part I 32305A66F66				1				
—	Job	Description: Considered as a repeat visit No Customer's own words							
	kostenfreie Wäsche Part I 0011319		Local		1				
—	26/11/2024	Warranty	229252 Km	02832	Job: Fx Replace driver's airbag, part III (SDI)				
—	Job: Fx Replace driver's airbag, part III (SDI)								
	Description: Fx Replace driver's airbag, part III (SDI) Considered as a repeat visit No Customer's own words								
	Replace driver's airbag Flat rate unit I 00 76 283				5 FRU				
	Fx Replace driver's airbag, part III (SDI) Defect I 00 32 62 03 00								
	Airbag module, driver's side Part I 32305A66F66				1				

— 14/11/2024 Repair 228459 Km 00027 , Job
Job
Job

— Job

Description:

Considered as a repeat visit No

Customer's own words

Depotservice Rädermontage Winterräder mo Local 6 FRU
Flat rate unit | AZ36 00 2

— Job

Description:

Considered as a repeat visit No

Customer's own words

Radsatz auslagern Local 2 FRU
Flat rate unit | AZ36 00 1

— Job


Description:

Considered as a repeat visit No


Customer's own words

Fahrzeugüberprüfung im Rahmen der Annahm Local 0 FRU
Flat rate unit | 00 52 054


— 06/03/2024 Key 211762 Km 02832 Key 10



— 06/03/2024 Key 211761 Km 02832 Key 10



— 06/03/2024 Service 211761 Km 02832 Automatic
Niederlassung
Dortmund ,
Dortmund



— 06/03/2024 Repair 211761 Km 02832 Job
Niederlassung Job
Dortmund Job
BMW AG, Job
Dortmund Job
Job
Job

Job
Job
Job
Job
Job
Job
Job
Job

— Job

Description:

Considered as a repeat visit No

Customer's own words

Windshield washer antifreeze Part I 83125A85517	1
--	---

— Job

Description:

Considered as a repeat visit No

Customer's own words

Nachrüstung Service Inclusive Basis 3Jah Part I 5100102	Local	1
--	-------	---

— Job

Description:

Considered as a repeat visit No

Customer's own words

Service - standard scope Flat rate unit I 00 00 105	2 FRU
--	-------

— Job

Description:

Considered as a repeat visit No

Customer's own words

Engine oil service Flat rate unit I 00 00 610	3 FRU
--	-------

Ölzuschlag für Service Inklusive Part I 0000162	Local	1
--	-------	---

Set oil-filter element Part I 11 42 8 575 211	1
--	---

BMW Engine Oil LL04 0W30 Part I 83 21 2 405 950	5
--	---

— Job

Description:

Considered as a repeat visit No

Customer's own words

Microfilter service Flat rate unit I 00 00 616	2 FRU
---	-------

Microfilter/activated Carbon container Part I 64 11 9 237 555	1
--	---

— Job

Description:

Considered as a repeat visit No

Customer's own words

Brake fluid service Flat rate unit I 00 00 618	4 FRU
---	-------

Brake fluid DOT4 LV, low viscosity Part I 83 13 2 184 843	1
--	---

— Job

Description:

Considered as a repeat visit No

Customer's own words

Service fuel filter Flat rate unit I 00 00 604	3 FRU
---	-------

Fuel filter cartridge Part I 13 32 7 822 497	1
---	---

— Job

Description:

Considered as a repeat visit No

Customer's own words

Service - air filter element Flat rate unit I 00 00 602	2 FRU
--	-------

Air filter element Part I 13 71 8 511 668	1
--	---

— Job

Description:

Considered as a repeat visit No

Customer's own words

Depotservice Raedermontage Sommerräder m Flat rate unit I AZ36 00 2	Local	6 FRU
--	-------	-------

— Job

Description:

Considered as a repeat visit No

Customer's own words

Einlagerung Radsatz eine Saison (7 Mon.) Part I 0036007	Local	1
--	-------	---

— Job

Description:

Considered as a repeat visit No

Customer's own words

Radsatz einlagern Flat rate unit I AZ36 00 0	Local	2 FRU
---	-------	-------

— Job

Description:

Considered as a repeat visit No

Customer's own wordsServiceberatung am Fahrzeug
Part I IF52050

Local

1

— Job

Description:

Considered as a repeat visit No

Customer's own wordsFahrzeug-Außen-Wäsche (kostenlos)
Part I 0011319

Local

1

— Job

Description:

Considered as a repeat visit No

Customer's own wordsMotorölservice - zusätzliche AW
Flat rate unit I IM00 25 0

Local

2 FRU

— Job

Description:

Considered as a repeat visit No

Customer's own words Befund O-Ton Mechaniker,- Motorabdeckung HL lose => 1x Puffer der Motorabdeckung HL
Puffer,ausgeschlagen => nach Rs. Sb. ersetzt,Dokumentationsaufwand SVC
Flat rate unit I AZ00 15 2

Local

2 FRU

Bump stop
Part I 11 12 7 614 138

1

— 06/03/2024 Warranty 211761 Km 02832

Job: Engine oil service
 Job: Service - standard scope
 Job: Washer fluid service
 Job: Service - air cleaner
 Job: Service - fuel filter
 Job: Service - brake fluid
 Job: Service - micro filter/activated carbon filter

— Job: Engine oil service

Description: Engine oil service

Considered as a repeat visit No

Customer's own wordsEngine oil service
Flat rate unit I 00 00 610

3 FRU

Engine oil service
Defect I 87 00 02 00 00Set oil-filter element
Part I 11 42 8 575 211

1

— Job: Service - standard scope

Description: Service - standard scope

Considered as a repeat visit No

Customer's own words

Service - standard scope	2 FRU
Flat rate unit I 00 00 105	

Service - standard scope
Defect I 87 00 06 00 00

— Job: Washer fluid service

Description: Washer fluid service

Considered as a repeat visit No

Customer's own words

Washer fluid service
Defect I 87 00 09 00 00

— Job: Service - air cleaner

Description: Service - air cleaner

Considered as a repeat visit No

Customer's own words

Service - air filter element	2 FRU
Flat rate unit I 00 00 602	

Service - air cleaner
Defect I 87 13 01 00 00

Air filter element	1
Part I 13 71 8 511 668	

— Job: Service - fuel filter

Description: Service - fuel filter

Considered as a repeat visit No

Customer's own words

Service fuel filter	3 FRU
Flat rate unit I 00 00 604	

Service - fuel filter
Defect I 87 13 02 00 00

Fuel filter cartridge	1
Part I 13 32 7 822 497	

— Job: Service - brake fluid

Description: Service - brake fluid

Considered as a repeat visit No

Customer's own words

Brake fluid service	4 FRU
Flat rate unit I 00 00 618	

Service - brake fluid
Defect I 87 34 00 00 00

— Job: Service - micro filter/activated carbon filter

Description: Service - micro filter/activated carbon filter

Considered as a repeat visit No


Customer's own words

Microfilter service 2 FRU
Flat rate unit I 00 00 616

Service - micro filter/activated carbon filter
Defect I 87 64 01 00 00

Microfilter/activated Carbon container 1
Part I 64 11 9 237 555

— 01/03/2024 Key 210688 Km 02832 Remote KeyRead



— 15/11/2023 Repair 204439 Km 02832
Niederlassung Job
Dortmund Job
BMW AG, Job
Dortmund Job

— Job

Description:

Considered as a repeat visit No

Customer's own words

Winterräder montieren Local 6 FRU
Flat rate unit I AZ36 00 2

— Job

Description:

Considered as a repeat visit No

Customer's own words

Sommerräder einlagern Local 2 FRU
Flat rate unit I AZ36 00 0

Einlagerung Radsatz eine Saison (7 Mon.) Local 1
Part I 0036007

— Job

Description:

Considered as a repeat visit No

Customer's own words

Fahrzeugüberprüfung im Rahmen der Annahm Local 0 FRU
Flat rate unit I 00 52 054

— Job

Description:

Considered as a repeat visit No

Customer's own words

Replace left and right wiper blade 1 FRU
Flat rate unit I 61 61 541

Set of wiper blades 1
Part I 61615A43585

— Job

Description:**Considered as a repeat visit** No**Customer's own words**

Set of valve caps Part I 36 12 2 447 401	1
---	---

22/06/2023	Warranty	188528 Km	02832	Job: F1x F2x F3x G0x G1x G3x B47O B47K B47U B47T Replacing EGR cooler (high-temperature)
------------	----------	-----------	-------	--

— Job: F1x F2x F3x G0x G1x G3x B47O B47K B47U B47T Replacing EGR cooler (high-temperature)

Description: F1x F2x F3x G0x G1x G3x B47O B47K B47U B47T Replacing EGR cooler (high-temperature)**Considered as a repeat visit** No**Customer's own words**

Additional work: run function test for pressure sensor system Flat rate unit I 00 74 636	3 FRU
---	-------

Additional work: enter component identification of new exhaust gas recirculation cooler in diagnostic system Flat rate unit I 00 74 637	1 FRU
--	-------

Additional work cleaning the exhaust gas recirculation pipe Flat rate unit I 00 74 638	2 FRU
---	-------

Replace exhaust gas recirculation cooler, including exhaust gas recirculation valve Flat rate unit I 00 74 635	20 FRU
---	--------

F1x F2x F3x G0x G1x G3x B47O B47K B47U B47T Replacing EGR cooler (high-temperature) Defect I 00 11 13 07 00	
--	--

Exhaust gas radiator high temperature Part I 11 71 7 822 347	1
---	---

EGR small parts set Part I 11 71 8 490 640	1
---	---

Vacuum hose black Part I 11 65 8 595 650	1
---	---

Pipe union Part I 11 71 7 799 853	2
--------------------------------------	---

Holder Part I 61 13 1 369 832	1
----------------------------------	---

Connection piece Part I 11 65 7 803 012	1
--	---

O-ring Part I 11 61 8 512 681	1
----------------------------------	---

Acoustic cover front Part I 11 14 8 490 577	1
--	---

Hex Bolt with washer Part I 07 11 9 905 750	1
--	---

Pipe Part I 13 71 7 823 517	1
--------------------------------	---

21/06/2023	Key	188525 Km	Key 10
------------	-----	-----------	--------



23000
02/2025



23000
02/2025



23000
02/2025



23000
02/2025



380



11/2023



16000



60000
02/2027



-20
2.7 %

21/06/2023

Service

188525 Km

02832
Niederlassung
Dortmund,
Dortmund

Manual











✓













21/06/2023

Repair

188525 Km

02832
Niederlassung
Dortmund
BMW AG,
Dortmund

Job
Job
Job
Job
Job
Job

— Job

Description:

Considered as a repeat visit No

Customer's own words

Service - standard scope	2 FRU
Flat rate unit I 00 00 105	

— Job

Description:

Considered as a repeat visit No

Customer's own words O-Ton Kunde:„Bremsscheiben können bei Bedarf mit ersetzt werden,,,

Service, front brakes	6 FRU
Flat rate unit I 00 00 612	

Removing and installing or replacing both front brake discs	3 FRU
Flat rate unit I 34 11 613	

Repair kit brake pads asbestos-free	1
Part I 34 11 8 855 010	

Brake pad wear sensor, front left	1
Part I 34 35 6 792 289	

Brake disc, ventilated	2
Part I 34 11 8 848 417	

Inner hex bolt	2
Part I 34 21 1 161 806	

Torx screw with washer	4
Part I 34 10 6 864 424	

— Job

Description:

Considered as a repeat visit No

Customer's own words Arbeitsposition 0074635 wurde um einen Fahrzeugtest und Batterie,nachladen gekürzt (3AW),O-Ton Mechaniker:„AGR-Kühler neu von Borgwarner 2222-11-20 03 20541. Das kleine Rohr,von Rheinluftrohr ist porö

<https://myair-b2d.bmwgroup.com/air/faces/xhtml/fahrzeug/FahrzeugSingleView.xhtml?vin=WBA8H91020K748989>

12/59

s und bei der Demontage zerbrochen dieses,muss erneuert werden. Fotos wurden angefertigt.
Druck Sensorik Test lau,Testmodul in Ordnung,,,

Additional work: run function test for pressure sensor system Flat rate unit I 00 74 636	3 FRU
Additional work: enter component identification of new exhaust gas recirculation cooler in diagnostic system Flat rate unit I 00 74 637	1 FRU
Additional work cleaning the exhaust gas recirculation pipe Flat rate unit I 00 74 638	2 FRU
Replace exhaust gas recirculation cooler, including exhaust gas recirculation valve Flat rate unit I 00 74 635	20 FRU
Exhaust gas radiator high temperature Part I 11 71 7 822 347	1
EGR small parts set Part I 11 71 8 490 640	1
Vacuum hose Part I 11 65 8 595 650	1
Pipe union Part I 11 71 7 799 853	2
Holder Part I 61 13 1 369 832	1
Connection piece Part I 11 65 7 803 012	1
O-ring Part I 11 61 8 512 681	1
Radiator antifreeze Part I 83515A6CDD7	2
Acoustic cover front Part I 11 14 8 490 577	1
Hex Bolt with washer Part I 07 11 9 905 750	1
Pipe Part I 13 71 7 823 517	1

— Job

Description:

Considered as a repeat visit No

Customer's own words O-Ton Kunde:„Bei der HU aufgrund Abgastrelevanten Fehler duchgefallen,O-Ton Mechaniker:„Im Fehlerspeicher ist der Fehler "Lambdasonde nach Kat" abgespeichert.„Eine passende Service Lösung ist nicht vor handen. Die Leitungen und,Steckverbindungen sind unauffällig. Laut dem Testmodul ist die,Lambdasonde nach Katalysator zu erneuern. Im Anschluss ist die Kunden,Beanstandung neu zu bewerten. Nach RS SB Freigabe erhalten.„-->Funktionsprüfung durchgeführt,-->Fehlerspeicher ausegwertet,-->Testmodule abgearbeitet,

Supporting the voltage of the vehicle electrical system/recharging the vehicle electrical system battery Flat rate unit I 61 21 528	1 FRU
Troubleshooting electrical/electronic system Flat rate unit I 61 00 009	2 FRU
Performing vehicle test Flat rate unit I 00 00 556	2 FRU

Replacing the monitoring oxygen sensor
Flat rate unit | 13 62 664

4 FRU

Oxygen sensor
Part | 13 62 8 589 104

1

— Job

Description:

Considered as a repeat visit No

Customer's own words

Überprüfung nach § 29 STVZO Nachuntersuc
Part | 0012159

Local

1

— Job

Description:

Considered as a repeat visit No

Customer's own words

Fotoservice
Flat rate unit | AZ41 00 0


Local

2 FRU

— 13/06/2023 Key

187967 Km


Key 10



— 13/06/2023 Key

187961 Km

Remote KeyRead




— 13/06/2023 Service

187967 Km

02832
Niederlassung
Dortmund ,
Dortmund

Automatic



— 13/06/2023 Repair

187967 Km

02832
Niederlassung
Dortmund
BMW AG,
Dortmund

Job
Job
Job
Job

— Job

Description:

Considered as a repeat visit No

Customer's own words

Fahrzeugüberprüfung im Rahmen der Annahm
Flat rate unit | 00 52 054

Local

0 FRU

— Job

Description:

Considered as a repeat visit No

Customer's own words

Vorführung gem. Anlage VIIIb zu §29 StVZO
Part I 0012173

Local

1

Überprüfung nach § 29 STVZO
Part I 0012159

Local

1

— Job

Description:

Considered as a repeat visit No

Customer's own words O-Ton Kunde: „Es musste kein Kühlmittel nachgefüllt werden, Kunde hat keine Zeit den Wagen bis morgen bei uns zu lassen. „TA AGR wird ein neuer Termin vereinbart, Bx7 Nx7 - Kühlmittelstand bei jedem Werks tattaufenthalt prüfen, O-Ton Mechaniker: „Korens 8513691-15 verbaut, Kühlmittelstand aktuell i.O., kein Kundenhinweis dass Kühlmittel nachgefüllt wurde, CCM i.O.,

Checking exhaust gas recirculation cooler index (further repairs
subsequently required - index not OK)
Flat rate unit I 00 73 830

1 FRU

Read out coolant Check Control message (OK)
Flat rate unit I 00 73 827

4 FRU

— Job

Description:

Considered as a repeat visit No

Customer's own words

Fahrzeug-Außen-Wäsche (kostenlos)
Part I 0011319

Local

1

— Job

Description:

Considered as a repeat visit No

Customer's own words

— 13/06/2023 Warranty 187967 Km 02832 Job: Fx Gx B37 B47 B57 N47 N57
Check coolant level (EGR)

— Job: Fx Gx B37 B47 B57 N47 N57 Check coolant level (EGR)

Description: Fx Gx B37 B47 B57 N47 N57 Check coolant level (EGR)

Considered as a repeat visit No

Customer's own words

Checking exhaust gas recirculation cooler index (further repairs
subsequently required - index not OK)
Flat rate unit I 00 73 830

1 FRU

Read out coolant Check Control message (OK)
Flat rate unit I 00 73 827

4 FRU

Fx Gx B37 B47 B57 N47 N57 Check coolant level (EGR)
Defect I 11 71 90 08 00

— 14/04/2023 Warranty 183974 Km 02832 Job: Fx Gx B37 B47 B57 N47 N57
Check coolant level (EGR)

— Job: Fx Gx B37 B47 B57 N47 N57 Check coolant level (EGR)

Description: Fx Gx B37 B47 B57 N47 N57 Check coolant level (EGR)

Considered as a repeat visit No

Customer's own words

Read out coolant Check Control message (OK) 4 FRU
Flat rate unit I 00 73 827

Fx Gx B37 B47 B57 N47 N57 Check coolant level (EGR)
Defect I 11 71 90 08 00

— 11/04/2023 Repair 183974 Km 02832 Job
Niederlassung Job
Dortmund Job
BMW AG, Job
Dortmund Job
Job
Job
Job

— Job

Description:

Considered as a repeat visit No

Customer's own words Satz-Nummer: 7018174152 angefordert zum 12.04.2023, Freigabe per Email / Hr. Wack am 07.04.2023, FP: 292,00 #, Räderwechseltermin am 14.04.2023 !!, Reifen HL ersetzt (Nagel im Reifen),

Radsatz auslagern Local 2 FRU
Flat rate unit I AZ36 00 1

einen Reifen HL RFT vorab ersetzen Local 6 FRU
Flat rate unit I AZ36 30 1

Bridgestone Potenza S 001 RFT 1
Part I 85 45 2 593 885

— Job

Description:

Considered as a repeat visit No

Customer's own words

Depotservice Rädermontage Sommerräder au Local 6 FRU
Flat rate unit I AZ36 00 2

— Job

Description:

Considered as a repeat visit No

Customer's own words

Radsatz einlagern Local 2 FRU
Flat rate unit I AZ36 00 0

— Job

Description:

Considered as a repeat visit No

Customer's own words

Fahrzeugüberprüfung im Rahmen der Annahm
Flat rate unit | 00 52 054

Local

0 FRU

— Job

Description:

Considered as a repeat visit No

Customer's own words

Einlagerung Radsatz eine Saison (7 Mon.)
Part I 0036007

Local

1

— Job

Description:

Considered as a repeat visit No

Customer's own words Bx7 Nx7 - Kühlmittelstand bei jedem Werkstattaufenthalt prüfen,Musste zwischenzeitlich bereits
Kühlmittel aufgefüllt werden ?, Nein *,

Read out coolant Check Control message (OK)
Flat rate unit | 00 73 827

4 FRU

— Job

Description:

Considered as a repeat visit No

Customer's own words

Fahrzeug-Außen-Wäsche (kostenlos)
Part I 0011319

Local

1

— Job

Description:


Considered as a repeat visit No

Customer's own words

— 28/02/2023 Key

180082 Km

Key 10



— 28/02/2023 Repair

180082 Km

02832
Niederlassung
Dortmund
BMW AG,
Dortmund

Job
Job
Job

— Job

Description:

Considered as a repeat visit No

Customer's own words

Replacing radial shaft seal for input flange of rear axle differential
Flat rate unit | 33 11 502

15 FRU

Repair kit insert nut
Part I 33 12 7 607 158

1

Shaft seal

1

Part I 31 50 7 609 535

dustcover plate, small 1
Part I 33 12 1 213 903

Hypoid axle oil G1 1
Part I 83 22 2 295 532

Muffler clamp 1
Part I 18 30 8 581 218

Screw plug with O-ring 1
Part I 33 11 7 525 064

— Job

Description:

Considered as a repeat visit No

Customer's own words

Fahrzeugueberpruefung im Rahmen derAnnah Local 1 FRU
Flat rate unit I 00 52 054

— Job

Description:

Considered as a repeat visit No

Customer's own words

— 24/02/2023 Key 179751 Km Key 10



2700
02/2024



2700
02/2024



2700
02/2024



2700
02/2024



42000



11/2023



24000



2700
02/2024



06/2023

— 24/02/2023 Service 179751 Km 02832 Automatic
Niederlassung
Dortmund ,
Dortmund



2700
02/2024
✓



2700
02/2024
✓



2700
02/2024
✓



2700
02/2024
✓



42000



11/2023



24000



2700
02/2024
✓



06/2023

— 24/02/2023 Repair 179751 Km 02832 Job
Niederlassung Job
Dortmund Job
BMW AG, Job
Dortmund Job
Job
Job
Job
Job
Job
Job
Job
Job

— Job

Description:

Considered as a repeat visit No

https://myair-b2d.bmwgroup.com/air/faces/xhtml/fahrzeug/FahrzeugSingleView.xhtml?vin=WBA8H91020K748989

18/59

Customer's own words F1x F2x F3x B47O B47K B47U Steuergeräte programmieren (DDE),O-TON Mechaniker:CC-Meldungen wurden lt. TA geprüft CC-Meldung 166 war,gespeichert daraufhin sollte die Maßnahme "SELSELP020000789766777",abgearbeitet werden.,Das Fzg. wurde lt. TA auf einen aktuellen Datenstand programmiert.,

Program control units 8 FRU
Flat rate unit I 00 71 907

Additional work: check CCM Check Control message and coolant level 1 FRU
Flat rate unit I 00 73 678

— Job

Description:

Considered as a repeat visit No

Customer's own words O-TON Mechaniker:Da bei der TA die CC-Meldung 166 gespeicgert war wurde,die Maßnahme "SELSELP020000789766777" abgearbeitet lt. dieser wurde,der AGR-Kühler mittels Endoskop geprüft. Es konnte sowoh
l an,AGR-Kühlereintritt als auch Austrittseite keine Undichtigkeit,festgestellt werden. Daher wurde das Fzg. lt. TA auf einen neuen,Datenstand programmiert.,

Check exhaust gas recirculation cooler (cooler outlet and inlet side), fill 12 FRU
coolant and carry out cooling system bleeding routine
Flat rate unit I 00 68 860

Additional work for administrative effort 2 FRU
Flat rate unit I 00 68 861

Gasket Steel 1
Part I 11 71 8 579 364

— Job

Description:

Considered as a repeat visit No

Customer's own words

Service - standard scope 2 FRU
Flat rate unit I 00 00 105

— Job

Description:

Considered as a repeat visit No

Customer's own words

Engine oil service 3 FRU
Flat rate unit I 00 00 610

BMW Engine Oil LL04 0W30 5
Part I 83 21 2 405 950

Set oil-filter element 1
Part I 11 42 8 575 211

— Job

Description:

Considered as a repeat visit No

Customer's own words

Service fuel filter 3 FRU
Flat rate unit I 00 00 604

Fuel filter cartridge 1
Part I 13 32 7 822 497

— Job

Description:

Considered as a repeat visit No

Customer's own words

Service - air filter element Flat rate unit I 00 00 602	2 FRU
--	-------

Air filter element Part I 13 71 8 511 668	1
--	---

— Job

Description:

Considered as a repeat visit No

Customer's own words

Microfilter service Flat rate unit I 00 00 616	2 FRU
---	-------

Microfilter/activated Carbon container Part I 64 11 9 237 555	1
--	---

— Job

Description:

Considered as a repeat visit No

Customer's own words O-TON Mechaniker:,CC-Meldung "wenig Waschwasser" wird angezeigt,Blinker VR ist schwächer als VL,Licht war verstellt kor.,leichte oberflächliche Steinschläge Frontscheibe,Türkantenschutz VL ist leicht spröde,HA-Getriebeeingang ist undicht lt. SB wird ein neuer Termin dafür,gemacht,Luftdruck rundum gleichmäßig zu gering kor.,Warn-Weste ist vorhanden,Warndreieck ist vorhanden,Erste-Hilfe-Tasche nicht mehr verwendbar (30/11/21),kein Reifenpannen-Set im Fzg. aktuell RFT-Reifen montiert,

Service, vehicle check Flat rate unit I 00 00 624	6 FRU
--	-------

— Job

Description:

Considered as a repeat visit No

Customer's own words

Zusatz zum Fahrzeugcheck / Inspektion Flat rate unit I AZ10 00 1	Local	2 FRU
---	-------	-------

— Job

Description:

Considered as a repeat visit No

Customer's own words

Motoroelservice - zusaetzliche AW Flat rate unit I IM00 25 0	Local	2 FRU
---	-------	-------

— Job

Description:

Considered as a repeat visit No

Customer's own words

Fahrzeugueberpruefung im Rahmen derAnnah	Local	1 FRU
--	-------	-------

Flat rate unit | 00 52 054

— Job

Description:

Considered as a repeat visit No

Customer's own words

Fahrzeug-Außen-Wäsche (kostenlos)
Part | 0011319

Local

1

— Job

Description:

Considered as a repeat visit No

Customer's own words

Fotoservice
Flat rate unit | AZ41 00 0

Local

2 FRU

- 24/02/2023 Warranty 179759 Km 02832 Job: F1x F2x F3x B47O B47K B47U Programming control units (DDE)
Job: G0x G1x G2x G3x B57 Check and if necessary replace exhaust-gas recirculation cooler

— Job: F1x F2x F3x B47O B47K B47U Programming control units (DDE)

Description: F1x F2x F3x B47O B47K B47U Programming control units (DDE)

Considered as a repeat visit No

Customer's own words

Program control units
Flat rate unit | 00 71 907

8 FRU

Additional work: check CCM Check Control message and coolant level
Flat rate unit | 00 73 678

1 FRU

F1x F2x F3x B47O B47K B47U Programming control units (DDE)
Defect | 00 13 50 03 00

— Job: G0x G1x G2x G3x B57 Check and if necessary replace exhaust-gas recirculation cooler

Description: G0x G1x G2x G3x B57 Check and if necessary replace exhaust-gas recirculation cooler

Considered as a repeat visit No

Customer's own words

Check exhaust gas recirculation cooler (cooler outlet and inlet side), fill coolant and carry out cooling system bleeding routine
Flat rate unit | 00 68 860

12 FRU

Additional work for administrative effort
Flat rate unit | 00 68 861

2 FRU

G0x G1x G2x G3x B57 Check and if necessary replace exhaust-gas recirculation cooler
Defect | 11 71 90 05 00

Gasket Steel
Part | 11 71 8 579 364

1

- 11/11/2022 Key 173398 Km 02832 Key 10

 10000 02/2024	 10000 02/2024	 10000 02/2024	 10000 02/2024	 49000 02/2024	 11/2023	 31000 02/2024	 10000 02/2024	 06/2023
--	--	--	--	--	---	--	---	---

—	11/11/2022	Repair	173398 Km	02832	Job
				Niederlassung	Job
				Dortmund	Job
				BMW AG,	Job
				Dortmund	Job
					Job
					Job

— Job

Description:

Considered as a repeat visit No

Customer's own words

— Job

Description:

Considered as a repeat visit No

Customer's own words

Fahrzeugüberprüfung im Rahmen der Annahm	Local	0 FRU
Flat rate unit I 00 52 054		

— Job

Description:

Considered as a repeat visit No

Customer's own words

Radsatz einlagern	Local	2 FRU
Flat rate unit I AZ36 00 0		

— Job

Description:

Considered as a repeat visit No

Customer's own words

— Job

Description:

Considered as a repeat visit No

Customer's own words

Depotservice Rädermontage Winterräder mo	Local	6 FRU
Flat rate unit I AZ36 00 2		

— Job

Description:

Considered as a repeat visit No

Customer's own words

Einlagerung Radsatz eine Saison (7 Mon.)	Local	1
Part I 0036007		

— Job

Description:

Considered as a repeat visit No

Customer's own words

Fahrzeug-Außen-Wäsche (kostenlos)
Part I 0011319

Local

1

— 26/10/2022 Repair 154248 Km 02832 Job
Niederlassung Job
Dortmund Job
BMW AG,
Dortmund

— Job

Description:

Considered as a repeat visit No

Customer's own words einen Reifen H.L mit Notlaufeigenschaften vor Saisonwechsel ersetzen,

einen Reifen H.L mit Notlaufeigenschaften
Flat rate unit I AZ36 30 1

Local

6 FRU

Radsatz auslagern
Flat rate unit I AZ36 00 1

Local

2 FRU

— Job

Description:

Considered as a repeat visit No

Customer's own words

Pirelli W 240 Sottozero II r-f
Part I 85 45 2 593 804

1

— Job

Description:

Considered as a repeat visit No

Customer's own words

— 05/04/2022 Repair 154248 Km 02832 Job
Niederlassung Job
Dortmund Job
BMW AG, Job
Dortmund

— Job

Description:

Considered as a repeat visit No

Customer's own words

Depotservice Rädermontage Sommerräder mo
Flat rate unit I AZ36 00 2

Local

6 FRU

— Job

Description:

Considered as a repeat visit No

Customer's own words

Radsatz einlagern
Flat rate unit | AZ36 00 0

Local

2 FRU

— Job

Description:

Considered as a repeat visit No

Customer's own words

Fahrzeugüberprüfung im Rahmen der Annahm
Flat rate unit | 00 52 054

Local

0 FRU

— Job

Description:

Considered as a repeat visit No

Customer's own words

Einlagerungskosten
Part I 0036007

Local

1

— 15/03/2022 Key 153569 Km 02832 Key 10

29000
02/2024

29000
676

29000
676

29000
676

70000

11/2023

49000

29000
02/2024

06/2023

— 15/03/2022 Repair 151472 Km 02832 Job

Niederlassung
Dortmund
BMW AG,
Dortmund

Job
Job
Job
Job
Job
Job
Job

— Job

Description:

Considered as a repeat visit No

Customer's own words

— Job

Description:

Considered as a repeat visit No

Customer's own words Auftragserweiterung/sonstige Hinweise:>>Streuscheibe Scheinwerfer VL ist im nicht sichtbaren Bereich unterhalb,unfallbedingt gerissen Gefahr von freutigkeits Eintritt Scheinwerfer,muss ersetzt werden
(Fotos erstellt),>>Träger Stoßfänger vorne oben und unten ohne erkennbare Beschädigung,Schadensbereich liegt links ACC Einstellung ist nicht notwendig,LED-Scheinwerfer links ersetzt,

Zeitzuschlag für eine Hauptarbeit
Flat rate unit | AZ41 12 8

Local

2 FRU

Replacing front bumper panel
Flat rate unit | 51 11 592

11 FRU

Additional work with Park Distance Control
Flat rate unit | 66 20 615

2 FRU

Performing vehicle test	2 FRU
Flat rate unit I 00 00 556	

Supporting the voltage of the vehicle electrical system/recharging the vehicle electrical system battery	1 FRU
Flat rate unit I 61 21 528	

Replacing left LED headlight	18 FRU
Flat rate unit I 63 12 641	

— Job

Description:

Considered as a repeat visit No

Customer's own words

Zeitzuschlag für eine Hauptarbeit	Local	16 FRU
Flat rate unit I AZ99 00 0		

Painting front bumper panel	11 FRU
Flat rate unit I 99 68 535	

— Job

Description:

Considered as a repeat visit No

Customer's own words

Fahrzeugüberprüfung im Rahmen der Annahm	Local	0 FRU
Flat rate unit I 00 52 054		

— Job

Description:

Considered as a repeat visit No

Customer's own words

kostenlose Fahrzeugoberwäsche	Local	1
Part I 0011319		

— Job

Description:

Considered as a repeat visit No

Customer's own words

Ultrasonic sensor Alpine White	1
Part I 66 20 9 261 587	

Panel, bumper, primed, front	1
Part I 51 11 8 067 941	

Headlight LED, AHL, left	1
Part I 63 11 7 419 627	

Countersunk screw	3
Part I 07 11 9 908 008	


Plaque	1
Part I 51 76 7 288 752	

— Job

Description:

Considered as a repeat visit No

Customer's own words



— 22/02/2022 Repair 151472 Km 02832
 Niederlassung
 Dortmund
 BMW AG,
 Dortmund
 Job
 Job
 Job
 Job
 Job
 Job
 Job
 Job
 Job

— Job

Description:

Considered as a repeat visit No

Customer's own words Serviceinclusive,

Service - standard scope 2 FRU
 Flat rate unit I 00 00 105

— Job

Description:

Considered as a repeat visit No

Customer's own words

Replace left and right wiper blade 1 FRU
 Flat rate unit I 61 61 541

Set of wiper blades 1
 Part I 61615A43585

— Job

Description:

Considered as a repeat visit No

Customer's own words

Engine oil service 3 FRU
 Flat rate unit I 00 00 610

Ölzuschlag für Service Inklusive Local 1
 Part I 0000162

BMW Engine Oil LL04 0W30 5
 Part I 83 21 2 405 950

Set oil-filter element 1
 Part I 11 42 8 575 211

— Job

Description:

Considered as a repeat visit No

Customer's own words

Microfilter service 2 FRU
 Flat rate unit I 00 00 616

Microfilter/activated Carbon container 1

Part I 64 11 9 237 555

— Job

Description:

Considered as a repeat visit No

Customer's own words

Motorölservice - zusätzliche AW
Flat rate unit I IM00 25 0

Local

2 FRU

— Job

Description:

Considered as a repeat visit No

Customer's own words

kostenlose Fahrzeugoberwäsche
Part I 0011319

Local

1

— Job

Description:

Considered as a repeat visit No

Customer's own words

Fahrzeugüberprüfung im Rahmen der Annahme
Flat rate unit I 00 52 054

Local

1 FRU

— Job

Description:

Considered as a repeat visit No

Customer's own words

— Job

Description:

Considered as a repeat visit No

Customer's own words

battery
Part I 61 31 9 217 643

1

— Job

Description:

Considered as a repeat visit No

Customer's own words

—	22/02/2022	Warranty	151475 Km	02832	Job: Engine oil service Job: Service - standard scope Job: Service - micro filter/activated carbon filter
---	------------	----------	-----------	-------	---

— Job: Engine oil service

Description: Engine oil service

Considered as a repeat visit No

Customer's own words

Engine oil service

3 FRU

Flat rate unit I 00 00 610

Engine oil service

Defect I 87 00 02 00 00

Set oil-filter element

Part I 11 42 8 575 211

1

— Job: Service - standard scope

Description: Service - standard scope**Considered as a repeat visit** No**Customer's own words**

Service - standard scope

2 FRU

Flat rate unit I 00 00 105

Service - standard scope

Defect I 87 00 06 00 00

— Job: Service - micro filter/activated carbon filter

Description: Service - micro filter/activated carbon filter**Considered as a repeat visit** No**Customer's own words**

Microfilter service

2 FRU

Flat rate unit I 00 00 616

Service - micro filter/activated carbon filter

Defect I 87 64 01 00 00

Microfilter/activated Carbon container






1

Part I 64 11 9 237 555

— 26/11/2021 Key

145525 Km

Key 10








— 26/11/2021 Service

145525 Km

02832
Niederlassung
Dortmund ,
Dortmund

Automatic



— 26/11/2021 Repair

145530 Km

02832
Niederlassung
Dortmund
BMW AG,
DortmundJob
Job
Job
Job
Job
Job
Job

— Job

Description:**Considered as a repeat visit** No

Customer's own words			
Service - standard scope			2 FRU
Flat rate unit I 00 00 105			
— Job			
Description:			
Considered as a repeat visit No			
Customer's own words			
Brake fluid service			4 FRU
Flat rate unit I 00 00 618			
Brake fluid DOT4 LV, low viscosity			1
Part I 83 13 2 184 843			
— Job			
Description:			
Considered as a repeat visit No			
Customer's own words			
Winterräder montieren	Local		6 FRU
Flat rate unit I AZ36 00 2			
— Job			
Description:			
Considered as a repeat visit No			
Customer's own words			
Radsatz einlagern	Local		2 FRU
Flat rate unit I AZ36 00 0			
Sommerräder einlagern	Local		1
Part I 0036007			
— Job			
Description:			
Considered as a repeat visit No			
Customer's own words			
Fahrzeugüberprüfung im Rahmen der Annahm	Local		0 FRU
Flat rate unit I 00 52 054			
— Job			
Description:			
Considered as a repeat visit No			
Customer's own words			
— Job			
Description:			
Considered as a repeat visit No			
Customer's own words			
— Job			
Description:			
Considered as a repeat visit No			

Customer's own words

— 26/11/2021 Warranty 145530 Km 02832 Job: Service - standard scope
Job: Service - brake fluid

— Job: Service - standard scope

Description: Service - standard scope

Considered as a repeat visit No

Customer's own words

Service - standard scope	2 FRU
Flat rate unit I 00 00 105	

Service - standard scope
Defect I 87 00 06 00 00

— Job: Service - brake fluid

Description: Service - brake fluid

Considered as a repeat visit No

Customer's own words

Brake fluid service	4 FRU
Flat rate unit I 00 00 618	

Service - brake fluid
Defect I 87 34 00 00 00

— 21/10/2021 Repair 127422 Km 02832 Job
Niederlassung Job
Dortmund Job
BMW AG,
Dortmund

— Job

Description:

Considered as a repeat visit No

Customer's own words vier Reifen mit Notlaufeigenschaften vor Saisonwechsel ersetzen,

vier Reifen mit Notlaufeigenschaften vor	Local	23 FRU
Flat rate unit I AZ36 30 4		

— Job

Description:

Considered as a repeat visit No

Customer's own words

Pirelli W 240 Sottozero II r-f	1
Part I 85 45 2 593 804	

Pirelli W 240 Sottozero II r-f	1
Part I 85 45 2 593 804	

Pirelli W 240 Sottozero II r-f	1
Part I 85 45 2 593 804	

Pirelli W 240 Sottozero II r-f	1
Part I 85 45 2 593 804	

— Job

Description:

Considered as a repeat visit No

Customer's own words

— 15/03/2021 Repair 127422 Km 02832 Job
Niederlassung Job
Dortmund Job
BMW AG, Job
Dortmund Job

— Job

Description:

Considered as a repeat visit No

Customer's own words

Sommerräder montieren	Local	6 FRU
Flat rate unit I AZ36 00 2		

— Job

Description:

Considered as a repeat visit No

Customer's own words

Winterräder einlagern	Local	2 FRU
Flat rate unit I AZ36 00 0		

— Job

Description:

Considered as a repeat visit No

Customer's own words

Einlagerungskosten	Local	1
Part I 0036007		

— Job

Description:

Considered as a repeat visit No

Customer's own words

Bridgestone Potenza S 001 RFT	1
Part I 85 45 2 593 885	

Bridgestone Potenza S 001 RFT	1
Part I 85 45 2 593 885	

— Job

Description:

Considered as a repeat visit No

Customer's own words

zwei Reifen ersetzen Sommer Hinterachse	Local	12 FRU
Flat rate unit I AZ36 30 2		

— 27/11/2020 Key 121482 Km 02832 Key 10

 -10 08/2021	 -10 277	 -10 277	 -10 277	 110000	 0 08/2021	 90000	 -10 08/2021	 0 06/2021
--	--	--	--	--	--	---	---	--

— 27/11/2020 Service

121482 Km

02832
Niederlassung
Dortmund ,
Dortmund

Automatic

 -10 08/2021 ✓	 -10 08/2021 ✓	 -10 08/2021 ✓	 -10 08/2021 ✓	 110000	 0 08/2021	 90000	 -10 08/2021 ✓	 0 06/2021
--	--	--	--	---	---	--	---	---

— 27/11/2020 Repair

121486 Km

02832
Niederlassung
Dortmund
BMW AG,
DortmundJob
Job
Job
Job
Job
Job
Job
Job
Job
Job
Job
Job

— Job

Description:

Considered as a repeat visit No

Customer's own words Kosten für Zusatzdämpfer hinten ersetzen ca. 250 Euro <(>&<)>,Räderwechsel mit Einlagerung 139 Euro,Service Inclusive,

Service consultation at vehicle with Service Ticket
Flat rate unit I 00 52 052

0 FRU

— Job

Description:

Considered as a repeat visit No

Customer's own words

Service - standard scope
Flat rate unit I 00 00 105

2 FRU

— Job

Description:

Considered as a repeat visit No

Customer's own words Scheinwerfer können eingestellt werden wenn nötig,

Service, vehicle check
Flat rate unit I 00 00 624

6 FRU

— Job

Description:

Considered as a repeat visit No

Customer's own words

Engine oil service Flat rate unit I 00 00 610		3 FRU
--	--	-------

Ölzuschlag für Service inklusive Part I 0000162	Local	1
--	-------	---

Set oil-filter element Part I 11 42 8 575 211		1
--	--	---

BMW Engine Oil LL04 0W30 Part I 83 21 2 405 950		5
--	--	---

— Job

Description:**Considered as a repeat visit** No**Customer's own words**

Microfilter service Flat rate unit I 00 00 616		2 FRU
---	--	-------

Microfilter/activated Carbon container Part I 64 11 9 237 555		1
--	--	---

— Job

Description:**Considered as a repeat visit** No**Customer's own words**

Service - air filter element Flat rate unit I 00 00 602		2 FRU
--	--	-------

Air filter element Part I 13 71 8 511 668		1
--	--	---

— Job

Description:**Considered as a repeat visit** No**Customer's own words**

Service fuel filter Flat rate unit I 00 00 604		3 FRU
---	--	-------

Fuel filter cartridge Part I 13 32 8 572 522		1
---	--	---

— Job

Description:**Considered as a repeat visit** No**Customer's own words**

Depotservice Rädermontage Flat rate unit I AZ36 00 2	Local	6 FRU
---	-------	-------

— Job

Description:**Considered as a repeat visit** No**Customer's own words**

Radsatz einlagern Flat rate unit I AZ36 00 0	Local	2 FRU
---	-------	-------

— Job

Description:

Considered as a repeat visit No

Customer's own words

— Job

Description:

Considered as a repeat visit No

Customer's own words

Removing and installing both rear shock absorbers Flat rate unit I 33 52 525	9 FRU
---	-------

Auxiliary damper, rear Part I 33 53 6 857 730	2
--	---

Hexalobular socket screw Part I 07 11 9 907 137	6
--	---

Gasket Part I 33 50 6 866 038	2
----------------------------------	---

Hex nut with flange Part I 07 11 9 907 135	2
---	---

Torx screw with collar Part I 07 11 9 907 372	2
--	---

Self-locking collar nut Part I 33 32 6 760 668	2
---	---

— Job

Description:

Considered as a repeat visit No

Customer's own words

!!! unknown BMW-Id A1A166 null !!! Part I A1A166	Local	1
---	-------	---

— Job

Description:

Considered as a repeat visit No

Customer's own words

Motorölservice - zusätzliche AW Flat rate unit I IM00 25 0	Local	2 FRU
---	-------	-------

— Job

Description:

Considered as a repeat visit No

Customer's own words

Zusatz zum Fahrzeugcheck / Inspektion Flat rate unit I AZ10 00 1	Local	2 FRU
---	-------	-------

—	27/11/2020	Warranty	121486 Km	02832	Job: Engine oil service Job: Service - vehicle check Job: Service - standard scope Job: Washer fluid service Job: Service - air cleaner
---	------------	----------	-----------	-------	---

Job: Service - fuel filter
Job: Service - micro filter/activated
carbon filter

— Job: Engine oil service

Description: Engine oil service

Considered as a repeat visit No

Customer's own words

Engine oil service Flat rate unit I 00 00 610	3 FRU
--	-------

Engine oil service Defect I 87 00 02 00 00

Set oil-filter element Part I 11 42 8 575 211	1
--	---

— Job: Service - vehicle check

Description: Service - vehicle check

Considered as a repeat visit No

Customer's own words

Service, vehicle check Flat rate unit I 00 00 624	6 FRU
--	-------

Service - vehicle check Defect I 87 00 05 00 00
--

— Job: Service - standard scope

Description: Service - standard scope

Considered as a repeat visit No

Customer's own words

Service - standard scope Flat rate unit I 00 00 105	2 FRU
--	-------

Service - standard scope Defect I 87 00 06 00 00

— Job: Washer fluid service

Description: Washer fluid service

Considered as a repeat visit No

Customer's own words

Washer fluid service Defect I 87 00 09 00 00

— Job: Service - air cleaner

Description: Service - air cleaner

Considered as a repeat visit No

Customer's own words

Service - air filter element	2 FRU
Flat rate unit 00 00 602	

Service - air cleaner
Defect 87 13 01 00 00

Air filter element	1
Part 13 71 8 511 668	

— Job: Service - fuel filter

Description: Service - fuel filter

Considered as a repeat visit No

Customer's own words

Service fuel filter	3 FRU
Flat rate unit 00 00 604	

Service - fuel filter
Defect 87 13 02 00 00

Fuel filter cartridge	1
Part 13 32 8 572 522	

— Job: Service - micro filter/activated carbon filter

Description: Service - micro filter/activated carbon filter

Considered as a repeat visit No

Customer's own words

Microfilter service	2 FRU
Flat rate unit 00 00 616	

Service - micro filter/activated carbon filter
Defect 87 64 01 00 00

Microfilter/activated Carbon container	1
Part 64 11 9 237 555	

—	08/04/2020	Repair	106041 Km	02832	Job
				Niederlassung	Job
				Dortmund	Job
				BMW AG,	Job
				Dortmund	

— Job

Description:

Considered as a repeat visit No

Customer's own words

Depotservice Rädermontage Sommerräder mo	Local	6 FRU
Flat rate unit AZ36 00 2		

— Job

Description:

Considered as a repeat visit No

Customer's own words

Radsatz einlagern	Local	2 FRU
Flat rate unit AZ36 00 0		

— Job

Description:

Considered as a repeat visit No

Customer's own words

Fahrzeugüberprüfung im Rahmen der Annahm
Flat rate unit I 00 52 054

Local

0 FRU

— Job

Description:

Considered as a repeat visit No

Customer's own words

Einlagerungskosten
Part I 0036007

Local

1

— 19/02/2020 Key

102314 Km

02832

Key 10

									
20000	20000	20000	20000	1500	8000	20000			
08/2021	522	522	522	08/2021		08/2021			06/2021

— 19/02/2020 Service

102314 Km

02832

Automatic

Niederlassung
Dortmund ,
Dortmund

									
20000	20000	20000	20000	1500	0	8000	20000		0
08/2021	08/2021	08/2021	08/2021	08/2021	08/2021	08/2021	08/2021		06/2021
				✓		✓			

— 19/02/2020 Repair

102318 Km

02832

Niederlassung
Dortmund
BMW AG,
Dortmund

Job
Job
Job
Job
Job
Job
Job

— Job

Description:

Considered as a repeat visit No

Customer's own words

Removing and installing or replacing both front brake discs
Flat rate unit I 34 11 613

3 FRU

Brake disc, ventilated
Part I 34 11 6 792 219

2

Inner hex bolt
Part I 34 21 1 161 806

2

Torx screw with washer
Part I 34 10 6 864 424

4

— Job

Description:

Considered as a repeat visit No

Customer's own words

— Job

Description:

Considered as a repeat visit No

Customer's own words

Service - standard scope	2 FRU
Flat rate unit I 00 00 105	

— Job

Description:

Considered as a repeat visit No

Customer's own words

Service, rear brakes	7 FRU
Flat rate unit I 00 00 614	

Repair kit, brake pads asbestos-free	1
Part I 34 21 6 873 093	

Brake-pad sensor, rear	1
Part I 34 35 6 792 292	

Brake-pad paste	2
Part I 83 19 2 158 851	

— Job

Description:

Considered as a repeat visit No

Customer's own words

Service, front brakes	6 FRU
Flat rate unit I 00 00 612	

Repair kit, brake pads asbestos-free	1
Part I 34 10 6 859 181	

Brake pad wear sensor, front left	1
Part I 34 35 6 792 289	

Brake-pad paste	2
Part I 83 19 2 158 851	

— Job

Description:

Considered as a repeat visit No

Customer's own words Abgabe SA, keine SB am Fzg. gewünscht,

Fahrzeugüberprüfung im Rahmen der	Local	1 FRU
Flat rate unit I 00 52 054		

— Job

Description:

Considered as a repeat visit No

Customer's own words

kostenlose Fahrzeugoberwäsche	Local	1
Part I 0011319		

— Job

Description:

Considered as a repeat visit No

Customer's own words

—	20/11/2019	Key		98912 Km	02832		Key 10	
								
23000	23000	23000	23000	4700	0	8000	23000	0
08/2021	650	650	650		08/2021		08/2021	06/2021

20/11/2019			98912 Km			02832			Key 10		
											
23000	23000		23000	23000	4700	0	8000	23000		0	
08/2021	650		650	650		08/2021		08/2021		06/2021	

—	20/11/2019	Repair	98913 Km	02832	Job
				Niederlassung	Job
				Dortmund	Job
				BMW AG,	Job
				Dortmund	Job
					Job
					Job
					Job

— Job

Description:

Considered as a repeat visit No

Customer's own words Befund:,- Datum: 24.10.2018,--> lt. TA ist der AGR Kühler i.O.!!,

Check exhaust-gas recirculation cooler production date (then no further repairs necessary) 3 FRU

Flat rate unit I 00 68 736

— Job

Description:

Considered as a repeat visit No

Customer's own words

Depotservice Rädermontage Local 6 FRU

Flat rate unit I AZ36 00 2

— Job

Description:

Considered as a repeat visit No

Customer's own words

Radsatz einlagern Local 2 FRU

Flat rate unit I AZ36 00 0

— Job

Description:

Considered as a repeat visit No

Customer's own words

Einlagerungskosten Local 1

Part I 0036007

— Job

Description:

Considered as a repeat visit No

Customer's own words

Fahrzeugüberprüfung im Rahmen der
Flat rate unit I 00 52 054

Local

1 FRU

— Job

Description:

Considered as a repeat visit No

Customer's own words

kostenlose Fahrzeugoberwäsche
Part I 0011319

Local

1

— Job

Description:

Considered as a repeat visit No

Customer's own words

— Job

Description:

Considered as a repeat visit No

Customer's own words

— 20/11/2019 Warranty 98913 Km 02832 Job: F1x F2x F3x F4x G0x G1x G3x B47 Check and if required replace exhaust-gas recirculation cooler

— Job: F1x F2x F3x F4x G0x G1x G3x B47 Check and if required replace exhaust-gas recirculation cooler

Description: F1x F2x F3x F4x G0x G1x G3x B47 Check and if required replace exhaust-gas recirculation cooler

Considered as a repeat visit No








Customer's own words

Check exhaust-gas recirculation cooler production date (then no further
repairs necessary)
Flat rate unit I 00 68 736

3 FRU

F1x F2x F3x F4x G0x G1x G3x B47 Check and if required replace
exhaust-gas recirculation cooler
Defect I 00 11 40 05 00

— 21/08/2019 Key 90518 Km 02832 Key 10



— 21/08/2019 Service 90518 Km 02832 Automatic
Niederlassung
Dortmund ,
Dortmund

								
2100	0	2100	0	13000	0	8000	34000	0
09/2020		09/2020			06/2019		09/2022	06/2021
✓		✓			✓			

— 21/08/2019 Repair 90518 Km 02832
 Niederlassung Job
 Dortmund Job
 BMW AG, Job
 Dortmund Job
 Job
 Job
 Job
 Job
 Job

— Job

Description:

Considered as a repeat visit No

Customer's own words Kulanz Hinterachse prüfen Eingang undkicht,Befund:„Der Simmering am Eingang des HAG ist undicht und muss ersetzt werden.,

Fotoservice	Local	2 FRU
Flat rate unit I AZ41 00 0		

— Job

Description:

Considered as a repeat visit No

Customer's own words

Motorölservice - zusätzliche AW	Local	2 FRU
Flat rate unit I IM00 25 0		

— Job

Description:

Considered as a repeat visit No

Customer's own words

Service - standard scope	2 FRU
Flat rate unit I 00 00 105	

— Job

Description:

Considered as a repeat visit No

Customer's own words

Microfilter service	2 FRU
Flat rate unit I 00 00 616	

Microfilter/activated Carbon container	1
Part I 64 11 9 237 555	

— Job

Description:

Considered as a repeat visit No

Customer's own words

Brake fluid service	4 FRU
---------------------	-------

Flat rate unit I 00 00 618

Brake fluid DOT4 LV, low viscosity
Part I 83 13 2 184 843

1

— Job

Description:

Considered as a repeat visit No

Customer's own words

Engine oil service
Flat rate unit I 00 00 610

3 FRU

Set oil-filter element
Part I 11 42 8 575 211

1

BMW Engine Oil LL04 0W30
Part I 83 21 2 405 950

5

— Job

Description:

Considered as a repeat visit No

Customer's own words

Replace left and right wiper blade
Flat rate unit I 61 61 541

1 FRU

Set of wiper blades
Part I 61 61 2 241 375

1

— Job

Description:

Considered as a repeat visit No

Customer's own words

Service consultation at vehicle with Service Ticket
Flat rate unit I 00 52 052

1 FRU

— Job

Description:

Considered as a repeat visit No

Customer's own words

kostenlose Fahrzeugüberwäsche
Part I 0011319

Local

1

— Job

Description:

Considered as a repeat visit No









Customer's own words

— 01/04/2019 Key

75059 Km

02832

Key 10



— 29/03/2019 Repair 1 Km 02832 Job
Niederlassung Job
Dortmund Job
BMW AG, Job
Dortmund

— Job

Description:

Considered as a repeat visit No

Customer's own words

Depotservice Rädermontage SR montieren,W Flat rate unit I AZ36 00 2	Local	6 FRU
--	-------	-------

Set of valve caps Part I 36 12 2 447 402		1
---	--	---

— Job

Description:

Considered as a repeat visit No

Customer's own words

Radsatz einlagern Flat rate unit I AZ36 00 0	Local	2 FRU
---	-------	-------

Einlagerungskosten Winterräder einlagern Part I 0036007	Local	1
--	-------	---

— Job

Description:

Considered as a repeat visit No

Customer's own words

— Job

Description:

Considered as a repeat visit No

Customer's own words

Fahrzeugüberprüfung im Rahmen der Annahm Flat rate unit I 00 52 054	Local	0 FRU
--	-------	-------

— 05/03/2019 Repair 69326 Km 02832 Job
Niederlassung Job
Dortmund Job
BMW AG, Job
Dortmund

— Job

Description:

Considered as a repeat visit No

Customer's own words zwei Reifen der VA vor Saisonwechsel ersetzen,

zwei Reifen der VA vor Saisonwechsel ers Flat rate unit I AZ36 30 2	Local	12 FRU
--	-------	--------

— Job

Description:

Considered as a repeat visit No

Customer's own words

Bridgestone Potenza S 001 RFT
Part I 85 45 2 593 884

2

— Job

Description:

Considered as a repeat visit No

Customer's own words

Fahrzeugüberprüfung im Rahmen der Annahm
Flat rate unit I 00 52 054

Local

0 FRU

— Job

Description:


Considered as a repeat visit No

Customer's own words

— 23/01/2019 Key

69322 Km


Key 10



— 23/01/2019 Key

69322 Km

Key 10



— 23/01/2019 Repair

69326 Km

02832
Niederlassung
Dortmund
BMW AG,
Dortmund

Job
Job
Job
Job
Job

— Job

Description:

Considered as a repeat visit No

Customer's own words

Sichtkontrolle Flüssigkeiten nachfüllen
Flat rate unit I AZ00 00 0

Local

2 FRU

— Job

Description:

Considered as a repeat visit No

Customer's own words

Motorwäsche
Part I 0011359

Local

1

— Job

Description:

Considered as a repeat visit No

Customer's own words Befund;-> AGR Kühler mit der Teileendnummer ...691 hat den Index 10 und muss,geprüft werden,-> Kühler ist bereits auf der Austrittsseite stark verkott/verschmolzen,und muss ersetzt werden,-> Messwerte der Saugrohrdruckprüfung sind in Ordnung,

Additional work of checking EGR cooler Flat rate unit I 00 67 703	1 FRU
--	-------

Perform additional work for pressure sensor system function Flat rate unit I 00 67 695	3 FRU
---	-------

Replace exhaust gas recirculation cooler and clean exhaust gas recirculation pipe Flat rate unit I 00 66 769	26 FRU
---	--------

Exhaust gas radiator high temperature Part I 11 71 8 513 691	1
---	---

EGR small parts set Part I 11 71 8 490 222	1
---	---

Anti-freeze Part I 83 19 2 211 358	4
---------------------------------------	---

— Job

Description:

Considered as a repeat visit No

Customer's own words

Fahrzeugüberprüfung im Rahmen der Annahme Flat rate unit I 00 52 054	Local	0 FRU
---	-------	-------

— Job

Description:

Considered as a repeat visit No

Customer's own words

kostenlose Fahrzeugüberwäsche Part I 0011319	Local	1
---	-------	---

— Job

Description:

Considered as a repeat visit No

Customer's own words

—	23/01/2019 Warranty	69326 Km	02832	Job: F10 F11 F25 F26 F31 F34 F36 B47O Replacing exhaust-gas recirculation cooler
---	---------------------	----------	-------	--

— Job: F10 F11 F25 F26 F31 F34 F36 B47O Replacing exhaust-gas recirculation cooler

Description: F10 F11 F25 F26 F31 F34 F36 B47O Replacing exhaust-gas recirculation cooler

Considered as a repeat visit No

Customer's own words

Additional work of checking EGR cooler Flat rate unit I 00 67 703	1 FRU
--	-------

Perform additional work for pressure sensor system function Flat rate unit I 00 67 695	3 FRU
---	-------

Replace exhaust gas recirculation cooler and clean exhaust gas recirculation pipe	26 FRU
---	--------

Flat rate unit | 00 66 769

F10 F11 F25 F26 F31 F34 F36 B47O Replacing exhaust-gas
recirculation cooler
Defect | 00 11 83 04 00

Exhaust gas radiator high temperature
Part | 11 71 8 513 691

1

EGR small parts set
Part | 11 71 8 490 222

1

— 26/11/2018 Repair 66758 Km 02832 Job
Niederlassung Job
Dortmund Job
BMW AG,
Dortmund

— Job

Description:

Considered as a repeat visit No

Customer's own words

Depotservice Rädermontage WR montieren u
Flat rate unit | AZ36 00 2

Local

6 FRU

— Job

Description:

Considered as a repeat visit No

Customer's own words

Radsatz einlagern
Flat rate unit | AZ36 00 0

Local

2 FRU

Einlagerungskosten
Part | 0036007

Local

1

— Job

Description:

Considered as a repeat visit No


Customer's own words

Fahrzeugüberprüfung im Rahmen der Annahm
Flat rate unit | 00 52 054


Local

0 FRU

— 04/09/2018 Key 61657 Km Key 1



— 04/09/2018 Service 61657 Km 02832 Automatic
Niederlassung
Dortmund,
Dortmund



—	04/09/2018	Repair	61676 Km	02832 Niederlassung Dortmund BMW AG, Dortmund	Job Job Job Job Job Job Job Job Job Job Job Job
---	------------	--------	----------	---	--

— Job

Description:

Considered as a repeat visit No

Customer's own words

Engine oil service Flat rate unit I 00 00 610	3 FRU
--	-------

Set oil-filter element Part I 11 42 8 575 211	1
--	---

BMW Engine Oil LL04 0W30 Part I 83 21 2 405 950	5
--	---

— Job

Description:

Considered as a repeat visit No

Customer's own words

Service - standard scope Flat rate unit I 00 00 105	2 FRU
--	-------

— Job

Description:

Considered as a repeat visit No

Customer's own words

Service - air filter element Flat rate unit I 00 00 602	2 FRU
--	-------

Air filter element Part I 13 71 8 511 668	1
--	---

— Job

Description:

Considered as a repeat visit No

Customer's own words

Service fuel filter Flat rate unit I 00 00 604	3 FRU
---	-------

Fuel filter cartridge Part I 13 32 8 572 522	1
---	---

— Job

Description:

Considered as a repeat visit No

Customer's own words

Microfilter service	2 FRU
Flat rate unit 00 00 616	

Microfilter/activated Carbon container	1
Part 64 11 9 237 555	

— Job

Description:**Considered as a repeat visit** No**Customer's own words** -beide Reifen vorne sind außen abgefahren,-Profil tief der Reifen vorne bitte beobachten noch 4 mm,

Zusatz zum Fahrzeugcheck / Inspektion	Local	2 FRU
Flat rate unit AZ10 00 1		

Hinweis:	Local	1 FRU
Flat rate unit AZ88 00 7		

Zusatz zum Fahrzeugcheck / Inspektion	Local	2 FRU
Flat rate unit AZ10 00 1		

Service, vehicle check	6 FRU
Flat rate unit 00 00 624	

— Job

Description:**Considered as a repeat visit** No**Customer's own words**

Sichtkontrolle Flüssigkeiten nachfüllen	Local	2 FRU
Flat rate unit AZ00 00 0		

— Job

Description:**Considered as a repeat visit** No**Customer's own words**

kostenlose Fahrzeugoberwäsche	Local	1
Part 0011319		

— Job

Description:**Considered as a repeat visit** No**Customer's own words**

— Job

Description:**Considered as a repeat visit** No**Customer's own words** Sensor Geschwindigkeitsregelungprüfen,

Scheinwerfer rechts ersetzt	Local	4 FRU
Flat rate unit AZEL000		

Vorbereitungsarbeit für Hohlraum- konser	Local	3 FRU
Flat rate unit AZ97 00 3		

Replace three holders for the front side panel	1 FRU
Flat rate unit 41 35 610	

Replacing front right side panel	9 FRU
----------------------------------	-------

Flat rate unit | 41 35 555

Removing and installing front panel Flat rate unit 41 33 039	20 FRU
---	--------

Replacing front bumper panel Flat rate unit 51 11 592	11 FRU
--	--------

Additional work with Park Distance Control Flat rate unit 66 20 615	2 FRU
--	-------

Remove and install/replace left or right side sill trim panel Flat rate unit 51 71 947	4 FRU
---	-------

Performing vehicle test Flat rate unit 00 00 556	2 FRU
---	-------

Cavity preservation for side panel, front left or right Flat rate unit 97 35 512	2 FRU
---	-------

— Job

Description:**Considered as a repeat visit** No**Customer's own words**

Zeitzuschlag für eine Hauptarbeit Flat rate unit AZ99 00 0	Local	18 FRU
---	-------	--------

Stoßfängerverkleidung vorn lackiert Flat rate unit AZLA000	Local	11 FRU
---	-------	--------

Seitenwand vorn rechts lackiert Flat rate unit AZLA000	Local	7 FRU
---	-------	-------

— Job

Description:**Considered as a repeat visit** No**Customer's own words**

Side panel bracket, front right 2 Part 41 35 7 298 038	1
---	---

Side panel, front right Part 41 00 7 438 440	1
---	---

Panel, bumper, primed, front Part 51 11 8 067 941	1
--	---

Expanding rivet Part 51 16 1 881 149	3
---	---

Mounting, side panel, front bottom right Part 51 11 7 279 712	1
--	---

Set, mounting, PDC/PMA sensor, front Part 51 11 8 067 950	1
--	---

Headlight LED, AHL, right Part 63 11 7 419 628	1
---	---

Emblem Part 51 14 8 058 881	1
----------------------------------	---

Licence plate base Part 51 11 8 054 157	1
--	---

Phillips head screw for plastic material Part 07 14 6 959 925	5
--	---

Bracket headlight right
Part I 51 64 7 285 598 1

Plaque
Part I 51 76 7 288 752 1

— Job

Description:

Considered as a repeat visit No

Customer's own words

Motorölservice - zusätzliche AW Local 2 FRU
Flat rate unit I IM00 25 0

— 17/05/2018 Key 50201 Km 02832 Key 1

									
12000	12000	12000	12000	46000	0	30000	12000		0
09/2019	501	501	501		06/2019		09/2019		06/2019

— 11/04/2018 Repair 46508 Km 02832 Job
Niederlassung Job
Dortmund Job
BMW AG,
Dortmund

— Job

Description:

Considered as a repeat visit No

Customer's own words

Depotservice Rädermontage SR montieren, Local 6 FRU
Flat rate unit I AZ36 00 2

— Job

Description:

Considered as a repeat visit No

Customer's own words

Radsatz einlagern Local 2 FRU
Flat rate unit I AZ36 00 0

Einlagerungskosten Local 1
Part I 0036007

— Job

Description:

Considered as a repeat visit No

Customer's own words

Fahrzeugüberprüfung im Rahmen der Annahm Local 0 FRU
Flat rate unit I 00 52 054

— 08/11/2017 Key 34013 Km 02832 Key 1

								
28000	28000	28000	28000	50000	0	40000	28000	0
09/2019	691	691	691		06/2019		09/2019	06/2019

— 08/11/2017 Repair 34017 Km 02832
 Niederlassung Job
 Dortmund Job
 BMW AG, Job
 Dortmund Job
 Job
 Job
 Job

— Job

Description:

Considered as a repeat visit No

Customer's own words

RDCi Wheel/Tyre set Winter light alloy
 Part I 36 11 0 047 956

4

— Job

Description:

Considered as a repeat visit No

Customer's own words

Radsatz einlagern
 Flat rate unit I AZ36 00 0

Local

2 FRU

Einlagerungskosten
 Part I 0036007

Local

1

— Job

Description:

Considered as a repeat visit No

Customer's own words Befund:,AGR-Ventil ist laut Funktionstest in Ordnung und kann im Fahrzeug,verbleiben.,

Carrying out the ABL and programming the control units
 Flat rate unit I 00 64 941

8 FRU

— Job

Description:

Considered as a repeat visit No

Customer's own words

Sichtkontrolle Flüssigkeiten nachfüllen
 Flat rate unit I AZ00 00 0

Local

2 FRU

— Job

Description:

Considered as a repeat visit No

Customer's own words Fahrzeug wurde am Counter angenommen,

Fahrzeugüberprüfung im Rahmen der Annahm
 Flat rate unit I 00 52 054

Local

0 FRU

— Job

Description:

Considered as a repeat visit No

Customer's own words

kostenlose Fahrzeugoberwäsche
Part I 0011319

Local

1

— Job

Description:

Considered as a repeat visit No

Customer's own words

— Job

Description:

Considered as a repeat visit No

Customer's own words

Depotservice Rädermontage neuen Winterra
Flat rate unit I AZ36 00 2

Local

6 FRU

— 08/11/2017 Warranty 34017 Km 02832 Job: F1x F2x F3x B47
programming control units and if
necessary, replacing the EGR valve

— Job: F1x F2x F3x B47 programming control units and if necessary, replacing the EGR valve

Description: F1x F2x F3x B47 programming control units and if necessary, replacing the EGR valve

Considered as a repeat visit No


Customer's own words

Carrying out the ABL and programming the control units
Flat rate unit I 00 64 941


8 FRU

F1x F2x F3x B47 programming control units and if necessary, replacing
the EGR valve
Defect I 00 11 45 04 00

— 07/09/2017 Key 30451 Km 02832 Key 1



— 07/09/2017 Key 30450 Km 02832 Key 1



— 07/09/2017 Service 30450 Km 02832 Automatic
Niederlassung
Dortmund,
Dortmund

 410 06/2018 ✓	 0	 410 06/2018 ✓	 0	 50000	 0 06/2019	 42000	 32000 06/2020	 0 06/2019
---	---	---	---	---	--	---	---	--

— 07/09/2017 Repair 30456 Km 02832
 Niederlassung Job
 Dortmund Job
 BMW AG, Job
 Dortmund Job
 Job
 Job
 Job

— Job

Description:

Considered as a repeat visit No

Customer's own words

Sichtkontrolle Flüssigkeiten nachfüllen
 Flat rate unit | AZ00 00 0

Local

2 FRU

— Job

Description:

Considered as a repeat visit No

Customer's own words

UVV für Dienstfahrzeuge
 Flat rate unit | AZ88 01 8

Local

12 FRU

— Job

Description:

Considered as a repeat visit No

Customer's own words

Service - standard scope
 Flat rate unit | 00 00 105

2 FRU

— Job

Description:

Considered as a repeat visit No

Customer's own words

Engine oil service
 Flat rate unit | 00 00 610

3 FRU

Set oil-filter element
 Part | 11 42 8 575 211

1

BMW Engine Oil LL04 0W30
 Part | 83 21 2 405 950

5

— Job

Description:

Considered as a repeat visit No

Customer's own words

Microfilter service	2 FRU
Flat rate unit I 00 00 616	

Microfilter/activated Carbon container	1
Part I 64 11 9 237 555	

— Job

Description:

Considered as a repeat visit No

Customer's own words

Service consultation with customer at vehicle without service ticket	0 FRU
Flat rate unit I 00 52 053	

— Job

Description:

Considered as a repeat visit No

Customer's own words

kostenlose Fahrzeugüberwäsche	Local	1
Part I 0011319		


— Job

Description:

Considered as a repeat visit No

Customer's own words

— 28/03/2017 Key	16328 Km	02832	Key 0
------------------	----------	-------	-------



— 28/03/2017 Repair	16328 Km	02832 Niederlassung Dortmund BMW AG, Dortmund	Job
---------------------	----------	---	-----

— Job

Description:

Considered as a repeat visit No

Customer's own words

Auslieferungsdurchsicht BPS	Local	15 FRU
Flat rate unit I AZ00 00 3		

Supporting the voltage of the vehicle electrical system/recharging the vehicle electrical system battery	1 FRU
Flat rate unit I 61 21 528	

Windshield washer antifreeze	1
Part I 83 12 2 409 031	

— 04/01/2017 Repair	16319 Km	00082 Niederlassung Bonn BMW AG, Bonn	Job Job Job Job
---------------------	----------	--	--------------------------

Job
Job
Job
Job

— Job

Description:

Considered as a repeat visit No

Customer's own words Standtage:14/offen: 1991,00,Auftrag an Fa. Cirkin am: 04.01.17,

Fahrzeugüberprüfung im Rahmen der Annahm Flat rate unit I 00 52 054	Local	0 FRU
--	-------	-------

— Job

Description:

Considered as a repeat visit No

Customer's own words

1. Auftrag Fa. Cirkin Technik: Premium L Part I 0000156	Local	1
--	-------	---

— Job

Description:

Considered as a repeat visit No

Customer's own words

Servicehistorie pflegen. Rundum Sorglos Part I 0000156	Local	1
---	-------	---

— Job

Description:

Considered as a repeat visit No

Customer's own words

— Job

Description:

Considered as a repeat visit No

Customer's own words

— Job

Description:

Considered as a repeat visit No

Customer's own words

Stoßstange hinten inst. Part I 0000156	Local	1
---	-------	---

Stoßstange hinten lackieren. Part I 0000156	Local	1
--	-------	---

— Job

Description:

Considered as a repeat visit No

Customer's own words


— Job

Description:

Considered as a repeat visit No

Customer's own words

— 11/08/2016 Key 5232 Km 04107 Key 0



— 11/08/2016 Repair 5232 Km 04107

Niederlassung Job
München Job
BMW AG, Job
München Job
Job
Job

— Job

Description:

Considered as a repeat visit No

Customer's own words

— Job

Description:

Considered as a repeat visit No

Customer's own words *E O-Ton Kunde: Das Infodisplay stürzt ständig ab s. Email Anhang. Bitte,Diagnose durchführen Fzg wird heute wieder benötigt. Zur Instandsetzung,wird neuer Termin vereinbart,zu Pos 40;- Fehlerspeiche
r ausgelesen relevante Fehler abgelegt,- Testmodul abgearbeitet,- Display Funktionsprüfung durchgeführt Testbilder abgespielt wurden,alle einwandfrei angezeigt i.O,- Sicherung geprüft i.O,- Headunit h
at mehrere Resets gespeichert,- Headunit ausgebaut um Leitungen und Steckverbindungen zu prüfen i.O,- CID ausbaut um Leitungen und Steckverbindungen zu prüfen i.O,- HSD leitung zwischen CID und Headun
it gemessen und Steckverbindungen,geprüft i.O,- Testmodul fortgeführt Laut Testmodul muss eine Fahrzeugprogrammierung,durchgeführt werden.,- Sollte der Fehler danach erneut Auftreten muss die Headunit
ersetzt,laut Testmodul ersetzt werden.,- Programmierung durchgeführt -> Programmierabbruch bei der Headunit,- Fehlerspeicher ausgelesen fortgeführt Testmodule abgearbeitet,- Headunit meldet sich nich
t mehr,- Batteriereset durchgeführt,- TC fall angelegt NR. 62831605,Headunit muss ersetzt werden laut PUMA,- Fahrzeugprogrammierung erneut durchgeführt,- Tausch war erfolgreich i.O,

Performing vehicle test 4 FRU
Flat rate unit I 00 00 006

Vehicle diagnosis - carrying out the ABL 4 FRU
Flat rate unit I 61 00 006

Programming/encoding control unit(s) including deleting fault memories 4 FRU
Flat rate unit I 61 00 730

Remove and install Central Information Display 3 FRU
Flat rate unit I 65 50 557

Troubleshooting electrical/electronic system 6 FRU
Flat rate unit I 61 00 009

Additional work after first termination while programming/encoding Flat rate unit I 61 00 731	4 FRU
Continuing vehicle test and deleting fault memory Flat rate unit I 61 00 980	2 FRU
Replace HU-H Flat rate unit I 65 12 816	8 FRU
TeileClearing, lump-sum fee Flat rate unit I 00 58 677	2 FRU
RP REMAN Headunit High 2 Part I 65 12 9 391 821	1

— Job

Description:

Considered as a repeat visit No

Customer's own words

Füllstände prüfen und ergänzen Nein Flat rate unit I AZ00 33 3	Local	1 FRU
---	-------	-------

— Job

Description:

Considered as a repeat visit No

Customer's own words

Service, advisory consultation at vehicle Flat rate unit I 00 52 050	0 FRU
---	-------

— Job

Description:

Considered as a repeat visit No

Customer's own words

kostenlose Fahrzeugoberwäsche Part I 0011319	Local	1
---	-------	---

— Job

Description:

Considered as a repeat visit No

Customer's own words

Endkontrolle Flat rate unit I AZ00 45 0	Local	1 FRU
--	-------	-------

— Job

Description:

Considered as a repeat visit No

Customer's own words

— 11/08/2016 Warranty 5232 Km 04107 Job: Headunit High HU-H

— Job: Headunit High HU-H

Description: Headunit High HU-H

Considered as a repeat visit No

Customer's own words

Performing vehicle test Flat rate unit I 00 00 006	4 FRU
Vehicle diagnosis - carrying out the ABL Flat rate unit I 61 00 006	4 FRU
Programming/encoding control unit(s) including deleting fault memories Flat rate unit I 61 00 730	4 FRU
Remove and install Central Information Display Flat rate unit I 65 50 557	3 FRU
Troubleshooting electrical/electronic system Flat rate unit I 61 00 009	6 FRU
Additional work after first termination while programming/encoding Flat rate unit I 61 00 731	4 FRU
Continuing vehicle test and deleting fault memory Flat rate unit I 61 00 980	2 FRU
Replace HU-H Flat rate unit I 65 12 816	6 FRU
TeileClearing, lump-sum fee Flat rate unit I 00 58 677	1 FRU
Headunit High HU-H Defect I 65 12 58 02 00	
RP REMAN Headunit High 2 Part I 65 12 9 391 821	1

— 17/06/2016 Repair 121482 Km 02832 Job
Niederlassung Job
Dortmund Job
BMW AG,
Dortmund

— Job

Description:

Considered as a repeat visit No

Customer's own words

Rädereinlagerung Premium Part I 36999	Local	1
--	-------	---

— Job

Description:

Considered as a repeat visit No

Customer's own words

— Job

Description:

Considered as a repeat visit No

Customer's own words

Nachrüstung Service-Inclusive GA Service Part I 5100102	Local	1
--	-------	---