

BMW 3er 318d



Stock number:	CD09899
Build year:	2012
First registration:	04/2014
Odometer reading:	190,559 km
Fuel type:	Diesel
Horsepower:	105 kW / 143 HP
Cylinder capacity:	1,995 ccm
Gear box:	Automatic
Inspection expires:	04/2025
Body type:	Sedan
Total number of owners:	2
Keys:	2
Prior damage / Accident according to previous owner	No
Country of origin:	DE
Country of last registration:	BE
Environmental class:	EURO 5
COC papers:	Yes
Seats:	5
Color:	Black (Original)
Upholstery:	Leather (Original)
Door count:	4
CO2 Emissions:	118g/km

Car location

-



00 / 0:23



[illegible]

ONE THIRD LONG LIFE	5.4	14.9
DOUBLE	1	2.0
INTERMEDIATE	1	2.0
ULTRA	1	2.0
SERVICE RESIST	1	2.0
WEEK	1	2.0
MONTH RETURN	1	2.0

ITEM	QTY	UNIT PRICE	TOTAL
OUTLETTER	1	12.00	
INTERLOCKER	1	90.00	
BRANDER/FILTER	1	50.00	
LOCKER/ITER	1	50.00	
CLIP SWIV LONGLINE	1	1.00	
VALEDCOPPER	1	20.00	
BRANDPOT/STOP/STAMPING	1	90.00	
WATER	1		


COMPENSER BAKEN ACHESTAN VERLETEN ZUWILKEL 99

By Corbin D

BTW A = 25.76 255.87

DATE 08/01/2018

TIME 10:00



MAIN CAR DETAILS

CAR HIGHLIGHTS / ADDITIONAL PHOTOS



General



General



General



General

CAR EQUIPMENT

Some content has been automatically translated.

 Xenon lights	Bi-Xenon headlights
 Heated seats	Front seat heating
 Sunroof	Electric sliding/tilting sunroof (glass)
 Park Distance Control	Park-Distance-Control (PDC) front and rear Rearview camera
 Power steering	Power steering Servotronic
 Hands-free system	Bluetooth hands-free system with USB audio interface Mobile phone predisposition with Bluetooth interface
 Navigation System	Professional audio-navigation system
 Airbag	Driver side airbag / passenger side airbag Rear Cranial Airbag System Front head airbag system Front side airbag
 AC System	Automatic dual-zone air conditioning with automatic air circulation control
 DPF / FAP	Particulate filter
 Power windows	Electric windows front + rear
 ESP	Dynamic Stability Control (DSC)
 Immobilizer	Immobilizer
 On-board computer	On-board computer
 Entertainment system	BMW Professional audio system (Radio / DVD player compatible with MP3) Instrument cluster (extended scope)






ABS

Anti-lock Braking System (ABS)

CAR SERVICE DETAILS

Service book details:	Digital service book
Service appointment:	All
Last service on:	04/17/2023
Last service Mileage:	179,378 km
Drive belt change on:	-
Drive belt change Mileage:	-


Car service images 5 images available



TECHNICAL INSPECTION

Date of latest technical inspection:	04/15/2024
Mileage at latest technical inspection:	187,483 km

Technical inspection images 1 image



TEST DRIVE INFORMATION

TEST DRIVE LOCATION: ON PUBLIC STREET < 80KM/H (LOWER SPEED)

NO SPECIFIC FINDINGS

CAR DATA ACCORDING TO IDENTIFICATION NUMBER (VIN)

Some content has been automatically translated.

-  Upholstery: Dakota Leather
-  Automatic transmission - (8-speed)
-  AUX-IN connection (AUX-IN)
-  White blinkers
-  Regenerative braking
-  Check Control System
-  Tachometer
-  Dynamic brake lights
-  Velour floor mats
-  Drink holder



PAINT THICKNESS NEW

Hood	120 µm
Roof	105 µm
Front fender left	110 µm
Front fender right	114 µm
Rear fender left	110 µm
Rear fender right	213 µm
Front door left	145 µm
Front door right	129 µm
Rear door left	181 µm
Rear door right	186 µm
Tailgate (Boot lid)	109 µm

CAR DAMAGE

DAMAGE AREAS

Sub-area images are merely displayed for orientation purposes and the damage summary reports the area's condition in detail. Please note that we take photos of all significant damages. Minor damage will be displayed below in the table without a corresponding image.



No damage specific images

1/9



No damage specific images

2/9



No damage specific images

3/9



No damage specific images

4/9



No damage specific images

5/9



6/9



7/9



8/9



9/9

Damage and severity

FRONT BUMPER

2 SCRATCHES

0

Length: ≥20mm & <50mm Surface scratch

3 STONE CHIPS

0

Width: ≤3mm No paint damage

HOOD

3 STONE CHIPS

0

Width: ≤3mm No paint damage

DAMAGE SUMMARY

The results of this car's evaluation are summarised in the DAMAGE SUMMARY table and visualised in the DAMAGE AREAS section below.

Damage / Part	Severity
1 DENT Front left door (1)	Width: ≥5mm & <20mm , Paint damage
3 REPAINT Rear left door (1) Rear right fender (1) Rear right door (1)	Thickness: ≥125µm & <250µm , Professional repaint
8 SCRATCHES Front bumper (2) Left mirror housing (1) Front left door (2) Rear bumper (2) Rear right door (1)	Length: ≥20mm & <50mm , Surface scratch
2 SCRATCHES Front left door (1) Rear right door (1)	Length: <20mm , Deep scratch - down to primer
6 STONE CHIPS Front bumper (3) Hood (3)	Width: ≤3mm , No paint damage

3 RECONDITIONING NECESSARY

Passenger seat (1) Driver seat (1) Steering Wheel (1)


1 SCRATCH

Length: <50mm

Front door interior left (1)

MAIN WHEELS DETAILS [i](#)

This section visualises the state of the car's tires, brake pad and disc condition. In the case that any rim-related damages are found on this car they will be displayed in the car damages section.



FRONT LEFT - (1/4)

Tire type
Summer

DOT
3220

Profile depth (mm)
5

Tire condition
No issues found

Rim type
Aluminium

Brake type
Disc brake

Brake pad thickness
≥ 3mm

Brake disc condition
Not measurable