

Thank you for ordering from us!
www.checkvin.eu

Vehicle

BMW 420D A, 140KW

WBA4E91000G595216



Development code
Colour
Actual integration level
Start of warranty

F36
mineral-grau metallic
F020-22-11-510
19 May 2016

Technical campaigns

There are no Campaigns for this vehicle.

Warranty extension/VIN-based goodwill

Status	Campaign number	Description
Open	1SACC011056	Exhaust gas recirculation cooler Bx7 Local campaign number: -

Special information

There are no Campaigns for this vehicle.

Restrictions on the warranty

There are no restrictions on the warranty.

⚠ Market-specific restrictions are not currently displayed. Please check this in WDF/WXE via S-Gate.

Live Diagnosis

 There are no service solutions for Live Diagnosis.

Service contracts

No BSI contracts

Information on faults workshop/Service Consultation

There is no information on faults.

Navigation map

Installed map	Enabling code (subscription)	Latest navigation map included in subscription	Latest navigation map subject to charge
Road Map EUROPE Route 2016-1 (As of: 13 Dec 2024)	Enabling code valid for navigation maps with release date up to 31 Dec 2025 (SWID: 00B4008F).	Road Map EUROPE EAST Route 2025	-

Vehicle details

Vehicle type	Passenger car
Brand	BMW
Model	420D A
Body	COUPE
Vehicle identification number (last 7 digits)	G595216
Vehicle identification number (17 digits)	WBA4E91000G595216
Development code	F36
Steering	LL
Engine	B47O
Engine number	75029622
Exhaust re-treatment	EURO6, W, PI/CI, M, N1 I
Transmission	AUT
Transmission number	0412524ZRI
Head unit serial number	MM01DFG1115830
Drive	HECK
Integration level, works	F020-16-03-504
Production date	13 May 2016
Production plant	Dingolfing
Delivery date	13 Jun 2016
Delivering retailer	Fuhrpark, München, DE
National-market version	EUR
Paint code	B39
Upholstery code	HAAT
Model code	4E01
Basic type	4E91
Lead type	4E01

Optional equipment

Optional equipment ex works:

01CA Selection of COP-relevant vehicles
 01CB CO2 equipment
 0205 Automatic transmission
 0230 Extra package, EU-speciifc
 0258 Tyres with runflat properties
 02PE BMW LA wheel, M star spoke 400
 02VB Tyre pressure display
 0302 Alarm system
 0320 Deleted, model lettering
 0321 Exterior parts in body colour
 0337 M Sports package
 03AC Trailer coupling
 03AG Reversing camera
 0403 Glass roof, electrical
 0420 Sun protection glazing
 0423 Floor mats velours
 0428 Warning triangle and first aid kit
 0431 Interior mirror with automatic-dip
 0459 Seat adjustment, electric, with memory
 0465 Through-loading system
 0481 Sports seat
 0488 Lumbar support, driver and passenger
 0493 Storage compartment package
 0494 Seat heating driver/passenger
 04AE Armrest front, retractable
 04FT Alum. brushed lengthw. acc. black hi-gls
 0502 Headlight cleaning system
 0508 Park Distance Control (PDC)
 0521 Rain sensor
 0522 Xenon Light
 0534 Automatic air conditioning
 0544 Cruise control with braking function
 0548 Kilometre speedo
 0563 Lights package
 0575 Additional 12V sockets
 05AC High-beam assistant
 05AL Active Protection
 05DA Passenger airbag deactivation
 0606 Navigation system Business
 0676 HiFi speaker system
 0698 Area-Code 2 for DVD
 06AC Intelligent emergency call
 06AE Teleservices
 06AK Connected Drive Services
 06AM Real-Time Traffic Information
 06AN Concierge Services
 06AP Remote Services
 06AR Internet
 06NH Hands-free system with USB interface
 06WA Instrument panel with extended scope
 0704 M Sports suspension
 0710 M leather steering wheel
 0715 M Aerodynamics package
 0760 High gloss shadow line
 0775 Headlining anthracite
 07LF Modell M Sport
 07S9 Connected Drive Services Paket
 07VB Comfort Package
 0801 German version
 0851 Language version German
 0879 On-board literature, German
 08KA Oil service interval 24 mths / 30,000 km
 08TH Road sign detection
 09AA Outer skin protection
 A090 90 Ah AGM battery
 POLS Cloth cushion

Retrofitted optional equipment:

This vehicle has no retrofits.

Vehicle histories

Date	Type	Vehicle mileage	Retailer	Overview
------	------	-----------------	----------	----------

—

13/12/2024

Key

216710 Km

00193

Key 0



13000

05/2026





13000

05/2026





90000

06/2025





80000



44000

05/2028



06/2025

—

09/12/2024

Key

216350 Km

26140

Remote KeyRead



14000

05/2026





14000

05/2026





90000

06/2025





80000



45000

05/2028



06/2025

—

09/12/2024

Key

216350 Km

00886

Key 0



14000

05/2026





14000

05/2026





90000

06/2025





80000



45000

05/2028



06/2025

—

09/12/2024

Repair

216350 Km

00083 ,

Job

—

Job

Description:

Considered as a repeat visit No

Customer's own words

Serviceberatung am Fahrzeug	Local	1
Part I IF52050		

—

22/11/2024

Key

214878 Km

25742

Key 0



15000

05/2026





15000

05/2026





90000

06/2025





80000



46000

05/2028



06/2025

—

22/11/2024

Warranty

214881 Km

25742

Job: Fx Replace driver's airbag, part III (SDI)

— Job: Fx Replace driver's airbag, part III (SDI)

Description: Fx Replace driver's airbag, part III (SDI)

Considered as a repeat visit No

Customer's own words

Replace driver's airbag	5 FRU
Flat rate unit I 00 76 283	

Fx Replace driver's airbag, part III (SDI)

Defect I 00 32 62 03 00

Airbag module, driver's side	1
Part I 32305A66F66	

—

24/05/2024

Service

198706 Km

OSS-60008252
Autohaus C.-D.
Rudorff e.K.,
Emtinghausen


Manual

https://myair-b2d.bmwgroup.com/air/faces/xhtml/fahrzeug/FahrzeugSingleView.xhtml?vin=WBA4E91000G595216


4/30




03/05/2024 Key 197213 Km 03415 Remote KeyRead



03/05/2024 Key 197213 Km 25742 Remote KeyRead



23/06/2023 Key 173665 Km Key 0



23/06/2023 Warranty 173665 Km 25742 Job: F1x F2x F3x G0x G1x G3x B47O B47K B47U B47T Replacing EGR cooler (high-temperature)

Job: F1x F2x F3x G0x G1x G3x B47O B47K B47U B47T Replacing EGR cooler (high-temperature)

Description: F1x F2x F3x G0x G1x G3x B47O B47K B47U B47T Replacing EGR cooler (high-temperature)

Considered as a repeat visit No

Customer's own words

Replace exhaust gas recirculation cooler, including exhaust gas recirculation valve
Flat rate unit I 00 74 635 23 FRU

Additional work: run function test for pressure sensor system
Flat rate unit I 00 74 636 3 FRU

Additional work: enter component identification of new exhaust gas recirculation cooler in diagnostic system
Flat rate unit I 00 74 637 1 FRU

Additional work cleaning the exhaust gas recirculation pipe
Flat rate unit I 00 74 638 2 FRU

Removing and installing/replacing the exhaust manifold
Flat rate unit I 18 40 540 19 FRU

Additional work with panoramic roof
Flat rate unit I 51 71 960 3 FRU

Job time without allowance for / engine
Flat rate unit I 11 99 000 12 FRU

F1x F2x F3x G0x G1x G3x B47O B47K B47U B47T Replacing EGR cooler (high-temperature)
Defect I 00 11 13 07 00

Acoustic cover front Part I 11 14 8 490 577	1
O-ring Part I 11 61 8 512 681	1
Exhaust manifold Part I 11 62 8 519 888	1
Connection piece Part I 11 65 7 803 012	1
Vacuum hose black Part I 11 65 8 595 650	1
Pipe union Part I 11 71 7 799 853	2
Exhaust gas radiator high temperature Part I 11 71 7 822 347	1
EGR small parts set Part I 11 71 8 490 640	1
Gasket Steel Part I 11 71 8 579 364	1
Pipe Part I 13 71 8 479 957	1
Filtered air pipe with resonator Part I 13 71 8 479 958	1
Oval head screw Part I 35 21 7 685 343	2
Holder Part I 61 13 1 369 832	1
ASA-stud bolt Part I 11 12 8 597 830	8

—

09/06/2023

Key

172658 Km

Key 0



16000

09/2024



16000

09/2024



16000

09/2024



16000

09/2024



100000

09/2024



-39

5.3 %



100000

09/2024



16000

09/2024



-39

5.3 %

—

09/06/2023

Service

172658 Km

25742 Procar
Automobile
Münsterland
GmbH ,
Münster

Automatic



16000

09/2024



16000

09/2024



16000

09/2024



16000

09/2024



100000

06/2023



0

05/2023



100000

06/2023



16000

09/2024



0

05/2023

—

09/06/2023

Repair

173665 Km

25742 Procar
Automobile
Münsterland
GmbH ,
Münster

Job
Job
Job
Job
Job

—

Job

Description:

Considered as a repeat visit No

Customer's own words

Service - standard scope	2 FRU
Flat rate unit 00 00 105	

— Job

Description:

Considered as a repeat visit No

Customer's own words

Brake fluid service	4 FRU
Flat rate unit 00 00 618	

Brake fluid DOT4 LV, low viscosity	1
Part 83 13 2 184 842	

— Job

Description:

Considered as a repeat visit No

Customer's own words

Räder auslagern	Local	1 FRU
Flat rate unit 36 99 029		

Sommerräder montieren Räder-Mo ntage Basic	Local	7 FRU
Flat rate unit 36 99 019		

— Job

Description:

Considered as a repeat visit No

Customer's own words

AU Extern Dekra Abgasuntersuch ung für DEKRA	Local	5 FRU
Flat rate unit 00 00 446		

— Job

Description:

Considered as a repeat visit No

Customer's own words

Dekra Abnahme	Local	1 FRU
Flat rate unit 99 99 999		

— 24/05/2023 Key 172088 Km Remote KeyRead

 17000 09/2024	 17000 09/2024	 17000 09/2024	 17000 09/2024	 100000 09/2024	 -22 3 %	 100000 09/2024	 17000 09/2024	 -22 3 %
---	---	---	---	--	---	--	--	---

— 24/01/2023 Key 165658 Km Key 0

 23000 09/2024	 23000 09/2024	 23000 09/2024	 23000 09/2024	 100000 05/2023	 100000 09/2024	 23000 09/2024	 05/2023
---	---	---	---	--	--	--	--

— 24/01/2023 Warranty 165658 Km 25742 Job: F1x F2x F3x B47O B47K B47U Programming control units (DDE)

— Job: F1x F2x F3x B47O B47K B47U Programming control units (DDE)

Description: F1x F2x F3x B47O B47K B47U Programming control units (DDE)

Considered as a repeat visit No


Customer's own words

Program control units 9 FRU
Flat rate unit I 00 71 349








Initialising more than one system 2 FRU
Flat rate unit I 61 00 832

F1x F2x F3x B47O B47K B47U Programming control units (DDE)
Defect I 00 13 50 03 00









— 15/09/2022 Service 157480 Km OSS-60008252 Manual
Autohaus C.-D. Rudorff e.K., Emtinghausen



— 20/04/2021 Key 126135 Km Key 1



— 01/04/2021 Key 125434 Km Key 1



— 01/04/2021 Repair 125434 Km 00088 Job
Niederlassung Job
Bremen BMW Job
AG, Bremen Job
Job

— Job

Description:

Considered as a repeat visit No

Customer's own words

Replace left and right radial shaft seal for driven shafts on rear axle differential 24 FRU
Flat rate unit I 33 10 024

Hypoid axle oil G1 1
Part I 83 22 2 295 532

Gasket set differential Part I 33 10 7 564 416	2
Assembly ring Part I 31 53 7 502 681	4
Hex Bolt with washer Part I 33 17 6 760 343	2
Self-locking collar nut Part I 33 30 6 760 349	3
Repair kit insert nut Part I 33 12 7 607 158	1
Nut Part I 33 17 6 866 285	1
ASA-Bolt Part I 33 17 6 866 691	1
Collar nut Part I 33 40 6 799 223	2
Torx screw Part I 33 32 6 764 505	6
Self-locking collar nut Part I 33 32 6 760 668	2
Hexagon screw with flange Part I 07 11 9 906 489	2
Hexalobular socket screw Part I 07 11 9 907 137	6
Screw plug with O-ring Part I 33 11 7 525 064	1
battery Part I 61 31 9 217 643	1

— Job

Description:

Considered as a repeat visit No

Customer's own words

Removing and installing both rear shock absorbers Flat rate unit I 33 52 525	9 FRU
Self-locking collar nut Part I 33 32 6 760 668	2
Hex nut Part I 33 50 6 896 360	2
Auxiliary damper, rear Part I 33 53 6 855 439	2

— Job

Description:

Considered as a repeat visit No

Customer's own words

Replacing right fog light Flat rate unit I 63 17 576	4 FRU
Bumper grille, front right Part I 51 11 8 054 508	1

Fog lights, right
Part I 63 17 7 248 912

1

— Job

Description:

Considered as a repeat visit No

Customer's own words

— Job

Description:

Considered as a repeat visit No

Customer's own words

Diverse Zusatzarbeiten
Flat rate unit I AZ00 00 3

Local

6 FRU

— Job

Description:

Considered as a repeat visit No

Customer's own words

BMW Mug Logo
Part I 80 23 2 466 202

1

— 09/07/2020 Key

111382 Km

36850

Key 1

								
240	240	240	240	60000	70000	240		
05/2021	292	292	292	05/2021		05/2021		05/2021

— 09/07/2020 Service

111382 Km

36850

Automatic

Cloppenburg
GmbH , Verden

								
240	240	240	240	60000	0	70000	240	0
05/2021	05/2021	05/2021	05/2021	05/2021	05/2021	05/2021	05/2021	05/2021
✓	✓	✓	✓				✓	

— 09/07/2020 Repair

111383 Km

36850

Cloppenburg
GmbH , Verden

Job
Job
Job
Job
Job
Job
Job
Job
Job

— Job

Description:

Considered as a repeat visit No

Customer's own words

Service Beratung am Fahrzeug mit iPad und Kunde
Flat rate unit I 00 97 097

Local

0 FRU

— Job

Description:

Considered as a repeat visit No

Customer's own words

Job time without allowance for / painting Flat rate unit I 99 99 000	0 FRU
---	-------

Service - standard scope Flat rate unit I 00 00 105	2 FRU
--	-------

— Job

Description:

Considered as a repeat visit No

Customer's own words

Engine oil service Flat rate unit I 00 00 610	3 FRU
--	-------

Set oil-filter element Part I 11 42 8 575 211	1
--	---

BMW Engine Oil LL04 5W30 Part I 83 21 2 405 948	5
--	---

— Job

Description:

Considered as a repeat visit No

Customer's own words

Microfilter service Flat rate unit I 00 00 616	2 FRU
---	-------

Microfilter/activated Carbon container Part I 64 11 9 237 555	1
--	---

— Job

Description:

Considered as a repeat visit No

Customer's own words

Service, vehicle check Flat rate unit I 00 00 624	6 FRU
--	-------

— Job

Description:

Considered as a repeat visit No

Customer's own words

Service fuel filter Flat rate unit I 00 00 604	3 FRU
---	-------

Fuel filter cartridge Part I 13 32 8 572 522	1
---	---

— Job

Description:

Considered as a repeat visit No

Customer's own words

Service - air filter element
Flat rate unit I 00 00 602

2 FRU

Air filter element
Part I 13 71 8 511 668

1

— Job

Description:

Considered as a repeat visit No

Customer's own words

Fussraum aussaugen (ohne Berechnung)
Flat rate unit I 00 11 001

Local

2 FRU

— Job

Description:

Considered as a repeat visit No

Customer's own words

Maschinelle Außenwäsche (ohne Berechnung)
Flat rate unit I 00 11 002

Local








1 FRU

— 28/05/2019 Key

82708 Km

36850

Key 1










— 28/05/2019 Service

82708 Km

36850

Automatic

Cloppenburg
GmbH, Verden



— 28/05/2019 Repair

82713 Km

36850

Cloppenburg
GmbH, Verden

Job
Job
Job
Job
Job
Job
Job
Job
Job
Job
Job

— Job

Description:

Considered as a repeat visit No

Customer's own words

Service Beratung am Fahrzeug mit iPad ohne Kunde Flat rate unit I 00 98 098	Local	0 FRU
--	-------	-------

Fetch and bring service zone Flat rate unit I 00 99 200		0 FRU
--	--	-------

— Job

Description:

Considered as a repeat visit No

Customer's own words

Service - standard scope Flat rate unit I 00 00 105		2 FRU
--	--	-------

Engine oil service Flat rate unit I 00 00 610		3 FRU
--	--	-------

BMW MOTORÖL 0W30 LONGL.04 Part I 83 21 2 405 674	Local	5
---	-------	---

Set oil-filter element Part I 11 42 8 575 211		1
--	--	---

— Job

Description:

Considered as a repeat visit No

Customer's own words

Microfilter service Flat rate unit I 00 00 616		2 FRU
---	--	-------

Microfilter/activated Carbon container Part I 64 11 9 237 555		1
--	--	---

— Job

Description:

Considered as a repeat visit No

Customer's own words

Service, rear brakes Flat rate unit I 00 00 614		7 FRU
--	--	-------

Repair kit, brake pads asbestos-free Part I 34 21 6 873 093		1
--	--	---

Brake-pad sensor, rear Part I 34 35 6 792 292		1
--	--	---

Brake-pad paste Part I 83 19 2 158 851		2
---	--	---

Brake cleaner 2.0 Part I 83 19 2 365 214		1
---	--	---

Clip Part I 34 21 6 850 853		2
--------------------------------	--	---

— Job

Description:

Considered as a repeat visit No

Customer's own words

Brake fluid service		4 FRU
---------------------	--	-------

Flat rate unit I 00 00 618

Brake fluid DOT4 LV, low viscosity
Part I 83 13 0 443 026

1.2

— Job

Description:

Considered as a repeat visit No

Customer's own words

Service Standard W.O.L.K.E.
Flat rate unit I 00 99 400

1 FRU

— Job

Description:

Considered as a repeat visit No

Customer's own words

Fussraum aussaugen (ohne Berechnung)
Flat rate unit I 00 11 001

Local

2 FRU

— Job

Description:

Considered as a repeat visit No

Customer's own words

Maschinelle Außenwäsche (ohne Berechnung)
Flat rate unit I 00 11 002

Local

1 FRU

— Job

Description:

Considered as a repeat visit No

Customer's own words

— Job

Description:

Considered as a repeat visit No

Customer's own words

— Job

Description:

Considered as a repeat visit No

Customer's own words

— Job

Description:


Considered as a repeat visit No

Customer's own words


— 23/11/2018 Key

67369 Km

Key 1



— 23/11/2018 Service 67369 Km 36850 Cloppenburg GmbH, Verden Manual



— 23/11/2018 Repair 67382 Km 36850 Cloppenburg GmbH, Verden Job
Job
Job
Job
Job
Job

— Job

Description:

Considered as a repeat visit No

Customer's own words

Vehicle check in course of reception
Flat rate unit I 00 52 054

0 FRU

— Job

Description:

Considered as a repeat visit No

Customer's own words

Job time without allowance for / maintenance
Flat rate unit I 00 99 000

0 FRU

Flap, towing eye, primed
Part I 51 11 8 061 005

1

— Job

Description:

Considered as a repeat visit No

Customer's own words

Service - standard scope
Flat rate unit I 00 00 105

2 FRU

— Job

Description:

Considered as a repeat visit No

Customer's own words

Service, front brakes
Flat rate unit I 00 00 612

6 FRU

Removing and installing or replacing both front brake discs
Flat rate unit I 34 11 613

3 FRU

Brake disc, ventilated

2

Part I 34 11 6 792 219

Repair kit, brake pads asbestos-free
Part I 34 10 6 859 181

1

Brake pad wear sensor, front left
Part I 34 35 6 792 289

1

Clip
Part I 34 10 6 790 927

2

Torx screw with washer
Part I 34 10 6 864 424

5

Brake-pad paste
Part I 83 19 2 158 851

2

Safety cleaner 2.0
Part I 83 19 2 362 037

1

Inner hex bolt
Part I 34 21 1 161 806

2

— Job

Description:

Considered as a repeat visit No

Customer's own words

Oberwäsche und Innenraum aussaugen (ohne Berechnung)
Flat rate unit I 00 11 005

Local

3 FRU

— Job

Description:

Considered as a repeat visit No

Customer's own words

Lackierung: Abschleppkappe Abschleppkappe
Flat rate unit I 99 99 999

Local

1 FRU

— 23/11/2018 Warranty 67382 Km 36850 Job: F10 F11 F25 F26 F31 F34 F36 B47O Replacing exhaust-gas recirculation cooler

— Job: F10 F11 F25 F26 F31 F34 F36 B47O Replacing exhaust-gas recirculation cooler

Description: F10 F11 F25 F26 F31 F34 F36 B47O Replacing exhaust-gas recirculation cooler

Considered as a repeat visit No

Customer's own words

Replace exhaust gas recirculation cooler and clean exhaust gas
recirculation pipe
Flat rate unit I 00 66 769

26 FRU

F10 F11 F25 F26 F31 F34 F36 B47O Replacing exhaust-gas
recirculation cooler
Defect I 00 11 83 04 00exhaust cooler
Part I 11 71 8 477 659

1

Gasket Steel
Part I 11 62 8 576 287

1

Pipe union
Part I 11 71 7 799 853

2

Torx bolt

2

Part I 11 71 2 249 909

Gasket Steel
Part I 11 61 8 508 626

1


O-ring
Part I 11 61 8 512 681

1

— 09/11/2018 Key

66482 Km

Key 1




— 20/07/2018 Key

56928 Km

00088

Key 1




— 20/07/2018 Service

56928 Km

00088

Automatic

Niederlassung
Bremen ,
Bremen

— 20/07/2018 Repair

56928 Km

00088

Niederlassung
Bremen BMW
AG, BremenJob
Job
Job
Job
Job
Job
Job

— Job

Description:

Considered as a repeat visit No

Customer's own words U-Boden beschädigt.,HA-Getriebe li.und re. undicht.,

Service, vehicle check
Flat rate unit I 00 00 624

6 FRU

— Job

Description:

Considered as a repeat visit No

Customer's own words

Motorölservice - zusätzliche AW
Flat rate unit I IM00 25 0

Local

2 FRU

Engine oil service
Flat rate unit I 00 00 610

3 FRU

Set oil-filter element
Part I 11 42 8 575 211

1

BMW Engine Oil LL04 0W30
Part I 83 21 2 405 950

5

— Job

Description:

Considered as a repeat visit No

Customer's own words

Service fuel filter Flat rate unit I 00 00 604	3 FRU
---	-------

Fuel filter cartridge Part I 13 32 8 572 522	1
---	---

— Job

Description:

Considered as a repeat visit No

Customer's own words

Service - air filter element Flat rate unit I 00 00 602	2 FRU
--	-------

Air filter element Part I 13 71 8 511 668	1
--	---

— Job

Description:

Considered as a repeat visit No

Customer's own words

Microfilter service Flat rate unit I 00 00 616	2 FRU
---	-------

Microfilter/activated Carbon container Part I 64 11 9 237 555	1
--	---

— Job

Description:

Considered as a repeat visit No

Customer's own words Standardumfang,

Service - standard scope Flat rate unit I 00 00 105	2 FRU
--	-------

— Job

Description:

Considered as a repeat visit No

Customer's own words

Serviceberatung am Fahrzeug Part I 52050	Local	1
---	-------	---

— Job

Description:

Considered as a repeat visit No

Customer's own words

									
10000	10000	10000	10000	28000	0	15000	10000		0
07/2019	484	484	484		05/2019		07/2019		06/2019

— 03/04/2018 Repair 48038 Km 00088 Job
 Niederlassung
 Bremen BMW
 AG, Bremen Job
 Job

— Job

Description:

Considered as a repeat visit No

Customer's own words

Fahrzeugüberprüfung im Rahmen der Annahm	Local	0 FRU
Flat rate unit I 00 52 054		

— Job

Description:

Considered as a repeat visit No

Customer's own words W-Räder ins Fahrzeug legen,

Rädersatz komplett ummontieren	Local	6 FRU
Flat rate unit I AZ80 00 1		

— Job

Description:

Considered as a repeat visit No

Customer's own words

Performing vehicle test		2 FRU
Flat rate unit I 00 00 556		

— Job

Description:

Considered as a repeat visit No

Customer's own words

Service to check the vehicle prior to expiry of the warranty		4 FRU
Flat rate unit I 00 00 608		

— Job

Description:

Considered as a repeat visit No

Customer's own words

— 03/04/2018 Warranty 48038 Km 00088 Job

— Job

Description:

Considered as a repeat visit No

Customer's own words

Performing vehicle test
Flat rate unit I 00 00 556

0 FRU

Defect I 99 99 01 13 00

10/11/2017

Key

37688 Km

00088

Key 1



21000

07/2019



21000

627



21000

627



21000

627



39000



0

05/2019



26000



21000

07/2019



0

06/2019

10/11/2017

Key

37682 Km

00088

Key 1



21000

07/2019



21000

627



21000

627



21000

627



39000



0

05/2019



26000



21000

07/2019



0

06/2019

10/11/2017	Repair	37688 Km	00088	Job
			Niederlassung	Job
			Bremen BMW	Job
			AG, Bremen	

— Job

Description:

Considered as a repeat visit No

Customer's own words 7% Rabatt auf den Radsatz A.Ünsal.,

Rädersatz komplett ummontieren	Local	6 FRU
Flat rate unit I AZ80 00 1		

RDCi wheel with tyre, winter Ferricgrey	4
Part I 36 11 2 456 814	

— Job

Description:

Considered as a repeat visit No

Customer's own words

Ersteinlagerungsgebühr Saison-Radsatz	Local	1
Part I 0099442		

— Job

Description:

Considered as a repeat visit No

Customer's own words

09/10/2017			Key		35135 Km		36850		Key 1	
										
24000	24000		24000		24000	40000	0	28000	24000	0
07/2019	660		660		660		05/2019		07/2019	06/2019

09/10/2017	Warranty	35140 Km	36850	Job: F1x F2x F3x B47 programming control units and if necessary, replacing the EGR valve
------------	----------	----------	-------	--

- Job: F1x F2x F3x B47 programming control units and if necessary, replacing the EGR valve

Description: F1x F2x F3x B47 programming control units and if necessary, replacing the EGR valve

Considered as a repeat visit No

Customer's own words

Carrying out the ABL and programming the control units Flat rate unit I 00 64 941	8 FRU
--	-------

F1x F2x F3x B47 programming control units and if necessary, replacing the EGR valve Defect I 00 11 45 04 00
--

- 14/08/2017 Repair 28596 Km 00088 Job
Niederlassung
Bremen BMW
AG, Bremen

- Job

Description:

Considered as a repeat visit No

Customer's own words Teile am Fzg fehlten nach Werkstattaufenthalt, zu Lasten Service,

Kappe Abschleppöse lackieren Flat rate unit I AZ41 99 0	Local	2 FRU
--	-------	-------

Flap, towing eye, primed Part I 51 11 8 061 005	1
--	---

Plug Part I 07 14 7 255 351	1
--------------------------------	---

- 10/08/2017 Warranty 28596 Km 00088 Job: EGR cooler (incl. bypass flap) / exhaust cooler
Job: Oxygen monitor sensor

- Job: EGR cooler (incl. bypass flap) / exhaust cooler

Description: EGR cooler (incl. bypass flap) / exhaust cooler

Considered as a repeat visit No

Customer's own words

EGR cooler (incl. bypass flap) / exhaust cooler Defect I 11 71 06 48 99
--

Torx bolt Part I 11 71 2 249 909	2
-------------------------------------	---

- Job: Oxygen monitor sensor

Description: Oxygen monitor sensor

Considered as a repeat visit No

Customer's own words

Oxygen monitor sensor Defect I 11 78 03 15 00
--

Oxygen sensor Part I 13 62 8 589 104	1
---	---

- 10/08/2017 Warranty 28596 Km 00088 Job: EGR cooler (incl. bypass flap) / exhaust cooler
Job: Oxygen monitor sensor

— Job: EGR cooler (incl. bypass flap) / exhaust cooler

Description: EGR cooler (incl. bypass flap) / exhaust cooler**Considered as a repeat visit** No**Customer's own words**

Performing vehicle test Flat rate unit I 00 00 006	4 FRU
Removing and installing or replacing EGR cooler Flat rate unit I 11 71 600	23 FRU
Check the cooling system for watertightness with the special tool Flat rate unit I 17 00 509	2 FRU
EGR cooler (incl. bypass flap) / exhaust cooler Defect I 11 71 06 48 99	
Gasket Steel Part I 11 61 8 571 005	1
Pipe union Part I 11 71 7 799 853	2
Torx bolt Part I 11 71 2 249 909	2
Exhaust gas radiator high temperature Part I 11 71 8 513 691	1
Gasket Steel Part I 11 62 8 576 287	1
Cable tie Part I 61 13 1 367 599	2

— Job: Oxygen monitor sensor

Description: Oxygen monitor sensor**Considered as a repeat visit** No**Customer's own words**

Replacing the monitoring oxygen sensor Flat rate unit I 13 62 664	4 FRU
Oxygen monitor sensor Defect I 11 78 03 15 00	
Oxygen sensor Part I 13 62 8 589 104	1

— Job: EGR cooler (incl. bypass flap) / exhaust cooler

Description: EGR cooler (incl. bypass flap) / exhaust cooler**Considered as a repeat visit** No**Customer's own words**

EGR cooler (incl. bypass flap) / exhaust cooler Defect I 11 71 06 48 98	
--	--

— 07/08/2017 Key 28596 Km 00088 Key 1

									
30000	30000	30000	30000	36000	0	26000	30000		0
07/2019	722	722	722		05/2019		07/2019		06/2019

— 07/08/2017 Repair 28596 Km 00088 Job
Niederlassung Job
Bremen BMW Job
AG, Bremen Job
Job

— Job

Description:

Considered as a repeat visit No

Customer's own words Fahrzeugtest durchführen<(><)> laut testmodul lambdasonde,defeckt-ersetzen<(><)> agr kühler wegen wasserverlust <(><)>,checkc.meldungen wasserstand zu niedrig küchlsystem geprüft keine,undicht.nach aussen,Bartels,,Kühlwasserverlust. Das Fzg wurde am 21.07.17 ausgeliefert. Kunde musste,bereits 5mal Kühlwasser nachfüllen. Es ist äußerlich nichts,festzustellen Fahrzeugtest durchführen<(><)> laut testmodul lambdasonde,defeckt-ersetzen (Erst in der Werkstatt festgestellt.<(><)> agr kühler,wegen wasserverlust innen ersetzt <(><)> checkc.meldungen wasserstand,zu niedrig küchlsystem geprüft keine undicht .nach aussen,

Performing vehicle test 4 FRU
Flat rate unit I 00 00 006

Removing and installing or replacing EGR cooler 23 FRU
Flat rate unit I 11 71 600

Check the cooling system for watertightness with the special tool 2 FRU
Flat rate unit I 17 00 509

Gasket Steel 1
Part I 11 61 8 571 005

Pipe union 2
Part I 11 71 7 799 853

Torx bolt 2
Part I 11 71 2 249 909

Exhaust gas radiator high temperature 1
Part I 11 71 8 513 691

Anti-freeze 3
Part I 83 19 2 218 347

Gasket Steel 1
Part I 11 62 8 576 287

Cable tie 2
Part I 61 13 1 367 599

— Job

Description:

Considered as a repeat visit No

Customer's own words

Fahrzeugüberprüfung im Rahmen der Annahm Local 0 FRU
Flat rate unit I 00 52 054

— Job

Description:

Considered as a repeat visit No

Customer's own words

Schnellinnenrg.+Oberw. *Serviceleistung*
Part I 0011315

Local

1

— Job

Description:

Considered as a repeat visit No

Customer's own words

Replacing the monitoring oxygen sensor
Flat rate unit I 13 62 664

4 FRU

Oxygen sensor
Part I 13 62 8 589 104

1

— Job

Description:

Considered as a repeat visit No

Customer's own words

Ersatzfahrzeug (24 Stunden)
Part I 0000160

Local


5

— 21/07/2017 Service

27611 Km

00088
Niederlassung
Bremen,
Bremen

Manual











— 20/07/2017 Key

27632 Km

00088

Key 0



— 27/06/2017 Repair

27611 Km

00088
Niederlassung
Bremen BMW
AG, Bremen

Job
Job
Job
Job
Job
Job
Job
Job
Job
Job
Job

— Job

Description:

Considered as a repeat visit No

Customer's own words

Aufbereitung Gebrauchte Automobile Arwe

Local

1

Part I 0099366

— Job

Description:

Considered as a repeat visit No

Customer's own words Achtung-Achtung-Achtung!!!!!!!,Unfallschaden beheben lt.Gutachten!!!!,Festpreis 2200-
 #,Abrechnung über GA.Gemeinkosten!!!!!!!,,Ab-/Aufrüstarbeiten Seitenwand vore rechts,Ab- und
 Aufrüstarbeiten der Tür
 vorn li nks oder rechts für lackieren,Ab- und Aufrüstarbeiten der Seiten- wand hinten rechts
 lackieren,Ziergitter in Stoßfängerverkleidung vorn aus- und einbauen/
 ersetzen,Nebelscheinwerfer links a
 us- und einbauen,Nebelscheinwerfer rechts aus- und einbauen,Scheinwerfer rechts aus- und
 einbauen,Frontziergitter-Mitte links oder rechts aus- und einbauen/ersetzen,Frontziergitter-Mitte
 links oder re
 chts aus- und einbauen/ersetzen,Abdeckung- Radhaus hinten links oder rechts ab- und
 anbauen/ ersetzen,Seitenwand hinten rechts instandsetzen,Hohlraumkonservierung für
 Seitenwand hin ten links oder rec
 hts,Außengriff vorne rechts lackieren,

Ab-/Aufrüstarbeiten Seitenwand vore rech Flat rate unit AZ41 99 0	Local	5 FRU
Ab- und Aufrüstarbeiten der Tür vorn li Flat rate unit AZ41 99 0	Local	9 FRU
Ab- und Aufrüstarbeiten der Seiten- wand Flat rate unit AZ41 99 0	Local	2 FRU
Ziergitter in Stoßfängerverkleidung vorn Flat rate unit AZ41 99 0	Local	3 FRU
Kennzeichen vorn ab- anbauen Flat rate unit AZ41 99 0	Local	1 FRU
Nebelscheinwerfer links aus- und einbaue Flat rate unit AZ41 99 0	Local	2 FRU
Nebelscheinwerfer rechts aus- und einbau Flat rate unit AZ41 99 0	Local	2 FRU
Scheinwerfer rechts aus- und einbauen Flat rate unit AZ41 99 0	Local	5 FRU
Frontziergitter-Mitte links oder rechts Flat rate unit AZ41 99 0	Local	1 FRU
Frontziergitter-Mitte links oder rechts Flat rate unit AZ41 99 0	Local	1 FRU
Abdeckung- Radhaus hinten links oder rec Flat rate unit AZ41 99 0	Local	3 FRU
Abdecktopf ersetzen Flat rate unit AZ41 99 0	Local	4 FRU
Vorder- oder Hinterrad ab- und anbauen Flat rate unit AZ41 99 0	Local	1 FRU
Vorder- oder Hinterrad ab- und anbauen Flat rate unit AZ41 99 0	Local	1 FRU
Fehlerspeicher auslesen Flat rate unit AZ41 99 0	Local	4 FRU
Tür vorne rechts instandsetzen Flat rate unit AZ41 99 0	Local	6 FRU
Tür hinten rechts instandsetzen Flat rate unit AZ41 99 0	Local	6 FRU
Seitenwand hinten rechts instandsetzen	Local	36 FRU

Flat rate unit | AZ41 99 0

Hohlraumkonservierung für Seitenwand hin Flat rate unit AZ41 99 0	Local	5 FRU
Seitenwand vorne rechts instandsetzen Flat rate unit AZ41 99 0	Local	20 FRU
Außengriff vorne rechts lackieren Flat rate unit AZ41 99 0	Local	3 FRU
Carry out Kinematics Diagnosis System wheel alignment with vehicle load up to design position Flat rate unit 32 00 150		17 FRU
Adjusting rear axle and front axle Flat rate unit 32 00 630		11 FRU
Stripping and refitting work for painting the rear left or right doors Flat rate unit 51 18 850		3 FRU
Removing and installing front bumper panel Flat rate unit 51 11 656		9 FRU
Additional work: headlight washer system Flat rate unit 61 67 805		1 FRU
Removing and installing ornamental grille in front bumper panel Flat rate unit 51 11 683		1 FRU
Removing and installing ornamental grille in front bumper panel Flat rate unit 51 11 683		1 FRU
Removing and installing/replacing one ultrasonic sensor at the front Flat rate unit 66 20 522		1 FRU
Removing and installing/replacing one ultrasonic sensor at the front Flat rate unit 66 20 522		1 FRU
Replacing front BMW badge Flat rate unit 51 14 501		1 FRU
Replacing left or right rear side window Flat rate unit 51 36 571		14 FRU
Removing and installing rear bumper panel Flat rate unit 51 12 656		4 FRU
Removing and installing/replacing one ultrasonic sensor at the rear Flat rate unit 66 20 542		1 FRU
Removing and installing the rear bumper lower trim Flat rate unit 51 12 662		2 FRU
Removing and installing/replacing rear left or right bumper guide Flat rate unit 51 12 828		2 FRU
Removing and installing left or right roof trim strip Flat rate unit 51 13 780		1 FRU
Replacing a tyre with run-flat technology Flat rate unit 36 12 506		6 FRU
Initialising tyre failure indicator Flat rate unit 36 11 500		1 FRU
Painting front bumper panel Flat rate unit 99 68 539		24 FRU
Painting left or right front side panel Flat rate unit 99 35 529		13 FRU
Painting left or right front door Flat rate unit 99 51 558		28 FRU

Painting left or right rear door	22 FRU
Flat rate unit 99 52 558	

Painting rear bumper panel	26 FRU
Flat rate unit 99 69 539	

Painting left or right rear side panel	45 FRU
Flat rate unit 99 36 013	

Lackmaterial	Local	829
Part 99 99 9 999 990		

Channel cover, exterior, door, front right	1
Part 51 35 7 310 206	

Channel cover, outer, door, rear right	1
Part 51 35 7 332 520	

Joint seal, B-pillar, right	1
Part 51 76 7 326 508	

Emblem	1
Part 51 14 8 058 881	

— Job

Description:

Considered as a repeat visit No

Customer's own words

Replacing windshield	24 FRU
Flat rate unit 51 31 011	

Plak.4 Gruen	Local	1
Part 99 99 0 000 012		

Green windscreen	1
Part 51 31 7 285 900	

Cover, windshield, top	1
Part 51 31 7 285 915	

Drip moulding, left	1
Part 51 31 7 285 927	

Drip moulding, right	1
Part 51 31 7 285 928	

Clip, drip moulding	4
Part 51 13 7 258 183	

Clip, drip moulding	6
Part 51 13 7 321 818	

Bump stop	12
Part 51 31 7 288 462	

Repair kit, window glass, cold, 1 hour	1
Part 83 19 2 289 285	

Adhesive primer VP 206	1
Part 83 19 9 407 777	

Sound insulation f apron	1
Part 51 48 8 238 934	

Plug	1
Part 07 14 7 255 351	

— Job

Description:

Considered as a repeat visit No

Customer's own words Festpreis,Lack lt. Angabe Lange!!,Festpreis 250-#+50%,Motorhaube lack,Festpreis höher als normaler Betrag,

Painting engine hood	43 FRU
Flat rate unit I 99 61 539	

— Job

Description:

Considered as a repeat visit No

Customer's own words

Fremdleistungen Fa.Weinberg Fa.Weinberg	Local	1
Part I 0000154		

— Job

Description:

Considered as a repeat visit No

Customer's own words

— Job

Description:

Considered as a repeat visit No

Customer's own words

— Job

Description:

Considered as a repeat visit No

Customer's own words

Premium Selection Gebrauchte Automobile	Local	15 FRU
Flat rate unit I AZ00 03 6		

— Job

Description:

Considered as a repeat visit No

Customer's own words

Motorölservice - zusätzliche AW	Local	2 FRU
Flat rate unit I IM00 25 0		

Engine oil service	3 FRU
Flat rate unit I 00 00 610	

Set oil-filter element	1
Part I 11 42 8 575 211	

BMW Engine Oil LL04 0W30	5
Part I 83 21 2 405 950	

— Job

Description:

Considered as a repeat visit No

Customer's own words

Microfilter service	2 FRU
Flat rate unit I 00 00 616	

Microfilter/activated Carbon container
Part I 64 11 9 237 555

1

— Job

Description:

Considered as a repeat visit No

Customer's own words

Warnweste gelb
Part I 99 99 9 920 471

Local

1

BMW key ring Square
Part I 80 56 0 443 278

1

— Job

Description:

Considered as a repeat visit No

Customer's own words

Plug
Part I 07 14 7 255 351

1

Plaque
Part I 51 76 7 288 752


1

— 20/06/2017 Key

27611 Km

00088

Key 0




— 18/01/2017 Key

13322 Km

00088

Key 1




— 18/01/2017 Key

13321 Km

00088

Key 1



— 18/01/2017 Repair

13322 Km

00088

Niederlassung
Bremen BMW
AG, Bremen

Job

Job

Job

— Job

Description:

Considered as a repeat visit No

Customer's own words

— Job

Description:

Considered as a repeat visit No

Customer's own words

Auslieferungsdurchsicht Flat rate unit I AZ00 03 3	Local	3 FRU
Performing vehicle test Flat rate unit I 00 00 006		4 FRU
Windshield washer antifreeze Part I 83 12 2 298 528		2

— Job

Description:

Considered as a repeat visit No

Customer's own words Winterräder montieren,Sommerräder ins Lager Poolreihe (Stempel / Unterschrift),

Removing and installing front and rear wheels Flat rate unit I 36 10 360		6 FRU
RDCi wheel with tyre, winter Ferricgrey Part I 36 11 2 289 747		4