



Activate your new vouchers that might be used on this car



BMW 5er 530e M Sport



VAT deductible (21%)

Stock number:	NB33958
Build year:	2018
First registration:	08/2018
Odometer reading:	179,270 km
Fuel type:	Hybrid
Horsepower:	135 kW / 185 HP
Cylinder capacity:	1,998 ccm
Gear box:	Automatic
Inspection expires:	06/2026
Body type:	Sedan
Total number of owners:	2
Keys:	2
Prior damage / Accident according to previous owner	Yes
Country of origin:	DE
Country of last registration:	BE
Environmental class:	EURO 6d-TEMP
COC papers:	No
Seats:	5
Color:	Gray (Original)
Upholstery:	Alcantara (Original)
Door count:	4





Car location

-





0:00 / 0:14






MAIN CAR DETAILS


CAR HIGHLIGHTS / ADDITIONAL PHOTOS



Engine




General



General



General



General

OTHER NOTES

Registration papers are perforated and they expire on 16.08.25
Registration outside Belgium cannot be guaranteed

TEST DRIVE INFORMATION

TEST DRIVE LOCATION: ON PUBLIC STREET < 80KM/H (LOWER SPEED)

NO SPECIFIC FINDINGS

VEHICLE CONDITION

1 area with sign of previous accident

Repair status: Repaired

Repaired by: Unknown


Repair cost: Unknown

Repair document not available

5 damaged areas

2 repainted panels

Exterior



Interior

Wheels

Underbody

Engine and drive system



Damages

Panel	Damage	Severity	Description	Quantity	
<u>Front bumper</u>	Scratch	Length: ≥100mm	Deep scratch - down to primer	1	1
<u>Windscreen</u>	Stone chip	Width: ≤3mm	Not in driver's eyeline	3	0
<u>Hood</u>	Repaint	Thickness: ≥250µm & <500µm	Professional repaint	1	0

DAMAGE SUMMARY

The results of this car’s evaluation are summarised in the DAMAGE SUMMARY table and visualised in the DAMAGE AREAS section below.

Damage / Part	Severity
1 REPAINT Rear right fender (1)	Thickness: ≥500µm , Professional repaint
1 REPAINT Hood (1)	Thickness: ≥250µm & <500µm , Professional repaint
3 SCRATCHES Front bumper (1) Rear bumper (2)	Length: ≥100mm , Deep scratch - down to primer
1 SCRATCH Rear right fender (1)	Length: ≥50mm & <100mm , Surface scratch
7 SCRATCHES Front left rim (2) Rear left rim (1) Rear right rim (2) Front right rim (2)	Length: ≥25mm , Deep scratch
3 SCRATCHES Rear left door (1) Rear right door (2)	Length: ≥20mm & <50mm , Deep scratch - down to primer
1 STONE CHIP Front left fender (1)	Width: ≤3mm , Paint damage
3 STONE CHIPS Windscreen (3)	Width: ≤3mm , Not in driver's eyeline
1 WORN OUT Steering Wheel (1)	

CAR EQUIPMENT

Some content has been automatically translated.

 Heated seats	Front seat heating Front seat heating
 Seat settings	Partially electrically adjustable front seats
 Sunroof	Electric sliding/tilting sunroof (glass)
 Park Distance Control	Rearview camera Park-Distance-Control (PDC) front and rear Rearview camera
 Power steering	Power steering Servotronic
 Hands-free system	Bluetooth hands-free system with USB audio interface Voice processor system
 Sport seats	Sports seats in front
 Navigation System	ConnectedDrive navigation package Professional audio-navigation system
 Airbag	Disconnectable passenger airbag Driver side airbag / passenger side airbag Driver's knee airbag Rear Cranial Airbag System Front head airbag system Front side airbag
 AC System	Automatic climate control 2 zones with automatic air recirculation control, extended range
 Power windows	Electric windows front + rear
 ESP	Dynamic Stability Control (DSC)
 Immobilizer	Immobilizer
 Cruise Control	Cruise control, Active with Stop&Go function

✓ On-board computer	On-board computer
✓ Theft alarm system / security alarm	Alarm system Alarm system
✓ Entertainment system	In navigation system
✓ ABS	Anti-lock Braking System (ABS)

CAR SERVICE DETAILS

Service book details:	Digital service book
Service appointment:	Some
Last service on:	11/27/2024
Last service Mileage:	172,201 km
Drive belt change on:	-
Drive belt change Mileage:	-


Car service images 2 images available



TECHNICAL INSPECTION

Date of latest technical inspection:	06/10/2025
Mileage at latest technical inspection:	178,276 km

Technical inspection images 1 image



ELECTRIC CAR DETAILS

Fuel type:
Hybrid

Battery leased:
No

Is charging cable available:
No

CAR DATA ACCORDING TO IDENTIFICATION NUMBER (VIN)

Some content has been automatically translated.

- ☒ Driving assistance system: active Lane departure warning
- ☒ Driver Assistance System: Front collision warning with brake function
- ☒ Driving Assistant: Lane Change Control
- ☒ Driving assistance system: lane departure warning system
- ☒ Driving assistance system: lane departure warning system
- ☒ Driver Assistance System: Attention Assistant
- ☒ Driving Assistance System: Driving Assistant Plus
- ☒ Driving Assistance System: Driving Assistant
- ☒ Automatic headlight range control
- ☒ Security system Active Protection

