

Vehicle

BMW 520d, 140kW

WBA5L31070D677744



Development code	F11
Color	black-sapphire metallic
Actual integration level	F010-23-07-530
Start of warranty	August 13, 2014

▼ Technical Campaigns

There are no campaigns available.

▼ Special information

There are no campaigns available.

▼ Live Diagnosis

 There are no service solutions for Live Diagnosis.

▼ Service contracts

No BSI contracts available

You can find additional service contract information and selection options in the DCSNet warranty vehicle enquiry.

▼ Information on faults, workshop/Service Consultation

No information on faults is available.

▼ Navigation map

Installed map	Enabling code (subscription)	Latest navigation map included in subscription	Latest navigation map subject to charge
Road Map EUROPE WEST Next 2020-2 (as of: Jun 3, 2024)	Release code valid for navigation maps with release date up to Dec 31, 2025 (SWID: 00A9008F).	Road Map EUROPE WEST Next 2025	-

▼ Vehicle details

Vehicle type	Passenger car
--------------	---------------

Brand	BMW
Model	520d
Body	TOUR
Vehicle identification number (last 7 characters)	D677744
Vehicle identification number (17 characters)	WBA5L31070D677744
Development code	F11
Steering	LL
Engine	B47O
Engine number	90928967
Exhaust re-treatment	EURO6;W;PI/CI; M, N1 I
Transmission	AUT
Transmission number	0004679XAB
Head unit serial number	HB2067E7915328
Drive	HECK
Integration level	F010-14-07-503
Production date	Jul 29, 2014
Production works	Dingolfing
Delivery date	Aug 26, 2014
Delivering Retailers	No information
National-market version	EUR
Paint code	475
Upholstery code	LCSW
Model code	5L41
Base type	5L31
Lead type	5L41

▾ Optional equipment

Optional equipment fitted at the factory:

01CA Selection of COP relevant vehicles
 01CB CO2 package
 01CC Auto start/stop function
 01CD Brake Energy Regeneration
 0230 EU-specific additional contents
 0258 Tire with run-flat functionality
 02D3 BMW LA wheel, Star Spoke 365
 02TE Automatic transmission w/ shift paddles
 02VB Tire pressure display
 0302 Alarm system
 0316 automatic trunk lid mechanism

Retrofitted optional equipment:

This vehicle has no retrofits.

0322 Comfort access
0386 Roof railing
03AC Trailer coupling
03AG Reversing camera
0402 Electric panoramic roof
0418 Luggage compartment package
0423 Floor mats, velours
0428 Warning triangle and first aid kit
0430 Interior/outside mirror with auto dip
0431 Interior mirror with automatic-dip
0459 Seat adjuster, electric, with memory
0488 Lumbar support, driver and passenger
0494 Seat heating driver/passenger
04BN Fine-wood trim ash grain
04U2 Driving experience switch incl. ECO PRO
04UR Ambient interior lighting
0502 Headlight cleaning system
0508 Park Distance Control (PDC)
0524 Adaptive Headlights
0534 Automatic air conditioning
0548 Kilometer-calibrated speedometer
0575 Supplementary 12V sockets
05A1 LED Fog lights
05AC High-beam assistant
05AG Lane-change warning
05AL Active Protection
05AR Traffic congestion assistant
05AT Driving Assistant Plus
0609 Navigation system Professional
0610 Head-up display
0654 DAB tuner (DAB-enabled)
0688 Harman/Kardon Surround Sound system
0698 Area-Code 2 for DVD
06AC Intelligent emergency SOS call
06AE Teleservices
06AK Connected Drive Services
06AM Real-Time Traffic Information
06AN Concierge Services
06AP Remote Services
06FV Online Entertainment
06NS Convenience phone, expanded Smartphone
06WA Instrument cluster, expanded equipment
0710 M leather steering wheel
0760 High gloss shadow line
07A2 Innovation Package II
07RS Package Comfort
07XP Navigation package, Connected Drive
0801 German version
0851 Language version German
0879 On-board vehicle literature German
08KA Oil service interval, 24 mos./30,000 km
08TF Active pedestrian protection
08TH Road sign detection
09AA Outer skin protection
A105 105 AH AGM battery
LEDE Leather trim

▾ Vehicle histories

	Date	Type	Vehicle mileage	Dealer	Overview
—	06/17/2026	Service	243605 km	OSS-50028640 Auto-Tauber GmbH, Obermichelbach	Automatic

													
1900			1900			31000	06/2027	06/2027	140000	1900		06/2027	
✓			✓							✓			

— 06/12/2025 Service 216228 km OSS-50028640 Manual
Auto-Tauber GmbH,
Obermichelbach

													
✓	✓		✓		✓	✓	✓	✓	✓		✓	✓	✓

— 06/03/2024 Key 196260 km 02356 Key 0

												
20000	20000		20000		20000	19000			100000	45000		
01/2026	01/2026		01/2026		01/2026		01/2026			01/2028		06/2025

— 04/04/2024 Key 193146 km 02356 Remote KeyRead

												
24000	24000		24000		24000	20000			100000	49000		
01/2026	01/2026		01/2026		01/2026		01/2026			01/2028		06/2025


— 01/11/2024 Service 191732 km OSS-50028640 Manual
Auto-Tauber GmbH,
Obermichelbach

													
✓			✓						✓				

— 06/22/2023 Service 184112 km OSS-50028640 Manual
Auto-Tauber GmbH,
Obermichelbach

													
									✓			✓	✓

— 01/28/2022 Service 167964 km OSS-50028640 Manual
Auto-Tauber GmbH,
Obermichelbach



— 10/29/2021 Service 165803 km OSS-50028640 Manual
Auto-Tauber GmbH,
Obermichelbach



— 04/19/2021 Key 159140 km Key 0

22000	22000	22000	22000	26000	0	170000	60000	0
01/2022	286	286	286		11/2021		1016	11/2021

— 04/19/2021 Key 159082 km Key 0

22000	22000	22000	22000	26000	0	170000	60000	0
01/2022	288	288	288		11/2021		1018	11/2021

— 04/19/2021 Repair 159140 km 29428 B&K GmbH , Bad
Homburg v.d.H.

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Kunde beanstandet: Flat rate unit I KB	Local	1 FRU
Safety First Check inkl. Fehlerspeicher Flat rate unit I 00 99 111	Local	7 FRU
Lin BUS Kommunikationsfehler Flat rate unit I 99 99 999	Local	1 FRU
Kabelbaum/Fußraummodul geprüft Flat rate unit I 99 99 999	Local	1 FRU
best. für ML1 am 21.4. T.Vieweg Flat rate unit I 99 99 999	Local	1 FRU
Supporting the voltage of the vehicle electrical system/recharging the vehicle electrical system battery Flat rate unit I 61 21 528		1 FRU

Work time without specification/engine Flat rate unit I 11 99 000	4 FRU
Removing and installing rear bumper panel Flat rate unit I 51 12 656	7 FRU
Additional work with Park Distance Control Flat rate unit I 66 20 600	1 FRU
Replacing FRM Flat rate unit I 61 35 616	7 FRU
Program/encode control unit(s), includes deleting the fault memory Flat rate unit I 61 00 730	4 FRU
Initializing more than one system Flat rate unit I 61 00 832	2 FRU
Troubleshooting in the electrical/electronic system Flat rate unit I 61 00 009	12 FRU
Removing and installing driver assistance system control element Flat rate unit I 61 31 538	2 FRU
Removing and installing/replacing the light operating unit Flat rate unit I 61 31 537	2 FRU
Footwell module Part I 61 35 6 992 947	1

—	03/05/2020	Key	152877 km	29428	Key 0				
 28000 01/2022	 28000 697	 28000 697	 28000 697	 32000	 0 11/2021	 160000	 -3000 -34 4.7 %	 0 11/2021	
—	03/05/2020	Service	152877 km	29428 B&K GmbH & Co. KG, Bad Homburg v.d.H.	Manual				
									
—	03/05/2020	Repair	152877 km	29428 B&K GmbH , Bad Homburg v.d.H.	Job Job Job Job				
—	Job								

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Standard scope of service Flat rate unit I 00 00 105	2 FRU
---	-------

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Vehicle check service	7 FRU
Flat rate unit I 00 00 624	

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Servicewäsche Oberwäsche maschinell,	Local	1 FRU
Flat rate unit I WS1		

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Während des Werkstattaufenthalts	Local	1 FRU
Flat rate unit I MÄ		

sind uns folgende Mängel an	Local	1 FRU
Flat rate unit I MÄ		

Ihrem Fahrzeug aufgefallen:	Local	1 FRU
Flat rate unit I MÄ		

-Verbandkasten abgelaufen	Local	1 FRU
Flat rate unit I 99 99 999		

—	11/20/2019	Repair	143413 km	29428 B&K GmbH , Bad Homburg v.d.H.	Job Job Job Job Job
---	------------	--------	-----------	---	---------------------------------

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Service Beratung am Fahrzeug ohne Kunde	Local	1 FRU
Flat rate unit I 00 52 053		

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Standard scope of service	2 FRU
---------------------------	-------

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Brake fluid service	4 FRU
Flat rate unit I 00 00 618	

BR.REINIGER	Local	0.5
Part I 99 99 0 000 064		

Brake fluid DOT4 LV, low viscosity	1
Part I 83 13 0 443 026	

Gas spring front flap, active	2
Part I 51 23 7 309 117	

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Prüfgebühren	Local	1 FRU
Flat rate unit I 99 99 999		

Demonstration for state emissions inspection	7 FRU
Flat rate unit I 00 00 127	

— Job


Description:

Is interpreted as a repeat visit: No

Customer's own words:

Servicewäsche Oberwäsche maschinell,	Local	1 FRU
Flat rate unit I WS1		

11/19/2019	Key	143413 km	29428	Key 0
------------	-----	-----------	-------	-------



11/19/2019	Service	143413 km	29428 B&K GmbH & Co. KG, Bad Homburg v.d.H.	Manual
------------	---------	-----------	--	--------



—	09/06/2018	Key	120189 km	Key 0					
									
-2100	-2100	-2100	-2100	70000	0	120000	28000	0	
03/2019	206	206	206		10/2019		03/2021	10/2019	
—	09/06/2018	Service	120189 km	29428 B&K GmbH & Co. KG, Bad Homburg	Automatic				
									
-2100	-2100	-2100	-2100	70000	10/2019	120000	28000	10/2019	
✓	✓	✓	✓						
—	10/02/2017	Key	102736 km	29428	Key 0				
									
17000	17000	17000	17000	90000	0	100000	47000	0	
03/2019	545	545	545		-63 8.6 %		03/2021	-32 4.4 %	
—	10/02/2017	Service	102736 km	29428 B&K GmbH & Co. KG, Bad Homburg	Automatic				
									
17000	17000	17000	17000	90000	07/2017	100000	47000	08/2017	
					✓			✓	
—	10/02/2017	Repair	102736 km	29428 B&K GmbH, Bad Homburg v.d.H.	Job Job Job Job Job				

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Standard scope of service
Flat rate unit I 00 00 105

2 FRU

Standard scope of service
Flat rate unit I 00 00 105

0 FRU

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Brake fluid service Flat rate unit I 00 00 618		4 FRU
BR.REINIGER Part I 99 99 0 000 064	Local	0.5
Brake fluid DOT4 LV, low viscosity Part I 83 13 0 443 026		1

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

§ emission test with on-board diagnosis Flat rate unit I 00 00 528		1 FRU
---	--	-------

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Prüfgebühren Flat rate unit I 99 99 999	Local	1 FRU
--	-------	-------

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

12-Punkte-Check Flat rate unit I 00 99 270	Local	6 FRU
---	-------	-------

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Licht-Test Flat rate unit I 00 12 290	Local	3 FRU
--	-------	-------

—	10/02/2017	Repair	102736 km	29428 B&K GmbH , Bad Homburg v.d.H.	Job
---	------------	--------	-----------	---	-----

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

12-Punkte-Check	Local	6 FRU
-----------------	-------	-------

—	03/13/2017	Key	88814 km	29428	Key 0
---	------------	-----	----------	-------	-------

 -8000 12/2017	 0	 -8000 293	 0	 5000	 0 07/2017	 2600	 -8000 12/2017	 0 08/2017
---	--	---	--	---	---	---	--	---

—	03/13/2017	Service	88814 km	29428 B&K GmbH & Co. KG, Bad Homburg	Automatic
---	------------	---------	----------	--------------------------------------	-----------

 -8000 ✓	 0	 -8000 ✓	 0	 5000 ✓	 0 07/2017	 2600 ✓	 -8000 ✓	 0 08/2017
---	--	---	--	--	---	--	--	---

—	03/13/2017	Repair	88814 km	29428 B&K GmbH , Bad Homburg v.d.H.	Job Job Job Job Job Job Job Job Job
---	------------	--------	----------	-------------------------------------	---

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Standard scope of service Flat rate unit I 00 00 105	2 FRU
---	-------

Standard scope of service Flat rate unit I 00 00 105	0 FRU
---	-------

SCHEIBENKLAR Part I 99 99 9 407 408	Local	2
--	-------	---

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Service - microfilter Flat rate unit I 00 00 616	3 FRU
---	-------

DESINFEKTION Part I 08 93 7 641 0	Local	1
--------------------------------------	-------	---

Set, microfilter/activ. charcoal filter Part I 64 11 9 272 642	1
---	---

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Service - front brakes	7 FRU
Flat rate unit I 00 00 612	

Removing and installing/replacing both front brake discs	3 FRU
Flat rate unit I 34 11 613	

BR.REINIGER	Local	1
Part I 99 99 0 000 064		

Brake pad paste	2
Part I 83 19 2 158 851	

Repair kit, brake pads asbestos-free	1
Part I 34 11 6 858 047	

Brake pad wear sensor, front left	1
Part I 34 35 6 791 958	

Brake disc, lightweight, ventilated	2
Part I 34 11 6 794 429	

Inner hex bolt	2
Part I 34 21 1 161 806	

Hex bolt	4
Part I 34 11 6 772 117	

Brake pad wear sensor	1
Part I 34 35 6 789 440	

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Rear brakes service	8 FRU
Flat rate unit I 00 00 614	

Removing and installing/renewing both brake discs	2 FRU
Flat rate unit I 34 21 932	

BR.REINIGER	Local	1
Part I 99 99 0 000 064		

Repair kit, brake pads asbestos-free	1
Part I 34 21 6 862 202	

Brake pad paste	2
Part I 83 19 2 158 851	

Brake pad wear sensor, rear	1
Part I 34 35 6 791 963	

Brake disc, lightweight, ventilated	2
Part I 34 21 6 775 287	

Inner hex bolt	2
----------------	---

Hex bolt	4
Part I 34 11 6 772 117	

Glow plug	1
Part I 12 23 0 035 934	

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Vehicle check service	7 FRU
Flat rate unit I 00 00 624	

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Engine oil service	3 FRU
Flat rate unit I 00 00 610	

Engine oil service	0 FRU
Flat rate unit I 00 00 610	

CASTROL EDGE 0W30	Local	5
Part I 99 99 9 999 100		

Set oil-filter element	1
Part I 11 42 8 575 211	

Screw plug	1
Part I 11 13 7 535 106	

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Angelieferte Sommerräder montieren Winterräder ins Fzg. legen	Local	7 FRU
Flat rate unit I R3S		

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Replacing four tires with run-flat technology	24 FRU
Flat rate unit I 36 12 577	

GEWICHTE	Local	8
Part I 99 99 0 000 090		

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

anlage ersetzen Flat rate unit I 99 99 999	Local	1 FRU
Work time without specification / vehicle electrical system Flat rate unit I 61 99 000		0 FRU
Cover f filler pipe Part I 61 66 7 238 068		1

— 03/13/2017 Repair 88814 km 29428 B&K GmbH , Bad Homburg v.d.H. Job

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

12-Punkte-Check Flat rate unit I 00 99 270	Local	6 FRU
---	-------	-------

— 02/05/2017 Repair 83454 km 26842 BMW Mobiler Service Einsatzleitzentrale , München Job

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

— 06/22/2016 Key 65771 km 29428 Key 0

 15000 12/2017	 0	 15000 556	 0	 5000	 0 07/2017	 23000	 15000 12/2017	 0 08/2017
---	--	---	--	---	---	--	--	---

— 06/13/2016 Key 64988 km 29428 Key 0

 15000 12/2017	 0	 15000 566	 0	 5000	 0 07/2017	 23000	 15000 12/2017	 0 08/2017
---	--	---	--	---	---	--	--	---

— 06/13/2016 Repair 64988 km 29428 B&K GmbH , Bad Homburg v.d.H. Job

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Garantiedurchsicht

Flat rate unit I 00 99 001

Local









4 FRU

— 12/29/2015 Key

50493 km

29428

Key 0



— 12/29/2015 Service

50493 km

29428 B & K
GmbH & Co.
KG, Bad
Homburg v.d.H.

Manual



— 12/29/2015 Repair

50493 km

29428 B&K
GmbH , Bad
Homburg v.d.H.

Job
Job
Job
Job
Job
Job
Job

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Standard scope of service

Flat rate unit I 00 00 105

2 FRU

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Vehicle check service Flat rate unit I 00 00 624		7 FRU
Work time without specification/body equipment Flat rate unit I 51 99 000		0 FRU
SCHEIBENKLAR Part I 99 99 9 407 408	Local	2

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Engine oil service Flat rate unit I 00 00 610		3 FRU
CASTROL EDGE SAE 0W-30 Part I 99 99 9 999 100	Local	5
Set oil-filter element Part I 11 42 8 575 211		1
Screw plug Part I 11 13 7 535 106		1

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Fuel filter service Flat rate unit I 00 00 604		5 FRU
Fuel filter cartridge Part I 13 32 7 811 227		1
Hose clamp Part I 07 12 9 952 104		1

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Service - air filter insert Flat rate unit I 00 00 602		1 FRU
Air filter element Part I 13 71 8 570 043		1

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Service - microfilter		3 FRU
-----------------------	--	-------

Flat rate unit I 00 00 616

Set, microfilter/activ. charcoal filter
Part I 64 11 9 272 642

1

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

12-Punkte-Check

Flat rate unit I 00 99 270

Local

6 FRU

— 12/29/2015 Repair 50493 km 29428 B&K GmbH , Bad Homburg v.d.H. Job

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

12-Punkte-Check

Flat rate unit I 00 99 270

Local

6 FRU

— 07/21/2015 Repair 24204 km 29428 B&K GmbH , Bad Homburg v.d.H. Job Job

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

instandsetzen

Flat rate unit I 99 99 999

Local

1 FRU

nach Befund ersetzen

Flat rate unit I 99 99 999

Local

1 FRU

ersetzen, Scheinwerfer ausgebaut

Flat rate unit I 99 99 999

Local

1 FRU

Work time without specification/body equipment

Flat rate unit I 51 99 000

0 FRU

Work time without specification/body equipment

Flat rate unit I 51 99 000

2 FRU

Replacing front left side panel

Flat rate unit I 41 35 550

12 FRU

Removing and installing front bumper panel

Flat rate unit I 51 11 656

9 FRU

Removing and installing/replacing both supports for bumper cover, front

Flat rate unit I 51 11 566

7 FRU

Removing and installing/replacing support for front bumper cover Flat rate unit I 51 11 551	4 FRU
Replace bumper cover, front Flat rate unit I 51 11 592	6 FRU
Additional work with Park Distance Control Flat rate unit I 66 20 610	4 FRU
Replacing pedestrian protection sensor (fiber optic cable) Flat rate unit I 65 76 626	4 FRU
Removing and installing headlight, left Flat rate unit I 63 12 527	5 FRU
Replacing headlight, left or right Flat rate unit I 63 12 532	4 FRU
Removing and installing/replacing left high-pressure nozzle of headlight cleaning system Flat rate unit I 61 67 621	2 FRU
Remove and install/replace left or right side sill trim panel Flat rate unit I 51 71 947	7 FRU
Removing and installing left or right front door trim panel Flat rate unit I 51 41 503	6 FRU
Removing and installing/replacing the sound insulation at the front left or right door Flat rate unit I 51 48 560	3 FRU
Removing and installing the exterior mirror on front left or right door Flat rate unit I 51 16 501	3 FRU
Removing and installing/replacing window recess finisher strip on front door, outer Flat rate unit I 51 21 800	2 FRU
Remove and install/replace window frame trim of the front left or front right door Flat rate unit I 51 32 920	2 FRU
Removing and installing/replacing the cover on the bottom left or right of the front door Flat rate unit I 51 21 870	2 FRU
Removing and installing/replacing left or right front outside door handle Flat rate unit I 51 21 770	1 FRU
Performing vehicle test Flat rate unit I 00 00 556	3 FRU
Supporting the voltage of the vehicle electrical system/recharging the vehicle electrical system battery Flat rate unit I 61 21 528	1 FRU
Resume vehicle test and clear fault memory Flat rate unit I 61 00 980	2 FRU
Program/encode control unit(s), includes deleting the fault memory Flat rate unit I 61 00 730	4 FRU
Adjusting the ACC sensor Flat rate unit I 66 31 502	4 FRU
Work time without specification/engine	2 FRU

Flat rate unit | 11 99 000

Work time without specification/body equipment 12 FRU
Flat rate unit | 51 99 000

SCHEIBENKLAR Local 2
Part | 99 99 9 407 408

!!! unknown BMW-Id 07119100101 KLAMMER !!! Local 25
Part | 07 11 9 100 101

Trim cover, bumper, primed, front 1
Part | 51 11 7 332 677

Lever left 1
Part | 51 11 7 331 753

Covering primend left 1
Part | 51 11 7 332 683

Spring 1
Part | 51 11 7 202 885

Expanding rivet 2
Part | 51 11 1 908 077

Carrier, bumper front 1
Part | 51 11 7 200 705

Shock absorber front 1
Part | 51 11 7 331 748

Blind rivet 4
Part | 07 14 9 191 219

Badge 1
Part | 51 14 7 057 794

Ultrasonic sensor, black 1
Part | 66 20 9 270 495

Decoupling ring PDC torque converter 1
Part | 66 20 9 142 107

High-pressure nozzle, left 1
Part | 61 67 7 377 667

AHL-xenon headlight, left 1
Part | 63 11 7 343 907

Blind rivet 2
Part | 66 31 6 777 308

Sensor, pedestrian protection f-optic 1
Part | 65 76 9 318 777

Sensor 1
Part | 65 77 9 241 032

Support left 1
Part | 51 64 7 200 793

Support 2
Part | 51 11 7 263 325

Side panel, front left 1
Part | 41 35 7 248 659

Spacer left

Part I 51 11 7 207 931

1

Expanding rivet

Part I 51 16 1 881 149

3

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Painting bumper cover, front

Flat rate unit I 99 68 529

16 FRU

Work time without specification/paintwork

Flat rate unit I 99 99 000

2 FRU

Painting the side panel, left or right

Flat rate unit I 99 35 519

8 FRU

Work time without specification/paintwork

Flat rate unit I 99 99 000

1 FRU

Painting the front door, left or right

Flat rate unit I 99 51 538

9 FRU

Work time without specification/paintwork

Flat rate unit I 99 99 000

21 FRU

LACKANTEIL

Part I 99 99 9 100 000

Local

57

—

06/24/2015

Service

20424 km

00664
Niederlassung
München,
München

Manual



—

06/12/2015

Repair

20423 km

00664
Niederlassung
München
Filiale
Fröttmaning
BMW AG,
München

Job
Job
Job
Job
Job
Job
Job
Job
Job
Job

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Service consultation at the vehicle Flat rate unit I 00 52 050	0 FRU
---	-------

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Premium Select Durchsicht ggf. Transport Flat rate unit I AZ00 35 2	Local	19 FRU
--	-------	--------

Valve caps RDC Part I 36 11 1 095 436	4
--	---

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Engine oil service Flat rate unit I 00 00 610	3 FRU
--	-------

Set oil-filter element Part I 11 42 8 575 211	1
--	---

BMW Engine Oil LL04 5W30 Part I 83 21 2 405 948	5
--	---

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Service - microfilter Flat rate unit I 00 00 616	3 FRU
---	-------

Set, microfilter/activ. charcoal filter Part I 64 11 9 272 642	1
---	---

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Supporting the voltage of the vehicle electrical system/recharging the vehicle electrical system battery Flat rate unit I 61 21 528	1 FRU
---	-------

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words: Funktionstest/Prüfplan Lamdasonde durchgeführt da Fehlerspeicher,eintrag. Befund: Lambdasonde nach Kat. nicht adaptiert lt. Prüfplan,muss eine Adaptionfahrt durchgeführt werden.,

Remove and install/replace left or right underbody panelling Flat rate unit I 51 71 515	3 FRU
--	-------

Performing vehicle test Flat rate unit I 00 00 556	3 FRU
---	-------

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words: FS nach PF gelesen Kurzschluß Unterbrechung der Lambdasondenheizung,nach Plus Sonde nach Kat. Fehler seit 1500km gespeichert. Leitung,zwischen DDE und Sonde nach Kat geprüft. Leitungen i.O. Widerstand der,Sondenheizung geprüft Soll 3 Ohm ist unendlich. Befund Lambdasonde nach,Kat defekt. Sonde ers Adaption angestoßen und FS gelöscht. PF,durchgeführt und abschließend nochmals den FS gelesen keine Fehler mehr,gespeichert.,

Carrying out vehicle test Flat rate unit I 00 00 006	4 FRU
---	-------

Troubleshooting Flat rate unit I 12 00 009	6 FRU
---	-------

Removing and installing Digital Diesel Electronics control unit Flat rate unit I 13 61 600	4 FRU
---	-------

Replacing oxygen sensor monitor Flat rate unit I 13 62 664	4 FRU
---	-------

Performing vehicle test Flat rate unit I 00 00 556	3 FRU
---	-------

Oxygen sensor Part I 13 62 8 570 689	1
---	---

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

—	06/11/2015	Repair	20423 km	00664 Niederlassung München Filiale Fröttmaning BMW AG, München	Job Job Job
---	------------	--------	----------	---	-------------------

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Presser Rg. 28543	Local	1
Part I 0000154		

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

—	05/11/2015	Repair	17999 km	00664 Niederlassung München Filiale Fröttmaning BMW AG, München	Job Job
---	------------	--------	----------	---	------------

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words: Reifen HR hat Luftverlust,bitte prüfen/begutachten,ca. 1bar über Nacht,Im Reifen hinten links ist ein Nagel eingefahren.,

Replace a tire with a run-flat equipment specification	9 FRU
Flat rate unit I 36 12 005	

—	04/21/2015	Repair	16650 km	00664 Niederlassung München Filiale Fröttmaning BMW AG, München	Job Job Job
---	------------	--------	----------	---	-------------------

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words: bereits von Verkäufer freigebremst aber leider immernoch extrem schlechte Bremsleistung, Hinten bitte prüfen ggf auch abdrehen,

Precision-turning both front brake blades on both sides Flat rate unit I 34 11 667	11 FRU
---	--------

Precision turning both brake disks on both sides Flat rate unit I 34 21 947	11 FRU
--	--------

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words: Nach Abdrehen beim prüfen auf dem Bremsenprüfstand das Bremswerte trotz, abdrehen der Bremsscheiben nicht i.O. waren. Nach demontage der, Bremsbeläge vorne wie hinten festgestellt das Bremsbeläge auf beiden, Achsen verglast sind. Nach rücksprachem mit Hr. Schwörer Beläge auf, beiden Achsen ers.,

Replacing the brake pads of the disk brakes, front and rear Flat rate unit I 34 11 515	10 FRU
---	--------

Repair kit, brake pads asbestos-free Part I 34 11 6 858 047	1
--	---

Brake pad wear sensor, front left Part I 34 35 6 791 958	1
---	---

Clip Part I 34 11 6 798 879	2
--------------------------------	---

Brake pad paste Part I 83 19 2 158 851	4
---	---

Repair kit, brake pads asbestos-free Part I 34 21 6 796 741	1
--	---

Brake pad wear sensor, rear Part I 34 35 6 791 963	1
---	---

—	04/08/2015	Repair	16482 km	00664 Niederlassung München Filiale Fröttmaning BMW AG, München	Job Job Job Job
---	------------	--------	----------	---	--------------------------

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words: Befund: Bremsscheiben VA und HA korrodiert laut SB keine rep,

Öl/Wasser/Luft ggf. Transportsicherungen	Local	4 FRU
Flat rate unit I AZ00 35 6		

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Supporting the voltage of the vehicle electrical system/recharging the vehicle electrical system battery	1 FRU
Flat rate unit I 61 21 528	

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Service consultation at the vehicle	0 FRU
Flat rate unit I 00 52 050	

—	03/19/2015	Repair	16482 km	00664 Niederlassung München Filiale Fröttmaning BMW AG, München	Job Job
---	------------	--------	----------	---	------------

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

BLG	Local	1
-----	-------	---

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words: