Vehicle

BMW 320i, 135kW

WBA8A11030A119611

Development code	F30
Color	mineral-grau metallic
Actual integration level	F020-20-11-520
Start of warranty	January 3, 2018

Technical Campaigns

There are no campaigns available.

Special information

There are no campaigns available.

Live Diagnosis

There are no service solutions for Live Diagnosis.

Service contracts

No BSI contracts available

You can find additional service contract information and selection options in the DCSNet warranty vehicle enquiry.

Information on faults, workshop/Service Consultation

No information on faults is available.

Navigation map

Installed map	Enabling code (subscription)	Latest navigation map included in subscription	Latest navigation map subject to charge
Road Map EUROPE WEST Route 2024 (as of: Jan 7, 2026)	Release code valid for navigation maps with release date up to Dec 31, 2025 (SWID: 00B4008F).	Road Map EUROPE WEST Route 2025	-

Vehicle details

Vehicle type	Passenger car

Brand	BMW
Model	320i
Body	LIM
Vehicle identification number (last 7 characters)	A119611
Vehicle identification number (17 characters)	WBA8A11030A119611
Development code	F30
Steering	LL
Engine	B48M
Engine number	F1451769
Exhaust re-treatment	EURO6;W;PI/CI; M, N1 I
Transmission	AUT
Transmission number	0987770ZYZ
Head unit serial number	MM01DFH2502710
Drive	HECK
Integration level	F020-17-03-505
Production date	Jun 14, 2017
Production works	Muenchen
Delivery date	Jun 21, 2017
Delivering Retailers	Autohaus Kühnert, Schleiz, DE
National-market version	EUR
Paint code	B39
Upholstery code	CCL2
Model code	8A21
Base type	8A11
Lead type	8A21

Optional equipment

Optional equipment fitted at the factory:

01CA Selection of COP relevant vehicles
01CB CO2 package
0205 Automatic transmission
0230 EU-specific additional contents
0248 Steering wheel heater
0258 Tire with run-flat functionality
02A6 BMW LA wheel, Double Spoke 392
02VB Tire pressure display
02VL Variable Sport steering
02XE Sport leather steering wheel
0302 Alarm system

Retrofitted optional equipment:

This vehicle has no retrofits.

0320 Deleted, model lettering
03AC Trailer coupling
0420 Sun protection glazing
0423 Floor mats, velours
0428 Warning triangle and first aid kit
0430 Interior/outside mirror with auto dip
0431 Interior mirror with automatic-dip
0465 Through-loading system
0481 Sports seat
0493 Storage compartment package
0494 Seat heating driver/passenger
04AE Armrest front, retractable
04LU Black, highgloss Perlglanz chrome accent
04NE Blow-by heater
0507 Park Distance Control (PDC), rear
0521 Rain sensor
0534 Automatic air conditioning
0544 Cruise control with braking function
0548 Kilometer-calibrated speedometer
0563 Light package
0575 Supplementary 12V sockets
05A1 LED Fog lights
05A2 LED headlight
05AC High-beam assistant
05AG Lane-change warning
05DA Passenger airbag deactivation
05DC Rear-seat headrests, folding
0606 Navigation system Business
0676 HiFi speaker system
0698 Area-Code 2 for DVD
06AC Intelligent emergency SOS call
06AE Teleservices
06NH Hands-free with USB interface
06WA Instrument cluster, expanded equipment
07AC Sport Line
07LD Modell Sport Line
0801 German version
0851 Language version German
0879 On-board vehicle literature German
08KA Oil service interval, 24 mos./30,000 km
08R9 Refrigerant R1234yf
08TH Road sign detection
09AA Outer skin protection
A090 90 AH AGM battery
POLS Cloth cushion

Vehicle histories

	Date	Type	Vehicle mileage	Dealer	Overview
—	05/27/2026	Key	194153 km	33282	Key 1
	17000 01/2028	17000 01/2028	17000 01/2028	17000 01/2028	28000 07/2026	70000	17000 01/2028	01/2027
—	04/21/2026	Key	191057 km	04553	Key 1

21000	21000	21000	21000	32000		80000	21000		§
01/2028	01/2028	01/2028	01/2028		07/2026		01/2028		01/2027

— 04/21/2026 Repair 191063 km 04553 , Job
Job: Räder wechseln

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Kühnert Sicherheitscheck Local 3 FRU
Flat rate unit | 00 99 305

— Job: Räder wechseln

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Räder wechseln
Package | MM04RADWECH10

Detaching and attaching the front and rear wheels 9
Flat rate unit | 36 10 360

Wheel cleaning 1
Flat rate unit | 00 99 040

— 03/31/2026 Key 189115 km 52605 Key 1

23000	23000	23000	23000	33000		80000	23000		§
01/2028	01/2028	01/2028	01/2028		07/2026		01/2028		01/2027

— 02/20/2026 Key 186414 km 52605 Key 1

27000	27000	27000	27000	36000		80000	27000		§
01/2028	01/2028	01/2028	01/2028		07/2026		01/2028		01/2027

— 01/07/2026 Key 183767 km 04553 Key 1

-120 0.5 %			-120	38000		90000	23000		§
01/2027			01/2027		07/2026		01/2029		01/2027

— 01/07/2026 Service 183767 km 04553 Autohaus Kühnert Automatic

GmbH&Co. KG ,
Langenwetzendorf

-120	0	0	-120	38000	0	90000	23000	0
✓			✓					

— 01/07/2026 Repair 183836 km 04553 , Job: Service Standardumfang
Job: Service Motoröl
Job: Service Mikrofilter
Job

— Job: Service Standardumfang

Description: MKP 0000105 : BMW Service 5+, 20% Nachlass Nachlass

Is interpreted as a repeat visit: No

Customer's own words:

Service Standardumfang
Package | 0000105

Standard scope of service Flat rate unit | 00 00 105	2

— Job: Service Motoröl

Description: MKP 0000610 : BMW Service 5+, 20% Nachlass Nachlass

Is interpreted as a repeat visit: No

Customer's own words:

Service Motoröl
Package | 0000610

Engine oil service Flat rate unit | 00 00 610	3
Set oil-filter element Part | 11 42 8 575 211	1
BMW TwinPower Turbo LL-19FE 0W-30 Part | 83215A65BF8	5.25

— Job: Service Mikrofilter

Description: MKP 0000616 : BMW Service 5+, 20% Nachlass Nachlass

Is interpreted as a repeat visit: No

Customer's own words:

Service Mikrofilter
Package | 0000616

Service - microfilter Flat rate unit | 00 00 616	2
Microfilter/activated Carbon container Part | 64 11 9 237 555	1

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Windshield Washer Antifreeze Part I 83 12 2 413 058	1
Antifr./anti-corros.agent Frostox HT-12 Part I 83195A53164	1

—	01/05/2026	Key	183725 km	04553	Remote KeyRead

-20 0.1 % 01/2027			-20 01/2027	38000	07/2026	90000	23000 01/2029	01/2027

—	12/10/2025	Key	181207 km	52605	Key 1

2900 01/2027			2900 01/2027	40000	07/2026	100000	26000 01/2029	01/2027

—	11/07/2025	Key	179364 km	04553	Key 1

6000 01/2027			6000 01/2027	42000	07/2026	2200	31000 01/2029	01/2027

—	11/07/2025	Service	179364 km	04553 Autohaus Kühnert GmbH&Co. KG , Langenwetzendorf	Automatic

6000 01/2027	0	0	6000 01/2027	42000	0 07/2026	2200 ✓	31000 01/2029	0 01/2027

—	11/07/2025	Repair	179374 km	04553 ,	Job Job: Service Standardumfang Job Job: Ersatzfahrzeug Vermietung Job: Fahrzeugwäsche kostenlos Job: Spurstange links oder rec

— Job

Description: MKP 0000614 : BMW Service 5+, 20% Nachlass Nachlass

Is interpreted as a repeat visit: No

Customer's own words:

Hex screw with collar Part I 34 20 6 850 536	4
Inner hex bolt	2

Part | 34 21 1 161 806

Brake disc, ventilated Part | 34 21 6 792 227		2

Bremsenreiniger, acetonfr
Package | 0000614

Rear brakes service Flat rate unit | 00 00 614		7
Brake cleaner, acetone-free Part | 83 19 2 413 695		1
Brake pad wear sensor, rear Part | 34 35 6 792 292		1
Repair kit brake pads asbestos-free Part | 34 21 8 855 013		1
Brake pad paste Part | 83 19 2 158 851		2

— Job: Service Standardumfang

Description: MKP 0000105 : BMW Service 5+, 20% Nachlass Nachlass

Is interpreted as a repeat visit: No

Customer's own words:

Service Standardumfang
Package | 0000105

Standard scope of service Flat rate unit | 00 00 105		2

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Kühnert Sicherheitscheck Flat rate unit | 00 99 305	Local	3 FRU

— Job: Ersatzfahrzeug Vermietung

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Ersatzfahrzeug Vermietung
Package | MM01ERSATZFZG*BMJD21

Ersatzfahrzeug Vermietung Flat rate unit | 99 99 999	Local	1

— Job: Fahrzeugwäsche kostenlos

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Fahrzeugwäsche kostenlos
Package | MM02WÄSCHE*BMJD21

Outside car wash and interior vehicle cleaning 0
Flat rate unit | 00 11 329

— Job: Spurstange links oder rec

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Spurstange links oder rec
Package | 3221231

Replacing left or right tie rod 9
Flat rate unit | 32 21 231

Kinematics Diagnosis System wheel alignment with ride height measurement without loading the vehicle 8
Flat rate unit | 32 00 595

Adjusting toe-in on front axle 6
Flat rate unit | 32 00 601

Left tie rod 1
Part | 32 10 6 799 960

Combination nut 1
Part | 33 30 6 787 062

Pipe clamp 1
Part | 32 10 6 765 232

Hose clamp 1
Part | 32 13 6 756 011

— 11/05/2025 Key 179156 km 04553 Remote KeyRead

7000			7000	42000		2400	32000	
01/2027			01/2027		07/2026		01/2029	01/2027

— 11/03/2025 Key 178961 km 04553 Key 1

7000			7000	42000		2500	32000	
01/2027			01/2027		07/2026		01/2029	01/2027

— 09/01/2025 Key 175492 km 52605 Key 1

12000			12000	46000		4600	38000	
01/2027			01/2027		07/2026		01/2029	01/2027

— 05/26/2025 Key 169169 km 52605 Key 10

20000			20000	50000		6000	48000		§
01/2027			01/2027		07/2026		01/2029		01/2027

— 01/07/2025 Key 160636 km 04553 Key 1

-2000	-2000	-2000	-2000	60000		6000	-2000		§
7.7 %							3.8 %		
11/2025	11/2025	11/2025	11/2025		07/2026		11/2025		-6
									0.8 %

— 01/07/2025 Service 160636 km 04553 Autohaus Kühnert GmbH&Co. KG , Langenwetzendorf Automatic

-2000	-2000	-2000	-2000	60000		6000	-2000		§
11/2025	11/2025	11/2025	11/2025		07/2026		11/2025		01/2025
✓	✓	✓	✓				✓		

— 01/07/2025 Repair 160647 km 04553 ,

Job: Satz Ölfiltereinsatz
Job: Luftfiltereinsatz
Job: Mikrofilter/Aktivkohlefil
Job: Sechskantschraube mit Sch
Job: Service Fahrzeug-Check
Job: Service Standardumfang
Job
Job: Vorbereitung für
Job: Wischerblatt links und re
Job: Ersatzfahrzeug Vermietung
Job
Job

— Job: Satz Ölfiltereinsatz

Description: MKP 0000610 : BMW Service 5+, 20% Nachlass Nachlass

Is interpreted as a repeat visit: No

Customer's own words:

Satz Ölfiltereinsatz
Package | 0000610

Engine oil service Flat rate unit | 00 00 610	3
Set oil-filter element Part | 11 42 8 575 211	1
BMW TwinPower Turbo LL-19FE 0W-30 Part | 83215A65BF8	5.25

— Job: Luftfiltereinsatz

Description: MKP 0000602 : BMW Service 5+, 20% Nachlass Nachlass

Is interpreted as a repeat visit: No

Customer's own words:

Luftfiltereinsatz
Package | 0000602

Service - air filter insert Flat rate unit | 00 00 602	1
Air filter element Part | 13 71 8 605 164	1

— Job: Mikrofilter/Aktivkohlefil

Description: MKP 0000616 : BMW Service 5+, 20% Nachlass Nachlass

Is interpreted as a repeat visit: No

Customer's own words:

Mikrofilter/Aktivkohlefil
Package | 0000616

Service - microfilter Flat rate unit | 00 00 616	2
Microfilter/activated Carbon container Part | 64 11 9 237 555	1

— Job: Sechskantschraube mit Sch

Description: MKP 0000622 : BMW Service 5+, 20% Nachlass Nachlass

Is interpreted as a repeat visit: No

Customer's own words:

Sechskantschraube mit Sch
Package | 0000622

Spark plugs service Flat rate unit | 00 00 622	11
Hex bolt with washer Part | 31 10 6 854 219	2
Torx screw with collar Part | 07 14 7 270 121	2
Spark plug, High Power Part | 12 12 0 040 551	4

— Job: Service Fahrzeug-Check

Description: MKP 0000624 : BMW Service 5+, 20% Nachlass Nachlass

Is interpreted as a repeat visit: No

Customer's own words:

Service Fahrzeug-Check
Package | 0000624

Vehicle check service Flat rate unit | 00 00 624	6

— Job: Service Standardumfang

Description: MKP 0000105 : BMW Service 5+, 20% Nachlass Nachlass

Is interpreted as a repeat visit: No

Customer's own words:

Service Standardumfang
Package | 0000105

Standard scope of service Flat rate unit | 00 00 105	2

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Removing and installing/sealing or replacing complete full flow oil filter Flat rate unit | 11 42 520	64 FRU
Work time without specification/engine Flat rate unit | 11 99 000	6 FRU
Connector Part | 11 11 8 511 205	1
Oil filter housing Part | 11 42 8 596 283	1
Gasket Part | 13 54 8 632 344	1
Seal for intake system Part | 11 61 8 637 800	4
Hose, cylinder head-expansion tank Part | 17 12 9 845 173	1

— Job: Vorbereitung für

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Vorbereitung für
Package | MM01TÜV

Vorbereitung für Hauptuntersuchung #HU2 Flat rate unit | 99 00 002	Local	2
Abgasuntersuchung Dieselfahrz./Kat.-Fahrzeuge #AU2 Flat rate unit | 00 00 401	Local	5
Prüf- & Klebesiegel Set Flat rate unit | 99 99 999	Local	1
Hauptuntersuchung TÜV Flat rate unit | 99 99 999	Local	1

— Job: Wischerblatt links und re

Description: MKP 6161541 : BMW Service 5+, 20% Nachlass Nachlass

Is interpreted as a repeat visit: No

Customer's own words:

Wischerblatt links und re

Package | 6161541

Replace left and right wiper blade Flat rate unit | 61 61 541		1
Set of wiper blades Part | 61615A43585		1

— Job: Ersatzfahrzeug Vermietung

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Ersatzfahrzeug Vermietung
Package | MM01ERSATZFZG*BMJD21

Ersatzfahrzeug Vermietung Flat rate unit | 99 99 999	Local	3

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Replacing both rear shock absorbers Flat rate unit | 33 52 530	11 FRU
Shock absorber, rear Part | 33 52 6 883 830	2
Auxiliary shock absorber, rear Part | 33 53 6 855 439	2
Gasket Part | 33 50 6 866 038	2
Hex nut wiht flange Part | 07 11 9 907 135	2
Torx screw with collar Part | 07 11 9 907 372	2
Star-socket screw Part | 07 11 9 907 137	6
Self-locking collar nut Part | 33 32 6 760 668	2

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Removing and installing both complete front spring struts Flat rate unit | 31 31 515	22 FRU
Hex bolt with washer Part | 31 30 6 869 931	10
Spring pad with guard tube, top	2

Part | 31 30 6 791 712

Additional shock absorber, front Part | 31 33 6 855 440	2
Hexagon nut with collar Part | 33 32 6 768 884	2
Hex nut Part | 07 11 9 905 032	2
Hexagon screw with flange Part | 31 30 6 798 530	2
Combination nut Part | 33 30 6 787 062	4

— 01/07/2025 Repair 160647 km 04553 , Job

— Job

Description: Fahrzeug abgeschleppt aus Jena nach Langenwetzendorf

Is interpreted as a repeat visit: No

Customer's own words:

Abschleppkosten Eigen (vom Händler selbst) Flat rate unit | 99 99 999	Local	1 FRU

— 11/13/2024 Key 157013 km 04553 Key 10

2100	2100	2100	2100	70000		7000	2100	
11/2025	11/2025	11/2025	11/2025		07/2026		11/2025	01/2025

— 07/03/2024 Key 149768 km 04553 Key 10

12000	12000	12000	12000	1600		7000	12000	
11/2025	11/2025	11/2025	11/2025		-2 0.3 %		11/2025	01/2025

— 07/03/2024 Service 149768 km 04553 Autohaus Kühnert GmbH&Co. KG , Langenwetzendorf Automatic

12000	12000	12000	12000	1600		7000	12000	
				✓	✓			

— 07/03/2024 Repair 149780 km 04553 , Job
Job
Job
Job
Job

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Standard scope of service Flat rate unit I 00 00 105	2 FRU

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Service - front brakes Flat rate unit I 00 00 612	6 FRU
Brake cleaner, acetone-free Part I 83 19 2 413 695	1
Brake pad wear sensor, front left Part I 34 35 6 792 289	1
Repair kit, brake pads Part I 34 11 8 855 002	1
Brake pad paste Part I 83 19 2 158 851	2

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Brake fluid service Flat rate unit I 00 00 618	4 FRU
Brake fluid DOT4 LV, low viscosity Part I 83 13 2 184 843	1

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Performing vehicle test Flat rate unit I 00 00 556	2 FRU
Supporting the voltage of the vehicle electrical system/recharging the vehicle electrical system battery Flat rate unit I 61 21 528	1 FRU
Replace ultrasonic sensor for left or right PMA Flat rate unit I 66 33 512	2 FRU
Decoupling ring PDC torque converter Part I 66 20 6 923 000	1

Ultrasonic sensor, Mineral Gray 1
Part | 66 20 9 261 581

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Ersatzfahrzeug Vermietung 00000000 Local 1 FRU
Flat rate unit | 99 99 999

— 01/23/2024 Key 137659 km 04553 Key 10

25000	25000	25000	25000	16000	07/2024	7000	25000	01/2025
11/2025	11/2025	11/2025	11/2025				11/2025	

— 01/23/2024 Repair 137671 km 04553 Autohaus Kühnert GmbH & Co. KG , Langenwetzendorf Job Job

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Detaching and attaching the front and rear wheels 6 FRU
Flat rate unit | 36 10 360

Mounting four tires on rims and balancing dynamically 10 FRU
Flat rate unit | 36 12 574

Wheel electr. module RDCi w/ screw valve 4
Part | 36 10 6 881 890

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Wagen-Innenraum aussaugen zum Werkstattbesuch Local 1 FRU
Flat rate unit | 00 10 101

— 01/18/2024 Key 137232 km 04553 Key 10

25000	25000	25000	25000	16000	07/2024	7000	25000	01/2025
11/2025	11/2025	11/2025	11/2025				11/2025	

— 01/18/2024 Repair 137234 km 04553 Autohaus Kühnert GmbH & Job Job

Co. KG ,
Langenwetzendorf

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Supporting the voltage of the vehicle electrical system/recharging the vehicle electrical system battery Flat rate unit I 61 21 528	1 FRU

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Carrying out vehicle test Flat rate unit I 00 00 006	4 FRU

— 11/15/2023 Key 132673 km 04553 Key 10



— 11/15/2023 Service 132673 km 04553 Autohaus Kühnert GmbH&Co. KG , Langenwetzendorf Automatic



— 11/15/2023 Repair 132678 km 04553 Autohaus Kühnert GmbH & Co. KG , Langenwetzendorf Job Job Job Job

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Engine oil service Flat rate unit I 00 00 610	3 FRU
Set oil-filter element Part I 11 42 8 575 211	1

BMW Engine Oil LL04 0W30 — 5.25
Part | 83 21 2 405 950

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Service - microfilter — 2 FRU
Flat rate unit | 00 00 616

Microfilter/activated Carbon container — 1
Part | 64 11 9 237 555

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Standard scope of service — 2 FRU
Flat rate unit | 00 00 105

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Wagen-Innenraum aussaugen zum Werkstattbesuch — Local — 1 FRU
Flat rate unit | 00 10 101

— 04/22/2023 Key — 121490 km — Key 10



— 04/22/2023 Repair — 121514 km — 04111 Autohaus Fiebig GmbH , Jena — Job

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Check the cooling system for watertightness with the special tool — 4 FRU
Flat rate unit | 17 00 009

Work time without specification/radiator — 9 FRU
Flat rate unit | 17 99 000

Removing and installing/replacing cylinder head-expansion tank coolant line Flat rate unit I 17 12 512	15 FRU
Bleed the cooling system and check it for watertightness with the special tool Flat rate unit I 17 00 540	6 FRU
Hose, cylinder head-expansion tank Part I 17 12 9 845 173	1
Anti-freeze Part I 83 19 2 218 348	5

— 01/26/2023 Key 115366 km Key 1

24000			24000	39000		18000	60000
11/2024			11/2024		07/2024		11/2026

§ 01/2025

— 01/26/2023 Repair 115371 km 04553 Autohaus Kühnert GmbH & Co. KG , Langenwetzendorf Job Job Job

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Fahrzeug-Verbringung Flat rate unit I 00 99 001	Local	4 FRU
Replace rear bumper panel Flat rate unit I 51 12 157		7 FRU
Removing and installing/replacing the support for the rear bumper cover Flat rate unit I 51 12 552		3 FRU
Additional work with Park Distance Control Flat rate unit I 66 20 610		4 FRU
Performing vehicle test Flat rate unit I 00 00 556		2 FRU
Supporting the voltage of the vehicle electrical system/recharging the vehicle electrical system battery Flat rate unit I 61 21 528		1 FRU

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Bumper trim panel, primed, rear Part I 51 12 7 384 603	1
Adhesive set K6	1

Part | 83195A547C4

Kit, mount for PDC/PMA sensor, rear Part | 51 12 7 445 146	1
Badge Part | 51 76 7 288 752	1
Trim on grill, side, right Part | 51 11 7 475 994	1

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Fremdrechnung Nr:46902 Lackierung 00000000 Flat rate unit | 99 99 999	Local	1 FRU

—	01/26/2023	Repair	115371 km	04553 Autohaus Kühnert GmbH & Co. KG , Langenwetzendorf	Job Job Job

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Fahrzeug-Verbringung Flat rate unit | 00 99 001	Local	-4 FRU
Replace rear bumper panel Flat rate unit | 51 12 157		-7 FRU
Removing and installing/replacing the support for the rear bumper cover Flat rate unit | 51 12 552		-3 FRU
Additional work with Park Distance Control Flat rate unit | 66 20 610		-4 FRU
Performing vehicle test Flat rate unit | 00 00 556		-2 FRU
Supporting the voltage of the vehicle electrical system/recharging the vehicle electrical system battery Flat rate unit | 61 21 528		-1 FRU

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Bumper trim panel, primed, rear Part | 51 12 7 384 603	-1
Adhesive set K6 Part | 83195A547C4	-1

Kit, mount for PDC/PMA sensor, rear Part I 51 12 7 445 146		-1
Badge Part I 51 76 7 288 752		-1
Trim on grill, side, right Part I 51 11 7 475 994		-1

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Fremdrechnung Nr:46902 Lackierung 00000000 Flat rate unit I 99 99 999	Local	-1 FRU

—	01/26/2023	Repair	115371 km	04553 Autohaus Kühnert GmbH & Co. KG , Langenwetzendorf	Job Job

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Fahrzeug-Verbringung Flat rate unit I 00 99 001	Local	4 FRU
Replace rear bumper panel Flat rate unit I 51 12 157		7 FRU
Removing and installing/replacing the support for the rear bumper cover Flat rate unit I 51 12 552		3 FRU
Additional work with Park Distance Control Flat rate unit I 66 20 610		4 FRU
Performing vehicle test Flat rate unit I 00 00 556		2 FRU
Supporting the voltage of the vehicle electrical system/recharging the vehicle electrical system battery Flat rate unit I 61 21 528		1 FRU
Bumper trim panel, primed, rear Part I 51 12 7 384 603		1
Adhesive set K6 Part I 83195A547C4		1
Kit, mount for PDC/PMA sensor, rear Part I 51 12 7 445 146		1
Badge Part I 51 76 7 288 752		1
Trim on grill, side, right Part I 51 11 7 475 994		1

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Fremdrechnung Nr:46902 Lackierung 00000000 Flat rate unit I 99 99 999	Local	1 FRU

— 01/17/2023 Key 114627 km Remote KeyRead

24000			24000	39000		19000	60000		
11/2024			11/2024		07/2024		11/2026		01/2025

— 01/11/2023 Key 114249 km Key 1

25000			25000	40000		19000	60000		-10
11/2024			11/2024		07/2024		11/2026		1.4 %

— 01/11/2023 Repair 114249 km 04553 Autohaus Kühnert GmbH & Co. KG , Langenwetzendorf Job Job Job

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Installing navigation map(s) Flat rate unit I 65 90 600	2 FRU
Enable code HU-B Nav map Eur. Route Upd. Part I 65 90 2 409 897	1

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Vorbereitung für Flat rate unit I 99 00 002	Local	2 FRU
Abgasuntersuchung Flat rate unit I 00 00 401	Local	5 FRU

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Hauptuntersuchung TÜV Flat rate unit I 99 99 999	Local	1 FRU
Prüf- Klebesiegel Set Flat rate unit I 99 99 999	Local	1 FRU

— 11/03/2022 Key 108903 km 04553 Key 1

-600 2.1 % 12/2023	-600 12/2023	-600 12/2023	-600 12/2023	47000	07/2024	26000	-600 1 % 12/2023	01/2023

— 11/03/2022 Service 108903 km 04553 Autohaus Kühnert GmbH&Co. KG , Langenwetzendorf Automatic

-600 ✓	-600 ✓	-600 ✓	-600 ✓	47000		26000	-600 ✓	

— 11/03/2022 Repair 108912 km 04553 Autohaus Kühnert GmbH & Co. KG , Langenwetzendorf Job Job Job Job Job Job Job Job Job Job Job

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Standard scope of service Flat rate unit I 00 00 105	2 FRU
Windshield Washer Antifreeze Part I 83 12 2 413 058	2
Anti-freeze Part I 83 19 2 218 348	0.75

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Removing and installing/renewing both brake discs Flat rate unit I 34 21 320	12 FRU
Brake cleaner, acetone-free Part I 83 19 2 413 695	1
Brake disc, ventilated Part I 34 21 6 792 227	2
Inner hex bolt Part I 34 21 1 161 806	2
Hex screw with collar Part I 34 20 6 850 536	4
Repair kit, brake pads asbestos-free Part I 34 21 6 873 093	1
Brake pad paste Part I 83 19 2 158 851	2
Brake pad wear sensor, rear Part I 34 35 6 792 292	1

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Engine oil service Flat rate unit I 00 00 610	3 FRU
Set oil-filter element Part I 11 42 8 575 211	1
BMW Engine Oil LL04 0W30 Part I 83 21 2 405 950	5.25

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Service - air filter insert Flat rate unit I 00 00 602	1 FRU
Air filter element Part I 13 71 8 605 164	1

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Service - microfilter Flat rate unit I 00 00 616	2 FRU
Microfilter/activated Carbon container	1

Part | 64 11 9 237 555

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Spark plugs service Flat rate unit | 00 00 622	11 FRU
Torx screw with collar Part | 07 14 7 270 121	2
Spark plug, High Power Part | 12 12 0 040 551	4
Hex bolt with washer Part | 31 10 6 854 219	2

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Vehicle check service Flat rate unit | 00 00 624	6 FRU

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Carry out Kinematics Diagnosis System wheel alignment with vehicle load up to design position Flat rate unit | 32 00 590	16 FRU

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Adjusting the rear axle and front axle Flat rate unit | 32 00 630	11 FRU

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Replace left and right wiper blade — 1 FRU
Flat rate unit | 61 61 541

Set of wiper blades — 1
Part | 61615A43585

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Ersatzfahrzeug Vermietung — Local — 1 FRU
Flat rate unit | 99 99 999

— 10/27/2022 Key — 108354 km — Remote KeyRead

-140 0.5 % 12/2023	-140 12/2023	-140 12/2023	-140 12/2023	48000	07/2024	27000	-140 0.2 % 12/2023	01/2023

— 07/08/2022 Key — 99840 km — 04553 — Key 1

9000 12/2023	9000 503	9000 503	9000 503	60000	-7 1 %	35000	9000 12/2023	01/2023

— 07/08/2022 Service — 99840 km — 04553 Autohaus Kühnert GmbH&Co. KG , Langenwetzendorf — Automatic

9000	9000	9000	9000	60000	✓	35000	9000	

— 07/08/2022 Repair — 99845 km — 04553 Autohaus Kühnert GmbH & Co. KG , Langenwetzendorf — Job Job

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Standard scope of service — 2 FRU
Flat rate unit | 00 00 105

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Brake fluid service Flat rate unit I 00 00 618	4 FRU
Brake fluid DOT4 LV, low viscosity Part I 83 13 2 184 843	1

— 07/07/2022 Key 99724 km 04553 Remote KeyRead

9000	9000	9000	9000	60000	-6	35000	9000	01/2023
12/2023	504	504	504		0.8 %		12/2023	

— 12/14/2021 Key 79702 km Key 1

30000	30000	30000	30000	80000		60000	30000	01/2023
12/2023	707	707	707		07/2022		12/2023	

— 12/14/2021 Repair 79708 km 04553 Autohaus Kühnert GmbH & Co. KG , Langenwetzendorf Job Job

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Wagenwäsche und Innenraum aussaugen zum Werkstattbesuch Flat rate unit I 00 10 100	Local	0 FRU

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Ersatzfahrzeug Vermietung 00000000 Flat rate unit I 99 99 999	Local	3 FRU
Fremdrechnung Nr: Lackierung 00000000 Flat rate unit I 99 99 999	Local	1 FRU
Fremdrechnung Nr: Lackierung 00000000 Flat rate unit I 99 99 999	Local	1 FRU
Fahrzeug-Verbringung Flat rate unit I 00 99 001	Local	3 FRU
Replace rear bumper panel Flat rate unit I 51 12 157		7 FRU
Additional work with Park Distance Control		4 FRU

Flat rate unit I 66 20 610	
Adjusting rear lid Flat rate unit I 41 62 514	18 FRU
Removing and installing rear lid Flat rate unit I 41 62 510	10 FRU
Stripping and refitting work for painting tailgate Flat rate unit I 51 18 870	7 FRU
Performing vehicle test Flat rate unit I 00 00 556	2 FRU
Cavity sealant for trunk lid Flat rate unit I 97 62 501	2 FRU
Bumper trim panel, primed, rear Part I 51 12 7 384 603	1
Adhesive set K6 Part I 83 19 2 317 925	1
Kit, mount for PDC/PMA sensor, rear Part I 51 12 7 445 146	1
Trim strip, black Part I 51 12 7 384 571	1
Screening, right Part I 66 32 6 794 269	1
Grommet Part I 51 14 1 852 899	8
Clamp Part I 51 13 8 144 998	8

— 12/10/2021 Key 79138 km Key 1

-1700			-1700	80000		60000	28000	
10/2022			291		07/2022		1011	01/2023

— 12/10/2021 Service 79138 km 04553 Autohaus Kühnert GmbH&Co. KG , Langenwetzendorf Automatic

-1700	0	0	-1700	80000	0	60000	28000	0
✓			✓					

— 12/10/2021 Repair 79144 km 04553 Autohaus Kühnert GmbH & Co. KG , Langenwetzendorf Job Job Job

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Standard scope of service Flat rate unit I 00 00 105	2 FRU
Anti-freeze Part I 83 19 2 218 348	0.4

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Engine oil service Flat rate unit I 00 00 610	3 FRU
BMW Engine Oil LL04 0W30 Part I 83 21 2 405 950	5.25
Set oil-filter element Part I 11 42 8 575 211	1

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Service - microfilter Flat rate unit I 00 00 616	2 FRU
Microfilter/activated Carbon container Part I 64 11 9 237 555	1

— 12/06/2021 Key 78685 km Remote KeyRead



— 08/12/2021 Key 71642 km Key 1



— 08/12/2021 Service 71642 km 04553 Autohaus Kühnert GmbH&Co. KG , Langenwetzendorf Automatic



—	08/12/2021	Repair	71648 km	04553 Autohaus Kühnert GmbH & Co. KG , Langenwetzendorf	Job Job Job

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Standard scope of service Flat rate unit I 00 00 105	2 FRU

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Service - front brakes Flat rate unit I 00 00 612	6 FRU
Removing and installing/replacing both front brake discs Flat rate unit I 34 11 613	3 FRU
Repair kit, brake pads asbestos-free Part I 34 11 6 874 331	1
Brake pad wear sensor, front left Part I 34 35 6 792 289	1
Brake cleaner, acetone-free Part I 83 19 2 413 695	1
Brake pad paste Part I 83 19 2 158 851	2
Brake disc, ventilated Part I 34 11 6 792 217	2
Torx screw with washer Part I 34 10 6 864 424	4
Inner hex bolt Part I 34 21 1 161 806	2

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Wagenwäsche und Innenraum aussaugen zum Werkstattbesuch Flat rate unit I 00 10 100	Local	2 FRU

— 04/29/2021 Key 60985 km Key 10



— 02/02/2021 Repair 55033 km 04553 Autohaus Kühnert GmbH & Co. KG , Langenwetzendorf Job

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Fremdrechnung Nr:44047 Lackierung 00000000 Flat rate unit I 99 99 999	Local	1 FRU
Fahrzeug-Verbringung Flat rate unit I 00 99 001	Local	12 FRU
Vorder- und Hinterräder montieren incl. auswuchten zwecks Vermessung Flat rate unit I 36 10 362	Local	6 FRU
Work time without specification/body Flat rate unit I 41 99 000		6 FRU
Carry out Kinematics Diagnosis System wheel alignment with vehicle load up to design position Flat rate unit I 32 00 590		16 FRU
Adjusting rear axle Flat rate unit I 32 00 620		6 FRU
Stripping and refitting work for painting doors, rear left or right Flat rate unit I 51 18 350		4 FRU
Removing and installing/replacing the sound insulation at the rear left or right door Flat rate unit I 51 48 570		6 FRU
Replacing rear left side panel Flat rate unit I 41 35 101		174 FRU
Replace rear bumper panel Flat rate unit I 51 12 657		1 FRU
Additional work with Park Distance Control Flat rate unit I 66 20 602		5 FRU
Initialising tyre failure indicator Flat rate unit I 36 11 500		1 FRU
Replace a tire with a run-flat equipment specification Flat rate unit I 36 12 506		6 FRU
Performing vehicle test		2 FRU

Flat rate unit I 00 00 556		
Supporting the voltage of the vehicle electrical system/recharging the vehicle electrical system battery Flat rate unit I 61 21 528		1 FRU
Work time without specification/body Flat rate unit I 41 99 000		16 FRU
Cavity preservation for side panel, rear left or right Flat rate unit I 97 35 601		5 FRU
Work time without specification/vehicle underbody preservation Flat rate unit I 97 99 000		6 FRU
AZ without specification/maintenance Flat rate unit I 00 99 000		3 FRU
Interior vehicle cleaning Flat rate unit I 00 11 315		6 FRU
Dezent 7X16 TD 5/120 ET35 Part I TTDP9SA35	Local	1
Fracht-u.Verpackung Felge Part I VS0000178	Local	1
Schleifmittel Part I FT000004	Local	3
Kleinersatzteile Part I 0000100	Local	1
Left rear side panel Part I 41 00 7 298 171		1
Blind plug Part I 07 14 7 127 540		1
Blind rivet N1 Part I 83 19 0 301 414		1
Blind rivet N3 Part I 83 19 0 301 421		12
Body adhesive K5 Part I 83 19 2 157 298		1
Body adhesive K5 Part I 83 19 2 158 654		1
Seam sealer Part I 83 42 2 409 985		1
Cleaner R1 Part I 83 19 2 211 217		1
Screw Part I 83 19 0 301 639		3
Punch rivet N4 Part I 83 19 2 457 307		39
Reinforcement plate, C-pillar, left Part I 41 21 7 298 191		2

Reinforcement plate, rocker panel, left Part I 41 21 7 298 207	2
Bumper trim panel, primed, rear Part I 51 12 7 384 603	1
Adhesive set K6 Part I 83 19 2 317 925	1
Kit, mount for PDC/PMA sensor, rear Part I 51 12 7 445 146	1
Guide for bumper, side, left Part I 51 12 7 384 465	1
Handle bracket, left prime-coated Part I 51 21 7 207 561	1
Lock cylinder base left Part I 51 21 7 060 667	1
Handle bracket base, left Part I 51 21 7 060 293	1
Sound insulating door rear left Part I 51 48 7 263 413	1
Covering door, primed left Part I 51 21 7 162 433	1
Cover, wheel housing, rear left Part I 51 71 7 260 293	1
Goodyear Ultra Grip 8 Performance ROF Part I 85 45 2 593 576	1
Cavity protection spray Part I 83 42 2 457 337	1
Blind rivet nut, flat headed Part I 51 24 8 226 003	1
Snap-lock coupling Part I 07 14 7 306 640	1
Rubber buffer Part I 54 34 7 166 771	1
Zub.-Stanznietgerät/Accsy. punch riveter Part I 81 43 2 209 937	1
Rep. kit, screw valve for RDCi Part I 36 10 6 876 673	1
Bump stop Part I 51 31 2 996 980	8
Mounting kit clips Part I 63 25 7 312 498	1
Battery Part I 61 31 9 217 643	1
Trunk edge protector film, transparent Part I 51 91 2 240 320	1
Plastic nut for coarse threaded pin	20

Part | 07 14 7 336 362

— 02/01/2021 Key 55025 km Key 10

23000	0	0	23000	15000	0	80000	60000	0
10/2022			637		07/2022		1368	-1 0.1 %

— 01/04/2021 Key 53499 km Key 10

24000	0	0	24000	15000	0	80000	60000	0
10/2022			665		07/2022		1396	01/2021

— 01/04/2021 Repair 53508 km 04553 Autohaus Kühnert GmbH & Co. KG , Langenwetzendorf Job Job

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Vorbereitung für Hauptuntersuchung #HU2 Flat rate unit | 99 00 002	Local	2 FRU
Abgasuntersuchung Dieselfahrz./Kat.-Fahrzeuge #AU2 Flat rate unit | 00 00 401	Local	5 FRU

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Hauptuntersuchung Dekra 00000000 Flat rate unit | 99 99 999	Local	1 FRU
Prüf- Klebesiegel Set 00000000 Flat rate unit | 99 99 999	Local	1 FRU

— 11/13/2020 Key 50272 km Key 10

28000	0	0	28000	17000	0	80000	60000	0
10/2022			717		07/2022		1448	01/2021

— 11/13/2020 Repair 50272 km 04553 Autohaus Kühnert GmbH & Co. KG , Langenwetzendorf Job Job Job Job

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Carrying out vehicle test — 4 FRU
Flat rate unit | 00 00 006

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Carrying out vehicle diagnosis, ABL — 0 FRU
Flat rate unit | 61 00 006

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

!!! unknown BMW-Id ESTIMATE CC: 00767 !!! — Local — 0 FRU
Flat rate unit | -

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

!!! unknown BMW-Id ESTIMATE Total Ausfallinstrumente sporadisch !!! — Local — 0 FRU
Flat rate unit | -

— 10/01/2020 Key 48293 km Key 10

-320	-320	-320	-320	19000	0	21000	-320	0
06/2021	272	272	272		07/2022		06/2021	01/2021

— 10/01/2020 Service 48293 km 04553 Autohaus Kühnert GmbH&Co. KG , Langenwetzendorf Automatic

-320	-320	-320	-320	19000	0	21000	-320	0
06/2021	06/2021	06/2021	06/2021		07/2022		06/2021	01/2021
✓	✓	✓	✓			✓	✓	

— 10/01/2020 Repair 48297 km 04553 Autohaus Kühnert GmbH & Job Job Job

		Co. KG , Langenwetzendorf	Job Job Job Job Job Job Job Job Job

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Rear brakes service Flat rate unit I 00 00 614	7 FRU
Repair kit, brake pads asbestos-free Part I 34 21 6 873 093	1
Brake pad wear sensor, rear Part I 34 35 6 792 292	1
Brake cleaner, acetone-free Part I 83 19 2 413 695	1
Brake pad paste Part I 83 19 2 158 851	2

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Kinematics Diagnosis System wheel alignment with ride height measurement without loading the vehicle Flat rate unit I 32 00 595	10 FRU

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Adjusting the rear axle and front axle Flat rate unit I 32 00 630	11 FRU

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Replace left and right wiper blade Flat rate unit I 61 61 541	1 FRU
Set of wiper blades	1

Part | 61 61 2 241 375

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Outside car wash and interior vehicle cleaning Flat rate unit | 00 11 329	0 FRU

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Engine oil service Flat rate unit | 00 00 610	3 FRU
BMW Engine Oil LL04 0W30 Part | 83 21 2 405 950	5.25
Set oil-filter element Part | 11 42 8 575 211	1

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Service - air filter insert Flat rate unit | 00 00 602	1 FRU
Air filter element Part | 13 71 8 605 164	1

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Service - microfilter Flat rate unit | 00 00 616	2 FRU
Microfilter/activated Carbon container Part | 64 11 9 237 555	1

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Spark plugs service Flat rate unit | 00 00 622	11 FRU

Hex bolt with washer Part I 31 10 6 854 219	2
Spark plug, High Power Part I 12 12 0 040 551	4
Torx screw with collar Part I 07 14 7 270 121	2

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Vehicle check service Flat rate unit I 00 00 624	6 FRU
Standard scope of service Flat rate unit I 00 00 105	2 FRU
Windshield Washer Antifreeze Part I 83 12 2 413 058	1

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Installing navigation map(s) Flat rate unit I 65 90 600	2 FRU

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Ersatzwagen Bonusheft 00000000 Flat rate unit I 99 99 999	Local	1 FRU

— 07/02/2020 Key 44099 km 04553 Key 10

6000 06/2021	6000 329	6000 329	6000 329	24000	-31 4.2 %	26000	6000 06/2021	01/2021

— 07/02/2020 Service 44099 km 04553 Autohaus Kühnert GmbH&Co. KG , Langenwetzendorf Automatic

6000 06/2021	6000 06/2021	6000 06/2021	6000 06/2021	24000	0 06/2020 ✓	26000	6000 06/2021	0 01/2021

—	07/02/2020	Repair	44104 km	04553 Autohaus Kühnert GmbH & Co. KG , Langenwetzendorf	Job Job

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Standard scope of service Flat rate unit I 00 00 105	2 FRU

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Brake fluid service Flat rate unit I 00 00 618	4 FRU
Brake fluid DOT4 LV, low viscosity Part I 83 13 2 184 843	1

—	06/28/2019	Key	22527 km	04553	Key 10

2300 06/2019	0	0	2300 2	40000	0 06/2020	42000	28000 06/2021	0 01/2021

—	06/28/2019	Service	22527 km	04553 Autohaus Kühnert GmbH&Co. KG , Greiz	Automatic

2300 06/2019 ✓	0	0	2300 06/2019 ✓	40000	0 06/2020	42000	28000 06/2021	0 01/2021

—	06/28/2019	Repair	22598 km	04553 Autohaus Kühnert GmbH & Co. KG , Langenwetzendorf	Job Job Job Job

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Standard scope of service Flat rate unit I 00 00 105	2 FRU

Washer fluid, concentrated 1
Part | 83 12 2 298 203

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Service - microfilter 2 FRU
Flat rate unit | 00 00 616

Microfilter/activated Carbon container 1
Part | 64 11 9 237 555

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Engine oil service 3 FRU
Flat rate unit | 00 00 610

Set oil-filter element 1
Part | 11 42 8 575 211

BMW Engine Oil LL04 0W30 5.25
Part | 83 21 2 405 950

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Installing navigation map(s) 4 FRU
Flat rate unit | 65 90 600

— 03/25/2019 Key 17619 km 04111 Key 10

9000	0	0	9000	45000	0	47000	35000	0
06/2019			97		06/2020		06/2021	01/2021

— 03/25/2019 Repair 17620 km 04111 Autohaus Fiebig GmbH , Jena Job

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Remove and install/replace vehicle exterior mirror on left or right front door — 6 FRU
Flat rate unit | 51 16 000

heated outside mirror, right — 1
Part | 51 16 7 459 092

— 03/14/2019 Key 16962 km 04111 Key 10

10000	0	0	10000	46000	0	47000	36000	0
06/2019			108		06/2020		06/2021	01/2021

— 03/14/2019 Repair 16962 km 04111 Autohaus Fiebig GmbH , Jena Job

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Removing and installing/replacing cover cap on exterior mirror, left and right — 4 FRU
Flat rate unit | 51 16 043

— 03/08/2019 Key 16893 km Key 10

10000	0	0	10000	46000	0	47000	36000	0
06/2019			113		06/2020		06/2021	01/2021

— 02/11/2019 Key 15867 km 04111 Key 10

11000	0	0	11000	46000	0	48000	38000	0
06/2019			139		06/2020		06/2021	01/2021

— 01/21/2019 Key 14083 km 04111 Key 10

13000	0	0	13000	46000	0	47000	40000	0
06/2019			160		06/2020		06/2021	01/2021

— 01/21/2019 Repair 14083 km 04111 Autohaus Fiebig GmbH , Jena Job

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Lackierungskosten Flat rate unit I 99 99 999	Local	1 FRU
Work time without specification/body equipment Flat rate unit I 51 99 000		2 FRU
Removing and installing front bumper panel Flat rate unit I 51 11 656		9 FRU
Replace bumper cover, front Flat rate unit I 51 11 592		12 FRU
Replacing right headlight Flat rate unit I 63 12 509		7 FRU
Adjusting headlights Flat rate unit I 63 10 502		2 FRU
Removing and installing/replacing front left or right wheel arch cover Flat rate unit I 51 71 538		4 FRU
Performing vehicle test Flat rate unit I 00 00 556		2 FRU
Work time without specification/body equipment Flat rate unit I 51 99 000		3 FRU
Trim cover, bumper, primed, front Part I 51 11 7 445 135		1
Headlight with LED technology, right Part I 63 11 7 419 634		1
Partially open grid, right Part I 51 11 7 396 888		1
Mount, side wall front, lower left Part I 51 11 7 279 711		1
Mount, side wall front, lower right Part I 51 11 7 279 712		1
Mount, side wall front, upper right Part I 51 11 7 255 362		1
Badge Part I 51 76 7 288 752		1
Support, fog lamp right Part I 51 11 7 386 362		1
Badge Part I 51 76 7 288 752		1
Air inlet finisher, right Part I 51 11 7 396 854		1
Finisher, rod, center Part I 51 11 7 396 831		1

— 01/14/2019 Key 13813 km Key 10

13000	0	0	13000	46000	0	48000	40000	0		
06/2019			166		06/2020		06/2021	01/2021		

— 10/10/2018 Key 9163 km Key 10

20000	0	0	20000	47000	0	49000	48000	0	
06/2019			263		06/2020		06/2021	01/2021	

— 09/24/2018 Key 8705 km Key 10

20000	0	0	20000	47000	0	49000	48000	0	
06/2019			278		06/2020		06/2021	01/2021	

— 09/20/2018 Key 8705 km Key 10

20000	0	0	20000	47000	0	49000	48000	0	
06/2019			283		06/2020		06/2021	01/2021	

— 09/20/2018 Repair 8705 km 04111 Autohaus Fiebig GmbH , Jena Job

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Lackierungskosten Flat rate unit I 99 99 999	Local	1 FRU
Work time without specification/body equipment Flat rate unit I 51 99 000		2 FRU
Carry out Kinematics Diagnosis System wheel alignment with vehicle load up to design position Flat rate unit I 32 00 590		16 FRU
Removing and installing front left side panel Flat rate unit I 41 35 581		8 FRU
Removing and installing front bumper panel Flat rate unit I 51 11 656		9 FRU
Removing and installing/replacing support for front bumper cover Flat rate unit I 51 11 551		10 FRU
Replace bumper cover, front Flat rate unit I 51 11 592		12 FRU

Replacing headlight, left or right Flat rate unit I 63 12 532	4 FRU
Adjusting headlights Flat rate unit I 63 10 502	2 FRU
Removing and installing bonnet Flat rate unit I 41 61 600	3 FRU
Replace hood Flat rate unit I 41 61 501	6 FRU
Work time without specification/body equipment Flat rate unit I 51 99 000	1 FRU
Remove and install/replace left or right side sill trim panel Flat rate unit I 51 71 947	4 FRU
Replace a tire with a run-flat equipment specification Flat rate unit I 36 12 506	6 FRU
Initialising tyre failure indicator Flat rate unit I 36 11 500	1 FRU
Performing vehicle test Flat rate unit I 00 00 556	2 FRU
Work time without specification/body Flat rate unit I 41 99 000	5 FRU
Work time without specification/wheels Flat rate unit I 36 99 000	0 FRU
Work time without specification/vehicle underbody preservation Flat rate unit I 97 99 000	3 FRU
Cavity sealant for hood Flat rate unit I 97 61 501	2 FRU
Trim cover, bumper, primed, front Part I 51 11 7 445 135	1
Hood Part I 41 00 7 290 944	1
Finisher, rod, center Part I 51 11 7 396 831	1
Insert, air intake, center Part I 51 11 7 386 152	1
Partially open grid, left Part I 51 11 7 396 887	1
Mount, side wall front, lower left Part I 51 11 7 279 711	1
Mount, side wall front, upper left Part I 51 11 7 255 361	1
Air inlet finisher, left Part I 51 11 7 396 853	1
Mount, bumper, front, top Part I 51 11 7 255 393	1

Shock absorber front Part I 51 11 7 396 916	1
Badge Part I 51 76 7 288 752	1
Front engine hood sealing Part I 51 76 7 255 802	1
Headlight, LED technology, left Part I 63 11 7 419 633	1
Front fog lamp, LED, left Part I 63 17 7 315 559	1
Support, fog lamp left Part I 51 11 7 386 361	1
Inscription, side Part I 51 14 7 418 528	1
Cover, wheelhousing, fr. sec., front lft Part I 51 71 7 260 725	1
Horn, low pitch Part I 61 33 7 400 706	1
Set of LED modules Part I 63 11 7 419 615	1
Control unit for front light electronics Part I 63 11 8 494 844	1
Support left Part I 51 64 7 245 791	1
Side panel bracket, front left 2 Part I 41 35 7 298 037	1
Label, coolant Part I 71 23 6 995 663	1
LED module turn signal left Part I 63 11 7 419 619	1
Expanding rivet Part I 51 16 1 881 149	3
Air duct, brake, left Part I 51 74 7 396 939	1

—	07/26/2018	Repair	6678 km	04553 Autohaus Kühnert GmbH & Co. KG , Langenwetzendorf	Job

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Auslieferungsdurchsicht für Gebrauchtwagen laut Checkliste Flat rate unit I 00 00 011	Local	12 FRU

Kennzeichen VFW / Kd. V-SK 136 - falsch geprägt Part I VS0000100	Local	1
FEINSTAUBPLAKETTE PM 2-4 Part I VS0000110	Local	1

— 06/06/2018 Repair 4033 km 04553 Autohaus Kühnert GmbH & Co. KG , Langenwetzendorf Job Job

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Carrying out vehicle test Flat rate unit I 00 00 006	4 FRU

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Work time without specification / vehicle electrical system Flat rate unit I 61 99 000	6 FRU

— 06/05/2018 Key 4032 km 04553 Key 1

26000 06/2019	0	0	26000 389	49000	0 06/2020	49000	60000 06/2021	0 01/2021

— 05/31/2018 Key 4015 km 04553 Key 1

26000 06/2019	0	0	26000 395	49000	0 06/2020	49000	60000 06/2021	0 01/2021

— 05/29/2018 Key 3521 km 04553 Key 1

27000 06/2019	0	0	27000 397	49000	0 06/2020	49000	60000 06/2021	0 01/2021

— 05/25/2018 Key 3272 km 04553 Key 1

27000 06/2019	0	0	27000 401	49000	0 06/2020	49000	60000 06/2021	0 01/2021		
— 05/23/2018	Key			3257 km		04553		Key 1		
27000 06/2019	0	0	27000 402	49000	0 06/2020	49000	60000 06/2021	0 01/2021		
— 05/18/2018	Key			3175 km		04553		Key 1		
27000 06/2019	0	0	27000 408	49000	0 06/2020	49000	60000 06/2021	0 01/2021		
— 05/15/2018	Key			2914 km		04553		Key 1		
27000 06/2019	0	0	27000 410	49000	0 06/2020	49000	60000 06/2021	0 01/2021		
— 05/09/2018	Key			2907 km		04553		Key 1		
27000 06/2019	0	0	27000 416	49000	0 06/2020	49000	60000 06/2021	0 01/2021		
— 05/08/2018	Key			2865 km		04553		Key 1		
27000 06/2019	0	0	27000 418	49000	0 06/2020	49000	60000 06/2021	0 01/2021		
— 05/08/2018	Repair			3257 km		04553 Autohaus Kühnert GmbH & Co. KG , Langenwetzendorf		Job		

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Detaching and attaching the front and rear wheels 6 FRU
Flat rate unit | 36 10 360

—	04/27/2018	Key	2584 km	07321	Key 1

28000	0	0	28000	49000	0	49000	60000	0
06/2019			428		06/2020		06/2021	01/2021

—	04/12/2018	Key	2449 km	07321	Key 1

28000	0	0	28000	49000	0	49000	60000	0
06/2019			443		06/2020		06/2021	01/2021

—	04/10/2018	Key	2366 km	04553	Key 1

28000	0	0	28000	49000	0	49000	60000	0
06/2019			446		06/2020		06/2021	01/2021

—	04/06/2018	Key	2307 km	04553	Key 1

28000	0	0	28000	49000	0	49000	60000	0
06/2019			449		06/2020		06/2021	01/2021

—	04/05/2018	Key	2211 km	04553	Key 1

28000	0	0	28000	49000	0	49000	60000	0
06/2019			457		06/2020		06/2021	01/2021

—	03/28/2018	Key	2199 km	04553	Key 1

28000	0	0	28000	49000	0	49000	60000	0
06/2019			458		06/2020		06/2021	01/2021

—	03/27/2018	Key	1799 km	04553	Key 1

28000	0	0	28000	49000	0	49000	60000	0
06/2019			460		06/2020		06/2021	01/2021

—	03/23/2018	Key	1768 km	04553	Key 1

28000	0	0	28000	49000	0	49000	60000	0		
06/2019			463		06/2020		06/2021	01/2021		
—	03/19/2018	Key			1616 km		04553		Key 1	
29000	0	0	29000	49000	0	49000	60000	0		
06/2019			467		06/2020		06/2021	01/2021		
—	03/17/2018	Key			1591 km		04553		Key 1	
29000	0	0	29000	49000	0	49000	60000	0		
06/2019			470		06/2020		06/2021	01/2021		
—	03/16/2018	Key			1438 km		04553		Key 1	
29000	0	0	29000	49000	0	49000	60000	0		
06/2019			471		06/2020		06/2021	01/2021		
—	03/15/2018	Key			1387 km		04553		Key 1	
29000	0	0	29000	49000	0	49000	60000	0		
06/2019			472		06/2020		06/2021	01/2021		
—	03/09/2018	Key			1361 km		04553		Key 1	
29000	0	0	29000	49000	0	49000	60000	0		
06/2019			477		06/2020		06/2021	01/2021		
—	03/06/2018	Key			1310 km		04553		Key 1	
29000	0	0	29000	49000	0	49000	60000	0		
06/2019			480		06/2020		06/2021	01/2021		
—	03/01/2018	Key			1167 km		04553		Key 1	
29000	0	0	29000	49000	0	49000	60000	0		
06/2019			485		06/2020		06/2021	01/2021		

—	03/01/2018	Key	1120 km	04553	Key 1									
	29000	0	0	29000		49000	0	49000	60000		0			
	06/2019			486			06/2020		06/2021		01/2021			
—	02/28/2018	Key	1027 km	04553	Key 1									
	29000	0	0	29000		50000	0	50000	60000		0			
	06/2019			487			06/2020		06/2021		01/2021			
—	02/26/2018	Key	904 km	04553	Key 1									
	29000	0	0	29000		50000	0	50000	60000		0			
	06/2019			488			06/2020		06/2021		01/2021			
—	02/22/2018	Key	880 km	04553	Key 1									
	29000	0	0	29000		50000	0	50000	60000		0			
	06/2019			492			06/2020		06/2021		01/2021			
—	02/14/2018	Key	845 km	04553	Key 1									
	30000	0	0	30000		50000	0	50000	60000		0			
	06/2019			500			06/2020		06/2021		01/2021			
—	02/12/2018	Key	750 km	04553	Key 1									
	30000	0	0	30000		50000	0	50000	60000		0			
	06/2019			503			06/2020		06/2021		01/2021			
—	02/12/2018	Key	724 km	04553	Key 1									
	30000	0	0	30000		50000	0	50000	60000		0			
	06/2019			503			06/2020		06/2021		01/2021			
—	02/02/2018	Key	482 km	04553	Key 1									

30000	0	0	30000	50000	0	50000	60000	0		
06/2019			512		06/2020		06/2021	01/2021		
—	02/02/2018	Key			456 km		04553		Key 1	
30000	0	0	30000	50000	0	50000	60000	0		
06/2019			512		06/2020		06/2021	01/2021		
—	01/31/2018	Key			390 km		04553		Key 1	
30000	0	0	30000	50000	0	50000	60000	0		
06/2019			514		06/2020		06/2021	01/2021		
—	01/29/2018	Key			357 km		04553		Key 1	
30000	0	0	30000	50000	0	50000	60000	0		
06/2019			516		06/2020		06/2021	01/2021		
—	01/26/2018	Key			326 km		04553		Key 1	
30000	0	0	30000	50000	0	50000	60000	0		
06/2019			519		06/2020		06/2021	01/2021		
—	01/23/2018	Key			185 km		04553		Key 1	
30000	0	0	30000	50000	0	50000	60000	0		
06/2019			522		06/2020		06/2021	01/2021		
—	01/12/2018	Key			185 km		04553		Key 1	
30000	0	0	30000	50000	0	50000	60000	0		
06/2019			534		06/2020		06/2021	01/2021		
—	01/08/2018	Key			27 km		04553		Key 1	
30000	0	0	30000	50000	0	50000	60000	0		
06/2019			537		06/2020		06/2021	01/2021		

—	01/05/2018	Repair	0 km	04553 Autohaus Kühnert GmbH & Co. KG , Langenwetzendorf	Job

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Detaching and attaching the front and rear wheels Flat rate unit | 36 10 360	6 FRU
Fillister head self-tapping screw Part | 07 14 3 448 498	6
Windshield Washer Antifreeze Part | 83 12 2 413 058	3

—	01/03/2018	Repair	0 km	07321 Autohaus Kühnert GmbH & Co. KG , Schleiz	Job

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Free pre-delivery check Flat rate unit | 00 00 009	12 FRU

—	06/22/2017	Repair	0 km	07321 Autohaus Kühnert GmbH & Co. KG , Schleiz	Job

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Transportmodus für Ausstellung zurücksetzen Flat rate unit | 00 00 003	Local	4 FRU
Work time without specification/wheels Flat rate unit | 36 99 000		1 FRU
Phillips screw f plastic material Part | 07 14 6 959 895		10
Set wheel locks Part | 36 13 6 776 076		1