

Vehicle

BMW 320d, 140kW

WBA8Y71010G399119



Development code	F34
Color	sparkling-brown metallic
Actual integration level	F020-22-07-530
Start of warranty	April 28, 2016

▼ Technical Campaigns

There are no campaigns available.

▼ Special information

There are no campaigns available.

▼ Live Diagnosis

 There are no service solutions for Live Diagnosis.

▼ Service contracts

No BSI contracts available

You can find additional service contract information and selection options in the DCSNet warranty vehicle enquiry.

▼ Information on faults, workshop/Service Consultation

No information on faults is available.

▼ Navigation map

Installed map	Enabling code (subscription)	Latest navigation map included in subscription	Latest navigation map subject to charge
Road Map EUROPE WEST Route 2022-1 (as of: May 21, 2025)	Release code valid for navigation maps with release date up to Dec 31, 2025 (SWID: 00B4008F).	Road Map EUROPE WEST Route 2025	-

▼ Vehicle details

Vehicle type	Passenger car
--------------	---------------

Brand	BMW
Model	320d
Body	SAT
Vehicle identification number (last 7 characters)	G399119
Vehicle identification number (17 characters)	WBA8Y71010G399119
Development code	F34
Steering	LL
Engine	B47O
Engine number	68249590
Exhaust re-treatment	EURO6;W;PI/Ci; M, N1 I
Transmission	AUT
Transmission number	0388458ZRI
Head unit serial number	MM01DFG1513397
Drive	HECK
Integration level	F020-16-03-503
Production date	Apr 14, 2016
Production works	Dingolfing
Delivery date	Apr 18, 2016
Delivering Retailers	No information
National-market version	EUR
Paint code	B53
Upholstery code	BEL2
Model code	8Y81
Base type	8Y71
Lead type	8Y81

▾ Optional equipment

Optional equipment fitted at the factory:

01CA Selection of COP relevant vehicles
 01CB CO2 package
 0205 Automatic transmission
 0216 Hydro steering-servotronic
 0230 Extra package, EU-specific
 0255 Sports leather steering wheel
 0258 Tire with run-flat functionality
 02A5 BMW LA wheel, Double Spoke 397
 02VB Tire pressure display
 03AC Trailer coupling
 0420 Sun protection glazing


Retrofitted optional equipment:

This vehicle has no retrofits.

0423 Floor mats, velours
 0428 Warning triangle and first aid kit
 0431 Interior mirror with automatic-dip
 0481 Sports seat
 0493 Storage compartment package
 0494 Seat heating driver/passenger
 04AE Armrest front, retractable
 04LV Black high-gloss, korall-rot accent
 0502 Headlight cleaning system
 0507 Park Distance Control (PDC), rear
 0520 Fog lights
 0521 Rain sensor
 0522 Xenon Light
 0534 Automatic air conditioning
 0544 Cruise control with braking function
 0548 Kilometer-calibrated speedometer
 0563 Lights package
 0575 Supplementary 12V sockets
 05DA Passenger airbag deactivation
 0606 Navigation system Business
 0676 HiFi speaker system
 0698 Area-Code 2 for DVD
 06AC Intelligent emergency SOS call
 06AE Teleservices
 06NH Hands-free with USB interface
 06WA Instrument cluster, expanded equipment
 07AC Sport Line
 07LD Modell Sport Line
 0801 German version
 0851 Language version German
 0879 On-board vehicle literature German
 08KA Oil service interval, 24 mos./30,000 km
 08TF Active pedestrian protection
 09AA Outer skin protection
 A090 90 AH AGM battery
 POLS Cloth cushion

▾ Vehicle histories


Date	Type	Vehicle mileage	Dealer	Overview
— 07/13/2026	Service	202600 km	OSS-60135299 SSK Fahrzeugservice GbR Mühlhäuser & Weil, Zell	Automatic
 1900 11/2026 ✓   1900 11/2026 ✓   80000  05/2027  05/2027  80000  33000 11/2028   				
— 04/08/2026	Service	198485 km	OSS-50027644 Gebr. Welchner GmbH, Zell u. A.	Automatic



— 05/21/2025 Service 181177 km OSS-50027644 Manual
Gebr. Welchner GmbH, Zell u. A.




— 11/20/2024 Service 172336 km OSS-50027644 Manual
Gebr. Welchner GmbH, Zell u. A.




— 11/19/2024 Service 172333 km OSS-50027644 Manual
Gebr. Welchner GmbH, Zell u. A.



— 10/05/2023 Key 152268 km 51646 Key 1



— 05/05/2023 Key 143108 km Key 1



— 05/05/2023 Service 143108 km 51646 Automatic
Autohaus Kühnert

 27000	 27000	 27000	 27000	 60000	 0	 0	 18000	 27000
					✓			

—	05/05/2023	Repair	143108 km	51646	Job
				Autohaus	Job
				Kühnert GmbH	Job
				& Co. KG ,	Job
				Plauen	

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Vorbereitung für Flat rate unit I 99 00 002	Local	2 FRU
Abgasuntersuchung Flat rate unit I 00 00 401	Local	5 FRU

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Standard scope of service Flat rate unit I 00 00 105		2 FRU
---	--	-------

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Brake fluid service Flat rate unit I 00 00 618		4 FRU
Brake fluid DOT4 LV, low viscosity Part I 83 13 2 184 843		1

— Job


Description:

Is interpreted as a repeat visit: No


Customer's own words:

Hauptuntersuchung TÜV Flat rate unit I 99 99 999	Local	1 FRU
Prüf- Klebesiegel Set Flat rate unit I 99 99 999	Local	1 FRU

— 02/20/2023 Key 141423 km Key 1



— 02/20/2023 Service 141423 km 51646 Automatic
Autohaus
Kühnert
GmbH&Co. KG
, Plauen



— 02/20/2023 Repair 141423 km 51646 Job
Autohaus Job
Kühnert GmbH Job
& Co. KG ,
Plauen

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Standard scope of service 2 FRU
Flat rate unit I 00 00 105

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Engine oil service 3 FRU
Flat rate unit I 00 00 610

BMW Engine Oil LL04 0W30 5
Part I 83 21 2 405 950

Set oil-filter element 1
Part I 11 42 8 575 211

Battery 1
Part I 61 31 9 217 643

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Service - microfilter 2 FRU

Flat rate unit I 00 00 616

Microfilter/activated Carbon container
Part I 64 11 9 237 555

1

— 02/08/2023 Key 141395 km Key 1

 -2300 7.9 % 05/2023	 05/2023	 -2300 05/2023	 05/2023	 70000	 04/2023	 04/2023	 19000	 27000 05/2025
--	--	---	--	--	--	--	---	---

— 08/29/2022 Key 135370 km Key 1

 4000 05/2023	 05/2023	 4000 05/2023	 05/2023	 70000	 04/2023	 04/2023	 24000	 35000 05/2025
--	--	--	--	--	--	--	---	---

— 08/29/2022 Repair 135370 km 51646 Job
Autohaus Job
Kühnert GmbH
& Co. KG ,
Plauen

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Remove and install/replace left and right fanfare horns 5 FRU
Flat rate unit I 61 33 060

Horn, low pitch 1
Part I 61 33 7 245 422

Horn, high pitch 1
Part I 61 33 7 245 423

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Installing navigation map(s) 1 FRU
Flat rate unit I 65 90 600

— 10/12/2021 Key 120201 km Key 0

 20000 05/2023	 05/2023	 20000 559	 05/2023	 70000	 04/2023	 36000	 50000 1279
---	--	---	--	--	--	--	---

—	10/12/2021	Repair	120201 km	23429 Autohaus Strauß GmbH , Plauen	Job
---	------------	--------	-----------	--	-----

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Service consultation at the vehicle with service ticket Flat rate unit I 00 52 052	0 FRU
---	-------

Enable code HU-B Nav map Eur. Route Upd. Part I 65 90 2 409 897	1
--	---

—	09/15/2021	Key	117401 km	Key 0
---	------------	-----	-----------	-------

								
22000		22000		70000		39000		60000
05/2023		586			04/2023			1306

—	09/15/2021	Repair	117401 km	23429 Autohaus Strauß GmbH , Plauen	Job
---	------------	--------	-----------	--	-----

— Job

Description: LWR ausgefallen

Is interpreted as a repeat visit: No

Customer's own words:

Service consultation at the vehicle with service ticket Flat rate unit I 00 52 052	0 FRU
---	-------

Carrying out vehicle test Flat rate unit I 00 00 006	5 FRU
---	-------

Removing and installing/replacing rear left or right wheel arch cover Flat rate unit I 51 71 541	4 FRU
---	-------

Program/encode control unit(s), includes deleting the fault memory Flat rate unit I 61 00 730	6 FRU
--	-------


Schrumpfschlauch Part I FT99 77 1 004 8	Local	3
--	-------	---

Cable connector Part I 61 13 8 353 747	3
---	---

—	07/01/2021	Key	113401 km	Key 0
---	------------	-----	-----------	-------



—	07/01/2021	Service	113401 km	23429 Autohaus Strauß GmbH , Plauen	Automatic
---	------------	---------	-----------	--	-----------



—	07/01/2021	Repair	113408 km	23429 Autohaus Strauß GmbH , Plauen	Job
---	------------	--------	-----------	--	-----

— Job

Description: Beide Bremsscheiben vorn aus- und einbauen/ ersetzen

Is interpreted as a repeat visit: No

Customer's own words:

Removing and installing/replacing both front brake discs Flat rate unit I 34 11 220	4 FRU
--	-------

Standard scope of service Flat rate unit I 00 00 105	2 FRU
---	-------

Service - front brakes Flat rate unit I 00 00 612	9 FRU
--	-------

Brake pad wear sensor, front left Part I 34 35 6 792 289	1
---	---

Brake pad paste Part I 83 19 2 158 851	2
---	---

Repair kit, brake pads asbestos-free Part I 34 10 6 859 181	1
--	---

Inner hex bolt Part I 34 21 1 161 806	2
--	---

Brake cleaner, acetone-free Part I 83 19 2 413 695	1
---	---

Brake disc, ventilated Part I 34 11 6 792 219	2
--	---

Torx screw with washer Part I 34 10 6 864 424	4
--	---

—	06/22/2021	Key	112318 km	Remote KeyRead
---	------------	-----	-----------	----------------

							
27000		27000		1800	04/2023	42000	60000
05/2023		669					1389

— 05/20/2021 Key 109257 km Key 0

							
-50	-50	-50	-50	14000	04/2023	44000	-50
02/2022	251	251	251				02/2022

— 05/20/2021 Service 109257 km 23429 Automatic
Autohaus
Strauß GmbH ,
Plauen

							
-50	-50	-50	-50	14000	0	44000	-50
✓	✓	✓	✓				✓

— 05/20/2021 Repair 109257 km 23429 Job
Autohaus Job
Strauß GmbH , Job
Plauen Job
Job
Job

— Job

Description: Standardumfang

Is interpreted as a repeat visit: No

Customer's own words:

Service consultation at the vehicle with service ticket 0 FRU
Flat rate unit I 00 52 052

— Job

Description: Motoröl

Is interpreted as a repeat visit: No

Customer's own words:

Standard scope of service 2 FRU
Flat rate unit I 00 00 105

Engine oil service 3 FRU
Flat rate unit I 00 00 610

GUTSCHEIN 25€ HU/AU Kampagne Local -1
Part I GUTSCHEIN4

Scheibenklar Local 1
Part I FT99 22 9 407 7

Set oil-filter element 1
Part I 11 42 8 575 211

— Job

Description: Kraftstofffilter

Is interpreted as a repeat visit: No

Customer's own words:

Fuel filter service Flat rate unit I 00 00 604	3 FRU
---	-------

Hose clamp Part I 07 12 9 952 104	1
--------------------------------------	---

Fuel filter cartridge Part I 13 32 8 572 522	1
---	---

— Job

Description: Luftfiltereinsatz

Is interpreted as a repeat visit: No

Customer's own words:

Service - air filter insert Flat rate unit I 00 00 602	2 FRU
---	-------

Air filter element Part I 13 71 8 511 668	1
--	---

— Job

Description: Mikrofilter (ggf. weiter Zusatzarbeit(en) beachten)

Is interpreted as a repeat visit: No

Customer's own words:

Service - microfilter Flat rate unit I 00 00 616	2 FRU
---	-------

Microfilter/activated Carbon container Part I 64 11 9 237 555	1
--	---

— Job

Description: Fahrzeug-Check

Is interpreted as a repeat visit: No


Customer's own words:

Vehicle check service Flat rate unit I 00 00 624	6 FRU
---	-------

— 04/29/2021 Key

107962 km

Key 0



—	04/29/2021	Service	107962 km	23429 Autohaus Strauß GmbH , Plauen	Automatic
---	------------	---------	-----------	--	-----------

1400	1400	1400	1400	16000	1400	47000	1400
01/2022	01/2022	01/2022	01/2022	04/2021	01/2022	01/2022	01/2022

—	04/29/2021	Repair	107962 km	23429 Autohaus Strauß GmbH , Plauen	Job Job
---	------------	--------	-----------	--	------------

— Job

Description: Bremsflüssigkeit

Is interpreted as a repeat visit: No

Customer's own words:

Standard scope of service Flat rate unit I 00 00 105	2 FRU
Brake fluid service Flat rate unit I 00 00 618	4 FRU
!!! unknown BMW-Id 99229407513 Bremsflüssigkeit !!! Part I 99 22 9 407 513	Local 1

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Abgasuntersuchung 2-jährig DEKRA Flat rate unit I AU2 EXT	Local 4 FRU
Bereitstellen zur Hauptuntersuchung Flat rate unit I -	Local 1 FRU
Preliminary check to statutory vehicle inspection Flat rate unit I 00 12 600	5 FRU

—	04/09/2021	Key	107801 km	Remote KeyRead
---	------------	-----	-----------	----------------

1600	1600	1600	1600	16000	-8 1.1 %	47000	1600
02/2022	292	292	292	02/2022	02/2022	02/2022	02/2022

—	06/03/2020	Key	87135 km	23429	Key 0
---	------------	-----	----------	-------	-------

							
23000	23000	23000	23000	34000	23000	4500	23000
02/2022	598	598	598		04/2021		02/2022

— 06/03/2020 Service 87135 km 23429 Manual
Autohaus
Strauß GmbH,
Plauen

									
						✓			

— 06/03/2020 Repair 87135 km 23429 Job
Autohaus
Strauß GmbH ,
Plauen

— Job

Description: Bremse H prüfen

Is interpreted as a repeat visit: No

Customer's own words:

Removing and installing/renewing both brake discs 12 FRU
Flat rate unit I 34 21 320

Brake disc, ventilated 2
Part I 34 21 6 864 900

Inner hex bolt 2
Part I 34 21 1 161 806

Brake pad wear sensor, rear 1
Part I 34 35 6 792 292

Repair kit, brake pads asbestos-free 1
Part I 34 21 6 873 093

Brake pad paste 2
Part I 83 19 2 158 851

Brake cleaner 2.0 1
Part I 83 19 2 365 214

— 05/25/2020 Key 87051 km 23429 Key 0

							
23000	23000	23000	23000	34000	23000	4600	23000
02/2022	606	606	606		04/2021		02/2022

— 02/11/2020 Service 81453 km 23429 Manual
Autohaus
Strauß GmbH,
Plauen



— 02/10/2020 Key 81453 km 23429 Key 0



— 02/10/2020 Repair 81453 km 23429
Autohaus
Strauß GmbH ,
Plauen Job: Service Motoröl
Job: Service Mikrofilter
Job
Job

— Job: Service Motoröl

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Service Motoröl

Package I 000061018Y810

Engine oil service	3
Flat rate unit I 00 00 610	
Set oil-filter element	1
Part I 11 42 8 575 211	
BMW Engine Oil LL04 0W30	5
Part I 83 21 2 405 950	

— Job: Service Mikrofilter

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Service Mikrofilter

Package I 000061618Y810

Service - microfilter	2
Flat rate unit I 00 00 616	
Microfilter/activated Carbon container	1
Part I 64 11 9 237 555	

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

!!! unknown BMW-Id ESTIMATE Standardumfang !!! Local 0 FRU
Flat rate unit I -

Standard scope of service
Flat rate unit I 00 00 105

2 FRU

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

!!! unknown BMW-Id ESTIMATE 03741/221977 !!!
Flat rate unit I -

Local

0 FRU

— 02/10/2020 Repair 81453 km 23429 Autohaus Strauß GmbH, Plauen Job Job

— Job

Description: Erreichbar unter

Is interpreted as a repeat visit: No

Customer's own words:

Service consultation at the vehicle with service ticket
Flat rate unit I 00 52 052

0 FRU

— Job

Description: Service Motoröl

Is interpreted as a repeat visit: No

Customer's own words:

Engine oil service 3 FRU
Flat rate unit I 00 00 610

Service - microfilter 2 FRU
Flat rate unit I 00 00 616








Standard scope of service 2 FRU
Flat rate unit I 00 00 105

Set oil-filter element 1
Part I 11 42 8 575 211

BMW Engine Oil LL04 0W30 5
Part I 83 21 2 405 950

Microfilter/activated Carbon container 1
Part I 64 11 9 237 555

— 09/04/2019 Key 70987 km 23429 Key 0



— 09/04/2019 Repair 70987 km 23429 Autohaus Job Job

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

alle Flüssigkeitsstände prüfen und ergänzen JA: NEIN:X Flat rate unit I AW00 00 2	Local	0 FRU
Service consultation at the vehicle with service ticket Flat rate unit I 00 52 052		0 FRU

— Job

Description: TA AGR-Kühler

Is interpreted as a repeat visit: No

Customer's own words:

Additional work, check EGR cooler label Flat rate unit I 00 67 703		1 FRU
Replace exhaust-gas recirculation cooler and replace or remount exhaust-gas recirculation valve; clean exhaust gas recirculation pipe Flat rate unit I 00 66 955		28 FRU
Additional work, perform pressure sensor system function Flat rate unit I 00 67 695		3 FRU
Kühlerfrostschutz Part I FT99 22 9 407 4	Local	4
exhaust cooler Part I 11 71 8 596 444		1
Set of small parts Part I 11 71 8 597 652		1
Pipe union Part I 11 71 7 799 853		2
O-ring Part I 11 61 8 512 681		1
Oval head screw Part I 35 21 7 685 343		2

— Job

Description: O-Ton, Motor ruckelt bei 50 Km/h

Is interpreted as a repeat visit: No

Customer's own words:

Performing vehicle test Flat rate unit I 00 00 556		2 FRU
Supporting the voltage of the vehicle electrical system/recharging the vehicle electrical system battery Flat rate unit I 61 21 528		1 FRU

3 FRU

1

—	04/16/2019 Service	63096 km	23429 Autohaus Strauß GmbH, Plauen	Manual

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

alle Flüssigkeitsstände prüfen und ergänzen JA: NEIN:X Flat rate unit I AW00 00 2	Local	0 FRU
Service consultation at the vehicle with service ticket Flat rate unit I 00 52 052		0 FRU

— Job

Description: Unfallschaden instandsetzen

Is interpreted as a repeat visit: No

Customer's own words:

Assessment of vehicle involved in an accident Flat rate unit I 41 00 001	2 FRU
Removing and installing front bumper panel Flat rate unit I 51 11 656	9 FRU
Removing and installing/replacing both supports for bumper cover, front Flat rate unit I 51 11 566	13 FRU
Replacing center pedestrian protection sensor Flat rate unit I 65 76 607	1 FRU
Replacing pedestrian protection sensor (fiber optic cable) Flat rate unit I 65 76 626	2 FRU
Replace bumper cover, front Flat rate unit I 51 11 592	11 FRU
Additional work, headlight cleaning system Flat rate unit I 61 67 803	3 FRU

Replacing all cooling air routings for coolant radiator Flat rate unit I 51 71 600	6 FRU
Removing and installing left and right headlights Flat rate unit I 63 12 826	8 FRU
Replacing headlight, left or right Flat rate unit I 63 12 524	4 FRU
Replacing headlight, left or right Flat rate unit I 63 12 524	4 FRU
Removing and installing bonnet Flat rate unit I 41 61 510	5 FRU
Removing and installing or replacing insulation sheet on engine hood Flat rate unit I 51 48 501	2 FRU
Discharging, evacuating and filling air conditioner Flat rate unit I 64 50 509	6 FRU
Removing and installing coolant radiator Flat rate unit I 17 11 510	14 FRU
Removing and installing or replacing charge air cooler Flat rate unit I 17 51 550	2 FRU
Removing and installing/replacing air conditioning condenser Flat rate unit I 64 53 550	1 FRU
Performing vehicle test Flat rate unit I 00 00 556	2 FRU
Assessment of vehicle involved in an accident Flat rate unit I 41 00 001	12 FRU
Assessment of vehicle involved in an accident Flat rate unit I 41 00 001	3 FRU
Assessment of vehicle involved in an accident Flat rate unit I 41 00 001	7 FRU
Assessment of vehicle involved in an accident Flat rate unit I 41 00 001	1 FRU
KLEINERSATZTEILE Part I KLEINERSATZ	Local 1
Trim cover, bumper, primed, front Part I 51 11 7 371 861	1
Support, center Part I 51 11 7 296 308	1
Badge Part I 51 76 7 288 752	1
Fog lights, left Part I 63 17 7 248 911	1
Condenser air conditioning Part I 64 50 6 804 722	1
Expanding rivet Part I 51 11 1 908 077	4

Closed grid, left Part I 51 11 7 293 793	1
Grille, front, right Part I 51 13 7 294 808	1
Finisher, rod, left Part I 51 11 7 294 893	1
Flap, towing eye, primed Part I 51 11 7 371 845	1
Mount, bumper, front, top Part I 51 11 7 275 178	1
Shock absorber front Part I 51 11 7 295 543	1
Air ducts to radiator Part I 51 74 7 294 902	1
Air duct, bottom Part I 51 74 7 294 911	1
Grille, front, left Part I 51 13 7 294 807	1
Insert, air intake, center Part I 51 11 7 293 808	1
Acceleration sensor, pedestrian protect Part I 65 77 9 196 020	1
Sensor, pedestrian protection f-optic Part I 65 76 9 318 775	1
Bi-xenon headlight, left Part I 63 11 7 355 555	1
Bi-xenon headlight, right Part I 63 11 7 355 556	1
Support, fog lamp left Part I 51 11 7 293 799	1
Charge-air cooler Part I 17 51 7 600 532	1
C-clip nut Part I 51 71 7 065 773	10
Gasket ring Part I 64 50 8 375 741	1
Gasket ring Part I 64 50 8 374 959	1
Module mount, left Part I 17 11 7 600 536	1
Bracket for module, left Part I 17 11 8 620 732	1
Cover for air duct Part I 51 74 7 390 255	1
Clip nut	18

Finisher, rod, right
Part I 51 11 7 294 894

1

— Job

Description: HU und AU durchführen DEKRA ext Extern

Is interpreted as a repeat visit: No

Customer's own words:

Bereitstellen zur Hauptuntersuchung Flat rate unit I -	Local	0 FRU
Abgasuntersuchung 2 Jährig DEKRA Flat rate unit I AU2 EXT	Local	3 FRU
Preliminary check to statutory vehicle inspection Flat rate unit I 00 12 600		5 FRU

— Job

Description: 4000

Is interpreted as a repeat visit: No

Customer's own words:

Standard scope of service Flat rate unit I 00 00 105		2 FRU
Brake fluid service Flat rate unit I 00 00 618		4 FRU
!!! unknown BMW-Id 99229407513 Bremsflüssigkeit !!! Part I 99 22 9 407 513	Local	1

— Job

Description: TA AGR Kühler prüfen durchführen

Is interpreted as a repeat visit: No

Customer's own words:

Check exhaust return cooler index (then check further with exhaust return cooler) Flat rate unit I 00 67 710		1 FRU
Visual inspection of EGR cooler output and checking cooler intake with CCM coolant level Flat rate unit I 00 67 714		12 FRU

— 11/30/2018 Key

55149 km

Key 0

							
30000	0	30000	0	48000	0	5000	60000
11/2020		731			04/2019		11/2022

—	11/30/2018	Repair	55149 km	07340 Autohaus Strauß GmbH , Oelsnitz	Job Job
---	------------	--------	----------	--	------------

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Fehler Klimaanlage	Local	24 FRU
Flat rate unit I -		

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

!!! unknown BMW-Id ESTIMATE 03741/221977 !!!	Local	0 FRU
Flat rate unit I -		

—	11/30/2018	Repair	55149 km	07340 Autohaus Strauß GmbH , Oelsnitz	Job Job
---	------------	--------	----------	--	------------

— Job

Description: Erreichbar unter

Is interpreted as a repeat visit: No

Customer's own words:

03741/221977	Local	0 FRU
Flat rate unit I ESTIMAT		

Service consultation at the vehicle with service ticket		0 FRU
Flat rate unit I 00 52 052		

— Job

Description: Fehler Klimaanlage

Is interpreted as a repeat visit: No

Customer's own words:

Carrying out vehicle test		4 FRU
Flat rate unit I 00 00 006		

Supporting the voltage of the vehicle electrical system/recharging the vehicle electrical system battery		1 FRU
Flat rate unit I 61 21 528		

Carrying out vehicle diagnosis, ABL		1 FRU
Flat rate unit I 61 00 006		

Replacing control panel of air conditioning system		5 FRU
Flat rate unit I 64 11 878		

Program/encode control unit(s), includes deleting the fault memory
Flat rate unit I 61 00 730

4 FRU

Automatic air conditioning control
Part I 64 11 9 363 546

1

—	11/19/2018	Key	54538 km	Key 0											
															
		-1300	-1300	-1300	-1300	49000	0	5000	-1300						
		07/2019	254	254	254		04/2019		07/2019						
—	11/19/2018	Service	54539 km	07340 Autohaus Strauß GmbH, Oelsnitz	Manual										
															
		✓	✓	✓	✓				✓						
—	11/12/2018	Repair	54538 km	07340 Autohaus Strauß GmbH , Oelsnitz	Job Job Job										

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

alle Flüssigkeitsstände prüfen und ergänzen JA: NEIN:x
Flat rate unit I AW00 00 2

Local

0 FRU

Service consultation at the vehicle with service ticket
Flat rate unit I 00 52 052

0 FRU

— Job

Description: Service Kraftstofffilter

Is interpreted as a repeat visit: No

Customer's own words:

Unfallschaden lt. Gutachten beseitigen
Flat rate unit I AW00 00 0

Local

0 FRU

Removing and installing rear lid
Flat rate unit I 41 62 510

23 FRU

Work time without specification/body
Flat rate unit I 41 99 000

2 FRU

Replace trunk lid
Flat rate unit I 41 62 501

30 FRU

Performing vehicle test Flat rate unit I 00 00 556	2 FRU
Work time without specification/vehicle underbody preservation Flat rate unit I 97 99 000	3 FRU
Cavity sealant for trunk lid Flat rate unit I 97 62 501	2 FRU
Work time without specification/body equipment Flat rate unit I 51 99 000	6 FRU
Trunk lid Part I 41 00 7 363 253	1
Seal, rear spoiler, left Part I 51 76 7 371 655	1
Seal, rear spoiler, right Part I 51 76 7 371 656	1
Badge Part I 51 14 7 301 062	1
Label Part I 51 14 7 351 952	1
Label Part I 51 14 7 351 971	1
Paint activator, stick Part I 83 19 2 154 458	1
Repair flat rate, window, cold, 1 hr. Part I 83 19 2 289 285	1
Cleaner R1 Part I 83 19 2 211 217	1
Hook&loop fastener Part I 51 37 7 164 933	10
Grommet Part I 51 14 8 209 932	2
Expanding nut Part I 51 71 7 154 520	3
Expanding nut Part I 07 14 6 974 274	4
Clip Part I 51 13 7 177 926	6
Bump stop Part I 51 31 7 288 462	10
Clip Natur Part I 51 43 7 001 491	4
Cavity protection spray Part I 83 42 2 457 337	1
LED module Part I 63 31 9 308 996	1

— Job

Description: Service Mikrofilter

Is interpreted as a repeat visit: No

Customer's own words:

Engine oil service	3 FRU
Flat rate unit I 00 00 610	

Standard scope of service	2 FRU
Flat rate unit I 00 00 105	

Vehicle check service	6 FRU
Flat rate unit I 00 00 624	

Service - air filter insert	2 FRU
Flat rate unit I 00 00 602	

Service - microfilter	2 FRU
Flat rate unit I 00 00 616	

Fuel filter service	3 FRU
Flat rate unit I 00 00 604	

Scheibenklar mit Frostschutz	Local	2.5
Part I FT99 22 9 407 7		

Oel Zusatzpauschale BSI	Local	1
Part I ZUSATZVERGÜ		

Set oil-filter element	1
Part I 11 42 8 575 211	


Fuel filter cartridge	1
Part I 13 32 8 572 522	

Air filter element	1
Part I 13 71 8 511 668	


Microfilter/activated Carbon container	1
Part I 64 11 9 237 555	

BMW Engine Oil LL04 0W30	5
Part I 83 21 2 405 950	

—	10/22/2018	Key	53492 km	Key 0
---	------------	-----	----------	-------



—	07/06/2018	Key	50387 km	07340	Key 0
---	------------	-----	----------	-------	-------



—	07/06/2018	Service	50387 km	07340	Automatic
				Autohaus	

							
2800	2800	2800	2800	-800	0	5000	2800
07/2019	07/2019	07/2019	07/2019	✓	04/2019		07/2019

— 07/06/2018 Repair 50387 km 07340 Autohaus Strauß GmbH , Oelsnitz Job: Service Bremse vorn Job Job

— Job: Service Bremse vorn

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Service Bremse vorn

Package I 000061218Y810

Service - front brakes	6
Flat rate unit I 00 00 612	
Repair kit, brake pads asbestos-free	1
Part I 34 10 6 859 181	
Brake cleaner 2.0	1
Part I 83 19 2 365 214	
Brake pad paste	2
Part I 83 19 2 158 851	
Brake pad wear sensor, front left	1
Part I 34 35 6 792 289	

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Standardumfang	Local	0 FRU
Flat rate unit I -		
Standard scope of service		2 FRU
Flat rate unit I 00 00 105		

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

!!! unknown BMW-Id ESTIMATE 03741/221977 !!!	Local	0 FRU
Flat rate unit I -		

— 07/06/2018 Repair 50387 km 07340 Autohaus Job Job

— Job

Description: Erreichbar unter
Is interpreted as a repeat visit: No
Customer's own words:

03741/221977	Local	0 FRU
Flat rate unit ESTIMAT		

— Job

Description: CBS: Service Bremse vorn
Is interpreted as a repeat visit: No
Customer's own words:


Service - front brakes Flat rate unit 00 00 612	6 FRU
Standard scope of service Flat rate unit 00 00 105	2 FRU
Repair kit, brake pads asbestos-free Part 34 10 6 859 181	1
Brake cleaner 2.0 Part 83 19 2 365 214	1
Brake pad paste Part 83 19 2 158 851	2
Brake pad wear sensor, front left Part 34 35 6 792 289	1

— Job

Description: CBS: Standardumfang
Is interpreted as a repeat visit: No
Customer's own words:

Carrying out vehicle test including deleting fault memory and recharging batteries Flat rate unit 00 20 020	1 FRU
--	-------

— 04/03/2018 Key 44205 km 07340 Key 0



— 03/01/2018 Key 43558 km 07340 Key 0

							
10000	10000	10000	10000	15000	0	7000	10000
07/2019	517	517	517		04/2019		07/2019

—	03/01/2018	Repair	43558 km	07340 Autohaus Strauß GmbH , Oelsnitz	Job Job
---	------------	--------	----------	--	------------

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Carrying out vehicle test
Flat rate unit I 00 00 006 4 FRU

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

!!! unknown BMW-Id ESTIMATE 03741/221977 !!!
Flat rate unit I - Local 0 FRU

—	03/01/2018	Repair	43558 km	07340 Autohaus Strauß GmbH , Oelsnitz	Job Job
---	------------	--------	----------	--	------------

— Job

Description: Erreichbar unter

Is interpreted as a repeat visit: No

Customer's own words:

03741/221977
Flat rate unit I ESTIMAT Local 0 FRU

Service consultation at the vehicle with service ticket
Flat rate unit I 00 52 052 0 FRU

— Job

Description: Fahrzeugtest durchführen

Is interpreted as a repeat visit: No

Customer's own words:

Vehicle service - check before expiry of warranty
Flat rate unit I 00 00 102 5 FRU

Performing vehicle test
Flat rate unit I 00 00 556 2 FRU

—	02/01/2018	Key	43091 km	07340	Key 0		
							
11000	11000	11000	11000	16000	0	8000	11000
07/2019	545	545	545		04/2019		07/2019
—	02/01/2018	Repair	43091 km	07340	Job		
				Autohaus	Job		
				Strauß GmbH ,			
				Oelsnitz			

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

alle Flüssigkeitsstände prüfen und ergänzen JA: NEIN: Local 0 FRU
Flat rate unit I AW00 00 2

Service consultation at the vehicle with service ticket 0 FRU
Flat rate unit I 00 52 052

— Job

Description: TA Steuergeräte programmieren AGR

Is interpreted as a repeat visit: No

Customer's own words:

Operating test module and programming control unit 8 FRU
Flat rate unit I 00 64 941

—	07/25/2017	Key	26332 km	07340	Key 0		
							
1200	0	1200	0	36000	0	28000	30000
04/2018		279			04/2019		04/2020
—	07/25/2017	Service	26332 km	07340	Manual		
				Autohaus			
				Strauß GmbH,			
				Oelsnitz			

									
✓		✓							

—	07/25/2017	Repair	26332 km	07340	Job: Standard scope of service
				Autohaus	Job: Service - microfilter
				Strauß GmbH ,	Job: Engine oil service
				Oelsnitz	Job

— Job: Standard scope of service

Description:**Is interpreted as a repeat visit:** No**Customer's own words:**

Standard scope of service

Package I 0000105

Standard scope of service

Flat rate unit I 00 00 105

2

— Job: Service - microfilter

Description:**Is interpreted as a repeat visit:** No**Customer's own words:**

Service - microfilter

Package I 0000616

Service - microfilter

Flat rate unit I 00 00 616

2

Microfilter/activated Carbon container

Part I 64 11 9 237 555

1

Pollen filter housing cleaner

Part I 83 19 2 180 509

1

— Job: Engine oil service

Description:**Is interpreted as a repeat visit:** No**Customer's own words:**

Engine oil service

Package I 0000610

Engine oil service

Flat rate unit I 00 00 610

3

Set oil-filter element

Part I 11 42 8 575 211

1

BMW Engine Oil LL04 0W30

Part I 83 21 2 405 950

5

— Job

Description:**Is interpreted as a repeat visit:** No**Customer's own words:**

!!! unknown BMW-Id ESTIMATE 03741/221977 !!!

Flat rate unit I -

Local

0 FRU

—	07/25/2017	Repair	26332 km	07340	Job
				Autohaus	Job
				Strauß GmbH ,	Job
				Oelsnitz	Job

— Job

Description: Erreichbar unter

Is interpreted as a repeat visit: No

Customer's own words:

Service consultation at the vehicle with service ticket	0 FRU
Flat rate unit I 00 52 052	

— Job

Description: CBS: Standardumfang

Is interpreted as a repeat visit: No

Customer's own words:

Standard scope of service	2 FRU
Flat rate unit I 00 00 105	

— Job

Description: CBS: Mikrofilter (ggf. weiter Zusatzarbeit(en) beachten)

Is interpreted as a repeat visit: No

Customer's own words:

Service - microfilter	2 FRU
Flat rate unit I 00 00 616	

Microfilter/activated Carbon container	1
Part I 64 11 9 237 555	

— Job

Description: CBS: Motoröl

Is interpreted as a repeat visit: No

Customer's own words:


Engine oil service	3 FRU
Flat rate unit I 00 00 610	

Oel Zusatzpauschale BSI	1	Local
Part I ZUSATZVERGÜ		

Set oil-filter element	1
Part I 11 42 8 575 211	

BMW Engine Oil LL04 0W30	5
Part I 83 21 2 405 950	

— 01/26/2017 Key	16894 km 31999	Key 0
------------------	----------------	-------



— 01/26/2017 Repair	16894 km 07340	Job
	Autohaus	

— Job

Description:


Is interpreted as a repeat visit: No

Customer's own words:

alle Flüssigkeitsstände prüfen und ergänzen JA: NEIN: Local 0 FRU
Flat rate unit I AW00 00 2

Service consultation at the vehicle with service ticket 0 FRU
Flat rate unit I 00 52 052

— 12/21/2016 Key 16301 km 31999 Key 0




— 06/30/2016 Repair 2062 km 07340
Autohaus
Strauß GmbH ,
Oelsnitz

— 06/23/2016 Key 2 km 31999 Key 0



— 06/23/2016 Key 2062 km 31999 Key 0



— 06/20/2016 Repair 1990 km 07340 Job
Autohaus
Strauß GmbH ,
Oelsnitz Job

— Job

Description: Ablieferungsdurchsicht

Is interpreted as a repeat visit: No

Customer's own words:

Free pre-delivery check 9 FRU
Flat rate unit I 00 00 009

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

— 05/30/2016 Key 925 km 31999 Key 0

							
29000	0	29000	0	49000	0	49000	60000
04/2018		699			04/2019		04/2020

— 05/26/2016 Key 913 km 31999 Key 0

							
29000	0	29000	0	49000	0	49000	60000
04/2018		703			04/2019		04/2020

— 05/26/2016 Key 873 km 31999 Key 0

							
29000	0	29000	0	49000	0	49000	60000
04/2018		705			04/2019		04/2020

— 05/19/2016 Key 764 km 31999 Key 0

							
29000	0	29000	0	50000	0	49000	60000
04/2018		710			04/2019		04/2020

— 05/19/2016 Key 691 km 31999 Key 0

							
29000	0	29000	0	50000	0	49000	60000
04/2018		711			04/2019		04/2020

— 05/17/2016 Key 535 km 31999 Key 0

							
29000	0	29000	0	50000	0	49000	60000
04/2018		712			04/2019		04/2020

— 05/13/2016 Key 447 km 31999 Key 0

							
29000	0	29000	0	50000	0	49000	60000
04/2018		716			04/2019		04/2020

— 04/30/2016 Repair 11 km 23429 Autohaus Strauß GmbH , Plauen Job

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Zul.-gebühr VFW PL-ST 580
Part I FTZ550001

Local 1

Bes. Zulassung NW
Part I FTZ550002

Local 1

— 04/29/2016 Repair 11 km 07340 Autohaus Strauß GmbH , Oelsnitz Job

— Job

Description: Ablieferungsdurchsicht

Is interpreted as a repeat visit: No

Customer's own words:

Free pre-delivery check
Flat rate unit I 00 00 009

9 FRU

FEINSTAUBPLAKETTE
Part I FTF5500005

Local 1