

Vehicle

BMW 320d, 140kW

WBA8H91080K872331



Development code	F31
Color	black-sapphire metallic
Actual integration level	F020-22-03-552
Start of warranty	February 24, 2017

▼ Technical Campaigns

There are no campaigns available.

▼ Special information

There are no campaigns available.

▼ Live Diagnosis

 There are no service solutions for Live Diagnosis.

▼ Service contracts

No BSI contracts available

You can find additional service contract information and selection options in the DCSNet warranty vehicle enquiry.

▼ Information on faults, workshop/Service Consultation

No information on faults is available.

▼ Navigation map

Note: The installed map cannot be identified. One of the following maps could be installed in the vehicle.

Installed map	Enabling code (subscription)	Latest navigation map included in subscription	Latest navigation map subject to charge
Road Map EUROPE EVO 2024-2 (as of: Mar 27, 2026)	-	-	-
Road Map EUROPE EVO 2024-2 (as of: Mar 27, 2026)	Release code valid for navigation maps with release date up to Dec 31, 2099 (SWID: 01200FFF).	Road Map EUROPE EVO 2026-1	-

▾ Vehicle details

Vehicle type	Passenger car
Brand	BMW
Model	320d
Body	TOUR
Vehicle identification number (last 7 characters)	K872331
Vehicle identification number (17 characters)	WBA8H91080K872331
Development code	F31
Steering	LL
Engine	B47O
Engine number	67279880
Exhaust re-treatment	EURO6;W;PI/CI; M, N1 I
Transmission	AUT
Transmission number	0699247WC7
Head unit serial number	HB2240H8112669
Drive	HECK
Integration level	F020-16-11-502
Production date	Jan 27, 2017
Production works	Muenchen
Delivery date	Mar 8, 2017
Delivering Retailers	No information
National-market version	EUR
Paint code	475
Upholstery code	LCSW
Model code	8H01
Base type	8H91
Lead type	8H01

▾ Optional equipment

Optional equipment fitted at the factory:

01CA Selection of COP relevant vehicles
01CB CO2 package
0205 Automatic transmission
0216 Hydro steering-servotronic
0230 EU-specific additional contents


Retrofitted optional equipment:

This vehicle has no retrofits.

0255 Sports leather steering wheel
0258 Tire with run-flat functionality
02VB Tire pressure display
0302 Alarm system
0322 Comfort access
03AA Roof railing black
03AC Trailer coupling
0402 Electric panoramic roof
0423 Floor mats, velours
0428 Warning triangle and first aid kit
0430 Interior/outside mirror with auto dip
0431 Interior mirror with automatic-dip
0441 Smoker package
0488 Lumbar support, driver and passenger
0493 Storage compartment package
0494 Seat heating driver/passenger
04AE Armrest front, retractable
04GA Ashgrain Perlglanz chrome accent
0508 Park Distance Control (PDC)
0521 Rain sensor
0534 Automatic air conditioning
0544 Cruise control with braking function
0548 Kilometer-calibrated speedometer
0563 Lights package
0575 Supplementary 12V sockets
05A1 LED Fog lights
05A2 LED headlight
05AC High-beam assistant
05AL Active Protection
05DA Passenger airbag deactivation
05DC Rear-seat headrests, folding
0609 Navigation system Professional
0676 HiFi speaker system
0698 Area-Code 2 for DVD
06AC Intelligent emergency SOS call
06AE Teleservices
06AK Connected Drive Services
06AM Real-Time Traffic Information
06AN Concierge Services
06AP Remote Services
06NS Convenience phone, expanded Smartphone
06WA Instrument cluster, expanded equipment
07LE Modell Luxury Line
07S2 Luxury Line
0801 German version
0851 Language version German
0879 On-board vehicle literature German
08KA Oil service interval, 24 mos./30,000 km
08R9 Refrigerant R1234yf
08TH Road sign detection
0931 Winter instead of summer tires ex-fact.
09BM Navigation package, Connected Drive
A090 90 AH AGM battery
LEDE Leather trim

▾ Vehicle histories

	Date	Type	Vehicle mileage	Dealer	Overview
—	03/24/2026	Key	191021 km	33854	Key 0



— 03/24/2026 Repair 146542 km 33854 , Job

— Job

Description: Haftpflichtschaden laut Gutachten instandsetzen

Is interpreted as a repeat visit: No

Customer's own words:

Remove and install / replace V support	16 FRU
Flat rate unit I 51 64 512	

Work time without specification/body equipment	2 FRU
Flat rate unit I 51 99 000	

Removing and installing/replacing support for front bumper cover	10 FRU
Flat rate unit I 51 11 551	

Work time without specification/body equipment	3 FRU
Flat rate unit I 51 99 000	

Removing and installing/replacing support for front lower bumper cover	1 FRU
Flat rate unit I 51 11 561	

Replacing front bumper panel	20 FRU
Flat rate unit I 51 11 657	

Work time without specification/body equipment	10 FRU
Flat rate unit I 51 99 000	

Work time without specification/body equipment	2 FRU
Flat rate unit I 51 99 000	

Work time without specification/body equipment	3 FRU
Flat rate unit I 51 99 000	

Additional work with Park Distance Control	1 FRU
Flat rate unit I 66 20 601	

Additional work with Park Distance Control	5 FRU
Flat rate unit I 66 20 614	

Work time without specification/body equipment	0 FRU
Flat rate unit I 51 99 000	

Additional work with Park Distance Control	4 FRU
Flat rate unit I 66 20 610	

Lackierrechnung	Local	1 FRU
Flat rate unit I FL00 00 0		

Ersatzfahrzeug 3Tage	Local	1 FRU
Flat rate unit I FLBM000		

Set of mounted parts, bumper, front	1
Part I 51 11 2 471 536	

Shock absorber front	1
Part I 51 11 7 396 916	

Trim cover, bumper, primed, front Part I 51 11 7 427 120	1
Set of mounts, front PDC / PMA sensor Part I 51 11 7 445 076	1
Grille, front, left Part I 51 13 7 263 481	1
Grille, front, right Part I 51 13 7 263 482	1
Badge Part I 51 76 7 288 752	1
Adhesive K6 Part I 83195B683D3	1
Primer Loctite 770 Part I 83195B683D4	1
Mount, bumper, front, top Part I 51 11 7 255 393	1
Support Part I 51 11 7 371 572	1
Hex nut with plate Part I 07 11 9 905 949	1
Air ducts to radiator Part I 51 74 7 255 413	1
Cover for air duct Part I 51 74 7 390 255	2
V-brace for front panel Part I 51 64 7 245 789	1
Torx-bolt with washer Part I 07 14 7 301 867	4
Air duct front bottom Part I 51 74 7 401 233	1
Blind rivet Part I 07 14 9 191 219	2
ASA screw, self-threading Part I 34 50 9 804 151	1

—	02/23/2026	Key	187473 km	33854	Key 0			
								
16000	16000	16000	16000	22000		13000	16000	
12/2027	12/2027	12/2027	12/2027		03/2026		12/2027	03/2026
—	02/05/2026	Key	185466 km	33854	Remote KeyRead			

								
19000	19000	19000	19000	24000	15000	19000		
12/2027	12/2027	12/2027	12/2027		03/2026		12/2027	03/2026

— 02/20/2025 Key 153525 km 33854 Key 0

								
16000		16000		50000	60000	43000		
09/2026		09/2026			03/2026	09/2028		03/2026

— 02/19/2025 Key 153426 km 34745 Remote KeyRead

								
16000		16000		50000	60000	43000		
09/2026		09/2026			03/2026	09/2028		03/2026

— 01/16/2025 Key 152011 km 33854 Key 0

								
18000		18000		50000	60000	44000		
09/2026		09/2026			03/2026	09/2028		03/2026

— 01/16/2025 Repair 146542 km 33854 , Job

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Work time without specification/body equipment Flat rate unit I 51 99 000	2 FRU
Removing and installing/replacing door sill trim, front left or right Flat rate unit I 51 47 565	1 FRU
Remove and install/replace left or right side sill trim panel Flat rate unit I 51 71 947	4 FRU
Removing and installing left or right front door Flat rate unit I 41 51 580	3 FRU
Removing and installing or replacing casing on outside mirror, left or right Flat rate unit I 51 16 540	2 FRU
Removing and installing or replacing retaining ring on outside mirror, left or right Flat rate unit I 51 16 545	4 FRU
Removing and installing rear left or right door Flat rate unit I 41 52 580	3 FRU
Adjust left or right front and rear door Flat rate unit I 41 51 563	4 FRU

Replacing door at front and rear on left or right Flat rate unit I 41 51 562	72 FRU
Removing and installing/replacing the window recess finisher strip of the rear inner door Flat rate unit I 51 22 830	1 FRU
Work time without specification/body equipment Flat rate unit I 51 99 000	12 FRU
Work time without specification/body Flat rate unit I 41 99 000	30 FRU
Work time without specification/body Flat rate unit I 41 99 000	30 FRU
Work time without specification/vehicle underbody preservation Flat rate unit I 97 99 000	3 FRU
Cavity sealant for the front door, left or right Flat rate unit I 97 51 501	2 FRU
Work time without specification/vehicle underbody preservation Flat rate unit I 97 99 000	6 FRU
Work time without specification/body equipment Flat rate unit I 51 99 000	1 FRU
Work time without specification/body equipment Flat rate unit I 51 99 000	1 FRU
Door front right Part I 41 00 9 628 764	1
Right upper front door hinge Part I 41 51 7 284 534	1
Right lower front door hinge Part I 41 51 7 284 536	1
Handle bracket, right prime-coated Part I 51 21 7 332 566	1
Covering door, primed right Part I 51 21 7 162 434	1
Housing lower section, grained, right Part I 51 16 7 284 128	1
Outside mirror cover cap, right, primed Part I 51 16 7 292 746	1
Holder, black grained, right Part I 51 16 7 284 124	1
Door rear right Part I 41 00 9 628 766	1
Repair flat rate, window, cold, 1 hr. Part I 83 19 2 289 285	1
Cleaner R1 Part I 83 19 2 211 217	1
Rocker panel trim, primed, right Part I 51 77 7 312 752	1
Supporting ledge right	1

Supporting ledge right Part I 51 77 7 256 918	1
Supporting ledge right Part I 51 77 7 256 920	1
Front entrance cover Part I 51 47 7 410 460	1
Supporting ledge right Part I 51 77 7 240 874	1
Type plate Part I 71215A0C986	1
Instruction notice, Passenger's airbag Part I 07 14 9 384 060	1
Door brake, rear right Part I 51 22 7 446 730	1
Torx-bolt with washer Part I 51 22 6 976 687	2
Sound insulating door rear right Part I 51 48 7 263 414	1
Sound insulation, door, front right Part I 51 48 7 263 412	1
Door weatherstrip rear right Part I 51 35 7 377 416	1
Door weatherstrip front Part I 51 33 7 258 329	1
Outside antenna, comfort access Part I 65 20 9 220 831	1

—	01/02/2025	Key	151801 km	33854	Key 0			
								
18000		18000		50000	03/2026	60000	44000	03/2026
09/2026		09/2026					09/2028	
—	10/10/2024	Key	146542 km	33854	Key 0			
								
26000		26000		15000	03/2026	40000	50000	03/2026
09/2026		09/2026					09/2028	
—	04/12/2024	Key	139344 km	33854	Key 0			
								
1700	1700	1700	1700	18000	03/2026	43000	50000	03/2026
07/2024	07/2024	07/2024	07/2024				07/2028	

—


03/11/2024

Key

138549 km

33854

Key 0



—


03/11/2024

Service

138549 km

33854 Müller-Dynamic GmbH , Lebach

Automatic



—

03/11/2024

Repair

138549 km

33854 ,

Job
Job
Job
Job
Job
Job

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Vehicle check in frame of acceptance

Flat rate unit I 00 52 054

1 FRU

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Standard scope of service

Flat rate unit I 00 00 105

2 FRU

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Brake fluid service

Flat rate unit I 00 00 618

4 FRU

Brake fluid DOT4 LV, low viscosity

Part I 83 13 2 184 843

0

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Vorführung zur Abgasuntersuchung Flat rate unit I 00 00 168	Local	1 FRU
--	-------	-------

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Fahrzeug waschen und aussaugen Flat rate unit I 00 00 180	Local	1 FRU
--	-------	-------

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Replacing both rear shock absorbers Flat rate unit I 33 52 530	11 FRU
---	--------

Replacing cylinder head cover Flat rate unit I 11 12 510	42 FRU
---	--------

Attachment set spring strut, rear Part I 33 52 2 467 121	2
---	---

Auxiliary shock absorber, rear Part I 33 53 6 850 537	2
--	---

Cylinder head cover Part I 11 12 8 581 798	1
---	---








Cap for oil filler Part I 11 12 8 655 331	1
--	---

O-ring Part I 13 62 8 658 854	1
----------------------------------	---


Gasket ring Part I 13 53 2 247 156	4
---------------------------------------	---

Profile-gasket Part I 11 61 8 571 001	4
--	---

— 01/22/2024 Key 136575 km 33854 Key 0



— 01/22/2024 Service 136575 km 33854 Müller-Dynamic GmbH, Lebach Automatic



—	01/22/2024	Repair	136575 km	33854 Müller-Dynamic GmbH, Lebach	Job Job Job Job Job Job Job Job
---	------------	--------	-----------	-----------------------------------	--

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Vehicle check in frame of acceptance Flat rate unit I 00 52 054	1 FRU
--	-------

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Replace exhaust gas recirculation cooler, including exhaust gas recirculation valve Flat rate unit I 00 74 635	23 FRU
---	--------

Performing additional work for pressure sensor functional check Flat rate unit I 00 74 636	3 FRU
---	-------

Additional work: enter component identification of new exhaust-gas recirculation cooler in diagnostic system Flat rate unit I 00 74 637	1 FRU
--	-------

Additional work: clean EGR pipe Flat rate unit I 00 74 638	6 FRU
---	-------

Kühlflüssigkeit Part I FT81 22 9 400 1	Local	5
---	-------	---

Exhaust gas cooler high temperature Part I 11 71 7 822 347	1
---	---

AGR small parts set Part I 11 71 8 490 640	1
---	---

Vacuum hose black Part I 11 65 8 595 650	1
---	---

Pipe union Part I 11 71 7 799 853	2
--------------------------------------	---

Holder Part I 61 13 1 369 832	1
----------------------------------	---

Connection piece Part I 11 65 7 803 012	1
--	---

O-ring Part I 11 61 8 512 681	1
----------------------------------	---

Acoustic cover front Part I 11 14 8 490 577	1
--	---

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Standard scope of service Flat rate unit I 00 00 105	2 FRU
---	-------

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Vehicle check service Flat rate unit I 00 00 624	6 FRU
---	-------

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Engine oil service Flat rate unit I 00 00 610	3 FRU
--	-------

BMW TwinPower Turbo LL-19FE 0W-30 Part I 83215A65BF8	5
---	---

Set oil-filter element Part I 11 42 8 575 211	1
--	---

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Fuel filter service Flat rate unit I 00 00 604	3 FRU
---	-------

Fuel filter cartridge Part I 13 32 7 822 497	1
---	---

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Service - air filter insert
Flat rate unit I 00 00 602

2 FRU

Air filter element
Part I 13 71 8 511 668

1

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Service - microfilter
Flat rate unit I 00 00 616

2 FRU

Microfilter/activated Carbon container
Part I 64 11 9 237 555

1

— Job

Description:

Is interpreted as a repeat visit: No








Customer's own words:

Fahrzeug waschen und aussaugen
Flat rate unit I 00 00 180








Local

1 FRU










— 09/15/2023 Key 130518 km 33854 Key 0



— 09/11/2023 Key 130222 km 33854 Key 0



— 09/11/2023 Service 130222 km 33854 Müller-Dynamic GmbH, Lebach Automatic



— 09/11/2023 Repair 130222 km 33854 Müller-Dynamic GmbH, Lebach Job
Job
Job
Job
Job
Job
Job

— Job

Description:**Is interpreted as a repeat visit:** No**Customer's own words:**

Vehicle check in frame of acceptance Flat rate unit I 00 52 054	1 FRU
--	-------

— Job

Description:**Is interpreted as a repeat visit:** No**Customer's own words:**

Remove and install/replace the exhaust-gas recirculation cooler Flat rate unit I 11 71 100	25 FRU
---	--------

Gasket Steel Part I 11 71 8 579 364	1
--	---

Oval head screw Part I 35 21 7 685 343	2
---	---

— Job

Description:**Is interpreted as a repeat visit:** No**Customer's own words:**

Standard scope of service Flat rate unit I 00 00 105	2 FRU
---	-------

— Job

Description:**Is interpreted as a repeat visit:** No**Customer's own words:**

Rear brakes service Flat rate unit I 00 00 614	7 FRU
---	-------

Brake pad paste Part I 83 19 2 158 851	2
---	---

Brake cleaner 2.0 Part I 83 19 2 365 214	1
---	---

Brake pad wear sensor, rear Part I 34 35 6 792 292	1
---	---

Repair kit brake pads asbestos-free Part I 34 21 8 855 013	1
---	---

Clip Part I 34 21 6 850 853	2
--------------------------------	---

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Removing and installing/renewing both brake discs Flat rate unit I 34 21 932	4 FRU
Hex screw with collar Part I 34 20 6 850 536	4
Brake disc, ventilated Part I 34 21 6 864 900	2
Inner hex bolt Part I 34 21 1 161 806	2

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Work time without specification/body equipment Flat rate unit I 51 99 000	1 FRU
Cover, tow fitting, front, primed Part I 51 11 7 396 837	1

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Räder von Vorne nach Hinten tauschen Flat rate unit I 00 01 000	Local	4 FRU
Kinematics Diagnosis System wheel alignment with ride height measurement without loading the vehicle Flat rate unit I 32 00 155		11 FRU

— Job








Description:

Is interpreted as a repeat visit: No

Customer's own words:

Fahrzeug waschen und aussaugen Flat rate unit I 00 00 180	Local	1 FRU
--	-------	-------

— 07/24/2023 Key 127246 km Remote KeyRead



— 07/21/2022 Key 110043 km 33854 Key 0

								
100		100		49000		5000	27000	
10/2022		70			02/2024		10/2024	02/2024

—	07/21/2022	Service	110043 km	33854 Müller-Dynamic GmbH , Lebach	Automatic
---	------------	---------	-----------	------------------------------------	-----------

								
100	0	100	0	49000	0	5000	27000	0
✓		✓						

—	07/21/2022	Repair	110043 km	33854 Müller-Dynamic GmbH , Lebach	Job Job Job Job Job Job
---	------------	--------	-----------	------------------------------------	--

—	Job
---	-----

Description:	
Is interpreted as a repeat visit:	No
Customer's own words:	
Vehicle check in frame of acceptance	1 FRU
Flat rate unit I 00 52 054	

—	Job
---	-----

Description:	
Is interpreted as a repeat visit:	No
Customer's own words:	
Standard scope of service	2 FRU
Flat rate unit I 00 00 105	

—	Job
---	-----

Description:	
Is interpreted as a repeat visit:	No
Customer's own words:	
Engine oil service	3 FRU
Flat rate unit I 00 00 610	
Set oil-filter element	1
Part I 11 42 8 575 211	
BMW Engine Oil LL04 5W30	5
Part I 83 21 2 405 948	

—	Job
---	-----

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Service - microfilter	2 FRU
Flat rate unit I 00 00 616	

Microfilter/activated Carbon container	1
Part I 64 11 9 237 555	

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Work time without specification/body equipment	12 FRU
Flat rate unit I 51 99 000	

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:


Fahrzeug waschen und aussaugen	Local	3 FRU
Flat rate unit I 00 00 180		

Program control units	8 FRU
Flat rate unit I 00 71 907	

Implement fault memory and pressure sensor functional check (in conjunction with one of the traffic reports mentioned above (program control units)	1 FRU
Flat rate unit I 00 72 677	

Cover, tow fitting, front, primed	1
Part I 51 11 7 396 837	

— 07/18/2022 Key 109705 km 33854 Remote KeyRead



— 02/24/2022 Key 102396 km 33854 Key 0

 1800 09/2022	 1800 187	 1800 187	 1800 187	 60000	 -23 3.1 %	 5000	 1800 09/2022	 -23 3.1 %
---	---	---	---	---	--	--	--	--

— 02/24/2022 Service 102127 km 33854 Müller-Dynamic GmbH, Lebach Automatic

 2000 ✓	 2000 ✓	 2000 ✓	 2000 ✓	 60000	 ✓	 6000	 2000 ✓	 ✓
--	--	--	--	--	--	---	---	--

— 09/02/2020 Key 79210 km 33854 Key 0

 -330 03/2021	 0	 -330 210	 0	 38000	 0 02/2022	 31000	 25000 03/2023	 0 02/2022
--	--	--	--	--	---	--	--	---

— 09/02/2020 Service 79210 km 33854 Müller-Dynamic GmbH, Lebach Automatic

 -330 03/2021 ✓	 0	 -330 03/2021 ✓	 0	 38000	 0 02/2022	 31000	 25000 03/2023	 0 02/2022
--	---	--	---	---	--	---	---	--

— 09/02/2020 Repair 79210 km 32663 Müller-Dynamic GmbH, Simmern Job
Job: Standard scope of service
Job: Service - microfilter
Job: Engine oil service
Job

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Package I MM01D09_10000

Local

Vehicle check in frame of acceptance
Flat rate unit I 00 52 054

1

— Job: Standard scope of service

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Standard scope of service
Package I 0000105

Standard scope of service
Flat rate unit I 00 00 105

2

— Job: Service - microfilter

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Service - microfilter
Package I 0000616

Service - microfilter
Flat rate unit I 00 00 616

2

Microfilter/activated Carbon container
Part I 64 11 9 237 555

1

— Job: Engine oil service

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Engine oil service
Package I 0000610

Engine oil service
Flat rate unit I 00 00 610

3

Set oil-filter element
Part I 11 42 8 575 211

1

BMW Engine Oil LL04 5W30
Part I 83 21 2 405 948

5

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Package I MM02D01_10000

Local

Fahrzeug waschen und aussaugen
Flat rate unit I 00 00 180

Local

3

—	09/02/2020	Repair	79210 km	33854 Müller-Dynamic GmbH, Lebach	Job Job Job Job Job
---	------------	--------	----------	-----------------------------------	---------------------------------

— Job

Description: Fahrzeugüberprüfung im Rahmen der Annahme / / /

Is interpreted as a repeat visit: No

Customer's own words:

Vehicle check in frame of acceptance

1 FRU

— Job

Description: CBS: Service Standardumfang

Is interpreted as a repeat visit: No

Customer's own words:

Standard scope of service Flat rate unit I 00 00 105	2 FRU
---	-------

— Job

Description: CBS: Service Mikrofilter

Is interpreted as a repeat visit: No

Customer's own words:

Service - microfilter Flat rate unit I 00 00 616	2 FRU
Microfilter/activated Carbon container Part I 64 11 9 237 555	1

— Job

Description: CBS: Service Motoröl

Is interpreted as a repeat visit: No

Customer's own words:

Engine oil service Flat rate unit I 00 00 610	3 FRU
Set oil-filter element Part I 11 42 8 575 211	1
BMW Engine Oil LL04 5W30 Part I 83 21 2 405 948	5

— Job


Description: Fahrzeug waschen und aussaugen /

Is interpreted as a repeat visit: No

Customer's own words:

!!! unknown BMW-Id 0000180 Fahrzeug waschen und aussaugen Motorölstand prüfen/ergänzen !!! Flat rate unit I 00 00 180	Local	3 FRU
---	-------	-------

— 02/11/2020 Key 70132 km 33854 Key 0



— 02/11/2020 Service 70132 km 33854 Müller-Dynamic Automatic

								
9000	0	9000	0	48000	0	45000	34000	0
03/2021		03/2021			01/2020		03/2023	02/2020
					✓			

—	02/11/2020	Repair	70132 km	32663 Müller-Dynamic GmbH , Simmern	Job Job Job: Standard scope of service Job: Brake fluid service Job Job Job Job
---	------------	--------	----------	--	--

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Package I MM01D09_10000

Local

Vehicle check in frame of acceptance
Flat rate unit I 00 52 054

1

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Produktionsdatum Abgasrückführungskühler prüfen
Flat rate unit I 00 68 736

Local

1 FRU

— Job: Standard scope of service

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Standard scope of service
Package I 0000105

Standard scope of service
Flat rate unit I 00 00 105

2

— Job: Brake fluid service

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Brake fluid service
Package I 0000618

Brake fluid service

4

Flat rate unit I 00 00 618

Brake fluid DOT4 LV, low viscosity
Part I 83 13 2 184 843

1

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Package I PAK000012_10000

Local

Abgasuntersuchung

Local

6

Flat rate unit I 00 00 168

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Package I MM01D16_10000

Local

Ersatzwagen

Local

1

Flat rate unit I 00 00 164

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Package I MM02D01_10000

Local

Fahrzeug waschen und aussaugen

Local

3

Flat rate unit I 00 00 180

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

!!! unknown BMW-Id ESTIMATE Herr Krüger !!!

Local

0 FRU

Flat rate unit I -

!!! unknown BMW-Id ESTIMATE 0178-8634011 !!!

Local

0 FRU

Flat rate unit I -

—	02/11/2020	Repair	70133 km	33854 Müller-Dynamic GmbH, Lebach	Job Job Job Job Job Job
---	------------	--------	----------	-----------------------------------	--

— Job

Description: Fahrzeugüberprüfung im Rahmen der Annahme /

Is interpreted as a repeat visit: No

Customer's own words:

Vehicle check in frame of acceptance
Flat rate unit I 00 52 054

1 FRU

— Job

Description: CBS: Service Standardumfang

Is interpreted as a repeat visit: No

Customer's own words:

Standard scope of service
Flat rate unit I 00 00 105

2 FRU

— Job

Description: CBS: Service Bremsflüssigkeit

Is interpreted as a repeat visit: No

Customer's own words:

Brake fluid service
Flat rate unit I 00 00 618

4 FRU

Brake fluid DOT4 LV, low viscosity
Part I 83 13 2 184 843

1

— Job

Description: TÜV und AU (LEB) /

Is interpreted as a repeat visit: No

Customer's own words:

!!! unknown BMW-Id 0000168 Abgasuntersuchung !!!
Flat rate unit I 00 00 168

Local

6 FRU

— Job

Description: Serviceersatzwagen /

Is interpreted as a repeat visit: No

Customer's own words:

!!! unknown BMW-Id 0000164 Ersatzwagen !!!
Flat rate unit I 00 00 164

Local

1 FRU

— Job

Description: Fahrzeug waschen und aussaugen /

Is interpreted as a repeat visit: No

Customer's own words:

!!! unknown BMW-Id 0000180 Fahrzeug waschen und aussaugen
Motorölstand prüfen/ergänzen !!!
Flat rate unit I 00 00 180

Local

3 FRU

									
20000	0	20000	0	350	0	5000	47000		0
03/2021		624			01/2020		03/2023		02/2020

— 07/16/2019 Service 60286 km 33854 Müller-Dynamic GmbH, Lebach Automatic

									
20000	0	20000	0	350	0	5000	47000		0
03/2021		03/2021		✓	01/2020	✓	03/2023		02/2020

— 07/16/2019 Repair 60286 km 32663 Müller-Dynamic GmbH, Simmern

Job
 Job: Standard scope of service
 Job: Service - front brakes
 Job: Removing and installing/replacing both front brake discs
 Job
 Job: Rear brakes service
 Job
 Job
 Job

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Package I MM01D09_10000

Local

Vehicle check in frame of acceptance
 Flat rate unit I 00 52 054

1

— Job: Standard scope of service

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Standard scope of service
 Package I 0000105

Standard scope of service
 Flat rate unit I 00 00 105

2

— Job: Service - front brakes

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Service - front brakes
 Package I 0000612

Service - front brakes Flat rate unit I 00 00 612	6
Repair kit, brake pads asbestos-free Part I 34 10 6 859 181	1
Brake pad wear sensor, front left Part I 34 35 6 792 289	1
Brake pad paste Part I 83 19 2 158 851	2
Brake cleaner, acetone-free Part I 83 19 2 413 695	1

— Job: Removing and installing/replacing both front brake discs

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Removing and installing/replacing both front brake discs
Package I 3411613

Removing and installing/replacing both front brake discs Flat rate unit I 34 11 613	3
Torx screw with washer Part I 34 10 6 864 424	4
Brake disc, ventilated Part I 34 11 6 792 219	2
Inner hex bolt Part I 34 21 1 161 806	2

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words: Klimaanlage riecht zeitweise unangenehm-desinfizieren/ Kühlleistung prüfen

Work time without specification/air conditioning
Flat rate unit I 64 99 000

0 FRU

— Job: Rear brakes service

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Rear brakes service
Package I 0000614

Rear brakes service Flat rate unit I 00 00 614	7
Repair kit, brake pads asbestos-free Part I 34 21 6 873 093	1
Brake pad wear sensor, rear Part I 34 35 6 792 292	1

Brake pad paste	2
Part I 83 19 2 158 851	
Brake cleaner, acetone-free	1
Part I 83 19 2 413 695	

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Package I MM01D16_10000	Local	
Ersatzwagen	Local	1
Flat rate unit I 00 00 164		

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Package I MM02D01_10000	Local	
Fahrzeug waschen und aussaugen	Local	3
Flat rate unit I 00 00 180		

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

!!! unknown BMW-Id ESTIMATE !!!	Local	0 FRU
Flat rate unit I -		
!!! unknown BMW-Id ESTIMATE !!!	Local	0 FRU
Flat rate unit I -		

—	07/16/2019	Repair	60301 km	33854 Müller-Dynamic GmbH , Lebach	Job Job Job Job Job Job Job
---	------------	--------	----------	------------------------------------	---

— Job

Description: Ansprechpartner

Is interpreted as a repeat visit: No

Customer's own words:

Herr Krüger	Local	0 FRU
Flat rate unit I ESTIMAT		

0178-8634011
Flat rate unit I ESTIMAT

Local

0 FRU

— Job

Description: CBS: Standardumfang

Is interpreted as a repeat visit: No

Customer's own words:

Standard scope of service
Flat rate unit I 00 00 105

2 FRU

— Job

Description: CBS: Bremse vorn

Is interpreted as a repeat visit: No

Customer's own words:

Service - front brakes
Flat rate unit I 00 00 612

6 FRU

Repair kit, brake pads asbestos-free
Part I 34 10 6 859 181

1

Brake pad wear sensor, front left
Part I 34 35 6 792 289

1

Brake cleaner 2.0
Part I 83 19 2 365 214

1

Brake pad paste
Part I 83 19 2 158 851

2

— Job

Description: Beide Bremsscheiben vorn aus- und einbauen/ ersetzen

Is interpreted as a repeat visit: No

Customer's own words:

Removing and installing/replacing both front brake discs
Flat rate unit I 34 11 613

3 FRU

Torx screw with washer
Part I 34 10 6 864 424

4

Brake disc, ventilated
Part I 34 11 6 792 219

2

Inner hex bolt
Part I 34 21 1 161 806

2

— Job

Description: Arbeitszeit ohne Vorgabe/Heiz- und Klimaanlage

Is interpreted as a repeat visit: No

Customer's own words:

Work time without specification/air conditioning
Flat rate unit I 64 99 000

4 FRU

Klimaanlagen / Reiniger

Local

1

Windshield Washer Antifreeze 1
Part I 83 12 2 468 609

— Job

Description: CBS: Bremse hinten

Is interpreted as a repeat visit: No

Customer's own words:

Rear brakes service 7 FRU
Flat rate unit I 00 00 614

Repair kit, brake pads asbestos-free 1
Part I 34 21 6 873 093

Brake pad wear sensor, rear 1
Part I 34 35 6 792 292

Brake cleaner 2.0 1
Part I 83 19 2 365 214

Brake pad paste 2
Part I 83 19 2 158 851

— Job

Description: Serviceersatzwagen /

Is interpreted as a repeat visit: No

Customer's own words:

!!! unknown BMW-Id 0000164 Ersatzwagen !!! Local 0 FRU
Flat rate unit I 00 00 164

— Job








Description: Fahrzeug waschen und aussaugen /

Is interpreted as a repeat visit: No

Customer's own words:

!!! unknown BMW-Id 0000180 Fahrzeug waschen und aussaugen Local 3 FRU
Motorölstand prüfen/ergänzen !!!
Flat rate unit I 00 00 180

— 05/08/2019 Key 55755 km 33854 Key 0



— 05/08/2019 Repair 55755 km 32663 Müller-Dynamic GmbH, Simmern Job
Job
Job
Job

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Package I MM01D09_10000	Local	
Vehicle check in frame of acceptance		1
Flat rate unit I 00 52 054		

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words: Zuerst ruckelte das Fahrzeug zeitweise und heute kam Fehlermeldung „Antrieb gestört“ nach Neustart i.O.

Package I PAK000019_10000	Local	
Carrying out vehicle test		4
Flat rate unit I 00 00 006		
Carrying out vehicle diagnosis, ABL		0
Flat rate unit I 61 00 006		
Supporting the voltage of the vehicle electrical system/recharging the vehicle electrical system battery		1
Flat rate unit I 61 21 528		

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Package I MM01D16_10000	Local	
Ersatzwagen	Local	1
Flat rate unit I 00 00 164		

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Package I MM02D01_10000	Local	
Fahrzeug waschen und aussaugen	Local	3
Flat rate unit I 00 00 180		

— 03/07/2019 Key 53255 km 33854 Key 0

										
1100	1100	1100	1100	15000	0	6000	1100		0	
02/2020	359	359	359		01/2020		02/2020		02/2020	

— 03/07/2019 Service 53255 km 33854 Müller-Dynamic Automatic

									
1100	1100	1100	1100	15000	0	6000	1100		0
02/2020	02/2020	02/2020	02/2020		01/2020		02/2020		02/2020
✓	✓	✓	✓				✓		

—	03/07/2019	Repair	53255 km	32663 Müller-Dynamic GmbH , Simmern	Job: Service Fahrzeug-Check Job: Service Motoröl Job: Service Kraftstofffilter Job: Service Luftfiltereinsatz Job: Service Mikrofilter Job Job Job Job Job
---	------------	--------	----------	-------------------------------------	---

— Job: Service Fahrzeug-Check

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Service Fahrzeug-Check
Package I 000062418H010

— Job: Service Motoröl

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Service Motoröl
Package I 000061018H010

Set oil-filter element Part I 11 42 8 575 211	1
BMW Engine Oil LL04 5W30 Part I 83 21 2 405 948	5

— Job: Service Kraftstofffilter

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Service Kraftstofffilter
Package I 000060418H010

Fuel filter cartridge Part I 13 32 8 572 522	1
---	---

— Job: Service Luftfiltereinsatz

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Service Luftfiltereinsatz
Package I 000060218H010

Air filter element 1
Part I 13 71 8 511 668

— Job: Service Mikrofilter

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Service Mikrofilter
Package I 000061618H010

Microfilter/activated Carbon container 1
Part I 64 11 9 237 555

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Package I MM01D09_10000

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Package I MM01D16_10000 Local

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Package I MM02D01_10000 Local

—	03/07/2019	Repair	53259 km	33854 Müller-Dynamic GmbH, Lebach	Job Job Job Job Job Job Job
---	------------	--------	----------	-----------------------------------	---

— Job

Description: Fahrzeug waschen und aussaugen /

Is interpreted as a repeat visit: No

Customer's own words:

!!! unknown BMW-Id 0000180 Fahrzeug waschen und aussaugen Motorölstand prüfen/ergänzen !!! Flat rate unit I 00 00 180	Local	3 FRU
---	-------	-------

— Job

Description: CBS: Service Fahrzeug-Check

Is interpreted as a repeat visit: No

Customer's own words:

Vehicle check service Flat rate unit I 00 00 624	6 FRU
---	-------

— Job

Description: CBS: Service Motoröl

Is interpreted as a repeat visit: No

Customer's own words:

Engine oil service Flat rate unit I 00 00 610	3 FRU
--	-------

Set oil-filter element Part I 11 42 8 575 211	1
--	---

BMW Engine Oil LL04 5W30 Part I 83 21 2 405 948	5
--	---

— Job

Description: CBS: Service Kraftstofffilter

Is interpreted as a repeat visit: No

Customer's own words:

Fuel filter service Flat rate unit I 00 00 604	3 FRU
---	-------

Fuel filter cartridge Part I 13 32 8 572 522	1
---	---

— Job

Description: CBS: Service Luftfiltereinsatz

Is interpreted as a repeat visit: No

Customer's own words:

Service - air filter insert 2 FRU
Flat rate unit I 00 00 602

Air filter element 1
Part I 13 71 8 511 668

— Job

Description: CBS: Service Mikrofilter

Is interpreted as a repeat visit: No

Customer's own words:

Service - microfilter 2 FRU
Flat rate unit I 00 00 616

Microfilter/activated Carbon container 1
Part I 64 11 9 237 555

— Job

Description: CBS: Standardumfang

Is interpreted as a repeat visit: No

Customer's own words:

Standard scope of service 2 FRU
Flat rate unit I 00 00 105

— Job

Description: Kantenschutz

Is interpreted as a repeat visit: No

Customer's own words:


Replacing edge protection for left or right front door 5 FRU
Flat rate unit I 51 72 000

Edge protection, door, front 1
Part I 51 72 7 303 968

— 02/06/2018 Service 27629 km 27909 Autohaus Reisacher GmbH, Ulm Manual



— 02/01/2018 Key 27628 km 27909 Key 0



—	02/01/2018	Repair	27637 km	27909 Autohaus Reisacher GmbH, Ulm	Job Job Job
---	------------	--------	----------	---	-------------------

— Job

Description: Kleine Auslieferungsdurchsicht JGA/VfW (0099014)

Is interpreted as a repeat visit: No

Customer's own words:

!!! unknown BMW-Id 0099014 Kl. Auslieferungsdurchsicht Kratzer,DellenLocal prüfen AdBlue soll immer VOLL sein,ggf. auffüllen !!! Flat rate unit I 00 99 014	8 FRU
---	-------

Standard scope of service Flat rate unit I 00 00 105	2 FRU
---	-------

Engine oil service Flat rate unit I 00 00 610	3 FRU
--	-------

Service - microfilter Flat rate unit I 00 00 616	2 FRU
---	-------

Replacing all wiper blades Flat rate unit I 61 61 547	1 FRU
--	-------

Set oil-filter element Part I 11 42 8 575 211	1
--	---

Microfilter/activated Carbon container Part I 64 11 9 237 555	1
--	---

Set of wiper blades Part I 61 61 2 241 375	1
---	---

Wiper blade Part I 61 62 7 356 763	1
---------------------------------------	---

Windshield Washer Antifreeze Part I 83 12 2 409 031	2
--	---

BMW Engine Oil LL04 0W30 Part I 83 21 2 405 950	5
--	---

— Job

Description: HU und AU durchführen Dekra intern ULM

Is interpreted as a repeat visit: No

Customer's own words:

Bereitstellen zur Hauptuntersuchung Flat rate unit I -	Local	1 FRU
---	-------	-------

Abgasmessung Diesel mit OBD 2 Jährig Flat rate unit I -	Local	5 FRU
--	-------	-------

— Job

Description: prüfen und instandsetzen

Is interpreted as a repeat visit: No

Customer's own words:

!!! unknown BMW-Id 5199500 Kugelkopf AHK gangbar machen !!! Local 2 FRU
Flat rate unit I 51 99 500

—	03/02/2017	Service	2 km	30982 ISIS/ ITools int. Kunden Inlan, Garching	Manual
---	------------	---------	------	---	--------



0

03/2017

✓