

Vehicle

BMW 430i, 185kW

WBA4D91030G765815



Development code
Color
Actual integration level
Start of warranty

F36
black-sapphire metallic
F020-16-11-502
November 18, 2016

▼ Technical Campaigns

There are no campaigns available.

▼ Special information

There are no campaigns available.

▼ Live Diagnosis

 There are no service solutions for Live Diagnosis.

▼ Service contracts

No BSI contracts available

You can find additional service contract information and selection options in the DCSNet warranty vehicle enquiry.

▼ Information on faults, workshop/Service Consultation

No information on faults is available.

▼ Navigation map

Note: The installed map cannot be identified. One of the following maps could be installed in the vehicle.

Installed map	Enabling code (subscription)	Latest navigation map included in subscription	Latest navigation map subject to charge
Road Map EUROPE EVO 2016-4 (as of: Oct 2, 2020)	-	-	-
Road Map EUROPE EVO 2016-4 (as of: Oct 2, 2020)	Release code valid for navigation maps with release date up to Dec 31, 2099 (SWID: 01200FFF).	Road Map EUROPE EVO 2026-1	-

▾ Vehicle details

Vehicle type	Passenger car
Brand	BMW
Model	430i
Body	COUPE
Vehicle identification number (last 7 characters)	G765815
Vehicle identification number (17 characters)	WBA4D91030G765815
Development code	F36
Steering	LL
Engine	B48O
Engine number	15179798
Exhaust re-treatment	EURO6;W;PI/CI; M, N1 I
Transmission	AUT
Transmission number	0670830WDP
Head unit serial number	HB2240G8073144
Drive	HECK
Integration level	F020-16-11-502
Production date	Nov 9, 2016
Production works	Dingolfing
Delivery date	Nov 10, 2016
Delivering Retailers	No information
National-market version	EUR
Paint code	475
Upholstery code	LCV1
Model code	4D01
Base type	4D91
Lead type	4D01

▾ Optional equipment

Optional equipment fitted at the factory:

01CA Selection of COP relevant vehicles
01CB CO2 package
0230 EU-specific additional contents
0258 Tire with run-flat functionality
02NH M Sport brakes

Retrofitted optional equipment:

This vehicle has no retrofits.

02PF BMW LA wheel M Star Spoke 403
02TB Sport automatic transmission
02VB Tire pressure display
02VF Adaptive M suspension
0302 Alarm system
0320 Deleted, model lettering
0322 Comfort access
0337 M Sports package
03AG Reversing camera
0403 Glass roof, electrical
0420 Sun protection glazing
0423 Floor mats, velours
0428 Warning triangle and first aid kit
0430 Interior/outside mirror with auto dip
0431 Interior mirror with automatic-dip
0481 Sports seat
0488 Lumbar support, driver and passenger
0493 Storage compartment package
0494 Seat heating driver/passenger
04AE Armrest front, retractable
04FU Fine wood 'Fineline' anthracite/accent
04NE Blow-by heater
0502 Headlight cleaning system
0508 Park Distance Control (PDC)
0521 Rain sensor
0534 Automatic air conditioning
0548 Kilometer-calibrated speedometer
0552 Adaptive LED headlight
0563 Lights package
0575 Supplementary 12V sockets
05AC High-beam assistant
05AS Driving Assistant
05DA Passenger airbag deactivation
05DF Active cruise control+Stop&Go function
05DP Park Assistant
0609 Navigation system Professional
0610 Head-up display
0688 Harman/Kardon Surround Sound system
0698 Area-Code 2 for DVD
06AC Intelligent emergency SOS call
06AE Teleservices
06AK Connected Drive Services
06AM Real-Time Traffic Information
06AN Concierge Services
06AP Remote Services
06CP Smartphone integration
06NS Convenience phone, expanded Smartphone
06WA Instrument cluster, expanded equipment
0710 M leather steering wheel
0715 M Aerodynamics package
0760 High gloss shadow line
0775 Headlining anthracite
07LF Modell M Sport
07R7 Innovation package
07XP Navigation package, Connected Drive
0801 German version
0851 Language version German
0879 On-board vehicle literature German
08KA Oil service interval, 24 mos./30,000 km
08R9 Refrigerant R1234yf
08TH Road sign detection
A090 90 AH AGM battery
LEDE Leather trim

Date	Type	Vehicle mileage				Dealer	Overview
03/25/2026	Key	207441 km				32320	Remote KeyRead
							
16000	16000	16000	16000	37000	10/2027	60000	16000
04/2027	04/2027	04/2027	04/2027				04/2027
03/25/2026	Key	207441 km				32320	Key 0
							
16000	16000	16000	16000	37000	10/2027	60000	16000
04/2027	04/2027	04/2027	04/2027				04/2027
11/10/2025	Key	202471 km				22526	Key 0
							
21000	21000	21000	21000	46000	10/2027	70000	21000
04/2027	04/2027	04/2027	04/2027				04/2027
11/10/2025	Repair	202471 km				22526 ,	Job Job: Kostenlose Fzg.Wäsche Job

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Check the cooling system for watertightness with the special tool 4 FRU
Flat rate unit I 17 00 009

Removing and installing/replacing cylinder head-expansion tank coolant line 15 FRU
Flat rate unit I 17 12 512

Hose, cylinder head-expansion tank 1
Part I 17 12 9 845 173

Radiator antifreeze 2
Part I 83515A6CDD7

— Job: Kostenlose Fzg.Wäsche

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Kostenlose Fzg.Wäsche
Package I 0200000

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

—	10/14/2025	Key	200912 km	32320	Key 0		
 23000 04/2027	 23000 04/2027	 23000 04/2027	 23000 04/2027	 48000	 -13 1.8 %	 70000	 23000 04/2027
—	10/14/2025	Service	200912 km	32320 Alfred Wahl GmbH&Co. KG , Gießen	Automatic		
 23000 04/2027	 23000 04/2027	 23000 04/2027	 23000 04/2027	 48000	 10/2025 ✓	 70000	 23000 04/2027
—	04/02/2025	Key	190044 km	34409	Remote KeyRead		
 1400 10/2025			 1400 10/2025	 60000	 10/2025	 80000	 35000 10/2027
—	04/02/2025	Key	190044 km	32320	Key 0		
 1400 10/2025			 1400 10/2025	 60000	 10/2025	 80000	 35000 10/2027
—	04/02/2025	Service	190044 km	32320 Alfred Wahl GmbH&Co. KG , Gießen	Automatic		
 1400 10/2025 ✓			 1400 10/2025 ✓	 60000	 10/2025	 80000	 35000 10/2027
—	03/26/2025	Key	189911 km	34409	Remote KeyRead		

			
1500			1500
10/2025			10/2025

			
60000		80000	35000
	10/2025		10/2027

— 11/22/2024 Key 184875 km 32320 Key 0

			
7000			7000
10/2025			10/2025

			
60000		80000	40000
	10/2025		10/2027

— 05/02/2023 Key 147666 km Key 0

			
17000			17000
09/2024			09/2024

			
20000		40000	50000
	10/2023		09/2026

— 05/02/2023 Repair 147666 km 32320
 Autohaus Wahl Job
 Mittelhessen Job
 GmbH & Co. Job
 KG , Gießen Job

— Job

Description:
 Is interpreted as a repeat visit: No
 Customer's own words:

Windshield Washer Antifreeze Part I 83125A1A171	2
--	---

— Job

Description:
 Is interpreted as a repeat visit: No
 Customer's own words:

Original BMW Motorenöl LL04 0W-30 Part I FT97 99 0 000 0	Local	0.25
---	-------	------

— Job

Description:
 Is interpreted as a repeat visit: No
 Customer's own words:

Checking brake pad thickness Flat rate unit I 34 00 510	1 FRU
--	-------

— Job

Description:
 Is interpreted as a repeat visit: No

Customer's own words:

Replace left and right wiper blade
Flat rate unit I 61 61 541 1 FRU

Set of wiper blades
Part I 61615A43587 1

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Räder maschinell reinigen (Oberflächenreinigung)
Flat rate unit I 99 99 999 Local 1 FRU

— 04/14/2023 Key 147222 km Remote KeyRead



— 10/26/2022 Key 134422 km Key 0



— 09/08/2022 Key 131232 km 32320 Key 0



— 09/08/2022 Service 131232 km 32320 Automatic
Autohaus Wahl
Mittelhessen
GmbH&Co. KG
, Gießen



— 09/08/2022 Repair 131232 km 32320 Job
Autohaus Wahl Job
Mittelhessen Job
GmbH & Co. Job
KG , Gießen Job
Job
Job

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Standard scope of service	2 FRU
Flat rate unit I 00 00 105	

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Vehicle check service	6 FRU
Flat rate unit I 00 00 624	

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Engine oil service	3 FRU
Flat rate unit I 00 00 610	

Original BMW Motorenöl LL04 0W-30	Local	5.25
Part I FT97 99 0 000 0		

Set oil-filter element	1
Part I 11 42 8 575 211	

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Service - microfilter	2 FRU
Flat rate unit I 00 00 616	

Microfilter/activated Carbon container	1
Part I 64 11 9 237 555	

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Service - air filter insert	1 FRU
Flat rate unit I 00 00 602	

Air filter element	1
Part I 13 71 8 605 164	

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Spark plugs service
Flat rate unit I 00 00 622 11 FRU

Spark plug, High Power
Part I 12 12 0 040 551 4

Torx screw with collar
Part I 07 14 7 270 121 4

— Job



Description:

Is interpreted as a repeat visit: No


Customer's own words:

Der 20% Altersrabatt auf ausgewählte Serviceleistung en
Flat rate unit I 99 99 999 Local 1 FRU

— 08/17/2022 Key 129267 km 32320 Remote KeyRead



— 03/21/2022 Key 119157 km 32320 Key 0



— 03/15/2022 Repair 119157 km 32320 Job
Autohaus Wahl
Mittelhessen
GmbH & Co.
KG , Gießen

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Replacing four tires with run-flat technology
Flat rate unit I 36 12 577 23 FRU

— 03/08/2022 Key 118109 km 32320 Remote KeyRead

13000	13000	13000	13000
05/2023	413	413	413

60000	10/2023	70000	13000
			05/2023

— 10/22/2021 Key 109165 km Key 0

22000	22000	22000	22000
05/2023	549	549	549

70000	11/2021	80000	22000
			05/2023

— 10/22/2021 Service 109165 km 32320 Automatic
Autohaus Wahl
Mittelhessen
GmbH&Co. KG
, Gießen

22000	22000	22000	22000

70000	0	80000	22000
	✓		

— 10/22/2021 Repair 109165 km 32320 Job
Autohaus Wahl Job
Mittelhessen Job
GmbH & Co. Job
KG , Gießen

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Brake fluid service 4 FRU
Flat rate unit I 00 00 618

Brake fluid DOT4 LV, low viscosity 1
Part I 83 13 2 184 843

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Standard scope of service 2 FRU
Flat rate unit I 00 00 105

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

§ emission test with on-board diagnosis 5 FRU

— Job



Description:

Is interpreted as a repeat visit: No



Customer's own words:

HU Geb. n. §29 StVZO DEKRA 00000000	Local	1 FRU
Flat rate unit I 99 99 999		
Mietwagen SI-JA 283 22.10.2021 00000000	Local	1 FRU
Flat rate unit I 99 99 999		

— 05/20/2021 Key 98035 km Key 0



— 05/20/2021 Service 98035 km 32320 Automatic
Autohaus Wahl
Mittelhessen
GmbH&Co. KG
, Gießen



— 05/20/2021 Repair 98035 km 32320 Alfred Job
Wahl GmbH & Job
Co. KG, Job
Gießen Job
Job

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Reinigung zum Schnellservice * Frontscheibe reinigen * Fußraum vorne aussaugen	Local	1 FRU
Flat rate unit I 00 52 900		
Fast service with compact check or service consultation at the vehicle		1 FRU
Flat rate unit I 00 52 055		

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Standard scope of service		7 FRU
---------------------------	--	-------

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Engine oil service	3 FRU
Flat rate unit I 00 00 610	

Original BMW Motorenöl LL04 0W-30	Local	5.25
Part I FT97 99 0 000 0		

Set oil-filter element	1
Part I 11 42 8 575 211	

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Service - microfilter	2 FRU
Flat rate unit I 00 00 616	

Microfilter/activated Carbon container	1
Part I 64 11 9 237 555	

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Replace left and right wiper blade	1 FRU
Flat rate unit I 61 61 541	

Set of wiper blades	1
Part I 61 61 2 349 870	

—	03/26/2021	Key	94343 km	Key 0
---	------------	-----	----------	-------

			
3700	0	0	3700
11/2021			249

			
90000	0	100000	37000
	11/2021		11/2023

—	03/24/2021	Repair	94343 km	32320 Alfred Wahl GmbH & Co. KG , Gießen	Job Job Job
---	------------	--------	----------	--	-------------------

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Check Kompakt Annahme

Flat rate unit I 00 11 200

Local

2 FRU

Battery

Part I 61 31 9 217 643

1

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Scheibenklar auffüllen JA () NEIN () bis - Grad

Flat rate unit I 00 00 246

Local

0 FRU

Windshield Washer Antifreeze

Part I 83 12 2 468 611

2

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Motorölstand prüfen, ggf. ergänzen JA () NEIN ()

Flat rate unit I 00 00 247

Local

0 FRU

— 03/18/2021 Key

94215 km

Key 0



3800

11/2021



0



0



3800

256



90000



0

11/2021



100000



37000

11/2023

— 03/18/2021 Repair

94215 km

32320 Alfred Wahl GmbH & Co. KG , Gießen

Job
Job
Job
Job

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Package I MM02001*BM4D01

Local

Pflegepaket Komfort

Flat rate unit I AZ00 03 1

Local

0

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Package I MM02004*BM4D01

Local

Pflegepaket Lack/Politur
Flat rate unit I AZ00 03 4

Local 0

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Package I MM02007*BM4D01

Local

Pflegepaket Innenraum
Flat rate unit I AZ00 03 7

Local 0

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

!!! unknown BMW-Id ESTIMATE 0151-46359917 !!!
Flat rate unit I -

Local 0 FRU

— 10/01/2020 Key 82799 km 32320 Key 0

			
16000	0	0	16000
11/2021			424

			
1000	0	12000	49000
	11/2021		11/2023

— 10/01/2020 Service 82799 km 32320 ASW Automatic
Wahl GmbH & Co. KG, Gießen

			
16000	0	0	16000
11/2021			11/2021

			
1000	0	12000	49000
✓	11/2021	✓	11/2023

— 10/01/2020 Repair 82806 km 32320 Alfred Job
Wahl GmbH & Job
Co. KG , Job
Gießen Job
Job

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Standard scope of service
Flat rate unit I 00 00 105

2 FRU

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Service - front brakes Flat rate unit I 00 00 612		6 FRU
A.Reiniger Part I FT99 99 0 000 0	Local	1
Repair kit, brake pads asbestos-free Part I 34 11 6 878 882		1
Guide pin Part I 34 11 6 850 934		2
Expansion spring Part I 34 11 6 862 801		2
Brake pad wear sensor, front left Part I 34 35 6 792 289		1
Brake pad paste Part I 83 19 2 158 851		2

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Rear brakes service Flat rate unit I 00 00 614		7 FRU
A.Reiniger Part I FT99 99 0 000 0	Local	1
Expansion spring Part I 34 21 6 857 151		2
Guide pin Part I 34 21 6 857 152		2
Repair kit, brake pads asbestos-free Part I 34 21 6 887 576		1
Brake pad wear sensor, rear Part I 34 35 6 792 292		1
Brake pad paste Part I 83 19 2 158 851		2

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

AZ without specification/maintenance Flat rate unit I 00 99 000		0 FRU
Windshield Washer Antifreeze Part I 83 12 2 468 611		2

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Mietwagen SI-NA 269 01.10.-02.10.2020 00000000 Local 1 FRU
Flat rate unit I 99 99 999

— 09/15/2020 Repair 73659 km 32320 Alfred Wahl GmbH & Co. KG, Gießen Job

— Job






Description:

Is interpreted as a repeat visit: No

Customer's own words:

Replacing four tires with run-flat technology 23 FRU
Flat rate unit I 36 12 577

— 05/15/2020 Key 73659 km 32320 Key 0



— 05/15/2020 Repair 73659 km 32320 Alfred Wahl GmbH & Co. KG, Gießen Job
Job
Job
Job
Job

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Package I MM01005*BM4D01 Local
Scheibenwaschanlage mit Local 0
Flat rate unit I AZ00 00 5

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Package I MM01023*BM4D01

Local

Motorölstand prüfen, ggf.
Flat rate unit I AZ00 01 6

Local

0

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Package I MM04010*BM4D01

Local

Kompleträder montieren
Flat rate unit I AZ36 00 1

Local

6

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Package I MM04014*BM4D01

Local

Vorder- und Hinterräder
Flat rate unit I AZ36 00 4

Local

4

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Package I MM04020*BM4D01

Local

Kompleträder einlagern
Flat rate unit I AZ36 00 2

Local

1

Räder maschinell reinigen
Flat rate unit I AZ36 00 5

Local









1

— 11/08/2019 Key

64985 km

32320

Key 0










— 11/08/2019 Service

64985 km

32320 ASW
Wahl
GmbH&Co. KG
, Gießen

Automatic



—	11/08/2019	Repair	65012 km	32320 Alfred Wahl GmbH & Co. KG, Gießen	Job Job Job Job Job Job Job Job Job
---	------------	--------	----------	--	---

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Standard scope of service Flat rate unit I 00 00 105	2 FRU
---	-------

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Vehicle check service Flat rate unit I 00 00 624	6 FRU
---	-------

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Engine oil service Flat rate unit I 00 00 610	3 FRU
--	-------

Original BMW Motorenöl LL04 0W-30 Part I FT97 99 0 000 0	Local	5.25
---	-------	------

Set oil-filter element Part I 11 42 8 575 211	1
--	---

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Service - microfilter Flat rate unit I 00 00 616	2 FRU
---	-------

Microfilter/activated Carbon container Part I 64 11 9 237 555	1
--	---

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Service - air filter insert Flat rate unit I 00 00 602	1 FRU
---	-------

Air filter element Part I 13 71 8 605 164	1
--	---

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Spark plugs service Flat rate unit I 00 00 622	11 FRU
---	--------

Torx screw with collar Part I 07 14 7 270 121	4
--	---

Spark plug, High Power Part I 12 12 0 040 551	4
--	---

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Brake fluid service Flat rate unit I 00 00 618	4 FRU
---	-------

Brake fluid DOT4 LV, low viscosity Part I 83 13 2 184 843	1
--	---

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

§ emission test with on-board diagnosis Flat rate unit I 00 00 528	5 FRU
---	-------

(Mandatory) general inspection Flat rate unit I 00 12 559	0 FRU
--	-------

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Outside car wash and interior vehicle cleaning Flat rate unit I 00 11 329	0 FRU
--	-------

— Job

Description:

Is interpreted as a repeat visit: No








Customer's own words:

HU Geb. n. §29 StVZO (zur ext. Verrechnung) 00000000
Flat rate unit I 99 99 999

Local

1 FRU

— 05/21/2019 Key 55779 km 32320 Key 0



— 05/21/2019 Repair 0 km 32320 Alfred Wahl GmbH & Co. KG, Gießen Job Job Job Job Job

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Service consultation at the vehicle
Flat rate unit I 00 52 050

0 FRU

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Work time without specification/body equipment
Flat rate unit I 51 99 000

2 FRU

Removing and installing rear bumper panel
Flat rate unit I 51 12 656

4 FRU

Replace rear bumper panel
Flat rate unit I 51 12 657

1 FRU

Additional work with Park Distance Control
Flat rate unit I 66 20 602

2 FRU

Performing vehicle test
Flat rate unit I 00 00 556

2 FRU

Resume vehicle test and clear fault memory
Flat rate unit I 61 00 980

2 FRU

Work time without specification/body equipment
Flat rate unit I 51 99 000

3 FRU

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Painting bumper cover, rear Flat rate unit I 99 69 525	0 FRU
Work time without specification/paintwork Flat rate unit I 99 99 000	0 FRU

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Bumper trim panel, primed, rear Part I 51 12 8 073 080	1
Trim panel, bumper, rear, bottom Part I 51 12 8 054 563	1

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Lackierarbeiten (-R-) 00000000 Flat rate unit I 99 99 999	Local	1 FRU
Leihfahrzeug SI-PT 774 21.05.-23.05.19 00000000 Flat rate unit I 99 99 999	Local	1 FRU

— 05/10/2019 Key 55350 km 32320 Key 0

 11000 04/2020	 11000 356	 11000 356	 11000 356	 19000	 0 11/2019	 36000	 11000 04/2020
---	---	---	---	--	---	--	--

— 05/04/2019 Key 55241 km 32320 Key 0

 11000 04/2020	 11000 362	 11000 362	 11000 362	 19000	 0 11/2019	 36000	 11000 04/2020
---	---	---	---	--	---	--	--

— 10/27/2018 Repair 44292 km 32320 Alfred Wahl GmbH & Co. KG, Gießen Job Job Job

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Kompakt-Check	Local	1 FRU
---------------	-------	-------

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Motorölstand prüfen, ggf. ergänzen JA (X) NEIN ()
 Flat rate unit I 00 00 247

Local

0 FRU

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Scheibenklar auffüllen JA (X) NEIN ()
 Flat rate unit I 00 00 246

Local









0 FRU

— 07/30/2018 Key

39314 km

32320

Key 0



— 07/30/2018 Repair

0 km

32320 Alfred
 Wahl GmbH &
 Co. KG,
 Gießen

Job
 Job
 Job
 Job
 Job

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Service consultation at the vehicle
 Flat rate unit I 00 52 050

0 FRU

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Work time without specification/body equipment
 Flat rate unit I 51 99 000

2 FRU

Removing and installing or replacing water strip on left or right side of
 windshield
 Flat rate unit I 51 31 530

1 FRU

Removing and installing left or right roof trim strip
 Flat rate unit I 51 13 780

1 FRU

Stripping and refitting work for painting side panel, rear left Flat rate unit I 51 18 720	2 FRU
Removing and installing/replacing rear left or right wheel arch cover Flat rate unit I 51 71 541	3 FRU
Removing and installing front or rear wheel Flat rate unit I 36 10 800	1 FRU
Removing and installing rear bumper panel Flat rate unit I 51 12 656	4 FRU
Replace rear bumper panel Flat rate unit I 51 12 657	1 FRU
Additional work with Park Distance Control Flat rate unit I 66 20 602	2 FRU
Removing and installing/replacing the bumper guide, rear left or right Flat rate unit I 51 12 828	2 FRU
Performing vehicle test Flat rate unit I 00 00 556	2 FRU
Resume vehicle test and clear fault memory Flat rate unit I 61 00 980	2 FRU
Work time without specification/body equipment Flat rate unit I 51 99 000	3 FRU

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Work time without specification/paintwork Flat rate unit I 99 99 000	0 FRU
Painting the rear quarter panel, left or right Flat rate unit I 99 36 529	0 FRU
Painting bumper cover, rear Flat rate unit I 99 69 525	0 FRU
Work time without specification/paintwork Flat rate unit I 99 99 000	0 FRU
AZ without specification/maintenance Flat rate unit I 00 99 000	18 FRU

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Bumper trim panel, primed, rear Part I 51 12 8 073 080	1
Guide for bumper, side, left Part I 51 12 7 428 731	1
Ultrasonic sensor, black	1

1 FRU



2 FRU

1

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Service - microfilter Flat rate unit I 00 00 616	2 FRU
Microfilter/activated Carbon container Part I 64 11 9 237 555	1

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Outside car wash and interior vehicle cleaning Flat rate unit I 00 11 329	0 FRU
AZ without specification/maintenance Flat rate unit I 00 99 000	0 FRU

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Kosten Mietwagen SI-PS 817 12.04.2018 Flat rate unit I 99 99 999	Local	1 FRU
---	-------	-------

— 10/14/2017 Key 21948 km 32320 Key 0

 10000 11/2018	 0	 0	 10000 412	 50000	 0 11/2019	 60000	 42000 11/2020
---	--	--	---	--	---	--	--

— 10/14/2017 Repair 21948 km 00139 Alfred Wahl GmbH & Co. KG, Siegen Job Job Job

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Räderwechsel MIT Wuchten Flat rate unit I -	Local	6 FRU
--	-------	-------

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Package I MM04GIEßEN

Local

Räder montieren

Flat rate unit I AZ01 02 1

Local

6

Rädereinlagerung inkl.

Flat rate unit I AZ01 02 4

Local

1

Vorder- und Hinterräder

Flat rate unit I AZ01 02 5

Local

7

Kompakt-Check

Flat rate unit I 00 52 000

Local

1

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

!!! unknown BMW-Id ESTIMATE 0151-58719510 !!!

Local

0 FRU



Flat rate unit I -

— 04/08/2017 Key


7804 km

32320



Key 0

24000
11/2018



0




0

24000
600

50000

0
11/2019

60000

60000
11/2020

— 04/08/2017 Repair

7804 km

32320 Alfred
Wahl GmbH &
Co. KG,
Gießen

Job

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Kompakt-Check Ablaufdatum Verbandskasten (12 /2022)

Local

1 FRU

Flat rate unit I 00 52 000

Scheibenklar auffüllen JA (X) NEIN ()

Local

0 FRU

Flat rate unit I 00 00 246

Motorölstand prüfen, ggf. ergänzen JA (X) NEIN ()

Local

0 FRU

Flat rate unit I 00 00 247

Windshield Washer Antifreeze

2

Part I 83 12 2 296 208

— 11/14/2016 Repair

0 km

32320 Alfred
Wahl GmbH &

Job

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Free pre-delivery check	9 FRU
Flat rate unit I 00 00 009	