

Vehicle

BMW 330d xDrive, 210kW

WBA6N510X0FK64487



Development codeG21

ColorPortimao blau metallic

Actual integration levelS18A-23-11-550

Start of warrantyNovember 27, 2020

 There are active service contracts present.

▼ Technical Campaigns

There are no campaigns available.

▼ Special information

There are no campaigns available.

▼ Live Diagnosis

 There are no service solutions for Live Diagnosis.

▼ Service contracts

Description	Issuer	Billing as of	Duration	Vehicle mileage
UC Service Inclusive for Used Cars - 5 years / 100,000 km	AG	Dec 19, 2025	to Dec 18, 2030	to 237970 km

You can find additional service contract information and selection options in the DCSNet warranty vehicle enquiry.

▼ Information on faults, workshop/Service Consultation

No information on faults is available.

▼ Navigation map

Installed map	Enabling code (subscription)	Latest navigation map included in subscription	Latest navigation map subject to charge
Road Map EUROPE Live 2023-3 (as of: Aug 18, 2026)	Release code valid for navigation maps with release date up to Dec 31, 2099 (SWID: 01559912).	Road Map EUROPE Live 2026-3	-

▼ Vehicle details

Vehicle type	Passenger car
Brand	BMW
Model	330d xDrive
Body	TOUR
Vehicle identification number (last 7 characters)	FK64487
Vehicle identification number (17 characters)	WBA6N510X0FK64487
Development code	G21
Steering	LL
Engine	B57P
Engine number	54706247
Exhaust re-treatment	Euro 6 AP
Transmission	AUT
Transmission number	0414686WLD
Head unit serial number	ALB314L1493099
Drive	ALLR
Integration level	S18A-20-11-520
Production date	Nov 18, 2020
Production works	Muenchen
Delivery date	Nov 19, 2020
Delivering Retailers	Helming & Sohn GmbH, Lingen, DE
National-market version	EUR
Paint code	C31
Upholstery code	KGNL
Model code	6N61
Base type	6N51
Lead type	6N61

▾ Optional equipment

Optional equipment fitted at the factory:

01AG Higher-capacity fuel tank
 01CB CO2 package
 01CE Energy recovery system
 01PL 19" LA wheel double spoke 791M em.op.
 0230 EU-specific additional contents
 0258 Tire with run-flat functionality
 02NH M Sport brakes
 02PA Wheel bolt retainer
 02T4 M sport differential

Retrofitted optional equipment:

This vehicle has no retrofits.

02TB Sport automatic transmission
02VB Tire pressure display
02VF Adaptive M suspension
02VL Variable Sport steering
0302 Alarm system
0320 Deleted, model lettering
0322 Comfort Access
03BE Mirror caps, black
03KA Acoustic comfort windows
03MC M roofrailing, Shadow Line
03MF M lights ShadowLine
0420 Sun protection glazing
0428 Warning triangle and first aid kit
0430 Interior/outside mirror with auto dip
0431 Interior mirror with automatic-dip
0481 Sports seat
0488 Lumbar support, driver and passenger
0493 Storage compartment package
0494 Seat heating driver/passenger
04KA Fine-wood trim Oak grain, open-cell
04U0 Electroplat.cover/clip f.operat.elements
04UR Ambient interior lighting
0534 Automatic air conditioning
0548 Kilometer-calibrated speedometer
05A1 LED Fog lights
05AC High-beam assistant
05AL Active Protection
05AQ Active Guard Plus
05AU Driving assistant professional
05AZ BMW Laserlicht
05DA Passenger airbag deactivation
05DC Rear-seat headrests, folding
05DM Parking assistance system
0610 Head-up display
0654 DAB tuner (DAB-enabled)
0688 Harman/Kardon Surround Sound system
06AE Teleservices
06AF Statutory emergency request
06AK Connected Drive Services
06C4 Connected Package Professional
06NW Phoning with wireless charging
06U3 BMW Live dashboard Professional
06WD WLAN Hotspot
0710 M leather steering wheel
0715 M Aerodynamics package
0760 High gloss shadow line
0775 Headlining anthracite
07LF Modell M Sport
07M9 M Shadow Line with expanded scope
07R7 Innovation package
0801 German version
0851 Language version German
0879 On-board vehicle literature German
08KA Oil service interval, 24 mos./30,000 km
08R9 Refrigerant R1234yf
08TF Active pedestrian protection
08TR Decoding supplementary functions
09AA Outer skin protection
09D5 Entertainment package de
09D6 Fahrerlebnis package de
A090 90 AH AGM battery

► Software version control units

▼ Vehicle histories

	Date	Type	Vehicle mileage	Dealer	Overview
—	08/18/2026	Repair	152900 km	04569 ,	Job Job

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Service consultation at the vehicle Flat rate unit I 00 52 050	1 FRU
---	-------

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Replace windshield Flat rate unit I 51 31 011	29 FRU
--	--------

Additional work with KAFAS camera Flat rate unit I 66 51 990	5 FRU
---	-------

Water accessory element, right Part I 51 31 9 466 592	1
--	---

Sound insulation windshield Part I 51 48 7 941 312	2
---	---

Repair flat rate, window, cold, 1 hr. Part I 83 19 2 289 285	1
---	---

Drip moulding, left Part I 51 31 7 427 873	1
---	---

Cover, windshield, top Part I 51 31 7 427 861	1
--	---

Water accessory element, left Part I 51 31 9 466 591	1
---	---

Drip molding, right Part I 51 31 7 427 874	1
---	---

Bump stop Part I 51 31 7 288 462	2
-------------------------------------	---

Windshield, green, rain/light/fog Part I 51 31 7 477 267	1
---	---

Adhesive tape Part I 83 19 2 157 772	2
---	---

Cleanser R2 Part I 83195B67072	0.1
-----------------------------------	-----

—	08/17/2026	Key	152900 km	04569	Key 10
---	------------	-----	-----------	-------	--------

 25000 03/2028	 25000 03/2028	 25000 03/2028	 25000 03/2028		 12/2027	 12/2027		 25000 03/2028	 12/2027	
--	--	--	--	--	---	---	---	--	---	--

— 08/13/2026 Key 152861 km 04569 Key 10

 26000 03/2028	 26000 03/2028	 26000 03/2028	 26000 03/2028		 12/2027	 12/2027		 26000 03/2028	 12/2027	
---	---	---	---	---	--	--	--	---	--	---

— 08/11/2026 Key 152839 km 39906 Key 10

 26000 03/2028	 26000 03/2028	 26000 03/2028	 26000 03/2028		 12/2027	 12/2027		 26000 03/2028	 12/2027	
---	---	---	---	---	--	--	--	---	--	---

— 03/06/2026 Key 144977 km 04569 Key 10

 140 04/2027		 140 04/2027			 12/2027	 12/2027		 34000 04/2029	 12/2027	
---	---	---	---	---	--	--	--	---	--	---

— 03/06/2026 Service 144977 km 04569 Automatic
Niederlassung
Chemnitz ,
Chemnitz

 140 04/2027 ✓		 140 04/2027 ✓			 12/2027	 12/2027		 34000 04/2029	 12/2027	
--	---	--	---	---	--	--	--	---	--	---

— 03/06/2026 Repair 144977 km 04543 ,
Job
Job
Job
Job
Job
Job
Job
Job
Job

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words: Keine weiteren Arbeiten, Abholung: 06.03.2026 / Ca. 15:00 Uhr, Tel. +49 1514 2522665, Gesamtkosten ca. 1200 Euro,

Fast service with compact check or service consultation at the vehicle
Flat rate unit I 00 52 055

0 FRU

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Service consultation at the vehicle	0 FRU
Flat rate unit I 00 52 050	

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

BMW glass cleaner with antifreeze	1
Part I 83125B5ED57	

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Standard scope of service	2 FRU
Flat rate unit I 00 00 105	

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Service - microfilter	2 FRU
Flat rate unit I 00 00 616	

Microfilter/activated Carbon container	1
Part I 64 11 9 382 886	

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Engine oil service Flat rate unit I 00 00 610		3 FRU
Set oil-filter element Part I 11425B4C845		1
BMW TwinPower Turbo LL-19FE 0W-30 Part I 83215A65BF8		7
Battery Part I 66 12 6 912 985		1
Ölzuschlag für Service inklusive Part I 0000162	Local	1

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Motorölservice - zusätzliche AW Flat rate unit I IM00 25 0	Local	2 FRU
---	-------	-------

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Vehicle check in frame of acceptance Flat rate unit I 00 52 054		1 FRU
--	--	-------

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words: Ölverlust HA Getriebe bei HU bemängelt,*E: Kundenbeanstandung prüfen und ggf. defekte Teile ersetzen. Ölundichtigkeit am Hinterachsgetriebe befunden und nach RS. Instandse,

Replacing radial shaft seal for input flange of rear axle differential Flat rate unit I 33 11 502		20 FRU
--	--	--------

Screw plug with O-ring Part I 33 11 7 525 064		1
--	--	---

Shaft seal Part I 33 10 7 609 536		1
--------------------------------------	--	---

Repair kit recessed nut blue Part I 33 12 7 607 158		1
--	--	---

— 03/03/2026 Key 144975 km 04569 Remote KeyRead

 160 04/2027		 160 04/2027			 12/2027	 12/2027		 34000 04/2029	 12/2027	
---	---	---	---	---	--	--	--	---	--	---

— 12/30/2025 Repair 137971 km 04543 , Job

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words: Kosten Intern, aufgrund beschädigung Lenkradkranz zum Vorgänger-Auftrag.Absprache mit Serviceleiter Herr Lange.,

Fast service with compact check or service consultation at the vehicle
Flat rate unit I 00 52 055

0 FRU

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Standard Pflegepaket innerbetriebliche v
Part I 0099521

Local

1

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Einen Reifen a+e / Lack.
Flat rate unit I NL36 01 0

Local

9 FRU

BMW Felgenreparatur Felge VR
Flat rate unit I NL99 10 3

Local

24 FRU

—	12/19/2025	Key	137970 km	04569	Key 10
---	------------	-----	-----------	-------	--------

 8000 04/2027	 	 8000 04/2027	 	 	 -18 2.5 %	 -18 2.5 %	 	 41000 04/2029	 -18 2.5 %	
--	---	--	---	---	---	---	--	---	---	---

—	12/19/2025	Service	137970 km	04569 Niederlassung Chemnitz , Chemnitz	Automatic
---	------------	---------	-----------	--	-----------

 8000 04/2027	 	 8000 04/2027	 	 	 12/2025 ✓	 12/2025 ✓	 	 41000 04/2029	 12/2025 ✓	
--	---	--	---	---	---	---	--	---	---	---

—	12/19/2025	Repair	137970 km	04543 ,	Job Job Job Job Job Job
---	------------	--------	-----------	---------	--

— Job

Description:**Is interpreted as a repeat visit:** No**Customer's own words:** Keine weiteren Arbeiten, Abholung: 19.12.2025 ca. 13:00 Uhr, Gesamtkosten: 600 Euro#, Tel: 01514 2522665,

Fast service with compact check or service consultation at the vehicle	0 FRU
Flat rate unit I 00 52 055	

— Job

Description:**Is interpreted as a repeat visit:** No**Customer's own words:**

Ersatzfahrzeug (24 Stunden) zum Service	Local	1
Part I 0000160		

— Job

Description:**Is interpreted as a repeat visit:** No**Customer's own words:**

Standard scope of service	2 FRU
Flat rate unit I 00 00 105	

— Job

Description:**Is interpreted as a repeat visit:** No**Customer's own words:**

Brake fluid service	4 FRU
Flat rate unit I 00 00 618	

Brake fluid DOT4 LV, low viscosity	1
Part I 83 13 2 184 843	

— Job

Description:**Is interpreted as a repeat visit:** No**Customer's own words:** Gasdruckfedern für Frontklappe prüfen (bei Ersatz 51 23 266 / 766),

Removing and installing or replacing both gas pressure props for engine hood	1 FRU
Flat rate unit I 51 23 766	

Gas spring front flap, passive	2
Part I 51 23 7 419 387	

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Hauptuntersuchung nach § 29 StVZO
Part I 0012159

Local

1

§ Abgasuntersuchung mit OBD und Sonde
Part I NL12159

Local

1

Vergütung gem. Nr. 6.4 der Anlagen VIIIb
Part I NL12160

Local

1

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Vehicle check in frame of acceptance
Flat rate unit I 00 52 054

1 FRU

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Replace left and right wiper blade
Flat rate unit I 61 61 541

1 FRU

Set of wiper blades
Part I 61 61 9 478 361

1

—

12/19/2025 Repair

137970 km

04543 ,

Job
Job
Job

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words: Tel: 01514 2522665, Keine weiteren Arbeiten, Abholung: 23.12.2025 ca. 14:00 Uhr,

Fast service with compact check or service consultation at the vehicle
Flat rate unit I 00 52 055

0 FRU

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Neuen Winterradsatz anbauen, innerbetrie
Flat rate unit I NL36 00 3

Local

7 FRU

— Job

Description:

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words: Fertigstellung Donnerstag RR,

Vehicle check in frame of acceptance	1 FRU
Flat rate unit I 00 52 054	

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Standard scope of service	2 FRU
Flat rate unit I 00 00 105	

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Engine oil service	3 FRU
Flat rate unit I 00 00 610	

BMW TwinPower Turbo LL-19FE 0W-30	7
Part I 83215A65BF8	

Set oil-filter element	1
Part I 11 42 7 826 799	

Battery	1
Part I 66 12 6 912 985	

Ölzuschlag für Service Inklusive	Local	1
Part I 0000162		

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Fuel filter service	5 FRU
Flat rate unit I 00 00 604	

Fuel filter cartridge	1
Part I 13 32 8 591 019	

Self-locking hex nut	2
Part I 64 50 9 123 157	

— Job

Description:**Is interpreted as a repeat visit:** No**Customer's own words:**

Service - air filter insert	1 FRU
Flat rate unit I 00 00 602	

Air filter element	1
Part I 13 71 8 594 535	

— Job**Description:****Is interpreted as a repeat visit:** No**Customer's own words:**

Service - microfilter	2 FRU
Flat rate unit I 00 00 616	

Microfilter/activated Carbon container	1
Part I 64 11 9 382 886	

— Job**Description:****Is interpreted as a repeat visit:** No**Customer's own words:**

Vehicle check service	6 FRU
Flat rate unit I 00 00 624	

— Job**Description:****Is interpreted as a repeat visit:** No**Customer's own words:**

Motorölservice - zusätzliche AW	Local	2 FRU
Flat rate unit I IM00 25 0		

— Job**Description:****Is interpreted as a repeat visit:** No**Customer's own words:**

BMW glass cleaner with antifreeze	1
Part I 83125B5ED57	

— Job**Description:****Is interpreted as a repeat visit:** No**Customer's own words:**

Alle Scheinwerfer einstellen	Local	3 FRU
Flat rate unit I NL63 00 2		

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Nachrüstung Service Inclusive 5Jahre/100
Part I 5100102

Local 1

—	04/01/2025	Key	112085 km	04569	Remote KeyRead								
													
	1100	1100		1100						1100			
	03/2026	03/2026		03/2026			12/2025	12/2025		03/2026		12/2025	
—	12/16/2024	Key	103198 km	04569	Key 10								
													
	11000	11000		11000						11000			
	03/2026	03/2026		03/2026			12/2025	12/2025		03/2026		12/2025	
—	12/12/2024	Key	102714 km	04569	Key 10								
													
	11000	11000		11000						11000			
	03/2026	03/2026		03/2026			12/2025	12/2025		03/2026		12/2025	
—	10/04/2024	Key	99265 km	04569	Key 10								
													
	15000	15000		15000						15000			
	03/2026	03/2026		03/2026			12/2025	12/2025		03/2026		12/2025	
—	10/04/2024	Repair	99265 km	04543 ,	Job Job Job Job Job Job								

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Zeitzuschlag für eine Hauptarbeit
Flat rate unit I NL41 00 0

Local 2 FRU

Removing and installing rear bumper panel
Flat rate unit I 51 12 656

16 FRU

Replace rear bumper panel Flat rate unit I 51 12 657	4 FRU
---	-------

Additional work with Park Distance Control Flat rate unit I 66 20 603	1 FRU
--	-------

Performing vehicle test Flat rate unit I 00 00 556	6 FRU
---	-------

Supporting the voltage of the vehicle electrical system/recharging the vehicle electrical system battery Flat rate unit I 61 21 528	1 FRU
--	-------

Prüf-und Kalibrierfahrt Flat rate unit I NL41 00 0	Local	3 FRU
---	-------	-------

Performing vehicle test Flat rate unit I 00 00 556	4 FRU
---	-------

Supporting the voltage of the vehicle electrical system/recharging the vehicle electrical system battery Flat rate unit I 61 21 528	1 FRU
--	-------

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words: Zeitzuschlag für eine Hauptarbeit,Umfasst: Farbe mischen und Farbmuster spritzen,

M - Painting bumper cover, rear Flat rate unit I 99 69 571	11 FRU
---	--------

Zeitzuschlag für eine Hauptarbeit Umfass Flat rate unit I NL99 00 0	Local	16 FRU
--	-------	--------

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Kit, mount for PDC/PMA sensor, rear Part I 51 12 9 851 721	1
---	---

Bumper trim panel, rear Part I 51 12 8 099 912	1
---	---

Self-locking hex nut Part I 64 50 9 123 157	4
--	---

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Steinschläge Frontklappe auslegen Flat rate unit I NL99 00 0	Local	1 FRU
---	-------	-------

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words: Sommerräder ins Fahrzeug legen,RW lt. RS Herr Hahn kostenlos - WR waren nicht angefordert - dadurch,Verzögerung bei der Rep.,

Alle Räder ab- und anbauen (Radsatz mont
Flat rate unit I NL36 00 1

Local 7 FRU

Battery
Part I 66 12 6 912 985

1

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Lackmaterial
Part I 99 99 9 999 990

Local 119

— 07/12/2024 Key 91433 km 04569 Key 10

 23000 03/2026	 23000 03/2026	 23000 03/2026	 23000 03/2026	 12/2025	 12/2025	 03/2026	 12/2025	 23000 03/2026	 12/2025	 12/2025
---	---	---	---	--	--	--	---	---	--	--

— 07/12/2024 Repair 91433 km 04543 , Job

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Replace the wiper arm for the rear wiper
Flat rate unit I 61 62 030

2 FRU

Rear window wiper arm
Part I 61 62 7 468 053

1

— 03/15/2024 Key 80850 km 04569 Key 10

 -100 0.4 % 12/2024	 12/2024	 -100 12/2024	 12/2025	 12/2025	 12/2025	 12/2026	 28000 12/2026	 12/2025	 12/2025
---	--	--	--	--	--	--	--	--	--

— 03/15/2024 Service 80850 km 04569 Automatic
Niederlassung
Chemnitz ,
Chemnitz

 -100 12/2024 ✓	 12/2024	 -100 12/2024 ✓	 12/2025	 12/2025	 12/2025	 28000 12/2026	 12/2025
---	--	---	--	--	--	---	--

—	03/15/2024	Repair	80850 km	04569 Niederlassung Chemnitz BMW AG, Chemnitz	Job Job Job Job Job Job
---	------------	--------	----------	---	--

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Service Standard Fahrzeugpflege Part I IF00200	Local	1
---	-------	---

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words: keine Füllstände ergänzen,

Standard scope of service Flat rate unit I 00 00 105	2 FRU
---	-------

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Engine oil service Flat rate unit I 00 00 610	3 FRU
--	-------

BMW Engine Oil LL04 0W30 Part I 83 21 2 405 950	7
--	---

Set oil-filter element Part I 11 42 7 826 799	1
--	---

Battery Part I 66 12 6 912 985	1
-----------------------------------	---

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Service - microfilter Flat rate unit I 00 00 616	2 FRU
---	-------

Microfilter/activated Carbon container Part I 64 11 9 382 886	1
--	---

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Alle Räder ab- und anbauen(Radsatz Flat rate unit I NL36 00 1	Local	7 FRU
Radsatz Stationär wuchten - Aktionspreis Flat rate unit I NL36 00 6	Local	12 FRU
Räderlagerung extern (1 Saison) Part I NL36100	Local	1

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Motorölservice - zusätzliche AW Flat rate unit I IM00 25 0	Local	2 FRU
---	-------	-------

— 03/12/2024 Key 79903 km 04569 Key 10

 700 12/2024		 700 12/2024			 12/2025	 12/2025		 28000 12/2026	 12/2025	
---	---	---	---	---	--	--	--	---	--	---

— 12/14/2023 Key 69943 km 21584 Key 10

 10000 12/2024		 10000 12/2024			 12/2025	 12/2025	 36000 12/2026	
---	---	---	---	---	--	--	--	---

— 12/14/2023 Repair 69943 km 45556 Helming & Sohn GmbH , Wietmarschen Job Job Job Job Job

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Auslieferungsdurchsicht Fzg ohne BPS Flat rate unit I 80 00 001	Local	4 FRU
--	-------	-------

Insulated mug 1

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Batterie laden	Local	2 FRU
Flat rate unit I 80 00 400		

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Rädertausch Basic WR aus MEP (FJ80930) SR ins Fzg	Local	6 FRU
Flat rate unit I 00 99 001		

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

(statutory) general inspection		1 FRU
Flat rate unit I 00 12 159		

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Lackierungskosten CarColor Frontbereich, Stoßf. H 00000000	Local	1 FRU
Flat rate unit I 99 99 999		

NG Fremdleistung Wellmeyer Motorh. 00000000	Local	1 FRU
Flat rate unit I 99 99 999		

HU §29 StVZO incl. AU mit Endrohrmessung 00000000	Local	1 FRU
Flat rate unit I 99 99 999		

—	12/12/2023	Repair	69932 km	00893 Helming & Sohn GmbH , Lingen	Job Job Job Job Job
---	------------	--------	----------	---	---------------------------------

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Standard scope of service2 FRU

Flat rate unit I 00 00 105

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Brake fluid service4 FRU

Flat rate unit I 00 00 618

Brake fluid DOT4 LV, low viscosity1

Part I 83 13 2 184 843

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Hereinnahmecheck ohne BPSLocal4 FRU

Flat rate unit I 80 00 003

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Zwei Runflat-Reifen ersetzenLocal16 FRU

Flat rate unit I 36 12 995

Pirelli P-Zero r-f2

Part I 85 45 2 729 095

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Installing navigation map(s)2 FRU

Flat rate unit I 65 90 600


—12/08/2023Service69922 km00893Manual

Helming & Sohn GmbH, Lingen







11/22/2023 Key 69922 km 00893 Key 10



11/22/2023 Service 69922 km 00893 Automatic
Helming&Sohn GmbH , Lingen



08/09/2023 Key 66017 km Key 10



08/09/2023 Repair 66017 km 00893 Job
Helming & Sohn GmbH , Lingen Job Job

Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Additional work with KAFAS camera 5 FRU
Flat rate unit I 66 51 990

Replace windshield 29 FRU
Flat rate unit I 51 31 011

Scheibenklebstoff Local 1
Part I FT08 90 0 238 3

Replacemt.small plates, low beam sensor 1
Part I 61 35 9 856 157

Windshield, green, rain/light/fog 1
Part I 51 31 7 477 267

Bump stop 2
Part I 51 31 7 288 462

Cleaner R1 Part I 83 19 2 211 217	1
Drip molding, right Part I 51 31 7 427 874	1
Sound insulation windshield Part I 51 48 7 941 312	2
Water accessory element, left Part I 51 31 9 466 591	1
Water accessory element, right Part I 51 31 9 466 592	1
Cover, windshield, top Part I 51 31 7 427 861	1
Drip moulding, left Part I 51 31 7 427 873	1

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Werkstattwäsche kostenfrei Flat rate unit I 80 11 329	Local	1 FRU
--	-------	-------

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Serviceersatzwagen zum Vorzugspreis Flat rate unit I 99 99 999	Local	1 FRU
---	-------	-------

— 07/18/2023 Key 64849 km Key 10

 14000 12/2024		 14000 12/2024			 11/2023	 11/2023		 39000 12/2026	
---	---	---	---	---	--	--	--	---	---

— 06/20/2023 Key 63619 km Key 10

 16000 12/2024		 16000 12/2024		 -10 0 %	 11/2023	 11/2023		 41000 12/2026	
---	---	---	---	---	--	--	--	---	---

— 06/20/2023 Service 63619 km 00893
Helming&Sohn
GmbH , Lingen Automatic

									
16000		16000		-10	11/2023	11/2023			41000
12/2024		12/2024		✓					12/2026

— 06/20/2023 Repair 63619 km 00893 Helming & Sohn GmbH, Lingen Job Job

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Standard scope of service 2 FRU
Flat rate unit I 00 00 105

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Service - front brakes 7 FRU
Flat rate unit I 00 00 612

Brake pad wear sensor, front 1
Part I 34 35 6 870 349

Brake cleaner, acetone-free 1
Part I 83 19 2 413 695

Torx screw with washer 4
Part I 34 10 6 864 424

Repair kit, brake pads asbestos-free 1
Part I 34 11 6 889 570

Brake pad paste 2
Part I 83 19 2 158 851

— 05/30/2023 Key 63595 km Key 10

									
16000		16000		10	11/2023	11/2023		41000	
12/2024		12/2024						12/2026	

— 12/09/2022 Key 53233 km Key 10

									
-1600 5.9 %	-1600	-1600	-1600		11/2023	11/2023	3400	-1600 3 %	
09/2023	09/2023	09/2023	09/2023					09/2023	

—	12/09/2022	Service	53233 km	00893 Helming&Sohn GmbH , Lingen	Automatic
---	------------	---------	----------	--	-----------

								
-1600	-1600	-1600	-1600				3400	-1600
✓	✓	✓	✓				✓	

—	12/09/2022	Repair	53238 km	00893 Helming & Sohn GmbH , Lingen	Job Job Job Job Job Job Job
---	------------	--------	----------	---	---

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Standard scope of service Flat rate unit I 00 00 105	2 FRU
---	-------

Engine oil service Flat rate unit I 00 00 610	3 FRU
--	-------

MOTORÖL SAE 5W-30 Longlife 04 Part I 99 99 0 398 511	Local	7
---	-------	---

Battery Part I 66 12 6 912 985	1
-----------------------------------	---

Set oil-filter element Part I 11 42 7 826 799	1
--	---

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Fuel filter service Flat rate unit I 00 00 604	5 FRU
---	-------

Fuel filter cartridge Part I 13 32 8 591 019	1
---	---

Self-locking hex nut Part I 64 50 9 123 157	2
--	---

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Service - air filter insert Flat rate unit I 00 00 602	1 FRU
---	-------

Air filter element Part I 13 71 8 594 535	1
--	---

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Service - microfilter Flat rate unit I 00 00 616	2 FRU
---	-------

Microfilter/activated Carbon container Part I 64 11 9 382 886	1
--	---

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Vehicle check service Flat rate unit I 00 00 624	6 FRU
---	-------

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Rear brakes service Flat rate unit I 00 00 614	8 FRU
---	-------

Repair kit, brake pads asbestos-free Part I 34 20 6 888 835	1
--	---

Brake cleaner, acetone-free Part I 83 19 2 413 695	1
---	---

Brake pad wear sensor, rear Part I 34 35 6 870 354	1
---	---

Brake pad paste Part I 83 19 2 158 851	2
---	---

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Replacing all wiper blades Flat rate unit I 61 61 547	1 FRU
--	-------

Set of wiper blades Part I 61 61 9 478 361	1
---	---

Wiper blade	1
-------------	---

— Job

Description:**Is interpreted as a repeat visit:** No**Customer's own words:**

Werkstattwäsche kostenfrei	Local	1 FRU
Flat rate unit I 80 11 329		

—	12/09/2022	Repair	53238 km	00893 Helming & Sohn GmbH , Lingen	Job
---	------------	--------	----------	---	-----

— Job

Description:**Is interpreted as a repeat visit:** No**Customer's own words:**

Replace windshield	29 FRU
Flat rate unit I 51 31 011	

Additional work with KAFAS camera	5 FRU
Flat rate unit I 66 51 990	

Entsorgung	Local	1
Part I FT99 99 0 000 8		

Scheibenklebstoff	Local	1
Part I FT08 90 0 238 3		

FEINSTAUBPLAKETTE	Local	1
Part I FT8000222		

Windshield, green, rain/light/fog	1
Part I 51 31 7 477 267	

Cover, windshield, top	1
Part I 51 31 7 427 861	

Bump stop	2
Part I 51 31 7 288 462	

Cleaner R1	1
Part I 83 19 2 211 217	

Sound insulation windshield	2
Part I 51 48 7 941 312	

Water accessory element, left	1
Part I 51 31 9 466 591	

Water accessory element, right	1
Part I 51 31 9 466 592	

—	12/09/2022	Repair	53238 km	00893 Helming & Sohn GmbH , Lingen	Job
---	------------	--------	----------	---	-----

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Service standard W.O.L.F.E.

2 FRU

Flat rate unit I 00 99 400

Windshield Washer Antifreeze

2

Part I 83 12 2 413 059

— 11/25/2022 Key 51590 km 00893 Remote KeyRead

									
50	50	50	50				5000	50	
09/2023	09/2023	09/2023	09/2023		11/2023	11/2023		09/2023	

— 04/13/2022 Key 39370 km 02731 Key 10

									
12000	12000	12000	12000					12000	
09/2023	499	499	499		11/2023	559		09/2023	

— 04/08/2022 Key 38644 km 02731 Key 10

									
13000	13000	13000	13000					13000	
09/2023	503	503	503		11/2023	563		09/2023	

— 09/02/2021 Key 24709 km Key 10

									
-420		-420					26000		
11/2022		419			11/2023		1139		

— 09/02/2021 Service 24709 km 00893 Automatic
Helming&Sohn
GmbH , Lingen

							
-420		-420					26000
✓		✓					

— 09/02/2021 Repair 24715 km 00893 Job
Helming &
Sohn GmbH , Lingen Job
Job
Job

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Standard scope of service	2 FRU
Flat rate unit I 00 00 105	

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Engine oil service	3 FRU
Flat rate unit I 00 00 610	

MOTORÖL SAE 5W-30 Longlife 04	Local	7
Part I 99 99 0 398 511		

Set oil-filter element	1
Part I 11 42 8 583 898	

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Service - microfilter	2 FRU
Flat rate unit I 00 00 616	

Microfilter/activated Carbon container	1
Part I 64 11 9 382 886	

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Werkstattwäsche kostenfrei	Local	0 FRU
Flat rate unit I 80 11 329		

—	09/02/2021	Repair	24715 km	00893 Helming & Sohn GmbH , Lingen	Job
---	------------	--------	----------	---	-----

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Replacing windshield	28 FRU
Flat rate unit I 51 31 511	

Additional work with KAFAS camera	5 FRU
-----------------------------------	-------

Flat rate unit | 66 51 990

Scheibenklebstoff Part FT08 90 0 238 3	Local	1
Entsorgung Part FT99 99 0 000 8	Local	1
Windshield, green, rain/light/fog Part 51 31 7 477 267		1
Cover, windshield, top Part 51 31 7 427 861		1
Bump stop Part 51 31 7 288 462		2
Cleaner R1 Part 83 19 2 211 217		1
Sound insulation windshield Part 51 48 7 941 312		2
Water accessory element, left Part 51 31 9 466 591		1
Water accessory element, right Part 51 31 9 466 592		1

—	08/23/2021	Key	24098 km	Key 10	
 230 11/2022	 230 428	 230 428	   11/2023   27000 1148		
—	11/27/2020	Service	8 km	00893 Helming&Sohn GmbH, Lingen	Manual
					 0 11/2020 ✓
—	11/25/2020	Repair	0 km	00893 Helming & Sohn GmbH, Lingen	Job Job Job

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Free pre-delivery check
Flat rate unit | 00 00 009 9 FRU

Work time without specification/body equipment
Flat rate unit | 51 99 000 2 FRU

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Release code HU-H-3 map Europe initial
Part I 65 90 2 560 755

1

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Neuwagenreinigung
Flat rate unit I 80 11 333

Local

1 FRU