

Vehicle

BMW 520d, 140kW

WBA5L31010G486741



Development code	F11
Color	sophisto-grau brillant metallic
Actual integration level	F010-24-07-515
Start of warranty	November 11, 2016

▼ Technical Campaigns

There are no campaigns available.

▼ Special information

There are no campaigns available.

▼ Live Diagnosis

 There are no service solutions for Live Diagnosis.

▼ Service contracts

No BSI contracts available

You can find additional service contract information and selection options in the DCSNet warranty vehicle enquiry.

▼ Information on faults, workshop/Service Consultation

No information on faults is available.

▼ Navigation map

Installed map	Enabling code (subscription)	Latest navigation map included in subscription	Latest navigation map subject to charge
Road Map EUROPE Next 2016-2 (as of: Oct 24, 2024)	Release code valid for navigation maps with release date up to Dec 31, 2025 (SWID: 00A9008F).	Road Map EUROPE WEST Next 2025	-

▼ Vehicle details

Vehicle type	Passenger car
--------------	---------------

Brand	BMW
Model	520d
Body	TOUR
Vehicle identification number (last 7 characters)	G486741
Vehicle identification number (17 characters)	WBA5L31010G486741
Development code	F11
Steering	LL
Engine	B47O
Engine number	54549724
Exhaust re-treatment	EURO6;W;PI/CI; M, N1 I
Transmission	AUT
Transmission number	0543470WC6
Head unit serial number	HB2068G8250101
Drive	HECK
Integration level	F010-16-07-504
Production date	Aug 24, 2016
Production works	Dingolfing
Delivery date	Aug 26, 2016
Delivering Retailers	No information
National-market version	EUR
Paint code	A90
Upholstery code	LCOX
Model code	5L41
Base type	5L31
Lead type	5L41

▾ Optional equipment

Optional equipment fitted at the factory:

01CA Selection of COP relevant vehicles
 01CB CO2 package
 01CC Auto start/stop function
 01CD Brake Energy Regeneration
 0205 Automatic transmission
 0230 EU-specific additional contents
 0255 Sports leather steering wheel
 0258 Tire with run-flat functionality
 02AU BMW LA wheel Streamline 364
 02VB Tire pressure display
 0302 Alarm system

Retrofitted optional equipment:

This vehicle has no retrofits.

0316 automatic trunk lid mechanism
 0320 Deleted, model lettering
 0386 Roof railing
 0402 Electric panoramic roof
 0423 Floor mats, velours
 0428 Warning triangle and first aid kit
 0430 Interior/outside mirror with auto dip
 0431 Interior mirror with automatic-dip
 0456 Comfort seat with memory
 0488 Lumbar support, driver and passenger
 0494 Seat heating driver/passenger
 04BN Fine-wood trim ash grain
 04U2 Driving experience switch incl. ECO PRO
 04UR Ambient interior lighting
 0502 Headlight cleaning system
 0508 Park Distance Control (PDC)
 0524 Adaptive Headlights
 0534 Automatic air conditioning
 0548 Kilometer-calibrated speedometer
 0575 Supplementary 12V sockets
 05A1 LED Fog lights
 05AC High-beam assistant
 05AG Lane-change warning
 05AS Driving Assistant
 0609 Navigation system Professional
 0610 Head-up display
 0676 HiFi speaker system
 0698 Area-Code 2 for DVD
 06AC Intelligent emergency SOS call
 06AE Teleservices
 06AK Connected Drive Services
 06AM Real-Time Traffic Information
 06AN Concierge Services
 06AP Remote Services
 06NS Convenience phone, expanded Smartphone
 06WA Instrument cluster, expanded equipment
 07A2 Innovation Package II
 07S2 Luxury Line
 0801 German version
 0851 Language version German
 0879 On-board vehicle literature German
 08KA Oil service interval, 24 mos./30,000 km
 08R9 Refrigerant R1234yf
 08TF Active pedestrian protection
 08TH Road sign detection
 09AA Outer skin protection
 09BM Navigation package, Connected Drive
 A090 90 AH AGM battery
 LEDE Leather trim

▾ Vehicle histories

	Date	Type	Vehicle mileage	Dealer	Overview
—	03/05/2026	Key	198740 km	29843	Remote KeyRead
	 1000 01/2027  1000 01/2027  1000 01/2027  1000 01/2027  100000 11/2027  11/2027  11/2027  42000  1000 01/2027  11/2027  11/2027				
—	10/21/2024	Key	160551 km	29843	Key 0

 7000 01/2026		 7000 01/2026		 100000	 08/2025	 08/2025	 80000	 38000 01/2028	 11/2025	 11/2025
---	--	---	--	--	---	---	--	--	---	---

— 07/12/2024 Key 152448 km 29843 Key 0

 14000 01/2026		 14000 01/2026		 100000	 08/2025	 08/2025	 90000	 45000 01/2028	 11/2025	 11/2025
---	---	---	---	---	--	--	---	---	--	--

— 10/26/2023 Key 130729 km 29843 Key 0

 16000 03/2025	 16000 03/2025	 16000 03/2025	 16000 03/2025	 100000	 08/2025	 08/2025	 100000	 47000 03/2027	 11/2023	 11/2023
---	---	---	---	---	--	--	--	---	--	--

— 10/26/2023 Repair 130729 km 29843 Kohl-Automobile GmbH, Heinsberg Job Job

— Job

Description: Untergurt mit Gurtstrammer links

Is interpreted as a repeat visit: No

Customer's own words:

Removing and installing/replacing front lower strap on the driver's seat 8 FRU
Flat rate unit I 72 11 070

Lower belt with left belt tensioner 1
Part I 72 11 7 328 841

Fillister head screw 2
Part I 07 14 6 989 597

Fillister head screw 4
Part I 07 14 9 156 953

— Job

Description: (Kühlmittel nicht aufgefüllt) Check-Control- Meldung Kühlmittel auslesen

Is interpreted as a repeat visit: No

Customer's own words:

Read out coolant Check Control message (not OK) 1 FRU
Flat rate unit I 00 73 828

Checking exhaust gas recirculation cooler index (further repairs subsequently required - index not OK) 1 FRU
Flat rate unit I 00 73 830

Check exhaust gas recirculation cooler (cooler outlet and inlet side), fill coolant and carry out cooling system bleeding routine 15 FRU
Flat rate unit I 00 68 860

Additional work/checking engine cooling system for water tightness
Flat rate unit I 00 74 823

2 FRU

Gasket Steel
Part I 11 71 8 579 364

1

Oval head screw
Part I 35 21 7 685 343

2

—	08/25/2022	Key	100228 km	29843	Key 0								
													
16000	16000	16000	16000	5000			5000	47000					
01/2024	01/2024	01/2024	01/2024		11/2023	11/2023		01/2026			11/2023	11/2023	
—	08/09/2022	Key	98648 km	29843	Remote KeyRead								
													
17000	17000	17000	17000	5000			5000	48000					
01/2024	01/2024	01/2024	01/2024		11/2023	11/2023		01/2026			11/2023	11/2023	
—	01/21/2022	Key	84348 km		Key 0								
													
-1600		-1600		5000			5000	-1600					
10/2022		250			11/2023	640		10/2022			11/2023	11/2023	
—	01/21/2022	Service	84348 km	29843 Kohl- Automobile GmbH , Heinsberg	Automatic								
													
-1600		-1600		5000			5000	-1600					
09/2022		09/2022		10/2023			09/2022		10/2023	10/2023			
✓		✓					✓						
Comment: -													
—	01/21/2022	Repair	84348 km	29843 Kohl- Automobile GmbH , Heinsberg	Job Job Job								

— Job

Description: Service Motoröl

Is interpreted as a repeat visit: No

Customer's own words:

Engine oil service
Flat rate unit I 00 00 610

3 FRU

Service - microfilter
Flat rate unit I 00 00 616

3 FRU

Standard scope of service
Flat rate unit I 00 00 105

2 FRU

Castrol Edge 5W-30 Longlife 04
Part I FTT0530

Local

5

Set oil-filter element
Part I 11 42 8 575 211

1

Set, microfilter/activ. charcoal filter
Part I 64 11 9 272 642

1

— Job

Description: Service Fahrzeugcheck

Is interpreted as a repeat visit: No

Customer's own words:

Vehicle check service
Flat rate unit I 00 00 624

7 FRU

Adjusting headlights
Flat rate unit I 63 10 502

2 FRU

Adjusting front fog light
Flat rate unit I 63 10 515

1 FRU

Windshield Washer Antifreeze
Part I 83 12 2 413 061

1

— Job

Description: Fahrzeugwäsche

Is interpreted as a repeat visit: No

Customer's own words:

Maschinelle Oberwäsche ohne Berechnung
Flat rate unit I -






Local

2 FRU

— 12/01/2021 Key

80321 km






Key 0



— 11/26/2021 Key

80310 km

Key 0



— 11/19/2021 Key

79371 km

Remote KeyRead

 3400 10/2022		 3400 313		 5000	 11/2023	 703	 5000	 3400 10/2022	 11/2023	 11/2023
---	--	---	--	--	---	---	---	---	---	---

— 09/01/2021 Key 73646 km Remote KeyRead

 10000 10/2022		 10000 390		 5000	 10/2021	 9000	 10000 10/2022	 11/2021	 11/2021
---	---	---	---	---	--	---	--	--	--

— 09/17/2018 Service 29590 km OSS-60010942 Autohaus Moll GmbH & Co, Nürnberg Manual

 ✓		 ✓					 ✓		
--	---	--	---	---	---	---	---	---	---

Comment: -

— 06/20/2018 Key 26302 km 00089 Key 0

 3200 08/2018	 0	 3200 72	 0	 26000	 0 08/2019	 47000	 33000 08/2020	 0 09/2019	 0 09/2019
--	--	---	--	--	---	--	--	---	---

— 06/20/2018 Repair 26302 km 00089 Niederlassung Nürnberg BMW AG, Nürnberg Job Job Job

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words: TA durchführen, #Motor rucktgeth fast aus und nimmt kein Gas an. Check-engine leuchtet., Abgabe über Herr Goffin Fa. Euromaster!,

Performing test module, programming control units and replacing exhaust-gas recirculation valve 15 FRU
Flat rate unit I 00 64 942

EGR-valve 1
Part I 11 71 8 594 492

Gasket Steel 1
Part I 11 71 8 579 364

Oval head screw 2
Part I 35 21 7 685 343

Hose clamp 2

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Service consultation at the vehicle	0 FRU
Flat rate unit I 00 52 050	

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

kostenlose Fahrzeugoberwäsche	Local	1
Part I 0011319		

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Befund: Marderschaden nicht Reaprieren	Local	1
Part I 0011322		