

**Thank you for ordering from us!**  
[www.checkvin.eu](http://www.checkvin.eu)

#### Vehicle

**BMW 318D A, 110KW**

WBA8H71070K657818



Development code F31  
Colour mineral-grau metallic  
Actual integration level F020-18-03-532  
Start of warranty 24 September 2015

Delivery stop



Technical Campaigns are available.

#### Technical campaigns

| Status | Campaign number | Description                                                                                                                                                                                                | Reservation |
|--------|-----------------|------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|-------------|
| Open   | 10011130700     | Replacing the exhaust gas recirculation cooler (high temperature)<br> <b>Delivery stop</b><br>Local campaign number: SK |             |
| Open   | 10011350700     | Exhaust gas recirculation cooler customer notification<br>Local campaign number: SK                                                                                                                        |             |
| Open   | 10013500300     | Program control units (DDE)<br>Local campaign number: SK                                                                                                                                                   |             |
| Open   | 10032550300     | Check the driver's airbag, replace if necessary (conversion SDI)<br> <b>Delivery stop</b><br>Local campaign number: -   |             |

#### VIN-based goodwill

| Status | Campaign number | Description                                                      |
|--------|-----------------|------------------------------------------------------------------|
| Open   | 1SACC011056     | Exhaust gas recirculation cooler Bx7<br>Local campaign number: - |

#### Special information

There are no Campaigns for this vehicle.

Restrictions on the warranty

There are no restrictions on the warranty.

⚠ Market-specific restrictions are not currently displayed. Please check this in WDF/WXE via S-Gate.

Live Diagnosis

 There are no service solutions for Live Diagnosis.

Service contracts

No BSI contracts

Information on faults workshop/Service Consultation

There is no information on faults.

Navigation map

**Note:** The installed map cannot be clearly identified. Presumably one of the following maps is present in the vehicle.

| Installed map                                   | Enabling code (subscription)                                                                   | Latest navigation map included in subscription | Latest navigation map subject to charge |
|-------------------------------------------------|------------------------------------------------------------------------------------------------|------------------------------------------------|-----------------------------------------|
| Road Map EUROPE EVO 2015-4 (As of: 18 Dec 2020) | Enabling code valid for navigation maps with release date up to 30 Sept 2018 (SWID: 00F10038). | Road Map EUROPE EVO 2018-4                     | Road Map EUROPE EVO 2024-2              |
| Road Map EUROPE EVO 2015-4 (As of: 18 Dec 2020) | -                                                                                              | -                                              | -                                       |

Vehicle details

|                                               |                          |
|-----------------------------------------------|--------------------------|
| Vehicle type                                  | Passenger car            |
| Brand                                         | BMW                      |
| Model                                         | 318D A                   |
| Body                                          | TOUR                     |
| Vehicle identification number (last 7 digits) | K657818                  |
| Vehicle identification number (17 digits)     | WBA8H71070K657818        |
| Development code                              | F31                      |
| Steering                                      | LL                       |
| Engine                                        | B47U                     |
| Engine number                                 | 50369385                 |
| Exhaust re-treatment                          | EURO6, W, PI/CI, M, N1 I |
| Transmission                                  | AUT                      |
| Transmission number                           | 0133982ZEK               |
| Head unit serial number                       | HB2140F7663111           |

|                          |                     |
|--------------------------|---------------------|
| Drive                    | HECK                |
| Integration level, works | F020-15-07-506      |
| Production date          | 18 Sept 2015        |
| Production plant         | Muenchen            |
| Delivery date            | 25 Sept 2015        |
| Delivering retailer      | BMW AG, München, DE |
| National-market version  | EUR                 |
| Paint code               | B39                 |
| Upholstery code          | CCL1                |
| Model code               | 8H81                |
| Basic type               | 8H71                |
| Lead type                | 8H81                |

---

### Optional equipment

---

#### Optional equipment ex works:

01CA Selection of COP-relevant vehicles  
 01CB CO2 equipment  
 0205 Automatic transmission  
 0216 Hydro steering-servotronic  
 0230 Extra package, EU-speciifc  
 0255 Sports leather steering wheel  
 0258 Tyres with runflat properties  
 02L3 BMW LA wheel, V-spoke 395  
 02VB Tyre pressure display  
 0320 Deleted, model lettering  
 0322 Comfort access system  
 03AA Roof railing black  
 03DZ Omission of additional lettering, outer  
 0420 Sun protection glazing  
 0423 Floor mats velours  
 0428 Warning triangle and first aid kit  
 0431 Interior mirror with automatic-dip  
 0481 Sports seat  
 0488 Lumbar support, driver and passenger  
 0493 Storage compartment package  
 0494 Seat heating driver/passenger  
 04AE Armrest front, retractable  
 04LU black high-gloss accent chrm. Perlglanz  
 0508 Park Distance Control (PDC)  
 0521 Rain sensor  
 0534 Automatic air conditioning  
 0544 Cruise control with brake function  
 0548 Kilometre speedo  
 0552 Adaptive LED headlight  
 0563 Lights package  
 0575 Additional 12V sockets  
 05A1 LED Fog lights  
 05AC High-beam assistant  
 05AL Active Protection  
 05AS Driving Assistant  
 05DA Passenger airbag deactivation  
 05DC Rear-seat headrests, folding  
 0609 Navigation system Professional  
 0610 Head-up display  
 0698 Area-Code 2 for DVD  
 06AC Intelligent emergency call  
 06AE Teleservices  
 06AK Connected Drive Services  
 06AM Real-Time Traffic Information

#### Retrofitted optional equipment:

This vehicle has no retrofits.

06AN Concierge Services  
 06AP Remote Services  
 06NS Comfort telephony w/ enhanced Smartphone  
 06WA Instrument panel with extended scope  
 07AC Sport Line  
 07LD Modell Sport Line  
 07R7 Innovation package  
 07XP Navigation package Connected Drive  
 0801 German version  
 0851 Language version German  
 0879 On-board literature, German  
 08KA Oil service interval 24 mths / 30,000 km  
 08TH Road sign detection  
 09AA Outer skin protection  
 09BD Business Package  
 A090 90 Ah AGM battery  
 POLS Cloth cushion

## Vehicle histories

| Date       | Type     | Vehicle mileage | Retailer | Overview |
|------------|----------|-----------------|----------|----------|
| 22/12/2020 | Warranty | 188240 Km       | 00664    | Job      |

— Job







Description:

Considered as a repeat visit No

Customer's own words

Defect | 85 40 00 14 KB

|            |     |           |       |
|------------|-----|-----------|-------|
| 18/12/2020 | Key | 188238 Km | Key 0 |
|------------|-----|-----------|-------|



|            |        |           |               |     |
|------------|--------|-----------|---------------|-----|
| 18/12/2020 | Repair | 188238 Km | 00664         | Job |
|            |        |           | Niederlassung | Job |
|            |        |           | München       | Job |
|            |        |           | Filiale       | Job |
|            |        |           | Fröttmaning   | Job |
|            |        |           | BMW AG,       |     |
|            |        |           | München       |     |

— Job

Description:

Considered as a repeat visit No

Customer's own words

Füllstände prüfen und nicht ergänzen  
 Flat rate unit | AZ00 33 4

Local

1 FRU

— Job

Description:

Considered as a repeat visit No

Customer's own words

Fahrzeugüberprüfung im Rahmen der Annahme  
 Flat rate unit | 00 52 054

Local

1 FRU

Endkontrolle  
Flat rate unit | AZ00 45 0

Local

1 FRU

## — Job

## Description:

Considered as a repeat visit No

Customer's own words

kostenlose Fahrzeugoberwäsche  
Part I 0011319

Local

1

## — Job

## Description:

Considered as a repeat visit No

Customer's own words TA 0011890500 abarbeiten,

Vis. insp. of EGR cooler outlet and inlet (OK), check CC message for  
coolant level (OK) and note the prod. date of the installed exhaust gas  
recirc. cooler  
Flat rate unit | 00 70 024

14 FRU

Ersatzfahrzeug  
Part I 0000158

Local

1

Gasket Steel  
Part I 11 71 8 579 364

1

## — Job

## Description:

Considered as a repeat visit No

Customer's own words

— 18/12/2020 Warranty

188238 Km

00664

Job: F1x F2x F3x G0x G1x G3x  
B47O B47T B47U B47K Check  
and, if required, replace EGR cooler  
(recheck)

— Job: F1x F2x F3x G0x G1x G3x B47O B47T B47U B47K Check and, if required, replace EGR cooler (recheck)

Description: F1x F2x F3x G0x G1x G3x B47O B47T B47U B47K Check and, if required, replace EGR cooler (recheck)

Considered as a repeat visit No

Customer's own words

Vis. insp. of EGR cooler outlet and inlet (OK), check CC message for  
coolant level (OK) and note the prod. date of the installed exhaust gas  
recirc. cooler  
Flat rate unit | 00 70 024

14 FRU

F1x F2x F3x G0x G1x G3x B47O B47T B47U B47K Check and, if  
required, replace EGR cooler (recheck)  
Defect I 00 11 89 05 00

Gasket Steel  
Part I 11 71 8 579 364










1

— 02/09/2020 Key

181438 Km

00664

Key 0



— 02/09/2020 Service 181438 Km 00664 Automatic  
 Niederlassung  
 München  
 Filiale  
 Fröttmaning ,  
 München

|                                                                                   |                                                                                   |                                                                                   |                                                                                   |                                                                                   |                                                                                   |                                                                                   |                                                                                    |                                                                                     |
|-----------------------------------------------------------------------------------|-----------------------------------------------------------------------------------|-----------------------------------------------------------------------------------|-----------------------------------------------------------------------------------|-----------------------------------------------------------------------------------|-----------------------------------------------------------------------------------|-----------------------------------------------------------------------------------|------------------------------------------------------------------------------------|-------------------------------------------------------------------------------------|
|  |  |  |  |  |  |  |  |  |
| 2200                                                                              | 2200                                                                              | 2200                                                                              | 2200                                                                              | 50000                                                                             | 0                                                                                 | 600                                                                               | 2200                                                                               | 0                                                                                   |
| 07/2021                                                                           | 07/2021                                                                           | 07/2021                                                                           | 07/2021                                                                           |                                                                                   | 08/2020                                                                           |                                                                                   | 07/2021                                                                            | 08/2020                                                                             |
| ✓                                                                                 | ✓                                                                                 | ✓                                                                                 | ✓                                                                                 |                                                                                   | ✓                                                                                 | ✓                                                                                 | ✓                                                                                  | ✓                                                                                   |

— 02/09/2020 Repair 181438 Km 00664 Job  
 Niederlassung Job  
 München Job  
 Filiale Job  
 Fröttmaning Job  
 BMW AG, Job  
 München Job  
 Job  
 Job  
 Job  
 Job  
 Job  
 Job  
 Job

— Job

Description:

Considered as a repeat visit No

Customer's own words

---

Service - standard scope 2 FRU  
 Flat rate unit I 00 00 105

— Job

Description:

Considered as a repeat visit No

Customer's own words

---

Microfilter service 2 FRU  
 Flat rate unit I 00 00 616

---

Microfilter/activated Carbon container 1  
 Part I 64 11 9 237 555

— Job

Description:

Considered as a repeat visit No

Customer's own words BEFUND OHNE FREIGABE.;- Motorhaubendämmmatte beschädigt,- Abblendlicht links war zu tief -> eingestellt,- Verbandskasten haltbar bis 12/2020,- Riss im Reifen HR,- Zusatzpuffer der hinteren Stoßdämpfer beginnen zu reißen,- Luftdruck HA um 0.2bar zu wenig -> korrigiert,- Bremspedalgummi war nicht richtig montiert -> berichtigt,

---

Service, vehicle check 6 FRU  
 Flat rate unit I 00 00 624

— Job

Description:

Considered as a repeat visit No

**Customer's own words**

|                                                            |       |
|------------------------------------------------------------|-------|
| Service - air filter element<br>Flat rate unit I 00 00 602 | 2 FRU |
|------------------------------------------------------------|-------|

|                                              |   |
|----------------------------------------------|---|
| Air filter element<br>Part I 13 71 8 511 668 | 1 |
|----------------------------------------------|---|

## — Job

**Description:****Considered as a repeat visit** No**Customer's own words**

|                                               |       |   |
|-----------------------------------------------|-------|---|
| Überprüfung nach § 29 STVZO<br>Part I 0012159 | Local | 1 |
|-----------------------------------------------|-------|---|

## — Job

**Description:****Considered as a repeat visit** No**Customer's own words**

|                                                   |       |
|---------------------------------------------------|-------|
| Service fuel filter<br>Flat rate unit I 00 00 604 | 3 FRU |
|---------------------------------------------------|-------|

|                                                 |   |
|-------------------------------------------------|---|
| Fuel filter cartridge<br>Part I 13 32 8 572 522 | 1 |
|-------------------------------------------------|---|

## — Job

**Description:****Considered as a repeat visit** No**Customer's own words**

|                                                    |       |
|----------------------------------------------------|-------|
| Service, rear brakes<br>Flat rate unit I 00 00 614 | 7 FRU |
|----------------------------------------------------|-------|

|                                                                |   |
|----------------------------------------------------------------|---|
| Repair kit, brake pads asbestos-free<br>Part I 34 21 6 873 093 | 1 |
|----------------------------------------------------------------|---|

|                                                  |   |
|--------------------------------------------------|---|
| Brake-pad sensor, rear<br>Part I 34 35 6 792 292 | 1 |
|--------------------------------------------------|---|

|                                                      |   |
|------------------------------------------------------|---|
| Brake cleaner acetone-free<br>Part I 83 19 2 413 695 | 1 |
|------------------------------------------------------|---|

|                                           |   |
|-------------------------------------------|---|
| Brake-pad paste<br>Part I 83 19 2 158 851 | 2 |
|-------------------------------------------|---|

## — Job

**Description:****Considered as a repeat visit** No**Customer's own words**

|                                                   |       |
|---------------------------------------------------|-------|
| Brake fluid service<br>Flat rate unit I 00 00 618 | 4 FRU |
|---------------------------------------------------|-------|

|                                                              |   |
|--------------------------------------------------------------|---|
| Brake fluid DOT4 LV, low viscosity<br>Part I 83 13 0 443 030 | 1 |
|--------------------------------------------------------------|---|

## — Job

**Description:****Considered as a repeat visit** No**Customer's own words**

|                                                    |       |
|----------------------------------------------------|-------|
| Engine oil service<br>Flat rate unit I 00 00 610   | 3 FRU |
| Set oil-filter element<br>Part I 11 42 8 575 211   | 1     |
| BMW Engine Oil LL04 0W30<br>Part I 83 21 2 405 950 | 5     |

## — Job

## Description:

Considered as a repeat visit No

## Customer's own words

|                                                                                          |       |
|------------------------------------------------------------------------------------------|-------|
| Removing and installing or replacing both rear brake discs<br>Flat rate unit I 34 21 932 | 4 FRU |
| Brake disc, ventilated<br>Part I 34 21 6 864 900                                         | 2     |
| Inner hex bolt<br>Part I 34 21 1 161 806                                                 | 2     |
| Hex screw with collar<br>Part I 34 20 6 850 536                                          | 4     |
| Expanding nut<br>Part I 07 14 7 306 224                                                  | 2     |

## — Job

## Description:

Considered as a repeat visit No

## Customer's own words

|                                                               |       |       |
|---------------------------------------------------------------|-------|-------|
| Motorölservice - zusätzliche AW<br>Flat rate unit I IM00 25 0 | Local | 2 FRU |
|---------------------------------------------------------------|-------|-------|

## — Job

## Description:

Considered as a repeat visit No

## Customer's own words

|                                                                    |       |       |
|--------------------------------------------------------------------|-------|-------|
| Endkontrolle<br>Flat rate unit I AZ00 45 0                         | Local | 1 FRU |
| Füllstände prüfen und nicht ergänzen<br>Flat rate unit I AZ00 33 4 | Local | 1 FRU |

## — Job

## Description:

Considered as a repeat visit No

## Customer's own words

|                                                 |       |   |
|-------------------------------------------------|-------|---|
| kostenlose Fahrzeugoberwäsche<br>Part I 0011319 | Local | 1 |
|-------------------------------------------------|-------|---|

## — Job

## Description:

Considered as a repeat visit No

Customer's own words Preis 1250.- Euro, Tel 0160-4422110,

Service consultation at vehicle with Service Ticket  
Flat rate unit I 00 52 052

0 FRU

— 16/06/2020 Key 175570 Km 00050 Key 0

|                                                                                   |                                                                                   |                                                                                   |                                                                                   |                                                                                   |                                                                                   |                                                                                   |                                                                                    |                                                                                     |                                                                                     |
|-----------------------------------------------------------------------------------|-----------------------------------------------------------------------------------|-----------------------------------------------------------------------------------|-----------------------------------------------------------------------------------|-----------------------------------------------------------------------------------|-----------------------------------------------------------------------------------|-----------------------------------------------------------------------------------|------------------------------------------------------------------------------------|-------------------------------------------------------------------------------------|-------------------------------------------------------------------------------------|
|  |  |  |  |  |  |  |  |  |  |
| 8000                                                                              | 8000                                                                              | 8000                                                                              | 8000                                                                              | 60000                                                                             |                                                                                   | 10000                                                                             | 8000                                                                               |                                                                                     |                                                                                     |
| 07/2021                                                                           | 375                                                                               | 375                                                                               | 375                                                                               |                                                                                   | 08/2020                                                                           |                                                                                   | 07/2021                                                                            |                                                                                     | 08/2020                                                                             |

— 09/06/2020 Repair 175584 Km 30749  
Niederlassung Job  
München Job  
Karosserie- Job  
und Job  
Lackzentrum Job  
BMW AG, Job  
Garching Job  
Job  
Job

— Job

Description:

Considered as a repeat visit No

Customer's own words

— Job

Description:

Considered as a repeat visit No

Customer's own words

— Job

Description:

Considered as a repeat visit No

Customer's own words

— Job

Description:

Considered as a repeat visit No

Customer's own words Kostenlose Zusatzarbeit -Kennzeichen vorne instandsetzen,Kühlluftführungen für Kühlmittelkühler ersetzen,

|                                                                          |       |        |
|--------------------------------------------------------------------------|-------|--------|
| Kostenlose Zusatzarbeit -Kennzeichen vor<br>Flat rate unit I AZ00 10 0   | Local | 1 FRU  |
| Kühlluftführungen für Kühlmittelkühler e<br>Flat rate unit I AZ51 99 0   | Local | 19 FRU |
| Replacing front bumper panel<br>Flat rate unit I 51 11 157               |       | 22 FRU |
| Additional work with Park Distance Control<br>Flat rate unit I 66 20 614 |       | 5 FRU  |
| Performing vehicle test<br>Flat rate unit I 00 00 556                    |       | 2 FRU  |

— Job

Description:

Considered as a repeat visit No

Customer's own words

|                             |        |
|-----------------------------|--------|
| Painting front bumper panel | 31 FRU |
| Flat rate unit I 99 68 019  |        |

— Job

Description:

Considered as a repeat visit No

Customer's own words

|                                      |       |       |
|--------------------------------------|-------|-------|
| Endkontrolle                         | Local | 1 FRU |
| Flat rate unit I AZ00 45 0           |       |       |
| Füllstände prüfen und nicht ergänzen | Local | 1 FRU |
| Flat rate unit I AZ00 33 4           |       |       |

— Job

Description:

Considered as a repeat visit No

Customer's own words

|                                   |       |   |
|-----------------------------------|-------|---|
| Schadenbedingte Reparatureinigung | Local | 1 |
| Part I 11321                      |       |   |
| Kostenlose Fahrzeugdesinfektion   | Local | 1 |
| Part I 0011311                    |       |   |

— Job

Description:

Considered as a repeat visit No

Customer's own words

|                                                                      |       |
|----------------------------------------------------------------------|-------|
| Service consultation with customer at vehicle without service ticket | 0 FRU |
| Flat rate unit I 00 52 053                                           |       |

— Job

Description:

Considered as a repeat visit No

Customer's own words

|                                          |   |
|------------------------------------------|---|
| Mounting, side panel, front bottom left  | 1 |
| Part I 51 11 7 279 711                   |   |
| Mounting, side panel, front bottom right | 1 |
| Part I 51 11 7 279 712                   |   |
| Insert, air inlet, middle                | 1 |
| Part I 51 11 7 386 152                   |   |
| Support, fog lamp left                   | 1 |
| Part I 51 11 7 386 361                   |   |
| Support, fog lamp right                  | 1 |
| Part I 51 11 7 386 362                   |   |
| Finisher, rod, left                      | 1 |
| Part I 51 11 7 396 835                   |   |
| Finisher, rod, right                     | 1 |
| Part I 51 11 7 396 836                   |   |

|                                                                    |   |
|--------------------------------------------------------------------|---|
| Closed grid, left<br>Part I 51 11 7 396 885                        | 1 |
| Closed grid, right<br>Part I 51 11 7 396 886                       | 1 |
| Set, mounting, PDC/PMA sensor, front<br>Part I 51 11 7 445 076     | 1 |
| Panel, bumper, primed, front<br>Part I 51 11 7 445 135             | 1 |
| Air duct front bottom<br>Part I 51 74 7 401 233                    | 1 |
| Plaque<br>Part I 51 76 7 288 752                                   | 1 |
| Adhesive set K6<br>Part I 83 19 2 317 925                          | 1 |
| Finisher, rod, centre<br>Part I 51 11 7 396 831                    | 1 |
| Air inlet finisher, left<br>Part I 51 11 7 396 853                 | 1 |
| Air inlet finisher, right<br>Part I 51 11 7 396 854                | 1 |
| Covering cap<br>Part I 51 18 1 813 017                             | 2 |
| Covering cap<br>Part I 51 18 7 060 798                             | 2 |
| Phillips head screw for plastic material<br>Part I 07 14 6 959 892 | 4 |
| Washer<br>Part I 07 11 9 904 208                                   | 4 |

## — Job

## Description:

Considered as a repeat visit No

## Customer's own words

|                        |       |     |
|------------------------|-------|-----|
| Lackmaterial           | Local | 114 |
| Part I 99 99 9 999 990 |       |     |

## — 04/12/2019 Key

164549 Km

00050

Key 1

|                                                                                     |                                                                                     |                                                                                     |                                                                                     |                                                                                     |                                                                                     |                                                                                     |                                                                                      |                                                                                       |                                                                                       |
|-------------------------------------------------------------------------------------|-------------------------------------------------------------------------------------|-------------------------------------------------------------------------------------|-------------------------------------------------------------------------------------|-------------------------------------------------------------------------------------|-------------------------------------------------------------------------------------|-------------------------------------------------------------------------------------|--------------------------------------------------------------------------------------|---------------------------------------------------------------------------------------|---------------------------------------------------------------------------------------|
|  |  |  |  |  |  |  |  |  |  |
| 20000                                                                               | 20000                                                                               | 20000                                                                               | 20000                                                                               | -1200                                                                               | 0                                                                                   | 22000                                                                               | 20000                                                                                |                                                                                       | 0                                                                                     |
| 07/2021                                                                             | 605                                                                                 | 605                                                                                 | 605                                                                                 | 08/2020                                                                             |                                                                                     | 07/2021                                                                             |                                                                                      |                                                                                       | 08/2020                                                                               |

## — 04/12/2019 Service

164549 Km

00050

Automatic

Niederlassung  
München MINI  
München ,  
München

|                                                                                     |                                                                                     |                                                                                     |                                                                                     |                                                                                     |                                                                                     |                                                                                     |                                                                                      |                                                                                       |                                                                                       |
|-------------------------------------------------------------------------------------|-------------------------------------------------------------------------------------|-------------------------------------------------------------------------------------|-------------------------------------------------------------------------------------|-------------------------------------------------------------------------------------|-------------------------------------------------------------------------------------|-------------------------------------------------------------------------------------|--------------------------------------------------------------------------------------|---------------------------------------------------------------------------------------|---------------------------------------------------------------------------------------|
|  |  |  |  |  |  |  |  |  |  |
| 20000                                                                               | 20000                                                                               | 20000                                                                               | 20000                                                                               | -1200                                                                               | 0                                                                                   | 22000                                                                               | 20000                                                                                |                                                                                       | 0                                                                                     |
| 07/2021                                                                             | 07/2021                                                                             | 07/2021                                                                             | 07/2021                                                                             | ✓                                                                                   | 08/2020                                                                             | 07/2021                                                                             |                                                                                      |                                                                                       | 08/2020                                                                               |

|   |            |        |           |               |     |
|---|------------|--------|-----------|---------------|-----|
| — | 04/12/2019 | Repair | 164549 Km | 00050         | Job |
|   |            |        |           | Niederlassung | Job |
|   |            |        |           | München MINI  | Job |
|   |            |        |           | München       | Job |
|   |            |        |           | BMW AG,       | Job |
|   |            |        |           | München       | Job |

## — Job

## Description:

Considered as a repeat visit No

## Customer's own words

|                                                                                            |       |
|--------------------------------------------------------------------------------------------|-------|
| Check exhaust-gas recirculation cooler production date (then no further repairs necessary) | 3 FRU |
| Flat rate unit I 00 68 736                                                                 |       |

## — Job

## Description:

Considered as a repeat visit No

## Customer's own words

|                            |       |
|----------------------------|-------|
| Service - standard scope   | 2 FRU |
| Flat rate unit I 00 00 105 |       |

## — Job

## Description:

Considered as a repeat visit No

**Customer's own words** bei Untermaß Bremsscheiben RS SB,telefonische Freigabe Auftragserweiterung am: 4.12.2019,Uhrzeit: 8:53,Grund: Bremsscheiben vorne,Kosten: ca. 500-,durch Name: Fr. Schuhlade,,Beide Bremsscheiben vorn ersetzen,

|                            |       |
|----------------------------|-------|
| Service, front brakes      | 6 FRU |
| Flat rate unit I 00 00 612 |       |

|                                                             |       |
|-------------------------------------------------------------|-------|
| Removing and installing or replacing both front brake discs | 3 FRU |
| Flat rate unit I 34 11 613                                  |       |

|                                      |   |
|--------------------------------------|---|
| Repair kit, brake pads asbestos-free | 1 |
| Part I 34 11 6 874 331               |   |

|                                   |   |
|-----------------------------------|---|
| Brake pad wear sensor, front left | 1 |
| Part I 34 35 6 792 289            |   |

|                        |   |
|------------------------|---|
| Brake disc, ventilated | 2 |
| Part I 34 11 6 792 217 |   |

|                        |   |
|------------------------|---|
| Inner hex bolt         | 2 |
| Part I 34 21 1 161 806 |   |

|                        |   |
|------------------------|---|
| Torx screw with washer | 4 |
| Part I 34 10 6 864 424 |   |

|                        |   |
|------------------------|---|
| Clip                   | 2 |
| Part I 34 11 6 850 645 |   |

## — Job

## Description:

Considered as a repeat visit No

## Customer's own words

|                                      |       |       |
|--------------------------------------|-------|-------|
| Füllstände prüfen und nicht ergänzen | Local | 1 FRU |
| Flat rate unit I AZ00 33 4           |       |       |

|                                            |       |       |
|--------------------------------------------|-------|-------|
| Endkontrolle<br>Flat rate unit I AZ00 45 0 | Local | 1 FRU |
|--------------------------------------------|-------|-------|

|                                                                                   |  |       |
|-----------------------------------------------------------------------------------|--|-------|
| Service consultation at vehicle with Service Ticket<br>Flat rate unit I 00 52 052 |  | 1 FRU |
|-----------------------------------------------------------------------------------|--|-------|

## — Job

## Description:

Considered as a repeat visit No

Customer's own words

|                                   |       |   |
|-----------------------------------|-------|---|
| Service-Reinigung<br>Part I 11320 | Local | 1 |
|-----------------------------------|-------|---|

## — Job

## Description:

Considered as a repeat visit No

Customer's own words

|                   |           |                                                                                               |     |
|-------------------|-----------|-----------------------------------------------------------------------------------------------|-----|
| 04/12/2019 Repair | 164550 Km | 30749<br>Niederlassung<br>München<br>Karosserie-<br>und<br>Lackzentrum<br>BMW AG,<br>Garching | Job |
|-------------------|-----------|-----------------------------------------------------------------------------------------------|-----|

## — Job

## Description:

Considered as a repeat visit No

Customer's own words Dieser Kostenvoranschlag ist 4 Wochen gültig. Verdeckte Schäden konnten,nicht berücksichtigt werden.,

|                                                                                                    |  |       |
|----------------------------------------------------------------------------------------------------|--|-------|
| Service consultation with customer at vehicle without service ticket<br>Flat rate unit I 00 52 053 |  | 0 FRU |
|----------------------------------------------------------------------------------------------------|--|-------|

|                                                                   |       |   |
|-------------------------------------------------------------------|-------|---|
| KV f. Unfall erstellen (ab 1000,- Euro)<br>Part I 99 99 0 012 210 | Local | 1 |
|-------------------------------------------------------------------|-------|---|

|                     |           |       |                                                                                                           |
|---------------------|-----------|-------|-----------------------------------------------------------------------------------------------------------|
| 04/12/2019 Warranty | 164549 Km | 00050 | Job: F1x F2x F3x F4x G0x G1x G3x<br>B47 Check and if required replace<br>exhaust-gas recirculation cooler |
|---------------------|-----------|-------|-----------------------------------------------------------------------------------------------------------|

## — Job: F1x F2x F3x F4x G0x G1x G3x B47 Check and if required replace exhaust-gas recirculation cooler

Description: F1x F2x F3x F4x G0x G1x G3x B47 Check and if required replace exhaust-gas recirculation cooler

Considered as a repeat visit No

Customer's own words

|                                                                                                                             |  |       |
|-----------------------------------------------------------------------------------------------------------------------------|--|-------|
| Check exhaust-gas recirculation cooler production date (then no further<br>repairs necessary)<br>Flat rate unit I 00 68 736 |  | 3 FRU |
|-----------------------------------------------------------------------------------------------------------------------------|--|-------|

F1x F2x F3x F4x G0x G1x G3x B47 Check and if required replace  
exhaust-gas recirculation cooler  
Defect I 00 11 40 05 00

|                |           |       |       |
|----------------|-----------|-------|-------|
| 10/07/2019 Key | 152665 Km | 00050 | Key 1 |
|----------------|-----------|-------|-------|

|                                                                                                     |                                                                                       |                                                                                                 |                                                                                       |                                                                                          |                                                                                                  |                                                                                           |                                                                                                       |                                                                                                    |
|-----------------------------------------------------------------------------------------------------|---------------------------------------------------------------------------------------|-------------------------------------------------------------------------------------------------|---------------------------------------------------------------------------------------|------------------------------------------------------------------------------------------|--------------------------------------------------------------------------------------------------|-------------------------------------------------------------------------------------------|-------------------------------------------------------------------------------------------------------|----------------------------------------------------------------------------------------------------|
| <br>-700<br>08/2020 | <br>0 | <br>-700<br>418 | <br>0 | <br>9000 | <br>0<br>08/2020 | <br>36000 | <br>30000<br>08/2022 | <br>0<br>08/2020 |
|-----------------------------------------------------------------------------------------------------|---------------------------------------------------------------------------------------|-------------------------------------------------------------------------------------------------|---------------------------------------------------------------------------------------|------------------------------------------------------------------------------------------|--------------------------------------------------------------------------------------------------|-------------------------------------------------------------------------------------------|-------------------------------------------------------------------------------------------------------|----------------------------------------------------------------------------------------------------|

— 10/07/2019 Service

152665 Km

00050  
Niederlassung  
München MINI  
München ,  
München

Automatic

|                                                                                                           |                                                                                        |                                                                                                           |                                                                                        |                                                                                           |                                                                                                   |                                                                                            |                                                                                                        |                                                                                                     |
|-----------------------------------------------------------------------------------------------------------|----------------------------------------------------------------------------------------|-----------------------------------------------------------------------------------------------------------|----------------------------------------------------------------------------------------|-------------------------------------------------------------------------------------------|---------------------------------------------------------------------------------------------------|--------------------------------------------------------------------------------------------|--------------------------------------------------------------------------------------------------------|-----------------------------------------------------------------------------------------------------|
| <br>-700<br>08/2020<br>✓ | <br>0 | <br>-700<br>08/2020<br>✓ | <br>0 | <br>9000 | <br>0<br>08/2020 | <br>36000 | <br>30000<br>08/2022 | <br>0<br>08/2020 |
|-----------------------------------------------------------------------------------------------------------|----------------------------------------------------------------------------------------|-----------------------------------------------------------------------------------------------------------|----------------------------------------------------------------------------------------|-------------------------------------------------------------------------------------------|---------------------------------------------------------------------------------------------------|--------------------------------------------------------------------------------------------|--------------------------------------------------------------------------------------------------------|-----------------------------------------------------------------------------------------------------|

— 10/07/2019 Repair

152666 Km

00050  
Niederlassung  
München MINI  
München  
BMW AG,  
München  
Job  
Job  
Job  
Job  
Job  
Job  
Job  
Job  
Job

— Job

Description:

Considered as a repeat visit No

Customer's own words

|                                                        |       |
|--------------------------------------------------------|-------|
| Service - standard scope<br>Flat rate unit I 00 00 105 | 2 FRU |
|--------------------------------------------------------|-------|

— Job

Description:

Considered as a repeat visit No

Customer's own words

|                                                  |       |
|--------------------------------------------------|-------|
| Engine oil service<br>Flat rate unit I 00 00 610 | 3 FRU |
|--------------------------------------------------|-------|

|                                                  |   |
|--------------------------------------------------|---|
| Set oil-filter element<br>Part I 11 42 8 575 211 | 1 |
|--------------------------------------------------|---|

|                                                    |   |
|----------------------------------------------------|---|
| BMW Engine Oil LL04 0W30<br>Part I 83 21 2 405 950 | 5 |
|----------------------------------------------------|---|

— Job

Description:

Considered as a repeat visit No

Customer's own words

|                                                               |       |       |
|---------------------------------------------------------------|-------|-------|
| Motorölservice - zusätzliche AW<br>Flat rate unit I IM00 25 0 | Local | 2 FRU |
|---------------------------------------------------------------|-------|-------|

— Job

Description:

Considered as a repeat visit No

**Customer's own words**

|                            |       |
|----------------------------|-------|
| Microfilter service        | 2 FRU |
| Flat rate unit I 00 00 616 |       |

|                                        |   |
|----------------------------------------|---|
| Microfilter/activated Carbon container | 1 |
| Part I 64 11 9 237 555                 |   |

## — Job

**Description:****Considered as a repeat visit** No**Customer's own words** Frontscheibe ersetzen (Steinschlag),Extra Rechnung für Frontscheibe mitr WA Rabatt!,,

|                            |        |
|----------------------------|--------|
| Replacing windshield       | 24 FRU |
| Flat rate unit I 51 31 011 |        |

|                            |       |
|----------------------------|-------|
| Calibrate KAFAS camera     | 4 FRU |
| Flat rate unit I 66 51 525 |       |

|                        |   |
|------------------------|---|
| Cover, windshield, top | 1 |
| Part I 51 31 7 258 053 |   |

|                                      |   |
|--------------------------------------|---|
| Windscreen, green, rain sensor / HUD | 1 |
| Part I 51 31 7 258 072               |   |

|                        |   |
|------------------------|---|
| Drip moulding, left    | 1 |
| Part I 51 31 7 258 187 |   |

|                        |   |
|------------------------|---|
| Drip moulding, right   | 1 |
| Part I 51 31 7 258 188 |   |

|                        |    |
|------------------------|----|
| Bump stop              | 11 |
| Part I 51 31 7 288 462 |    |

|                        |   |
|------------------------|---|
| Clamp                  | 2 |
| Part I 51 43 7 321 215 |   |

|                          |   |
|--------------------------|---|
| Sound insulation f apron | 1 |
| Part I 51 48 7 325 890   |   |

|                                        |   |
|----------------------------------------|---|
| Repair kit, window glass, cold, 1 hour | 1 |
| Part I 83 19 2 289 285                 |   |

## — Job

**Description:****Considered as a repeat visit** No**Customer's own words**

|                                              |       |
|----------------------------------------------|-------|
| Check exhaust gas recirculation cooler index | 3 FRU |
| Flat rate unit I 00 67 702                   |       |

## — Job

**Description:****Considered as a repeat visit** No**Customer's own words**

|                            |       |       |
|----------------------------|-------|-------|
| Endkontrolle               | Local | 1 FRU |
| Flat rate unit I AZ00 45 0 |       |       |

|                                                     |       |
|-----------------------------------------------------|-------|
| Service consultation at vehicle with Service Ticket | 1 FRU |
| Flat rate unit I 00 52 052                          |       |

## — Job

**Description:****Considered as a repeat visit** No

Customer's own words

Service-Reinigung  
Part I 11320

Local

1

— Job

Description:

Considered as a repeat visit No

Customer's own words

Füllstände prüfen und nicht ergänzen  
Flat rate unit I AZ00 33 4

Local

1 FRU

— Job

Description:

Considered as a repeat visit No

Customer's own words

— 10/07/2019 Warranty 152666 Km 00050 Job: F10 F11 F25 F26 F31 F34 F36 B47O Replacing exhaust-gas recirculation cooler

— Job: F10 F11 F25 F26 F31 F34 F36 B47O Replacing exhaust-gas recirculation cooler

Description: F10 F11 F25 F26 F31 F34 F36 B47O Replacing exhaust-gas recirculation cooler

Considered as a repeat visit No


Customer's own words

Check exhaust gas recirculation cooler index  
Flat rate unit I 00 67 702

3 FRU


F10 F11 F25 F26 F31 F34 F36 B47O Replacing exhaust-gas recirculation cooler  
Defect I 00 11 83 04 00

— 23/08/2018 Key 121237 Km Key 0



— 23/08/2018 Service 121237 Km 00664 Automatic

Niederlassung  
München  
Filiale  
Fröttmaning,  
München



— 23/08/2018 Repair 121237 Km 00664 Job  
Niederlassung Job  
München Job  
Filiale Job  
Fröttmaning Job  
BMW AG, Job  
München Job  
Job

Job  
Job  
Job  
Job  
Job  
Job  
Job

## — Job

**Description:****Considered as a repeat visit** No**Customer's own words**

|                            |       |
|----------------------------|-------|
| Engine oil service         | 3 FRU |
| Flat rate unit I 00 00 610 |       |

|                        |   |
|------------------------|---|
| Set oil-filter element | 1 |
| Part I 11 42 8 575 211 |   |

|                          |   |
|--------------------------|---|
| BMW Engine Oil LL04 0W30 | 5 |
| Part I 83 21 2 405 950   |   |

## — Job

**Description:****Considered as a repeat visit** No**Customer's own words**

|                            |       |
|----------------------------|-------|
| Service - standard scope   | 2 FRU |
| Flat rate unit I 00 00 105 |       |

## — Job

**Description:****Considered as a repeat visit** No**Customer's own words**

|                              |       |
|------------------------------|-------|
| Service - air filter element | 2 FRU |
| Flat rate unit I 00 00 602   |       |

|                        |   |
|------------------------|---|
| Air filter element     | 1 |
| Part I 13 71 8 511 668 |   |

## — Job

**Description:****Considered as a repeat visit** No**Customer's own words**

|                            |       |
|----------------------------|-------|
| Service fuel filter        | 3 FRU |
| Flat rate unit I 00 00 604 |       |

|                        |   |
|------------------------|---|
| Fuel filter cartridge  | 1 |
| Part I 13 32 8 572 522 |   |

## — Job

**Description:****Considered as a repeat visit** No**Customer's own words**

|                            |       |
|----------------------------|-------|
| Microfilter service        | 2 FRU |
| Flat rate unit I 00 00 616 |       |

|                                        |   |
|----------------------------------------|---|
| Microfilter/activated Carbon container | 1 |
|----------------------------------------|---|

Part I 64 11 9 237 555

## — Job

## Description:

Considered as a repeat visit No

## Customer's own words

|                                                   |       |
|---------------------------------------------------|-------|
| Brake fluid service<br>Flat rate unit I 00 00 618 | 4 FRU |
|---------------------------------------------------|-------|

|                                                              |   |
|--------------------------------------------------------------|---|
| Brake fluid DOT4 LV, low viscosity<br>Part I 83 13 0 443 030 | 1 |
|--------------------------------------------------------------|---|

## — Job

## Description:

Considered as a repeat visit No

## Customer's own words

|                                                       |       |       |
|-------------------------------------------------------|-------|-------|
| Scheinwerfer einstellen<br>Flat rate unit I AZ00 10 0 | Local | 3 FRU |
|-------------------------------------------------------|-------|-------|

|                                                      |       |
|------------------------------------------------------|-------|
| Service, vehicle check<br>Flat rate unit I 00 00 624 | 6 FRU |
|------------------------------------------------------|-------|

## — Job

## Description:

Considered as a repeat visit No

## Customer's own words

|                                                    |       |
|----------------------------------------------------|-------|
| Service, rear brakes<br>Flat rate unit I 00 00 614 | 7 FRU |
|----------------------------------------------------|-------|

|                                                                |   |
|----------------------------------------------------------------|---|
| Repair kit, brake pads asbestos-free<br>Part I 34 21 6 873 093 | 1 |
|----------------------------------------------------------------|---|

|                                                  |   |
|--------------------------------------------------|---|
| Brake-pad sensor, rear<br>Part I 34 35 6 792 292 | 1 |
|--------------------------------------------------|---|

|                                           |   |
|-------------------------------------------|---|
| Brake-pad paste<br>Part I 83 19 2 158 851 | 2 |
|-------------------------------------------|---|

## — Job

## Description:

Considered as a repeat visit No

## Customer's own words

|                                                                                          |       |
|------------------------------------------------------------------------------------------|-------|
| Removing and installing or replacing both rear brake discs<br>Flat rate unit I 34 21 932 | 4 FRU |
|------------------------------------------------------------------------------------------|-------|

|                                                  |   |
|--------------------------------------------------|---|
| Brake disc, ventilated<br>Part I 34 21 6 864 900 | 2 |
|--------------------------------------------------|---|

|                                          |   |
|------------------------------------------|---|
| Inner hex bolt<br>Part I 34 21 1 161 806 | 2 |
|------------------------------------------|---|

|                                                 |   |
|-------------------------------------------------|---|
| Hex screw with collar<br>Part I 34 20 6 850 536 | 4 |
|-------------------------------------------------|---|

## — Job

## Description:

Considered as a repeat visit No

Customer's own words

Motorölservice - zusätzliche AW  
Flat rate unit I IM00 25 0

Local

2 FRU

— Job

Description:

Considered as a repeat visit No

Customer's own words

Überprüfung nach § 29 STVZO  
Part I 0012159

Local

1

— Job

Description:

Considered as a repeat visit No

Customer's own words

Endkontrolle  
Flat rate unit I AZ00 45 0

Local

1 FRU

Füllstände prüfen und ergänzen NEIN  
Flat rate unit I AZ00 33 3

Local

1 FRU

— Job

Description:

Considered as a repeat visit No

Customer's own words

kostenlose Fahrzeugoberwäsche  
Part I 0011319

Local

1

— Job

Description:

Considered as a repeat visit No

Customer's own words Preis 1100.- EuroTel 0175-5944091,Info Kratzer Stoßstange vorn  
rechtsMotorhaubendämmatte Marder,

Service consultation at vehicle with Service Ticket  
Flat rate unit I 00 52 052

0 FRU

— Job

Description:

Considered as a repeat visit No










Customer's own words

— 11/06/2018 Key

116003 Km

00664

Key 0



— 11/06/2018 Repair

116003 Km

00664

Job

Niederlassung

Job

München

Job

Filiale

Job

Fröttmaning

Job

Job

## — Job

## Description:

Considered as a repeat visit No

**Customer's own words** Befund:,- Kühlsystem abgedrückt,- keine Druckverlust erkennbar,- Fehlerspeicher ausgelesen,- keine relevanten Fehler gespeichert,- nach passender PUMA Maßnahme gesucht,- passende PUMA Maßnahme 5213420  
0 gefunden,- PUMA Maßnahme abgearbeitet und NED zum Kühlmittelstand abgearbeitet,- laut NED ist der AGR- Kühler zu ersetzen,DIAGCODE D 1170D0000000\_32\_002,,

|                                                                   |       |
|-------------------------------------------------------------------|-------|
| Check the cooling system for watertightness with the special tool | 4 FRU |
| Flat rate unit I 17 00 009                                        |       |

|                            |       |
|----------------------------|-------|
| Performing vehicle test    | 2 FRU |
| Flat rate unit I 00 00 556 |       |

## — Job

## Description:

Considered as a repeat visit No

## Customer's own words

|                            |       |       |
|----------------------------|-------|-------|
| Reparaturwäsche            | Local | 4 FRU |
| Flat rate unit I AZ00 32 0 |       |       |

|                                                 |        |
|-------------------------------------------------|--------|
| Removing and installing or replacing EGR cooler | 23 FRU |
| Flat rate unit I 11 71 600                      |        |

|                        |   |
|------------------------|---|
| Torx bolt              | 2 |
| Part I 11 71 2 249 909 |   |

|                        |   |
|------------------------|---|
| Torx-bolt with washer  | 3 |
| Part I 07 12 9 905 423 |   |

|                        |   |
|------------------------|---|
| Anti-freeze            | 4 |
| Part I 83 19 2 211 358 |   |

## — Job

## Description:

Considered as a repeat visit No

## Customer's own words

|                                       |   |
|---------------------------------------|---|
| Exhaust gas radiator high temperature | 1 |
| Part I 11 71 8 513 691                |   |

|                        |   |
|------------------------|---|
| Gasket Steel           | 1 |
| Part I 11 61 8 571 005 |   |

|                        |   |
|------------------------|---|
| Gasket Steel           | 1 |
| Part I 11 62 8 576 287 |   |

|                        |   |
|------------------------|---|
| Pipe union             | 2 |
| Part I 11 71 7 799 853 |   |

## — Job

## Description:

Considered as a repeat visit No

## Customer's own words

|                            |       |       |
|----------------------------|-------|-------|
| Endkontrolle               | Local | 1 FRU |
| Flat rate unit I AZ00 45 0 |       |       |

|                                      |       |       |
|--------------------------------------|-------|-------|
| Füllmengen prüfen und nicht ergänzen | Local | 1 FRU |
|--------------------------------------|-------|-------|

Flat rate unit | AZ00 00 4

Service consultation at vehicle with Service Ticket

Flat rate unit | 00 52 052

1 FRU

— Job

Description:

Considered as a repeat visit    No

Customer's own words

Service-Reinigung

Part I 11320

Local

1

— Job

Description:

Considered as a repeat visit    No

Customer's own words

—

11/06/2018    Warranty

116003 Km

00664

Job: EGR cooler (incl. bypass flap) / exhaust cooler

— Job: EGR cooler (incl. bypass flap) / exhaust cooler

Description:    EGR cooler (incl. bypass flap) / exhaust cooler

Considered as a repeat visit    No

Customer's own words

EGR cooler (incl. bypass flap) / exhaust cooler

Defect I 11 71 06 48 00

Exhaust gas radiator high temperature

Part I 11 71 8 513 691

1

Gasket Steel

Part I 11 61 8 571 005

1

Gasket Steel

Part I 11 62 8 576 287

1

Pipe union

Part I 11 71 7 799 853

2


—

23/05/2018    Key

114053 Km

00664

Key 0



—

23/05/2018    Repair

114053 Km

00664

Job  
Niederlassung  
München  
Filiale  
Fröttmaning  
BMW AG,  
München  
Job  
Job  
Job  
Job  
Job

— Job

**Description:****Considered as a repeat visit** No**Customer's own words**

|                                                        |       |
|--------------------------------------------------------|-------|
| Carrying out the ABL and programming the control units | 8 FRU |
| Flat rate unit I 00 64 941                             |       |

## — Job

**Description:****Considered as a repeat visit** No**Customer's own words** PDC Halter ankleben,

|                            |       |
|----------------------------|-------|
| Localizing body problem(s) | 1 FRU |
| Flat rate unit I 51 00 001 |       |

|                                            |       |
|--------------------------------------------|-------|
| Removing and installing front bumper panel | 9 FRU |
| Flat rate unit I 51 11 656                 |       |

|                        |   |
|------------------------|---|
| Adhesive set K6        | 1 |
| Part I 83 19 2 317 925 |   |

## — Job

**Description:****Considered as a repeat visit** No**Customer's own words**

|                            |        |
|----------------------------|--------|
| Replacing windshield       | 24 FRU |
| Flat rate unit I 51 31 011 |        |

|                        |   |
|------------------------|---|
| Cover, windshield, top | 1 |
| Part I 51 31 7 258 053 |   |

|                                      |   |
|--------------------------------------|---|
| Windscreen, green, rain sensor / HUD | 1 |
| Part I 51 31 7 258 066               |   |

|                        |   |
|------------------------|---|
| Drip moulding, left    | 1 |
| Part I 51 31 7 258 187 |   |

|                        |   |
|------------------------|---|
| Drip moulding, right   | 1 |
| Part I 51 31 7 258 188 |   |

|                        |    |
|------------------------|----|
| Bump stop              | 11 |
| Part I 51 31 7 288 462 |    |

|                        |   |
|------------------------|---|
| Clamp                  | 2 |
| Part I 51 43 7 321 215 |   |

|                          |   |
|--------------------------|---|
| Sound insulation f apron | 1 |
| Part I 51 48 7 325 890   |   |

|                                        |   |
|----------------------------------------|---|
| Repair kit, window glass, cold, 1 hour | 1 |
| Part I 83 19 2 289 285                 |   |

|                                      |   |
|--------------------------------------|---|
| Windscreen, green, rain sensor / HUD | 1 |
| Part I 51 31 7 258 072               |   |

## — Job

**Description:****Considered as a repeat visit** No**Customer's own words**

|                            |       |       |
|----------------------------|-------|-------|
| Endkontrolle               | Local | 1 FRU |
| Flat rate unit I AZ00 45 0 |       |       |

|                                           |       |
|-------------------------------------------|-------|
| Service, advisory consultation at vehicle | 1 FRU |
|-------------------------------------------|-------|

Flat rate unit | 00 52 050

## — Job

## Description:

Considered as a repeat visit No

Customer's own words Bef: Kühlmittel auf Min- keine undichtigkeit erkennbar bitte beobachten,

|                                |       |       |
|--------------------------------|-------|-------|
| Füllstände prüfen und ergänzen | Local | 1 FRU |
| Flat rate unit   AZ00 33 3     |       |       |

|                        |  |   |
|------------------------|--|---|
| Anti-freeze            |  | 1 |
| Part   83 19 2 211 358 |  |   |

## — Job

## Description:

Considered as a repeat visit No

Customer's own words

|                   |       |   |
|-------------------|-------|---|
| Service-Reinigung | Local | 1 |
| Part   11320      |       |   |

## — Job

## Description:

Considered as a repeat visit No

Customer's own words

|                              |       |       |
|------------------------------|-------|-------|
| Angelieferte Räder montieren | Local | 6 FRU |
| Flat rate unit   AZ36 01 0   |       |       |

## — Job

## Description:

Considered as a repeat visit No

Customer's own words

|                                          |       |        |
|------------------------------------------|-------|--------|
| Vier Reifen auf Felge montieren (83,20 E | Local | 29 FRU |
| Flat rate unit   AZ36 03 4               |       |        |

|                          |  |   |
|--------------------------|--|---|
| Pirelli Cinturato P7 r-f |  | 4 |
| Part   85 45 2 547 376   |  |   |

## — Job

## Description:

Considered as a repeat visit No

Customer's own words

|                                      |       |       |
|--------------------------------------|-------|-------|
| Räder ins Fahrzeug legen (Kostenlos) | Local | 1 FRU |
| Flat rate unit   AZ36 01 5           |       |       |

## — Job

## Description:

Considered as a repeat visit No

Customer's own words

|                                   |       |       |
|-----------------------------------|-------|-------|
| Luftdruck korrigieren und RDC/RPA | Local | 1 FRU |
| Flat rate unit   AZ00 04 0        |       |       |

## — Job

Description:

Considered as a repeat visit No

Customer's own words

- 23/05/2018 Warranty 114053 Km 00664 Job: F1x F2x F3x B47 programming control units and if necessary, replacing the EGR valve

- Job: F1x F2x F3x B47 programming control units and if necessary, replacing the EGR valve

Description: F1x F2x F3x B47 programming control units and if necessary, replacing the EGR valve

Considered as a repeat visit No


Customer's own words

Carrying out the ABL and programming the control units  
Flat rate unit I 00 64 941

8 FRU

F1x F2x F3x B47 programming control units and if necessary, replacing the EGR valve  
Defect I 00 11 45 04 00

- 09/01/2017 Key 63737 Km 00050 Key 1



- 09/01/2017 Service 63737 Km 00050 Manual  
Niederlassung München, München



- 09/01/2017 Repair 63743 Km 00050 Job  
Niederlassung Job  
München MINI Job  
München Job  
BMW AG, Job  
München Job  
Job  
Job  
Job  
Job

- Job

Description:

Considered as a repeat visit No

Customer's own words

Service - standard scope  
Flat rate unit I 00 00 105

2 FRU

- Job

Description:

Considered as a repeat visit No

**Customer's own words**

|                                                  |       |
|--------------------------------------------------|-------|
| Engine oil service<br>Flat rate unit I 00 00 610 | 3 FRU |
|--------------------------------------------------|-------|

|                                                  |   |
|--------------------------------------------------|---|
| Set oil-filter element<br>Part I 11 42 8 575 211 | 1 |
|--------------------------------------------------|---|

|                                                    |   |
|----------------------------------------------------|---|
| BMW Engine Oil LL04 0W30<br>Part I 83 21 2 405 950 | 5 |
|----------------------------------------------------|---|

## — Job

**Description:****Considered as a repeat visit** No**Customer's own words**

|                                                            |       |
|------------------------------------------------------------|-------|
| Service - air filter element<br>Flat rate unit I 00 00 602 | 2 FRU |
|------------------------------------------------------------|-------|

|                                              |   |
|----------------------------------------------|---|
| Air filter element<br>Part I 13 71 8 511 668 | 1 |
|----------------------------------------------|---|

## — Job

**Description:****Considered as a repeat visit** No**Customer's own words**

|                                                   |       |
|---------------------------------------------------|-------|
| Service fuel filter<br>Flat rate unit I 00 00 604 | 3 FRU |
|---------------------------------------------------|-------|

|                                                 |   |
|-------------------------------------------------|---|
| Fuel filter cartridge<br>Part I 13 32 8 572 522 | 1 |
|-------------------------------------------------|---|

## — Job

**Description:****Considered as a repeat visit** No**Customer's own words**

|                                                   |       |
|---------------------------------------------------|-------|
| Microfilter service<br>Flat rate unit I 00 00 616 | 2 FRU |
|---------------------------------------------------|-------|

|                                                                  |   |
|------------------------------------------------------------------|---|
| Microfilter/activated Carbon container<br>Part I 64 11 9 237 555 | 1 |
|------------------------------------------------------------------|---|

|                                      |   |
|--------------------------------------|---|
| Hose clamp<br>Part I 07 12 9 952 104 | 1 |
|--------------------------------------|---|

## — Job

**Description:****Considered as a repeat visit** No**Customer's own words**

|                                                      |       |
|------------------------------------------------------|-------|
| Service, vehicle check<br>Flat rate unit I 00 00 624 | 6 FRU |
|------------------------------------------------------|-------|

## — Job

**Description:****Considered as a repeat visit** No

**Customer's own words** Luftdruck korrigieren und RDC/RPA initialisieren (RDC leuchtet),KEINE GW!!! Falscher RAdsatz verbaut,Zu Pos 210: Fehler für RDC gespeichert TEstmodul aufrufen und,abarbeiten lt. Tester keine Kommunika

tion zu den RDC-Empfängern Räder,prüfen hier ist aber nirgends ein RDC-Ventil verbaut  
überprüfen ob die,RDC-Ventile hier nachgerüstet werden können lt. ETK können  
Ventile,nachgerüstet werden derzeit k  
eine Rep Kunde braucht Fahrzeug, Teilenummer für Radelektroniken 36106856209,26AW  
Arbeitszeit,

|                                                                            |       |       |
|----------------------------------------------------------------------------|-------|-------|
| Luftdruck korrigieren und RDC/RPA initia<br>Flat rate unit   AZ00 04 0     | Local | 1 FRU |
| Performing vehicle test<br>Flat rate unit   00 00 556                      |       | 2 FRU |
| Troubleshooting electrical/electronic system<br>Flat rate unit   61 00 009 |       | 2 FRU |

— Job

Description:

Considered as a repeat visit No

Customer's own words Fertigsrellung 16uhr po 1-6 450 euro,

|                                                                                   |       |       |
|-----------------------------------------------------------------------------------|-------|-------|
| Endkontrolle<br>Flat rate unit   AZ00 45 0                                        | Local | 1 FRU |
| Füllstände prüfen und ergänzen ohne Sche<br>Flat rate unit   AZ00 33 3            | Local | 1 FRU |
| Service consultation at vehicle with Service Ticket<br>Flat rate unit   00 52 052 |       | 0 FRU |

— Job

Description:

Considered as a repeat visit No

Customer's own words

|                                   |       |   |
|-----------------------------------|-------|---|
| Service-Reinigung<br>Part I 11320 | Local | 1 |
|-----------------------------------|-------|---|

— Job

Description:

Considered as a repeat visit No

Customer's own words

|                                                               |       |       |
|---------------------------------------------------------------|-------|-------|
| Motorölservice - zusätzliche AW<br>Flat rate unit   IM00 25 0 | Local | 2 FRU |
|---------------------------------------------------------------|-------|-------|

— 26/09/2016 Key 48376 Km 00050 Key 1

|                                                                                     |                                                                                     |                                                                                     |                                                                                     |                                                                                     |                                                                                     |                                                                                     |                                                                                      |                                                                                       |                                                                                       |
|-------------------------------------------------------------------------------------|-------------------------------------------------------------------------------------|-------------------------------------------------------------------------------------|-------------------------------------------------------------------------------------|-------------------------------------------------------------------------------------|-------------------------------------------------------------------------------------|-------------------------------------------------------------------------------------|--------------------------------------------------------------------------------------|---------------------------------------------------------------------------------------|---------------------------------------------------------------------------------------|
|  |  |  |  |  |  |  |  |  |  |
| 15000                                                                               | 15000                                                                               | 15000                                                                               | 15000                                                                               | 32000                                                                               | 0                                                                                   | 29000                                                                               | 15000                                                                                |                                                                                       | 0                                                                                     |
| 06/2018                                                                             | 642                                                                                 | 642                                                                                 | 642                                                                                 |                                                                                     | 09/2018                                                                             |                                                                                     | 06/2018                                                                              |                                                                                       | 09/2018                                                                               |

— 26/09/2016 Repair 48383 Km 00050 Job  
Niederlassung Job  
München MINI Job  
München Job  
BMW AG, Job  
München

— Job

Description:

Considered as a repeat visit No

Customer's own words

Fehlermeldung RDC leuchtet auf Reifendruck jedoch i.O.,Bitte prüfen und RS mit SB nach Befund,zu Pos1,Befund:Luftdruck nicht I.O.,Fahrzeuginfluentdruck auf Soll ergänzt,Fahrzeug neu bewerten,

Performing vehicle test

Flat rate unit | 00 00 006

4 FRU

— Job

Description:

Considered as a repeat visit    No

Customer's own words

Endkontrolle

Flat rate unit | AZ00 45 0

Local

1 FRU

— Job

Description:

Considered as a repeat visit    No

Customer's own words

Füllstände prüfen und nicht ergänzen

Flat rate unit | AZ00 33 4

Local

1 FRU

— Job

Description:

Considered as a repeat visit    No

Customer's own words

Fahrzeugüberprüfung im Rahmen der Annahm

Flat rate unit | 00 52 054

Local

0 FRU

— Job

Description:

Considered as a repeat visit    No

Customer's own words

Service-Reinigung

Part | 11320

Local

1

—

26/09/2016    Warranty

48383 Km

00050

Job: Wheel electronics (RDC)

— Job: Wheel electronics (RDC)

Description:    Wheel electronics (RDC)

Considered as a repeat visit    No

Customer's own words

Performing vehicle test

Flat rate unit | 00 00 006

4 FRU

Wheel electronics (RDC)

Defect | 36 20 01 02 00


—

06/06/2016    Key

31968 Km

00050

Key 1



—

06/06/2016

Service

31968 Km

00050  
Niederlassung  
München,  
München

Manual

✓

✓

✓

✓

✓

✓

✓

✓

✓

✓

✓

—

06/06/2016

Repair

31968 Km

00050  
Niederlassung  
München MINI  
München  
BMW AG,  
München

Job  
Job  
Job  
Job  
Job  
Job

— Job

Description:

Considered as a repeat visit

No

Customer's own words

|                                                        |       |
|--------------------------------------------------------|-------|
| Engine oil service<br>Flat rate unit I 00 00 610       | 3 FRU |
| Service - standard scope<br>Flat rate unit I 00 00 105 | 2 FRU |
| Set oil-filter element<br>Part I 11 42 8 575 211       | 1     |
| BMW Engine Oil LL04 5W30<br>Part I 83 21 2 405 948     | 5     |

— Job

Description:

Considered as a repeat visit

No

Customer's own words

|                                                               |       |       |
|---------------------------------------------------------------|-------|-------|
| Motorölservice - zusätzliche AW<br>Flat rate unit I IM00 25 0 | Local | 2 FRU |
|---------------------------------------------------------------|-------|-------|

— Job

Description:

Considered as a repeat visit

No

Customer's own words

|                                                                  |       |
|------------------------------------------------------------------|-------|
| Microfilter service<br>Flat rate unit I 00 00 616                | 2 FRU |
| Microfilter/activated Carbon container<br>Part I 64 11 9 237 555 | 1     |

— Job

Description:

Considered as a repeat visit

No

Customer's own words

|                                                                |       |       |
|----------------------------------------------------------------|-------|-------|
| Kompakt-Check inkl. Endkontrolle<br>Flat rate unit I AZ00 04 2 | Local | 2 FRU |
|----------------------------------------------------------------|-------|-------|

Füllstände prüfen und nicht ergänzen  
Flat rate unit I AZ00 33 4

Local

1 FRU

## — Job

Description:

Considered as a repeat visit No

Customer's own words

Service-Reinigung  
Part I 11320

Local

1

## — Job

Description:

Considered as a repeat visit No

Customer's own words

Quick service with compact check or service consultation at vehicle  
Flat rate unit I 00 52 055








0 FRU

— 10/12/2015 Key

10844 Km

00050

Key 0



— 10/12/2015 Repair

10844 Km

00050

Job

Niederlassung  
München MINI  
München  
BMW AG,  
München

Job  
Job  
Job  
Job

## — Job

Description:

Considered as a repeat visit No

**Customer's own words** Fahrzeugtest durchführen Einstiegsblende lösenbefestigenkeine,Resonanzen mehr nachvollziehbar//Lautsprecherton vorne links in Tür,überschlägt sich beim Telefonieren sehr stark (Kunde hat I-Phone,gekoppelt) auch bei anderen Telefon der Fall,Lautsprecherton vorne links in Tür überschlägt sich beim Telefonieren,sehr stark (Kunde hat Iphone gekoppelt); auch bei anderen Telefon der,Fall; überprüfen und nach Befund Rücksprache Schrömer,Einstiegsblende gelöst befestigt keine Resonanzen mehr,nachvollziehbar,

Performing vehicle test  
Flat rate unit I 00 00 006

4 FRU

Supporting the voltage of the vehicle electrical system/recharging the  
vehicle electrical system battery  
Flat rate unit I 61 21 528

1 FRU

## — Job

Description:

Considered as a repeat visit No

**Customer's own words** Füllstände ergänzen,Frostschutz Nein,Scheibenreiniger Nein,Motoröl Nein,

Endkontrolle  
Flat rate unit I AZ00 45 0

Local

1 FRU

Füllstände ergänzen Frostschutz Nein Sch

Local

1 FRU

Flat rate unit | AZ00 33 3

## — Job

**Description:****Considered as a repeat visit** No**Customer's own words**Service-Reinigung  
Part I 11320

Local

1

## — Job

**Description:****Considered as a repeat visit** No**Customer's own words** Fertigstellung 15:00 Uhr, Abrechnung über Gewährleistung, Fahrzeugabgabe durch Frau Schuladen am Service-Counter, Tel-Nr: 0175/5944091,Vehicle check in course of reception  
Flat rate unit | 00 52 054

0 FRU

## — Job

**Description:****Considered as a repeat visit** No**Customer's own words**

— 10/12/2015 Warranty 10844 Km 00050 Job: Speaker mounting

## — Job: Speaker mounting

**Description:** Speaker mounting**Considered as a repeat visit** No**Customer's own words**Performing vehicle test  
Flat rate unit | 00 00 006

4 FRU

Supporting the voltage of the vehicle electrical system/recharging the  
vehicle electrical system battery  
Flat rate unit | 61 21 528

1 FRU

Speaker mounting  
Defect | 65 13 03 37 00