

Thank you for ordering from us!
www.checkvin.eu

Vehicle

BMW 318D A, 105KW

WBA3D11000F097569



Development code F30
Colour black-sapphire metallic
Actual integration level F020-15-11-502
Start of warranty 31 December 2013

Delivery stop



Technical Campaigns are available.

Technical campaigns

Status	Campaign number	Description	Reservation
Open	10032550300	Check the driver's airbag, replace if necessary (conversion SDI)  Delivery stop Local campaign number: -	

Warranty extension/VIN-based goodwill

Status	Campaign number	Description
Open	1SACC211056	Exhaust gas recirculation cooler Nx7 Local campaign number: -

Special information

There are no Campaigns for this vehicle.

Restrictions on the warranty

There are no restrictions on the warranty.

⚠ Market-specific restrictions are not currently displayed. Please check this in WDF/WXE via S-Gate.

Live Diagnosis

 There are no service solutions for Live Diagnosis.

Service contracts

No BSI contracts

Information on faults workshop/Service Consultation

There is no information on faults.

Navigation map

Installed map	Enabling code (subscription)	Latest navigation map included in subscription	Latest navigation map subject to charge
Road Map Europe PREMIUM 2012 (As of: 21 Jun 2019)	Enabling code valid for navigation maps with release date up to 31 Dec 2025 (SWID: 0028008F).	Road Map Europe East PREMIUM (USB) 2025-2	-

Vehicle details

Vehicle type	Passenger car
Brand	BMW
Model	318D A
Body	LIM
Vehicle identification number (last 7 digits)	F097569
Vehicle identification number (17 digits)	WBA3D11000F097569
Development code	F30
Steering	LL
Engine	N47T
Engine number	80878105
Exhaust re-treatment	EURO5, J, Pl/Ci, M, N1 I
Transmission	AUT
Transmission number	4589210WVM
Head unit serial number	0008908703
Drive	HECK
Integration level, works	F020-12-03-503
Production date	1 Mar 2012
Production plant	Muenchen
Delivery date	16 Mar 2012
Delivering retailer	Jorssen Zuid, Aartselaar, BE
National-market version	EUR
Paint code	475
Upholstery code	LCLX
Model code	3D21

Basic type	3D11
Lead type	3D21

Optional equipment

Optional equipment ex works:


01CA Selection of COP-relevant vehicles
 0205 Automatic transmission
 0230 Extra package, EU-speciifc
 0249 Multifunction f steering wheel
 0255 Sports leather steering wheel
 0258 Tyres with runflat properties
 02FM BMW LA wheel, V-spoke 398
 02PA Locking wheel bolt
 02VL Variable sport steering
 0320 Deleted, model lettering
 03AG Reversing camera
 0403 Glass roof, electrical
 0423 Floor mats velours
 0430 Interior/outside mirror with auto dip
 0431 Interior mirror with automatic-dip
 0465 Through-loading system
 0493 Storage compartment package
 0494 Seat heating driver/passenger
 04AE Armrest front, retractable
 04CE Fine-wood version, Fineline, anthracite
 04DM Accent strips, pearl-effect chrome
 0502 Headlight cleaning system
 0508 Park Distance Control (PDC)
 0520 Fog lights
 0521 Rain sensor
 0522 Xenon Light
 0524 Adaptive Headlights
 0534 Automatic air conditioning
 0544 Cruise control with brake function
 0548 Kilometre speedo
 0563 Light package
 05AC High-beam assistant
 05DC Rear-seat headrests, folding
 0609 Navigation system Professional
 0676 HiFi speaker system
 0698 Area-Code 2 for DVD
 06AA BMW TeleServices
 06AB Control, Teleservices
 06NK Connection, Bluetooth and USB devices
 06VA CIC assignment
 06WA Instrument panel with extended scope
 0775 Headlining anthracite
 07S2 Luxury Line
 07VB Comfort Package
 07VD Sicht Packet
 0843 Power reduction
 0868 Language version, Dutch
 0886 On-board literature, Dutch
 08KA Oil service interval 24 mths / 30,000 km
 08S3 Automatic locking during starting
 08SM Car ident. number visible from outside
 08V1 Information plate
 A090 90 Ah AGM battery
 LEDE Leather equipment

Retrofitted optional equipment:

KCBS Correction of brake pad wear model

Vehicle histories

	Date	Type	Vehicle mileage	Retailer	Overview
—	21/06/2019	Key	127301 Km	05738	Key 10



— 21/06/2019 Warranty 127301 Km 05738 Job: Seat belt, front

— Job: Seat belt, front

Description: Seat belt, front

Considered as a repeat visit No

Customer's own words

Removing and installing or replacing left or right front seat belt 0 FRU
Flat rate unit I 72 11 033

Removing and installing driver's seat 0 FRU
Flat rate unit I 52 13 501

Seat belt, front
Defect I 72 11 00 29 00

Upper belt front left 1
Part I 72 11 7 243 307


Covering cap 1
Part I 72 11 7 284 489

Fillister head screw 4
Part I 07 14 9 321 690

— 12/04/2019 Key 122992 Km 05738 Key 10



— 12/04/2019 Service 122992 Km 05738 Jorssen Automatic
Zuid, Aartselaar



— 12/04/2019 Repair 122992 Km 05738 Jorssen Job
Zuid, Aartselaar

— Job

Description:

Considered as a repeat visit No

Customer's own words













(Statutory) vehicle inspection 0 FRU
Flat rate unit I 00 12 559

Service standaard omvang
Package I 0000105


Service - standard scope 2

Flat rate unit | 00 00 105

Service luchtfilterelement
Package | 0000602Service - air filter element 2
Flat rate unit | 00 00 602Air filter element 1
Part | 13718511668Service brandstoffilter
Package | 0000604Service fuel filter 3
Flat rate unit | 00 00 604Fuel filter cartridge 1
Part | 13328572522Service motorolie
Package | 0000610Engine oil service 3
Flat rate unit | 00 00 610Set oil-filter element 1
Part | 11428507683BMW Engine Oil LL04 5W30 5.2
Part | 83212405948Service microfilter
Package | 0000616Microfilter service 2
Flat rate unit | 00 00 616Microfilter/activated Carbon container 1
Part | 64119237555Service voertuig-check
Package | 0000624Service, vehicle check 6
Flat rate unit | 00 00 624

—	14/06/2018	Key	98203 Km	05738	Key 10	
						
-1100		-1100		33000	33000	28000
07/2019		377		05/2020		07/2021
						04/2019
—	14/06/2018	Service	98203 Km	05738 Jorssen Zuid, Aartselaar	Automatic	
						
-1100	0	-1100	0	33000	33000	28000
01/1970	01/1970	06/2019	01/1970	01/1970	01/1970	01/1970
✓		✓				
—	28/05/2018	Key	96859 Km	05738	Key 10	
						
460		460		34000	34000	30000
07/2019		393		-177 24.2 %	07/2021	04/2019

— 28/05/2018 Service 96859 Km 05738 Jorssen Automatic
Zuid,
Aartselaar



— 28/05/2018 Repair 96859 Km 05738 Jorssen Job
Zuid,
Aartselaar

— Job

Description:

Considered as a repeat visit No

Customer's own words

!!! unknown BMW-Id ESTIMATE Onderhoudshistorie door middel van Local 0 FRU
ICOM naar het motorvoertuig overdragen !!!
Flat rate unit I -

Service standaard omvang
Package I 0000105


Service - standard scope 2
Flat rate unit I 00 00 105

Service remvloeistof
Package I 0000618


Brake fluid service 4
Flat rate unit I 00 00 618

Brake fluid DOT4 LV, low viscosity 1
Part I 83132184843


— 11/09/2017 Key 75595 Km 05738 Key 10

































































— 24/07/2017 Key 71534 Km 05738 Key 10



— 24/07/2017 Key 71533 Km 05738 Key 10



— 24/07/2017 Service 71534 Km 05738 Jorssen Automatic
nv Jorssen
Aartselaar ,
Aartselaar

	 230 03/2018 ✓	 230 03/2018 ✓	 230 03/2018 ✓	 230 03/2018 ✓	 60000 ✓	 12/2017 ✓	 49000 ✓	 70000 03/2022 ✓	 08/2017 ✓
—	30/06/2017	Key		66914 Km	05738	Key 10			
	 3800 03/2018	 3800 273	 3800 273	 3800 273	 60000 ✓	 0 12/2017 ✓	 43000 ✓	 70000 03/2022 ✓	 0 08/2017 ✓
—	21/06/2017	Key		66061 Km	05738	Key 10			
	 4700 03/2018	 4700 283	 4700 283	 4700 283	 60000 ✓	 0 12/2017 ✓	 43000 ✓	 70000 03/2022 ✓	 0 08/2017 ✓
—	12/12/2016	Key		52083 Km	05738	Key 0			
	 20000 03/2018	 20000 474	 20000 474	 20000 474	 60000 ✓	 0 12/2017 ✓	 32000 ✓	 80000 03/2022 ✓	 0 08/2017 ✓
—	19/08/2016	Key		51980 Km	05738	Key 10			
	 20000 03/2018	 20000 589	 20000 589	 20000 589	 60000 ✓	 0 12/2017 ✓	 31000 ✓	 80000 03/2022 ✓	 0 03/2017 ✓
—	01/08/2016	Key		51980 Km	05738	Key 10			
	 20000 03/2018	 20000 609	 20000 609	 20000 609	 60000 ✓	 0 12/2017 ✓	 31000 ✓	 80000 03/2022 ✓	 0 03/2017 ✓
—	24/03/2016	Key		43275 Km	05738	Key 10			
	 -2300 07/2016	 -2300 129	 -2300 129	 -2300 129	 50000 ✓	 0 12/2017 ✓	 21000 ✓	 60000 07/2020 ✓	 0 05/2016 ✓
—	24/03/2016	Service		43275 Km	05738 Jorssen nv Jorssen Aartselaar , Aartselaar	Automatic			
	 -2300 07/2016 ✓	 -2300 07/2016 ✓	 -2300 07/2016 ✓	 -2300 07/2016 ✓	 50000 12/2017 ✓	 21000 07/2020 ✓	 60000 07/2020 ✓	 05/2016 ✓	
—	24/03/2016	Repair		43275 Km	05738 Jorssen Zuid , Aartselaar	Job			

— Job

Description:

Considered as a repeat visit No

Customer's own words

Hoge bezoekfrequentie. Herhalingsreparatie? Controleer de reparatiehistorie.	Local	0 FRU
Flat rate unit -		

Laadwens van de klant: Full	Local	0 FRU
Flat rate unit -		

Initiële laadtoestand hoog-voltage accu (SoC): 255%	Local	0 FRU
Flat rate unit -		

(Statutory) vehicle inspection		0 FRU
Flat rate unit 00 12 559		

Service - standard scope		
Package 0000105		

Service - standard scope		2
Flat rate unit 00 00 105		

Service - air filter element		
Package 0000602		

Service - air filter element		2
Flat rate unit 00 00 602		

Air filter element		1
Part 13718511668		

Service fuel filter		
Package 0000604		

Service fuel filter		3
Flat rate unit 00 00 604		

Fuel filter cartridge		1
Part 13328572522		

Engine oil service		
Package 0000610		

Engine oil service		3
Flat rate unit 00 00 610		

Set oil-filter element		1
Part 11428507683		

BMW Engine Oil LL04 5W30		5.2
Part 83212405948		


Microfilter service		
Package 0000616		

Microfilter service		2
Flat rate unit 00 00 616		


Microfilter/activated Carbon container		1
Part 64119237555		

Pollen-filter housing cleaner		1
Part 83192180509		

—	01/12/2015	Key	39131 Km	05738	Key 10
---	------------	-----	----------	-------	--------



— 01/12/2015 Service 39131 Km 05738 Jorssen Automatic
nv Jorssen
Aartselaar ,
Aartselaar



— 01/12/2015 Repair 39131 Km 05738 Jorssen Job
Zuid , Job
Aartselaar Job
Job
Job

— Job

Description:

Considered as a repeat visit No

Customer's own words

Laadwens van de klant: Full Flat rate unit -	Local	0 FRU
---	-------	-------

Initiële laadtoestand hoog-voltage accu (SoC): 255% Flat rate unit -	Local	0 FRU
---	-------	-------

Service - standard scope
Package I 0000105

Service - standard scope Flat rate unit I 00 00 105	2
--	---

Service - air filter element
Package I 0000602

Service - air filter element Flat rate unit I 00 00 602	2
--	---

Air filter element Part I 13718511668	1
--	---

Service fuel filter
Package I 0000604

Service fuel filter Flat rate unit I 00 00 604	3
---	---

Fuel filter cartridge Part I 13328572522	1
---	---

Engine oil service
Package I 0000610

Engine oil service Flat rate unit I 00 00 610	3
--	---

Set oil-filter element Part I 11428507683	1
--	---

BMW Engine Oil LL04 5W30 Part I 83212405948	5.2
--	-----

Service, front brakes
Package I 0000612

Service, front brakes Flat rate unit I 00 00 612	6
Repair kit, brake pads asbestos-free Part I 34116850568	1
Brake pad wear sensor, front left Part I 34356792289	1
Brake-pad paste Part I 83192158851	2
Brake cleaner acetone-free Part I 83192413695	1

Microfilter service
Package I 0000616

Microfilter service Flat rate unit I 00 00 616	2
Microfilter/activated Carbon container Part I 64119237555	1
Pollen-filter housing cleaner Part I 83192180509	1

Brake fluid service
Package I 0000618

Brake fluid service Flat rate unit I 00 00 618	4
Brake fluid DOT4 LV, low viscosity Part I 83132184843	1

Service, vehicle check
Package I 0000624

Service, vehicle check Flat rate unit I 00 00 624	6
--	---

— Job

Description:

Considered as a repeat visit No

Customer's own words

F2x F3x Rework corrosion protection of engine compartment (part 2) Flat rate unit I -	Local	3 FRU
--	-------	-------

— Job

Description:

Considered as a repeat visit No

Customer's own words

F20 F21 F30 F31 F35 Program control units (FEM) Flat rate unit I -	Local	4 FRU
---	-------	-------

— Job

Description:

Considered as a repeat visit No

Customer's own words

F20 F21 F30 F31 Rework the corrosion protection connector for luggage compartment
Flat rate unit | - Local 3 FRU

— Job

Description:**Considered as a repeat visit** No**Customer's own words**

F2x F3x Remove the water drain grommet of the units compartment
Flat rate unit | - Local 4 FRU

— 01/12/2015 Warranty 39131 Km 05738
Job: F20 F21 F30 F31 Rework the corrosion protection connector for luggage compartment
Job: F2x F3x Rework corrosion protection of engine compartment (part 2)
Job: F20 F21 F30 F31 F35 Program control units (FEM)
Job: F2x F3x Remove the water drain grommet of the units compartment

— Job: F20 F21 F30 F31 Rework the corrosion protection connector for luggage compartment

Description: F20 F21 F30 F31 Rework the corrosion protection connector for luggage compartment**Considered as a repeat visit** No**Customer's own words**

Rework corrosion protection
Flat rate unit | 00 61 607 3 FRU

F20 F21 F30 F31 Rework the corrosion protection connector for luggage compartment
Defect | 00 61 75 03 00

— Job: F2x F3x Rework corrosion protection of engine compartment (part 2)

Description: F2x F3x Rework corrosion protection of engine compartment (part 2)**Considered as a repeat visit** No**Customer's own words**

Rework corrosion protection
Flat rate unit | 00 61 943 3 FRU

F2x F3x Rework corrosion protection of engine compartment (part 2)
Defect | 00 51 30 03 00

Cover base B+
Part | 61 14 9 316 645 1

— Job: F20 F21 F30 F31 F35 Program control units (FEM)

Description: F20 F21 F30 F31 F35 Program control units (FEM)**Considered as a repeat visit** No**Customer's own words**

Programming and encoding charged under another technical campaign or repair
Flat rate unit | 00 61 536 1 FRU

F20 F21 F30 F31 F35 Program control units (FEM)
Defect | 00 61 68 03 00

— Job: F2x F3x Remove the water drain grommet of the units compartment

Description: F2x F3x Remove the water drain grommet of the units compartment

Considered as a repeat visit No

Customer's own words

Remove water drain grommet of units compartment
Flat rate unit I 00 61 960

4 FRU

F2x F3x Remove the water drain grommet of the units compartment
Defect I 00 64 75 01 00

— 27/08/2014 Key

11942 Km

05738

Key 1

								
24000	24000	24000	24000	26000	0	13000	24000	0
07/2016	703	703	703		03/2015		07/2016	05/2016