

Thank you for ordering from us!
www.checkvin.eu

Vehicle

BMW 318d, 110KW

WBA8Y510X0G430579



Development code F34
Colour glacier-silber metallic
Actual integration level F020-18-11-520
Start of warranty 26 October 2015

Delivery stop



Technical Campaigns are available.

Technical campaigns

Status	Campaign number	Description	Reservation
Open	10011150700	Replacing the exhaust gas recirculation cooler (high temperature) Delivery stop Local campaign number: -	
Open	10011350700	Exhaust gas recirculation cooler customer notification Local campaign number: -	
Open	10013510300	Program control units (DDE) Local campaign number: -	
Open	10032550300	Check the driver's airbag, replace if necessary (conversion SDI) Delivery stop Local campaign number: -	

Warranty extension/VIN-based goodwill

Status	Campaign number	Description
Open	1SACC011056	Exhaust gas recirculation cooler Bx7 Local campaign number: -

Special information

There are no Campaigns for this vehicle.

Restrictions on the warranty

There are no restrictions on the warranty.

⚠ Market-specific restrictions are not currently displayed. Please check this in WDF/WXE via S-Gate.

Live Diagnosis

 There are no service solutions for Live Diagnosis.

Service contracts

No BSI contracts

Information on faults workshop/Service Consultation

There is no information on faults.

Navigation map

Note: The installed map cannot be clearly identified. Presumably one of the following maps is present in the vehicle.

Installed map	Enabling code (subscription)	Latest navigation map included in subscription	Latest navigation map subject to charge
Road Map EUROPE EVO 2015-4 (As of: 5 Sept 2019)	Enabling code valid for navigation maps with release date up to 31 Dec 2099 (SWID: 00F10FFF).	Road Map EUROPE EVO 2024-2	-
Road Map EUROPE EVO 2015-4 (As of: 5 Sept 2019)	-	-	-

Vehicle details

Vehicle type	Passenger car
Brand	BMW
Model	318d
Body	SAT
Vehicle identification number (last 7 digits)	G430579
Vehicle identification number (17 digits)	WBA8Y510X0G430579
Development code	F34
Steering	LL
Engine	B47U
Engine number	65059406
Exhaust re-treatment	EURO6, W, PI/CI, M, N1 I
Transmission	MECH
Transmission number	1067233CBJ
Head unit serial number	HB2140F7669168

Drive	HECK
Integration level, works	F020-15-07-506
Production date	13 Oct 2015
Production plant	Dingolfing
Delivery date	17 Oct 2015
Delivering retailer	A&M Wijnegem, Wijnegem, BE
National-market version	EUR
Paint code	A83
Upholstery code	KCSW
Model code	8Y51
Basic type	8Y51
Lead type	8Y51

Optional equipment










Optional equipment ex works:

01CA Selection of COP-relevant vehicles
 01CB CO2 equipment
 0216 Hydro steering-servotronic
 0230 Extra package, EU-specific
 0255 Sports leather steering wheel
 02DX BMW LA wheel, star spoke 394
 02PA Locking wheel bolt
 02VB Tyre pressure display
 0302 Alarm system
 0320 Deleted, model lettering
 0321 Exterior parts in body colour
 0402 Panorama glass roof
 0423 Floor mats velours
 0430 Interior/outside mirror with auto dip
 0431 Interior mirror with automatic-dip
 0493 Storage compartment package
 0494 Seat heating driver/passenger
 04AE Armrest front, retractable
 04CG Interior trim strips "satin-silber" matt
 0502 Headlight cleaning system
 0508 Park Distance Control (PDC)
 0520 Fog lights
 0521 Rain sensor
 0522 Xenon Light
 0534 Automatic air conditioning
 0544 Cruise control with brake function
 0548 Kilometre speedo
 0563 Lights package
 0609 Navigation system Professional
 0698 Area-Code 2 for DVD
 06AC Intelligent emergency call
 06AE Teleservices
 06NS Comfort telephony w/ enhanced Smartphone
 06WA Instrument panel with extended scope
 07LC Modell Advantage
 0843 Power reduction
 0868 Language version Dutch
 0886 On-board literature, Dutch
 08KA Oil service interval 24 mths / 30,000 km
 08S3 Automatic locking during starting
 08TF Active pedestrian protection
 A090 90 Ah AGM battery
 KLED Leatherette

Retrofitted optional equipment:

This vehicle has no retrofits.

Vehicle histories

	Date	Type	Vehicle mileage	Retailer	Overview
—	05/09/2019	Key	95877 Km	05657	Key 0
	 -1300 05/2020		 -1300 236	  6000  11/2020	 7000  30000 05/2022
—	05/09/2019	Service	95877 Km	05657 van Osch Halen , Halen	Automatic
	 -1300 04/2020 ✓		 -1300 04/2020 ✓	  6000 10/2020 ✓	 7000  30000 04/2022 ✓
—	05/09/2019	Warranty	95877 Km	05657	Job: F10 F11 F25 F26 F31 F34 F36 B47O Replacing exhaust-gas recirculation cooler

— Job: F10 F11 F25 F26 F31 F34 F36 B47O Replacing exhaust-gas recirculation cooler

Description: F10 F11 F25 F26 F31 F34 F36 B47O Replacing exhaust-gas recirculation cooler

Considered as a repeat visit No

Customer's own words

Additional work of checking EGR cooler Flat rate unit I 00 67 703	1 FRU
--	-------

Replace exhaust-gas recirculation cooler and replace or remount exhaust-gas recirculation valve; clean exhaust gas recirculation pipe Flat rate unit I 00 66 955	28 FRU
--	--------

Perform additional work for pressure sensor system function Flat rate unit I 00 67 695	3 FRU
---	-------

Additional work for replacing intake system Flat rate unit I 00 67 696	24 FRU
---	--------

F10 F11 F25 F26 F31 F34 F36 B47O Replacing exhaust-gas
recirculation cooler
Defect I 00 11 83 04 00

exhaust cooler Part I 11 71 8 596 444	1
--	---

Set of small parts Part I 11 71 8 597 652	1
--	---

Intake manifold AGR with flap control Part I 11 61 8 513 655	1
---	---


Sensor, boost pressure Part I 13 62 8 637 896	1
--	---

Oval head screw Part I 35 21 7 685 343	2
---	---

—	19/11/2018	Key	76560 Km	Key 0
---	------------	-----	----------	-------



— 19/11/2018 Service 76560 Km 05657 van Automatic
Osch Halen , Halen



— 19/11/2018 Repair 76560 Km 05657 A&M Job
Halen , Halen

— Job

Description:

Considered as a repeat visit No

Customer's own words

!!! unknown BMW-Id ESTIMATE TC_ !!! Local 18 FRU
Flat rate unit I -

Service standaard omvang
Package I 0000105

Service - standard scope 2
Flat rate unit I 00 00 105

Service remvloeistof
Package I 0000618

Brake fluid service 6
Flat rate unit I 00 00 618

Brake fluid DOT4 LV, low viscosity 1
Part I 83132184843

— 19/11/2018 Warranty 76560 Km 05657 Job: F1x F2x F3x B47
programming control units and if necessary, replacing the EGR valve

— Job: F1x F2x F3x B47 programming control units and if necessary, replacing the EGR valve

Description: F1x F2x F3x B47 programming control units and if necessary, replacing the EGR valve


Considered as a repeat visit No

Customer's own words


Carrying out the ABL and programming the control units 8 FRU
Flat rate unit I 00 64 941

F1x F2x F3x B47 programming control units and if necessary, replacing
the EGR valve
Defect I 00 11 45 04 00

— 17/05/2018 Key 63568 Km 05657 Key 0



— 17/05/2018 Service 63568 Km 05657 van Automatic
Osch Halen ,
Halen



— 17/05/2018 Repair 63568 Km 05657 A&M Job
Halen , Halen

— Job

Description:

Considered as a repeat visit No

Customer's own words

!!! unknown BMW-Id ESTIMATE Onderhoudshistorie door middel van Local 0 FRU
ICOM naar het motorvoertuig overdragen !!!
Flat rate unit I -

Service standaard omvang
Package I 0000105

Service - standard scope 2
Flat rate unit I 00 00 105

Service luchtfilterelement
Package I 0000602

Service - air filter element 2
Flat rate unit I 00 00 602

Air filter element 1
Part I 13718511668

Service brandstoffilter
Package I 0000604

Service fuel filter 3
Flat rate unit I 00 00 604

Fuel filter cartridge 1
Part I 13328572522

Service motorolie
Package I 0000610

Engine oil service 3
Flat rate unit I 00 00 610

Set oil-filter element 1
Part I 11428575211

BMW Engine Oil LL04 5W30 5
Part I 83212405948

Service microfilter
Package I 0000616



















Microfilter service 2
Flat rate unit I 00 00 616

Microfilter/activated Carbon container 1
Part I 64119237555

Service voertuig-check
Package I 0000624

Service, vehicle check 6

Flat rate unit | 00 00 624

—	23/01/2017	Key	31550 Km	05657	Key 0		
							
-800	0	-800	0	60000	0	60000	31000
10/2017		280			10/2018		10/2019
—	23/01/2017	Key	31550 Km	05657	Key 0		
							
-800	0	-800	0	60000	0	60000	31000
10/2017		281			10/2018		10/2019
—	23/01/2017	Service	31550 Km	05657 van Osch&Zn nv van Osch Halen , Halen	Automatic		
							
-800		-800		60000	0	60000	31000
10/2017		10/2017		10/2018			10/2019
✓		✓					
—	23/01/2017	Repair	31550 Km	05657 A&M Halen , Halen	Job Job		

— Job

Description:

Considered as a repeat visit No

Customer's own words

Laadwens van de klant: Full	Local	0 FRU
Flat rate unit -		

Initiële laadtoestand hoog-voltage accu (SoC): 255%	Local	0 FRU
Flat rate unit -		

Service - standard scope
Package | 0000105

Service - standard scope	2
Flat rate unit 00 00 105	

Engine oil service
Package | 0000610

Engine oil service	3
Flat rate unit 00 00 610	

Set oil-filter element	1
Part 11428575211	

BMW Engine Oil LL04 5W30	5
Part 83212405948	

Microfilter service
Package | 0000616

Microfilter service	2
Flat rate unit 00 00 616	

Microfilter/activated Carbon container	1
Part 64119237555	

Pollen-filter housing cleaner
Part I 83192180509

1

— Job

Description:

Considered as a repeat visit No

Customer's own words

F34 F36 Bowdenkabel buitenhandgreep nabewerken Flat rate unit I -	Local	21 FRU
--	-------	--------

—	23/01/2017	Warranty	31550 Km	05657	Job: F34 F36 Reworking the Bowden cable on the outside door handle
---	------------	----------	----------	-------	--

— Job: F34 F36 Reworking the Bowden cable on the outside door handle

Description: F34 F36 Reworking the Bowden cable on the outside door handle

Considered as a repeat visit No

Customer's own words

Reworking the Bowden cable of both doors on the left Flat rate unit I 00 64 675	21 FRU
--	--------

F34 F36 Reworking the Bowden cable on the outside door handle Defect I 00 51 03 04 00
--

Cable tie Part I 61 13 1 367 599	2
-------------------------------------	---

—	29/06/2016	Warranty	17016 Km	05657	Job: Rotary latch lock/system lock, front
---	------------	----------	----------	-------	---

— Job: Rotary latch lock/system lock, front

Description: Rotary latch lock/system lock, front

Considered as a repeat visit No

Customer's own words

Performing vehicle test Flat rate unit I 00 00 006	4 FRU
---	-------

Removing and installing/replacing the outside door handle support including lock barrel, left or right Flat rate unit I 51 21 625	11 FRU
--	--------

Removing and installing/replacing the Bowden cable for the inner door opener on the front left or right door Flat rate unit I 51 21 735	4 FRU
--	-------

Job time without allowance for / body equipment Flat rate unit I 51 99 000	4 FRU
---	-------

Rotary latch lock/system lock, front Defect I 51 21 00 29 00

Bowd.cable,outside door handle front Part I 51 21 7 291 405	1
--	---

System latch, left Part I 51 21 7 202 143	1
--	---

Carrier, outside door handle, front left Part I 51 21 7 380 549	1
--	---

Bowden cable, inside door opener front	1
--	---

Part I 51 21 7 291 403

Sound insulation, door, front left
Part I 51 48 7 343 919

1

—

28/06/2016

Key

17016 Km

05657

Key 0

 14000 10/2017	 0	 14000 490	 0	 60000	 0 10/2018	 60000	 45000 10/2019
---	--	---	--	--	---	--	--