

Thank you for ordering from us!

www.checkvin.eu

Vehicle

BMW 320D A, 140KW

WBA8H91000A721876



Development code
Colour
Actual integration level
Start of warranty

F31
black 2
F020-18-03-532
1 June 2018

Technical campaigns

There are no Campaigns for this vehicle.

Warranty extension/VIN-based goodwill

Status	Campaign number	Description
Open	1SACC011056	Exhaust gas recirculation cooler Bx7 Local campaign number: -

Special information

There are no Campaigns for this vehicle.

Restrictions on the warranty

There are no restrictions on the warranty.

⚠ Market-specific restrictions are not currently displayed. Please check this in WDF/WXE via S-Gate.

Live Diagnosis

 There are no service solutions for Live Diagnosis.

Service contracts

No BSI contracts

Information on faults workshop/Service Consultation

There is no information on faults.

Navigation map

Note: The installed map cannot be clearly identified. Presumably one of the following maps is present in the vehicle.

Installed map	Enabling code (subscription)	Latest navigation map included in subscription	Latest navigation map subject to charge
Road Map EUROPE EVO 2018-1 (As of: 31 Oct 2022)	-	-	-
Road Map EUROPE EVO 2018-1 (As of: 31 Oct 2022)	-	-	-

Vehicle details

Vehicle type	Passenger car
Brand	BMW
Model	320D A
Body	TOUR
Vehicle identification number (last 7 digits)	A721876
Vehicle identification number (17 digits)	WBA8H91000A721876
Development code	F31
Steering	LL
Engine	B47O
Engine number	65315346
Exhaust re-treatment	EURO6, WLTP, AD, PI/CI, M, N1 I
Transmission	AUT
Transmission number	1744356W7O
Head unit serial number	HB2241J8284120
Drive	HECK
Integration level, works	F020-18-03-532
Production date	9 May 2018
Production plant	Muenchen
Delivery date	16 May 2018
Delivering retailer	Autohaus Krauth, Sinsheim, DE
National-market version	EUR
Paint code	668
Upholstery code	CCL1
Model code	8H01
Basic type	8H91
Lead type	8H01

Optional equipment

Optional equipment ex works:

0164 Exhaust emissions standard EU6
 01CA Selection of COP-relevant vehicles
 01CB CO2 equipment
 0205 Automatic transmission
 0216 Hydro steering-servotronic
 0230 Extra package, EU-specific
 0258 Tyres with runflat properties
 02A6 BMW LA wheel, double spoke 392
 02PA Locking wheel bolt
 02VB Tyre pressure display
 02XE Leather sports steering wheel
 0302 Alarm system
 0320 Deleted, model lettering
 0322 Comfort access system
 03AA Roof railing black
 03AG Reversing camera
 0423 Floor mats velours
 0428 Warning triangle and first aid kit
 0430 Interior/outside mirror with auto dip
 0431 Interior mirror with automatic-dip
 0481 Sports seat
 0488 Lumbar support, driver and passenger
 0493 Storage compartment package
 0494 Seat heating driver/passenger
 04AE Armrest front, retractable
 04LU black high-gloss accent chrm. Perlglanz
 0508 Park Distance Control (PDC)
 0521 Rain sensor
 0534 Automatic air conditioning
 0544 Cruise control with braking function
 0548 Kilometre speedo
 0552 Adaptive LED headlight
 0563 Lights package
 05A1 LED Fog lights
 05AC High-beam assistant
 05AS Driving Assistant
 05DA Passenger airbag deactivation
 05DC Rear-seat headrests, folding
 0609 Navigation system Professional
 0610 Head-up display
 0654 DAB tuner
 0676 HiFi speaker system
 0698 Area-Code 2 for DVD
 06AC Intelligent emergency call
 06AE Teleservices
 06AK Connected Drive Services
 06AM Real-Time Traffic Information
 06AN Concierge Services
 06AP Remote Services
 06NW Telephony with wireless charging
 06WA Instrument panel with extended scope
 06WD WLAN Hotspot
 07AC Sport Line
 07LD Modell Sport Line
 07R7 Innovation package
 0801 German version
 0851 Language version German
 0879 On-board literature, German
 08KA Oil service interval 24 mths / 30,000 km
 08R9 Refrigerant R1234yf
 08TH Road sign detection
 09AA Outer skin protection
 09BM Navigation package Connected Drive
 A090 90 Ah AGM battery
 POLS Cloth cushion

Retrofitted optional equipment:

This vehicle has no retrofits.

Control unit software version

Vehicle histories

	Date	Type	Vehicle mileage	Retailer	Overview
—	31/10/2022	Key	152392 Km	30316	Key 0
	 1400 08/2023   1400 08/2023   70000  03/2023  70000  32000 08/2025  09/2024				
—	31/10/2022	Warranty	152394 Km	30316	Job: F1x F2x F3x G0x G1x G3x B47O B47K B47U B47T Replacing EGR cooler (high-temperature)
— Job: F1x F2x F3x G0x G1x G3x B47O B47K B47U B47T Replacing EGR cooler (high-temperature)					
Description: F1x F2x F3x G0x G1x G3x B47O B47K B47U B47T Replacing EGR cooler (high-temperature)					
Considered as a repeat visit No					
Customer's own words					
Replace exhaust gas recirculation cooler, including exhaust gas recirculation valve Flat rate unit I 00 72 349					0 FRU
Additional work: run function test for pressure sensor system Flat rate unit I 00 72 939					0 FRU
Additional work: enter component identification of new exhaust gas recirculation cooler in diagnostic system Flat rate unit I 00 72 940					0 FRU
Additional work: clean exhaust gas recirculation pipe (not to be used when replacing intake system) Flat rate unit I 00 72 941					0 FRU
F1x F2x F3x G0x G1x G3x B47O B47K B47U B47T Replacing EGR cooler (high-temperature) Defect I 00 11 53 06 00					
Acoustic cover front Part I 11 14 8 490 577					1
EGR small parts set Part I 11 71 8 490 640					1
Connection piece Part I 11 65 7 803 012					1
O-ring Part I 11 61 8 512 681					1
Holder Part I 61 13 1 369 832					1
Pipe union Part I 11 71 7 799 853					2
Exhaust gas radiator high temperature Part I 11 71 7 822 347					1
Hex Bolt with washer Part I 07 11 9 905 750					1
—	31/10/2022	Warranty	152394 Km	30316	Job: F1x F2x F3x G0x G1x G3x B47O B47K B47U B47T Replacing EGR cooler (high-temperature)

— Job: F1x F2x F3x G0x G1x G3x B47O B47K B47U B47T Replacing EGR cooler (high-temperature)

Description: F1x F2x F3x G0x G1x G3x B47O B47K B47U B47T Replacing EGR cooler (high-temperature)

Considered as a repeat visit No

Customer's own words

Replace exhaust gas recirculation cooler, including exhaust gas recirculation valve	0 FRU
Flat rate unit I 00 72 349	

Additional work: run function test for pressure sensor system	0 FRU
Flat rate unit I 00 72 939	

Additional work: enter component identification of new exhaust gas recirculation cooler in diagnostic system	0 FRU
Flat rate unit I 00 72 940	

Additional work: clean exhaust gas recirculation pipe (not to be used when replacing intake system)	0 FRU
Flat rate unit I 00 72 941	

F1x F2x F3x G0x G1x G3x B47O B47K B47U B47T Replacing EGR cooler (high-temperature)	
Defect I 00 11 53 06 00	

Acoustic cover front	1
Part I 11 14 8 490 577	

EGR small parts set	1
Part I 11 71 8 490 640	

Connection piece	1
Part I 11 65 7 803 012	

O-ring	1
Part I 11 61 8 512 681	

Holder	1
Part I 61 13 1 369 832	

Pipe union	2
Part I 11 71 7 799 853	

Exhaust gas radiator high temperature	1
Part I 11 71 7 822 347	

Hex Bolt with washer	1
Part I 07 11 9 905 750	

—	31/10/2022	Warranty	152394 Km	30316	Job: F1x F2x F3x G0x G1x G3x B47O B47K B47U B47T Replacing EGR cooler (high-temperature)
---	------------	----------	-----------	-------	--

— Job: F1x F2x F3x G0x G1x G3x B47O B47K B47U B47T Replacing EGR cooler (high-temperature)

Description: F1x F2x F3x G0x G1x G3x B47O B47K B47U B47T Replacing EGR cooler (high-temperature)

Considered as a repeat visit No

Customer's own words

Replace exhaust gas recirculation cooler, including exhaust gas recirculation valve	0 FRU
Flat rate unit I 00 72 349	

Additional work: run function test for pressure sensor system	0 FRU
Flat rate unit I 00 72 939	

Additional work: enter component identification of new exhaust gas recirculation cooler in diagnostic system	0 FRU
Flat rate unit I 00 72 940	

Additional work: clean exhaust gas recirculation pipe (not to be used when replacing intake system)
Flat rate unit I 00 72 941

0 FRU

F1x F2x F3x G0x G1x G3x B47O B47K B47U B47T Replacing EGR cooler (high-temperature)
Defect I 00 11 53 06 00

Acoustic cover front
Part I 11 14 8 490 577

1

EGR small parts set
Part I 11 71 8 490 640

1

Connection piece
Part I 11 65 7 803 012

1

O-ring
Part I 11 61 8 512 681

1

Holder
Part I 61 13 1 369 832

1

Pipe union
Part I 11 71 7 799 853

2

Exhaust gas radiator high temperature
Part I 11 71 7 822 347

1

Hex Bolt with washer
Part I 07 11 9 905 750

1

—

03/05/2022

Key

145624 Km

04784

Key 0



9000

08/2023





9000

449





80000

03/2023





90000



40000

08/2025



03/2023

—

03/05/2022

Repair

145624 Km

04784

Job
Autohaus
Krauth GmbH
& Co. KG ,
Sinsheim

Job
Job
Job

— Job

Description:

Considered as a repeat visit No

Customer's own words

Removing and installing/replacing front ornamental grille, centre left or right
Flat rate unit I 51 13 001

12 FRU

Grille, front, right
Part I 51 13 7 260 498

1

— Job

Description:

Considered as a repeat visit No

Customer's own words

Fahrzeugfußräume aussaugen und Maschinelle Oberwäsche (ohne Berechnung)
Flat rate unit I 00 11 400

Local

1 FRU

https://myair-b2d.bmwgroup.com/air/faces/xhtml/fahrzeug/FahrzeugSingleView.xhtml?vin=WBA8H91000A721876

6/23

— Job

Description:

Considered as a repeat visit No

Customer's own words

Flüssigkeitstände prüfen und bei Bedarf ergänzen
Flat rate unit I 00 99 887

Local

0 FRU

Windshield washer antifreeze
Part I 83125A1A166






1

— 19/04/2022 Key

144821 Km

04784






Key 0



— 18/08/2021 Key

122753 Km

Key 0










— 18/08/2021 Service

122710 Km

04784

Automatic








Autohaus
Krauth
GmbH&Co. KG
, Sinsheim



— 17/08/2021 Key

122710 Km

Key 0



— 17/08/2021 Repair

122753 Km

04784

Autohaus
Krauth GmbH
& Co. KG ,
Sinsheim

Job
Job
Job
Job
Job
Job
Job
Job

— Job

Description:

Considered as a repeat visit No

Customer's own words

Service - standard scope
Flat rate unit I 00 00 105

2 FRU

— Job

Description:

Considered as a repeat visit No

Customer's own words

Microfilter service Flat rate unit I 00 00 616	2 FRU
---	-------

Microfilter/activated Carbon container Part I 64 11 9 237 555	1
--	---

— Job

Description:

Considered as a repeat visit No

Customer's own words

Engine oil service Flat rate unit I 00 00 610	3 FRU
--	-------

BMW Motoröl 0W-30 Longlife-04 Tankwagen Part I 83 21 2 405 674	Local	5
---	-------	---

Windshield washer antifreeze Part I 83125A1A166	1
--	---

Set oil-filter element Part I 11 42 8 575 211	1
--	---

— Job

Description:

Considered as a repeat visit No

Customer's own words

Service - air filter element Flat rate unit I 00 00 602	2 FRU
--	-------

Air filter element Part I 13 71 8 511 668	1
--	---

— Job

Description:

Considered as a repeat visit No

Customer's own words

Service fuel filter Flat rate unit I 00 00 604	3 FRU
---	-------

Fuel filter cartridge Part I 13 32 8 572 522	1
---	---

— Job

Description:

Considered as a repeat visit No

Customer's own words

Service, vehicle check Flat rate unit I 00 00 624	6 FRU
--	-------

— Job

Description:

Considered as a repeat visit No

Customer's own words

Fahrzeugfußräume aussaugen und maschinelle Oberwäsche - ohne Berechnung
Flat rate unit | 00 11 400

Local 0 FRU

— Job

Description:

Considered as a repeat visit No

Customer's own words

Service, rear brakes
Flat rate unit | 00 00 614

7 FRU

Brems. Korrosionsschutz
Part | FT99 88 9 555 0

Local 1

Plastilube / Anti-Quietsc
Part | FT99 88 9 555 1

Local 1

Repair kit, brake pads asbestos-free
Part | 34 21 6 873 093

1


Brake-pad sensor, rear
Part | 34 35 6 792 292

1

— 08/04/2021 Key

110408 Km

Key 0



— 08/04/2021 Repair

110419 Km

04784
Autohaus
Krauth GmbH
& Co. KG,
Sinsheim

Job
Job

— Job

Description:

Considered as a repeat visit No

Customer's own words

Fahrzeugfußräume aussaugen und maschinelle Oberwäsche - ohne Berechnung
Flat rate unit | 00 11 400

Local 0 FRU

— Job

Description:

Considered as a repeat visit No

Customer's own words

AdBlue nachfüllen
Flat rate unit | 00 99 885

Local 2 FRU

Diesel Exhaust Fluid AdBlue
Part | 83 19 2 289 602

140

— 08/04/2021 Warranty

110419 Km

04784

Job: Vibration damper (crankshaft)
Job: Radial shaft sealing ring
(RWDR) / dust plate on input flange

— Job: Vibration damper (crankshaft)

Description: Vibration damper (crankshaft)**Considered as a repeat visit** No**Customer's own words**

Removing and installing or replacing vibration damper Flat rate unit I 11 23 510	19 FRU
---	--------

Performing vehicle test Flat rate unit I 00 00 006	4 FRU
---	-------

Vibration damper (crankshaft) Defect I 11 23 00 39 00	
--	--

Rubber mounting Part I 18 20 8 570 668	1
---	---

Muffler clamp Part I 18 30 8 473 736	1
---	---

— Job: Radial shaft sealing ring (RWDR) / dust plate on input flange

Description: Radial shaft sealing ring (RWDR) / dust plate on input flange**Considered as a repeat visit** No**Customer's own words**

Replacing radial shaft seal for input flange of rear axle differential Flat rate unit I 33 11 502	15 FRU
--	--------

Radial shaft sealing ring (RWDR) / dust plate on input flange Defect I 33 12 02 48 00	
--	--

Fastening set, gasket Part I 18 30 8 578 628	1
---	---

Shaft seal Part I 31 50 7 609 535	1
--------------------------------------	---

Screw plug with O-ring Part I 33 11 7 525 064	1
--	---

Repair kit, recessed nut, blue Part I 33 12 7 607 158	1
--	---

Torx bolt Part I 33 30 6 861 221	2
-------------------------------------	---

— 22/03/2021 Key

108906 Km

Key 0

									
15000	15000	15000	15000	120000	0	7000	15000	0	0
09/2022	556	556	556		03/2023		09/2022		03/2023

— 22/03/2021 Key

108901 Km

Key 0









									
15000	15000	15000	15000	120000	0	7000	15000	0	0
09/2022	557	557	557		05/2021		09/2022		06/2021

— 22/03/2021 Service

108901 Km

04784
Autohaus
Krauth

Automatic

GmbH&Co. KG
, Sinsheim

— 22/03/2021 Repair 108906 Km 04784
Autohaus
Krauth GmbH
& Co. KG,
Sinsheim Job
Job
Job

— Job

Description:

Considered as a repeat visit No

Customer's own words

Service - standard scope
Flat rate unit I 00 00 105

2 FRU

— Job

Description:

Considered as a repeat visit No

Customer's own words

Brake fluid service
Flat rate unit I 00 00 618

4 FRU

Bremsflüssigkeit DOT 4*
Part I FT99 99 9 407 5

Local

1

— Job

Description:

Considered as a repeat visit No

Customer's own words

Presentation for emission inspection
Flat rate unit I 00 00 127

7 FRU

(Statutory) vehicle inspection
Flat rate unit I 00 12 159










3 FRU

verauslagte Gebühr für Hauptuntersuchung
Part I VBHAUPTUNTE










Local

1

— 11/03/2021 Key 107215 Km Key 0



— 02/03/2021 Key 106778 Km Key 0



— 02/03/2021 Service 106778 Km 04784 Automatic
 Autohaus
 Krauth
 GmbH&Co. KG
 , Sinsheim

									
17000	17000	17000	17000	1100	0	7000	17000		0
09/2022	09/2022	09/2022	09/2022		05/2021		09/2022		06/2021
				✓					

— 02/03/2021 Repair 106783 Km 04784 Job
 Autohaus
 Krauth GmbH
 & Co. KG ,
 Sinsheim Job
 Job
 Job

— Job

Description:

Considered as a repeat visit No

Customer's own words

Service - standard scope 2 FRU
 Flat rate unit I 00 00 105

— Job

Description:

Considered as a repeat visit No

Customer's own words

Service, front brakes 6 FRU
 Flat rate unit I 00 00 612

Brems. Korosionsschutz Local 1
 Part I FT99 88 9 555 0

Plastilube / Anti-Quietsc Local 1
 Part I FT99 88 9 555 1

Repair kit, brake pads asbestos-free 1
 Part I 34 10 6 859 181

Brake pad wear sensor, front left 1
 Part I 34 35 6 792 289

Brake-pad paste 2
 Part I 83 19 2 158 851

— Job

Description:

Considered as a repeat visit No

Customer's own words

Replace left and right wiper blade 1 FRU
 Flat rate unit I 61 61 541

Set of wiper blades 1
 Part I 61 61 2 241 375

— Job

Description:

Considered as a repeat visit No

Customer's own words

Fahrzeugfußräume aussaugen und maschinelle Oberwäsche - ohne
Berechnung
Flat rate unit I 00 11 400

Local 0 FRU

— 05/01/2021 Key 102028 Km 04784 Key 0

									
22000	22000	22000	22000	6000	0	7000	22000		0
09/2022	633	633	633		05/2021		09/2022		01/2021

— 05/01/2021 Repair 102028 Km 04784 Job
Autohaus
Krauth GmbH
& Co. KG , Job
Sinsheim Job

— Job

Description:

Considered as a repeat visit No

Customer's own words

APAS TC-1-0011880500 Local 18 FRU
Flat rate unit I -

!!! unknown BMW-Id ESTIMATE F1x F2x F3x G0x G1x G3x B47O B47T Local 0 FRU
B47U B47K AGR-Kühler prüfen ggf. ersetzen !!!
Flat rate unit I -

— Job

Description:

Considered as a repeat visit No

Customer's own words

Package I MM02AUßENWÄSCHE OB Local
Fahrzeugfußräume aussaugen Local 0
Flat rate unit I 00 11 400

— Job

Description:

Considered as a repeat visit No

Customer's own words

!!! unknown BMW-Id ESTIMATE Im Stand klappert es aus dem Motorraum aus dem Bereich Luftfilter. Bitte prüfen ggfs. Instandsetzen !!! Local 0 FRU
Flat rate unit I -

— Job

Description:

Considered as a repeat visit No

Customer's own words

!!! unknown BMW-Id ESTIMATE !!! Local 0 FRU
Flat rate unit I -

!!! unknown BMW-Id ESTIMATE !!! Local 0 FRU
Flat rate unit I -

— 05/01/2021 Warranty 102032 Km 04784 Job: F1x F2x F3x G0x G1x G3x B47O B47T B47U B47K Check and, if required, replace EGR cooler

— Job: F1x F2x F3x G0x G1x G3x B47O B47T B47U B47K Check and, if required, replace EGR cooler

Description: F1x F2x F3x G0x G1x G3x B47O B47T B47U B47K Check and, if required, replace EGR cooler

Considered as a repeat visit No

Customer's own words

Vis. insp. of EGR cool. out. and EGR cool. inl. (not OK). Rep. ex. gas rec. cool. us. the press. sens. syst. test and note prod. date of both ex. gas rec. cool. 34 FRU
Flat rate unit I 00 70 004

Additional work cleaning the exhaust gas recirculation pipe 2 FRU
Flat rate unit I 00 70 509

F1x F2x F3x G0x G1x G3x B47O B47T B47U B47K Check and, if required, replace EGR cooler
Defect I 00 11 88 05 00


Hex Bolt with washer 1
Part I 07 11 9 905 750

Pipe union 2
Part I 11 71 7 799 853


exhaust cooler 1
Part I 11 71 8 596 444

Set of small parts 1
Part I 11 71 8 597 652

— 01/09/2020 Key 92264 Km Key 0



— 01/09/2020 Service 92264 Km 04784 Automatic
Autohaus
Krauth
GmbH&Co.
KG, Sinsheim



— 01/09/2020 Repair 92304 Km 04784 Job
Autohaus Job
Krauth GmbH Job
& Co. KG, Job
Sinsheim Job

— Job

Description:

Considered as a repeat visit No

Customer's own words

Service - standard scope 2 FRU

Flat rate unit I 00 00 105

— Job

Description:

Considered as a repeat visit No

Customer's own words

Engine oil service Flat rate unit I 00 00 610	3 FRU
--	-------

BMW Motoröl 0W-30 Longlife-04 Tankwagen Part I 83 21 2 405 674	Local	5
---	-------	---

Set oil-filter element Part I 11 42 8 575 211	1
--	---

— Job

Description:

Considered as a repeat visit No

Customer's own words

Microfilter service Flat rate unit I 00 00 616	2 FRU
---	-------

Microfilter/activated Carbon container Part I 64 11 9 237 555	1
--	---

— Job

Description:

Considered as a repeat visit No

Customer's own words

Flüssigkeitstände prüfen und bei Bedarf ergänzen Flat rate unit I 00 99 887	Local	0 FRU
--	-------	-------

Windshield washer antifreeze Part I 83125A1A166	1
--	---

— Job

Description:

Considered as a repeat visit No

Customer's own words

Additional work, top up AdBlue Flat rate unit I 00 00 667	2 FRU
--	-------

Diesel Exhaust Fluid AdBlue Part I 83 19 2 289 602	10
---	----

— Job

Description:

Considered as a repeat visit No

Customer's own words

Fahrzeugfußräume aussaugen und maschinelle Oberwäsche - ohne Berechnung Flat rate unit I 00 11 400	Local	0 FRU
--	-------	-------

—	11/10/2019	Key	61607 Km	04784	Key 0
---	------------	-----	----------	-------	-------

 -110 02/2021	 -110 506	 -110 506	 -110 506	 44000	 0 05/2021	 29000	 -110 02/2021	 0 05/2021
---	---	---	---	---	--	---	--	--

— 11/10/2019 Service 61607 Km 04784 Automatic
Autohaus
Krauth
GmbH&Co. KG
, Sinsheim

 -110 02/2021 ✓	 -110 02/2021 ✓	 -110 02/2021 ✓	 -110 02/2021 ✓	 44000	 0 05/2021	 29000	 -110 02/2021 ✓	 0 05/2021
---	---	---	---	--	---	--	--	---

— 11/10/2019 Repair 61611 Km 04784 Job
Autohaus
Krauth GmbH
& Co. KG ,
Sinsheim Job
Job
Job
Job
Job
Job

— Job

Description:

Considered as a repeat visit No

Customer's own words

Service - standard scope 2 FRU
Flat rate unit I 00 00 105

Engine oil service 3 FRU
Flat rate unit I 00 00 610

BMW Motoröl 0W-30 Longlife-04 Tankwagen Local 5
Part I 83 21 2 405 674

Satz Ölfiltereinsatz SB* Local 1
Part I FT11 42 8 575 2

Schmiermittel Local 1
Part I FT99 88 9 555 1

Montagereiniger Local 1
Part I FT99 88 9 555 2

Windshield washer antifreeze 1
Part I 83 12 2 468 609

— Job

Description:

Considered as a repeat visit No

Customer's own words

Microfilter service 2 FRU
Flat rate unit I 00 00 616

Mikrofilter SB* Local 1
Part I FT64 11 9 237 5

— Job

Description:

Considered as a repeat visit No

Customer's own words

Service - air filter element Flat rate unit 00 00 602	2 FRU
--	-------

Luftfiltereinsatz SB* Part FT13 71 8 511 6	Local	1
---	-------	---

— Job

Description:

Considered as a repeat visit No

Customer's own words

Service fuel filter Flat rate unit 00 00 604	3 FRU
---	-------

Kraftstofffilterpatrone SB* Part FT13 32 8 572 5	Local	1
---	-------	---

— Job

Description:

Considered as a repeat visit No

Customer's own words

Service, vehicle check Flat rate unit 00 00 624	6 FRU
--	-------

— Job

Description:

Considered as a repeat visit No

Customer's own words

AdBlue nachfüllen Flat rate unit 00 99 885	Local	3 FRU
---	-------	-------

Diesel Exhaust Fluid AdBlue Part 83 19 2 289 602	190
---	-----

— Job

Description:


Considered as a repeat visit No

Customer's own words

Fahrzeugfußräume aussaugen und maschinelle Oberwäsche - ohne Berechnung Flat rate unit 00 11 400	Local	0 FRU
---	-------	-------

Annahme über Auftragstasche Serviceassistenz Flat rate unit 00 11 499	Local	0 FRU
--	-------	-------

— 05/08/2019 Key 53350 Km 04784 Key 0

— 27/06/2019 Repair 30539 Km 01061 Job
Autohaus
Krauth GmbH

— Job

Description:

Considered as a repeat visit No

Customer's own words

Painting rear bumper panel	29 FRU
Flat rate unit 99 69 015	


Lackmaterial Stufe 2 AW 9969015, 143 dm2	Local	143
Part 9969015		

— 26/06/2019 Key

48193 Km

04784

Key 0



— 26/06/2019 Repair

53394 Km

 04784
 Autohaus
 Krauth GmbH
 & Co. KG,
 Sinsheim

 Job
 Job
 Job
 Job

— Job

Description:

Considered as a repeat visit No

Customer's own words

Fahrzeug-/Teileverbringung zur Lackiererei	Local	36 FRU
Flat rate unit 00 00 001		

Zeitzuschlag für eine Hauptarbeit	Local	2 FRU
Flat rate unit 41 99 033		

Performing vehicle test	2 FRU
Flat rate unit 00 00 556	

Performing vehicle test	3 FRU
Flat rate unit 00 00 556	

Replacing rear silencer	10 FRU
Flat rate unit 18 10 510	

Replacing one exhaust cover	1 FRU
Flat rate unit 18 10 580	

Working time without specification/exhaust system	1 FRU
Flat rate unit 18 99 000	

Working time without specification/exhaust system	1 FRU
Flat rate unit 18 99 000	

Replacing luggage compartment lid	35 FRU
Flat rate unit 41 62 500	

Removing and installing/replacing support for rear bumper panel	3 FRU
Flat rate unit 51 12 552	

Removing and installing/replacing rear centre bumper guide	2 FRU
Flat rate unit 51 12 825	

Removing and installing/replacing rear left or right bumper guide	2 FRU
---	-------

Flat rate unit | 51 12 828

Additional work with Park Distance Control Flat rate unit 66 20 602	5 FRU
--	-------

Body cavity sealing of luggage compartment lid Flat rate unit 97 62 500	5 FRU
--	-------

Kleinersatzteile Part VS99 99 9 999 9	Local	1
--	-------	---

Rubber mounting Part 18 20 8 577 081	2
---	---

Tailpipe trim, black chrome Part 18 30 7 610 636	2
---	---

Bracket, rear silencer right Part 18 30 8 516 521	1
--	---

Bracket for rear silencer, left Part 18 30 8 516 522	1
---	---

Rear silencer Part 18 30 8 584 182	1
---	---

Welding sleeve Part 18 30 8 584 244	1
--	---

Trunk lid Part 41 00 7 314 180	1
-------------------------------------	---

Expanding nut Part 51 12 7 020 321	2
---	---

Reinforcement, bumper, rear bottom Part 51 12 7 256 921	1
--	---

Carrier, bumper rear Part 51 12 7 256 927	1
--	---

Guide, centre rear Part 51 12 7 260 462	1
--	---

Guide for bumper, side, left Part 51 12 7 384 479	1
--	---

Trim strip, black Part 51 12 7 384 571	1
---	---

Panel, bumper, primed, rear Part 51 12 7 384 619	1
---	---

Left protection foil Part 51 12 7 400 299	1
--	---

Right protection foil Part 51 12 7 400 300	1
---	---

Cover, towing eye, primed, rear Part 51 12 7 428 436	1
---	---

Set, mounting, PDC/PMA sensor, rear Part 51 12 7 445 160	1
---	---

Boot lid/tailgate push-button Part 51 24 7 463 162	1
---	---

Blind rivet nut, flat headed Part 51 24 8 226 003	2
--	---

Adhesive tape Part 51 49 7 302 869	2
---	---

Water channel, left	1
---------------------	---

Part I 51 49 7 359 785

Water channel, right Part I 51 49 7 359 786	1
--	---

Rear reflector, rear left Part I 63 14 7 400 207	1
---	---

Rear reflector, rear right Part I 63 14 7 400 208	1
--	---

Number-plate light LED Part I 63 26 7 193 293	2
--	---

Ultrasonic sensor colour code Part I 66 20 2 220 666	1
---	---

Windshield washer antifreeze Part I 83 12 2 468 609	4
--	---

Cleaner R2 Part I 83 19 0 417 324	1
--------------------------------------	---

Repair kit, window glass, cold, 1 hour Part I 83 19 2 289 285	1
--	---

Adhesive set K6 Part I 83 19 2 317 925	1
---	---

— Job

Description:

Considered as a repeat visit No

Customer's own words

Lackmaterial Part I VT8888101	Local	1
----------------------------------	-------	---

— Job

Description:

Considered as a repeat visit No

Customer's own words

Fahrzeugfußräume aussaugen und maschinelle Oberwäsche - ohne Berechnung Flat rate unit I 00 11 400	Local	0 FRU
---	-------	-------

— Job

Description:

Considered as a repeat visit No

Customer's own words

Vorbereitung zur Lackierung Flat rate unit I 99 99 999	Local	1 FRU
---	-------	-------

Vorbereitung zur Lackierung Zusatz für Kunststoffteile Flat rate unit I 99 99 999	Local	1 FRU
--	-------	-------

Farbmuster und Farbtonfindung Flat rate unit I 99 99 999	Local	1 FRU
---	-------	-------

Farbtonangleich Mischanlage Flat rate unit I 99 99 999	Local	1 FRU
---	-------	-------

Heckklappe lackieren Flat rate unit I 99 99 999	Local	1 FRU
--	-------	-------

Abdeckkappe Abschleppöse hinten lackieren	Local	1 FRU
---	-------	-------

Flat rate unit | 99 99 999

Stoßfänger hinten lackieren
Flat rate unit | 99 99 999

Local

1 FRU

Kosten Mietfahrzeug vom 26.06.19 bis 28.06.19
Flat rate unit | 99 99 999

Local

1 FRU

— 13/06/2019 Repair 0 Km 01061 Job
Autohaus Job
Krauth GmbH
& Co. KG ,
Walldorf

— Job

Description:

Considered as a repeat visit No

Customer's own words

Painting rear bumper panel
Flat rate unit | 99 69 015

29 FRU

Lackmaterial Stufe 2 AW 9969015, 143 dm2
Part I 9969015

Local

143

— Job

Description:

Considered as a repeat visit No

Customer's own words

Painting luggage compartment lid
Flat rate unit | 99 62 530


13 FRU

Lackmaterial Stufe 2 AW 9962530, 106 dm2
Part I 9962530


Local

106


— 14/05/2019 Key 44814 Km 04784 Key 0



— 18/02/2019 Key 30474 Km 04784 Key 0



— 18/02/2019 Service 30474 Km 04784 Automatic
Autohaus
Krauth
GmbH&Co. KG
, Sinsheim



— 18/02/2019 Repair 30539 Km 04784 Job
 Autohaus Job
 Krauth GmbH Job
 & Co. KG, Job
 Sinsheim Job

— Job

Description:

Considered as a repeat visit No

Customer's own words

Ein Kanister Scheibenklar aus Sonderaktion zum nachfüllen verwenden - Local Rest ins Fzg. Flat rate unit I 00 99 886	0 FRU
--	-------

Windshield washer antifreeze Part I 83 12 2 409 032	1
--	---

— Job

Description:

Considered as a repeat visit No

Customer's own words

Service - standard scope Flat rate unit I 00 00 105	2 FRU
--	-------

— Job

Description:

Considered as a repeat visit No

Customer's own words

Microfilter service Flat rate unit I 00 00 616	2 FRU
---	-------

Mikrofilter SB* Part I FT64 11 9 237 5	Local	1
---	-------	---

— Job

Description:

Considered as a repeat visit No

Customer's own words

Engine oil service Flat rate unit I 00 00 610	3 FRU
--	-------

BMW Motoröl 0W-30 Longlife-04 Tankwagen Part I 83 21 2 405 674	Local	5
---	-------	---

Satz Ölfiltereinsatz* Part I FT11 42 8 575 2	Local	1
---	-------	---

Montagereiniger Part I FT99 88 9 555 2	Local	1
---	-------	---

— Job

Description:

Considered as a repeat visit No

Customer's own words

Fahrzeugfußräume aussaugen und maschinelle Oberwäsche - ohne Berechnung

Local

0 FRU

Flat rate unit I 00 11 400

—


18/05/2018

Service

2 Km

02699 Krauth, Hockenheim

Manual



—

17/05/2018

Repair

0 Km

02699 Autohaus Krauth GmbH & Co. KG , Hockenheim

Job

— Job

Description:

Considered as a repeat visit No

Customer's own words

Free pre-delivery check	9 FRU
Flat rate unit I 00 00 009	
Installing navigation map(s)	2 FRU
Flat rate unit I 65 90 600	
Supporting the voltage of the vehicle electrical system/recharging the vehicle electrical system battery	1 FRU
Flat rate unit I 61 21 528	
Windshield washer antifreeze	1
Part I 83 12 2 409 031	