

Thank you for ordering from us!

www.checkvin.eu

Vehicle

BMW 430i A, 185KW

WBA4D91010G191943



Development code

F36

Colour

carbon-schwarz

Actual integration level

F020-16-03-504

Start of warranty

26 May 2016

Delivery stop



Technical Campaigns are available.

Technical campaigns

Status	Campaign number	Description	Reservation
Open	10032620300	Replacing driver's airbag part III (SDI)  Delivery stop Local campaign number: -	

Warranty extension/VIN-based goodwill

There are no Campaigns for this vehicle.

Special information

There are no Campaigns for this vehicle.

Restrictions on the warranty

There are no restrictions on the warranty.

⚠ Market-specific restrictions are not currently displayed. Please check this in WDF/WXE via S-Gate.

Live Diagnosis

 There are no service solutions for Live Diagnosis.

Service contracts

No BSI contracts

Information on faults workshop/Service Consultation

There is no information on faults.

Navigation map

Note: The installed map cannot be clearly identified. Presumably one of the following maps is present in the vehicle.

Installed map	Enabling code (subscription)	Latest navigation map included in subscription	Latest navigation map subject to charge
Road Map EUROPE EVO 2019-2 (As of: 20 Mar 2023)	-	-	-
Road Map EUROPE EVO 2019-2 (As of: 20 Mar 2023)	-	-	-

Vehicle details

Vehicle type	Passenger car
Brand	BMW
Model	430I A
Body	COUPE
Vehicle identification number (last 7 digits)	G191943
Vehicle identification number (17 digits)	WBA4D91010G191943
Development code	F36
Steering	LL
Engine	B48O
Engine number	25569595
Exhaust re-treatment	EURO6, W, PI/CI, M, N1 I
Transmission	AUT
Transmission number	0396843ZSY
Head unit serial number	HB2140G7841394
Drive	HECK
Integration level, works	F020-16-03-504
Production date	21 Apr 2016
Production plant	Dingolfing
Delivery date	25 Apr 2016
Delivering retailer	Lemmens - Le Couter, Desselgem (Waregem), BE
National-market version	EUR
Paint code	416
Upholstery code	HAAT
Model code	4D01
Basic type	4D91

Lead type

4D01

Optional equipment

Optional equipment ex works:


01CA Selection of COP-relevant vehicles
 01CB CO2 equipment
 0205 Automatic transmission
 0230 EU-specific additional contents
 0258 Tyres with runflat properties
 02PA Locking wheel bolt
 02PE BMW LA wheel, M star spoke 400
 02VB Tyre pressure display
 02VF Adaptive M chassis
 0302 Alarm system
 0320 Deleted, model lettering
 0321 Exterior parts in vehicle colour
 0322 Comfort access system
 0337 M Sports package
 03AG Reversing camera
 03DZ Omission of additional lettering, outer
 0403 Glass roof, electrical
 0420 Sun protection glazing
 0423 Floor mats velours
 0430 Interior/outside mirror with auto dip
 0431 Interior mirror with automatic-dip
 0459 Seat adjustment, electric, with memory
 0465 Through-loading system
 0481 Sports seat
 0488 Lumbar support, driver and passenger
 0493 Storage compartment package
 0494 Seat heating driver/passenger
 04AE Armrest front, retractable
 04FU Fine wood Fineline anthracite/acc.strip
 04NE Blow-by heater
 0502 Headlight cleaning system
 0508 Park Distance Control (PDC)
 0521 Rain sensor
 0522 Xenon Light
 0534 Automatic air conditioning
 0544 Cruise control with brake function
 0548 Kilometre speedo
 0563 Lights package
 05AG Lane change warning
 05DA Passenger airbag deactivation
 0609 Navigation system Professional
 0688 Harman/Kardon surround sound system
 0698 Area-Code 2 for DVD
 06AC Intelligent emergency call
 06AE Teleservices
 06AK Connected Drive Services
 06AM Real-Time Traffic Information
 06NH Hands-free system with USB interface
 06WA Instrument panel with extended scope
 0710 M Leather steering wheel
 0715 M Aerodynamics package
 0760 High gloss shadow line
 0775 Headlining anthracite
 07LF Modell M Sport
 0868 Language version Dutch
 0886 On-board literature, Dutch
 08KA Oil service interval 24 mths / 30,000 km
 08S3 Automatic locking during starting
 09AA Outer skin protection
 A090 90 Ah AGM battery
 POLS Cloth cushion

Retrofitted optional equipment:

This vehicle has no retrofits.

Vehicle histories



	Date	Type	Vehicle mileage	Retailer	Overview
—	14/12/2023	Warranty	178951 Km	40866	Job: Rear final drive housing
— Job: Rear final drive housing					
Description: Rear final drive housing					
Considered as a repeat visit No					
Customer's own words					
Replace left and right radial shaft seal for driven shafts on rear axle differential Flat rate unit I 33 10 524					0 FRU
Rear final drive housing Defect I 33 11 00 48 00					
Repair kit, recessed nut, blue Part I 33 12 7 607 158					1
Shaft seal Part I 31 50 7 609 535					1
Sealing kit rear axle differential Part I 33 10 8 860 346					2
—					
04/12/2023 Key			178951 Km	40866	Key 0
 14000 03/2025  14000 03/2025  14000 03/2025  14000 03/2025  100000 03/2025  17000 03/2025  14000 03/2025  14000 03/2025  01/2024					
04/12/2023 Repair			178951 Km	40866 , Desselgem	Job Job
— Job					
Description:					
Considered as a repeat visit No					
Customer's own words					
Replace left and right radial shaft seal for driven shafts on rear axle differential Flat rate unit I 33 10 524					22 FRU
Repair kit insert nut Part I 33 12 7 607 158					1
Shaft seal Part I 31 50 7 609 535					1
Sealing kit rear axle differential Part I 33 10 8 860 346					2
Hypoid axle oil G1 Part I 83 22 2 295 532					2
— Job					
Description:					
Considered as a repeat visit No					
Customer's own words					
—					
18/11/2023 Key			178220 Km	40866	Key 0



— 20/03/2023 Key

165881 Km

Key 0






— 20/03/2023 Service

165880 Km

40866
Lemmens-Le
Couter ,
Desselgem
(Waregem)

Manual



— 20/03/2023 Warranty

165880 Km

40866

Job: Oil filter element – full-flow oil filter

— Job: Oil filter element – full-flow oil filter

Description: Oil filter element – full-flow oil filter

Considered as a repeat visit No

Customer's own words

Performing vehicle test 2 FRU
Flat rate unit I 00 00 556

Removing and installing/sealing or replacing complete full flow oil filter 0 FRU
Flat rate unit I 11 42 520

Oil filter element – full-flow oil filter
Defect I 11 42 14 01 99

Oil filter housing 1
Part I 11 42 8 596 283

Seal, air intake system 4
Part I 11 61 8 637 800

Heat exchanger 1
Part I 11 42 8 585 624

Gasket 2
Part I 13 54 8 632 344

Torx-bolt with washer 7
Part I 07 12 9 905 516

Gasket ring 1
Part I 07 11 9 963 132

ASA-Bolt 3
Part I 11 42 8 575 973

— 16/03/2023 Key

165880 Km

Key 0

 11000 04/2024    11000 04/2024 <td>  100000  -74 10.1 %  27000  34000 04/2026  01/2024 <td> 15/11/2022 Key 161455 Km 40866 Key 0 </td></td>	 100000  -74 10.1 %  27000  34000 04/2026  01/2024 <td> 15/11/2022 Key 161455 Km 40866 Key 0 </td>	15/11/2022 Key 161455 Km 40866 Key 0
 17000 04/2024    17000 04/2024 <td>  100000  01/2023  33000  41000 04/2026  12/2022 <td> 11/04/2022 Key 153479 Km 40866 Key 0 </td></td>	 100000  01/2023  33000  41000 04/2026  12/2022 <td> 11/04/2022 Key 153479 Km 40866 Key 0 </td>	11/04/2022 Key 153479 Km 40866 Key 0
 13000 07/2023  13000 440  13000 440  13000 440 <td>  100000  01/2023  39000  13000 07/2023  12/2022 <td> 11/04/2022 Service 153479 Km 40866 Automatic Lemmens-Le Couter , Desselgem (Waregem) </td></td>	 100000  01/2023  39000  13000 07/2023  12/2022 <td> 11/04/2022 Service 153479 Km 40866 Automatic Lemmens-Le Couter , Desselgem (Waregem) </td>	11/04/2022 Service 153479 Km 40866 Automatic Lemmens-Le Couter , Desselgem (Waregem)
 13000 06/2023 ✓  13000 06/2023  13000 06/2023  13000 06/2023 ✓ <td>  100000  12/2022  39000  13000 06/2023  11/2022 <td> 31/03/2021 Warranty 133656 Km 40866 Job: Coolant pipe/coolant line </td></td>	 100000  12/2022  39000  13000 06/2023  11/2022 <td> 31/03/2021 Warranty 133656 Km 40866 Job: Coolant pipe/coolant line </td>	31/03/2021 Warranty 133656 Km 40866 Job: Coolant pipe/coolant line

— Job: Coolant pipe/coolant line

Description: Coolant pipe/coolant line

Considered as a repeat visit No

Customer's own words



Supporting the voltage of the vehicle electrical system/recharging the vehicle electrical system battery Flat rate unit I 61 21 528	1 FRU
Performing vehicle test Flat rate unit I 00 00 006	0 FRU
Removing and installing/replacing cylinder head-expansion tank coolant line Flat rate unit I 17 12 512	0 FRU
Check the cooling system for watertightness with the special tool Flat rate unit I 17 00 509	0 FRU
Coolant pipe/coolant line Defect I 17 12 34 48 00	
Hose, cylinder head-expansion tank Part I 17 12 9 845 173	1

—	30/03/2021	Key	133656 Km	Key 0
---	------------	-----	-----------	-------

—	 14000 07/2022			 14000 452	 49000	 01/2023	 48000	 38000 1172	 07/2021
	11/01/2021 Key				129766 Km	40866	Key 0		
	 19000 07/2022			 19000 530	 50000	 -10 1.4 %	 50000	 44000 1250	 07/2021
	11/01/2021 Service				129766 Km	40866 Lemmens-Le Couter , Desselgem (Waregem)	Automatic		
	 19000 06/2022			 19000 06/2022	 50000	 01/2021 ✓	 50000	 44000 06/2024	 06/2021
—	 8000 07/2021	 8000 376	 8000 376	 8000 376	 48000	 01/2021	 49000	 8000 07/2021	 06/2021
	15/06/2020 Service				122683 Km	40866 Lemmens-Le Couter , Desselgem (Waregem)	Automatic		
	 8000 06/2021 ✓	 8000 06/2021 ✓	 8000 06/2021 ✓	 8000 06/2021 ✓	 48000	 12/2020 ✓	 49000	 8000 06/2021 ✓	 05/2021
	28/05/2020 Key				122671 Km	40866	Key 0		
	 8000 07/2021	 8000 393	 8000 393	 8000 393	 48000	 01/2021	 49000	 8000 07/2021	 -27 3.7 %
21/04/2020 Key				121439 Km	40866	Key 1			
 9000 07/2021	 9000 430	 9000 430	 9000 430	 60000	 01/2021	 60000	 9000 07/2021	 05/2020	
27/11/2019 Key				111022 Km	40866	Key 1			

—	19000 07/2021 19000 574 19000 574 19000 574	70000 01/2021 70000 19000 07/2021 05/2020			
	15/07/2019	Key	96833 Km	40866	Key 1
—	1600 06/2020 1600 316	70000 01/2021 70000 35000 06/2022 05/2020			
	15/07/2019	Service	96833 Km	40866	Automatic
				Lemmens-Le Couter , Desselgem (Waregem)	
—	1600 05/2020 ✓ 1600 05/2020 ✓	70000 12/2020 70000 35000 05/2022 04/2020			
	25/06/2019	Key	94974 Km	40866	Key 1
—	3500 06/2020 3500 336	70000 01/2021 80000 37000 06/2022 05/2020			
	16/05/2019	Key	92471 Km	40866	Key 1
—	6000 06/2020 6000 375	70000 01/2021 80000 39000 06/2022 -45 6.2 %			
	22/01/2019	Key	82035 Km		Key 1
—	17000 06/2020 17000 489	1000 04/2019 06/2022 8000 50000 06/2022 04/2019			
	22/01/2019	Service	82035 Km	40866	Automatic
				Lemmens-Le Couter , Desselgem (Waregem)	
—	17000 01/1970 0 01/1970 0 01/1970 17000 01/1970	1000 01/1970 ✓ 0 01/1970 ✓ 8000 01/1970 ✓ 50000 01/1970 0 01/1970			
	16/01/2019	Key	81348 Km	40866	Key 1

—	18000 06/2020 18000 495	1300 04/2019 9000 60000 06/2022 04/2019	65400 Km	40866	Key 1
—	120 06/2019 120 340 120 340 120 340	28000 04/2019 04/2019 28000 120 06/2019 04/2019	65400 Km	40866	Automatic
			Lemmens-Le Couter , Desselgem (Waregem)		
—	120 01/1970 ✓ 120 05/2019 ✓ 120 05/2019 ✓ 120 05/2019 ✓	28000 01/1970 0 01/1970 28000 01/1970 120 01/1970 ✓ 0 01/1970	58016 Km	40866	Key 1
—	8000 06/2019 8000 427 8000 427 8000 427	34000 04/2019 04/2019 34000 8000 06/2019 04/2019	48504 Km	40866	Key 1
—	17000 06/2019 17000 578 17000 578 17000 578	60000 04/2019 0 04/2019 60000 17000 06/2019 0 04/2019	41705 Km	40866	Key 1
—	24000 06/2019 24000 681 24000 681 24000 681	60000 04/2019 0 04/2019 70000 24000 06/2019 0 04/2019	32514 Km	40866	Key 1
—	490 04/2018 0 0 490 322	70000 04/2019 0 04/2019 70000 34000 04/2020 0 04/2019	32514 Km	40866	Automatic
			Lemmens-Le Couter nv Lemmens-Le Couter , Desselgem (Waregem)		





— 08/03/2017 Key

26450 Km

40866

Key 1



— 28/02/2017 Warranty

26125 Km

40866

Job: Rear wheel bearing

— Job: Rear wheel bearing

Description: Rear wheel bearing**Considered as a repeat visit** No**Customer's own words**

Performing vehicle test
Flat rate unit I 00 00 556 2 FRU

Supporting the voltage of the vehicle electrical system/recharging the
vehicle electrical system battery 1 FRU
Flat rate unit I 61 21 528

Replacing wheel bearings of left or right rear axle shaft 38 FRU
Flat rate unit I 33 41 151

Rear wheel bearing
Defect I 33 41 03 39 00

Angular contact ball bearing,radial 1
Part I 33 41 6 792 361

Lock Ring 1
Part I 07 11 9 934 755

Collar nut 1
Part I 33 40 6 799 223

Drive flange hub 1
Part I 33 41 6 867 265



Wheel bolt black 5
Part I 36 13 6 781 151

— 27/02/2017 Key

26125 Km

40866

Key 1





— 22/02/2017 Key

24350 Km

40866

Key 1



— 22/02/2017 Warranty

24350 Km

40866

Job: Control unit for integrated
chassis management (ICM)

— Job: Control unit for integrated chassis management (ICM)

Description: Control unit for integrated chassis management (ICM)

Considered as a repeat visit No

Customer's own words

Performing vehicle test Flat rate unit I 00 00 556	2 FRU
Supporting the voltage of the vehicle electrical system/recharging the vehicle electrical system battery Flat rate unit I 61 21 528	1 FRU
Vehicle diagnosis - carrying out the ABL Flat rate unit I 61 00 006	9 FRU
Control unit for integrated chassis management (ICM) Defect I 34 50 00 14 00	

—

20/02/2017

Key

24288 Km

40866

Key 1



9000

04/2018



0



0



9000

433



70000



0

04/2019



70000



42000

04/2020



0

04/2019

<https://myair-b2d.bmwgroup.com/air/faces/xhtml/fahrzeug/FahrzeugSingleView.xhtml?vin=WBA4D91010G191943>

11/11