

Thank you for ordering from us!
www.checkvin.eu

Vehicle

BMW 320D EFF A, 120KW

WBA8J91050K837170



Development code
Colour
Actual integration level
Start of warranty

F31
Jatoba metallic
F020-22-11-510
22 November 2016

Technical campaigns

Warranty extension/VIN-based goodwill

Special information

Restrictions on the warranty

There are no restrictions on the warranty.

⚠ Market-specific restrictions are not currently displayed. Please check this in WDF/WXE via S-Gate.

Live Diagnosis

i There are no service solutions for Live Diagnosis.

Service contracts

No BSI contracts

Information on faults workshop/Service Consultation

There is no information on faults.

Navigation map

Note: The installed map cannot be clearly identified. Presumably one of the following maps is present in the vehicle.

Installed map	Enabling code (subscription)	Latest navigation map included in subscription	Latest navigation map subject to charge
Road Map EUROPE EVO 2020-1 (As of: 20 Jan 2025)	-	-	-

Road Map EUROPE EVO 2020-1 (As of: 20 Jan 2025)	Enabling code valid for navigation maps with release date up to 31 Dec 2099 (SWID: 01200FFF).	Road Map EUROPE EVO 2025-1	-
---	---	----------------------------	---

Vehicle details

Vehicle type	Passenger car
Brand	BMW
Model	320D EFF A
Body	TOUR
Vehicle identification number (last 7 digits)	K837170
Vehicle identification number (17 digits)	WBA8J91050K837170
Development code	F31
Steering	LL
Engine	B47O
Engine number	57269801
Exhaust re-treatment	EURO6, W, PI/CI, M, N1 I
Transmission	AUT
Transmission number	0655118WC7
Head unit serial number	HB2241G8071450
Drive	HECK
Integration level, works	F020-16-11-502
Production date	10 Nov 2016
Production plant	Muenchen
Delivery date	22 Nov 2016
Delivering retailer	Autohaus Michael Schmidt, Starnberg, DE
National-market version	EUR
Paint code	B65
Upholstery code	LCDY
Model code	8J01
Basic type	8J91
Lead type	8J01


Optional equipment

Optional equipment ex works: 01CA Selection of COP-relevant vehicles 01CB CO2 equipment 0216 Hydro steering-servotronic 0230 EU-specific additional contents 0255 Sports leather steering wheel 0258 Tyres with runflat properties 02H2 BMW LA wheel, multi spoke 416 02TB Sport automatic gearbox	Retrofitted optional equipment: This vehicle has no retrofits.
--	---


02VB Tyre pressure display
0302 Alarm system
0320 Deleted, model lettering
0322 Comfort access system
03AT Roof rails aluminium satinated
03DZ Omission of additional lettering, outer
0402 Panorama glass roof
0417 Roller sun visor, rear door
0420 Sun protection glazing
0423 Floor mats velours
0428 Warning triangle and first aid kit
0430 Interior/outside mirror with auto dip
0431 Interior mirror with automatic-dip
0459 Seat adjustment, electric, with memory
0481 Sports seat
0488 Lumbar support, driver and passenger
0493 Storage compartment package
0494 Seat heating driver/passenger
04AE Armrest front, retractable
04FW Fine wood Fineline walnut/accent strip
0508 Park Distance Control (PDC)
0521 Rain sensor
0534 Automatic air conditioning
0544 Cruise control with brake function
0548 Kilometre speedo
0552 Adaptive LED headlight
0563 Lights package
0575 Additional 12V power socket
05A1 LED Fog lights
05AC High-beam assistant
05AG Lane change warning
05DA Passenger airbag deactivation
05DC Rear-seat headrests, folding
05DP Park Assist
0609 Navigation system Professional
0610 Head-up display
0654 DAB tuner
0676 HiFi speaker system
0698 Area-Code 2 for DVD
06AC Intelligent emergency call
06AE Teleservices
06AK Connected Drive Services
06AM Real-Time Traffic Information
06AN Concierge Services
06AP Remote Services
06NW Telephony with wireless charging
06WA Instrument panel with extended scope
06WD WLAN Hotspot
07LE Modell Luxury Line
07R7 Innovation package
07S2 Luxury Line
0801 National version Germany
0851 Language version German
0879 On-board literature, German
08KA Oil service interval 24 mths / 30,000 km
08R9 Refrigerant R1234yf
08TH Road sign detection
09AA Outer skin protection
09BM Navigation package Connected Drive
A090 90 Ah AGM battery
LEDE Leather equipment

Vehicle histories

	Date	Type	Vehicle mileage	Retailer	Overview
—	20/01/2025	Key	218190 Km	03846	Key 0



— 20/01/2025 Service 218190 Km 03846 Andreas Ehrh Potsdam GmbH&Co. KG , Potsdam Automatic



— 20/01/2025 Warranty 218191 Km 03846 Job: Fx Checking driver's airbag and replacing if necessary (SDI conversion)

— Job: Fx Checking driver's airbag and replacing if necessary (SDI conversion)

Description: Fx Checking driver's airbag and replacing if necessary (SDI conversion)


Considered as a repeat visit No

Customer's own words


Check steering wheel (airbag module not affected) 1 FRU
Flat rate unit I 00 76 854

Fx Checking driver's airbag and replacing if necessary (SDI conversion)
Defect I 00 32 55 03 00


— 14/01/2025 Key 217834 Km 03846 Remote KeyRead



— 04/01/2025 Key 217456 Km 03846 Key 0



— 10/04/2024 Key 195617 Km 03846 Key 0



— 10/04/2024 Repair 195619 Km 03846 , Job
Job
Job

— Job

Description:

Considered as a repeat visit No

Customer's own words

Unfallschaden laut Gutachten instandsetzen Flat rate unit 41 99 001	Local	0 FRU
Removing and installing/replacing trim strip on gutter strip at rear left or right Flat rate unit 51 13 819		4 FRU
Removing and installing/replacing strip on side window at rear left or right bottom Flat rate unit 51 36 540		1 FRU
Remove and install/replace left or right side sill trim panel Flat rate unit 51 71 947		4 FRU
Performing vehicle test Flat rate unit 00 00 556		2 FRU
Removing and installing left or right front door Flat rate unit 41 51 580		3 FRU
Removing and installing/replacing the sound insulation at the front left or right door Flat rate unit 51 48 560		7 FRU
Removing and installing/replacing left or right front outside door handle Flat rate unit 51 21 770		2 FRU
Removing and installing the exterior mirror on front left or right door Flat rate unit 51 16 501		4 FRU
Replacing rear left or right door Flat rate unit 41 52 500		45 FRU
Cavity preservation for left or right rear door Flat rate unit 97 52 500		5 FRU
Removing and installing/replacing rear left or right wheel arch cover Flat rate unit 51 71 541		4 FRU
Replacing right-hand rear light Flat rate unit 63 21 767		2 FRU
Removing and installing the fuel filler flap Flat rate unit 41 63 500		1 FRU
Removing and installing rear bumper panel Flat rate unit 51 12 656		5 FRU
Additional work with Park Distance Control Flat rate unit 66 20 600		1 FRU
Job time without allowance for / body Flat rate unit 41 99 000		36 FRU
Job time without allowance for / body Flat rate unit 41 99 000		6 FRU
Job time without allowance for / body Flat rate unit 41 99 000		24 FRU
Zeitzuschlag für eine Hauptarbeit Flat rate unit 51 99 900	Local	2 FRU
Supporting ledge right Part 51 77 7 240 874		1
Supporting ledge right Part 51 77 7 256 916		1
Supporting ledge right Part 51 77 7 256 918		1
Supporting ledge right Part 51 77 7 256 920		1

Sill trim, primed, right Part I 51 77 7 312 752	1
Sound insulation, door, front right Part I 51 48 7 263 412	1
Door, rear right Part I 41 00 9 628 766	1
Repair kit, window glass, cold, 1 hour Part I 83 19 2 289 285	1
Sound deadener, door Part I 41 00 7 164 849	1
Sound insulating door rear right Part I 51 48 7 263 414	1
Set, template, door, rear Part I 01 29 2 317 853	1
Expanding nut Part I 07 14 7 265 039	2
Clip Part I 51 33 7 140 714	4
Side window sun blind hook Part I 51 34 7 120 805	1
Clamp Part I 51 34 7 120 806	2
Sealing, window guide web, right Part I 51 35 7 258 304	1
Sealing, cover, column B right Part I 51 35 7 355 892	1
Seal, trim, C-pillar, right Part I 51 35 7 355 894	1
Door weatherstrip, rear right Part I 51 35 7 377 416	1
Channel seal, outer, door, rear right Part I 51 35 7 496 144	1
Clip with washer, natur Part I 51 41 8 224 768	16
Clamp Part I 51 42 9 146 595	4
Clamp Part I 51 13 7 157 096	10
Cover pot Part I 51 17 7 238 100	1
Cavity protection Part I 83 42 9 415 497	1
KLEINMATERIAL KARO Part I FT99 99 8 888 0	Local 1

— Job

Description:

Considered as a repeat visit No

Customer's own words

Fahrzeugreinigung 1

Local

6 FRU

Flat rate unit | 41 99 002

— Job

Description:

Considered as a repeat visit No

Customer's own words

Lackierung Stufe 3 Seitenwand hinten rechts 00000000 Flat rate unit 99 99 999	Local	45 FRU
Lackierung Stufe 2 Verkleidung Schweller recht s 00000000 Flat rate unit 99 99 999	Local	6 FRU
Lackierung Stufe 3 Abdeckung Einstieg rechts 00000000 Flat rate unit 99 99 999	Local	11 FRU
Lackierung Stufe 3 Tür vorn rechts 00000000 Flat rate unit 99 99 999	Local	23 FRU
Lackierung Stufe 2 Tür hinten rechts 00000000 Flat rate unit 99 99 999	Local	12 FRU

— 02/02/2024 Key 188410 Km 03846 Key 0



12000

05/2025





12000

05/2025





43000

01/2026





50000

05/2027



38000

05/2027



01/2026

— 01/02/2024 Key 188371 Km 03846 Key 0



12000

05/2025





12000

05/2025





43000

01/2026





50000

05/2027



38000

05/2027



01/2026

— 30/01/2024 Key 188201 Km 03846 Key 0



13000

05/2025





13000

05/2025





43000

-60
8.2 %





50000

05/2027



39000

05/2027



-60
8.2 %

— 30/01/2024 Service 188201 Km 03846 Andreas Ehrl Potsdam GmbH&Co. KG , Potsdam Automatic



13000

05/2025





13000

05/2025





43000

12/2023
✓





50000

05/2027



39000

05/2027



12/2023

— 30/01/2024 Repair 188202 Km 03846 Andreas Ehrl Potsdam GmbH & Co. KG , Potsdam Job
Job
Job
Job
Job
Job

— Job

https://myair-b2d.bmwgroup.com/air/faces/xhtml/fahrzeug/FahrzeugSingleView.xhtml?vin=WBA8J91050K837170

7/31

Description:

Considered as a repeat visit No

Customer's own words

Kunde wünscht keine Serviceberatung am Fahrzeug gewünscht Flat rate unit I 01 00 001	Local	0 FRU
---	-------	-------

— Job

Description:

Considered as a repeat visit No

Customer's own words

Vorbereitung und Durchführung AU HU bei der DEKRA #TÜV2 Flat rate unit I 00 12 990	Local	2 FRU
---	-------	-------

— Job

Description:

Considered as a repeat visit No

Customer's own words

Brake fluid service Flat rate unit I 00 00 618		4 FRU
---	--	-------

Brake fluid DOT4, low-viscosity EU Part I 83135A82511		1
--	--	---

— Job

Description:

Considered as a repeat visit No

Customer's own words

Service - standard scope Flat rate unit I 00 00 105		2 FRU
--	--	-------

— Job

Description:

Considered as a repeat visit No

Customer's own words

Replace left and right wiper blade Flat rate unit I 61 61 541		1 FRU
--	--	-------

Set of wiper blades Part I 61615A43585		1
---	--	---

— Job

Description:

Considered as a repeat visit No

Customer's own words

Windshield washer antifreeze Part I 83125A85517		2
--	--	---

— Job

Description:

Considered as a repeat visit No


Customer's own words

Abgas-und Hauptuntersuchung bei der DEKRA (durchlaufender Po
Flat rate unit | 99 99 999


Local

1 FRU

— 15/12/2023 Key 185690 Km 03846 Remote KeyRead



— 16/08/2023 Key 177378 Km Key 0



— 16/08/2023 Warranty 177382 Km 03846 Job: F1x F2x F3x G0x G1x G3x B47O B47K B47U B47T Replacing EGR cooler (high-temperature)

— Job: F1x F2x F3x G0x G1x G3x B47O B47K B47U B47T Replacing EGR cooler (high-temperature)

Description: F1x F2x F3x G0x G1x G3x B47O B47K B47U B47T Replacing EGR cooler (high-temperature)

Considered as a repeat visit No

Customer's own words

Replace exhaust gas recirculation cooler, including exhaust gas recirculation valve
Flat rate unit | 00 74 057 25 FRU

Additional work: run function test for pressure sensor system
Flat rate unit | 00 74 636 3 FRU

Additional work: enter component identification of new exhaust gas recirculation cooler in diagnostic system
Flat rate unit | 00 74 637 1 FRU

Additional work cleaning the exhaust gas recirculation pipe
Flat rate unit | 00 74 638 2 FRU

F1x F2x F3x G0x G1x G3x B47O B47K B47U B47T Replacing EGR cooler (high-temperature)
Defect | 00 11 13 07 00

Exhaust gas radiator high temperature
Part | 11 71 7 822 347 1

EGR small parts set
Part | 11 71 8 490 640 1

Pipe union
Part | 11 71 7 799 853 2

Holder
Part | 61 13 1 369 832 1

Connection piece
Part | 11 65 7 803 012 1

Acoustic cover front
Part | 11 14 8 490 577 1

O-ring
Part | 11 61 8 512 681 1

— 16/06/2023 Key 174256 Km Remote KeyRead



29000

05/2025





29000

05/2025





60000

12/2023



80000

05/2027



60000

12/2023

— 23/05/2023 Key 173532 Km Key 0



-2200
7.9 %

01/2024



-2200

01/2024



-2200

01/2024



-2200

01/2024



60000

12/2023



3800

01/2024



-2200
3.9 %

12/2023

— 23/05/2023 Service 173532 Km 03846 Andreas Ehrl Potsdam GmbH&Co. KG , Potsdam Automatic



-2200

01/2024

✓



-2200

01/2024

✓



-2200

01/2024

✓



-2200

01/2024

✓



60000

12/2023



3800

01/2024

✓



-2200

12/2023

✓

— 23/05/2023 Repair 173536 Km 03846 Andreas Ehrl Potsdam GmbH & Co. KG , Potsdam Job
Job
Job
Job
Job
Job
Job
Job
Job

— Job

Description:
Considered as a repeat visit No
Customer's own words

Fahrzeugannahme durch Service- assistentin Flat rate unit I 01 00 002	Local	0 FRU
--	-------	-------

— Job

Description:
Considered as a repeat visit No
Customer's own words

Engine oil service Flat rate unit I 00 00 610		3 FRU
--	--	-------

Castrol Edge 0W30 BMW LL19FE Part I FT91 70 0 000 0	Local	5
--	-------	---

Set oil-filter element Part I 11 42 8 575 211		1
--	--	---

— Job

Description:
Considered as a repeat visit No
Customer's own words

https://myair-b2d.bmwgroup.com/air/faces/xhtml/fahrzeug/FahrzeugSingleView.xhtml?vin=WBA8J91050K837170

10/31

Service - standard scope
Flat rate unit I 00 00 105

2 FRU

— Job

Description:

Considered as a repeat visit No

Customer's own words

Microfilter service	2 FRU
Flat rate unit I 00 00 616	

Microfilter/activated Carbon container	1
Part I 64 11 9 237 555	

— Job

Description:

Considered as a repeat visit No

Customer's own words

Service fuel filter	3 FRU
Flat rate unit I 00 00 604	

Fuel filter cartridge	1
Part I 13 32 7 822 497	

— Job

Description:

Considered as a repeat visit No

Customer's own words

Service - air filter element	2 FRU
Flat rate unit I 00 00 602	

Air filter element	1
Part I 13 71 8 511 668	

— Job

Description:

Considered as a repeat visit No

Customer's own words

Service, vehicle check	6 FRU
Flat rate unit I 00 00 624	

— Job

Description:

Considered as a repeat visit No

Customer's own words

Service, rear brakes	7 FRU
Flat rate unit I 00 00 614	

Bremsklotzpaste	Local	2
Part I FT83 19 2 158 8		

Repair kit, brake pads	1
Part I 34 21 8 855 013	

Brake-pad sensor, rear	1
Part I 34 35 6 792 292	

Brake cleaner acetone-free
Part I 83 19 2 413 695

1

— Job

Description:

Considered as a repeat visit No

Customer's own words

Removing and installing or replacing both rear brake discs Flat rate unit I 34 21 932	4 FRU
Inner hex bolt Part I 34 21 1 161 806	2
Brake disc, ventilated Part I 34 21 6 864 900	2
Hex screw with collar Part I 34 20 6 850 536	4

— Job

Description:

Considered as a repeat visit No

Customer's own words

Hinweise: Flat rate unit I 00 11 222	Local	0 FRU
---	-------	-------

— 23/05/2023 Warranty 173536 Km 03846 Job: Fx Gx B37 B47 B57 N47 N57
Check coolant level (EGR)

— Job: Fx Gx B37 B47 B57 N47 N57 Check coolant level (EGR)

Description: Fx Gx B37 B47 B57 N47 N57 Check coolant level (EGR)

Considered as a repeat visit No

Customer's own words

Flat rate unit I 00 73 830	1 FRU
Flat rate unit I 00 73 827	4 FRU
Fx Gx B37 B47 B57 N47 N57 Check coolant level (EGR) Defect I 11 71 90 08 00	

— 19/05/2023 Key 173507 Km Remote KeyRead



— 26/01/2023 Warranty 165614 Km 03846 Job: F1x F2x F3x B47O B47K B47U Programming control units (DDE)
B47U Programming control units (DDE)
Job: G0x G1x G2x G3x B57 Check and if necessary replace exhaust-gas recirculation cooler

— Job: F1x F2x F3x B47O B47K B47U Programming control units (DDE)

Description: F1x F2x F3x B47O B47K B47U Programming control units (DDE)

Considered as a repeat visit No

Customer's own words

Program control units 8 FRU
Flat rate unit I 00 71 907

Additional work: check CCM Check Control message and coolant level 1 FRU
Flat rate unit I 00 73 678

F1x F2x F3x B47O B47K B47U Programming control units (DDE)
Defect I 00 13 50 03 00

- Job: G0x G1x G2x G3x B57 Check and if necessary replace exhaust-gas recirculation cooler

Description: G0x G1x G2x G3x B57 Check and if necessary replace exhaust-gas recirculation cooler

Considered as a repeat visit No


Customer's own words

Check exhaust gas recirculation cooler (cooler outlet and inlet side), fill coolant and carry out cooling system bleeding routine 12 FRU
Flat rate unit I 00 68 860

G0x G1x G2x G3x B57 Check and if necessary replace exhaust-gas recirculation cooler
Defect I 11 71 90 05 00

Gasket Steel 1
Part I 11 71 8 579 364

- 24/01/2023 Key 165610 Km Key 0



- 24/01/2023 Repair 165614 Km 03846 Andreas Job
Ehrl Potsdam Job
GmbH & Co. Job
KG , Potsdam Job

- Job

Description:

Considered as a repeat visit No

Customer's own words

Service consultation at vehicle with Service Ticket 1 FRU
Flat rate unit I 00 52 052

- Job

Description:

Considered as a repeat visit No

Customer's own words

Troubleshooting electrical/electronic system 2 FRU
Flat rate unit I 61 00 009

Replacing the washer fluid reservoir for the window washer system 9 FRU
Flat rate unit I 61 71 561

Job time without allowance for / electrical system 3 FRU
Flat rate unit I 61 99 000

Windshield washer antifreeze 2
Part I 83125A1A166

Expanding rivet
Part I 51 16 1 881 149

— Job

Description:

Considered as a repeat visit No

Customer's own words

Replacing all wiper blades Flat rate unit I 61 61 547	1 FRU
--	-------

Set of wiper blades Part I 61615A43585	1
---	---

Wiper blade Part I 61 62 7 356 763	1
---------------------------------------	---

— Job

Description:

Considered as a repeat visit No


Customer's own words

Hinweise: Flat rate unit I 00 11 222	Local	0 FRU
---	-------	-------

— 07/01/2022 Key

142266 Km


Key 0



— 16/12/2021 Key

139833 Km

Key 0




— 16/12/2021 Service

139833 Km

03846 Andreas
Ehrl Potsdam
GmbH&Co. KG
, Potsdam

Automatic



— 16/12/2021 Repair

139833 Km

03846 Andreas
Ehrl Potsdam
GmbH & Co.
KG , PotsdamJob
Job
Job
Job
Job
Job

— Job

Description:

Considered as a repeat visit No

Customer's own words

Kunde wünscht keine Serviceberatung am Fahrzeug Flat rate unit I 01 00 001	Local	0 FRU
---	-------	-------

Windshield washer antifreeze Part I 83125A1A166		2
--	--	---

— Job

Description:**Considered as a repeat visit** No**Customer's own words**

Brake fluid service Flat rate unit I 00 00 618		4 FRU
---	--	-------

Brake fluid DOT4 LV, low viscosity Part I 83 13 2 405 977		1
--	--	---

— Job

Description:**Considered as a repeat visit** No**Customer's own words**

Service - standard scope Flat rate unit I 00 00 105		2 FRU
--	--	-------

— Job

Description:**Considered as a repeat visit** No**Customer's own words**

Performing vehicle test Flat rate unit I 00 00 556		2 FRU
---	--	-------

Supporting the voltage of the vehicle electrical system/recharging the vehicle electrical system battery Flat rate unit I 61 21 528		1 FRU
---	--	-------

Replacing the washer fluid reservoir for the window washer system Flat rate unit I 61 71 561		9 FRU
---	--	-------

Expanding rivet Part I 51 16 1 881 149		3
---	--	---

— Job

Description:**Considered as a repeat visit** No**Customer's own words**

Vorbereitung und Durchführung AU HU Flat rate unit I 00 12 990	Local	2 FRU
---	-------	-------

— Job

Description:**Considered as a repeat visit** No**Customer's own words**

Fahrgastraum aussaugen Türeinstiege reinigen Softtec-Wäsche ohne Berechnung Flat rate unit I 09 99 007	Local	0 FRU
--	-------	-------

— Job

Description:

Considered as a repeat visit No

Customer's own words

Abgas-und Hauptuntersg. bei der DEKRA #HU2 00000000
Flat rate unit | 99 99 999


Local

1 FRU

— 30/06/2021 Key

124761 Km


Key 0



— 20/11/2020 Key

114137 Km

Key 0




— 20/11/2020 Service

114137 Km

03846 Andreas
Ehrl Potsdam,
Potsdam

Automatic



— 20/11/2020 Repair

114143 Km

03846 Andreas
Ehrl Potsdam
GmbH & Co.
KG , Potsdam

Job
Job
Job
Job
Job
Job
Job
Job
Job

— Job

Description:

Considered as a repeat visit No

Customer's own words

Service consultation at vehicle with Service Ticket
Flat rate unit | 00 52 052

0 FRU

— Job

Description:

Considered as a repeat visit No

Customer's own words

Engine oil service
Flat rate unit | 00 00 610

3 FRU

CASTROL Edge BMW LL04 Professional SAE 5W-30 Part I FT91 70 0 000 5	Local	5
Set oil-filter element Part I 11 42 8 575 211		1
— Job		
Description:		
Considered as a repeat visit No		
Customer's own words		
Service - standard scope Flat rate unit I 00 00 105		2 FRU
— Job		
Description:		
Considered as a repeat visit No		
Customer's own words		
Microfilter service Flat rate unit I 00 00 616		2 FRU
Microfilter/activated Carbon container Part I 64 11 9 237 555		1
— Job		
Description:		
Considered as a repeat visit No		
Customer's own words		
Service - air filter element Flat rate unit I 00 00 602		2 FRU
Air filter element Part I 13 71 8 511 668		1
— Job		
Description:		
Considered as a repeat visit No		
Customer's own words		
Service fuel filter Flat rate unit I 00 00 604		3 FRU
Fuel filter cartridge Part I 13 32 8 572 522		1
— Job		
Description:		
Considered as a repeat visit No		
Customer's own words		
Hinweise: Flat rate unit I 00 11 222	Local	0 FRU
Service, vehicle check Flat rate unit I 00 00 624		6 FRU
— Job		

Description:

Considered as a repeat visit No

Customer's own words

Replace left and right wiper blade	1 FRU
Flat rate unit I 61 61 541	

Set of wiper blades	1
Part I 61 61 2 241 375	

— Job

Description:

Considered as a repeat visit No

Customer's own words

Motor- und Motorraum reinigen (Sonderpreis)	Local	4 FRU
Flat rate unit I 00 11 999		

— Job


Description:

Considered as a repeat visit No

Customer's own words

Fahrgastraum aussaugen Türeinstiege reinigen Softtec-Wäsche ohne Berechnung	Local	0 FRU
Flat rate unit I 09 99 007		

— 17/01/2020 Key 90594 Km 03846 Key 0



— 17/01/2020 Repair 90598 Km 03846 Andreas Job
Ehrl Potsdam Job
GmbH & Co. Job
KG, Potsdam Job

— Job

Description:

Considered as a repeat visit No

Customer's own words

Kunde wünscht keine Serviceberatung am Fahrzeug	Local	0 FRU
Flat rate unit I 01 00 001		

— Job

Description:

Considered as a repeat visit No

Customer's own words

Fahrgastraum aussaugen Türeinstiege reinigen Softtec-Wäsche ohne Berechnung	Local	0 FRU
Flat rate unit I 09 99 007		

— Job

Description:

Considered as a repeat visit No

Customer's own words

— Job

Description:

Considered as a repeat visit No

Customer's own words

—	17/01/2020 Repair	87528 Km	03846 Andreas Ehrl Potsdam GmbH & Co. KG , Potsdam	Job Job Job Job Job
---	-------------------	----------	---	---------------------------------

— Job

Description:

Considered as a repeat visit No

Customer's own words

Service consultation at vehicle with Service Ticket	0 FRU
Flat rate unit I 00 52 052	

— Job

Description:

Considered as a repeat visit No

Customer's own words

Engine oil service	-3 FRU
Flat rate unit I 00 00 610	

Service - standard scope	-2 FRU
Flat rate unit I 00 00 105	

CASTROL Edge BMW LL04 Professional SAE 5W-30	Local	-5
Part I FT91700000530		

Set oil-filter element	-1
Part I 11 42 8 575 211	

— Job

Description:

Considered as a repeat visit No

Customer's own words

Microfilter service	-2 FRU
Flat rate unit I 00 00 616	

Microfilter/activated Carbon container	-1
Part I 64 11 9 237 555	

— Job

Description:

Considered as a repeat visit No

Customer's own words

Brake fluid service	-4 FRU
Flat rate unit I 00 00 618	

Brake fluid DOT4 LV, low viscosity	-1
------------------------------------	----

Part I 83 13 2 405 977

— Job

Description:

Considered as a repeat visit No

Customer's own words

Vorbereitung und Durchführung AU & HU beim TÜV NORD Flat rate unit I 00 12 990	Local	-2 FRU
---	-------	--------

Abgas- und Hauptunter- suchung durch DEKRA Part I VSHUGEBMITAUDEKRA	Local	-1
--	-------	----

— Job

Description:

Considered as a repeat visit No

Customer's own words

17/01/2020 Repair	87528 Km	03846 Andreas Ehrl Potsdam GmbH & Co. KG, Potsdam	Job Job Job Job Job
-------------------	----------	--	---------------------------------

— Job

Description:

Considered as a repeat visit No

Customer's own words

Service consultation at vehicle with Service Ticket Flat rate unit I 00 52 052	0 FRU
---	-------

— Job

Description:

Considered as a repeat visit No

Customer's own words

Engine oil service Flat rate unit I 00 00 610	3 FRU
--	-------

Service - standard scope Flat rate unit I 00 00 105	2 FRU
--	-------

CASTROL Edge BMW LL04 Professional SAE 5W-30 Part I FT91700000530	Local	5
--	-------	---

Set oil-filter element Part I 11 42 8 575 211	1
--	---

— Job

Description:

Considered as a repeat visit No

Customer's own words

Microfilter service Flat rate unit I 00 00 616	2 FRU
---	-------

Microfilter/activated Carbon container Part I 64 11 9 237 555	1
--	---

— Job

Description:

Considered as a repeat visit No

Customer's own words

Brake fluid service Flat rate unit I 00 00 618	4 FRU
---	-------

Brake fluid DOT4 LV, low viscosity Part I 83 13 2 405 977	1
--	---

— Job

Description:

Considered as a repeat visit No

Customer's own words

— Job

Description:

Considered as a repeat visit No

Customer's own words

17/01/2020 Repair	87528 Km	03846 Andreas Ehrl Potsdam GmbH & Co. KG, Potsdam	Job
-------------------	----------	---	-----

— Job

Description:

Considered as a repeat visit No

Customer's own words

Vorbereitung und Durchführung AU HU beim TÜV NORD Flat rate unit I 00 12 990	Local	2 FRU
---	-------	-------

Abgas- und Hauptunter- suchung durch DEKRA Part I VSHUGEBMITA	Local	1
--	-------	---

17/01/2020 Warranty	90598 Km	03846	Job: F1x F2x F3x F4x G0x G1x G3x B47 Check and if required replace exhaust-gas recirculation cooler
---------------------	----------	-------	---

— Job: F1x F2x F3x F4x G0x G1x G3x B47 Check and if required replace exhaust-gas recirculation cooler

Description: F1x F2x F3x F4x G0x G1x G3x B47 Check and if required replace exhaust-gas recirculation cooler

Considered as a repeat visit No

Customer's own words

Check label/ replace exhaust-gas recirculation cooler and remount exhaust-gas recirculation valve; clean exhaust-gas recirculation pipe Flat rate unit I 00 68 166	30 FRU
---	--------

Performing additional work for pressure sensor function Flat rate unit I 00 68 742	3 FRU
---	-------

F1x F2x F3x F4x G0x G1x G3x B47 Check and if required replace
exhaust-gas recirculation cooler
Defect I 00 11 40 05 00

exhaust cooler
Part I 11 71 8 596 444

1

Set of small parts
Part I 11 71 8 597 652

1

Pipe union
Part I 11 71 7 799 853

2

O-ring
Part I 11 61 8 512 681

1

Oval head screw
Part I 35 21 7 685 343


2

— 29/11/2019 Key

87528 Km

03846

Key 0




— 29/11/2019 Service

87528 Km

03846 Andreas
Ehrl Potsdam
GmbH&Co. KG
, Potsdam

Automatic



— 29/11/2019 Repair

87532 Km

03846 Andreas
Ehrl Potsdam
GmbH & Co.
KG , Potsdam

Job
Job
Job
Job
Job
Job
Job
Job
Job
Job
Job
Job

— Job

Description:

Considered as a repeat visit No

Customer's own words

Service consultation at vehicle with Service Ticket
Flat rate unit I 00 52 052

0 FRU

— Job

Description:

Considered as a repeat visit No

Customer's own words

Service, front brakes		6 FRU
Flat rate unit I 00 00 612		

Bremsklotzpaste	Local	2
Part I FT83192158851		

Repair kit, brake pads asbestos-free		1
Part I 34 11 6 874 331		

Brake pad wear sensor, front left		1
Part I 34 35 6 792 289		

Brake cleaner acetone-free		1
Part I 83 19 2 413 695		

— Job

Description:

Considered as a repeat visit No

Customer's own words

Removing and installing or replacing both front brake discs		3 FRU
Flat rate unit I 34 11 613		

Brake disc, ventilated		2
Part I 34 11 6 792 217		

Inner hex bolt		2
Part I 34 21 1 161 806		

Torx screw with washer		4
Part I 34 10 6 864 424		

— Job

Description:

Considered as a repeat visit No

Customer's own words

Service, rear brakes		7 FRU
Flat rate unit I 00 00 614		

Bremsklotzpaste	Local	2
Part I FT83192158851		

Repair kit, brake pads asbestos-free		1
Part I 34 21 6 873 093		

Brake-pad sensor, rear		1
Part I 34 35 6 792 292		

Brake cleaner acetone-free		1
Part I 83 19 2 413 695		

— Job

Description:

Considered as a repeat visit No

Customer's own words

Fahrgastraum aussaugen Türeinstiege reinigen Softtec-Wäsche ohne Berechnung	Local	0 FRU
Flat rate unit I 09 99 007		

— Job

Description:

Considered as a repeat visit No

Customer's own words

— Job

Description:

Considered as a repeat visit No

Customer's own words

— Job

Description:

Considered as a repeat visit No

Customer's own words

— Job

Description:

Considered as a repeat visit No

Customer's own words

— Job

Description:

Considered as a repeat visit No

Customer's own words

— Job

Description:

Considered as a repeat visit No

Customer's own words

— Job

Description:

Considered as a repeat visit No

Customer's own words

— Job

Description:

Considered as a repeat visit No

Customer's own words

— Job

Description:

Considered as a repeat visit No

Customer's own words

—	29/11/2019	Repair	87528 Km	03846 Andreas Ehrl Potsdam GmbH & Co. KG , Potsdam	Job Job Job Job Job
---	------------	--------	----------	---	---------------------------------

— Job

Description:

Considered as a repeat visit No

Customer's own words

Service consultation at vehicle with Service Ticket	0 FRU
Flat rate unit I 00 52 052	

— Job

Description:

Considered as a repeat visit No

Customer's own words

Engine oil service	3 FRU
Flat rate unit I 00 00 610	

Service - standard scope	2 FRU
Flat rate unit I 00 00 105	

CASTROL Edge BMW LL04 Professional SAE 5W-30	Local	5
Part I FT91 70 0 000 5		

Set oil-filter element	1
Part I 11 42 8 575 211	

— Job

Description:

Considered as a repeat visit No

Customer's own words

Microfilter service	2 FRU
Flat rate unit I 00 00 616	

Microfilter/activated Carbon container	1
Part I 64 11 9 237 555	

— Job

Description:

Considered as a repeat visit No

Customer's own words

Brake fluid service	4 FRU
Flat rate unit I 00 00 618	

Brake fluid DOT4 LV, low viscosity	1
Part I 83 13 2 405 977	

— Job

Description:


Considered as a repeat visit No

Customer's own words


Vorbereitung und Durchführung AU HU beim TÜV NORD	Local	2 FRU
Flat rate unit I 00 12 990		

Abgas- und Hauptunter- suchung durch DEKRA	Local	1
Part I VSHUGEBMITA		

—	26/10/2018 Key	60044 Km	Key 0
---	----------------	----------	-------



— 26/10/2018 Service 60044 Km 03846 Andreas Ehrl Potsdam GmbH&Co. KG , Potsdam Automatic



— 26/10/2018 Repair 60048 Km 03846 Andreas Ehrl Potsdam GmbH & Co. KG , Potsdam

Job
Job
Job
Job
Job
Job
Job
Job
Job
Job
Job
Job

— Job

Description:

Considered as a repeat visit No

Customer's own words

— Job

Description:

Considered as a repeat visit No

Customer's own words

Castrol Edge 0W30 CASTROL
Part I FT91700000030

Local

5

Set oil-filter element
Part I 11 42 8 575 211

1

— Job

Description:

Considered as a repeat visit No

Customer's own words

— Job

Description:

Considered as a repeat visit No

Customer's own words

— Job

Description:

Considered as a repeat visit No

Customer's own words

Microfilter/activated Carbon container
Part I 64 11 9 237 555

1

— Job

Description:

Considered as a repeat visit No

Customer's own words

Air filter element
Part I 13 71 8 511 668

1

— Job

Description:

Considered as a repeat visit No

Customer's own words

Fuel filter cartridge
Part I 13 32 8 572 522

1

— Job

Description:

Considered as a repeat visit No

Customer's own words

Set of wiper blades
Part I 61 61 2 241 375

1

— Job

Description:

Considered as a repeat visit No

Customer's own words

— Job

Description:

Considered as a repeat visit No

Customer's own words

— Job

Description:

Considered as a repeat visit No

Customer's own words

— Job

Description:

Considered as a repeat visit No

Customer's own words

— Job

Description:

Considered as a repeat visit No

Customer's own words

— 15/02/2018 Key 40173 Km 23470 Key 0

									
17000	17000	17000	17000	42000	0	24000	17000		0
11/2019	652	652	652		11/2019		11/2019		11/2019

— 15/02/2018 Repair 40188 Km 23470 Spaett GmbH & Co. KG , Freising Job
Job
Job
Job

— Job

Description:

Considered as a repeat visit No

Customer's own words

Endkontrolle durchgeführt
Flat rate unit I 00 11 800

Local

0 FRU

— Job

Description:

Considered as a repeat visit No

Customer's own words

— Job

Description:

Considered as a repeat visit No

Customer's own words

— Job

Description:

Considered as a repeat visit No

Customer's own words

— 15/02/2018 Warranty 40188 Km 23470 Job: Exhaust gas recirculation valve (EGR)

— Job: Exhaust gas recirculation valve (EGR)

Description: Exhaust gas recirculation valve (EGR)

Considered as a repeat visit No

Customer's own words

Performing vehicle test
Flat rate unit I 00 00 006

4 FRU

Supporting the voltage of the vehicle electrical system/recharging the
vehicle electrical system battery
Flat rate unit I 61 21 528

1 FRU

Vehicle diagnosis - carrying out the ABL
Flat rate unit I 61 00 006

1 FRU

Replacing exhaust gas recirculation valve
Flat rate unit I 11 71 501

7 FRU

Programming/encoding control unit(s) including deleting fault memories 4 FRU
Flat rate unit I 61 00 730

Exhaust gas recirculation valve (EGR)
Defect I 11 71 01 83 99

EGR-valve 1
Part I 11 71 8 513 132

Gasket Steel 1
Part I 11 71 8 579 364

Hose clamp 2
Part I 16 12 1 176 918

—	03/11/2017	Key		30084 Km	03846		Key 0		
									
-3300	0	-3300	0	45000	0	30000	24000		0
11/2018		392			11/2019		11/2020		11/2019

—	03/11/2017	Service	30084 Km	03846 Andreas	Manual				
				Ehrl Potsdam,					
				Potsdam					
									
✓		✓							

—	03/11/2017	Repair	30084 Km	03846 Andreas	Job
				Ehrl Potsdam	Job
				GmbH & Co.	Job
				KG , Potsdam	Job
					Job
					Job

— Job

Description:

Considered as a repeat visit No

Customer's own words

Fahrzeugannahme durch Service- assistentin Local 0 FRU
Flat rate unit I 01 00 002

— Job

Description:

Considered as a repeat visit No

Customer's own words

Engine oil service 3 FRU
Flat rate unit I 00 00 610

Castrol Edge 0W30 CASTROL Local 5
Part I FT91700000030

Set oil-filter element 1
Part I 11 42 8 575 211

— Job

Description:

Considered as a repeat visit No

Customer's own words

Service - standard scope
Flat rate unit I 00 00 105

2 FRU

— Job

Description:

Considered as a repeat visit No

Customer's own words

Microfilter service
Flat rate unit I 00 00 616

2 FRU

Microfilter/activated Carbon container
Part I 64 11 9 237 555

1

— Job

Description:

Considered as a repeat visit No

Customer's own words

-Fahrzeug aussaugen -Türeinstiege reinigen -kostenlose Soft-Tec-
Wäsche
Flat rate unit I 09 99 007

Local

0 FRU

— Job

Description:

Considered as a repeat visit No








Customer's own words

— 09/09/2017 Key

25965 Km

03846

Key 0



— 30/01/2017 Repair

347 Km

35779
Autohaus
Michael
Schmidt GmbH
, Starnberg

Job

— Job

Description: Auslagerung

Considered as a repeat visit No

Customer's own words

!!! unknown BMW-Id 3600004 Räder auslagern !!!
Flat rate unit I 36 00 004

Local

1 FRU

— 25/11/2016 Repair

347 Km

35779
Autohaus
Michael
Schmidt GmbH
, Starnberg

Job

— Job

Description:**Considered as a repeat visit** No**Customer's own words**

Nummer:9B5 Flat rate unit EINLAGE	Local	0 FRU
!!! unknown BMW-Id 3699008 Räderinnenseite aller 4 Räder mit Kennzeichen versehen !!! Flat rate unit 36 99 008	Local	1 FRU
Removing and installing front and rear wheels Flat rate unit 36 10 360		6 FRU
Initialising tyre failure indicator Flat rate unit 36 11 500		1 FRU
RDCi Wheel/Tyre set Winter light alloy Part 36 11 2 289 696		4