

Thank you for ordering from us!
www.checkvin.eu

Vehicle

BMW 318D A, 110KW

WBA8H71000A744448



Development code
Colour
Actual integration level
Start of warranty

F31
black-sapphire metallic
F020-20-07-525
29 November 2018

Technical campaigns

There are no Campaigns for this vehicle.

Warranty extension/VIN-based goodwill

Status	Campaign number	Description
Open	1SACC011056	Exhaust gas recirculation cooler Bx7 Local campaign number: -

Special information

There are no Campaigns for this vehicle.

Restrictions on the warranty

There are no restrictions on the warranty.

⚠ Market-specific restrictions are not currently displayed. Please check this in WDF/WXE via S-Gate.

Live Diagnosis

📘 There are no service solutions for Live Diagnosis.

Service contracts

No BSI contracts

Information on faults workshop/Service Consultation

There is no information on faults.

Navigation map

Installed map	Enabling code (subscription)	Latest navigation map included in subscription	Latest navigation map subject to charge
Road Map EUROPE Way 2019-3 (As of: 23 Nov 2022)	Enabling code valid for navigation maps with release date up to 31 Dec 2099 (SWID: 01309912).	Road Map EUROPE Way 2025-2	-

Vehicle details

Vehicle type	Passenger car
Brand	BMW
Model	318D A
Body	TOUR
Vehicle identification number (last 7 digits)	A744448
Vehicle identification number (17 digits)	WBA8H71000A744448
Development code	F31
Steering	LL
Engine	B47U
Engine number	53065513
Exhaust re-treatment	EURO6, WLTP, BG, PI/CI, M, N1 I
Transmission	AUT
Transmission number	2028232XEJ
Head unit serial number	MM07DBJ1085971
Drive	HECK
Integration level, works	F020-18-07-547
Production date	25 Oct 2018
Production plant	Muenchen
Delivery date	7 Dec 2018
Delivering retailer	BMW AG, C1-V-30, München, DE
National-market version	EUR
Paint code	475
Upholstery code	CCL2
Model code	8H81
Basic type	8H71
Lead type	8H81

Optional equipment

Optional equipment ex works:

0164 Exhaust emissions standard EU6
01CA Selection of COP-relevant vehicles
01CB CO2 equipment
0205 Automatic transmission
0216 Hydro steering-servotronic
0230 Extra package, EU-speciifc
024B BMW LA wheel, double spoke 397
0258 Tyres with runflat properties
02PA Locking wheel bolt
02VB Tyre pressure display
02XE Leather sports steering wheel
03AA Roof railing black
0423 Floor mats velours
0428 Warning triangle and first aid kit
0430 Interior/outside mirror with auto dip
0431 Interior mirror with automatic-dip
0441 Smoker package
0481 Sports seat
0488 Lumbar support, driver and passenger
0493 Storage compartment package
0494 Seat heating driver/passenger
04AE Armrest front, retractable
04LU black high-gloss accent chrm. Perlglanz
0508 Park Distance Control (PDC)
0521 Rain sensor
0534 Automatic air conditioning
0544 Cruise control with braking function
0548 Kilometre speedo
0563 Light package
05A1 LED Fog lights
05A2 LED headlight
05AC High-beam assistant
05DA Passenger airbag deactivation
05DC Rear-seat headrests, folding
0606 Navigation system Business
0650 CD drive
0676 HiFi speaker system
0698 Area-Code 2 for DVD
06AC Intelligent emergency call
06AE Teleservices
06AK Connected Drive Services
06AM Real-Time Traffic Information
06AN Concierge Services
06AP Remote Services
06NS Comfort telephony w/ enhanced Smartphone
06WA Instrument panel with extended scope
07AC Sport Line
07LD Modell Sport Line
0801 German version
0851 Language version German
0879 On-board literature, German
08KA Oil service interval 24 mths / 30,000 km
08R9 Refrigerant R1234yf
0941 Dummy-SALAPA
09BD Business Package
A090 90 Ah AGM battery
POLS Cloth cushion

Retrofitted optional equipment:

This vehicle has no retrofits.

Control unit software version

Vehicle histories

	Date	Type	Vehicle mileage	Retailer	Overview
—	26/06/2023	Key	191983 Km		Key 0

 -4200 13.5 % 08/2024   -4200 08/2024   80000 09/2023  100000 08/2026  27000 08/2026  \$ 03/2025	26/06/2023	Service	191983 Km	04543 Niederlassung Leipzig , Leipzig	Automatic
 -4200 08/2024   -4200 08/2024   80000 09/2023  100000 08/2026  27000 08/2026  \$ 03/2025	26/06/2023	Repair	191983 Km	04543 Niederlassung Leipzig BMW AG, Leipzig	Job Job Job Job Job Job Job

— Job

Description:
Considered as a repeat visit No
Customer's own words

Service - standard scope	2 FRU
Flat rate unit I 00 00 105	

— Job

Description:
Considered as a repeat visit No
Customer's own words Ölfilter + Öl im Kofferraum,

Handling bei Ölservice mit angeliefertem	Local	2 FRU
Flat rate unit I NL00 00 6		
Engine oil service		3 FRU
Flat rate unit I 00 00 610		

— Job

Description:
Considered as a repeat visit No
Customer's own words

Microfilter service	2 FRU
Flat rate unit I 00 00 616	
Microfilter/activated Carbon container	1
Part I 64 11 9 237 555	

— Job

Description:
Considered as a repeat visit No
Customer's own words

Füllstand Betriebsflüssigkeiten/Frost- s	Local	2 FRU
--	-------	-------

- Job

Customer's own words

- Job

Customer's own words

- Job

Customer's own words

—	05/06/2023	Key	189305 Km	Remote KeyRead
---	------------	-----	-----------	----------------



- Job

Customer's own words

— 16/01/2023 Key 173976 Km Key 0

14000
08/2024

14000
08/2024

14000
08/2024

80000
09/2023

24000
08/2026

45000
08/2026

11/2023

—

13/01/2023

Key

173869 Km

Key 0

14000
08/2024

14000
08/2024

14000
08/2024

80000
09/2023

24000
08/2026

45000
08/2026

11/2023

—

13/01/2023

Repair

173869 Km

01868
Autohaus
Weissenfels
GmbH ,
Montabaur

Job

— Job

Description:

Considered as a repeat visit No

Customer's own words

Removing and installing/replacing the glove box damper Flat rate unit I 51 16 383	6 FRU
Glove box damper Part I 51 16 9 227 250	1

—

23/11/2022

Warranty

166840 Km

01868

Job: F1x F2x F3x G0x G1x G3x
B47O B47K B47U B47T Replacing
EGR cooler (high-temperature)

— Job: F1x F2x F3x G0x G1x G3x B47O B47K B47U B47T Replacing EGR cooler (high-temperature)

Description: F1x F2x F3x G0x G1x G3x B47O B47K B47U B47T Replacing EGR cooler (high-temperature)

Considered as a repeat visit No

Customer's own words

Replace exhaust gas recirculation cooler, including exhaust gas recirculation valve Flat rate unit I 00 72 349	25 FRU
Additional work: run function test for pressure sensor system Flat rate unit I 00 72 939	3 FRU
Additional work: enter component identification of new exhaust gas recirculation cooler in diagnostic system Flat rate unit I 00 72 940	1 FRU
F1x F2x F3x G0x G1x G3x B47O B47K B47U B47T Replacing EGR cooler (high-temperature) Defect I 00 11 53 06 00	
Hex Bolt with washer Part I 07 11 9 905 750	1
Hex Bolt Part I 07 14 7 029 829	4
Acoustic cover front Part I 11 14 8 490 577	1

O-ring Part I 11 61 8 512 681	1
Connection piece Part I 11 65 7 803 012	1
Pipe union Part I 11 71 7 799 853	2
Exhaust gas radiator high temperature Part I 11 71 7 822 347	1
EGR small parts set Part I 11 71 8 490 640	1
Holder Part I 61 13 1 369 832	1

—

22/11/2022

Key

166832 Km

01868

Key 0



21000

08/2024





21000

08/2024





25000

09/2023





30000



60000

08/2026



11/2023

—

26/09/2022

Repair

158884 Km

00219 Baum-Automobile GmbH & Co. KG , Bad Neuenahr-Ahrweiler

Job

— Job

Description:

Considered as a repeat visit No

Customer's own words

Replace left and right radial shaft seal for driven shafts on rear axle differential Flat rate unit I 33 10 024	1 FRU
Anteilig Teilekosten Part I FT99 99 8 888 7	Local 1

—

26/09/2022

Repair

158884 Km

00219 Baum-Automobile GmbH & Co. KG , Bad Neuenahr-Ahrweiler

Job

— Job

Description:

Considered as a repeat visit No

Customer's own words

Replace left and right radial shaft seal for driven shafts on rear axle differential Flat rate unit I 33 10 024	-1 FRU
Anteilig Teilekosten Part I FT99 99 8 888 7	Local -1

https://myair-b2d.bmwgroup.com/air/faces/xhtml/fahrzeug/FahrzeugSingleView.xhtml?vin=WBA8H71000A744448

7/21

— 26/09/2022 Repair 158884 Km 00219 Baum- Automobile GmbH & Co. KG , Bad Neuenahr-Ahrweiler Job

— Job

Description:


Considered as a repeat visit No

Customer's own words

Replace left and right radial shaft seal for driven shafts on rear axle differential
Flat rate unit I 33 10 024 1 FRU

Anteilig Teilekosten Local 1
Part I FT99 99 8 888 7

— 21/09/2022 Key 158884 Km 01868 Key 0



— 21/09/2022 Repair 158889 Km 01868 Autohaus Weissenfels GmbH , Montabaur Job

— Job

Description:

Considered as a repeat visit No

Customer's own words

Replace left and right radial shaft seal for driven shafts on rear axle differential
Flat rate unit I 33 10 024 24 FRU

Replacing the radial shaft seal for the input flange
Flat rate unit I 33 11 512 5 FRU

Muffler clamp 1
Part I 18 30 8 581 218

Shaft seal 1
Part I 31 50 7 609 535

Assembly ring 2
Part I 31 53 7 502 681

Gasket set differential 2
Part I 33 10 7 564 416

Repair kit insert nut 1
Part I 33 12 7 607 158

Hex Bolt 1
Part I 33 17 6 760 342

Hex Bolt with washer 2
Part I 33 17 6 760 343

Self-locking collar nut 1

Part I 33 30 6 760 349

Hypoid axle oil G1

Part I 83 22 2 295 532

1

— 21/09/2022 Repair 158889 Km 01868 Job
Autohaus
Weissenfels
GmbH ,
Montabaur

— Job

Description:

Considered as a repeat visit No

Customer's own words

Replace left and right radial shaft seal for driven shafts on rear axle
differential
Flat rate unit I 33 10 024

24 FRU

Replacing the radial shaft seal for the input flange
Flat rate unit I 33 11 512

5 FRU

Muffler clamp
Part I 18 30 8 581 218

1

Shaft seal
Part I 31 50 7 609 535

1

Assembly ring
Part I 31 53 7 502 681

2

Gasket set differential
Part I 33 10 7 564 416

2

Repair kit insert nut
Part I 33 12 7 607 158

1

Hex Bolt
Part I 33 17 6 760 342

1


Hex Bolt with washer
Part I 33 17 6 760 343

2


Self-locking collar nut
Part I 33 30 6 760 349

1

— 30/08/2022 Key 156796 Km Key 0



— 30/08/2022 Service 156796 Km 01868 Automatic



—	30/08/2022 Repair	156800 Km	01868 Autohaus Weissenfels GmbH , Montabaur	Job Job Job Job Job
---	-------------------	-----------	---	---------------------------------

— Job

Description:

Considered as a repeat visit No

Customer's own words

Service - standard scope	2 FRU
Flat rate unit I 00 00 105	

Service, vehicle check	6 FRU
Flat rate unit I 00 00 624	

— Job

Description:

Considered as a repeat visit No

Customer's own words

Engine oil service	3 FRU
Flat rate unit I 00 00 610	

Entsorgung Altöl / vermischte Kraftstoffe	5	Local
Part I FT99 99 0 000 5		

Set oil-filter element	1
Part I 11 42 8 575 211	

— Job

Description:

Considered as a repeat visit No

Customer's own words

Microfilter service	2 FRU
Flat rate unit I 00 00 616	

Microfilter/activated Carbon container	1
Part I 64 11 9 237 555	

— Job

Description:

Considered as a repeat visit No

Customer's own words

Service fuel filter	3 FRU
Flat rate unit I 00 00 604	

Fuel filter cartridge	1
Part I 13 32 7 822 497	

— Job

Description:

Considered as a repeat visit No

Customer's own words

Service - air filter element	2 FRU
Flat rate unit I 00 00 602	

Air filter element
Part I 13 71 8 511 668

—	04/08/2022	Key	155171 Km	01868	Key 0		
 -2700 8.7 % 09/2023	 -2700 09/2023	 -2700 09/2023	 -2700 09/2023	 39000 09/2023	 46000 09/2023	 -2700 4.4 % 09/2023	 11/2023
—	22/07/2022	Key	153237 Km	01868	Key 0		
 -800 2.6 % 09/2023	 -800 399	 -800 399	 -800 399	 39000 09/2023	 46000 09/2023	 -800 1.3 % 09/2023	 11/2023
—	23/09/2021	Key	122040 Km		Key 0		
 250 02/2023		 250 488		 60000 10/2021	 70000 1208		 11/2021
—	23/09/2021	Service	122040 Km	01868 Autohaus Weissenfels GmbH , Montabaur	Automatic		
 250 ✓	 0	 250 ✓	 0	 60000	 0 ✓	 70000	 30000
—	23/09/2021	Repair	122040 Km	01868 Autohaus Weissenfels GmbH , Montabaur	Job Job Job Job		

— Job

Description:

Considered as a repeat visit No

Customer's own words

Service - standard scope
Flat rate unit I 00 00 105

2 FRU

— Job

Description:

Considered as a repeat visit No

Customer's own words

Engine oil service
Flat rate unit I 00 00 610

3 FRU

Entsorgung Altöl / vermischte Kraftstoffe
Part I FT99 99 0 000 5

Local

5

Set oil-filter element

1

Part I 11 42 8 575 211

— Job

Description:

Considered as a repeat visit No

Customer's own words

Microfilter service	2 FRU
Flat rate unit I 00 00 616	

Microfilter/activated Carbon container	1
Part I 64 11 9 237 555	

— Job

Description:


Considered as a repeat visit No

Customer's own words

Brake fluid service	4 FRU
Flat rate unit I 00 00 618	

BREMSFLUESSIGKEIT	Local	1
Part I FT99 99 9 999 0		

— 26/04/2021 Key	101665 Km	Key 0
------------------	-----------	-------



— 26/04/2021 Repair	101665 Km	01868 Autohaus Weissenfels GmbH , Montabaur
		Job

— Job

Description:

Considered as a repeat visit No


Customer's own words

Replacing two tyres with run-flat technology	12 FRU
Flat rate unit I 36 12 055	

— 15/02/2021 Service	93411 Km	01868 Autohaus Weissenfels GmbH, Montabaur
		Manual



— 12/02/2021 Key	93331 Km	Key 0
------------------	----------	-------



— 12/02/2021 Repair 93331 Km 01868 Job
Autohaus
Weissenfels
GmbH,
Montabaur

— Job

Description:

Considered as a repeat visit No

Customer's own words

Service - standard scope 2 FRU
Flat rate unit I 00 00 105

Engine oil service 3 FRU
Flat rate unit I 00 00 610

Entsorgung Altöl / vermischte Kraftstoffe Local 5
Part I FT99 99 0 000 5

Set oil-filter element 1
Part I 11 42 8 575 211

— Job

Description:

Considered as a repeat visit No

Customer's own words

Microfilter service 2 FRU
Flat rate unit I 00 00 616

Microfilter/activated Carbon container 1
Part I 64 11 9 237 555

— 12/02/2021 Warranty 93331 Km 01868 Job: F2x F3x F45 F46 F80 F87
G01 G08 G11 G12 Rework rear
light

— Job: F2x F3x F45 F46 F80 F87 G01 G08 G11 G12 Rework rear light

Description: F2x F3x F45 F46 F80 F87 G01 G08 G11 G12 Rework rear light

Considered as a repeat visit No

Customer's own words

Check the screw connections of both rear lights, no or only small cracks 3 FRU
visible, do not replace parts
Flat rate unit I 00 67 792

F2x F3x F45 F46 F80 F87 G01 G08 G11 G12 Rework rear light
Defect I 00 63 58 01 00

Self-locking hex nut 4
Part I 64 50 9 123 157

— 02/02/2021 Key 91676 Km Key 0

 130 07/2022	 130 544	 130 544	 130 544	 7000	 0 10/2021	 16000	 130 07/2022	 0 11/2021
--	--	--	--	--	--	---	---	--

— 05/11/2020 Key 78790 Km 01868 Key 0

 13000 07/2022	 13000 633	 13000 633	 13000 633	 30000	 0 10/2021	 28000	 13000 07/2022	 0 11/2021
---	---	---	---	--	---	--	--	---

— 05/11/2020 Repair 78790 Km 01868 Job

Autohaus
Weissenfels
GmbH ,
Montabaur

— Job

Description:

Considered as a repeat visit No

Customer's own words

Removing and installing front bumper panel
Flat rate unit I 51 11 156

11 FRU

— 24/07/2020 Key 63071 Km 01868 Key 0

 -3200 11/2021	 -3200 494	 -3200 494	 -3200 494	 47000	 0 10/2021	 45000	 -3200 11/2021	 0 11/2021
---	---	---	---	--	---	--	--	---

— 24/07/2020 Service 63071 Km 01868 Automatic

Autohaus
Weissenfels
GmbH,
Montabaur

 -3200 11/2021 ✓	 -3200 11/2021 ✓	 -3200 11/2021 ✓	 -3200 11/2021 ✓	 47000	 0 10/2021	 45000	 -3200 11/2021 ✓	 0 11/2021
--	--	--	--	--	---	--	---	---

— 24/07/2020 Repair 63080 Km 01868 Job

Autohaus
Weissenfels
GmbH ,
Montabaur
Job
Job
Job
Job
Job
Job

— Job

Description:

Considered as a repeat visit No

Customer's own words

Service - standard scope
Flat rate unit I 00 00 105

2 FRU

— Job

Description:

Considered as a repeat visit No

Customer's own words

Service, vehicle check	6 FRU
Flat rate unit I 00 00 624	

— Job

Description:

Considered as a repeat visit No

Customer's own words

Microfilter service	2 FRU
Flat rate unit I 00 00 616	

Microfilter/activated Carbon container	1
Part I 64 11 9 237 555	

— Job

Description:

Considered as a repeat visit No

Customer's own words

Engine oil service	3 FRU
Flat rate unit I 00 00 610	

Entsorgung Altöl / vermischte Kraftstoffe	Local	5
Part I FT99 99 0 000 5		

Scheibenklar BMW	Local	4
Part I FT99 99 9 999 1		

Set oil-filter element	1
Part I 11 42 8 575 211	

— Job

Description:

Considered as a repeat visit No

Customer's own words

Service - air filter element	2 FRU
Flat rate unit I 00 00 602	

Air filter element	1
Part I 13 71 8 511 668	

— Job

Description:

Considered as a repeat visit No

Customer's own words

Service fuel filter	3 FRU
Flat rate unit I 00 00 604	

Fuel filter cartridge	1
Part I 13 32 8 572 522	

— Job

Description:

Considered as a repeat visit No

Customer's own words

Diesel Exhaust Fluid AdBlue
Part I FT99 99 9 999 0

Local

18

— 24/07/2020 Warranty 63080 Km 01868 Job: Evaluation unit / SCR control unit

— Job: Evaluation unit / SCR control unit

Description: Evaluation unit / SCR control unit

Considered as a repeat visit No


Customer's own words

Performing vehicle test 2 FRU
Flat rate unit I 00 00 556


Programming/encoding control unit(s) including deleting fault memories 4 FRU
Flat rate unit I 61 00 730

Evaluation unit / SCR control unit
Defect I 16 19 10 12 00


— 05/06/2020 Key 56365 Km 01868 Key 0



— 18/11/2019 Key 30933 Km 01868 Key 0



— 18/11/2019 Service 30933 Km 01868 Automatic
Autohaus
Weissenfels
GmbH ,
Montabaur



— 18/11/2019 Repair 30946 Km 01868 Job
Autohaus
Weissenfels
GmbH ,
Montabaur Job
Job
Job
Job
Job

— Job

Description:

Considered as a repeat visit No

Customer's own words

Service - standard scope 2 FRU

Flat rate unit I 00 00 105

Diesel Exhaust Fluid AdBlue
Part I FT99 99 9 999 0

Local

10

— Job

Description:

Considered as a repeat visit No

Customer's own words

Engine oil service

Flat rate unit I 00 00 610

3 FRU

Scheibenklar BMW

Part I FT99 99 9 999 1

Local

4

Shell Helix Ultra Prof. BMW LL04 5W-30

Part I FT99 99 9 999 0

Local

5

Set oil-filter element

Part I 11 42 8 575 211

1

— Job

Description:

Considered as a repeat visit No

Customer's own words

Microfilter service

Flat rate unit I 00 00 616

2 FRU

Microfilter/activated Carbon container

Part I 64 11 9 237 555

1

— Job

Description:

Considered as a repeat visit No

Customer's own words

Service - air filter element

Flat rate unit I 00 00 602

2 FRU

Air filter element

Part I 13 71 8 511 668

1

— Job

Description:

Considered as a repeat visit No

Customer's own words

Service fuel filter

Flat rate unit I 00 00 604

3 FRU

Fuel filter cartridge

Part I 13 32 8 572 522

1

— Job

Description:

Considered as a repeat visit No

Customer's own words

(Statutory) vehicle inspection

5 FRU

Flat rate unit | 00 12 559

— Job

Description:

Considered as a repeat visit No

Customer's own words

Exhaust emission inspection

5 FRU









Flat rate unit | 00 00 440

— 28/06/2019 Key

12715 Km

01868

Key 0



— 28/06/2019 Warranty

12750 Km

01868

Job: Oxygen monitor sensor

— Job: Oxygen monitor sensor

Description: Oxygen monitor sensor

Considered as a repeat visit No

Customer's own words

Performing vehicle test

4 FRU

Flat rate unit | 00 00 006

Vehicle diagnosis - carrying out the ABL

6 FRU

Flat rate unit | 61 00 006

Replacing the monitoring oxygen sensor

4 FRU

Flat rate unit | 13 62 664

Oxygen monitor sensor

Defect | 11 78 03 15 00

Oxygen sensor

1








Part | 13 62 8 573 155

— 21/06/2019 Key

11860 Km

01868

Key 0










— 14/06/2019 Key

11463 Km

01868

Key 0



— 14/06/2019 Repair

0 Km

01868

 Autohaus
 Weissenfels
 GmbH ,
 Montabaur

Job

Job

— Job

Description:

Considered as a repeat visit No

Customer's own words

12-point check

6 FRU

Flat rate unit I 00 99 270

— Job

Description:

Considered as a repeat visit No

Customer's own words

Removing and installing front and rear wheels

6 FRU


Flat rate unit I 36 10 360

— 12/06/2019 Key

11463 Km

00219

Key 0




— 12/06/2019 Key

11463 Km

00219

Key 0



— 12/06/2019 Repair

11463 Km

00219 Baum-Automobile GmbH & Co. KG, Bad Neuenahr-Ahrweiler

Job

— Job

Description:

Considered as a repeat visit No

Customer's own words

BMW Premium Selection 360 degree vehicle check (for German market only)

17 FRU

Flat rate unit I 00 00 130

— 12/06/2019 Repair

11463 Km

00219 Baum-Automobile GmbH & Co. KG, Bad Neuenahr-Ahrweiler

Job

— Job

Description:

Considered as a repeat visit No

Customer's own words

BMW Premium Selection 360 degree vehicle check (for German market only)

17 FRU

Flat rate unit I 00 00 130

Window-cleaner tablet w/out antifreeze

1

Part I 83 12 2 298 201

BMW Engine Oil LL04 5W30
Part I 83 21 2 405 948









1

— 11/06/2019 Key

11463 Km

00219

Key 0



— 11/06/2019 Repair

11463 Km

00219 Baum-
Automobile
GmbH & Co.
KG , Bad
Neuenahr-
AhrweilerJob
Job

— Job

Description:

Considered as a repeat visit No

Customer's own words

Replacing engine hood Flat rate unit I 41 61 001	11 FRU
---	--------

Hohlraumversiegelung Part I FT99 99 9 306 0	Local	1
--	-------	---

Hood Part I 41 00 7 290 944	1
--------------------------------	---

Clip Part I 51 48 9 119 216	20
--------------------------------	----

Label, coolant Part I 71 23 6 995 664	1
--	---

— Job

Description:

Considered as a repeat visit No

Customer's own words

Lackierung Frontklappe 00000000 Flat rate unit I 99 99 999	Local	1 FRU
---	-------	-------

— 11/06/2019 Repair

11463 Km

00219 Baum-
Automobile
GmbH & Co.
KG , Bad
Neuenahr-
AhrweilerJob
Job

— Job

Description:

Considered as a repeat visit No

Customer's own words

Replacing engine hood Flat rate unit I 41 61 001	-11 FRU
---	---------

Hohlraumversiegelung	Local	-1
----------------------	-------	----

Part I FT99 99 9 306 0	
Hood Part I 41 00 7 290 944	-1
Clip Part I 51 48 9 119 216	-20
Label, coolant Part I 71 23 6 995 664	-1

— Job

Description:
Considered as a repeat visit No
Customer's own words

Lackierung Frontklappe 00000000 Flat rate unit I 99 99 999	Local	-1 FRU
---	-------	--------

—	04/12/2018	Repair	1 Km	00102 Niederlassung München Räder und Reifen Zentrum Garching BMW AG, Garching- Hochbrück	Job
---	------------	--------	------	--	-----

— Job

Description:
Considered as a repeat visit No
Customer's own words

Radwechsel pro Satz / Fuhrpark / Rent Part I 5100122	Local	1
---	-------	---

—	28/11/2018	Service	3 Km	30982 ISIS/ ITools int. Kunden Inlan, Garching	Manual
---	------------	---------	------	---	--------

