

Thank you for ordering from us!

www.checkvin.eu

Vehicle

BMW 420i A, 135KW

WBA4D31090G768215



Development code
Colour
Actual integration level
Start of warranty

F36
glacier-silber metallic
F020-20-03-540
14 December 2016

Technical campaigns

There are no Campaigns for this vehicle.

Warranty extension/VIN-based goodwill

There are no Campaigns for this vehicle.

Special information

There are no Campaigns for this vehicle.

Restrictions on the warranty

There are no restrictions on the warranty.

⚠ Market-specific restrictions are not currently displayed. Please check this in WDF/WXE via S-Gate.

Live Diagnosis

 There are no service solutions for Live Diagnosis.

Service contracts

No BSI contracts

Information on faults workshop/Service Consultation

There is no information on faults.

Navigation map

Note: The installed map cannot be clearly identified. Presumably one of the following maps is present in the vehicle.

Installed map	Enabling code (subscription)	Latest navigation map included in subscription	Latest navigation map subject to charge
Road Map EUROPE EVO 2016-4 (As of: 18 Jan 2023)	-	-	-
Road Map EUROPE EVO 2016-4 (As of: 18 Jan 2023)	Enabling code valid for navigation maps with release date up to 31 Dec 2099 (SWID: 01200FFF).	Road Map EUROPE EVO 2025-1	-

Vehicle details

Vehicle type	Passenger car
Brand	BMW
Model	420i A
Body	COUPE
Vehicle identification number (last 7 digits)	G768215
Vehicle identification number (17 digits)	WBA4D31090G768215
Development code	F36
Steering	LL
Engine	B48M
Engine number	F5331594
Exhaust re-treatment	EURO6, W, PI/CI, M, N1 I
Transmission	AUT
Transmission number	0604952WDP
Head unit serial number	HB2240G8077976
Drive	HECK
Integration level, works	F020-16-11-502
Production date	28 Nov 2016
Production plant	Dingolfing
Delivery date	30 Nov 2016
Delivering retailer	Jorssen Noord, Merksem, BE
National-market version	EUR
Paint code	A83
Upholstery code	LCSW
Model code	4D41
Basic type	4D31
Lead type	4D41

Optional equipment

Optional equipment ex works:

Retrofitted optional equipment:




01CA Selection of COP-relevant vehicles
 01CB CO2 equipment
 0205 Automatic transmission
 021C BMW LA wheel, M double spoke bicolor
 0230 EU-specific additional contents
 0258 Tyres with runflat properties
 02PA Locking wheel bolt
 02VB Tyre pressure display
 0302 Alarm system
 0337 M Sports package
 03L8 Exterior equipment, aluminium, satinised
 0420 Sun protection glazing
 0423 Floor mats velours
 0430 Interior/outside mirror with auto dip
 0431 Interior mirror with automatic-dip
 0459 Seat adjustment, electric, with memory
 0465 Through-loading system
 0481 Sports seat
 0493 Storage compartment package
 0494 Seat heating driver/passenger
 04AE Armrest front, retractable
 04NE Blow-by heater
 04WF Alum. Hexagon accent blue matt
 0502 Headlight cleaning system
 0508 Park Distance Control (PDC)
 0521 Rain sensor
 0522 Xenon Light
 0534 Automatic air conditioning
 0544 Cruise control with braking function
 0548 Kilometre speedo
 0563 Lights package
 05DA Passenger airbag deactivation
 0609 Navigation system Professional
 0610 Head-up display
 0698 Area-Code 2 for DVD
 06AC Intelligent emergency call
 06AE Teleservices
 06NW Telephony with wireless charging
 06WA Instrument panel with extended scope
 06WD WLAN Hotspot
 0704 M Sports suspension
 0710 M leather steering wheel
 0715 M Aerodynamics package
 0775 Headlining anthracite
 07LF Modell M Sport
 0843 Power reduction
 0868 Language version, Dutch
 0886 On-board literature, Dutch
 08KA Oil service interval 24 mths / 30,000 km
 08R9 Refrigerant R1234yf
 08S3 Automatic locking during starting
 08SM Car ident. number visible from outside
 08TH Road sign detection
 A090 90 Ah AGM battery
 LEDE Leather equipment

This vehicle has no retrofits.



Vehicle histories

	Date	Type	Vehicle mileage	Retailer	Overview
—	12/02/2025	Key	148381 Km	05670	Key 1
		   	   		
		-430 1.9 % -42 5.7 %	7000 -42 5.7 % 700 23000		01/2027
—	12/02/2025	Service	148381 Km	05670 Meeusen	Manual



Kalmthout,
Kalmthout





— 20/01/2025 Key 147833 Km 05670 Key 1






— 20/01/2025 Key 147775 Km 05670 Key 1



— 20/01/2025 Key 147775 Km 05670 Key 1



— 20/01/2025 Service 147775 Km 05670 Manual
Meeusen
Kalmthout,
Kalmthout



— 20/01/2025 Repair 148381 Km 05670 , KALMTHOUT Job
Job
Job
Job
Job

— Job

Description:

Considered as a repeat visit No

Customer's own words

Brake fluid service 4 FRU
Flat rate unit I 00 00 618

Remvloeistof DOT4 LV, laagviskeus1000ml, TU Local 1
Part I REMOLIE

— Job

Description:

Considered as a repeat visit No

Customer's own words

Service - standard scope	2 FRU
Flat rate unit I 00 00 105	

Engine oil service	3 FRU
Flat rate unit I 00 00 610	

Set oil-filter element	1
Part I 11 42 8 575 211	

Total Quartz ineo efficen 0W301000ml,TU	Local	5
Part I TOTAL		

Twin Power Turbo Additive Petrol	1
Part I 83195A07750	

battery	1
Part I 61 31 9 217 643	

Ruitensproeier met antivries	Local	4
Part I 01		

Antivries Koelwater G48	Local	0
Part I 02		

— Job

Description:

Considered as a repeat visit No

Customer's own words

Microfilter service	2 FRU
Flat rate unit I 00 00 616	

Microfilter/activated Carbon container	1
Part I 64 11 9 237 555	

— Job

Description:

Considered as a repeat visit No

Customer's own words

Service, rear brakes	7 FRU
Flat rate unit I 00 00 614	

Brake cleaner acetone-free	1
Part I 83 19 2 413 695	

Brake-pad sensor, rear	1
Part I 34 35 6 792 292	

Repair kit, brake pads asbestos-free	1
Part I 34 21 6 873 093	

Brake-pad paste	2
Part I 83 19 2 158 851	

— Job

Description:

Considered as a repeat visit No

Customer's own words

—	27/09/2024	Key	144720 Km	05670	Key 0
---	------------	-----	-----------	-------	-------



6000
01/2025







6000
01/2025



10000
01/2025





3300
01/2027



31000
01/2027

— 27/09/2024 Repair 144720 Km 05670 , KALMTHOUT Job Job

— Job

Description:
Considered as a repeat visit No
Customer's own words

Replacing light bulb for right xenon headlight Flat rate unit I 63 99 077	4 FRU
Bulb Xenon light with ignition element Part I 63 21 7 217 509	1

— Job

Description:
Considered as a repeat visit No
Customer's own words

unknown fru: Bestuurdersairbag vervangen Flat rate unit I 00 76 920	Local	3 FRU
Batterijtest Flat rate unit I -	Local	1 FRU
Airbag module, driver's side Part I 32305A66F66		1

— 27/09/2024 Warranty 144720 Km 05670 Job: Fx Replace driver's airbag, part III (SDI)

— Job: Fx Replace driver's airbag, part III (SDI)

Description: Fx Replace driver's airbag, part III (SDI)
Considered as a repeat visit No
Customer's own words

Replace driver's airbag Flat rate unit I 00 76 920	3 FRU
Fx Replace driver's airbag, part III (SDI) Defect I 00 32 62 03 00	
Airbag module, driver's side Part I 32305A66F66	1

— 26/08/2024 Key 143625 Km 05670 Key 0



8000
01/2025







8000
01/2025



11000
01/2025





14000
01/2027



33000
01/2027

— 26/08/2024 Repair 143625 Km 05670 , KALMTHOUT Job Job

— Job

Description:
Considered as a repeat visit No
Customer's own words

Motor olie SAE 5W-30 Longlife-041000ML, TU Part I TOTAL	Local	1
--	-------	---

— Job

Description:
Considered as a repeat visit No
Customer's own words

— 13/05/2024 Key 139244 Km 05670 Key 0



— 13/05/2024 Repair 139244 Km 05670 , KALMTHOUT Job
Job
Job

— Job

Description:
Considered as a repeat visit No
Customer's own words

Motor olie SAE 5W-30 Longlife-041000ML, TU Part I TOTAL	Local	1
--	-------	---

— Job

Description:
Considered as a repeat visit No
Customer's own words

Ruitensproeier met antivries Part I 01	Local	4
---	-------	---

Anitvries Koelwater G48 Part I 02	Local	0
--------------------------------------	-------	---

— Job

Description:
Considered as a repeat visit No
Customer's own words

— 28/12/2023 Key 134754 Km 05670 Key 0



— 28/12/2023 Repair 134754 Km 05670 , Job
KALMTHOUT

— Job

Description:

Considered as a repeat visit No



Customer's own words

Motor olie SAE 5W-30 Longlife-041000ML, TU
Part I TOTAL



Local

1


— 18/01/2023 Key 125427 Km Key 1





— 18/01/2023 Service 125427 Km 05670 Automatic
Meeusen ,
Kalmthout





— 04/01/2023 Key 125113 Km Key 0





— 27/07/2022 Key 119040 Km 05692 Key 1




— 14/06/2022 Key 117243 Km 05692 Key 0




— 18/01/2021 Key 96489 Km Key 1



— 18/01/2021 Service 96489 Km 05721 Jorssen Automatic
Noord ,
Merksem




— 03/12/2020 Key



93847 Km

Key 1




— 17/09/2019 Key



68651 Km

05721

Key 0




— 17/09/2019 Service




68651 Km

05721 Jorssen
Noord,
Merksem

Automatic




— 15/04/2019 Key




58028 Km

05721

Key 0




— 17/12/2018 Key




48344 Km

Key 0




— 23/04/2018 Key




32754 Km

05721

Key 0




— 23/04/2018 Service




32754 Km

05721 Jorssen
Noord,
Merksem

Automatic



— 23/04/2018 Repair



32754 Km

05721 Jorssen
Noord,
Job

— Job

Description:

Considered as a repeat visit No

Customer's own words

Service standaard omvang

Package I 0000105

Service - standard scope
Flat rate unit I 00 00 105

2

Service motorolie

Package I 0000610

Engine oil service
Flat rate unit I 00 00 610

3

BMW Engine Oil LL04 5W30
Part I 83212405948

5.25

Set oil-filter element
Part I 11428575211

1

Service microfilter

Package I 0000616

Microfilter service
Flat rate unit I 00 00 616

2

Microfilter/activated Carbon container
Part I 64119237555

1

Service voertuig-check

Package I 0000624

Service, vehicle check
Flat rate unit I 00 00 624



6

— 20/12/2017 Key

24685 Km

05721

Key 0





— 09/10/2017 Key

19351 Km

05721

Key 0





— 03/04/2017 Key

6832 Km

05721

Key 0



— 03/04/2017 Repair

6832 Km

05721 Jorssen
Noord,
Merksem

Job

— Job

Description:

Considered as a repeat visit No

Customer's own words

Laadwens van de klant: Full Flat rate unit -	Local	0 FRU
Initiële laadtoestand hoog-voltage accu (SoC): 255% Flat rate unit -	Local	0 FRU

— 14/12/2016 Key 2 Km 05721 Key 0

