

Thank you for ordering from us!

www.checkvin.eu

Vehicle

BMW 418D A, 110KW

WBA4E71090G519112



Development code

Colour

Actual integration level

Start of warranty

F36

mineral-weiss metallic

F020-23-07-530

23 December 2015

Technical campaigns

There are no Campaigns for this vehicle.

Warranty extension/VIN-based goodwill

Status	Campaign number	Description
Open	1SACC011056	Exhaust gas recirculation cooler Bx7 Local campaign number: -

Special information

There are no Campaigns for this vehicle.

Restrictions on the warranty

There are no restrictions on the warranty.

⚠ Market-specific restrictions are not currently displayed. Please check this in WDF/WXE via S-Gate.

Live Diagnosis

 There are no service solutions for Live Diagnosis.

Service contracts

No BSI contracts

Information on faults workshop/Service Consultation

There is no information on faults.

Navigation map

Note: The installed map cannot be clearly identified. Presumably one of the following maps is present in the vehicle.

Installed map	Enabling code (subscription)	Latest navigation map included in subscription	Latest navigation map subject to charge
Road Map EUROPE EVO 2015-3+ (As of: 29 Sept 2023)	Enabling code valid for navigation maps with release date up to 31 Dec 2099 (SWID: 00F10FFF).	Road Map EUROPE EVO 2025-1	-
Road Map EUROPE EVO 2015-3+ (As of: 29 Sept 2023)	-	-	-

Vehicle details

Vehicle type	Passenger car
Brand	BMW
Model	418D A
Body	COUPE
Vehicle identification number (last 7 digits)	G519112
Vehicle identification number (17 digits)	WBA4E71090G519112
Development code	F36
Steering	LL
Engine	B47U
Engine number	54839466
Exhaust re-treatment	EURO6, W, PI/CI, M, N1 I
Transmission	AUT
Transmission number	0287137ZQB
Head unit serial number	HB2140F7695119
Drive	HECK
Integration level, works	F020-15-11-503
Production date	10 Dec 2015
Production plant	Dingolfing
Delivery date	14 Dec 2015
Delivering retailer	Bilia Libramont, Libramont, BE
National-market version	EUR
Paint code	A96
Upholstery code	KCSW
Model code	4E81
Basic type	4E71
Lead type	4E81

Optional equipment

Optional equipment ex works:

- 01CA Selection of COP-relevant vehicles
- 01CB CO2 equipment
- 0205 Automatic transmission
- 0230 Extra package, EU-speciifc
- 0258 Tyres with runflat properties
- 02A5 BMW LA wheel, double spoke 397
- 02PA Locking wheel bolt
- 02VB Tyre pressure display
- 0302 Alarm system
- 0316 automatic trunk lid mechanism
- 03AC Trailer coupling
- 03BE Mirror caps black
- 0403 Glass roof, electrical
- 0420 Sun protection glazing
- 0423 Floor mats velours
- 0431 Interior mirror with automatic-dip
- 0465 Through-loading system
- 0481 Sports seat
- 0488 Lumbar support, driver and passenger
- 0493 Storage compartment package
- 04AE Armrest front, retractable
- 04FT Alum. brushed lengthw. acc. black hi-gls
- 0502 Headlight cleaning system
- 0508 Park Distance Control (PDC)
- 0521 Rain sensor
- 0534 Automatic air conditioning
- 0544 Cruise control with braking function
- 0548 Kilometre speedo
- 0552 Adaptive LED headlight
- 0563 Light package
- 05AC High-beam assistant
- 05DA Passenger airbag deactivation
- 0609 Navigation system Professional
- 0698 Area-Code 2 for DVD
- 06AC Intelligent emergency call
- 06AE Teleservices
- 06NS Comfort telephony w/ enhanced Smartphone
- 06WA Instrument panel with extended scope
- 0710 M leather steering wheel
- 0775 Headlining anthracite
- 07AC Sport Line
- 07LD Modell Sport Line
- 0854 Language version, French
- 0881 On-board literature, French
- 08KA Oil service interval 24 mths / 30,000 km
- 08S3 Automatic locking during starting
- 08SM Car ident. number visible from outside
- 09AA Outer skin protection
- A090 90 Ah AGM battery
- KLED Leatherette

Retrofitted optional equipment:

This vehicle has no retrofits.

Vehicle histories

	Date	Type	Vehicle mileage	Retailer	Overview
—	29/09/2023	Key	206529 Km	05654	Key 0

EGR cooler (high-temperature)
 Job: E84 Fx Gx Bx7 Nx7 Customer
 notification exhaust gas
 recirculation cooler
 Job: G0x G3x B47O Programming
 control units (DDE)
 Job: Fx Replace driver's airbag Part
 II (SDI)

- Job: F1x F2x F3x G0x G1x G3x B47O B47K B47U B47T Replacing EGR cooler (high-temperature)

Description: F1x F2x F3x G0x G1x G3x B47O B47K B47U B47T Replacing EGR cooler (high-temperature)

Considered as a repeat visit No

Customer's own words

Replace exhaust gas recirculation cooler, including exhaust gas recirculation valve Flat rate unit I 00 74 649	23 FRU
--	--------

F1x F2x F3x G0x G1x G3x B47O B47K B47U B47T Replacing EGR
cooler (high-temperature)
Defect I 00 11 15 07 00

Exhaust gas radiator high temperature Part I 11 71 7 822 347	1
---	---

Holder Part I 61 13 1 369 832	1
----------------------------------	---

Pipe union Part I 11 71 7 799 853	1
--------------------------------------	---

Vacuum hose black Part I 11 65 8 595 650	1
---	---

EGR small parts set Part I 11 71 8 490 640	1
---	---

Connection piece Part I 11 65 7 803 012	1
--	---

Acoustic cover front Part I 11 14 8 490 577	1
--	---

O-ring Part I 11 61 8 512 681	1
----------------------------------	---

- Job: E84 Fx Gx Bx7 Nx7 Customer notification exhaust gas recirculation cooler

Description: E84 Fx Gx Bx7 Nx7 Customer notification exhaust gas recirculation cooler

Considered as a repeat visit No

Customer's own words

Administrative effort Flat rate unit I 00 74 758	1 FRU
---	-------

E84 Fx Gx Bx7 Nx7 Customer notification exhaust gas recirculation
cooler
Defect I 00 11 35 07 00

- Job: G0x G3x B47O Programming control units (DDE)

Description: G0x G3x B47O Programming control units (DDE)

Considered as a repeat visit No

Customer's own words

Program control units Flat rate unit I 00 71 940	8 FRU
---	-------

G0x G3x B470 Programming control units (DDE)
Defect I 00 13 51 03 00

— Job: Fx Replace driver's airbag Part II (SDI)

Description: Fx Replace driver's airbag Part II (SDI)

Considered as a repeat visit No


Customer's own words

Replace driver's airbag Flat rate unit I 00 73 941	3 FRU
---	-------

Fx Replace driver's airbag Part II (SDI) Defect I 00 32 42 03 00

Airbag module, driver's side Part I 32305A66F66	1
--	---

— 06/10/2021 Service 144612 Km OSS-60033744 Multi Group SPRL, Jemeppe-sur-Meuse Manual




— 10/09/2021 Key 142233 Km Key 0




— 12/12/2020 Service 118124 Km OSS-60033744 Multi Group SPRL, Jemeppe-sur-Meuse Manual




— 14/01/2020 Key 95609 Km 05606 Key 0




— 06/01/2020 Key 95559 Km 40686 Key 1




— 18/12/2019 Key 95559 Km 40686 Key 1



— 02/12/2019 Key 94116 Km 40686 Key 1



— 13/11/2019 Key 93114 Km 40686 Key 1



— 23/09/2019 Key 89124 Km 40686 Key 1



— 23/09/2019 Key 89124 Km 40686 Key 1



— 23/09/2019 Service 89124 Km 40686 Bilia-Emond Libramont, Libramont Automatic



— 03/04/2019 Key 77179 Km Key 1




— 23/01/2019 Key 73608 Km 40686 Key 1



— 23/01/2019 Key 73607 Km Key 1



— 23/01/2019 Service 73607 Km 40686 Bilia-Emond Libramont, Libramont Automatic



— 23/01/2019 Warranty 73607 Km 40686 Job

— Job

Description:

Considered as a repeat visit No

Customer's own words

Checking index exhaust-gas recirculation cooler (no further repairs necessary afterwards)
Flat rate unit I 00 67 709


3 FRU

Defect I 00 11 10 05 00


— 06/11/2018 Key 68613 Km Key 1



— 06/11/2018 Service 68613 Km 40686 Bilia-Emond Libramont, Libramont Automatic



— 04/05/2018 Key 57835 Km 40686 Key 1



— 04/05/2018 Service 57835 Km 40686 Bilia-Emond Libramont, Libramont Automatic

							
900	900	900	900	13000	0	10000	900
01/1970	12/2018	12/2018	12/2018	01/1970	01/1970	01/1970	01/1970
✓	✓	✓	✓				✓

- 04/05/2018 Warranty 57835 Km 40686 Job: F1x F2x F3x B47 programming control units and if necessary, replacing the EGR valve

- Job: F1x F2x F3x B47 programming control units and if necessary, replacing the EGR valve

Description: F1x F2x F3x B47 programming control units and if necessary, replacing the EGR valve

Considered as a repeat visit No

Customer's own words

Carrying out the ABL and programming the control units
Flat rate unit I 00 64 941

8 FRU

F1x F2x F3x B47 programming control units and if necessary, replacing the EGR valve
Defect I 00 11 45 04 00

- 09/04/2018 Key 56071 Km 40686 Key 1

							
2600	2600	2600	2600	14000		12000	2600
01/2019	262	262	262		12/2018		01/2019

- 27/11/2017 Key 49626 Km 40686 Key 1

							
9000	9000	9000	9000	21000		19000	9000
01/2019	394	394	394		12/2018		01/2019

- 27/11/2017 Warranty 49626 Km 40686 Job: EGR cooler (incl. bypass flap) / exhaust cooler

- Job: EGR cooler (incl. bypass flap) / exhaust cooler

Description: EGR cooler (incl. bypass flap) / exhaust cooler

Considered as a repeat visit No

Customer's own words

Removing and installing or replacing EGR cooler
Flat rate unit I 11 71 100

25 FRU

EGR cooler (incl. bypass flap) / exhaust cooler
Defect I 11 71 06 48 00

Exhaust gas radiator high temperature
Part I 11 71 8 513 691

1

Gasket Steel
Part I 11 61 8 571 005

1

Pipe union
Part I 11 71 7 799 853

1

Gasket Steel
Part I 11 62 8 576 287

1

- 16/11/2017 Key 49115 Km 40686 Key 1

 10000 01/2019	 10000 441	 10000 441	 10000 441	 22000	 0 12/2018	 19000	 10000 01/2019
---	---	---	---	--	---	--	---

- 16/11/2017 Warranty 49115 Km 40686 Job: EGR cooler (incl. bypass flap) / exhaust cooler
Job: Headunit High HU-H

- Job: EGR cooler (incl. bypass flap) / exhaust cooler

Description: EGR cooler (incl. bypass flap) / exhaust cooler

Considered as a repeat visit No

Customer's own words

Bleed the cooling system and check it for watertightness with the special tool 5 FRU
Flat rate unit I 17 00 039

EGR cooler (incl. bypass flap) / exhaust cooler
Defect I 11 71 06 48 00

- Job: Headunit High HU-H

Description: Headunit High HU-H

Considered as a repeat visit No

Customer's own words

Performing vehicle test 0 FRU
Flat rate unit I 00 00 006

Supporting the voltage of the vehicle electrical system/recharging the vehicle electrical system battery 1 FRU
Flat rate unit I 61 21 528

Programming/encoding control unit(s) including deleting fault memories 4 FRU
Flat rate unit I 61 00 730

Continuing vehicle test and deleting fault memory 2 FRU
Flat rate unit I 61 00 980

Performing vehicle test 2 FRU
Flat rate unit I 00 00 556

Headunit High HU-H
Defect I 65 12 58 02 00

- 19/04/2017 Key 35234 Km 40686 Key 1

 23000 01/2019	 23000 652	 23000 652	 23000 652	 34000	 0 12/2018	 32000	 23000 01/2019
---	---	---	---	--	---	--	---

- 16/02/2017 Key 31250 Km 05606 Key 1

 27000 01/2019	 27000 714	 27000 714	 27000 714	 39000	 0 12/2018	 36000	 27000 01/2019
---	---	---	---	--	---	--	---

- 15/02/2017 Key 31200 Km 40686 Key 1

 27000 01/2019	 27000 715	 27000 715	 27000 715	 39000	 0 12/2018	 36000	 27000 01/2019
—	11/01/2017	Key	28717 Km	40686	Key 1		
 700 12/2017	 0	 700 354	 0	 43000	 0 12/2018	 41000	 29000 12/2019
—	11/01/2017	Service	28717 Km	40686	Bilia-Emond Libramont Bilia-Emond Libramont , Libramont	Automatic	
 700 12/2017 ✓		 700 12/2017 ✓		 43000	 12/2018	 41000	 29000 12/2019
—	28/11/2016	Key	26294 Km	40686	Key 1		
 3300 12/2017	 0	 3300 398	 0	 47000	 0 12/2018	 47000	 32000 12/2019
—	15/11/2016	Key	25582 Km	40686	Key 1		
 4100 12/2017	 0	 4100 411	 0	 49000	 0 12/2018	 48000	 35000 12/2019
—	21/03/2016	Key	6260 Km	40686	Key 1		
 23000 12/2017	 0	 23000 650	 0	 50000	 0 12/2018	 50000	 60000 12/2019
—	02/03/2016	Key	4740 Km	40686	Key 1		
 25000 12/2017	 0	 25000 669	 0	 50000	 0 12/2018	 50000	 60000 12/2019
—	06/01/2016	Key	484 Km	40686	Key 1		
 29000 12/2017	 0	 29000 724	 0	 50000	 0 12/2018	 50000	 60000 12/2019
—	05/01/2016	Key	418 Km	40686	Key 1		

							
29000	0	29000	0	50000	0	50000	60000
12/2017		725			12/2018		12/2019