

BMW Group - AIR: 2025-10-13 / 15:41
Retailer: 31520/01
Model: 518D A
Vehicle identification number: WBA5E31050D786942
Development code: F10
Model code: 5E41
Lead type: 5E41

Vehicle

BMW 518D A, 110KW
WBA5E31050D786942



Development code F10
Colour Jatoba metallic
Actual integration level F010-23-07-530
Start of warranty 30 December 2014

Delivery stop

 Technical Campaigns are available.

Technical campaigns

Status	Campaign number	Description	Reservation
Open	10032550300	Check the driver's airbag, replace if necessary (conversion SDI)  Delivery stop Local campaign number: -	

Warranty extension/VIN-based goodwill

Status	Campaign number	Description

Open	1SACC011056	Exhaust gas recirculation cooler Bx7 Local campaign number: -
------	-------------	--

Special information

There are no Campaigns for this vehicle.

Restrictions on the warranty

There are no restrictions on the warranty.

 Market-specific restrictions are not currently displayed. Please check this in WDF/WXE via S-Gate.

Live Diagnosis

 There are no service solutions for Live Diagnosis.

Service contracts

No BSI contracts

Information on faults workshop/Service Consultation

There is no information on faults.

Navigation map

Installed map	Enabling code (subscri...	Latest navigation map included in subscription	Latest navigation map subject to charge
	Enabling code valid for navigation maps with		

Road Map EUROPE Next 2015-1 (As of: 2 Apr 2024)	release date up to 31 Dec 2025 (SWID: 00A9008F).	Road Map EUROPE EAST Next 2025	-
---	--	-----------------------------------	---

Vehicle details

Vehicle type	Passenger car
Brand	BMW
Model	518D A
Body	LIM
Vehicle identification number (last 7 digits)	D786942
Vehicle identification number (17 digits)	WBA5E31050D786942
Development code	F10
Steering	LL
Engine	B47O
Engine number	91459104
Exhaust re-treatment	EURO6, W, PI/CI, M, N1 I
Transmission	AUT
Transmission number	0045477WAE
Head unit serial number	HB2068E7974840
Drive	HECK
Integration level, works	F010-14-11-502
Production date	12 Dec 2014
Production plant	Dingolfing

Delivery date	17 Dec 2014
Delivering retailer	Beliën Lommel, Lommel, BE
National-market version	EUR
Paint code	B65
Upholstery code	LCEZ
Model code	5E41
Basic type	5E31
Lead type	5E41

Optional equipment

Optional equipment ex works:

01CA Selection of COP-relevant vehicles
 01CB CO2 equipment
 01CC Auto start/stop function
 01CD Brake Energy Regeneration
 0205 Automatic transmission
 0230 EU-specific additional contents
 0255 Sports leather steering wheel
 02K1 BMW LA wheel, V spoke 236
 02PA Locking wheel bolt
 02VB Tyre pressure display
 0302 Alarm system
 0316 automatic trunk lid mechanism
 0322 Comfort access
 03AC Trailer coupling
 03AG Reversing camera
 0423 Floor mats velours
 0430 Interior/outside mirror with auto dip
 0431 Interior mirror with automatic-dip
 0465 Through-loading system
 0494 Seat heating driver/passenger
 04AT Interior trim finishers black high-gloss
 04U2 Driving experience switch incl. ECO PRO
 04UR Ambient interior light
 0502 Headlight cleaning system

Retrofitted optional equipment:

This vehicle has no retrofits.

- 0508 Park Distance Control (PDC)
- 0524 Adaptive headlights
- 0534 Automatic air conditioning
- 0548 Kilometre speedo
- 05AC High-beam assistant
- 0609 Navigation system Professional
- 0688 Harman/Kardon surround sound system
- 0698 Area-Code 2 for DVD
- 06AC Intelligent emergency call
- 06AE Teleservices
- 06NS Comfort telephony w/ enhanced Smartphone
- 0761 Individual sunshade glazing
- 0843 Power reduction
- 0868 Language version Dutch
- 0877 Omission of non-combined operation
- 0886 On-board literature, Dutch
- 08KA Oil service interval 24 mths / 30,000 km
- 08S3 Automatic locking during starting
- 08TF Active pedestrian protection
- A105 105 Ah AGM battery
- LEDE Leather equipment

Vehicle histories

Date		Type	Vehicle mileage			Retailer Overview		
08/04/2024		Key	215619 Km			05617	Key 0	
								
15000	15000	15000	15000	15000			120000	15000
10/2025	10/2025	10/2025	10/2025		10/2025	10/2025		10/2025
05/04/2024		Key	215439 Km			05617	Key 0	
								

								
16000	16000	16000	16000	15000			120000	16000
10/2025	10/2025	10/2025	10/2025		10/2025	10/2025		10/2025

—

05/04/2024

Repair

215619 Km

05617

Job

Job

, Brugge

— Job

Description:

Considered as a repeat visit No

Customer's own words

Remove and install/replace the door lock on the left or right rear doors	10 FRU
Flat rate unit 51 22 090	
System latch, right	1
Part 51 22 7 202 148	
Torx bolt	10
Part 07 14 7 186 859	
Clip with washer, natur	1
Part 51 41 8 224 768	

— Job

Description:

Considered as a repeat visit No

Customer's own words

Huurwagen BMW 116i	Local	1
Part H2DRD936		

—

02/04/2024

Key

215407 Km

05617

Key 0

								
16000	16000	16000	16000	15000			120000	16000
10/2025	10/2025	10/2025	10/2025		10/2025	10/2025		10/2025

—

25/03/2024

Key

215100 Km

05617

Key 0

								
16000	16000	16000	16000	15000			120000	16000
10/2025	10/2025	10/2025	10/2025		10/2025	10/2025		10/2025

—

27/02/2024

Repair

215619 Km

05617

Job

Job

, Brugge

Job

Job

Job

Job

— Job

Description:

Considered as a repeat visit No

Customer's own words

Sputwerk deurgreep	Local	1 FRU
Flat rate unit I -		
Removing and installing/replacing left or right front outside door handle		3 FRU

Flat rate unit | 51 21 170

Continuing vehicle test and deleting fault memory	2 FRU
---	-------

Flat rate unit | 61 00 980

Handle grip, primed, right	1
----------------------------	---

Part | 51 21 7 249 980

Grip, door handle, outside right	1
----------------------------------	---

Part | 51 21 7 316 388

— Job

Description:

Considered as a repeat visit No

Customer's own words

Checking lighting system for correct operation	2 FRU
--	-------

Flat rate unit | 63 00 009

— Job

Description:

Considered as a repeat visit No

Customer's own words

Performing vehicle test	4 FRU
-------------------------	-------

Flat rate unit | 00 00 006

Supporting the voltage of the vehicle electrical system/recharging the vehicle electrical system battery	1 FRU
--	-------

Flat rate unit | 61 21 528

Vehicle diagnosis - carrying out the ABL	4 FRU
--	-------

Flat rate unit | 61 00 006

— Job

Description:

Considered as a repeat visit No

Customer's own words

Job

— Description:
Considered as a repeat visit No
Customer's own words

— Job

Description:
Considered as a repeat visit No
Customer's own words

— Job

Description:
Considered as a repeat visit No
Customer's own words

—	09/02/2024	Key		213342 Km	05617	Key 0					
											
	19000	19000	19000	19000	16000			120000	19000		
	10/2025	10/2025	10/2025	10/2025		10/2025	10/2025		10/2025		

—	09/02/2024	Warranty		213342 Km	05617	Job: F1x F2x F3x G0x G1x G3x B47O B47K B47U B47T Replacing EGR cooler (high- temperature) Job: G0x G3x B47O
---	------------	----------	--	-----------	-------	---

- Job: F1x F2x F3x G0x G1x G3x B47O B47K B47U B47T Replacing EGR cooler (high-temperature)

Description: F1x F2x F3x G0x G1x G3x B47O B47K B47U B47T Replacing EGR cooler (high-temperature)

Considered as a repeat visit No

Customer's own words

Replace exhaust gas recirculation cooler, including exhaust gas recirculation valve	20 FRU
Flat rate unit I 00 74 649	

Additional work: run function test for pressure sensor system	3 FRU
Flat rate unit I 00 74 650	

Additional work: enter component identification of new exhaust gas recirculation cooler in diagnostic system	1 FRU
Flat rate unit I 00 74 651	

F1x F2x F3x G0x G1x G3x B47O B47K B47U B47T Replacing EGR cooler (high-temperature)	
Defect I 00 11 15 07 00	

Exhaust gas radiator high temperature	1
Part I 11 71 7 822 347	

EGR small parts set	1
Part I 11 71 8 490 640	

Pipe union	2
Part I 11 71 7 799 853	

Holder	1
Part I 61 13 1 369 832	

Connection piece	1
Part I 11 65 7 803 012	

O-ring	1
Part I 11 61 8 512 681	

Acoustic cover front	1
----------------------	---

— Job: G0x G3x B47O Programming control units (DDE)

Description: G0x G3x B47O Programming control units (DDE)

Considered as a repeat visit No

Customer's own words

Program control units 8 FRU
Flat rate unit I 00 71 940

G0x G3x B47O Programming control units (DDE)
Defect I 00 13 51 03 00

10/01/2024 Key212141 Km05617 Key 0



21000

10/2025



21000

10/2025



21000

10/2025



21000

10/2025



16000



10/2025



10/2025



120000



21000

10/2025

24/01/2023 Key188538 KmKey 0



18000

09/2024





18000

09/2024





35000



09/2024



09/2024



100000



48000

09/2026

10/10/2017 Key96766 Km05681 Key 0




















— 10/10/2017 Service 96766 Km 05681 Automatic
 Beli n
 Lommel
 nv Beli
 n
 Lommel
 ,
 Lommel



— 10/10/2017 Repair 96766 Km 05681 Job
 Beliën
 Lommel
 ,
 Lommel

— Job

Description:

Considered as a repeat visit No

Customer's own words

Laadwens van de klant: Full Local 0 FRU
 Flat rate unit I -

Initiële laadtoestand hoog-voltage accu (SoC): 255% Local 0 FRU
 Flat rate unit I -

Service - standard scope
 Package I 0000105

Service - standard scope 2
 Flat rate unit I 00 00 105

Engine oil service

Package I 0000610

Engine oil service	3
Flat rate unit I 00 00 610	
Set oil-filter element	1
Part I 11428575211	
BMW Engine Oil LL04 5W30	5
Part I 83212405948	

Service, front brakes

Package I 0000612

Service, front brakes	7
Flat rate unit I 00 00 612	
Repair kit, brake pads asbestos-free	1
Part I 34116858047	
Brake pad wear sensor, front left	1
Part I 34356791958	
Brake-pad paste	2
Part I 83192158851	
Brake cleaner acetone-free	1
Part I 83192413695	

Service, rear brakes

Package I 0000614

Service, rear brakes	8
Flat rate unit I 00 00 614	
Repair kit, brake pads asbestos-free	1
Part I 34216862202	
Brake-pad sensor, rear	1
Part I 34356791962	
Brake-pad paste	2
Part I 83192158851	
Brake cleaner acetone-free	1
Part I 83192413695	

Microfilter service

Package I 0000616

Microfilter service	2
---------------------	---

micromiter service Flat rate unit I 00 00 616	3
Set, microfilter/carbon canister Part I 64119272642	1
Pollen-filter housing cleaner Part I 83192180509	1


Brake fluid service Package I 0000618

Brake fluid service Flat rate unit I 00 00 618	4
Brake fluid DOT4 LV, low viscosity Part I 83132184843	1

Service, vehicle check Package I 0000624

Service, vehicle check Flat rate unit I 00 00 624	7
--	---

— 14/04/2017 Key 80051 Km 05718 Key 0



— 14/04/2017 Warranty 80051 Km 05718 Job: F0x F1x N47 B47 Replace air conditioning condenser Job

— Job: F0x F1x N47 B47 Replace air conditioning condenser

Description: F0x F1x N47 B47 Replace air conditioning condenser

Considered as a repeat visit No

Customer's own words

Check and replace air conditioning capacitor 17 FRU

Flat rate unit | 00 64 293

F0x F1x N47 B47 Replace air conditioning condenser

Defect | 00 64 93 01 00

Condenser, air conditioning

1

Part | 64 50 9 391 489

Gasket ring

1

Part | 64 50 8 375 741

Gasket ring

1

Part | 64 50 8 374 959

Hex Bolt

2

Part | 07 14 7 029 829

— Job

Description:

Considered as a repeat visit No

Customer's own words

Replacing the exhaust-gas recirculation cooler

22 FRU

Flat rate unit | 00 64 199

Defect | 00 11 36 04 00

exhaust cooler

1

Part | 11 71 8 596 444

Set of small parts

1

Part | 11 71 8 597 652

Pipe union

2

Part | 11 71 7 799 853

Oval head screw









2

Part | 35 21 7 685 343

— 22/12/2016 Key

70320 Km

05718 Key 0



—	15/07/2016	Key			55262 Km	05681	Key 0		
									
	800	800	800		800	2100	0	6000	800
	09/2017	442	442		442		12/2017		09/2017
—	15/07/2016	Service			55262 Km	05681	Automatic		
							Beli n		
							Lommel		
							nv Beli		
							n		
							Lommel		
							'		
							Lommel		
									
	800	800	800		800	2100		6000	800
	09/2017	09/2017	09/2017		09/2017		12/2017		09/2017
	✓	✓	✓		✓	✓			✓
—	15/07/2016	Repair			55262 Km	05681	Job		
							Beliën		
							Lommel		
							'		
							Lommel		
—	Job								

Description:

Considered as a repeat visit No

Customer's own words

Hoge bezoekfrequentie. Herhalingsreparatie? Local 0 FRU
 Controleer de reparatiehistorie.
 Flat rate unit I -

Laadwens van de klant: Full Local 0 FRU
 Flat rate unit I -

Initiële laadtoestand hoog-voltage accu (SoC): 255% Local 0 FRU

Flat rate unit | -

Service - standard scope

Package | 0000105

Service - standard scope	2
Flat rate unit 00 00 105	

Service - air filter element

Package | 0000602

Service - air filter element	1
Flat rate unit 00 00 602	

Air filter element	1
Part 13718570043	

Service fuel filter

Package | 0000604

Service fuel filter	5
Flat rate unit 00 00 604	

Fuel filter cartridge	1
Part 13327811227	

Hose clamp	1
Part 16121180240	

Engine oil service

Package | 0000610

Engine oil service	3
Flat rate unit 00 00 610	

Set oil-filter element	1
Part 11428575211	

BMW Engine Oil LL04 5W30	5
Part 83212405948	

Service, front brakes

Package | 0000612

Service, front brakes	7
Flat rate unit 00 00 612	

Repair kit, brake pads asbestos-free	1
Part 34116858047	

Brake disc	1
------------	---

Brake pad wear sensor, front left Part I 34356791958	1
Brake-pad paste Part I 83192158851	2
Brake cleaner acetone-free Part I 83192413695	1


Microfilter service
Package I 0000616

Microfilter service Flat rate unit I 00 00 616	3
Set, microfilter/carbon canister Part I 64119272642	1
Pollen-filter housing cleaner Part I 83192180509	1

Service, vehicle check
Package I 0000624

Service, vehicle check Flat rate unit I 00 00 624	7
--	---

— 21/03/2016 Key 46092 Km 05718 Key 0



— 21/03/2016 Warranty 46092 Km 05718 Job: EGR cooler (incl. bypass flap) / exhaust cooler
Job

— Job: EGR cooler (incl. bypass flap) / exhaust cooler

Description: EGR cooler (incl. bypass flap) / exhaust cooler

Considered as a repeat visit No

Customer's own words

Performing vehicle test 4 FRU
Flat rate unit | 00 00 006

Supporting the voltage of the vehicle electrical system/recharging the vehicle electrical system battery 1 FRU
Flat rate unit | 61 21 528

Removing and installing or replacing EGR cooler 15 FRU
Flat rate unit | 11 71 600

EGR cooler (incl. bypass flap) / exhaust cooler
Defect | 11 71 06 48 00

Exhaust gas radiator high temperature 1
Part | 11 71 8 513 691

Pipe union 2
Part | 11 71 7 799 853

Gasket Steel 1
Part | 11 61 8 571 005

— Job

Description:

Considered as a repeat visit No









Customer's own words

Performing vehicle test 3 FRU
Flat rate unit | 00 00 556

Job time without allowance for / engine 5 FRU
Flat rate unit | 11 99 000

Defect | 10 42 02 35 00

— 18/09/2015 Key 27178 Km 05681 Key 0



18/09/2015 Service

27178 Km

05681 Automatic

Beli n
Lommel
nv Beli
n
Lommel
,
Lommel



18/09/2015 Repair

27178 Km

05681 Job

Beliën
Lommel
,
Lommel

Job

Description:

Considered as a repeat visit No

Customer's own words

Service - standard scope

Package I 0000105

Service - standard scope

Flat rate unit I 00 00 105

2

Engine oil service

Package I 0000610

Engine oil service

Flat rate unit I 00 00 610

3

Set oil-filter element

Part I 11428575211

1

BMW Engine Oil LL04 5W30

Part I 83212405948

5

Microfilter service

Package I 0000616

Microfilter service	3
Flat rate unit I 00 00 616	

Set, microfilter/carbon canister	1
Part I 64119272642	

Pollen-filter housing cleaner	1
Part I 83192180509	