

Thank you for ordering from us!

www.checkvin.eu

Vehicle

BMW 320D XDR A, 140KW

WBA8J11000K626797



Development code F31
Colour alpinweiss 3
Actual integration level F020-22-07-530
Start of warranty 18 December 2015

Delivery stop



Technical Campaigns are available.

Technical campaigns

Status	Campaign number	Description	Reservation
Open	10011130700	Replacing the exhaust gas recirculation cooler (high temperature)  Delivery stop Local campaign number: SK	
Open	10011350700	Exhaust gas recirculation cooler customer notification Local campaign number: SK	
Open	10032550300	Check the driver's airbag, replace if necessary (conversion SDI)  Delivery stop Local campaign number: -	

Warranty extension/VIN-based goodwill

Status	Campaign number	Description
Open	1SACC011056	Exhaust gas recirculation cooler Bx7 Local campaign number: -

Special information

There are no Campaigns for this vehicle.

Restrictions on the warranty

There are no restrictions on the warranty.

⚠ Market-specific restrictions are not currently displayed. Please check this in WDF/WXE via S-Gate.

Live Diagnosis

 There are no service solutions for Live Diagnosis.

Service contracts

No BSI contracts

Information on faults workshop/Service Consultation

There is no information on faults.

Navigation map

Note: The installed map cannot be clearly identified. Presumably one of the following maps is present in the vehicle.

Installed map	Enabling code (subscription)	Latest navigation map included in subscription	Latest navigation map subject to charge
Road Map EUROPE EVO 2017-3 (As of: 18 Dec 2018)	-	-	-
Road Map EUROPE EVO 2017-3 (As of: 18 Dec 2018)	Enabling code valid for navigation maps with release date up to 31 Dec 2099 (SWID: 00F10FFF).	Road Map EUROPE EVO 2025-1	-

Vehicle details

Vehicle type	Passenger car
Brand	BMW
Model	320D XDR A
Body	TOUR
Vehicle identification number (last 7 digits)	K626797
Vehicle identification number (17 digits)	WBA8J11000K626797
Development code	F31
Steering	LL
Engine	B47O
Engine number	50919426
Exhaust re-treatment	EURO6, W, PI/CI, M, N1 I
Transmission	AUT
Transmission number	0083401ZN5
Head unit serial number	HB2140F7680702
Drive	ALLR
Integration level, works	F020-15-11-502
Production date	2 Nov 2015

Production plant	Muenchen
Delivery date	17 Nov 2015
Delivering retailer	Auto-Müller GmbH, Buchen-Hettingen, DE
National-market version	EUR
Paint code	300
Upholstery code	CCL1
Model code	8J21
Basic type	8J11
Lead type	8J21

Optional equipment

Optional equipment ex works:

01CA Selection of COP-relevant vehicles
 0205 Automatic transmission
 0216 Hydro steering-servotronic
 0230 EU-specific additional contents
 024B BMW LA wheel, double spoke 397
 0255 Sports leather steering wheel
 0258 Tyres with runflat properties
 02VB Tyre pressure display
 0302 Alarm system
 0320 Deleted, model lettering
 0322 Comfort access
 03AA Roof railing black
 03AC Trailer coupling
 03DZ Omission of additional lettering, outer
 0423 Floor mats velours
 0428 Warning triangle and first aid kit
 0431 Interior mirror with automatic-dip
 0481 Sports seat
 0488 Lumbar support, driver and passenger
 0493 Storage compartment package
 0494 Seat heating driver/passenger
 04AE Armrest front, retractable
 04LV black high-gloss accent korall-rot
 0508 Park Distance Control (PDC)
 0521 Rain sensor
 0534 Automatic air conditioning
 0544 Cruise control with brake function
 0548 Kilometre speedo
 0552 Adaptive LED headlight
 0563 Light package
 0575 Additional 12V sockets
 05A1 LED Fog lights
 05AC High-beam assistant
 05AS Driving Assistant
 05DA Passenger airbag deactivation
 05DC Rear-seat headrests, folding
 0609 Navigation system Professional
 0610 Head-up display
 0698 Area-Code 2 for DVD
 06AC Intelligent emergency call
 06AE Teleservices
 06AK Connected Drive Services
 06AM Real-Time Traffic Information
 06AN Concierge Services
 06AP Remote Services
 06NS Comfort telephony w/ enhanced Smartphone
 06WA Instrument panel with extended scope
 07AC Sport Line
 07LD Modell Sport Line
 07R7 Innovation package

Retrofitted optional equipment:

This vehicle has no retrofits.

								
10000	10000	10000	10000	34000		26000	38000	
-41 5.6 %	-41 5.6 %	-41 5.6 %	-41 5.6 %		-41 5.6 %		07/2024	-641 87.7 %

Customer's own words

F1x F2x F3x B47O B47K B47U Programming control units (DDE)
Defect | 00 13 50 03 00

								
10000	10000	10000	10000	34000	26000	38000		
-34 4.7 %	-34 4.7 %	-34 4.7 %	-34 4.7 %		-34 4.7 %		07/2024	-634 86.8 %

Customer's own words

Supporting the voltage of the vehicle electrical system/recharging the vehicle electrical system battery	1 FRU
--	-------

Flat rate unit | 61 21 528

Inlet valve

Defect | 11 34 00 76 00

Profile-gasket

Part | 11 61 7 633 521

1

Gasket Steel

Part | 11 61 8 508 626

1

Profile-gasket

Part | 11 61 8 571 001

4

Gasket ring

Part | 13 53 2 247 156

4

— Job: Cylinder head cover gasket

Description: Cylinder head cover gasket

Considered as a repeat visit No

Customer's own words

Removing and installing/sealing cylinder head cover

Flat rate unit | 11 12 601

0 FRU

Cylinder head cover gasket

Defect | 11 12 01 48 00

Gasket set, cylinder head cover

Part | 11 12 8 583 293

1

O-ring

Part | 13 62 8 658 854

1

— Job: Seal between mounting bracket and engine oil pan

Description: Seal between mounting bracket and engine oil pan

Considered as a repeat visit No

Customer's own words

Replacing radial shaft seal for input flange of front axle differential

Flat rate unit | 31 51 510

0 FRU

Replacing radial shaft seal for input flange of front axle differential

Flat rate unit | 31 51 511

0 FRU

Replacing radial shaft seal for output shaft, right

Flat rate unit | 31 51 522

0 FRU

Replacing right O-ring for front final drive

Flat rate unit | 31 51 560

0 FRU

Kinematics Diagnosis System wheel alignment with ride height measurement without loading the vehicle

Flat rate unit | 32 00 595

0 FRU

Adjusting rear axle and front axle

Flat rate unit | 32 00 630

0 FRU

Seal between mounting bracket and engine oil pan

Defect | 31 50 11 48 00

Torx screw with collar

Part | 07 14 7 270 121

2

Securing plate

Part | 23 21 1 490 120

1

Torx screw with ribs

Part | 26 11 7 529 387

8

Hex Bolt with washer Part I 31 10 6 854 219	2
Hex Bolt with washer Part I 31 10 6 858 433	10
Collar bolt with compression spring Part I 31 20 6 795 249	2
Ventilation connection Part I 31 50 7 595 196	1
Shaft seal with lock ring Part I 31 50 8 743 675	2
O-ring Part I 31 51 1 213 527	2
Shaft seal Part I 31 52 1 428 678	1
Screw plug with O-ring Part I 33 11 7 525 064	2
Self-locking collar nut Part I 33 32 6 760 668	2
Hexagon nut with collar Part I 33 32 6 768 884	2

10/12/2018			Key			157007 Km			Key 0		
											
27000	0		27000	0	27000	0	20000	27000	0		
11/2020			721			11/2020		11/2020	11/2020		

10/12/2018	Repair	157007 Km	00490 Auto-Müller GmbH , Buchen-Hettingen	Job Job Job
------------	--------	-----------	--	-------------------

— Job

Description:

Considered as a repeat visit No

Customer's own words

— Job

Description:

Considered as a repeat visit No

Customer's own words


— Job

Description:


Considered as a repeat visit No

Customer's own words

26/11/2018	Key	154943 Km	Key 0
------------	-----	-----------	-------



— 26/11/2018 Service 154943 Km 00490 Auto-Müller GmbH , Automatic
Buchen-Hettingen



— 26/11/2018 Repair 154943 Km 00490 Auto-Müller GmbH , Job
Buchen-Hettingen Job
Job
Job
Job
Job
Job
Job
Job
Job
Job
Job

— Job

Description:

Considered as a repeat visit No

Customer's own words

— Job

Description:

Considered as a repeat visit No

Customer's own words

— Job

Description:

Considered as a repeat visit No

Customer's own words

— Job

Description:

Considered as a repeat visit No

Customer's own words

— Job

Description:

Considered as a repeat visit No

Customer's own words

— Job

Description:

Considered as a repeat visit No

Customer's own words

— Job

Description:

Considered as a repeat visit No

Customer's own words

— Job

Description:

Considered as a repeat visit No

Customer's own words

— Job

Description:

Considered as a repeat visit No

Customer's own words

— Job

Description:

Considered as a repeat visit No

Customer's own words

— Job

Description:

Considered as a repeat visit No

Customer's own words

— Job

Description:

Considered as a repeat visit No

Customer's own words

— Job

Description:

Considered as a repeat visit No

Customer's own words

—	26/11/2018 Repair	154943 Km	00490 Auto-Müller GmbH , Buchen-Hettingen	Job Job Job Job Job Job Job Job Job Job
---	-------------------	-----------	--	--

— Job

Description:**Considered as a repeat visit** No**Customer's own words**

Service - standard scope		2 FRU
Flat rate unit I 00 00 105		

— Job

Description:**Considered as a repeat visit** No**Customer's own words**

Engine oil service		3 FRU
Flat rate unit I 00 00 610		

Satz Ölfiltereinsatz	Local	1
Part I 11 43 8 575 211		

BMW Engine Oil LL04 5W30		5
Part I 83 21 2 405 948		

— Job

Description:**Considered as a repeat visit** No**Customer's own words**

Microfilter service		2 FRU
Flat rate unit I 00 00 616		

Microfilter/activated Carbon container		1
Part I 64 11 9 237 555		

— Job

Description:**Considered as a repeat visit** No**Customer's own words**

Service - air filter element		2 FRU
Flat rate unit I 00 00 602		

Luftfiltereinsatz	Local	1
Part I 13 72 8 511 668		

— Job

Description:**Considered as a repeat visit** No**Customer's own words**

Service fuel filter		3 FRU
Flat rate unit I 00 00 604		

Kraftstofffilterpatrone	Local	1
Part I 13 33 8 572 522		

— Job

Description:**Considered as a repeat visit** No**Customer's own words**

Brake fluid service		4 FRU
---------------------	--	-------

Flat rate unit I 00 00 618

Brake fluid DOT4 LV, low viscosity
Part I 83 13 0 443 030

1

— Job

Description:

Considered as a repeat visit No

Customer's own words

Replace left and right wiper blade
Flat rate unit I 61 61 541

1 FRU

Set of wiper blades
Part I 61 61 2 241 375

1

— Job

Description:

Considered as a repeat visit No

Customer's own words

Replacing the wiper blade for the rear wiper
Flat rate unit I 61 62 520

1 FRU

Wiper blade
Part I 61 62 7 356 763

1

— Job

Description:

Considered as a repeat visit No

Customer's own words

Service pre-check for roadworthiness test (for German market only)
Flat rate unit I 00 00 671

5 FRU

Presentation for emission inspection
Flat rate unit I 00 00 527

1 FRU

Dekra/TÜV Gebühren EXTERN
Part I FT0000153

Local

1

— Job

Description:

Considered as a repeat visit No

Customer's own words

Windshield washer antifreeze
Part I 83 12 2 409 031

1

— Job

Description:

Considered as a repeat visit No

Customer's own words

Sondervereinbarung 87000200001
Flat rate unit I 99 99 999

Local

1 FRU

Job: Service - micro filter/activated carbon filter
 Job: Service - air cleaner
 Job: Service - fuel filter
 Job: Service - brake fluid
 Job: Service - front wiper blade
 Job: Service - rear wiper blade
 Job: Service - legally required vehicle inspection/exhaust emission inspection
 Job: Washer fluid service

— Job: Service - standard scope

Description: Service - standard scope

Considered as a repeat visit No

Customer's own words

Service - standard scope	2 FRU
Flat rate unit I 00 00 105	

Service - standard scope
Defect I 87 00 06 00 00

— Job: Engine oil service

Description: Engine oil service

Considered as a repeat visit No

Customer's own words

Engine oil service	3 FRU
Flat rate unit I 00 00 610	

Engine oil service
Defect I 87 00 02 00 00

Set oil-filter element	1
Part I 11 42 8 575 211	

— Job: Service - micro filter/activated carbon filter

Description: Service - micro filter/activated carbon filter

Considered as a repeat visit No

Customer's own words

Microfilter service	2 FRU
Flat rate unit I 00 00 616	

Service - micro filter/activated carbon filter
Defect I 87 64 01 00 00

Microfilter/activated Carbon container	1
Part I 64 11 9 237 555	

— Job: Service - air cleaner

Description: Service - air cleaner

Considered as a repeat visit No

Customer's own words

Service - air filter element	2 FRU
Flat rate unit I 00 00 602	

Service - air cleaner
Defect I 87 13 01 00 00

Air filter element	1
--------------------	---

— Job: Service - fuel filter

Description: Service - fuel filter**Considered as a repeat visit** No**Customer's own words**

Service fuel filter	3 FRU
Flat rate unit I 00 00 604	

Service - fuel filter	
Defect I 87 13 02 00 00	

Fuel filter cartridge	1
Part I 13 32 8 572 522	

— Job: Service - brake fluid

Description: Service - brake fluid**Considered as a repeat visit** No**Customer's own words**

Brake fluid service	4 FRU
Flat rate unit I 00 00 618	

Service - brake fluid	
Defect I 87 34 00 00 00	

— Job: Service - front wiper blade

Description: Service - front wiper blade**Considered as a repeat visit** No**Customer's own words**

Replace left and right wiper blade	1 FRU
Flat rate unit I 61 61 541	

Service - front wiper blade	
Defect I 87 61 61 00 00	

Set of wiper blades	1
Part I 61 61 2 241 375	

— Job: Service - rear wiper blade

Description: Service - rear wiper blade**Considered as a repeat visit** No**Customer's own words**

Replacing the wiper blade for the rear wiper	1 FRU
Flat rate unit I 61 62 520	

Service - rear wiper blade	
Defect I 87 61 62 00 00	

Wiper blade	1
Part I 61 62 7 356 763	

— Job: Service - legally required vehicle inspection/exhaust emission inspection

Description: Service - legally required vehicle inspection/exhaust emission inspection**Considered as a repeat visit** No**Customer's own words**

Service pre-check for roadworthiness test (for German market only)	5 FRU
--	-------

Flat rate unit I 00 00 671

Presentation for emission inspection
Flat rate unit I 00 00 527

1 FRU

Service - legally required vehicle inspection/exhaust emission inspection
Defect I 87 99 01 00 00

— Job: Washer fluid service

Description: Washer fluid service

Considered as a repeat visit No

Customer's own words

Washer fluid service
Defect I 87 00 09 00 00

— 26/11/2018 Warranty 154943 Km 00490 Job: F10 F11 F25 F26 F31 F34
F36 B47O Replacing exhaust-gas
recirculation cooler

— Job: F10 F11 F25 F26 F31 F34 F36 B47O Replacing exhaust-gas recirculation cooler

Description: F10 F11 F25 F26 F31 F34 F36 B47O Replacing exhaust-gas recirculation cooler

Considered as a repeat visit No

Customer's own words

Replace exhaust gas recirculation cooler and clean exhaust gas
recirculation pipe 26 FRU
Flat rate unit I 00 66 769








F10 F11 F25 F26 F31 F34 F36 B47O Replacing exhaust-gas
recirculation cooler
Defect I 00 11 83 04 00

Pipe union 2
Part I 11 71 7 799 853

exhaust cooler 1
Part I 11 71 8 477 659

EGR small parts set 1
Part I 11 71 8 490 222

— 15/10/2018 Key 150563 Km Key 0



— 04/10/2018 Repair 150563 Km 00490 Auto-Müller GmbH ,
Buchen-Hettingen Job
Job
Job
Job

— Job

Description:

Considered as a repeat visit No

Customer's own words

Räderpaket Premium Räder anbauen & wuchten inkl. TOP reinigen & einlagern
Flat rate unit I 00 99 040

Local

20 FRU

Window cleaner, concentrate
Part I 83 12 2 298 203

1

— Job

Description:

Considered as a repeat visit No

Customer's own words

Initialising tyre failure indicator
Flat rate unit I 36 11 500

1 FRU

— Job

Description:

Considered as a repeat visit No

Customer's own words

Light function test
Flat rate unit I 00 12 290

2 FRU

— Job

Description:

Considered as a repeat visit No

Customer's own words

Vehicle surface wash
Flat rate unit I 00 11 319

4 FRU

— Job

Description:

Considered as a repeat visit No








Customer's own words

— 25/06/2018 Key

131826 Km

00490

Key 0




— 25/06/2018 Service

131826 Km

00490 Auto-Müller GmbH,
Buchen-Hettingen

Manual



— 25/06/2018 Repair

131826 Km

00490 Auto-Müller GmbH,
Buchen-Hettingen

Job
Job
Job

— Job

Description:

Considered as a repeat visit No

Customer's own words

Service, front brakes Flat rate unit I 00 00 612	6 FRU
---	-------

Service - standard scope Flat rate unit I 00 00 105	2 FRU
--	-------

Removing and installing or replacing both front brake discs Flat rate unit I 34 11 613	3 FRU
---	-------

Repair kit, brake pads asbestos-free Part I 34 10 6 859 181	1
--	---

Brake pad wear sensor, front left Part I 34 35 6 792 289	1
---	---

Brake disc, ventilated Part I 34 11 6 792 219	2
--	---

Torx screw with washer Part I 34 10 6 864 424	4
--	---

— Job

Description:

Considered as a repeat visit No

Customer's own words

Service, rear brakes Flat rate unit I 00 00 614	7 FRU
--	-------

Inner hex bolt Part I 34 21 1 161 806	2
--	---

Brake-pad sensor, rear Part I 34 35 6 792 292	1
--	---

— Job

Description:

Considered as a repeat visit No

Customer's own words

Repair kit, brake pads asbestos-free Part I 34 21 6 873 093	1
--	---

—	25/06/2018	Repair	131826 Km	00490 Auto-Müller GmbH , Buchen-Hettingen	Job
---	------------	--------	-----------	--	-----

— Job

Description:

Considered as a repeat visit No

Customer's own words

Vehicle surface wash Flat rate unit I 00 11 319	4 FRU
--	-------

— Job: Service - front brakes

Description: Service - front brakes

Considered as a repeat visit No

Customer's own words

Service, front brakes Flat rate unit I 00 00 612	6 FRU
---	-------

Removing and installing or replacing both front brake discs Flat rate unit I 34 11 613	3 FRU
---	-------

Service - front brakes Defect I 87 34 11 01 00	
---	--

Repair kit, brake pads asbestos-free Part I 34 10 6 859 181	1
--	---

Brake pad wear sensor, front left Part I 34 35 6 792 289	1
---	---

Brake disc, ventilated Part I 34 11 6 792 219	2
--	---

Inner hex bolt Part I 34 21 1 161 806	2
--	---

Torx screw with washer Part I 34 10 6 864 424	4
--	---

— Job: Service - standard scope

Description: Service - standard scope

Considered as a repeat visit No

Customer's own words

Service - standard scope Flat rate unit I 00 00 105	2 FRU
--	-------

Service - standard scope Defect I 87 00 06 00 00	
---	--

— Job: Service - rear brakes

Description: Service - rear brakes

Considered as a repeat visit No

Customer's own words

Service, rear brakes Flat rate unit I 00 00 614	7 FRU
--	-------

Service - rear brakes Defect I 87 34 21 01 00	
--	--

Repair kit, brake pads asbestos-free Part I 34 21 6 873 093	1
--	---

Brake-pad sensor, rear Part I 34 35 6 792 292	1
--	---

 25000 05/2020	 25000 712	 25000 712	 25000 712	 19000 11/2018	 0 11/2018	 11000 05/2022	 60000 05/2022	 0 12/2018
---	---	---	---	---	---	---	--	---

— 19/06/2018 Repair 131202 Km 00490 Auto-Müller GmbH, Buchen-Hettingen Job Job

— Job

Description:

Considered as a repeat visit No

Customer's own words

Replacing four tyres with run-flat technology 30 FRU
Flat rate unit I 36 12 076

Reifen EfficientGrip Part I 225/45R1891YROF Local 2

Reifen EfficientGrip Part I 255/40R1895YROF Local 2

— Job

Description:

Considered as a repeat visit No

Customer's own words

Vehicle surface wash 4 FRU
Flat rate unit I 00 11 319

— 22/05/2018 Key 127117 Km 00490 Key 0

 1500 11/2019	 0	 1500 557	 0	 22000 11/2018	 0 11/2018	 15000 11/2019	 1500 11/2019	 0 12/2018
--	--	--	--	---	---	---	---	---

— 22/05/2018 Service 127117 Km 00490 Auto-Müller GmbH, Buchen-Hettingen Manual

 ✓	 ✓	 ✓	 ✓	 ✓	 ✓	 ✓	 ✓	 ✓
--	--	--	--	--	--	--	---	--

— 22/05/2018 Repair 127117 Km 00490 Auto-Müller GmbH, Buchen-Hettingen Job Job Job Job

— Job

Description:

Considered as a repeat visit No

Customer's own words

Service - standard scope
Flat rate unit I 00 00 105

2 FRU

— Job

Description:

Considered as a repeat visit No

Customer's own words

Engine oil service Flat rate unit I 00 00 610	3 FRU
--	-------

BMW Engine Oil LL04 5W30 Part I 83 21 2 405 948	5
--	---

Set oil-filter element Part I 11 42 8 575 211	1
--	---

— Job

Description:

Considered as a repeat visit No

Customer's own words

Microfilter service Flat rate unit I 00 00 616	2 FRU
---	-------

Mikrofilter/Aktivkohlefil Part I 64 12 9 237 555	Local	1
---	-------	---

— Job

Description:

Considered as a repeat visit No

Customer's own words

Service, vehicle check Flat rate unit I 00 00 624	6 FRU
--	-------

Window cleaner, concentrate Part I 83 12 2 298 203	1
---	---

— Job

Description:

Considered as a repeat visit No

Customer's own words

Sondervereinbarung 87000200001 Flat rate unit I 99 99 999	Local	1 FRU
--	-------	-------

—	22/05/2018	Warranty	127117 Km	00490	Job: Service - standard scope Job: Engine oil service Job: Service - micro filter/activated carbon filter Job: Service - vehicle check Job: Washer fluid service
---	------------	----------	-----------	-------	--

— Job: Service - standard scope

Description: Service - standard scope

Considered as a repeat visit No

Customer's own words

Service - standard scope	2 FRU
--------------------------	-------

Flat rate unit I 00 00 105

Service - standard scope
Defect I 87 00 06 00 00

— Job: Engine oil service

Description: Engine oil service

Considered as a repeat visit No

Customer's own words

Engine oil service 3 FRU
Flat rate unit I 00 00 610

Engine oil service
Defect I 87 00 02 00 00

Set oil-filter element 1
Part I 11 42 8 575 211

— Job: Service - micro filter/activated carbon filter

Description: Service - micro filter/activated carbon filter

Considered as a repeat visit No

Customer's own words

Microfilter service 2 FRU
Flat rate unit I 00 00 616

Service - micro filter/activated carbon filter
Defect I 87 64 01 00 00

Microfilter/activated Carbon container 1
Part I 64 11 9 237 555

— Job: Service - vehicle check

Description: Service - vehicle check

Considered as a repeat visit No

Customer's own words

Service, vehicle check 6 FRU
Flat rate unit I 00 00 624

Service - vehicle check
Defect I 87 00 05 00 00

— Job: Washer fluid service

Description: Washer fluid service

Considered as a repeat visit No

Customer's own words

Washer fluid service
Defect I 87 00 09 00 00

— 05/04/2018 Repair 122402 Km 00490 Auto-Müller GmbH, Job
Buchen-Hettingen Job

— Job

Description:

Considered as a repeat visit No

Customer's own words

Räderpaket Premium Räder anbauen & wuchten inkl. TOP reinigen & einlagern Local 20 FRU
Flat rate unit I 00 99 040

Initialising tyre failure indicator 1 FRU
Flat rate unit I 36 11 500

— Job


Description:

Considered as a repeat visit No


Customer's own words

Windshield washer antifreeze 1
Part I 83 12 2 409 031

— 15/03/2018 Key 119449 Km 00490 Key 0



— 13/03/2018 Key 119172 Km 00490 Key 0



— 13/03/2018 Repair 119172 Km 00490 Auto-Müller GmbH , Job
Buchen-Hettingen Job

— Job

Description:

Considered as a repeat visit No

Customer's own words

— Job

Description:

Considered as a repeat visit No

Customer's own words

Replacing four tyres with run-flat technology 29 FRU
Flat rate unit I 36 12 576

WiContact TS830P SSR Local 4
Part I 20560R1692HCONTINE

— Job

Description:

Considered as a repeat visit No

Customer's own words

Vehicle surface wash 4 FRU
Flat rate unit I 00 11 319

— 13/03/2018 Warranty 119172 Km 00490 Job: Exhaust gas recirculation valve (EGR)

— Job: Exhaust gas recirculation valve (EGR)

Description: Exhaust gas recirculation valve (EGR)

Considered as a repeat visit No

Customer's own words

Performing vehicle test 4 FRU
Flat rate unit I 00 00 006

Replacing exhaust gas recirculation valve 7 FRU
Flat rate unit I 11 71 501

Supporting the voltage of the vehicle electrical system/recharging the vehicle electrical system battery 1 FRU
Flat rate unit I 61 21 528

Exhaust gas recirculation valve (EGR)
Defect I 11 71 01 83 00

Hose clamp 2
Part I 07 12 9 952 104

EGR-valve 1
Part I 11 71 8 513 132

Gasket Steel 1
Part I 11 71 8 579 364

Oval head screw 2
Part I 35 21 7 685 343

— 20/12/2017 Key 108438 Km 41153 Key 0

								
22000	0	22000	0	43000	0	36000	22000	0
11/2019		710			11/2018		11/2019	12/2018

— 20/12/2017 Repair 108438 Km 41153 Rhein Ludwigsburg Zw. NI. der Autohaus Heermann u. Rhein GmbH Autohaus, Asperg Job Job

— Job

Description:

Considered as a repeat visit No

Customer's own words

Flat rate unit I - Local 0 FRU

Flat rate unit I - Local 0 FRU

— Job

Description:

Considered as a repeat visit No

Customer's own words

— 20/12/2017 Warranty 108438 Km 41153 Job: Window guide, rear

— Job: Window guide, rear

Description: Window guide, rear

Considered as a repeat visit No

Customer's own words


Replacing rubber window seal on both rear door window glass Flat rate unit I 51 34 712	23 FRU
---	--------

Window guide, rear Defect I 51 34 04 32 00


Window guide, left rear door Part I 51 35 7 414 535	1
--	---

Window guide, right rear door Part I 51 35 7 414 536	1
---	---

— 06/11/2017 Key 101089 Km 00490 Key 0



— 06/11/2017 Service 101089 Km 00490 Auto-Müller GmbH, Buchen-Hettingen Manual



— 06/11/2017 Repair 101096 Km 00490 Auto-Müller GmbH, Buchen-Hettingen Job
Job
Job
Job
Job

— Job

Description:

Considered as a repeat visit No

Customer's own words

Service - standard scope Flat rate unit I 00 00 105	2 FRU
--	-------

Engine oil service Flat rate unit I 00 00 610	3 FRU
--	-------

BMW Engine Oil LL04 5W30 Part I 83 21 2 405 948	5
--	---

Set oil-filter element Part I 11 42 8 575 211	1
--	---

— Job

Description:

Considered as a repeat visit No

Customer's own words

Microfilter service	2 FRU
Flat rate unit 00 00 616	

Microfilter/activated Carbon container	1
Part 64 11 9 237 555	

— Job

Description:

Considered as a repeat visit No

Customer's own words

Service fuel filter	3 FRU
Flat rate unit 00 00 604	

Fuel filter cartridge	1
Part 13 32 8 572 522	

— Job

Description:

Considered as a repeat visit No

Customer's own words

Service - air filter element	2 FRU
Flat rate unit 00 00 602	

Air filter element	1
Part 13 71 8 511 668	

— Job

Description:

Considered as a repeat visit No

Customer's own words

Aufwandsentschädigung 87000200001	Local	1 FRU
Flat rate unit 99 99 999		

—	06/11/2017	Repair	101096 Km	00490 Auto-Müller GmbH , Buchen-Hettingen	Job
---	------------	--------	-----------	--	-----

— Job

Description:

Considered as a repeat visit No

Customer's own words

Vehicle surface wash	4 FRU
Flat rate unit 00 11 319	

Vehicle check in course of reception	0 FRU
Flat rate unit 00 52 054	

Job time without allowance for / engine	8 FRU
Flat rate unit 11 99 000	

—	06/11/2017	Warranty	101096 Km	00490	Job: F1x F2x F3x B47 programming control units and if necessary, replacing the EGR valve
---	------------	----------	-----------	-------	--

- Job: F1x F2x F3x B47 programming control units and if necessary, replacing the EGR valve

Description: F1x F2x F3x B47 programming control units and if necessary, replacing the EGR valve

Considered as a repeat visit No

Customer's own words

Carrying out the ABL and programming the control units	8 FRU
Flat rate unit I 00 64 941	

F1x F2x F3x B47 programming control units and if necessary, replacing the EGR valve
Defect I 00 11 45 04 00

- 06/11/2017 Warranty 101096 Km 00490
 - Job: Service - standard scope
 - Job: Engine oil service
 - Job: Service - micro filter/activated carbon filter
 - Job: Service - fuel filter
 - Job: Service - air cleaner

- Job: Service - standard scope

Description: Service - standard scope

Considered as a repeat visit No

Customer's own words

Service - standard scope	2 FRU
Flat rate unit I 00 00 105	

Service - standard scope
Defect I 87 00 06 00 00

- Job: Engine oil service

Description: Engine oil service

Considered as a repeat visit No

Customer's own words

Engine oil service	3 FRU
Flat rate unit I 00 00 610	

Engine oil service
Defect I 87 00 02 00 00

Set oil-filter element	1
Part I 11 42 8 575 211	

- Job: Service - micro filter/activated carbon filter

Description: Service - micro filter/activated carbon filter

Considered as a repeat visit No

Customer's own words

Microfilter service	2 FRU
Flat rate unit I 00 00 616	

Service - micro filter/activated carbon filter
Defect I 87 64 01 00 00

Microfilter/activated Carbon container	1
Part I 64 11 9 237 555	

- Job: Service - fuel filter

Description: Service - fuel filter

Considered as a repeat visit No

Customer's own words

Service fuel filter
Flat rate unit | 00 00 604 3 FRU

Service - fuel filter
Defect | 87 13 02 00 00

Fuel filter cartridge
Part | 13 32 8 572 522 1

— Job: Service - air cleaner

Description: Service - air cleaner

Considered as a repeat visit No

Customer's own words

Service - air filter element
Flat rate unit | 00 00 602 2 FRU

Service - air cleaner
Defect | 87 13 01 00 00


Air filter element
Part | 13 71 8 511 668 1

— 10/10/2017 Key

97854 Km

00490

Key 0




— 10/10/2017 Service

97854 Km

00490 Auto-Müller GmbH,
Buchen-Hettingen

Manual



— 10/10/2017 Warranty

97860 Km

00490

Job: Service - standard scope
Job: Service - rear brakes
Job: Service - front brakes
Job: Service - topping up engine oil

— Job: Service - standard scope

Description: Service - standard scope

Considered as a repeat visit No

Customer's own words

Service - standard scope
Flat rate unit | 00 00 105 2 FRU

Service - standard scope
Defect | 87 00 06 00 00

— Job: Service - rear brakes

Description: Service - rear brakes

Considered as a repeat visit No

Customer's own words

Removing and installing or replacing brake pads of both rear disc brakes Flat rate unit I 34 21 739	0 FRU
--	-------

Removing and installing or replacing both rear brake discs Flat rate unit I 34 21 932	0 FRU
--	-------

Removing and installing or replacing all parking brake shoes Flat rate unit I 34 41 660	0 FRU
--	-------

Service - rear brakes Defect I 87 34 21 01 00	
--	--

Hex screw with collar Part I 34 20 6 850 536	4
---	---

Inner hex bolt Part I 34 21 1 161 806	2
--	---

Brake disc, ventilated Part I 34 21 6 864 900	2
--	---

Repair kit, brake pads asbestos-free Part I 34 21 6 873 093	1
--	---

Brake-pad sensor, rear Part I 34 35 6 792 292	1
--	---

Repair kit springs Part I 34 41 0 410 825	1
--	---

Repair kit brake shoe asbestos-free Part I 34 41 6 761 292	1
---	---

Adjusting screw Part I 34 41 6 851 437	2
---	---

Expanding lock Part I 34 41 6 851 439	2
--	---

— Job: Service - front brakes

Description: Service - front brakes

Considered as a repeat visit No

Customer's own words

Removing and installing or replacing brake pads of both front disc brakes Flat rate unit I 34 11 505	0 FRU
---	-------

Service - front brakes Defect I 87 34 11 01 00	
---	--

Repair kit, brake pads asbestos-free Part I 34 10 6 859 181	1
--	---

Brake pad wear sensor, front left Part I 34 35 6 792 289	1
---	---

— Job: Service - topping up engine oil

Description: Service - topping up engine oil

Considered as a repeat visit No

Customer's own words

Service - topping up engine oil Defect I 87 11 01 00 00	
--	--

— Job: Service - standard scope

Description: Service - standard scope**Considered as a repeat visit** No**Customer's own words**

Service - standard scope	2 FRU
Flat rate unit I 00 00 105	

Service - standard scope	
Defect I 87 00 06 00 00	

— Job: Service - topping up engine oil

Description: Service - topping up engine oil**Considered as a repeat visit** No**Customer's own words**

Service - topping up engine oil	
Defect I 87 11 01 00 00	

— Job: Service - front brakes

Description: Service - front brakes**Considered as a repeat visit** No**Customer's own words**

Service, front brakes	6 FRU
Flat rate unit I 00 00 612	

Service - front brakes	
Defect I 87 34 11 01 00	

Repair kit, brake pads asbestos-free	1
Part I 34 10 6 859 181	

Brake pad wear sensor, front left	1
Part I 34 35 6 792 289	

— Job: Service - rear brakes

Description: Service - rear brakes**Considered as a repeat visit** No**Customer's own words**

Service, rear brakes	7 FRU
Flat rate unit I 00 00 614	

Removing and installing or replacing both rear brake discs	0 FRU
Flat rate unit I 34 21 932	

Removing and installing or replacing all parking brake shoes	0 FRU
Flat rate unit I 34 41 660	

Service - rear brakes	
Defect I 87 34 21 01 00	

Hex screw with collar	4
Part I 34 20 6 850 536	

Inner hex bolt	2
Part I 34 21 1 161 806	

Brake disc, ventilated	2
Part I 34 21 6 864 900	

Repair kit, brake pads asbestos-free Part I 34 21 6 873 093	1
Brake-pad sensor, rear Part I 34 35 6 792 292	1
Repair kit brake shoe asbestos-free Part I 34 41 6 761 292	1
Repair kit springs Part I 34 41 0 410 825	1
Adjusting screw Part I 34 41 6 851 437	2
Expanding lock Part I 34 41 6 851 439	2

— 05/10/2017 Repair 97860 Km 00490 Auto-Müller GmbH, Job
Buchen- Job
Hettingen Job
Job
Job

— Job

Description:

Considered as a repeat visit No

Customer's own words

Räderpaket Premium Räder anbauen & wuchten inkl. TOP reinigen & einlagern Flat rate unit I 00 99 040	Local	20 FRU
---	-------	--------

Initialising tyre failure indicator Flat rate unit I 36 11 500	1 FRU
---	-------

— Job

Description:

Considered as a repeat visit No

Customer's own words

— Job

Description:

Considered as a repeat visit No

Customer's own words

— Job

Description:

Considered as a repeat visit No

Customer's own words

— Job

Description:

Considered as a repeat visit No

Customer's own words

— Job

Description:**Considered as a repeat visit** No**Customer's own words**

Vehicle surface wash Flat rate unit I 00 11 319	4 FRU
--	-------

Vehicle check in course of reception Flat rate unit I 00 52 054	0 FRU
--	-------

Anti-freeze Part I 83 19 2 218 347	0.5
---------------------------------------	-----

— Job

Description:**Considered as a repeat visit** No**Customer's own words**

—	05/10/2017	Repair	97860 Km	00490 Auto-Müller GmbH , Buchen-Hettingen	Job Job Job Job
---	------------	--------	----------	--	--------------------------

— Job

Description:**Considered as a repeat visit** No**Customer's own words**

Service - standard scope Flat rate unit I 00 00 105	2 FRU
--	-------

— Job

Description:**Considered as a repeat visit** No**Customer's own words**

Removing and installing or replacing brake pads of both rear disc brakes Flat rate unit I 34 21 200	8 FRU
--	-------

Removing and installing or replacing both rear brake discs Flat rate unit I 34 21 932	4 FRU
--	-------

Hex screw with collar Part I 34 20 6 850 536	4
---	---

Inner hex bolt Part I 34 21 1 161 806	2
--	---

Brake disc, ventilated Part I 34 21 6 864 900	2
--	---

Repair kit, brake pads asbestos-free Part I 34 21 6 873 093	1
--	---

Brake-pad sensor, rear Part I 34 35 6 792 292	1
--	---

Brake-pad paste Part I 83 19 2 158 851	2
---	---

— Job

Description:

Considered as a repeat visit No

Customer's own words

Removing and installing or replacing all parking brake shoes Flat rate unit I 34 41 660	4 FRU
--	-------

Repair kit springs Part I 34 41 0 410 825	1
--	---

Repair kit brake shoe asbestos-free Part I 34 41 6 761 292	1
---	---

Adjusting screw Part I 34 41 6 851 437	2
---	---

Expanding lock Part I 34 41 6 851 439	2
--	---

— Job

Description:

Considered as a repeat visit No

Customer's own words

Removing and installing or replacing brake pads of both front disc brakes Flat rate unit I 34 11 000	8 FRU
---	-------

Repair kit, brake pads asbestos-free Part I 34 10 6 859 181	1
--	---

Brake pad wear sensor, front left Part I 34 35 6 792 289	1
---	---

Brake-pad paste Part I 83 19 2 158 851	2
---	---

— Job

Description:

Considered as a repeat visit No

Customer's own words


BMW Engine Oil LL04 5W30 Part I 83 21 2 405 948	0.5
--	-----

— 11/05/2017 Key

75285 Km

00490

Key 0



— 11/05/2017 Repair

75285 Km

00490 Auto-
Müller GmbH ,
Buchen-
Hettingen

Job

— Job

Description:

Considered as a repeat visit No

Customer's own words

Replacing left or right control arm	1 FRU
-------------------------------------	-------

Flat rate unit | 31 12 571

Replacing left or right front spring strut
Flat rate unit | 31 31 501

5 FRU

Removing and installing complete left or right front spring strut
Flat rate unit | 31 31 502

13 FRU

Job time without allowance for / front axle
Flat rate unit | 31 99 000

2 FRU

Carry out Kinematics Diagnosis System wheel alignment with vehicle
load up to design position
Flat rate unit | 32 00 590

16 FRU

Carry out Kinematics Diagnosis System wheel alignment with vehicle
load up to design position
Flat rate unit | 32 00 590

16 FRU

Adjusting toe-in on front axle
Flat rate unit | 32 00 601

6 FRU

Replacing left or right tie rod
Flat rate unit | 32 21 734

4 FRU

Removing and installing or replacing both front brake discs
Flat rate unit | 34 11 612

3 FRU

Initialising tyre failure indicator
Flat rate unit | 36 11 500

1 FRU

Removing and installing/replacing the tyre pressure control wheel
electronics (RDC)
Flat rate unit | 36 11 535

1 FRU

Replacing a tyre with run-flat technology
Flat rate unit | 36 12 506

6 FRU

Job time without allowance for / body equipment
Flat rate unit | 51 99 000

2 FRU

KLeinteile
Part | FT99 08 0 010 1

Local

1

Hex nut
Part | 07 11 9 905 032

1

Hexagon screw with flange
Part | 31 10 6 795 930

1

Hex screw with collar
Part | 31 10 6 797 237

1

Tension strut with hydr. mount, right
Part | 31 12 6 854 724

1

Wishbone, right
Part | 31 12 6 854 728

1

Collar screw
Part | 31 20 6 783 065

4

Collar bolt with compression spring
Part | 31 20 6 795 249

1

Spherical collar screw
Part | 31 20 6 872 920

4

Wheel hub with bearing, front
Part | 31 20 6 876 844

1

Carrier, right
Part | 31 21 6 853 820

1

Spring pad with protective tube, top

1

Part I 31 30 6 791 712

Hexagon screw with flange
Part I 31 30 6 798 530

1

Hex Bolt with washer
Part I 31 30 6 869 931

5

Guide support
Part I 31 30 6 881 929

1

Front right spring strut
Part I 31 31 6 874 386

1

Spring pad lower
Part I 31 33 6 787 114

1

Additional damper, front
Part I 31 33 6 855 440

1

Pipe clamp
Part I 32 10 6 765 232

1

Right tie rod
Part I 32 10 6 792 030

1

Combination nut
Part I 33 30 6 787 062

2

Self-locking collar nut
Part I 33 32 6 760 668

1

Wheel electr. module RDCi w/ screw valve
Part I 36 10 6 881 890

1

Light alloy rim Ferricgrey
Part I 36 11 6 796 247

1

Bridgestone Potenza S 001 RFT
Part I 85 45 2 593 884










1

— 27/04/2017 Key

73530 Km

00490

Key 0




— 27/04/2017 Service

73530 Km

00490 Auto-
Müller GmbH,
Buchen-
Hettingen

Manual



— 27/04/2017 Repair

73530 Km

00490 Auto-
Müller GmbH,
Buchen-
Hettingen

Job
Job
Job
Job
Job

— Job

Description:

Considered as a repeat visit No

Customer's own words

Service - standard scope	2 FRU
Flat rate unit I 00 00 105	

— Job

Description:**Considered as a repeat visit** No**Customer's own words**

Engine oil service	3 FRU
Flat rate unit I 00 00 610	

Set oil-filter element	1
Part I 11 42 8 575 211	

BMW Engine Oil LL04 5W30	5
Part I 83 21 2 405 948	

— Job

Description:**Considered as a repeat visit** No**Customer's own words**

Microfilter service	2 FRU
Flat rate unit I 00 00 616	

Microfilter/activated Carbon container	1
Part I 64 11 9 237 555	

— Job

Description:**Considered as a repeat visit** No**Customer's own words**

Service, vehicle check	6 FRU
Flat rate unit I 00 00 624	

— Job

Description:**Considered as a repeat visit** No**Customer's own words**

Sondervereinbarung 87000200001	Local	1 FRU
Flat rate unit I 99 99 999		

—	27/04/2017	Repair	73530 Km	00490 Auto-Müller GmbH , Buchen-Hettingen	Job Job Job
---	------------	--------	----------	--	-------------------

— Job

Description:**Considered as a repeat visit** No**Customer's own words**

Carry out Kinematics Diagnosis System wheel alignment with vehicle load up to design position	16 FRU
Flat rate unit I 32 00 590	

— Job

Description:

Considered as a repeat visit No

Customer's own words

Replacing four tyres with run-flat technology	29 FRU
Flat rate unit 36 12 576	

S001 RFT	Local	2
Part 22545R1891YBRIDGES		

S001 RFT	Local	2
Part 25540R1895YBRIDGES		

— Job

Description:

Considered as a repeat visit No

Customer's own words

—	27/04/2017	Warranty	73530 Km	00490	Job: Service - standard scope Job: Engine oil service Job: Service - micro filter/activated carbon filter Job: Service - vehicle check
---	------------	----------	----------	-------	---

— Job: Service - standard scope

Description: Service - standard scope

Considered as a repeat visit No

Customer's own words

Service - standard scope	2 FRU
Flat rate unit 00 00 105	

Service - standard scope
Defect 87 00 06 00 00

— Job: Engine oil service

Description: Engine oil service

Considered as a repeat visit No

Customer's own words

Engine oil service	3 FRU
Flat rate unit 00 00 610	

Engine oil service
Defect 87 00 02 00 00

Set oil-filter element	1
Part 11 42 8 575 211	

— Job: Service - micro filter/activated carbon filter

Description: Service - micro filter/activated carbon filter

Considered as a repeat visit No

Customer's own words

Microfilter service	2 FRU
Flat rate unit 00 00 616	

Service - micro filter/activated carbon filter
Defect 87 64 01 00 00

— Job: Service - vehicle check

Description: Service - vehicle check

Considered as a repeat visit No

Customer's own words

Service, vehicle check
Flat rate unit I 00 00 624

6 FRU


Service - vehicle check
Defect I 87 00 05 00 00

— 04/04/2017 Key

69766 Km

00490

Key 0




— 13/03/2017 Key

65972 Km

00490

Key 0




— 13/03/2017 Service

65972 Km

00490 Auto-Müller GmbH,
Buchen-Hettingen

Manual



— 13/03/2017 Warranty

65972 Km

00490

Job: Service - standard scope
Job: Service - front brakes
Job: Service - rear brakes

— Job: Service - standard scope

Description: Service - standard scope

Considered as a repeat visit No

Customer's own words

Service - standard scope
Flat rate unit I 00 00 105

2 FRU

Service - standard scope
Defect I 87 00 06 00 00

— Job: Service - front brakes

Description: Service - front brakes

Considered as a repeat visit No

Customer's own words

Service, front brakes Flat rate unit I 00 00 612	6 FRU
Removing and installing or replacing both front brake discs Flat rate unit I 34 11 613	3 FRU
Service - front brakes Defect I 87 34 11 01 00	
Repair kit, brake pads asbestos-free Part I 34 10 6 859 181	1
Hex Bolt Part I 34 11 6 772 117	4
Brake disc, ventilated Part I 34 11 6 792 219	2
Inner hex bolt Part I 34 21 1 161 806	2
Brake pad wear sensor, front left Part I 34 35 6 792 289	1

— Job: Service - rear brakes

Description: Service - rear brakes

Considered as a repeat visit No

Customer's own words

Service, rear brakes Flat rate unit I 00 00 614	7 FRU
Service - rear brakes Defect I 87 34 21 01 00	
Repair kit, brake pads asbestos-free Part I 34 21 6 873 093	1
Brake-pad sensor, rear Part I 34 35 6 792 292	1

— 10/03/2017 Repair 65972 Km 00490 Auto-Müller GmbH , Job
Buchen- Job
Hettingen Job

— Job

Description:

Considered as a repeat visit No

Customer's own words

Räderpaket Premium Räder anbauen & wuchten inkl. TOP reinigen & einlagern Flat rate unit I 00 99 040	Local 20 FRU
---	--------------

— Job

Description:

Considered as a repeat visit No

Customer's own words

Service Standard W.O.L.K.E. Flat rate unit I 00 99 400	0 FRU
---	-------

BMW Engine Oil LL04 5W30 Part I 83 21 2 405 948	0.5
--	-----

— Job

Description:

Considered as a repeat visit No

Customer's own words

— Job

Description:

Considered as a repeat visit No

Customer's own words

Vehicle surface wash Flat rate unit I 00 11 319	4 FRU
--	-------

—	10/03/2017	Repair	65972 Km	00490 Auto-Müller GmbH , Buchen-Hettingen	Job Job
---	------------	--------	----------	--	------------

— Job

Description:

Considered as a repeat visit No

Customer's own words

Service - standard scope Flat rate unit I 00 00 105	2 FRU
--	-------

Service, front brakes Flat rate unit I 00 00 612	6 FRU
---	-------

Removing and installing or replacing both front brake discs Flat rate unit I 34 11 613	3 FRU
---	-------

Repair kit, brake pads asbestos-free Part I 34 10 6 859 181	1
--	---

Hex Bolt Part I 34 11 6 772 117	4
------------------------------------	---

Brake disc, ventilated Part I 34 11 6 792 219	2
--	---

Inner hex bolt Part I 34 21 1 161 806	2
--	---

Brake pad wear sensor, front left Part I 34 35 6 792 289	1
---	---

— Job

Description:

Considered as a repeat visit No

Customer's own words


Service, rear brakes Flat rate unit I 00 00 614	7 FRU
--	-------

Repair kit, brake pads asbestos-free	1
--------------------------------------	---

Brake-pad sensor, rear
Part I 34 35 6 792 292

1

— 24/01/2017 Key 58617 Km 41153 Key 0



— 24/01/2017 Warranty 58617 Km 41153 Job: Exhaust gas recirculation valve (EGR)
Job: Headunit High HU-H

— Job: Exhaust gas recirculation valve (EGR)

Description: Exhaust gas recirculation valve (EGR)

Considered as a repeat visit No

Customer's own words

Performing vehicle test 4 FRU
Flat rate unit I 00 00 006

Supporting the voltage of the vehicle electrical system/recharging the vehicle electrical system battery 1 FRU
Flat rate unit I 61 21 528

Replacing exhaust gas recirculation valve 7 FRU
Flat rate unit I 11 71 501

Exhaust gas recirculation valve (EGR)
Defect I 11 71 01 83 00

EGR-valve 1
Part I 11 71 8 513 132

Oval head screw 2
Part I 35 21 7 685 343

Gasket Steel 1
Part I 11 71 8 579 364

Hose clamp 2
Part I 07 12 9 952 104

— Job: Headunit High HU-H

Description: Headunit High HU-H

Considered as a repeat visit No


Customer's own words

Vehicle diagnosis - carrying out the ABL 1 FRU
Flat rate unit I 61 00 006

Programming/encoding control unit(s) including deleting fault memories 4 FRU
Flat rate unit I 61 00 730

Headunit High HU-H
Defect I 65 12 58 02 00

— 21/11/2016 Service 51087 Km 00490 Auto-Müller GmbH, Buchen-Hettingen Manual



— 21/11/2016 Repair

51096 Km

00490 Auto-Müller GmbH,
Buchen-Hettingen

Job
Job
Job
Job
Job

— Job

Description:

Considered as a repeat visit No

Customer's own words

Service - standard scope Flat rate unit I 00 00 105	2 FRU
--	-------

Engine oil service Flat rate unit I 00 00 610	3 FRU
--	-------

Set oil-filter element Part I 11 42 8 575 211	1
--	---

BMW Engine Oil LL04 5W30 Part I 83 21 2 405 948	5
--	---

Windshield washer antifreeze Part I 83 12 2 409 031	1
--	---

— Job

Description:

Considered as a repeat visit No

Customer's own words

Microfilter service Flat rate unit I 00 00 616	2 FRU
---	-------

Microfilter/activated Carbon container Part I 64 11 9 237 555	1
--	---

— Job

Description:

Considered as a repeat visit No

Customer's own words

Service fuel filter Flat rate unit I 00 00 604	3 FRU
---	-------

Fuel filter cartridge Part I 13 32 8 572 522	1
---	---

— Job

Description:

Considered as a repeat visit No

Customer's own words

Service - air filter element Flat rate unit I 00 00 602	2 FRU
--	-------

— Job

Description:

Considered as a repeat visit No

Customer's own words

Service, vehicle check	6 FRU
Flat rate unit I 00 00 624	

— Job

Description:

Considered as a repeat visit No

Customer's own words

Sondervereinbarung 87000200001	Local	1 FRU
Flat rate unit I 99 99 999		

— 21/11/2016 Warranty 51096 Km 00490

Job: Service - standard scope
Job: Engine oil service
Job: Service - micro filter/activated carbon filter
Job: Service - fuel filter
Job: Service - air cleaner
Job: Service - vehicle check

— Job: Service - standard scope

Description: Service - standard scope

Considered as a repeat visit No

Customer's own words

Service - standard scope	2 FRU
Flat rate unit I 00 00 105	

Service - standard scope
Defect I 87 00 06 00 00

— Job: Engine oil service

Description: Engine oil service

Considered as a repeat visit No

Customer's own words

Engine oil service	3 FRU
Flat rate unit I 00 00 610	

Engine oil service
Defect I 87 00 02 00 00

Set oil-filter element	1
Part I 11 42 8 575 211	

— Job: Service - micro filter/activated carbon filter

Description: Service - micro filter/activated carbon filter

Considered as a repeat visit No

Customer's own words

Microfilter service	2 FRU
Flat rate unit I 00 00 616	

Service - micro filter/activated carbon filter
Defect I 87 64 01 00 00

Microfilter/activated Carbon container
Part I 64 11 9 237 555

1

— Job: Service - fuel filter

Description: Service - fuel filter

Considered as a repeat visit No

Customer's own words

Service fuel filter
Flat rate unit I 00 00 604

3 FRU

Service - fuel filter
Defect I 87 13 02 00 00

Fuel filter cartridge
Part I 13 32 8 572 522

1

— Job: Service - air cleaner

Description: Service - air cleaner

Considered as a repeat visit No

Customer's own words

Service - air filter element
Flat rate unit I 00 00 602

2 FRU

Service - air cleaner
Defect I 87 13 01 00 00

Air filter element
Part I 13 71 8 511 668

1

— Job: Service - vehicle check

Description: Service - vehicle check

Considered as a repeat visit No

Customer's own words

Service, vehicle check
Flat rate unit I 00 00 624

6 FRU









Service - vehicle check
Defect I 87 00 05 00 00

— 13/10/2016 Key

45346 Km

00490

Key 0



— 10/10/2016 Repair

45346 Km

00490 Auto-
Müller GmbH,
Buchen-
Hettingen

Job

— Job

Description:

Considered as a repeat visit No

Customer's own words

Räderpaket Premium Räder anbauen & wuchten inkl. TOP reinigen & einlagern
Flat rate unit I 00 99 040

Local

20 FRU

Initialising tyre failure indicator
Flat rate unit I 36 11 500









1 FRU

— 05/09/2016 Key

38640 Km

00490

Key 0



— 05/09/2016 Warranty

38640 Km

00490

Job: Rear final drive housing

— Job: Rear final drive housing

Description: Rear final drive housing

Considered as a repeat visit No

Customer's own words

Replace left and right radial shaft seal for driven shafts on rear axle differential
Flat rate unit I 33 10 024

24 FRU

Rear final drive housing
Defect I 33 11 00 48 00

ASA-Bolt
Part I 26 11 7 621 344

3

Self-locking hex nut
Part I 26 12 7 536 563

3

Gasket set differential
Part I 33 10 7 564 416










2

— 22/08/2016 Key

36961 Km

00490

Key 0



— 22/08/2016 Service

36961 Km

00490 Auto-Müller GmbH,
Buchen-Hettingen

Manual



— 22/08/2016 Repair

36961 Km

00490 Auto-Müller GmbH,
Buchen-Hettingen

Job

— Job

Description:

Considered as a repeat visit No

Customer's own words

Service - standard scope	2 FRU
--------------------------	-------

Flat rate unit I 00 00 105	
----------------------------	--

Service, front brakes	6 FRU
-----------------------	-------

Flat rate unit I 00 00 612	
----------------------------	--

Service, rear brakes	7 FRU
----------------------	-------

Flat rate unit I 00 00 614	
----------------------------	--

Repair kit, brake pads asbestos-free	1
--------------------------------------	---

Part I 34 10 6 859 181	
------------------------	--

Brake pad wear sensor, front left	1
-----------------------------------	---

Part I 34 35 6 792 289	
------------------------	--

Repair kit, brake pads asbestos-free	1
--------------------------------------	---

Part I 34 21 6 873 093	
------------------------	--

Brake-pad sensor, rear	1
------------------------	---

Part I 34 35 6 792 292	
------------------------	--

—	22/08/2016	Warranty	36961 Km	00490	Job: Service - standard scope Job: Service - front brakes Job: Service - rear brakes
---	------------	----------	----------	-------	--

— Job: Service - standard scope

Description: Service - standard scope

Considered as a repeat visit No

Customer's own words

Service - standard scope	2 FRU
--------------------------	-------

Flat rate unit I 00 00 105	
----------------------------	--

Service - standard scope	
--------------------------	--

Defect I 87 00 06 00 00	
-------------------------	--

— Job: Service - front brakes

Description: Service - front brakes

Considered as a repeat visit No

Customer's own words

Service, front brakes	6 FRU
-----------------------	-------

Flat rate unit I 00 00 612	
----------------------------	--

Service - front brakes	
------------------------	--

Defect I 87 34 11 01 00	
-------------------------	--

Repair kit, brake pads asbestos-free	1
--------------------------------------	---

Part I 34 10 6 859 181	
------------------------	--

Brake pad wear sensor, front left	1
-----------------------------------	---

Part I 34 35 6 792 289	
------------------------	--

— Job: Service - rear brakes

Description: Service - rear brakes

Considered as a repeat visit No

Customer's own words

Service, rear brakes	7 FRU
----------------------	-------

Flat rate unit I 00 00 614	
----------------------------	--

Service - rear brakes	
-----------------------	--

Defect I 87 34 21 01 00	
-------------------------	--

Repair kit, brake pads asbestos-free
Part I 34 21 6 873 093

1

Brake-pad sensor, rear
Part I 34 35 6 792 292

1

— 10/05/2016 Warranty 23924 Km 00490 Job: Service - standard scope
Job: Engine oil service
Job: Service - micro filter/activated carbon filter

— Job: Service - standard scope

Description: Service - standard scope

Considered as a repeat visit No

Customer's own words

Service - standard scope
Flat rate unit I 00 00 105

2 FRU

Service - standard scope
Defect I 87 00 06 00 00

— Job: Engine oil service

Description: Engine oil service

Considered as a repeat visit No

Customer's own words

Engine oil service
Flat rate unit I 00 00 610

3 FRU

Engine oil service
Defect I 87 00 02 00 00

Set oil-filter element
Part I 11 42 8 575 211

1

— Job: Service - micro filter/activated carbon filter

Description: Service - micro filter/activated carbon filter

Considered as a repeat visit No

Customer's own words

Microfilter service
Flat rate unit I 00 00 616










2 FRU

Service - micro filter/activated carbon filter
Defect I 87 64 01 00 00


Microfilter/activated Carbon container
Part I 64 11 9 237 555

1

— 09/05/2016 Key 23924 Km 00490 Key 0



— 09/05/2016 Service 23924 Km 00490 Auto-Müller GmbH, Buchen-Hettingen Manual



— 09/05/2016 Repair

23924 Km

00490 Auto-Müller GmbH ,
Buchen-Hettingen

Job

— Job

Description:

Considered as a repeat visit No

Customer's own words

Sondervereinbarung 87000200001
Flat rate unit | 99 99 999

Local

1 FRU

Service - standard scope
Flat rate unit | 00 00 105

2 FRU

Engine oil service
Flat rate unit | 00 00 610

3 FRU

Microfilter service
Flat rate unit | 00 00 616

2 FRU

Set oil-filter element
Part | 11 42 8 575 211

1

BMW Engine Oil LL04 5W30
Part | 83 21 2 405 948

5

Microfilter/activated Carbon container
Part | 64 11 9 237 555

1

Window cleaner, concentrate
Part | 83 12 2 298 203









1

— 07/04/2016 Key

17517 Km

00490

Key 0



— 07/04/2016 Repair

17523 Km

00490 Auto-Müller GmbH ,
Buchen-Hettingen

Job

Job

Job

— Job

Description:

Considered as a repeat visit No

Customer's own words

Season storage fee incl. wheel cleaning Flat rate unit I 00 99 020	33 FRU
Removing and installing front and rear wheels Flat rate unit I 36 10 360	6 FRU
Initialising tyre failure indicator Flat rate unit I 36 11 500	1 FRU

— Job

Description:

Considered as a repeat visit No

Customer's own words

Kostenloses Aussaugen Flat rate unit I 00 99 321	Local	2 FRU
Vehicle surface wash Flat rate unit I 00 11 319		3 FRU

— Job

Description:

Considered as a repeat visit No

Customer's own words


Vehicle check in course of reception Flat rate unit I 00 52 054	0 FRU
--	-------

— 11/01/2016 Key

2797 Km

00490

Key 0



— 11/01/2016 Warranty

2798 Km

00490

Job: KAFAS camera (camera-based driver assist systems)

— Job: KAFAS camera (camera-based driver assist systems)

Description: KAFAS camera (camera-based driver assist systems)

Considered as a repeat visit No

Customer's own words

Performing vehicle test Flat rate unit I 00 00 556	2 FRU
Calibrate KAFAS camera Flat rate unit I 66 51 525	4 FRU
Job time without allowance for / electronic transceiver systems Flat rate unit I 66 99 000	6 FRU
KAFAS camera (camera-based driver assist systems) Defect I 66 51 02 14 00	

— 01/12/2015 Repair

2 Km

00490 Auto-Müller GmbH,
Buchen-Hettingen

Job

— Job

Description:

Considered as a repeat visit No

Customer's own words

Free pre-delivery check	9 FRU
Flat rate unit I 00 00 009	

Aufbereitung Enzo	Local	1
Part I FT0000154		

—	01/12/2015	Repair	2 Km	00490 Auto-Müller GmbH , Buchen-Hettingen	Job
---	------------	--------	------	--	-----

— Job

Description:

Considered as a repeat visit No

Customer's own words

Removing and installing front and rear wheels	6 FRU
Flat rate unit I 36 10 360	

Retrofitting independent heating	120 FRU
Flat rate unit I 72 64 012	

Programming/encoding control unit(s) including deleting fault memories	5 FRU
Flat rate unit I 61 00 730	

Bleed the cooling system and check it for watertightness with the special tool	6 FRU
Flat rate unit I 17 00 039	

Windshield washer antifreeze	2
Part I 83 12 2 298 528	

RDCi Wheel/Tyre set Winter Steel	4
Part I 36 11 2 411 436	

Install.kit, independent heater	1
Part I 64 50 2 359 944	

Retrofit kit, remote cntrl,indep.heating	1
Part I 64 50 0 435 769	

Hose clamp	4
Part I 07 12 9 952 109	

Anti-freeze	5
Part I 83 19 2 218 347	