

Thank you for ordering from us!

www.checkvin.eu

Vehicle

BMW 420D xDr, 140KW

WBA4F11090G313718



Development code
Colour
Actual integration level
Start of warranty

F36
imperial-blau brillant metallic
F020-22-07-530
30 June 2015

Technical campaigns

There are no Campaigns for this vehicle.

Warranty extension/VIN-based goodwill

Status	Campaign number	Description
Open	1SACC011056	Exhaust gas recirculation cooler Bx7 Local campaign number: -

Special information

There are no Campaigns for this vehicle.

Restrictions on the warranty

There are no restrictions on the warranty.

⚠ Market-specific restrictions are not currently displayed. Please check this in WDF/WXE via S-Gate.

Live Diagnosis

 There are no service solutions for Live Diagnosis.

Service contracts

No BSI contracts

Information on faults workshop/Service Consultation

There is no information on faults.

Navigation map

Installed map	Enabling code (subscription)	Latest navigation map included in subscription	Latest navigation map subject to charge
Road Map EUROPE Next 2015-2 (As of: 1 Aug 2025)	Enabling code valid for navigation maps with release date up to 31 Dec 2025 (SWID: 00A9008F).	Road Map EUROPE WEST Next 2025	-

Vehicle details

Vehicle type	Passenger car
Brand	BMW
Model	420D xDr
Body	COUPE
Vehicle identification number (last 7 digits)	G313718
Vehicle identification number (17 digits)	WBA4F11090G313718
Development code	F36
Steering	LL
Engine	B47O
Engine number	59339289
Exhaust re-treatment	EURO6;W;PI/CI; M, N1 I
Transmission	AUT
Transmission number	0044186XA6
Head unit serial number	HB2068F8082402
Drive	ALLR
Integration level, works	F020-15-03-503
Production date	18 Jun 2015
Production plant	Dingolfing
Delivery date	24 Jun 2015
Delivering retailer	No information
National-market version	EUR
Paint code	A89
Upholstery code	CBAT
Model code	4F21
Basic type	4F11
Lead type	4F21

Optional equipment

Optional equipment ex works:

01CA Selection of COP-relevant vehicles
0205 Automatic transmission
0230 Extra package, EU-speciifc
0248 Steering wheel heater
0258 Tyres with runflat properties
02A5 BMW LA wheel, double spoke 397
02VB Tyre pressure display
02VL Variable sport steering
02XE Leather sports steering wheel
0316 automatic trunk lid mechanism
0320 Deleted, model lettering
0321 Exterior parts in body colour
0322 Comfort access
0423 Floor mats velours
0428 Warning triangle and first aid kit
0430 Interior/outside mirror with auto dip
0431 Interior mirror with automatic-dip
0465 Through-loading system
0481 Sports seat
0488 Lumbar support, driver and passenger
0493 Storage compartment package
0494 Seat heating driver/passenger
04AD Interior trim strips, brushed aluminium
04AE Armrest front, retractable
04DL Accent strips, black, high-polish
0502 Headlight cleaning system
0508 Park Distance Control (PDC)
0521 Rain sensor
0522 Xenon Light
0524 Adaptive Headlights
0534 Automatic air conditioning
0544 Cruise control with braking function
0548 Kilometre speedo
0563 Light package
0575 Additional 12V power socket
05AC High-beam assistant
05DA Passenger airbag deactivation
0609 Navigation system Professional
0610 Head-up display
0688 Harman/Kardon surround sound system
0698 Area-Code 2 for DVD
06AC Intelligent emergency call
06AE Teleservices
06AK Connected Drive Services
06AM Real-Time Traffic Information
06AN Concierge Services
06AP Remote Services
06NS Comfort telephony w/ enhanced Smartphone
06WA Instrument panel with extended scope
0760 High gloss shadow line
0775 Headlining anthracite
07AC Sport Line
07R7 Innovation package
07VB Comfort Package
07XP Navigation package Connected Drive
0801 German version
0851 Language version German
0879 On-board literature, German
08KA Oil service interval 24 mths / 30,000 km
08TH Road sign detection
09AA Outer skin protection
A090 90 Ah AGM battery
POLS Cloth cushion

Retrofitted optional equipment:

This vehicle has no retrofits.

Vehicle histories

	Date	Type	Vehicle mileage	Retailer	Overview
—	01/08/2025	Warranty	197993 Km	28244	Job: F1x F2x F3x G0x G1x G3x B47O B47K B47U B47T Replacing

— Job: F1x F2x F3x G0x G1x G3x B47O B47K B47U B47T Replacing EGR cooler (high-temperature)

Description: F1x F2x F3x G0x G1x G3x B47O B47K B47U B47T Replacing EGR cooler (high-temperature)

Considered as a repeat visit No

Customer's own words

Replace exhaust gas recirculation cooler, including exhaust gas recirculation valve Flat rate unit I 00 74 057	25 FRU
--	--------

Additional work: run function test for pressure sensor system Flat rate unit I 00 74 636	3 FRU
---	-------

Additional work: enter component identification of new exhaust gas recirculation cooler in diagnostic system Flat rate unit I 00 74 637	1 FRU
---	-------

Additional work cleaning the exhaust gas recirculation pipe Flat rate unit I 00 74 638	6 FRU
---	-------

F1x F2x F3x G0x G1x G3x B47O B47K B47U B47T Replacing EGR
cooler (high-temperature)
Defect I 00 11 13 07 00

Acoustic cover front Part I 11 14 8 490 577	1
--	---

O-ring Part I 11 61 8 512 681	1
----------------------------------	---

Connection piece Part I 11 65 7 803 012	1
--	---

Pipe union Part I 11 71 7 799 853	2
--------------------------------------	---

Exhaust gas radiator high temperature Part I 11 71 7 822 347	1
---	---

EGR small parts set Part I 11 71 8 490 640	1
---	---

Holder Part I 61 13 1 369 832	1
----------------------------------	---

Pipe Part I 13 71 7 823 517	1
--------------------------------	---

— Job: E84 Fx Gx Bx7 Nx7 Customer notification exhaust gas recirculation cooler


Description: E84 Fx Gx Bx7 Nx7 Customer notification exhaust gas recirculation cooler

Considered as a repeat visit No


Customer's own words

Administrative effort Flat rate unit I 00 74 758	1 FRU
---	-------

E84 Fx Gx Bx7 Nx7 Customer notification exhaust gas recirculation
cooler
Defect I 00 11 35 07 00



— 24/07/2025 Key 197783 Km 28244 Remote KeyRead



— 25/10/2022 Repair 167680 Km 28243 ahg
Autohandelsgesellschaft
mbH , Pforzheim Job

— Job

Description:

Considered as a repeat visit No

Customer's own words

Vehicle surface wash	1 FRU
Flat rate unit I 00 11 319	

— 25/10/2022 Warranty 167681 Km 28243 Job: F1x F2x F3x B47O B47K B47U Programming control units (DDE)

— Job: F1x F2x F3x B47O B47K B47U Programming control units (DDE)

Description: F1x F2x F3x B47O B47K B47U Programming control units (DDE)

Considered as a repeat visit No

Customer's own words

Program control units	9 FRU
Flat rate unit I 00 71 349	

Initialising sunroof and power windows	1 FRU
Flat rate unit I 61 00 830	

Additionally delete fault memory	1 FRU
Flat rate unit I 61 00 981	

F1x F2x F3x B47O B47K B47U Programming control units (DDE)
Defect I 00 13 50 03 00

— 25/10/2022 Warranty 167681 Km 28243 Job: F1x F2x F3x B47O B47K B47U Programming control units (DDE)

— Job: F1x F2x F3x B47O B47K B47U Programming control units (DDE)

Description: F1x F2x F3x B47O B47K B47U Programming control units (DDE)

Considered as a repeat visit No

Customer's own words

Program control units	9 FRU
Flat rate unit I 00 71 349	

Initialising sunroof and power windows	1 FRU
Flat rate unit I 61 00 830	

Additionally delete fault memory
Flat rate unit I 61 00 981

1 FRU

F1x F2x F3x B47O B47K B47U Programming control units (DDE)
Defect I 00 13 50 03 00

—	24/10/2022	Key	167680 Km		28243	Key 0			
									
	8000	8000	8000	8000	18000	70000	8000		
	06/2023	06/2023	06/2023	06/2023		07/2024		06/2023	07/2024
—	20/01/2022	Key	157097 Km		Key 0				
									
	20000	20000	20000	20000	29000	5000	20000		
	06/2023	491	491	491		08/2022		06/2023	08/2022
—	22/01/2020	Warranty	123782 Km		28243	Job: F1x F2x F3x F4x G0x G1x G3x B47 Check and if required replace exhaust-gas recirculation cooler			

— Job: F1x F2x F3x F4x G0x G1x G3x B47 Check and if required replace exhaust-gas recirculation cooler

Description: F1x F2x F3x F4x G0x G1x G3x B47 Check and if required replace exhaust-gas recirculation cooler

Considered as a repeat visit No

Customer's own words

Check label/ replace exhaust-gas recirculation cooler and remount exhaust-gas recirculation valve; clean exhaust-gas recirculation pipe
Flat rate unit I 00 68 166 30 FRU

Performing additional work for pressure sensor function
Flat rate unit I 00 68 742 3 FRU

F1x F2x F3x F4x G0x G1x G3x B47 Check and if required replace exhaust-gas recirculation cooler
Defect I 00 11 40 05 00

O-ring
Part I 11 61 8 583 456 1

Pipe union
Part I 11 71 7 799 853 2

exhaust cooler
Part I 11 71 8 596 444 1

Set of small parts
Part I 11 71 8 597 652 1

Oval head screw
Part I 35 21 7 685 343 2

—	21/01/2020	Key		123775 Km	28243		Key 1	
								
21000	0	21000	0	60000	0	29000	60000	0
07/2021		556			06/2020		07/2023	08/2020

—	21/05/2019	Key	112145 Km	01569	Key 1
---	------------	-----	-----------	-------	-------



— 03/12/2018 Repair 103694 Km 01569 Autohaus Netuschil GmbH, Böblingen Job

— Job

Description:

Considered as a repeat visit No

Customer's own words

— 03/12/2018 Warranty 103697 Km 01569 Job: Exhaust gas recirculation valve (EGR)

— Job: Exhaust gas recirculation valve (EGR)

Description: Exhaust gas recirculation valve (EGR)

Considered as a repeat visit No

Customer's own words

Performing vehicle test 4 FRU
Flat rate unit I 00 00 006

Replacing exhaust gas recirculation valve 7 FRU
Flat rate unit I 11 71 501

Vehicle diagnosis - carrying out the ABL 4 FRU
Flat rate unit I 61 00 006

Supporting the voltage of the vehicle electrical system/recharging the vehicle electrical system battery 0 FRU
Flat rate unit I 61 21 528

Job time without allowance for / electrical system 2 FRU
Flat rate unit I 61 99 000

Exhaust gas recirculation valve (EGR)
Defect I 11 71 01 83 00

Hex Bolt with washer 1
Part I 07 11 9 905 750

Hose clamp 2
Part I 07 12 9 952 104

EGR-valve 1
Part I 11 71 8 513 132

Gasket Steel 1
Part I 11 71 8 579 364

Oval head screw 2
Part I 35 21 7 685 343

— 30/11/2018 Key 103694 Km Key 1

									
11000	11000	11000	11000	37000	0	60000	11000		0
02/2020	455	455	455		06/2020		02/2020		08/2020

— 30/11/2018 Repair 103697 Km 01569
 Autohaus
 Netuschil
 GmbH,
 Böblingen

— Job

Description:

Considered as a repeat visit No

Customer's own words

Netuschil Flüssigkeiten Test Local 2 FRU
 Flat rate unit I 03 00 333

Holder 1
 Part I 61 13 1 369 832

Anti-freeze 0.5
 Part I 83 19 2 211 191

— Job

Description:

Considered as a repeat visit No

Customer's own words

Vehicle surface wash 1 FRU
 Flat rate unit I 00 11 319

— 26/11/2018 Key 103241 Km Key 1

									
12000	12000	12000	12000	38000	0	60000	12000		0
02/2020	459	459	459		06/2020		02/2020		08/2020

— 28/06/2018 Warranty 96723 Km 00083 Job: Service - brake fluid
 Job: Service - standard scope

— Job: Service - brake fluid

Description: Service - brake fluid

Considered as a repeat visit No

Customer's own words

Brake fluid service 4 FRU
 Flat rate unit I 00 00 618

Service - brake fluid
 Defect I 87 34 00 00 00

— Job: Service - standard scope

Description: Service - standard scope

Considered as a repeat visit No

Customer's own words

Service - standard scope
Flat rate unit I 00 00 105

2 FRU

Service - standard scope
Defect I 87 00 06 00 00

— 28/06/2018 Warranty 96723 Km 00083 Job: Radial shaft sealing ring
(RWDR) / dust plate on input flange

— Job: Radial shaft sealing ring (RWDR) / dust plate on input flange

Description: Radial shaft sealing ring (RWDR) / dust plate on input flange

Considered as a repeat visit No

Customer's own words

Performing vehicle test 0 FRU
Flat rate unit I 00 00 556

Supporting the voltage of the vehicle electrical system/recharging the
vehicle electrical system battery 0 FRU
Flat rate unit I 61 21 528

Replace left and right radial shaft seal for driven shafts on rear axle
differential 0 FRU
Flat rate unit I 33 10 524

Radial shaft sealing ring (RWDR) / dust plate on input flange
Defect I 33 12 02 48 00

Gasket set differential 1
Part I 33 10 7 564 416

Repair kit, recessed nut, blue 1
Part I 33 12 7 607 158

Torx bolt 2
Part I 33 30 6 861 221

Torx screw 6
Part I 33 32 6 764 505

Self-locking hex nut 3
Part I 26 12 7 536 563

Self-locking collar nut 1
Part I 33 30 6 760 349

Hex Bolt with washer 2
Part I 33 17 6 760 343


Self-locking hex nut 3
Part I 26 12 7 536 563

Hex Bolt 3
Part I 26 11 7 527 475

Screw plug with O-ring 1
Part I 33 11 7 525 064

Gasket set differential 1
Part I 33 10 7 564 416

— 25/06/2018 Service 96723 Km 00083 Manual
Niederlassung
Hamburg,
Hamburg



— 25/06/2018 Repair

96723 Km

00083
Niederlassung
Hamburg
BMW AG,
Hamburg

Job
Job
Job
Job
Job
Job
Job

— Job

Description:

Considered as a repeat visit No

Customer's own words

Brake fluid service Flat rate unit I 00 00 618	4 FRU
---	-------

Brake fluid DOT4 LV, low viscosity Part I 83 13 2 184 843	1
--	---

— Job

Description:

Considered as a repeat visit No

Customer's own words

Service - standard scope Flat rate unit I 00 00 105	2 FRU
--	-------

— Job

Description:

Considered as a repeat visit No

Customer's own words *Laut DEKRA Radialwellendichtring HA Diff undicht- bitte prüfen und nach,Befund Rückspr.,

Performing vehicle test Flat rate unit I 00 00 556	2 FRU
---	-------

Supporting the voltage of the vehicle electrical system/recharging the vehicle electrical system battery Flat rate unit I 61 21 528	1 FRU
---	-------

Replace left and right radial shaft seal for driven shafts on rear axle differential Flat rate unit I 33 10 524	22 FRU
---	--------

Gasket set differential Part I 33 10 7 564 416	2
---	---

Repair kit, recessed nut, blue Part I 33 12 7 607 158	1
--	---

Torx bolt Part I 33 30 6 861 221	2
-------------------------------------	---

Self-locking collar nut Part I 33 30 6 760 349	1
---	---

Hex Bolt with washer Part I 33 17 6 760 343	2
--	---

Self-locking hex nut	3
----------------------	---

Part I 26 12 7 536 563

Hex Bolt Part I 26 11 7 527 475	3
------------------------------------	---

Screw plug with O-ring Part I 33 11 7 525 064	1
--	---

Self-locking hex nut Part I 26 12 7 536 563	3
--	---

Torx screw Part I 33 32 6 764 505	6
--------------------------------------	---

— Job

Description:

Considered as a repeat visit No

Customer's own words Arbeitszeit ohne Vorgabe/Hinterachse,,-keine FS einträge,,-keine passende Maßnahme vorhanden,,-NED für Undichtigkeit am HA-Getriebe abarbeiten:,-> lt. Testmodul Radialwellendichtring der Abtriebswelle links ersetzen,,An der rechten Abtriebswelle bildet sich auch eine leichte Ölspur. Nach,eigenen Befinde Wellendichtring der Abtriebswelle rechts mit ersetzen,,B: beide Radialwellendichtringe der Abtriebswellen ersetzen,,Ölspuren an Hinterachsgetriebe entfernen (nach Rep.),

Digitalbilder fertigen Flat rate unit I AZ41 12 7	Local	1 FRU
--	-------	-------

Kulanz prüfen Flat rate unit I AZ00KUP	Local	1 FRU
---	-------	-------

Job time without allowance for / rear axle Flat rate unit I 33 99 000		1 FRU
--	--	-------

Job time without allowance for / rear axle Flat rate unit I 33 99 000		2 FRU
--	--	-------

— Job

Description:

Considered as a repeat visit No

Customer's own words Analysefahrt nach durchgeführten Wartungs- und Reparaturarbeiten,durch den Mechaniker auf dem Servicehof.,

Analysefahrt nach durchgeführten Wartung Flat rate unit I AZ00PRO	Local	1 FRU
--	-------	-------

— Job

Description:

Considered as a repeat visit No

Customer's own words

Grease Optitemp HT 1 LF Part I 83 23 0 417 754	1
---	---

Lubricating mat.Optitemp 2 LN 584 LO Part I 83 19 0 447 919	1
--	---

Safety cleaner 2.0 Part I 83 19 2 364 762	5
--	---

Hypoid axle oil G1 Part I 83 22 2 295 532	1
--	---

— Job

Description:

Considered as a repeat visit No

Customer's own words

—	22/06/2018	Key		96723 Km	00083	Key 0			
									
	20000	20000	20000	20000	48000	0	80000	20000	0
	02/2020	617	617	617		06/2018		02/2020	06/2018
—	02/05/2018	Key		93070 Km	28043	Key 0			
									
	23000	23000	23000	23000	50000	0	80000	23000	0
	02/2020	668	668	668		06/2018		02/2020	06/2018
—	02/05/2018	Repair		93070 Km	28043	Job			
					Autohaus Riegel GmbH , Trittau				

— Job

Description:

Considered as a repeat visit No

Customer's own words

zum Lackierer verbracht Flat rate unit -	Local	1 FRU
Lackierungs-Fremdleistung Flat rate unit -	Local	1 FRU
Tür vorn rechts lackiert Flat rate unit -	Local	1 FRU
-Spiegelkappe rechts lackiert- Flat rate unit -	Local	1 FRU
Replace front left or right door Flat rate unit 41 51 101		40 FRU
Cavity preservation for left or right front door Flat rate unit 97 51 500		5 FRU
Door, front, right Part 41 00 7 347 722		1
Joint seal, door, front Part 51 76 7 310 234		1
Channel cover,exterior,door, front right Part 51 35 7 310 206		1
Sound insulation, door, front right Part 51 48 7 410 006		1
Clip Natur Part 51 43 7 001 491		1
Clamp Part 51 41 8 240 509		5

—	02/05/2018	Repair	93070 Km	28043	Job Job Job
				Autohaus	

— Job

Description:
Considered as a repeat visit No
Customer's own words

Sommerräder stationär ausgewuchtet Flat rate unit -	Local	8 FRU
Sommerräder montiert Flat rate unit -	Local	5 FRU
Anteilige Kosten für Winterräder Flat rate unit -	Local	1 FRU

— Job

Description:
Considered as a repeat visit No
Customer's own words

Dellenentfernung ohne Lackierung Flat rate unit -	Local	1 FRU
-Seitenteil HL- Flat rate unit -	Local	1 FRU

— Job

Description:
Considered as a repeat visit No
Customer's own words

Anteilige Kosten für Fahrzeug- Flat rate unit -	Local	0 FRU
--	-------	-------

17/04/2018		Key	92114 Km		28043		Key 0	
								
24000	24000	24000	24000	50000	0	80000	24000	0
02/2020	683	683	683		06/2018		02/2020	06/2018

17/04/2018	Repair	92114 Km	28043	Job
			Autohaus Riegel GmbH , Trittau	

— Job

Description:
Considered as a repeat visit No
Customer's own words

Replacing light bulb for right xenon headlight Flat rate unit 63 99 077	4 FRU
Bulb Xenon light with ignition element Part 63 21 7 217 509	1

— 28/03/2018 Repair 1 Km 28043 Job
 Autohaus
 Riegel GmbH,
 Trittau

— Job


Description:

Considered as a repeat visit No


Customer's own words

Set of wiper blades 1
 Part I 61 61 2 349 870

— 19/03/2018 Key 87666 Km 28043 Key 0



— 19/03/2018 Service 87666 Km 28043 Automatic
 Autohaus
 Riegel GmbH,
 Trittau



— 19/03/2018 Repair 87677 Km 28043 Job
 Autohaus
 Riegel GmbH,
 Trittau

— Job

Description:

Considered as a repeat visit No

Customer's own words

Bremspaste Local 1
 Part I F/91000000158

Repair kit, brake pads asbestos-free 1
 Part I 34 21 6 873 093

Brake-pad sensor, rear 1
 Part I 34 35 6 792 292

Brake disc, ventilated 2
 Part I 34 21 6 864 900

Inner hex bolt 2
 Part I 34 21 1 161 806

Brake cleaner acetone-free 1
 Part I 83 19 2 413 695

— Job

Description:

Considered as a repeat visit No

Customer's own words

- 14/02/2018 Key 85506 Km 28043 Key 10

 110 03/2019	 0	 110 410	 0	 60000	 0 06/2018	 6000	 30000 03/2021	 0 06/2018
---	--	---	--	--	---	---	---	---
- 14/02/2018 Service 85506 Km 28043 Automatic
Autohaus
Riegel GmbH,
Trittau

 110 ✓	 0	 110 ✓	 0	 60000 06/2018	 6000	 30000	 06/2018
---	--	---	--	---	---	--	--
- 13/02/2018 Warranty 85509 Km 28043

Job: Service - standard scope
Job: Engine oil service
Job: Service - micro filter/activated carbon filter

Job: Service - standard scope

Description: Service - standard scope

Considered as a repeat visit No

Customer's own words

Service - standard scope Flat rate unit I 00 00 105	2 FRU
--	-------

Service - standard scope Defect I 87 00 06 00 00

Job: Engine oil service

Description: Engine oil service

Considered as a repeat visit No

Customer's own words

Engine oil service Flat rate unit I 00 00 610	3 FRU
--	-------

Engine oil service Defect I 87 00 02 00 00

Set oil-filter element Part I 11 42 8 575 211	1
--	---

Job: Service - micro filter/activated carbon filter

Description: Service - micro filter/activated carbon filter

Considered as a repeat visit No


Customer's own words

Microfilter service 2 FRU
Flat rate unit I 00 00 616


Service - micro filter/activated carbon filter
Defect I 87 64 01 00 00

Microfilter/activated Carbon container 1
Part I 64 11 9 237 555

— 16/10/2017 Key 74424 Km 28043 Key 0



— 16/10/2017 Key 74374 Km 28043 Key 0



— 16/10/2017 Repair 74424 Km 28043 Job
Autohaus Riegel GmbH , Tittau Job

— Job

Description:

Considered as a repeat visit No

Customer's own words

Winterräder stationär ausgewuchtet Local 8 FRU
Flat rate unit I -

Winterräder montiert Local 5 FRU
Flat rate unit I -

Anteilige Kosten für Sommerräder Local 0 FRU
Flat rate unit I -

Klebegewicht,5g Local 49
Part I F/99000000712

— Job

Description:

Considered as a repeat visit No

Customer's own words

Light function test 2 FRU
Flat rate unit I 00 12 290

Checking antifreeze concentration 2 FRU
Flat rate unit I 00 12 121

Windshield washer antifreeze 3
Part I 83 12 0 404 498

— 16/10/2017 Warranty 74424 Km 28043 Job: F1x F2x F3x B47
programming control units and if necessary, replacing the EGR valve

- Job: F1x F2x F3x B47 programming control units and if necessary, replacing the EGR valve

Description: F1x F2x F3x B47 programming control units and if necessary, replacing the EGR valve


Considered as a repeat visit No

Customer's own words

Carrying out the ABL and programming the control units 8 FRU
Flat rate unit I 00 64 941

F1x F2x F3x B47 programming control units and if necessary, replacing the EGR valve
Defect I 00 11 45 04 00

- 07/09/2017 Key 68890 Km 28043 Key 0



- 07/09/2017 Warranty 68901 Km 28043 Job

- Job

Description:

Considered as a repeat visit No

Customer's own words

Replacing the exhaust-gas recirculation cooler 25 FRU
Flat rate unit I 00 64 199

Defect I 00 11 36 04 00


exhaust cooler 1
Part I 11 71 8 596 444

Set of small parts 1
Part I 11 71 8 597 652

Pipe union 2
Part I 11 71 7 799 853

Oval head screw 2
Part I 35 21 7 685 343

- 31/05/2017 Key 61697 Km 28043 Key 0



- 31/05/2017 Repair 61701 Km 28043 Job

Autohaus
Riegel GmbH ,
Trittau

- Job

Description:

Considered as a repeat visit No

Customer's own words

Additional job with rain/light sensor 3 FRU

Flat rate unit | 61 35 994

Feinstaubplakette grün
Part I 99 99 9 999 094

Local

1

Green windscreen
Part I 51 31 7 285 901

1

Cover, windshield, top
Part I 51 31 7 285 915

1

Bump stop
Part I 51 31 7 288 462

10

Sound insulation f apron
Part I 51 48 7 325 890

1

Sensor rain/light/solar/misting over HUD
Part I 61 35 9 861 557

1

Repair kit, window glass, cold, 1 hour
Part I 83 19 2 289 285

1

Clip Natur
Part I 51 43 7 001 491







1

— 26/04/2017 Key

59015 Km

28043

Key 0







— 26/04/2017 Service

59015 Km

28043

Automatic

Autohaus
Riegel GmbH,
Trittau



— 26/04/2017 Repair

59021 Km

28043

Job

Autohaus
Riegel GmbH ,
Trittau

Job

— Job

Description:

Considered as a repeat visit No

Customer's own words

Sommerräder stationär ausgewuchtet
Flat rate unit | -

Local

8 FRU

Sommerräder montiert
Flat rate unit | -

Local

5 FRU

Anteilige Kosten für Winterräder
Flat rate unit | -

Local

1 FRU

Klebegewicht,5g
Part I F/99000000712

Local

30

— Job

Description:

Considered as a repeat visit No

Customer's own words

Removing and installing or replacing both front brake discs
Flat rate unit I 34 11 610 7 FRU

Bremspaste Local 1
Part I F/91000000158




Repair kit, brake pads asbestos-free 1
Part I 34 10 6 859 181

Brake pad wear sensor, front left 1
Part I 34 35 6 792 289

Brake cleaner acetone-free 1
Part I 83 19 2 413 695

Brake disc, ventilated 2
Part I 34 11 6 792 219

Inner hex bolt 2
Part I 34 21 1 161 806



— Job

Description:

Considered as a repeat visit No

Customer's own words

Service - standard scope 2 FRU
Flat rate unit I 00 00 105

— Job

Description:

Considered as a repeat visit No

Customer's own words

Engine oil service Flat rate unit I 00 00 610	3 FRU
--	-------

Special agreement with warranty department Flat rate unit I 00 00 162	0 FRU
--	-------

Synt.Motoröl/5W30 Part I F/91000000296	Local	5
---	-------	---

Set oil-filter element Part I 11 42 8 575 211	1
--	---

Windshield washer antifreeze Part I 83 12 0 404 498	2
--	---

— Job

Description:

Considered as a repeat visit No

Customer's own words

Microfilter service Flat rate unit I 00 00 616	2 FRU
---	-------

Microfilter/activated Carbon container Part I 64 11 9 237 555	1
--	---

— Job

Description:

Considered as a repeat visit No

Customer's own words

Service - air filter element Flat rate unit I 00 00 602	2 FRU
--	-------

Air filter element Part I 13 71 8 511 668	1
--	---

— Job

Description:

Considered as a repeat visit No

Customer's own words

Service fuel filter Flat rate unit I 00 00 604	3 FRU
---	-------

Fuel filter cartridge Part I 13 32 8 572 522	1
---	---

— Job

Description:

Considered as a repeat visit No

Customer's own words

Service, vehicle check Flat rate unit I 00 00 624	6 FRU
--	-------

—	02/03/2017 Warranty	56029 Km	28043	Job: Service - standard scope Job: Engine oil service Job: Service - micro filter/activated carbon filter Job: Service - air cleaner Job: Service - fuel filter Job: Service - vehicle check
---	---------------------	----------	-------	---

— Job: Service - standard scope

Description: Service - standard scope

Considered as a repeat visit No

Customer's own words

Service - standard scope	2 FRU
Flat rate unit I 00 00 105	

Service - standard scope
Defect I 87 00 06 00 00

— Job: Engine oil service

Description: Engine oil service

Considered as a repeat visit No

Customer's own words

Engine oil service	3 FRU
Flat rate unit I 00 00 610	

Engine oil service
Defect I 87 00 02 00 00

Set oil-filter element	1
Part I 11 42 8 575 211	

— Job: Service - micro filter/activated carbon filter

Description: Service - micro filter/activated carbon filter

Considered as a repeat visit No

Customer's own words

Microfilter service	2 FRU
Flat rate unit I 00 00 616	

Service - micro filter/activated carbon filter
Defect I 87 64 01 00 00

Microfilter/activated Carbon container	1
Part I 64 11 9 237 555	

— Job: Service - air cleaner

Description: Service - air cleaner

Considered as a repeat visit No

Customer's own words

Service - air filter element	2 FRU
Flat rate unit I 00 00 602	

Service - air cleaner
Defect I 87 13 01 00 00

Air filter element	1
Part I 13 71 8 511 668	

— Job: Service - fuel filter

Description: Service - fuel filter

Considered as a repeat visit No

Customer's own words

Service fuel filter	3 FRU
Flat rate unit I 00 00 604	

Service - fuel filter
Defect I 87 13 02 00 00

Fuel filter cartridge	1
Part I 13 32 8 572 522	

— Job: Service - vehicle check

Description: Service - vehicle check

Considered as a repeat visit No

Customer's own words

Service, vehicle check	6 FRU
Flat rate unit I 00 00 624	


Service - vehicle check
Defect I 87 00 05 00 00

— 27/10/2016 Key

45667 Km

28043

Key 0



— 27/10/2016 Repair

45710 Km

28043
Autohaus
Riegel GmbH,
Trittau

Job
Job

— Job

Description:

Considered as a repeat visit No

Customer's own words

Winterräder stationär ausgewuchtet	Local	8 FRU
Flat rate unit I 36 10 364		

Winterräder montiert	Local	5 FRU
Flat rate unit I 36 10 361		

Anteilige Kosten für Sommerräder Einlagerung (incl. Reinigung)	Local	1 FRU
Flat rate unit I 36 99 001		

Klebegewicht,5g	Local	41
Part I 99 00 0 000 712		

— Job

Description:

Considered as a repeat visit No

Customer's own words

Light function test	2 FRU
Flat rate unit I 00 12 290	

Checking antifreeze concentration	2 FRU
-----------------------------------	-------

Windshield washer antifreeze
Part I 83 12 0 404 498

2

— 23/09/2016 Key 43247 Km 28043 Key 0

								
14000	14000	14000	14000	45000	0	32000	14000	0
04/2018	584	584	584		06/2018		04/2018	06/2018

— 23/09/2016 Repair 43247 Km 28043 Job
Autohaus
Riegel GmbH ,
Trittau

— Job

Description:

Considered as a repeat visit No

Customer's own words

Troubleshooting in the tyre pressure control (RDC) system
Flat rate unit I 36 11 100

4 FRU

— 19/04/2016 Key 25885 Km 28043 Key 0

								
28000	28000	28000	28000	60000	0	45000	28000	0
04/2018	740	740	740		06/2018		04/2018	06/2018

— 19/04/2016 Key 25876 Km 28043 Key 0

								
2100	0	2100	0	60000	0	45000	31000	0
06/2017		437			06/2018		06/2019	06/2018

— 19/04/2016 Service 25876 Km 28043 Manual
Autohaus
Riegel GmbH,
Trittau

											
✓		✓									

— 19/04/2016 Repair 25885 Km 28043 Job
Autohaus
Riegel GmbH ,
Trittau

— Job

Description:

Considered as a repeat visit No

Customer's own words

Sommerräder stationär ausgewuchtet

Local

8 FRU

Flat rate unit | 36 10 364

Sommerräder montiert Flat rate unit 36 10 362	Local	5 FRU
--	-------	-------

Anteilige Kosten für Winterräder Einlagerung (incl. Reinigung) Flat rate unit 36 99 001	Local	1 FRU
--	-------	-------

Klebegewicht,5g Part 99 00 0 000 712	Local	47
---	-------	----

—	19/04/2016	Warranty	25876 Km	28043	Job: Service - standard scope Job: Engine oil service Job: Service - micro filter/activated carbon filter
---	------------	----------	----------	-------	---

— Job: Service - standard scope

Description: Service - standard scope

Considered as a repeat visit No

Customer's own words

Service - standard scope Flat rate unit 00 00 105	2 FRU
--	-------

Service - standard scope Defect 87 00 06 00 00

— Job: Engine oil service

Description: Engine oil service

Considered as a repeat visit No

Customer's own words

Engine oil service Flat rate unit 00 00 610	3 FRU
--	-------

Engine oil service Defect 87 00 02 00 00

Set oil-filter element Part 11 42 8 575 211	1
--	---

— Job: Service - micro filter/activated carbon filter

Description: Service - micro filter/activated carbon filter

Considered as a repeat visit No

Customer's own words

Microfilter service Flat rate unit 00 00 616	2 FRU
---	-------

Service - micro filter/activated carbon filter Defect 87 64 01 00 00

Microfilter/activated Carbon container Part 64 11 9 237 555	1
--	---

—	19/04/2016	Warranty	25885 Km	28043	Job: F1x F2x F3x F4x B47 Replacing the exhaust-gas recirculation valve
---	------------	----------	----------	-------	---

— Job: F1x F2x F3x F4x B47 Replacing the exhaust-gas recirculation valve

Description: F1x F2x F3x F4x B47 Replacing the exhaust-gas recirculation valve

Considered as a repeat visit No

Customer's own words

Replace exhaust-gas recirculation valve
Flat rate unit I 00 64 011 10 FRU

F1x F2x F3x F4x B47 Replacing the exhaust-gas recirculation valve
Defect I 00 11 15 04 00


EGR-valve
Part I 11 71 8 594 492 1

Gasket Steel
Part I 11 71 8 579 364 1

Oval head screw
Part I 35 21 7 685 343 2

Hose clamp
Part I 07 12 9 952 104 2

— 16/11/2015 Key 10850 Km 28043 Key 0



— 16/11/2015 Repair 10849 Km 28043 Job
Autohaus Riegel GmbH, Trittau Job

— Job

Description:

Considered as a repeat visit No

Customer's own words

neue Winterräder montiert
Flat rate unit I 36 10 361 Local 5 FRU

Anteilige Kosten für Sommerräder Einlagerung (incl. Reinigung)
Flat rate unit I 36 99 001 Local 1 FRU

RDCi wheel with tyre, winter Ferricgrey
Part I 36 11 2 289 747 4

— Job

Description:

Considered as a repeat visit No

Customer's own words

Checking antifreeze concentration
Flat rate unit I 00 12 121 2 FRU