

Thank you for ordering from us!

www.checkvin.eu

Vehicle

BMW 320D, 140KW

WBA8C51010K638376



Development code
Colour
Actual integration level
Start of warranty

F30
mineral-grau metallic
F020-22-07-530
29 February 2016

Technical campaigns

There are no Campaigns for this vehicle.

Warranty extension/VIN-based goodwill

Status	Campaign number	Description
Open	1SACC011056	Exhaust gas recirculation cooler Bx7 Local campaign number: -

Special information

There are no Campaigns for this vehicle.

Restrictions on the warranty

There are no restrictions on the warranty.

⚠ Market-specific restrictions are not currently displayed. Please check this in WDF/WXE via S-Gate.

Live Diagnosis

 There are no service solutions for Live Diagnosis.

Service contracts

No BSI contracts

Information on faults workshop/Service Consultation

There is no information on faults.

Navigation map

Note: The installed map cannot be clearly identified. Presumably one of the following maps is present in the vehicle.

Installed map	Enabling code (subscription)	Latest navigation map included in subscription	Latest navigation map subject to charge
Road Map EUROPE EVO 2022-1 (As of: 30 Nov 2023)	-	-	-
Road Map EUROPE EVO 2022-1 (As of: 30 Nov 2023)	Enabling code valid for navigation maps with release date up to 31 Dec 2099 (SWID: 00F10FFF).	Road Map EUROPE EVO 2025-2	-

Vehicle details

Vehicle type	Passenger car
Brand	BMW
Model	320D
Body	LIM
Vehicle identification number (last 7 digits)	K638376
Vehicle identification number (17 digits)	WBA8C51010K638376
Development code	F30
Steering	LL
Engine	B47O
Engine number	53319532
Exhaust re-treatment	EURO6;W;PI/CI; M, N1 I
Transmission	AUT
Transmission number	0232448ZRI
Head unit serial number	HB2140G7799740
Drive	HECK
Integration level, works	F020-15-11-505
Production date	13 Feb 2016
Production plant	Muenchen
Delivery date	17 Feb 2016
Delivering retailer	No information
National-market version	EUR
Paint code	B39
Upholstery code	LCSW
Model code	8C61
Basic type	8C51
Lead type	8C61

Optional equipment

Optional equipment ex works:


01CA Selection of COP-relevant vehicles
01CB CO2 equipment
0205 Automatic transmission
0216 Hydro steering-servotronic
0230 EU-specific additional contents
0255 Sports leather steering wheel
0258 Tyres with runflat properties
02H3 BMW LA wheel, multi spoke 414
02PA Locking wheel bolt
02VB Tyre pressure display
0320 Deleted, model lettering
03AG Reversing camera
0420 Sun protection glazing
0423 Floor mats velours
0428 Warning triangle and first aid kit
0430 Interior/outside mirror with auto dip
0431 Interior mirror with automatic-dip
0441 Smoker package
0459 Seat adjustment, electric, with memory
0465 Through-loading system
0493 Storage compartment package
0494 Seat heating driver/passenger
04AE Armrest front, retractable
04FT Alum. brushed lengthw. acc. black hi-gls
0508 Park Distance Control (PDC)
0521 Rain sensor
0534 Automatic air conditioning
0544 Cruise control with brake function
0548 Kilometre speedo
0563 Light package
05A2 LED headlight
05DA Passenger airbag deactivation
05DL Surround View
0609 Navigation system Professional
0610 Head-up display
0698 Area-Code 2 for DVD
06AC Intelligent emergency call
06AE Teleservices
06AK Connected Drive Services
06AM Real-Time Traffic Information
06AN Concierge Services
06AP Remote Services
06NS Comfort telephony w/ enhanced Smartphone
06UH Traffic Information
06WA Instrument panel with extended scope
0775 Headlining anthracite
07LE Modell Luxury Line
07S2 Luxury Line
07S9 Connected Drive Services Paket
0854 Language version, French
0881 On-board literature, French
08KA Oil service interval 24 mths / 30,000 km
08S3 Automatic locking during starting
09AA Outer skin protection
0XL3 BMW Individual leather steering wheel
A090 90 Ah AGM battery
LEDE Leather equipment

Retrofitted optional equipment:


This vehicle has no retrofits.

Vehicle histories

	Date	Type	Vehicle mileage	Retailer	Overview
—	22/07/2025	Key	246372 Km	32320	Key 1



— 22/07/2025 Service 246372 Km 32320 Alfred Wahl GmbH&Co. KG , Gießen Automatic



— 22/07/2025 Warranty 246372 Km 32320 Job
— Job


Description:

Considered as a repeat visit No


Customer's own words

Defect | 85 40 00 26 SA


— 09/07/2025 Key 245516 Km 32320 Remote KeyRead




— 04/07/2025 Key 245035 Km 46477 Remote KeyRead



— 30/04/2024 Service 220035 Km 46477 Alfred Wahl GmbH&Co. KG , Marburg Automatic



— 29/04/2024 Key 220035 Km 46477 Key 1



— 29/04/2024 Repair 220040 Km 46477 , Job
Job
Job
Job
Job

— Job

Description:

Considered as a repeat visit No

Customer's own words

Service - standard scope	2 FRU
Flat rate unit I 00 00 105	

— Job

Description:

Considered as a repeat visit No

Customer's own words

Engine oil service	3 FRU
Flat rate unit I 00 00 610	

Original BMW Motorenöl LL04 0W-30	Local	5
Part I FT97 99 0 000 0		

Set oil-filter element	1
Part I 11 42 8 575 211	

— Job

Description:

Considered as a repeat visit No

Customer's own words

Microfilter service	2 FRU
Flat rate unit I 00 00 616	

Microfilter/activated Carbon container	1
Part I 64 11 9 237 555	

— Job

Description:

Considered as a repeat visit No

Customer's own words

Service fuel filter	3 FRU
Flat rate unit I 00 00 604	

Fuel filter cartridge	1
Part I 13 32 7 822 497	

— Job

Description:

Considered as a repeat visit No

Customer's own words

Service - air filter element	2 FRU
Flat rate unit I 00 00 602	

Air filter element	1
Part I 13 71 8 511 668	

— Job

Description:

Customer's own words

Flat rate unit | 00 00 624

Customer's own words

Flat rate unit | 00 00 618

Part | 83 13 2 184 843

§
02/2025

§
02/2025

Job

Customer's own words

Flat rate unit | 18 31 080

Flat rate unit | 18 31 900

Part I 18 30 8 513 960

Part | 18 30 8 512 137

Part I 18 20 8 572 331

Part | 18 20 7 823 511

Part | 18 30 8 581 218

Part | 18 30 8 513 651

Hex Bolt with washer Part I 07 11 9 904 517	1
Self-locking collar nut Part I 07 11 9 905 374	4

30/11/2023	Warranty	213543 Km	46477	Job: F1x F2x F3x G0x G1x G3x B47O B47K B47U B47T Replacing EGR cooler (high-temperature)
------------	----------	-----------	-------	--

Job: F1x F2x F3x G0x G1x G3x B47O B47K B47U B47T Replacing EGR cooler (high-temperature)








Description: F1x F2x F3x G0x G1x G3x B47O B47K B47U B47T Replacing EGR cooler (high-temperature)

Considered as a repeat visit No








Customer's own words

Replace exhaust gas recirculation cooler, including exhaust gas recirculation valve Flat rate unit I 00 74 635	23 FRU
Additional work: run function test for pressure sensor system Flat rate unit I 00 74 636	3 FRU
Additional work: enter component identification of new exhaust gas recirculation cooler in diagnostic system Flat rate unit I 00 74 637	1 FRU
Additional work cleaning the exhaust gas recirculation pipe Flat rate unit I 00 74 638	6 FRU
F1x F2x F3x G0x G1x G3x B47O B47K B47U B47T Replacing EGR cooler (high-temperature) Defect I 00 11 13 07 00	
Exhaust gas radiator high temperature Part I 11 71 7 822 347	1
EGR small parts set Part I 11 71 8 490 640	1
Pipe union Part I 11 71 7 799 853	2
Holder Part I 61 13 1 369 832	1
Connection piece Part I 11 65 7 803 012	1
O-ring Part I 11 61 8 512 681	1
Acoustic cover front Part I 11 14 8 490 577	1
Hex Bolt with washer Part I 07 11 9 905 750	1

29/11/2023	Service	213543 Km	46477 Alfred Wahl GmbH&Co. KG , Marburg	Automatic
------------	---------	-----------	---	-----------

								
12000 10/2024	12000 10/2024	12000 10/2024	12000 10/2024	600 10/2024	✓	14000 10/2024	12000 10/2024	02/2025

28/11/2023	Key	213543 Km	46477	Key 1
------------	-----	-----------	-------	-------



— 28/11/2023 Repair 213543 Km 46477 Alfred Wahl GmbH & Co. KG , Marburg Job Job Job Job

— Job

Description:

Considered as a repeat visit No

Customer's own words

Service - standard scope	2 FRU
Flat rate unit I 00 00 105	

— Job

Description:

Considered as a repeat visit No

Customer's own words

Service, front brakes	6 FRU
Flat rate unit I 00 00 612	

A.Reiniger	Local	1
Part I FT99 99 0 000 0		

Repair kit brake pads asbestos-free	1
Part I 34 11 8 855 010	

Brake pad wear sensor, front left	1
Part I 34 35 6 792 289	

Brake-pad paste	2
Part I 83 19 2 158 851	

— Job

Description:

Considered as a repeat visit No

Customer's own words

Removing and installing or replacing both front brake discs	3 FRU
Flat rate unit I 34 11 613	

Brake disc, ventilated	2
Part I 34 11 8 848 417	

Inner hex bolt	2
Part I 34 21 1 161 806	

Torx screw with washer	4
Part I 34 10 6 864 424	

— Job

Description:

Considered as a repeat visit No

Customer's own words

—

09/11/2023

Key

212674 Km

46477

Remote KeyRead

									
13000	13000	13000	13000	1400	10/2024	15000	13000		
10/2024	10/2024	10/2024	10/2024				10/2024		02/2025

—

07/10/2022

Key

197560 Km

46477

Key 1

									
3500		3500		34000	01/2023	40000	33000		
09/2023		09/2023					09/2025		02/2023

—

07/10/2022

Service

197560 Km

46477

Automatic

Autohaus Wahl
Mittelhessen
GmbH&Co. KG
, Marburg

									
3500	0	3500	0	34000	0	40000	33000		
✓		✓							

—

07/10/2022

Repair

197563 Km

46477

Job
Job
Job
Job
Job

— Job

Description:

Considered as a repeat visit No

Customer's own words

Service - standard scope

Flat rate unit | 00 00 105

2 FRU

Windshield washer antifreeze

Part | 83 12 2 413 059

0.5

— Job

Description:

Considered as a repeat visit No

Customer's own words

Engine oil service

Flat rate unit | 00 00 610

3 FRU

Original BMW Motorenöl LL04 0W-30

Part | FT97 99 0 000 0

Local

5

Set oil-filter element

Part | 11 42 8 575 211

1

— Job

Description:**Considered as a repeat visit** No**Customer's own words**

Microfilter service	2 FRU
Flat rate unit I 00 00 616	

Microfilter/activated Carbon container	1
Part I 64 11 9 237 555	

— Job

Description:**Considered as a repeat visit** No**Customer's own words**

Brake fluid service	4 FRU
Flat rate unit I 00 00 618	

Brake fluid DOT4 LV, low viscosity	1
Part I 83 13 2 184 843	

— Job

Description:**Considered as a repeat visit** No**Customer's own words**

UV additive	10
Part I 83 19 2 199 566	

Lubricant refrigeration compressor	2
Part I 83 19 0 143 174	

Cooling agent	4
Part I 83 19 0 143 177	

— Job

Description:**Considered as a repeat visit** No**Customer's own words**

Klimaanlagen Reiniger	Local	1
Part I FT99 99 0 000 4		

—	07/10/2022	Warranty	197563 Km	46477	Job: F1x F2x F3x B47O B47K B47U Programming control units (DDE)
---	------------	----------	-----------	-------	---

— Job: F1x F2x F3x B47O B47K B47U Programming control units (DDE)

Description: F1x F2x F3x B47O B47K B47U Programming control units (DDE)**Considered as a repeat visit** No**Customer's own words**

Program control units	8 FRU
Flat rate unit I 00 71 907	

Initialising sunroof and power windows	1 FRU
Flat rate unit I 61 00 830	

Additionally delete fault memory	1 FRU
Flat rate unit I 61 00 981	

21/09/2022 Key 197064 Km Remote KeyRead

 3900 09/2023		 3900 09/2023		 35000	 01/2023	 41000	 33000 09/2025	 02/2023
--	---	--	---	--	--	--	--	--

08/10/2021 Key 174135 Km Key 1

 28000 09/2023		 28000 683		 60000	 01/2023	 70000	 60000 1403	 02/2023
---	---	---	---	--	--	--	---	--

08/10/2021 Repair 174137 Km 46477 Autohaus Wahl
Mittelhessen GmbH & Co.
KG , Marburg Job

Job

Description:

Considered as a repeat visit No

Customer's own words

Removing and installing or replacing both tension struts Flat rate unit I 31 12 080	11 FRU
Combination nut Part I 33 30 6 787 062	2
Tension strut with hydr. mount, right Part I 31 12 6 855 742	1
Hexagon screw with flange Part I 31 10 6 885 777	2
Tension strut with hydr. mount, left Part I 31 12 6 855 741	1

23/09/2021 Service 171832 Km 46477 Autohaus Wahl
Mittelhessen, Marburg Manual

 ✓	 ✓	 ✓	 ✓			 ✓	 ✓	 \$	 \$
--	--	--	--	---	---	--	---	---	---

23/09/2021 Repair 171843 Km 46477 Alfred Wahl GmbH & Co. KG , Marburg Job
Job
Job
Job
Job
Job
Job
Job
Job

— Job

Description:

Considered as a repeat visit No

Customer's own words

Service - standard scope	2 FRU
Flat rate unit I 00 00 105	

— Job

Description:

Considered as a repeat visit No

Customer's own words

Engine oil service	3 FRU
Flat rate unit I 00 00 610	

Original BMW MotorenölOriginal BMW Motorenöl	Local	5
Part I FT97 99 0 000 0		

Set oil-filter element	1
Part I 11 42 8 575 211	

— Job

Description:

Considered as a repeat visit No

Customer's own words

Microfilter service	2 FRU
Flat rate unit I 00 00 616	

Microfilter/activated Carbon container	1
Part I 64 11 9 237 555	

— Job

Description:

Considered as a repeat visit No

Customer's own words

Service, vehicle check	6 FRU
Flat rate unit I 00 00 624	

— Job

Description:

Considered as a repeat visit No

Customer's own words

Service - air filter element	2 FRU
Flat rate unit I 00 00 602	

Air filter element	1
Part I 13 71 8 511 668	

— Job

Description:

Considered as a repeat visit No

Customer's own words

Service fuel filter	3 FRU
---------------------	-------

Flat rate unit | 00 00 604

Fuel filter cartridge 1
Part | 13 32 8 572 522

— Job

Description:

Considered as a repeat visit No

Customer's own words

Windshield washer antifreeze 1.5
Part | 83 12 2 413 059

— Job

Description:

Considered as a repeat visit No

Customer's own words

Service, rear brakes 7 FRU
Flat rate unit | 00 00 614

A.Reiniger Local 1
Part | FT99 99 0 000 0

Brake-pad paste 2
Part | 83 19 2 158 851

Repair kit, brake pads asbestos-free 1
Part | 34 21 6 873 093

Brake-pad sensor, rear 1
Part | 34 35 6 792 292

— Job

Description:

Considered as a repeat visit No

Customer's own words

Removing and installing or replacing both rear brake discs 4 FRU
Flat rate unit | 34 21 932

Brake disc, ventilated 2
Part | 34 21 6 792 227










Hex screw with collar 4
Part | 34 20 6 850 536

Inner hex bolt 2
Part | 34 21 1 161 806

— 22/09/2021 Key

171832 Km

Key 1



— 07/05/2021 Key

156889 Km

Key 1

 16000 01/2023	 16000 633	 16000 633	 16000 633	 5000	 0 01/2023	 6000	 16000 01/2023	 0 02/2023
--	--	--	--	--	--	--	---	--

— 07/05/2021 Service 156889 Km 46477 Automatic
Autohaus Wahl
Mittelhessen
GmbH&Co. KG
, Marburg

 16000 01/2023	 16000 01/2023	 16000 01/2023	 16000 01/2023	 5000 ✓	 0 01/2023	 6000	 16000 01/2023	 0 02/2023
---	---	---	---	--	---	---	--	---

— 07/05/2021 Repair 156897 Km 46477 Alfred Job
Wahl GmbH & Co. KG , Job
Marburg Job

— Job

Description:

Considered as a repeat visit No

Customer's own words

Service - standard scope	2 FRU
Flat rate unit I 00 00 105	

— Job

Description:

Considered as a repeat visit No

Customer's own words

Service, front brakes	6 FRU
Flat rate unit I 00 00 612	

A.Reiniger	Local	1
Part I FT99 99 0 000 0		

Brake-pad paste	2
Part I 83 19 2 158 851	

Repair kit, brake pads asbestos-free	1
Part I 34 10 6 859 181	

Brake pad wear sensor, front left	1
Part I 34 35 6 792 289	

— Job

Description:

Considered as a repeat visit No

Customer's own words

Removing and installing or replacing both front brake discs	3 FRU
Flat rate unit I 34 11 613	

Torx screw with washer	4
Part I 34 10 6 864 424	

Brake disc, ventilated	2
Part I 34 11 6 792 219	

03/02/2021		Key		147077 Km		Key 1		
								
27000	27000	27000	27000	5000	0	11000	27000	0
01/2023	726	726	726		01/2023		01/2023	02/2021

—	03/02/2021	Service	147077 Km	46477	Automatic				
				Autohaus Wahl Mittelhessen GmbH&Co. KG , Marburg					
									
27000	27000	27000	27000	5000	0	11000	27000		0
01/2023	01/2023	01/2023	01/2023		01/2023		01/2023		02/2021
									✓

—	03/02/2021	Repair	147077 Km	46477 Alfred Wahl GmbH & Co. KG , Marburg	Job Job
---	------------	--------	-----------	--	------------

— Job

Description:

Considered as a repeat visit No

Customer's own words

Service pre-check for roadworthiness test (for German market only) 0 FRU
Flat rate unit I 00 00 671

Presentation for emission inspection 7 FRU
Flat rate unit I 00 00 127

— Job

Description:

Considered as a repeat visit No

Customer's own words

HU Geb. n. §29 StVZO (zur ext. Verrechnung) 00000000 Local 1 FRU
Flat rate unit I 99 99 999

—	05/01/2021	Service	143471 Km	46477	Automatic				
				Autohaus Wahl					
				Mittelhessen					
				GmbH&Co. KG					
				, Marburg					
									
2900	0	2900	0	5000	0	14000	32000		0
05/2022		05/2022			02/2021		05/2024		02/2021
✓		✓			✓				

—	05/01/2021	Repair	143471 Km	46477 Alfred Wahl GmbH & Co. KG , Marburg	Job Job Job Job
---	------------	--------	-----------	--	--------------------------

— Job

Description:

Considered as a repeat visit No

Customer's own words

Service - standard scope	2 FRU
Flat rate unit I 00 00 105	

— Job

Description:

Considered as a repeat visit No

Customer's own words

Engine oil service	3 FRU
Flat rate unit I 00 00 610	

Original BMW Motorenöl LL04 0W-30	Local	5
Part I FT97 99 0 000 0		

Set oil-filter element	1
Part I 11 42 8 575 211	

— Job

Description:

Considered as a repeat visit No

Customer's own words

Microfilter service	2 FRU
Flat rate unit I 00 00 616	

Microfilter/activated Carbon container	1
Part I 64 11 9 237 555	

— Job

Description:

Considered as a repeat visit No

Customer's own words

Brake fluid service	4 FRU
Flat rate unit I 00 00 618	

Brake fluid DOT4 LV, low viscosity	1
Part I 83 13 2 184 843	

— Job

Description:

Considered as a repeat visit No

Customer's own words

Job time without allowance for / brakes	0 FRU
Flat rate unit I 34 99 000	

— Job

Description:

Considered as a repeat visit No

Customer's own words

Kompakt-Check
Flat rate unit I 00 52 000

Local

3 FRU

- 05/01/2021 Warranty 143471 Km 46477 Job: F1x F2x F3x G0x G1x G3x B47O B47T B47U B47K Check and, if required, replace EGR cooler (recheck)

- Job: F1x F2x F3x G0x G1x G3x B47O B47T B47U B47K Check and, if required, replace EGR cooler (recheck)

Description: F1x F2x F3x G0x G1x G3x B47O B47T B47U B47K Check and, if required, replace EGR cooler (recheck)

Considered as a repeat visit No







Customer's own words

Vis. insp. of EGR cooler outlet and inlet (OK), check CC message for coolant level (OK) and note the prod. date of the installed exhaust gas recirc. cooler
Flat rate unit I 00 70 532



12 FRU

F1x F2x F3x G0x G1x G3x B47O B47T B47U B47K Check and, if required, replace EGR cooler (recheck)
Defect I 00 11 89 05 00

- 04/01/2021 Key 143471 Km 46477 Key 1



- 15/05/2020 Service 117391 Km 46477 Manual
Autohaus Wahl
Mittelhessen,
Marburg



- 15/05/2020 Repair 117397 Km 46477 Alfred Wahl GmbH & Co. KG, Marburg Job
Job
Job
Job

- Job

Description:

Considered as a repeat visit No

Customer's own words

Service - standard scope
Flat rate unit I 00 00 105

2 FRU

Engine oil service
Flat rate unit I 00 00 610

3 FRU

Original BMW Motorenöl LL04 0W-30
Part I FT97 99 0 000 0

Local

5

Set oil-filter element
Part I 11 42 8 575 211

1

— Job

Description:

Considered as a repeat visit No

Customer's own words

Microfilter service Flat rate unit I 00 00 616	2 FRU
---	-------

Microfilter/activated Carbon container Part I 64 11 9 237 555	1
--	---

— Job

Description:

Considered as a repeat visit No

Customer's own words

Service - air filter element Flat rate unit I 00 00 602	2 FRU
--	-------

Air filter element Part I 13 71 8 511 668	1
--	---

— Job

Description:

Considered as a repeat visit No

Customer's own words

Service fuel filter Flat rate unit I 00 00 604	3 FRU
---	-------

Fuel filter cartridge Part I 13 32 8 572 522	1
---	---

— Job

Description:

Considered as a repeat visit No

Customer's own words

Service, vehicle check Flat rate unit I 00 00 624	6 FRU
--	-------

— 14/05/2020 Key

117391 Km

46477

Key 1

 3100 08/2021	 3100 437	 3100 437	 3100 437	 5000	 02/2021	 41000	 3100 08/2021	 02/2021
--	--	--	--	---	--	--	---	--

— 14/05/2020 Service

117391 Km

46477
Autohaus Wahl
Mittelhessen
GmbH&Co.
KG, Marburg

Automatic

 3100	 3100	 3100	 3100	 5000	 02/2021	 41000	 3100 ✓	 02/2021
---	---	---	---	---	--	--	---	--

— 21/02/2020 Warranty 109190 Km 46477 Job: F1x F2x F3x F4x G0x G1x G3x B47 Check and if required replace exhaust-gas recirculation cooler

— Job: F1x F2x F3x F4x G0x G1x G3x B47 Check and if required replace exhaust-gas recirculation cooler

Description: F1x F2x F3x F4x G0x G1x G3x B47 Check and if required replace exhaust-gas recirculation cooler

Considered as a repeat visit No

Customer's own words

Check exhaust-gas recirculation cooler production date (then no further repairs necessary) 5 FRU
Flat rate unit I 00 68 163

F1x F2x F3x F4x G0x G1x G3x B47 Check and if required replace exhaust-gas recirculation cooler
Defect I 00 11 40 05 00

— 20/02/2020 Key 109190 Km 46477 Key 1

									
12000	12000	12000	12000	5000	50000	12000			
08/2021	521	521	521		02/2021		08/2021		03/2020

— 20/02/2020 Repair 109190 Km 46477 Alfred Wahl GmbH & Co. KG , Marburg Job
Job
Job

— Job

Description:

Considered as a repeat visit No

Customer's own words

Package I MM01002*BM8C61 Local
Kostenlose maschinelle Local 0
Flat rate unit I AZ00 00 2

— Job

Description:

Considered as a repeat visit No

Customer's own words

Check exhaust-gas recirculation cooler production date (then no further repairs necessary) 1 FRU
Flat rate unit I 00 68 736

— Job


Description:

Considered as a repeat visit No


Customer's own words

!!! unknown BMW-Id ESTIMATE 0173/5786452 !!! Local 0 FRU
Flat rate unit I -

— 08/08/2019 Key 90225 Km 46477 Key 1



— 08/08/2019 Service 90225 Km 46477 Automatic
Autohaus Wahl
Mittelhessen,
Marburg



— 08/08/2019 Repair 90229 Km 46477 Alfred Job
Wahl GmbH & Job
Co. KG , Job
Marburg Job

— Job

Description:

Considered as a repeat visit No

Customer's own words

Service - standard scope 2 FRU
Flat rate unit I 00 00 105

Engine oil service 3 FRU
Flat rate unit I 00 00 610

Original BMW Motorenöl LL04 0W-30 Local 5
Part I FT97 99 0 000 0

Set oil-filter element 1
Part I 11 42 8 575 211

— Job

Description:

Considered as a repeat visit No

Customer's own words

Microfilter service 2 FRU
Flat rate unit I 00 00 616

Microfilter/activated Carbon container 1
Part I 64 11 9 237 555

— Job

Description:

Considered as a repeat visit No

Customer's own words

Service, rear brakes 7 FRU
Flat rate unit I 00 00 614

A.Reiniger Local 1
Part I FT99 99 0 000 0

Repair kit, brake pads asbestos-free 1
Part I 34 21 6 873 093

Brake-pad sensor, rear
Part I 34 35 6 792 292

1

Brake-pad paste
Part I 83 19 2 158 851

2

— Job

Description:

Considered as a repeat visit No

Customer's own words

Removing and installing or replacing insulation sheet on engine hood
Flat rate unit I 51 48 501

2 FRU

Sound insulating engine hood
Part I 51 48 7 221 993

1

Clip
Part I 51 48 9 119 216






10

— 05/02/2019 Key

70498 Km

46477

Key 1







— 05/02/2019 Service

70498 Km

46477

Automatic

Autohaus Wahl
Mittelhessen
GmbH&Co.
KG, Marburg



— 05/02/2019 Repair

70498 Km

46477

Alfred
Wahl GmbH &
Co. KG ,
Marburg

Job

Job

— Job

Description:

Considered as a repeat visit No

Customer's own words

Service - standard scope
Flat rate unit I 00 00 105

2 FRU

— Job

Description:

Considered as a repeat visit No

Customer's own words

Brake fluid service
Flat rate unit I 00 00 618

4 FRU

Brake fluid DOT4 LV, low viscosity
Part I 83 13 2 184 843

1

— 05/02/2019 Warranty 70498 Km 46477 Job

— Job

Description:

Considered as a repeat visit No

Customer's own words

Check index exhaust-gas recirculation cooler (then continue check with exhaust-gas recirculation cooler) 1 FRU

Flat rate unit I 00 67 710

Visual inspection of EGR cooler output and input; replacing EGR cooler module; cleaning EGR tube/ pressure sensor function-testing 29 FRU

Flat rate unit I 00 67 711


Defect I 00 11 10 05 00

Exhaust gas radiator high temperature 1
Part I 11 71 8 513 691

EGR small parts set 1
Part I 11 71 8 490 222

Pipe union 2
Part I 11 71 7 799 853

— 01/02/2019 Key 70162 Km Key 1




— 20/10/2018 Key 59220 Km Key 1




— 20/10/2018 Service 59220 Km 33248 Automatic

Autohaus E.
Funke Inhaber
Ralf Funke e.K.,
Kirchhain



— 08/10/2018 Key 57770 Km Key 1



— 05/10/2018 Key 57477 Km Key 1

 1200 06/2019	 1200 268	 1200 268	 1200 268	 41000	 0 02/2019	 6000	 1200 06/2019	 0 03/2020
---	---	---	---	---	--	--	--	--

— 28/06/2018 Key 45640 Km 46477 Key 1

 13000 06/2019	 13000 367	 13000 367	 13000 367	 47000	 0 02/2019	 12000	 13000 06/2019	 0 03/2020
---	---	---	---	--	---	--	--	---

— 28/06/2018 Warranty 45657 Km 46477 Job: F1x F2x F3x B47 programming control units and if necessary, replacing the EGR valve

— Job: F1x F2x F3x B47 programming control units and if necessary, replacing the EGR valve

Description: F1x F2x F3x B47 programming control units and if necessary, replacing the EGR valve

Considered as a repeat visit No

Customer's own words

Carrying out the ABL and programming the control units
Flat rate unit I 00 64 941

8 FRU

F1x F2x F3x B47 programming control units and if necessary, replacing the EGR valve
Defect I 00 11 45 04 00

— 20/10/2017 Key 31421 Km 02735 Key 1

 27000 06/2019	 27000 617	 27000 617	 27000 617	 48000	 0 02/2019	 24000	 27000 06/2019	 0 03/2020
---	---	---	---	--	---	--	--	---

— 10/06/2017 Key 27659 Km 02735 Key 1

 1600 02/2018	 0	 1600 263	 0	 50000	 0 02/2019	 30000	 33000 02/2020	 0 03/2020
--	--	--	--	--	---	--	--	---

— 10/06/2017 Service 27659 Km 24141 Manual
Autohaus Otto
Bösner,
Marburg/Lahn

 ✓	 ✓	 ✓							
--	--	--	---	---	---	---	--	---	---

— 10/06/2017 Repair 27659 Km 02735 Job
Autohaus Otto
Bösner GmbH ,
Marburg/Lahn

— Job

Description:

Considered as a repeat visit No

Customer's own words

Service - standard scope 2 FRU
Flat rate unit I 00 00 105


Engine oil service 3 FRU
Flat rate unit I 00 00 610

Microfilter service 2 FRU
Flat rate unit I 00 00 616

MOTORÖL BMW LL04 0W-30 CASTROL EDGE Professional Local 5
Part I FT99 99 0 000 0

Set oil-filter element 1
Part I 11 42 8 575 211

Microfilter/activated Carbon container 1
Part I 64 11 9 237 555



01/06/2016 Repair 12690 Km 11450 GRAND SUD AUTO MARSEILLE (BMW), MARSEILLE Job

Job

Description: DEFAUT DE FREIN A MAIN, LE CLIENT ATTESTE QUE QUAND IL TIRE LE FREIN A MAIN RIEN NE SE PASSE

Considered as a repeat visit No

Customer's own words

Recherche générale de pannes Local 18 FRU
Flat rate unit I -

