

Vehicle

BMW 318d, 110kW

WBA8H71020A130338



Development code	F31
Color	black-sapphire metallic
Actual integration level	F020-22-03-552
Start of warranty	February 20, 2018

▼ Technical Campaigns

There are no campaigns available.

▼ Special information

There are no campaigns available.

▼ Live Diagnosis

⚠ An error has occurred. Please try again later.

▼ Service contracts

No BSI contracts available

You can find additional service contract information and selection options in the DCSNet warranty vehicle enquiry.

▼ Information on faults, workshop/Service Consultation

No information on faults is available.

▼ Navigation map

Installed map	Enabling code (subscription)	Latest navigation map included in subscription	Latest navigation map subject to charge
Road Map EUROPE Way 2017-3 (as of: Mar 25, 2024)	Release code valid for navigation maps with release date up to Dec 31, 2099 (SWID: 01309912).	Road Map EUROPE Way 2026-1	-

▼ Vehicle details

Vehicle type	Passenger car
--------------	---------------

Brand	BMW
Model	318d
Body	TOUR
Vehicle identification number (last 7 characters)	A130338
Vehicle identification number (17 characters)	WBA8H71020A130338
Development code	F31
Steering	LL
Engine	B47U
Engine number	52725240
Exhaust re-treatment	Euro 6 W
Transmission	AUT
Transmission number	1365819Z34
Head unit serial number	AL07FFH1274617
Drive	HECK
Integration level	F020-17-11-540
Production date	Jan 22, 2018
Production works	Muenchen
Delivery date	Jan 29, 2018
Delivering Retailers	Autohaus Rhein Bodensee Zw.-Nl. der, Friedrichshafen, DE
National-market version	EUR
Paint code	475
Upholstery code	HAAT
Model code	8H81
Base type	8H71
Lead type	8H81

▾ Optional equipment

Optional equipment fitted at the factory:

01CA Selection of COP relevant vehicles
 01CB CO2 package
 0205 Automatic transmission
 0216 Hydro steering-servotronic
 0230 EU-specific additional contents
 0258 Tire with run-flat functionality
 02PA Wheel bolt retainer
 02PE BMW LA wheel M Star Spoke 400
 02VB Tire pressure display
 0320 Deleted, model lettering
 0337 M Sports package

Retrofitted optional equipment:

This vehicle has no retrofits.

03AA Roof railing black
03DZ Delete extra external lettering
0423 Floor mats, velours
0428 Warning triangle and first aid kit
0430 Interior/outside mirror with auto dip
0431 Interior mirror with automatic-dip
0481 Sports seat
0488 Lumbar support, driver and passenger
0493 Storage compartment package
0494 Seat heating driver/passenger
04AE Armrest front, retractable
04WG Alu, hexagon, high-gloss black accent
0508 Park Distance Control (PDC)
0521 Rain sensor
0534 Automatic air conditioning
0544 Cruise control with brake function
0548 Kilometer-calibrated speedometer
0563 Light package
05A1 LED Fog lights
05A2 LED headlight
05AC High-beam assistant
05DA Passenger airbag deactivation
05DC Rear-seat headrests, folding
0606 Navigation system Business
0610 Head-up display
0650 CD player
0676 HiFi speaker system
0698 Area-Code 2 for DVD
06AC Intelligent emergency SOS call
06AE Teleservices
06AK Connected Drive Services
06AM Real-Time Traffic Information
06NS Convenience phone, expanded Smartphone
06WA Instrument cluster, expanded equipment
0704 M Sports suspension
0710 M leather steering wheel
0715 M Aerodynamics package
0760 High gloss shadow line
0775 Headlining anthracite
07LF Modell M Sport
0801 German version
0851 Language version German
0879 On-board vehicle literature German
08KA Oil service interval, 24 mos./30,000 km
08R9 Refrigerant R1234yf
08TH Road sign detection
09BD Business Package
A090 90 AH AGM battery
POLS Cloth cushion

► Software version control units

▼ Vehicle histories

Date		Type	Vehicle mileage		Dealer	Overview	
—	10/06/2025	Key	258963 km		09031	Key 0	
							
16000		16000		60000		80000	46000
04/2027		04/2027			12/2026		04/2029

—	10/06/2025	Repair	258963 km	04107 ,	Job Job Job Job
---	------------	--------	-----------	---------	--------------------------

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words: Handbremsbacken hinten rechts aus- und einbauen/ überprüft und gereinigt,O-Ton Kunde: Quietschgeräusch - bei Fahrt seit letzten Service,Ausführliche Begründung:,Nacharbeit zum letzten Service Auftrag
Geräusch nachvollziehbar nicht auf Kunden abrechenbar.,Zur Kenntnis genommen:,,,Mitarbeiter:_____,,Vorgesetzter:_____,,Aftersalesleiter:_____,

Removing and installing/replacing brake shoe expander for parking brake shoes at rear left or right Flat rate unit I 34 41 250	8 FRU
---	-------

Hex screw with collar Part I 34 20 6 850 536	2
---	---

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Ersatzfahrzeug Part I 0000158	Local	1
----------------------------------	-------	---

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Vehicle check in frame of acceptance Flat rate unit I 00 52 054	1 FRU
--	-------

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Dokumentationsaufwand SVC Flat rate unit I AZ00 15 2	Local	2 FRU
---	-------	-------

Endkontrolle Flat rate unit I AZ00 45 0	Local	1 FRU
--	-------	-------

—	09/25/2025	Key	258207 km	09031	Remote KeyRead
---	------------	-----	-----------	-------	----------------

							
17000		17000		60000		80000	48000
04/2027		04/2027			12/2026		04/2029

— 09/19/2025 Key 258134 km 09031 Key 0

							
17000		17000		60000		80000	48000
04/2027		04/2027			12/2026		04/2029

— 09/19/2025 Repair 258134 km 04107 , Job
Job
Job
Job

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Vehicle check in frame of acceptance
Flat rate unit I 00 52 054

1 FRU

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words: *E O-Ton: Bremse vorn und hinten wurde beim letzten Termin im August erneuert. Nun ist ein Geräusch vorhanden. Herr Gislo hat das Geräusch gehört. Bitte hierzu RS,*Info Werkstatt:
Nach telefonisch Rücksprache mit dem Kunden kommt das Geräusch (hoch) etwa zwischen 45 - 70 km/h hinten rechts auch gut hörbar ist es bei 75 km/h Tempomat. Man hört es vor allem gut wenn man neben einer "Wand" fährt da der Ton nochmal mehr reflektiert wird., ## Bitte Probefahrt durchführen ##,O-Ton
Mechaniker: Bei Probefahrt konnten Störgeräusche vom HA-Diff., festgestellt werden -> nach RS mit SB ist dies bekannt
Beanstandung, soll von der Bremse kommen! Feststellbremse neu eingestellt bei Probefahrt nach Rep. konnte derzeit kein Störgeräusch von der Bremse festgestellt werden. Bitte vom Kunden neu bewerten lassen.
sen., Ausführliche Begründung: Handbremse hat die Geräusche verursacht diese wurde bei dem letzten Werkstattbesuch Auftrag 21622906 nicht richtig eingestellt. Daswegen wird es auf IBT übernommen, Zur Kenntnis
genommen, Mitarbeiter: _____, Vorgesetzter: _____, Aftersalesleiter: _____

Adjusting parking brake
Flat rate unit I 34 10 014

5 FRU

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Endkontrolle
Flat rate unit I AZ00 45 0
Local 1 FRU

— 09/09/2025 Key 257887 km 09031 Remote KeyRead



— 08/18/2025 Repair 255295 km 04107 , Job

— Job


Description:

Is interpreted as a repeat visit: No


Customer's own words:

Ersatzfahrzeug (24 Stunden) M-VB 2070 3e
Part I 0000160
Local 1

— 08/08/2025 Key 255295 km 09031 Key 0



— 08/08/2025 Service 255295 km 09031 Automatic
Niederlassung
München
Airportservice ,
München-
Flughafen



— 08/08/2025 Repair 255295 km 04107 , Job
Job
Job
Job
Job
Job
Job
Job

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Vehicle check in frame of acceptance	1 FRU
Flat rate unit I 00 52 054	

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Standard scope of service	2 FRU
Flat rate unit I 00 00 105	

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Service - front brakes	6 FRU
Flat rate unit I 00 00 612	
Brake pad wear sensor, front left	1
Part I 34 35 6 792 289	
Repair kit, brake pads	1
Part I 34 11 8 855 002	
Clip	2
Part I 34 11 6 850 645	

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Rear brakes service	7 FRU
Flat rate unit I 00 00 614	
Brake pad wear sensor, rear	1
Part I 34 35 6 792 292	
Repair kit brake pads asbestos-free	1
Part I 34 21 8 855 013	
Clip	2
Part I 34 21 6 850 853	

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Removing and installing/replacing both front brake discs Flat rate unit I 34 11 613	3 FRU
Brake disc, ventilated Part I 34 11 6 792 217	2
Torx screw with washer Part I 34 10 6 864 424	4
Inner hex bolt Part I 34 21 1 161 806	2

— Job**Description:****Is interpreted as a repeat visit:** No

Customer's own words: Handbremsbacken angeschliffen,Nicht sehr viel Restbelagstärke vorhanden,Bei der Probefahrt am Berg wurde festgestellt dass die Handbremse erst,beim äußersten Anschlag fest wird (Fahrzeug mit Front ber gab),Auch nach erneuten und festeren Einstellen der Handbremse konnte das,Problem nicht behoben werden. Hanbremse muss bis Anschlag gezogen werden,An Kunden weitergeben!!,

Removing and installing/renewing both brake discs Flat rate unit I 34 21 932	4 FRU
Hex screw with collar Part I 34 20 6 850 536	4
Inner hex bolt Part I 34 21 1 161 806	2
Brake disc, ventilated Part I 34 21 6 864 900	2

— Job**Description:****Is interpreted as a repeat visit:** No**Customer's own words:**

Endkontrolle Flat rate unit I AZ00 45 0	Local	1 FRU
--	-------	-------

— Job**Description:****Is interpreted as a repeat visit:** No**Customer's own words:**

kostenfreie Wäsche Part I 0011319	Local	1
--------------------------------------	-------	---

— Job**Description:****Is interpreted as a repeat visit:** No**Customer's own words:**

Ersatzfahrzeug (24 Stunden) M-VB 2070 3e	Local	1
--	-------	---

—	08/07/2025	Key	255008 km	09031	Remote KeyRead
---	------------	-----	-----------	-------	----------------

 20000 04/2027	 20000 04/2027	 20000 04/2027	 2600 12/2026	 9000 04/2029	 50000 04/2029
---	---	---	--	--	---

—	04/16/2025	Key	244849 km	09031	Key 0
---	------------	-----	-----------	-------	-------

 120 03/2026	 120 03/2026	 120 03/2026	 120 03/2026	 26000 12/2026	 21000 03/2026
---	---	---	---	---	---

—	04/16/2025	Service	244849 km	09031 Niederlassung München Airportservice , München- Flughafen	Automatic
---	------------	---------	-----------	--	-----------

 120 03/2026 ✓	 120 03/2026 ✓	 120 03/2026 ✓	 120 03/2026 ✓	 26000 12/2026	 21000 03/2026 ✓
--	--	--	--	---	--

—	04/16/2025	Repair	244849 km	04107 ,	Job Job Job Job Job Job Job Job Job Job
---	------------	--------	-----------	---------	--

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Vehicle check in frame of acceptance
Flat rate unit I 00 52 054

1 FRU

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Standard scope of service
Flat rate unit I 00 00 105

2 FRU

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Engine oil service Flat rate unit I 00 00 610	3 FRU
--	-------

Set oil-filter element Part I 11 42 8 575 211	1
--	---

BMW Engine Oil LL04 0W30 Part I 83 21 2 405 950	5
--	---

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Fuel filter service Flat rate unit I 00 00 604	3 FRU
---	-------

Fuel filter cartridge Part I 13 32 7 822 497	1
---	---

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Service - air filter insert Flat rate unit I 00 00 602	2 FRU
---	-------

Air filter element Part I 13 71 8 511 668	1
--	---

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Service - microfilter Flat rate unit I 00 00 616	2 FRU
---	-------

Microfilter/activated Carbon container Part I 64 11 9 237 555	1
--	---

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Vehicle check service Flat rate unit I 00 00 624	6 FRU
---	-------

Adjusting headlights
Flat rate unit I 63 10 502 2 FRU

Adjusting front fog light
Flat rate unit I 63 10 515 1 FRU

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Motorölservice - zusätzliche AW Local 2 FRU
Flat rate unit I IM00 25 0

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words: INFO: Handschuhfach abgesperrt und kein Einschubschlüssel vorhanden ->,Handschuhfach konnte nicht kontrolliert werden,

Endkontrolle Local 1 FRU
Flat rate unit I AZ00 45 0

— Job


Description:

Is interpreted as a repeat visit: No


Customer's own words:

Ersatzfahrzeug Local 1
Part I 0000158

— 04/07/2025 Key 244147 km 09031 Remote KeyRead



— 12/20/2024 Key 235531 km 09031 Key 0



— 12/20/2024 Service 235531 km 09031 Automatic
Niederlassung
München
Airportservice ,
München-
Flughafen

							
10000	10000	10000	10000	39000	12/2024	34000	10000
03/2026	03/2026	03/2026	03/2026		✓		03/2026

—	12/20/2024	Repair	235531 km	04107 ,	Job
					Job
					Job
					Job
					Job

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words: Befund: Regelstangen Höhenstandssensor vorne und hinten fest Bilder in,Fleetback,

Standard scope of service	2 FRU
Flat rate unit I 00 00 105	

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Brake fluid service	4 FRU
Flat rate unit I 00 00 618	

Brake fluid DOT4 LV, low viscosity	1
Part I 83 13 0 443 030	

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Endkontrolle	Local	1 FRU
Flat rate unit I AZ00 45 0		

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Fahrzeugüberprüfung im Rahmen derAnnahme	Local	1 FRU
Flat rate unit I 00 52 054		

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Dokumentationsaufwand SVC	Local	2 FRU
---------------------------	-------	-------

—	12/05/2024	Key	233504 km	09031	Remote KeyRead		
							
12000	12000	12000	12000	39000	-4 0.5 %	35000	12000
03/2026	03/2026	03/2026	03/2026				03/2026
—	08/12/2024	Key	224295 km	04107	Key 0		
							
21000	21000	21000	21000	49000		45000	21000
03/2026	03/2026	03/2026	03/2026		12/2024		03/2026
—	08/12/2024	Repair	224295 km	04107 ,	Job Job Job		

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Ausgleich AW Haupt- und Verbundarbeit (M Flat rate unit AZ00 05 0	Local	2 FRU
--	-------	-------

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Fahrzeugüberprüfung im Rahmen derAnnahme Flat rate unit 00 52 054	Local	1 FRU
--	-------	-------

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words: Arbeitszeit ohne Vorgabe/Vorderachse,O-Ton: Wummern beim fahren Kunde ist mit Herr Müller -1188 im Kontakt und besprechen das Vorgehen am FZG.,Befund: Probefahrt durch den WM Herr Müller Rüdiger anm 1 2.08.2024 und,dem Kunden (Herr Toth) zur Kundenbeanstandung durchgeführt. Mit den,Meisterrädern sind keine abnormalen Geräusche feststellbar. Geräusche,werden von den Reifen verursacht diese haben Höh einschlag. Nach RS mit,Herr Toth bitte keine weiteren Reparaturen durchführen -> Fahrzeug wird,gegen 16:00 Uhr von Herr Toth abgeholt., Video in Fleet-Back hinterlegt !!!,

Removing and installing front and rear wheels Flat rate unit 36 10 820		4 FRU
---	--	-------

Radlager vorn und hinten prüfen Flat rate unit AZ31 99 0	Local	2 FRU
---	-------	-------

Luftdruck korrigieren und RDC/RPA initia	Local	1 FRU
--	-------	-------

Removing and installing front and rear wheels

Flat rate unit | 36 10 820

4 FRU

—	03/25/2024	Key	214001 km	04107	Key 0			
								
800		800		60000		60000	32000	
03/2025		03/2025			12/2024		03/2027	

—	03/25/2024	Key	214000 km	04107	Key 0			
								
800		800		60000		60000	32000	
03/2025		03/2025			12/2024		03/2027	

—	03/25/2024	Service	214001 km	04107 Niederlassung München , München	Automatic			
								
800	0	800	0	60000	0	60000	32000	
✓		✓						

—	03/25/2024	Repair	214001 km	04107 Niederlassung München BMW AG, München	Job Job Job Job Job Job
---	------------	--------	-----------	---	--

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Motorölservice - zusätzliche AW

Flat rate unit | IM00 25 0

Local

2 FRU

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words: Bei Rückfragen Frau Hartmann -1838,Rechnung per Mail,

Service consultation at the vehicle

Flat rate unit | 00 52 050

1 FRU

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Standard scope of service	2 FRU
Flat rate unit I 00 00 105	

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Engine oil service	3 FRU
Flat rate unit I 00 00 610	

Set oil-filter element	1
Part I 11 42 8 575 211	

BMW Engine Oil LL04 0W30	5
Part I 83 21 2 405 950	

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Service - microfilter	2 FRU
Flat rate unit I 00 00 616	

Microfilter/activated Carbon container	1
Part I 64 11 9 237 555	

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Fahrzeug-Außen-Wäsche (kostenlos)	Local	1
Part I 0011319		

10/13/2023	Key	203757 km	04107	Key 0
------------	-----	-----------	-------	-------



11000
03/2025





11000
03/2025





80000



12/2024



70000



42000
03/2027

10/13/2023	Repair	203757 km	04107 Niederlassung München BMW AG, München	Job Job
------------	--------	-----------	---	------------

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words: Serienstandsverbesserung: 10011130700 (SK) durchführen: F1x F2x F3x G0x G1x G3x B47O B47K B47U B47T AGR-Kühler (Hochtemperatur) ersetzen,

Replace exhaust-gas recirculation cooler, including exhaust-gas recirculation valve
Flat rate unit I 00 74 057 25 FRU

Performing additional work for pressure sensor functional check
Flat rate unit I 00 74 636 3 FRU

Additional work: enter component identification of new exhaust-gas recirculation cooler in diagnostic system
Flat rate unit I 00 74 637 1 FRU

Additional work: clean EGR pipe
Flat rate unit I 00 74 638 2 FRU

Exhaust gas cooler high temperature
Part I 11 71 7 822 347 1

AGR small parts set
Part I 11 71 8 490 640 1

Vacuum hose black
Part I 11 65 8 595 650 1

Pipe union
Part I 11 71 7 799 853 2

Holder
Part I 61 13 1 369 832 1

Connection piece
Part I 11 65 7 803 012 1

O-ring
Part I 11 61 8 512 681 1

Acoustic cover front
Part I 11 14 8 490 577 1

Anti-freeze
Part I 83 19 2 218 347 3

Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Fahrzeug-Außen-Wäsche (kostenlos) Local 1
Part I 0011319

03/27/2023 Key 183796 km Key 0


600
10/2023


600
10/2023


600
10/2023


600
10/2023


60000
12/2024


2500
10/2023


600
10/2023

03/27/2023 Service 183796 km 04107 Niederlassung München , München Manual



—	03/27/2023	Repair	183796 km	04107	Job
				Niederlassung	Job
				München	Job
				BMW AG,	Job
				München	Job
					Job
					Job
					Job
					Job
					Job
					Job

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words: Serviceberater Knaus -1821,Barzahlung nicht möglich!,

Motorölservice - zusätzliche AW	Local	2 FRU
Flat rate unit I IM00 25 0		

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Service consultation at the vehicle	0 FRU
Flat rate unit I 00 52 050	

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Standard scope of service	2 FRU
Flat rate unit I 00 00 105	

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Engine oil service	3 FRU
Flat rate unit I 00 00 610	
Set oil-filter element	1
Part I 11 42 8 575 211	
BMW Engine Oil LL04 0W30	5

— Job

Description:**Is interpreted as a repeat visit:** No**Customer's own words:**

Fuel filter service	3 FRU
Flat rate unit I 00 00 604	

Fuel filter cartridge	1
Part I 13 32 7 822 497	

— Job

Description:**Is interpreted as a repeat visit:** No**Customer's own words:**

Service - air filter insert	2 FRU
Flat rate unit I 00 00 602	

Air filter element	1
Part I 13 71 8 511 668	

— Job

Description:**Is interpreted as a repeat visit:** No**Customer's own words:**

Service - microfilter	2 FRU
Flat rate unit I 00 00 616	

Microfilter/activated Carbon container	1
Part I 64 11 9 237 555	

— Job

Description:**Is interpreted as a repeat visit:** No

Customer's own words: Befund:,-Oberflächliche Steinschläge in der Frontscheibe,-Wischer schmieren leicht,-Scheinwerfer und Nebelscheinwerfer verstellt -> eingestellt,-Delle im Kotflügel HR,-Kratzer Kotflügel VR,-Zusatzdämpfer hinten rissig,-Luftdruck minimal verstellt -> korrigiert,,-> Nach RS mit SB keine weitere Rep.,

Vehicle check service	6 FRU
Flat rate unit I 00 00 624	

— Job

Description:**Is interpreted as a repeat visit:** No**Customer's own words:**

Service - front brakes	6 FRU
Flat rate unit I 00 00 612	

Removing and installing/replacing both front brake discs Flat rate unit I 34 11 613	3 FRU
Rear brakes service Flat rate unit I 00 00 614	7 FRU
Removing and installing/renewing both brake discs Flat rate unit I 34 21 932	4 FRU
Removing and installing / replacing all parking brake shoes Flat rate unit I 34 41 660	4 FRU
Repair kit, brake pads asbestos-free Part I 34 11 6 874 331	1
Brake pad wear sensor, front left Part I 34 35 6 792 289	1
Torx screw with washer Part I 34 10 6 864 424	4
Brake disc, ventilated Part I 34 11 6 792 217	2
Inner hex bolt Part I 34 21 1 161 806	2
Repair kit, brake pads asbestos-free Part I 34 21 6 873 093	1
Brake pad wear sensor, rear Part I 34 35 6 792 292	1
Inner hex bolt Part I 34 21 1 161 806	2
Hex screw with collar Part I 34 20 6 850 536	4
Brake disc, ventilated Part I 34 21 6 864 900	2
Repair kit, brake shoe, complete Part I 34 21 2 213 311	1

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words: InfoCC: Kühlmittelstand bei jedem Werkstattaufenthalt prüfen,Keine CC Meldung im Fahrzeug hinterlegt.,Kühlmittelstand i.O.,Kein Kühlmittel in geraumer Zeit nachgefüllt.,i.O.,

Read out coolant Check Control message (OK) Flat rate unit I 00 73 827	4 FRU
---	-------

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Fahrzeug-Außen-Wäsche (kostenlos)
Part I 0011319

Local 1

—	02/16/2023	Key	181244 km			Remote KeyRead	
							
3100	3100	3100	3100	60000		4100	3100
10/2023	10/2023	10/2023	10/2023		12/2024		10/2023
—	12/07/2022	Key	175995 km			Key 0	
							
9000	9000	9000	9000	70000		17000	9000
10/2023	10/2023	10/2023	10/2023		01/2023		10/2023
—	12/07/2022	Service	175995 km			04107 Niederlassung München , München	Automatic
							
9000	9000	9000	9000	70000	0	17000	9000
					✓		
—	12/07/2022	Repair	175995 km			04107 Niederlassung München BMW AG, München	Job Job Job Job Job Job Job Job

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Endkontrolle
Flat rate unit I AZ00 45 0

Local 1 FRU

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Laub entfernen (Motorraum)
Flat rate unit I AZ00 65 0

Local 1 FRU

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

AIR Plausibilitätsprüfung Flat rate unit I AZ00 04 9	Local	2 FRU
---	-------	-------

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words: bei Rückfragen 1823,

Service consultation at the vehicle Flat rate unit I 00 52 050		1 FRU
---	--	-------

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Standard scope of service Flat rate unit I 00 00 105		2 FRU
---	--	-------

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Brake fluid service Flat rate unit I 00 00 618		4 FRU
---	--	-------

Brake fluid DOT4 LV, low viscosity Part I 83 13 0 443 030		1
--	--	---

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words: *E die Heckscheibenheizung geht nicht - KD vermutet Zusammenhang REP 17775159 Massekabels er#s. Bitte prüfen und nach RS SB inst - I,NFO FZG hat EUROPLUS,-FS ausgelesen,-Leitungen von REM zum Sperrkre is auf Durchgang und Kurzschluss gep.,i.o.,-Durchgangsmessung an der Heckscheibe durchgeführt->n.i.o.->6MOhm,->>Heckscheibe muss erneuert werden,Freigabenr. 52170924 100% L/M Real Garant,,Rechnung an: Rhein Bodensee ZW NL AH Heermann Rhein GmbH,Otto-Lilienthalstr. 25 88046 Friedrichshafen.,

Performing vehicle test Flat rate unit I 00 00 556		2 FRU
---	--	-------

Supporting the voltage of the vehicle electrical system/recharging the vehicle electrical system battery Flat rate unit I 61 21 528		1 FRU
--	--	-------

Replacing rear window

Flat rate unit I 51 31 731

13 FRU

Removing and installing control unit for rear electronics module (REM)

Flat rate unit I 61 35 775

3 FRU

Removing and installing or replacing wave trap, left

Flat rate unit I 65 24 540

2 FRU

Rear window

Part I 51 31 7 263 163

1

Repair flat rate, window, cold, 1 hr.

Part I 83 19 2 289 285

1

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Füllstände prüfen und nicht ergänzen

Local

1 FRU

Flat rate unit I AZ00 33 4

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Fahrzeug-Außen-Wäsche (kostenlos)

Local

1

Part I 0011319

07/20/2022

Key

162339 km

Key 0

										
23000	23000	23000	23000	23000	70000	30000	23000	23000	23000	23000
10/2023	431	431	431	431	01/2023		10/2023			

07/20/2022

Key

162339 km

Key 0

										
23000	23000	23000	23000	23000	70000	30000	23000	23000	23000	23000
10/2023	431	431	431	431	01/2023		10/2023			

07/20/2022

Repair

162339 km

04107

Job

Niederlassung

Job

München

Job

BMW AG,

Job

München

Job

Job

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Service consultation at the vehicle	1 FRU
Flat rate unit I 00 52 050	

— Job**Description:****Is interpreted as a repeat visit:** No**Customer's own words:**

Program control units	9 FRU
Flat rate unit I 00 71 349	

Resume vehicle test and clear fault memory	2 FRU
Flat rate unit I 61 00 980	

Initializing automatic tailgate operation	1 FRU
Flat rate unit I 61 00 986	

— Job**Description:****Is interpreted as a repeat visit:** No**Customer's own words:**

Implement fault memory and pressure sensor functional check (in conjunction with one of the traffic reports mentioned above (program control units)	1 FRU
Flat rate unit I 00 72 677	

— Job**Description:****Is interpreted as a repeat visit:** No

Customer's own words: O-Ton Kunde: Masseband hi li an Scharnier Heckklappe gebrochen bitte instandsetzen
Abwicklung über EuroPlus oder verk. Händler. Bi,tte RS Kiel -1596 wegen Arbeitsumfang Kd
wünscht nicht Heckspoiler a+
e,Masseband ersetzen (Spoiler abgebaut),

Masseband ersetzen (Spoiler abgebaut)	Local	1 FRU
Flat rate unit I AZ61 99 0		

Removing and installing rear spoiler	4 FRU	
Flat rate unit I 51 71 910		

Earth strap, trunk lid, left	1
Part I 61 12 9 247 542	

Hex bolt	2
Part I 61 13 9 115 568	

— Job**Description:****Is interpreted as a repeat visit:** No**Customer's own words:** Kostenzusage brutto in Euro aktuell ca. 50. Bezahlung bei Abholung,

Füllstände prüfen und nicht ergänzen	Local	1 FRU
Flat rate unit I AZ00 33 4		

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Servicewäsche (kostenlos)
Part I 0011319

Local








1

— 05/02/2022 Key

153937 km

04107

Key 0



— 04/20/2022 Repair

153420 km

35694
Autohaus
Rhein
Bodensee Zw.-
Nl. der AH
Heermann u.
Rhein GmbH,
Friedrichshafen

Job
Job
Job
Job

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Statutory emission test
Flat rate unit I 00 00 440

8 FRU

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Premium-Selection-Check (Eingang + Ausgang)
Flat rate unit I -

Local

12 FRU

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Work time without specification/body equipment
Flat rate unit I 51 99 000

0 FRU





















— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Hauptuntersuchung §29 - Agenturware - 00000000	Local	1 FRU
Flat rate unit I 99 99 999		
SCHEIBENKLAR	Local	3
Part I FT99 99 1 111 1		
Battery		2
Part I 61 31 9 217 643		

—	04/14/2022	Key	153420 km	35694	Key 0		
							
30000	30000	30000	30000	70000		32000	30000
10/2023	535	535	535		01/2023		10/2023
—	10/14/2021	Key	153382 km		Key 0		
							
-50		-50		70000		32000	31000
08/2022		287			01/2023		1007
—	10/14/2021	Service	153382 km	35694	Automatic		
					Autohaus Rhein Bodensee Zw.- Nl. der AH Heermann u. Rhein GmbH , Friedrichshafen		
							
-50	0	-50	0	70000	0	32000	31000
✓		✓					
—	10/14/2021	Repair	153383 km	35694	Job		
					Autohaus Rhein Bodensee Zw.- Nl. der AH Heermann u. Rhein GmbH , Friedrichshafen		
					Job Job Job		

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Standard scope of service	2 FRU
---------------------------	-------

Flat rate unit I 00 00 105

SCHEIBENKLAR
Part I FT99 99 1 111 1

Local 1.5

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Engine oil service 3 FRU
Flat rate unit I 00 00 610

Shell Helix Ultra ECT SAE 0W-30 BMW Longlife 04 Local 5
Part I FT9030

Set oil-filter element 1
Part I 11 42 8 575 211

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Service - microfilter 2 FRU
Flat rate unit I 00 00 616

Microfilter/activated Carbon container 1
Part I 64 11 9 237 555

— 03/11/2021 Key 142276 km Key 0

							
11000	0	11000	0	900	0	37000	40000
08/2022		538			01/2023		1269

— 03/11/2021 Service 142276 km 00242 B&K GmbH & Co. KG, Detmold Automatic

							
11000		11000		900	01/2023	37000	40000
				✓			

— 01/21/2021 Key 139694 km Key 0

							
14000	0	14000	0	2800	0	40000	45000
08/2022		586			01/2021		1317

— 01/21/2021 Service 139694 km 35694 Autohaus Rhein Automatic

Bodensee Zw.-
Nl. der AH
Heermann u.
Rhein GmbH ,
Friedrichshafen

							
14000	0	14000	0	2800	0	40000	45000
08/2022		08/2022			01/2021		08/2024
					✓		

—	01/21/2021	Repair	139694 km	35694	Job
				Autohaus	Job: Standard scope of service
				Rhein	Job: Brake fluid service
				Bodensee Zw.-	Job
				Nl. der AH	
				Heermann u.	
				Rhein GmbH ,	
				Friedrichshafen	

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Package I MM011*BM8H81

Local

— Job: Standard scope of service

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Standard scope of service

Package I 0000105

Standard scope of service

Flat rate unit I 00 00 105

2

— Job: Brake fluid service

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Brake fluid service

Package I 0000618

Brake fluid service

Flat rate unit I 00 00 618

4

!!! unknown BMW-Id FT99990000011 Bremsflüssigkeit

DOT4Bremsflüssigkeit DOT4 !!!

Part I FT99990000011

Local

1

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

!!! unknown BMW-Id ESTIMATE !!! Flat rate unit I -	Local	0 FRU
---	-------	-------

!!! unknown BMW-Id ESTIMATE !!! Flat rate unit I -	Local	0 FRU
---	-------	-------

—	01/21/2021	Repair	139695 km	35694 Autohaus Rhein Bodensee Zw.- Nl. der AH Heermann u. Rhein GmbH , Friedrichshafen	Job Job
---	------------	--------	-----------	---	------------

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Standard scope of service Flat rate unit I 00 00 105	2 FRU
---	-------

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Brake fluid service Flat rate unit I 00 00 618	4 FRU
---	-------

Bremsflüssigkeit DOT4 Part I FT99 99 0 000 0	Local	1
---	-------	---

—	10/23/2020	Key	131801 km	35694	Key 0
---	------------	-----	-----------	-------	-------

 22000 08/2022	 0	 22000 677	 0	 17000	 0 01/2021	 45000	 60000 1408
---	--	---	--	--	---	--	---

—	10/23/2020	Repair	131801 km	35694 Autohaus Rhein Bodensee Zw.- Nl. der AH Heermann u. Rhein GmbH , Friedrichshafen	Job Job
---	------------	--------	-----------	---	------------

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Komplettträder montieren
Flat rate unit I -

Local

6 FRU

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Räderkomplettpaket 00000000
Flat rate unit I 99 99 999

Local

1 FRU

— 10/12/2020 Key 130909 km 35694 Key 0

23000	0	23000	0	18000	0	45000	60000
08/2022		688			01/2021		1419

— 08/17/2020 Key 122478 km 35694 Key 0

600	600	600	600	25000	0	50000	600
12/2021	501	501	501		01/2021		12/2021

— 08/17/2020 Service 122478 km 35694 Automatic

Autohaus
Rhein
Bodensee Zw.-
Nl. der AH
Heermann u.
Rhein GmbH ,
Friedrichshafen

600	600	600	600	25000	0	50000	600
12/2021	12/2021	12/2021	12/2021		01/2021		12/2021
✓	✓	✓	✓				✓

— 08/17/2020 Repair 122482 km 35694 Job

Autohaus
Rhein
Bodensee Zw.-
Nl. der AH
Heermann u.
Rhein GmbH ,
Friedrichshafen

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

UVV Prüfung laut § 57 Abs. 1 BGV D29

Local

2 FRU

—	08/17/2020	Repair	122482 km	35694	Job
				Autohaus	Job
				Rhein	Job
				Bodensee Zw.-	Job
				Nl. der AH	Job
				Heermann u.	Job
				Rhein GmbH,	
				Friedrichshafen	

— Job

Description:**Is interpreted as a repeat visit:** No**Customer's own words:**

Standard scope of service	2 FRU
Flat rate unit I 00 00 105	

SCHEIBENKLAR	Local	1.5
Part I FT99 99 1 111 1		

— Job

Description:**Is interpreted as a repeat visit:** No**Customer's own words:**

Engine oil service	3 FRU
Flat rate unit I 00 00 610	

Shell Helix Ultra ECT SAE 0W-30 BMW Longlife 04	Local	5
Part I FT9030		

Set oil-filter element	1
Part I 11 42 8 575 211	

— Job

Description:**Is interpreted as a repeat visit:** No**Customer's own words:**

Service - microfilter	2 FRU
Flat rate unit I 00 00 616	

Microfilter/activated Carbon container	1
Part I 64 11 9 237 555	

— Job

Description:**Is interpreted as a repeat visit:** No**Customer's own words:**

Vehicle check service	6 FRU
Flat rate unit I 00 00 624	

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Service - air filter insert 2 FRU
Flat rate unit I 00 00 602

Air filter element 1
Part I 13 71 8 511 668

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Fuel filter service 3 FRU
Flat rate unit I 00 00 604

Fuel filter cartridge 1
Part I 13 32 8 572 522

— 03/26/2020 Key 110281 km 35694 Key 0

							
13000	13000	13000	13000	41000	0	1500	13000
12/2021	645	645	645		01/2021		12/2021

— 03/26/2020 Service 110281 km 35694 Automatic

Autohaus
Rhein
Bodensee Zw.-
Nl. der AH
Heermann u.
Rhein GmbH ,
Friedrichshafen

							
13000	13000	13000	13000	41000	0	1500	13000
12/2021	12/2021	12/2021	12/2021		01/2021		12/2021

— 03/26/2020 Repair 110290 km 35694 Job

Autohaus
Rhein
Bodensee Zw.-
Nl. der AH
Heermann u.
Rhein GmbH ,
Friedrichshafen

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Sommerräder montieren
Flat rate unit I -

Local

6 FRU

— Job**Description:**

Is interpreted as a repeat visit: No

Customer's own words:

Outside car wash and interior vehicle cleaning
Flat rate unit I 00 11 329

0 FRU

— Job**Description:**

Is interpreted as a repeat visit: No

Customer's own words:

Einlagerung + Reinigung Räder (ext.Dienstleister) 00000000
Flat rate unit I 99 99 999

Local

1 FRU

—	03/26/2020	Repair	110290 km	35694 Autohaus Rhein Bodensee Zw.- Nl. der AH Heermann u. Rhein GmbH , Friedrichshafen	Job Job
---	------------	--------	-----------	---	------------

— Job**Description:**

Is interpreted as a repeat visit: No

Customer's own words:

Standard scope of service
Flat rate unit I 00 00 105

2 FRU

— Job**Description:**

Is interpreted as a repeat visit: No

Customer's own words:

Rear brakes service
Flat rate unit I 00 00 614

7 FRU

Repair kit, brake pads asbestos-free
Part I 34 21 6 873 093

1

Brake pad wear sensor, rear
Part I 34 35 6 792 292

1

—	12/12/2019	Key	94275 km	35694	Key 0
---	------------	-----	----------	-------	-------

							
800	0	800	0	60000	0	30000	31000
04/2021		505			01/2021		04/2023

—	12/12/2019	Service	94275 km	35694	Automatic
				Autohaus	
				Rhein	
				Bodensee Zw.-	
				Nl. der AH	
				Heermann u.	
				Rhein GmbH ,	
				Friedrichshafen	

							
800	0	800	0	60000	0	30000	31000
04/2021		04/2021			01/2021		04/2023
✓		✓					

—	12/12/2019	Repair	94275 km	35694	Job: Standard scope of service
				Autohaus	Job: Engine oil service
				Rhein	Job: Service - microfilter
				Bodensee Zw.-	Job
				Nl. der AH	
				Heermann u.	
				Rhein GmbH ,	
				Friedrichshafen	

— Job: Standard scope of service

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Standard scope of service
Package I 0000105

Standard scope of service
Flat rate unit I 00 00 105

2

— Job: Engine oil service

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Engine oil service
Package I 0000610

Engine oil service
Flat rate unit I 00 00 610

3

!!! unknown BMW-Id FT9030 Shell Helix Ultra ECTShell Helix Ultra Local
ECT !!!
Part I FT9030

5

Set oil-filter element
Part I 11428575211

1

— Job: Service - microfilter

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Service - microfilter

Package I 0000616

Service - microfilter 2
Flat rate unit I 00 00 616

Microfilter/activated Carbon container 1
Part I 64119237555

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

!!! unknown BMW-Id ESTIMATE !!! Local 0 FRU
Flat rate unit I -

!!! unknown BMW-Id ESTIMATE !!! Local 0 FRU
Flat rate unit I -

— 11/12/2019 Key 90486 km 35694 Key 0

							
4600	0	4600	0	70000	0	34000	36000
04/2021		535			01/2021		04/2023

— 08/16/2019 Key 77958 km 35694 Key 0

							
17000	0	17000	0	700	0	42000	48000
04/2021		623			01/2021		04/2023

— 08/16/2019 Service 77958 km 35694 Automatic

Autohaus
Rhein
Bodensee Zw.-
Nl. der AH
Heermann u.
Rhein GmbH ,
Friedrichshafen

							
17000	0	17000	0	700	0	42000	48000
04/2021		04/2021		✓	01/2021		04/2023

— 08/16/2019 Repair 77958 km 35694 Job: Standard scope of service
Autohaus Job: Service - front brakes
Rhein Job

Bodensee Zw.-
Nl. der AH
Heermann u.
Rhein GmbH ,
Friedrichshafen

— Job: Standard scope of service

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Standard scope of service
Package I 0000105

Standard scope of service	2
Flat rate unit I 00 00 105	

— Job: Service - front brakes

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Service - front brakes
Package I 0000612

Service - front brakes	6
Flat rate unit I 00 00 612	

Repair kit, brake pads asbestos-free	1
Part I 34116874331	

Brake pad wear sensor, front left	1
Part I 34356792289	

Brake pad paste	2
Part I 83192158851	

Brake cleaner, acetone-free	1
Part I 83192413695	

— Job

Description:








Is interpreted as a repeat visit: No

Customer's own words:

!!! unknown BMW-Id ESTIMATE !!!	Local	0 FRU
Flat rate unit I -		

!!! unknown BMW-Id ESTIMATE !!!	Local	0 FRU
Flat rate unit I -		

— 07/08/2019 Key 72726 km 35694 Key 0



—	05/20/2019	Key	67091 km	35694	Key 0		
							
28000	0	28000	0	5000	0	50000	60000
04/2021		711			01/2021		04/2023
—	05/06/2019	Key	65545 km	35694	Key 0		
							
29000	0	29000	0	5000	0	60000	60000
04/2021		725			01/2021		04/2023
—	04/26/2019	Key	64050 km	35694	Key 0		
							
210	210	210	210	5000	0	60000	210
10/2020	554	554	554		01/2021		10/2020
—	04/26/2019	Service	64050 km	35694	Automatic		
					Autohaus Rhein Bodensee Zw.- Nl. der AH Heermann u. Rhein GmbH , Friedrichshafen		
							
210	210	210	210	5000	0	60000	210
10/2020	10/2020	10/2020	10/2020		01/2021		10/2020
✓	✓	✓	✓				✓
—	04/26/2019	Repair	64050 km	35694	Job: Standard scope of service Job: Vehicle check service Job: Engine oil service Job: Service - microfilter Job: Service - air filter insert Job: Fuel filter service Job: Job		
					Autohaus Rhein Bodensee Zw.- Nl. der AH Heermann u. Rhein GmbH , Friedrichshafen		

— Job: Standard scope of service

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Standard scope of service

Package I 0000105

Standard scope of service

Flat rate unit I 00 00 105

— Job: Vehicle check service

Description:**Is interpreted as a repeat visit:** No**Customer's own words:**

Vehicle check service

Package I 0000624

Vehicle check service
Flat rate unit I 00 00 624

6

— Job: Engine oil service**Description:****Is interpreted as a repeat visit:** No**Customer's own words:**

Engine oil service

Package I 0000610

Engine oil service
Flat rate unit I 00 00 610

3

!!! unknown BMW-Id FT9030 Shell Helix Ultra ECT SAE 0W-
30BMW Longlife 04 !!!
Part I FT9030

5

Local

Set oil-filter element
Part I 11428575211

1

— Job: Service - microfilter**Description:****Is interpreted as a repeat visit:** No**Customer's own words:**

Service - microfilter

Package I 0000616

Service - microfilter
Flat rate unit I 00 00 616

2

Microfilter/activated Carbon container
Part I 64119237555

1

— Job: Service - air filter insert**Description:****Is interpreted as a repeat visit:** No**Customer's own words:**

Service - air filter insert

Package I 0000602

Service - air filter insert
Flat rate unit I 00 00 602

2

Air filter element
Part I 13718511668

1

— Job: Fuel filter service

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Fuel filter service

Package I 0000604

Fuel filter service	3
Flat rate unit I 00 00 604	

Fuel filter cartridge	1
Part I 13328572522	

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Outside car wash and interior vehicle cleaning	0 FRU
Flat rate unit I 00 11 329	

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

!!! unknown BMW-Id ESTIMATE !!!	Local	0 FRU
Flat rate unit I -		

!!! unknown BMW-Id ESTIMATE !!!	Local	0 FRU
Flat rate unit I -		

—	03/27/2019	Key	57848 km	35694	Key 0
---	------------	-----	----------	-------	-------

							
7000	7000	7000	7000	11000	0	2100	7000
10/2020	583	583	583		01/2021		10/2020

—	03/27/2019	Service	57848 km	35694	Automatic
---	------------	---------	----------	-------	-----------

							
7000	7000	7000	7000	11000	0	2100	7000
10/2020	10/2020	10/2020	10/2020		01/2021	✓	10/2020

—	03/27/2019	Repair	57848 km	35694	Job Job Job
				Autohaus Rhein	

Bodensee Zw.- Job
Nl. der AH
Heermann u.
Rhein GmbH ,
Friedrichshafen

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

812182499	Local	0 FRU
Flat rate unit I -		

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Räder ab- und anmontieren	Local	6 FRU
Flat rate unit I 36 00 101		
Einlagerung + Reinigung Räder (ext.Dienstleister)	Local	1
Part I FT0000180		

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Outside car wash and interior vehicle cleaning	0 FRU
Flat rate unit I 00 11 329	


— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

—	10/08/2018	Key	34741 km	Key 0
---	------------	-----	----------	-------



—	10/08/2018	Service	34741 km	35694	Automatic
Autohaus Rhein Bodensee Zw.- Nl. der AH Heermann u. Rhein GmbH , Friedrichshafen					

-4900	0	-4900	0	31000	0	27000
01/2020		01/2020		01/2021		01/2022
✓		✓				

— 10/08/2018 Repair 34741 km 35694 Job
 Autohaus Job
 Rhein Job
 Bodensee Zw.- Job
 Nl. der AH Job
 Heermann u.
 Rhein GmbH ,
 Friedrichshafen

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Räder ab- und anmontieren	Local	6 FRU
Flat rate unit I 36 00 101		
Rädereinlagerung für eine Saison incl. Reinigu	Local	1
Part I FT0000180		

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:


— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:


— 03/29/2018 Key 5968 km 35694 Key 0




23000
01/2020




0




23000
672



0




49000




0

01/2021



47000



50000
01/2022

— 03/29/2018 Repair 5968 km 35694
Autohaus
Rhein
Bodensee Zw.-
Nl. der AH
Heermann u.
Rhein GmbH ,
Friedrichshafen

Job
Job
Job

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:


Rädereinlagerung für eine Saison incl. Reinigu
Part I FT0000180

Local

1

— 02/05/2018 Service 1 km 35694
Heermann und
Rhein GmbH,
Friedrichshafen

Manual



0
02/2018



— 02/02/2018 Repair 1 km 35694
Autohaus
Rhein
Bodensee Zw.-
Nl. der AH
Heermann u.
Rhein GmbH ,
Friedrichshafen

Job

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

UVV + Kleber Rettungskarte + Kleber Flat rate unit I 00 01 113	Local	2 FRU
Free pre-delivery check Flat rate unit I 00 00 009		9 FRU
Pre-delivery check, wiper water pump, winter tires and interior rearview mirror with digital compass Flat rate unit I 00 00 746		1 FRU
Suspension block pre-delivery check Flat rate unit I 00 00 741		1 FRU

—	02/02/2018	Repair	1 km	35694 Autohaus Rhein Bodensee Zw.- Nl. der AH Heermann u. Rhein GmbH , Friedrichshafen	Job
---	------------	--------	------	---	-----

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Räder ab- und anmontieren Flat rate unit I 36 00 101	Local	6 FRU
Rädereinlagerung für eine Saison incl. Reinigung Flat rate unit I 99 99 999	Local	1 FRU
RDCi wheel & tire, winter, light alloy Part I 36 11 2 289 696		4

—	01/29/2018	Key	1 km	35694	Key 0
---	------------	-----	------	-------	-------

