

Vehicle

BMW 318d, 110kW

WBA8H710X0K357979



Development code	F31
Color	alpinweiss 3
Actual integration level	F020-22-07-530
Start of warranty	August 5, 2015

▼ Technical Campaigns

There are no campaigns available.

▼ Special information

There are no campaigns available.

▼ Live Diagnosis

⚠ An error has occurred. Please try again later.

▼ Service contracts

No BSI contracts available

You can find additional service contract information and selection options in the DCSNet warranty vehicle enquiry.

▼ Information on faults, workshop/Service Consultation

No information on faults is available.

▼ Navigation map

Installed map	Enabling code (subscription)	Latest navigation map included in subscription	Latest navigation map subject to charge
Road Map EUROPE Route 2018-1 (as of: Aug 21, 2024)	Release code valid for navigation maps with release date up to Dec 31, 2025 (SWID: 00B4008F).	Road Map EUROPE WEST Route 2025	-

▼ Vehicle details

Vehicle type	Passenger car
--------------	---------------

Brand	BMW
Model	318d
Body	TOUR
Vehicle identification number (last 7 characters)	K357979
Vehicle identification number (17 characters)	WBA8H710X0K357979
Development code	F31
Steering	LL
Engine	B47U
Engine number	66429314
Exhaust re-treatment	EURO6;W;PI/CI; M, N1 I
Transmission	AUT
Transmission number	0121809ZEK
Head unit serial number	MM01DFF0868943
Drive	HECK
Integration level	F020-15-07-502
Production date	Jul 13, 2015
Production works	Muenchen
Delivery date	Jul 16, 2015
Delivering Retailers	No information
National-market version	EUR
Paint code	300
Upholstery code	BDAT
Model code	8H81
Base type	8H71
Lead type	8H81

▾ Optional equipment

Optional equipment fitted at the factory:

01CA Selection of COP relevant vehicles
 01CB CO2 package
 0205 Automatic transmission
 0216 Hydro steering-servotronic
 0230 Extra package, EU-specific
 0255 Sports leather steering wheel
 02FH BMW LA wheel, V Spoke 390
 02VB Tire pressure display
 0302 Alarm system
 0320 Deleted, model lettering
 03AA Roof railing black

Retrofitted optional equipment:

This vehicle has no retrofits.

0402 Electric panoramic roof
0423 Floor mats, velours
0428 Warning triangle and first aid kit
0430 Interior/outside mirror with auto dip
0431 Interior mirror with automatic-dip
0493 Storage compartment package
0494 Seat heating driver/passenger
04AE Armrest front, retractable
04CG Interior strips, "satin-silber" matt
0508 Park Distance Control (PDC)
0521 Rain sensor
0534 Automatic air conditioning
0544 Cruise control with braking function
0548 Kilometer-calibrated speedometer
0563 Light package
0575 Supplementary 12V sockets
05A2 LED headlight
05DA Passenger airbag deactivation
05DC Rear-seat headrests, folding
0606 Navigation system Business
0698 Area-Code 2 for DVD
06AC Intelligent emergency SOS call
06AE Teleservices
06NH Hands-free with USB interface
06WA Instrument cluster, expanded equipment
07LC Modell Advantage
0801 German version
0851 Language version German
0879 On-board vehicle literature German
08KA Oil service interval, 24 mos./30,000 km
09AA Outer skin protection
A090 90 AH AGM battery
POLS Cloth cushion

Vehicle histories

Date		Type	Vehicle mileage		Dealer		Overview	
—	09/18/2025	Key	170035 km		04561		Key 1	
 10000 11/2026   10000 11/2026   60000  11/2026  40000  35000 11/2028  12/2026								
—	08/21/2024	Key	156979 km		04561		Key 1	
 3200 10/2024  3200 10/2024  3200 10/2024  3200 10/2024  60000  10/2024  60000  31000 10/2026  10/2024								
—	08/21/2024	Repair	156979 km		00081 ,		Job Job Job Job Job	
—		Job						

Description:**Is interpreted as a repeat visit:** No**Customer's own words:**

Vehicle was already finished with another repair or technical campaign Flat rate unit I 00 74 759	1 FRU
--	-------

— Job**Description:****Is interpreted as a repeat visit:** No**Customer's own words:** Abgebrochene Distanzschraube entfernen(ausbohren),

Work time without specification/engine Flat rate unit I 11 99 000	1 FRU
--	-------

Spacer bolt Part I 11 14 8 580 379	1
---------------------------------------	---

— Job**Description:****Is interpreted as a repeat visit:** No**Customer's own words:** O-Ton Mechaniker: Distanzschraube für Akustikabdeckung lag abgebrochen,auf dem Unterfahrschutz. Deshalb hat der Rippenriemen an der,Akustikabdeckung geschliffen. Neue Akustikabdeckung kann nur mit ein er,neuen Distanzschraube sicher montiert werden.,--> Reste der Schraube muss aus dem Gewinde entfernt(ausgebohrt) werden,und die Schraube ersetzt werden.,,,,,,

Replace exhaust-gas recirculation cooler, including exhaust-gas recirculation valve Flat rate unit I 00 74 057	25 FRU
---	--------

Performing additional work for pressure sensor functional check Flat rate unit I 00 74 636	3 FRU
---	-------

Additional work: enter component identification of new exhaust-gas recirculation cooler in diagnostic system Flat rate unit I 00 74 637	1 FRU
--	-------

Additional work: clean EGR pipe Flat rate unit I 00 74 638	6 FRU
---	-------

Exhaust gas cooler high temperature Part I 11 71 7 822 347	1
---	---

AGR small parts set Part I 11 71 8 490 640	1
---	---

Vacuum hose black Part I 11 65 8 595 650	0.5
---	-----

Pipe union Part I 11 71 7 799 853	2
--------------------------------------	---

Holder Part I 61 13 1 369 832	1
----------------------------------	---

Connection piece Part I 11 65 7 803 012	1
--	---

O-ring	1
--------	---

Acoustic cover front 1
Part I 11 14 8 490 577

Anti-freeze 3
Part I 83 19 2 218 347

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

unknown fru: null Local 1 FRU
Flat rate unit I 00 76 854

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Service consultation at the vehicle 0 FRU
Flat rate unit I 00 52 050

— Job






Description:

Is interpreted as a repeat visit: No

Customer's own words:

Service Standard Fahrzeugpflege Local 1
Part I IF00200

— 09/06/2022 Key 133984 km 04561 Key 1



— 09/06/2022 Repair 133984 km 04561 Job
Niederlassung Job
Berlin Filiale Job
Weißensee
BMW AG,
Berlin

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Program control units 9 FRU
Flat rate unit I 00 71 349

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Serviceberatung am Fahrzeug Part I IF52050	Local	1
---	-------	---

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Service Standard Fahrzeugpflege Part I IF00200	Local	1
---	-------	---

—	01/09/2020	Repair	99298 km	04561 Niederlassung Berlin Filiale Weißensee BMW AG, Berlin	Job Job Job
---	------------	--------	----------	--	-------------------

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words: AGR Datum 29.05.15 laut TA AGR Kühler ers.,Kühlmittelstand i.o,Kühlsystem entlüftet
Drucktest i.o,Adaption gelöscht,

Check label/ replace exhaust-gas recirculation cooler and remount exhaust-gas recirculation valve; clean exhaust-gas recirculation pipe Flat rate unit I 00 68 166	30 FRU
--	--------

Additional work, perform pressure sensor function test Flat rate unit I 00 68 742	3 FRU
--	-------

exhaust cooler Part I 11 71 8 596 444	1
--	---

Set of small parts Part I 11 71 8 597 652	1
--	---

Pipe union Part I 11 71 7 799 853	2
--------------------------------------	---

O-ring Part I 11 61 8 512 681	1
----------------------------------	---

Oval head screw Part I 35 21 7 685 343	2
---	---

Anti-freeze Part I 83 19 2 211 358	3
---------------------------------------	---

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Fahrzeugüberprüfung im Rahmen der Annahm
Flat rate unit I 00 52 054

Local

0 FRU

— Job

Description:

Is interpreted as a repeat visit: No










Customer's own words:

— 01/08/2020 Key

99294 km

04561

Key 1












— 06/06/2019 Service

94262 km

04561
Niederlassung
Berlin Filiale
Weißensee ,
Berlin

Automatic



— 06/06/2019 Repair

94262 km

04561
Niederlassung
Berlin Filiale
Weißensee
BMW AG,
Berlin

Job
Job
Job
Job
Job
Job
Job
Job
Job
Job

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Serviceberatung am Fahrzeug
Part I 52050

Local

1

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Standard scope of service

2 FRU

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Engine oil service	3 FRU
Flat rate unit I 00 00 610	

Set oil-filter element	1
Part I 11 42 8 575 211	

BMW Engine Oil LL04 0W30	5
Part I 83 21 2 405 950	

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Motorölservice - zusätzliche AW	Local	2 FRU
Flat rate unit I IM00 25 0		

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Service - microfilter	2 FRU
Flat rate unit I 00 00 616	

Microfilter/activated Carbon container	1
Part I 64 11 9 237 555	

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

— 06/05/2019 Key 94262 km 04561 Key 1

									
1500	0	1500	0	80000	0	80000	33000		0
04/2020		329			08/2020		04/2022		09/2020

— 02/05/2019 Key 86448 km Key 0

									
9000	0	9000	0	80000	0	90000	40000		0
04/2020		453			08/2020		04/2022		09/2020

— 02/05/2019 Repair 86457 km 04561
Niederlassung
Berlin Filiale
Weißensee
BMW AG,
Berlin

Job
Job
Job
Job
Job

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

BMW Premium Selection 360 degree vehicle check (only for German market)

17 FRU

Flat rate unit I 00 00 130

Silicone spray

1

Part I 83 19 2 208 609

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Probefahrt nach PREMIUM SELECTION

Local

3 FRU

— Job

Description:**Is interpreted as a repeat visit:** No

Customer's own words: Air beachten ggf.AW in NMS ändern,Kühler geptüft--> Temperatursensor herausgeschraubt mithilfe induskop,hineingeschaut I.O.--> Agr ventil herausgeschraubt,mithilfe induskop herreingeschaut I.O.,Vorl aufleitung für Agr ventil Rissig (undicht) --> siehe bilder,Az Zeiten sind für den Agr Ventil Vorlaufleitung benötigt worden,

Visual inspection of exhaust gas recirculation cooler outlet and cooler inlet/check coolant level CCM and check coolant for tightness
Flat rate unit I 00 67 715

14 FRU

— Job

Description:**Is interpreted as a repeat visit:** No**Customer's own words:**

Bleed the cooling system and check it for watertightness with the special tool
Flat rate unit I 17 00 539

3 FRU

Coolant hose, supply
Part I 11 71 8 570 794

1

Hose clamp
Part I 16 12 1 176 918

2

Gasket Steel
Part I 11 71 8 579 364

1

Oval head screw
Part I 35 21 7 685 343

2

— Job

Description:**Is interpreted as a repeat visit:** No**Customer's own words:**

—	12/18/2018 Repair	86442 km	26796 Niederlassung Berlin Filiale Marzahn BMW AG, Berlin	Job
---	-------------------	----------	---	-----

— Job

Description:**Is interpreted as a repeat visit:** No

Customer's own words: Winterräder gegen Sommer- räder tauschen und im TV abgeben / Räder,wurden vom Kunden abgetreten,

Winterräder gegen Sommer- räder tauschen
Flat rate unit I AZ36 00 1

Local

6 FRU

—	10/15/2018	Key	81293 km	Key 0
---	------------	-----	----------	-------

								
15000	0	15000	0	70000	0	80000	46000	0
04/2020		563			08/2020		04/2022	09/2020

—	10/15/2018	Repair	81293 km	26796	Job
				Niederlassung	Job
				Berlin Filiale	Job
				Marzahn BMW	Job
				AG, Berlin	Job
					Job
					Job
					Job
					Job
					Job

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words: Unfallschaden instandsetzen Haftpflichtschaden RKÜ Freigabe der,Versicherung und Gutachten TÜV vom 31.08.18 liegen vor Kunde zahlt,MwSt.,

Fahrzeugüberprüfung im Rahmen der Annahm Flat rate unit I 00 52 054	Local	0 FRU
Performing vehicle test Flat rate unit I 00 00 556		2 FRU
Resume vehicle test and clear fault memory Flat rate unit I 61 00 980		2 FRU

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words: Ab- und Aufrüstarbeiten für Seitenwand vorn links lackieren,Ab- und Aufrüstarbeiten der Tür hinten links für lackieren,Ab- und Aufrüstarbeiten der Tür vorn links für lackieren,Schallisolierung an Tür
vorn links ersetzen,

Tür vorn links instandsetzen Flat rate unit I AZ41 00 3	Local	18 FRU
Work before/after painting front left or right side panel Flat rate unit I 51 18 619		7 FRU
Stripping and refitting work for painting the rear left or right doors Flat rate unit I 51 18 850		3 FRU
Remove and install front bumper cover		11 FRU

Flat rate unit I 51 11 156

Stripping and refitting work for painting the front left or right door 8 FRU

Flat rate unit I 51 18 750

Removing and installing headlight, left 3 FRU

Flat rate unit I 63 12 502

Adjusting headlights 2 FRU

Flat rate unit I 63 10 502

Removing and installing/replacing the sound insulation at the front left or right door 7 FRU

Flat rate unit I 51 48 560

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Reparaturbedingte Reinigung (KD1) Local 1
Part I 0099310

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words: Hohlraumkonservierung für Tür vorn links,

Cavity preservation for left or right front door 5 FRU
Flat rate unit I 97 51 500

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words: Tür vorn links lackieren Stufe 3,Lackierung Fa. Beckmann Lieferschein 185803-102882 vom 15.10.18 -,16.10.18; 50682- Euro netto,Seitenwand vorn links lackieren Stufe 1,Fahrzeug abkleben -abdecken für Reparaturlackierung,

Fahrzeug abkleben -abdecken für Reparatur Local 2 FRU
Flat rate unit I AZ99 01 7

Painting the front door, left or right 42 FRU
Flat rate unit I 99 51 014

Painting the side panel, left or right 5 FRU
Flat rate unit I 99 35 510

Painting the rear door, left or right 6 FRU
Flat rate unit I 99 52 539

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Seal, outer left mirror triangle Part I 51 33 7 352 231	1
Channel sealing,outside,door, front left Part I 51 33 7 258 295	1
Sound insulation, door, front left Part I 51 48 7 286 655	1
Clip Part I 07 14 7 152 593	7
Clamp Part I 51 41 8 240 509	5
Clip with washer, natur Part I 51 41 8 224 768	10

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Lackmaterial	Local	237
Part I 99 99 9 999 990		

—	09/26/2018	Service	79575 km	OSS- 50025613 LU Fahrzeugtechnik GmbH, Berlin	Automatic
---	------------	---------	----------	--	-----------

									
16000		16000		70000		80000	47000		
04/2020		04/2020			08/2020		04/2022		08/2018
				✓		✓			✓

—	08/27/2018	Key	77632 km		Key 0
---	------------	-----	----------	--	-------

									
18000	0	18000	0	2600	0	3300	49000		0
04/2020		611			08/2020		04/2022		08/2018

—	08/27/2018	Service	77626 km	26796 Niederlassung	Manual
---	------------	---------	----------	------------------------	--------



—	08/27/2018	Repair	77632 km	26796	Job
				Niederlassung	Job
				Berlin Filiale	Job
				Marzahn BMW	Job
				AG, Berlin	Job

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Brake fluid service	4 FRU
Flat rate unit I 00 00 618	

Brake fluid DOT4 LV, low viscosity	1
Part I 83 13 2 184 843	

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words: Laub aus Motorraum entfernen,

Laub aus Motorraum entfernen	Local	1 FRU
Flat rate unit I AZ00 00 4		

Standard scope of service	2 FRU
Flat rate unit I 00 00 105	

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Operating test module and programming control unit	8 FRU
Flat rate unit I 00 64 941	

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Fahrzeugüberprüfung im Rahmen der Annahm
Flat rate unit I 00 52 054

Local

0 FRU

kostenlose Fahrzeugoberwäsche
Part I 0011319

Local

1

— 04/17/2018 Key 66389 km 26796 Key 1

 -4100 08/2018	 -4100 136	 -4100 136	 -4100 136	 26000	 0 07/2018	 21000	 -4100 08/2018	 0 08/2018
---	---	---	---	--	---	--	--	---

— 04/17/2018 Service 66389 km 26796 Automatic
Niederlassung
Berlin Filiale
Marzahn ,
Berlin

 -4100 08/2018 ✓	 -4100 08/2018 ✓	 -4100 08/2018 ✓	 -4100 08/2018 ✓	 26000	 0 07/2018	 21000	 -4100 08/2018 ✓	 0 08/2018
--	--	--	--	--	---	--	---	---

— 04/17/2018 Repair 66389 km 26796 Job
Niederlassung Job
Berlin Filiale Job
Marzahn BMW Job
AG, Berlin Job
Job
Job
Job
Job
Job

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Standard scope of service
Flat rate unit I 00 00 105

2 FRU

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Service - microfilter
Flat rate unit I 00 00 616

2 FRU

Microfilter/activated Carbon container
Part I 64 11 9 237 555

1

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Vehicle check service	6 FRU
Flat rate unit I 00 00 624	

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Service - air filter insert	2 FRU
Flat rate unit I 00 00 602	

Air filter element	1
Part I 13 71 8 511 668	

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Fuel filter service	3 FRU
Flat rate unit I 00 00 604	

Fuel filter cartridge	1
Part I 13 32 8 572 522	

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words: Original BMW Öl Twin Power Turbo 0W-3083212365929 angeliefert 5 Flaschen,

Motorölservice (Öl angeliefert)	Local	4 FRU
Flat rate unit I AZ00 00 1		

Set oil-filter element	1
Part I 11 42 8 575 211	

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Motorölservice - zusätzliche AW	Local	2 FRU
Flat rate unit I IM00 25 0		

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Serviceberatung am Fahrzeug
Part I 52050

Local

1

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Service Standard Fahrzeugpflege
Part I 00200

Local

1

— Job

Description:

Is interpreted as a repeat visit: No










Customer's own words:

— 07/19/2017 Key

46859 km

26796

Key 0



— 07/19/2017 Repair

46864 km

26796

Niederlassung
Berlin Filiale
Marzahn BMW
AG, Berlin

Job
Job
Job
Job

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Vehicle service - check before expiry of warranty
Flat rate unit I 00 00 102

5 FRU

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Performing vehicle test
Flat rate unit I 00 00 556

2 FRU

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Serviceberatung am Fahrzeug

Local

1

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

— 08/25/2016 Key 32635 km 26796 Key 0

									
31000	31000	31000	31000	60000	0	60000	31000		0
08/2018	736	736	736		07/2018		08/2018		08/2018

— 08/25/2016 Repair 32635 km 26796 Job
 Niederlassung Job
 Berlin Filiale Job
 Marzahn BMW
 AG, Berlin

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words: *E undicht,

Replace left and right radial shaft seal for driven shafts on rear axle differential 24 FRU
 Flat rate unit I 33 10 024

Ersatzfahrzeug fremd "Fa.Sixt" Rg.Nr.: 9 Local 2
 Part I 0000158

Gasket set differential 2
 Part I 33 10 7 564 416

Repair kit recessed nut blue 1
 Part I 33 12 7 607 158

Self-locking collar nut 1
 Part I 33 30 6 760 349

Hex bolt 3
 Part I 26 11 7 635 643

Self-locking hex nut 3
 Part I 26 12 7 536 563

Screw plug with O-ring 1
 Part I 33 11 7 525 064

Torx bolt 4
 Part I 33 30 6 861 221

Torx screw 6
 Part I 33 32 6 764 505

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Fahrzeugüberprüfung im Rahmen der Annahm Flat rate unit I 00 52 054	Local	0 FRU
kostenlose Fahrzeugoberwäsche Part I 0011319	Local	1

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

— 08/15/2016 Key 31932 km 26796 Key 0

 -2000 08/2017	 0	 -2000 380	 0	 60000	 0 07/2018	 60000	 29000 08/2019	 0 08/2018
---	--	---	--	--	---	--	--	---

— 08/15/2016 Service 31932 km 26796 Manual
Niederlassung
Berlin, Berlin

 ✓	 ✓	 ✓								
--	--	--	---	---	---	---	--	---	---	---

— 08/15/2016 Repair 31932 km 26796 Job
Niederlassung Job
Berlin Filiale Job
Marzahn BMW Job
AG, Berlin Job
Job
Job
Job
Job

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Engine oil service Flat rate unit I 00 00 610	3 FRU
Set oil-filter element Part I 11 42 8 575 211	1
BMW Engine Oil LL04 0W30 Part I 83 21 2 405 950	5

— Job**Description:****Is interpreted as a repeat visit:** No**Customer's own words:**

Standard scope of service Flat rate unit I 00 00 105	2 FRU
---	-------

— Job**Description:****Is interpreted as a repeat visit:** No**Customer's own words:**

Service - microfilter Flat rate unit I 00 00 616	2 FRU
Microfilter/activated Carbon container Part I 64 11 9 237 555	1

— Job**Description:****Is interpreted as a repeat visit:** No**Customer's own words:** Fahrzeugüberprüfung im Rahmen der Annahme,Für Undichtheit an der Hinterachse links wird ein neuer Termin,vereinbart.,

Fahrzeugüberprüfung im Rahmen der Annahm Flat rate unit I 00 52 054	Local	0 FRU
--	-------	-------

— Job**Description:****Is interpreted as a repeat visit:** No**Customer's own words:**

kostenlose Fahrzeugoberwäsche Part I 0011319	Local	1
---	-------	---

— Job**Description:****Is interpreted as a repeat visit:** No**Customer's own words:****— Job**

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Motorölservice - zusätzliche AW Flat rate unit I IM00 25 0	Local	2 FRU
---	-------	-------

— Job


Description:

Is interpreted as a repeat visit: No

Customer's own words:

Füllmengen prüfen und ergänzen Flat rate unit I AZ00 00 4	Local	1 FRU
--	-------	-------

—	07/08/2016	Key	27946 km	26796	Key 0
---	------------	-----	----------	-------	-------



—	07/08/2016	Repair	27946 km	26796	Job
				Niederlassung	Job
				Berlin Filiale	Job
				Marzahn BMW	Job
				AG, Berlin	Job

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words: Reifen des angelieferten Rades (VoRe) ersetzen (Aktionspreis),

Reifen des angelieferten Rades (VoRe) er Flat rate unit I AZ36 50 1	Local	4 FRU
--	-------	-------

Michelin Energy Saver Part I 85 45 2 548 523		1
---	--	---

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Rep. kit, screw valve for RDCi Part I 36 10 6 867 147		1
--	--	---

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Fahrzeugüberprüfung im Rahmen der Annahm
Flat rate unit I 00 52 054

Local

0 FRU

— Job

Description:

Is interpreted as a repeat visit: No


Customer's own words:

— 04/28/2016 Key

20846 km

26796

Key 0




9000

08/2017



0




9000


490



0




60000




0

07/2018



60000



40000

08/2019



0

08/2018

— 04/28/2016 Repair

20846 km

26796

Niederlassung
Berlin Filiale
Marzahn BMW
AG, Berlin

Job

Job

Job

Job

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Replacing the exhaust-gas recirculation valve
Flat rate unit I 00 64 011

10 FRU

EGR-valve
Part I 11 71 8 594 492

1

Gasket Steel
Part I 11 71 8 579 364

1

Oval head screw
Part I 35 21 7 685 343

2

Hose clamp
Part I 07 12 9 952 104

2

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words: Füllmengen prüfen,

Füllmengen prüfen Flat rate unit I AZ00 00 4	Local	1 FRU
---	-------	-------

Fahrzeugüberprüfung im Rahmen der Annahm Flat rate unit I 00 52 054	Local	0 FRU
--	-------	-------

— Job


Description:

Is interpreted as a repeat visit: No

Customer's own words:

kostenlose Fahrzeugoberwäsche Part I 0011319	Local	1
---	-------	---

12/11/2015	Key	6995 km	26796	Key 0
------------	-----	---------	-------	-------



12/11/2015	Repair	6995 km	26796 Niederlassung Berlin Filiale Marzahn BMW AG, Berlin	Job Job
------------	--------	---------	---	------------

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Vehicle check in frame of acceptance Flat rate unit I 00 52 054		0 FRU
--	--	-------

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words: Vorführwagen Auslieferungsdurchsicht, Schadenkontrolle Übergabe Schäden ggf. auf BXA1 absplitten Ex Vfw, Kaiserdamm,

Vorführwagen Auslieferungsdurchsicht Sch Flat rate unit I AZ00 03 5	Local	7 FRU
--	-------	-------

10/16/2015	Repair	3507 km	00081 Niederlassung Berlin BMW AG, Berlin	Job Job Job
------------	--------	---------	--	-------------------

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Service consultation at the vehicle	0 FRU
Flat rate unit I 00 52 050	

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Winterräder aus Vorführwagenbestand mont	Local	6 FRU
Flat rate unit I AZ36 01 0		

Radsatzeinlagerungspaket BASIS	Local	1
Part I 36700		

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Gebrauchtes WKR	Local	4
Part I 99 99 9 289 738		

—	09/30/2015	Repair	2423 km	00081 Niederlassung Berlin BMW AG, Berlin	Job Job Job
---	------------	--------	---------	--	-------------------

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Einen Reifen ersetzen (Aktionspreis) Mic	Local	7 FRU
Flat rate unit I AZ36 50 1		

Michelin Energy Saver	1
Part I 85 45 2 548 523	

Clip	1
Part I 36 11 6 766 311	

Balance weight, zinc	1
Part I 36 11 6 766 315	

Balance weight, zinc, w. adhesive foil	1
Part I 36 11 6 766 328	

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Service consultation at the vehicle

0 FRU

Flat rate unit I 00 52 050