

Vehicle

BMW 520d xDrive, 140kW
WBA5E71070GK08170



Development codeF10

ColorJatoba metallic

Actual integration levelF010-22-11-510

Start of warrantyOctober 20, 2014

 There are active service contracts present.

▼ Technical Campaigns

There are no campaigns available.

▼ Special information

There are no campaigns available.

▼ Live Diagnosis

 An error has occurred. Please try again later.

▼ Service contracts

Description	Issuer	Billing as of	Duration	Vehicle mileage
UC Service Inclusive for Used Cars - 3 years / 40,000 km	AG	Aug 16, 2024	to Aug 15, 2027	to 255221 km

You can find additional service contract information and selection options in the DCSNet warranty vehicle enquiry.

▼ Information on faults, workshop/Service Consultation

No information on faults is available.

▼ Navigation map

Installed map	Enabling code (subscription)	Latest navigation map included in subscription	Latest navigation map subject to charge
Road Map EUROPE Next 2018-1 (as of: Dec 30, 2025)	Release code valid for navigation maps with release date up to Dec 31, 2025 (SWID: 00A9008F).	Road Map EUROPE WEST Next 2025	-

▼ Vehicle details

Vehicle type	Passenger car
Brand	BMW
Model	520d xDrive
Body	LIM
Vehicle identification number (last 7 characters)	GK08170
Vehicle identification number (17 characters)	WBA5E71070GK08170
Development code	F10
Steering	LL
Engine	B47O
Engine number	88669042
Exhaust re-treatment	EURO6;W;PI/CI; M, N1 I
Transmission	AUT
Transmission number	0030967WAF
Head unit serial number	HB2067E7928987
Drive	ALLR
Integration level	F010-14-07-505
Production date	Oct 10, 2014
Production works	Dingolfing
Delivery date	Oct 28, 2014
Delivering Retailers	No information
National-market version	EUR
Paint code	B65
Upholstery code	LCLZ
Model code	5E81
Base type	5E71
Lead type	5E81

▾ Optional equipment

Optional equipment fitted at the factory:

01CA Selection of COP relevant vehicles
 01CC Auto start/stop function
 01CD Brake Energy Regeneration
 0205 Automatic transmission
 0223 Adaptive chassis and suspension
 0230 Extra package, EU-specific
 0255 Sports leather steering wheel
 0258 Tire with run-flat functionality
 02VB Tire pressure display

Retrofitted optional equipment:

This vehicle has no retrofits.

02W1 BMW LA wheel, Multispoke 454
0302 Alarm system
0316 automatic trunk lid mechanism
0319 Integrated universal remote control
0320 Deleted, model lettering
0322 Comfort Access
0323 Soft-Close-Automatic doors
0358 Climate comfort windscreen
03AC Trailer coupling
03AG Reversing camera
03DZ Delete extra external lettering
0403 Glass roof, electrical
0415 Sun-blind, rear
0416 Roller sun vizor, rear lateral
0423 Floor mats, velours
0428 Warning triangle and first aid kit
0430 Interior/outside mirror with auto dip
0431 Interior mirror with automatic-dip
0441 Smoker package
0453 Climate-controlled seats, front
0455 Active seat for driver and front passenger
0456 Comfort seat with memory
0464 Ski bag
0465 Through-loading system
0488 Lumbar support, driver and passenger
0494 Seat heating driver/passenger
0496 Seat heating, rear
04CE Fine woodgrain vers., Fineline anthrac.
04M8 Individual rear-reading light
04NB Autom. climate control with 4-zone ctrl
04U2 Driving experience switch incl. ECO PRO
04UR Ambient interior lighting
0502 Headlight cleaning system
0508 Park Distance Control (PDC)
0536 Auxiliary heating
0548 Kilometer-calibrated speedometer
0552 Adaptive LED headlight
0575 Additional 12V socket
05A1 LED Fog lights
05AC High-beam assistant
05AG Lane-change warning
05AL Active Protection
05AT Driving Assistant Plus
05DL Surround View
0601 TV function
0609 Navigation system Professional
0610 Head-up display
0654 DAB tuner
0688 Harman/Kardon Surround Sound system
0696 DVD changer
0698 Area-Code 2 for DVD
06AC Intelligent emergency SOS call
06AE Teleservices
06AK Connected Drive Services
06AM Real-Time Traffic Information
06AN Concierge Services
06AP Remote Services
06AR Internet
06FV Online Entertainment
06NS Convenience phone, expanded Smartphone
06UK Night Vision with human recognition
06WB Multifunctional instrument display
0775 Headlining anthracite
07A2 Innovation Package II
07RS Package Comfort
07S2 Luxury Line
07XP Navigation package, Connected Drive
0801 German version

0851 Language version German
0879 On-board vehicle literature German
08KA Oil service interval, 24 mos./30,000 km
08TF Active pedestrian protection
08TH Road sign detection
A105 105 AH AGM battery
LEDE Leather trim

Vehicle histories

Date	Type	Vehicle mileage			Dealer	Overview				
02/11/2026	Key	230860 km			00089	Key 0				
 16000 08/2026	 16000 08/2026	 16000 08/2026	 16000 08/2026	 5000 08/2026	 12/2027	 12/2027	 160000 08/2026	 16000 08/2026	 11/2027	
12/18/2025	Key	226760 km			00089	Key 0				
 20000 08/2026	 20000 08/2026	 20000 08/2026	 20000 08/2026	 8000 08/2026	 -17 2.3 %	 -17 2.3 %	 170000 08/2026	 20000 08/2026	 -47 6.4 %	
12/18/2025	Service	226760 km			00089 Niederlassung Nürnberg , Nürnberg	Automatic				
 20000 08/2026	 20000 08/2026	 20000 08/2026	 20000 08/2026	 8000 08/2026	 12/2025 ✓	 12/2025 ✓	 170000 08/2026	 20000 08/2026	 11/2025	
12/18/2025	Repair	226760 km			00089 ,	Job Job Job Job Job Job Job Job Job Job Job Job Job Job Job Job Job Job Job				

Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Befund: -Gasdruckfedern sind seit 08/24
Part I 0011322

Local

1

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Vacuum pipe
Part I 22 11 6 781 560

1

Hex bolt
Part I 07 11 9 905 848

6

Star-socket screw
Part I 07 11 9 908 507

2

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words: <https://prod.fleetback.com/aftersales/cf482776-1829-492f-8f45-41c4c5befe15,,,,>

Proactive Service-Check
Flat rate unit I AZ00 00 0

Local

3 FRU

Test für Digitalisierung in der Werkstatt
Flat rate unit I AZ00 01 2

Local

1 FRU

Dokumentationsaufwand SVC
Flat rate unit I AZ00 15 2

Local

2 FRU

Proactive Service
Flat rate unit I AZ00 00 1

Local

2 FRU

Dokumentationsaufwand SVC
Flat rate unit I AZ00 15 2

Local

2 FRU

Test für Digitalisierung in der Werkstatt
Flat rate unit I AZ00 01 2

Local

1 FRU

Erstellung Kostenvoranschlag für die Pot
Flat rate unit I AZ00 01 5

Local

4 FRU

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Standard scope of service
Flat rate unit I 00 00 105

2 FRU

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Brake fluid service Flat rate unit I 00 00 618		4 FRU
Brake fluid DOT4 LV, low viscosity Part I 83 13 0 443 030		1

— Job**Description:****Is interpreted as a repeat visit:** No**Customer's own words:**

Fahrzeug befindet sich im Serienzustand Part I AZ21118	Local	1
---	-------	---

— Job**Description:****Is interpreted as a repeat visit:** No**Customer's own words:**

1.2 Servicewäsche Plus 50% Rabatt Umbau Part I 0011325	Local	1
---	-------	---

— Job**Description:****Is interpreted as a repeat visit:** No**Customer's own words:**

Ec-/ Kreditkarte und Paypal möglich Part I AZ22237	Local	1
Abholung nur bis 18 Uhr. Part I IF00202	Local	1
Keine Barzahlung möglich. Part I IF00203	Local	1

— Job**Description:****Is interpreted as a repeat visit:** No**Customer's own words:**

Hauptuntersuchung nach § 29 StVZO Part I 0012159	Local	1
Nachkontrolle zur Hauptuntersuchung gemäß Part I 0012159	Local	1

— Job**Description:****Is interpreted as a repeat visit:** No**Customer's own words:**

RITA vorab Check durchgeführt	Local	1
-------------------------------	-------	---

— Job

Description:**Is interpreted as a repeat visit:** No**Customer's own words:** MKP 5123766 : BMW Service 5+ 20% Nachlass,

Removing and installing or replacing both gas pressure props for engine hood Flat rate unit I 51 23 766	1 FRU
--	-------

Gas spring front flap, active Part I 51 23 7 309 117	2
---	---

— Job

Description:**Is interpreted as a repeat visit:** No**Customer's own words:**

Replacing both engine mounts Flat rate unit I 22 11 521	30 FRU
--	--------

Engine mount, left Part I 22 11 7 935 143	1
--	---

Engine mount, right Part I 22 11 7 935 144	1
---	---

Screw self-tapping Part I 31 10 6 783 907	10
--	----

— Job

Description:**Is interpreted as a repeat visit:** No**Customer's own words:**

First-aid kit, case, black Part I 71 10 7 263 439	1
--	---

— Job

Description:**Is interpreted as a repeat visit:** No**Customer's own words:**

Removing and installing or replacing both tension struts Flat rate unit I 31 12 627	13 FRU
--	--------

Hex bolt with washer Part I 31 10 6 786 310	2
--	---

Clip nut, left Part I 31 10 6 783 591	1
--	---

Hexagon nut with collar Part I 07 14 6 875 114	2
---	---

Collar screw with spring	2
--------------------------	---

Tension strut with hydraulic mount, right Part I 31 12 6 777 734	1
---	---

Tension strut with hydraulic mount, left Part I 31 12 6 777 733	1
--	---

Clip nut, right Part I 31 10 6 783 592	1
---	---

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Replacing both ride height sensors at front Flat rate unit I 37 14 530	4 FRU
---	-------

Scheinwerfer einstellen - Zusatzarbeit Flat rate unit I AZ63 00 0	Local	2 FRU
--	-------	-------

Control rod, left Part I 37 14 6 778 263	1
---	---

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words: MKP 0000614 : BMW Service 5+ 20% Nachlass,

Rear brakes service Flat rate unit I 00 00 614	8 FRU
---	-------

Brake cleaner, acetone-free Part I 83 19 2 413 695	1
---	---

Brake pad wear sensor, rear Part I 34 35 6 791 962	1
---	---

Repair kit, brake pads Part I 34 21 8 847 062	1
--	---

Brake pad paste Part I 83 19 2 158 851	2
---	---

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words: MKP 3421932 : BMW Service 5+ 20% Nachlass,

Removing and installing/renewing both brake discs Flat rate unit I 34 21 932	2 FRU
---	-------

Inner hex bolt Part I 34 21 1 161 806	2
--	---

Brake disc, lightweight, ventilated Part I 34 21 6 898 733	2
---	---

Torx screw with washer	4
------------------------	---

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Replace left and right wiper blade 1 FRU
Flat rate unit I 61 61 541

Set of wiper blades 1
Part I 61 61 2 458 015

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words: "O-Ton Mechaniker",Sicht prüfung i.o,Stecker hat keine korrosion i.o,Spannungsversorgung i.o,FS auslesen -> 3x Fehlercode im FS wegen der Lambdasonde nach Kat.,ABL
Lambdasonden durchgeführt -> Lambdas
onde nach Kat. ersetzen,Kundeninfo:,Im FS ist noch ein Fehler bezüglich zum DPF
Restwegstrecke,Restwegstrecke von ca 35880km -> i.o. -> Empfehlung: Langstreckenfahrt
damit Fzg. eine Regeneration durch
führt,,Diagnose Code,D1170_D0000000_12_401,

Performing vehicle test 3 FRU
Flat rate unit I 00 00 556

Supporting the voltage of the vehicle electrical system/recharging the
vehicle electrical system battery 1 FRU
Flat rate unit I 61 21 528








Replacing oxygen sensor monitor 5 FRU
Flat rate unit I 13 62 664

Troubleshooting 2 FRU
Flat rate unit I 12 00 009








Performing vehicle test 3 FRU
Flat rate unit I 00 00 556

Oxygen sensor 1
Part I 13 62 8 573 155

— 12/05/2025 Key 226687 km 00089 Remote KeyRead



— 11/25/2025 Key 226485 km 00089 Remote KeyRead



— 08/16/2024 Key 215221 km 00089 Key 0

-3500 11.3 % 11/2024		-3500 11/2024		19000 12/2025		180000 12/2025	28000 11/2026	

—

08/16/2024

Service

215221 km

00089
Niederlassung
Nürnberg ,
Nürnberg

Automatic

-3500 11/2024 ✓		-3500 11/2024 ✓		19000 12/2025		180000 12/2025	28000 11/2026	11/2025

—

08/16/2024

Repair

215221 km

00089 ,

Job

Job

Job

Job

Job

Job

Job

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Flüssigkeiten prüfen und ergänzen oder S Flat rate unit I AZ00 00 2	Local	1 FRU
Motorölservice - zusätzliche AW Flat rate unit I IM00 25 0	Local	2 FRU

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Standard scope of service Flat rate unit I 00 00 105	2 FRU
---	-------

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Engine oil service Flat rate unit I 00 00 610	3 FRU
Set oil-filter element Part I 11 42 8 575 211	1
BMW Engine Oil LL04 0W30	5

Ölzuschlag für Service Inklusive
Part I 0000162

Local

1

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Service - microfilter

3 FRU

Flat rate unit I 00 00 616

Set, microfilter/activ. charcoal filter

1

Part I 64 11 9 272 642

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Windshield Washer Antifreeze

1.5

Part I 83 12 2 413 061

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words: Sonderbefundnummer: SDC 0032550300,

unknown fru: null

Local

1 FRU

Flat rate unit I 00 76 854

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

GA Service Inklusive für Gebrauchtwagen

Local

1

Part I 5100102

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Fahrzeug-Außen-Wäsche (kostenlos)

Local

1

Part I 0011319

—

08/01/2024 Key

212986 km

01299

Remote KeyRead

 -1300 4.2 % 11/2024		 -1300 11/2024		 20000	 12/2025	 12/2025	 180000	 30000 11/2026	 11/2025
---	--	--	--	---	---	---	---	--	---

—	12/15/2023	Key	197371 km	00089	Key 0
---	------------	-----	-----------	-------	-------

 15000 11/2024		 15000 11/2024		 31000	 -44 6 %	 -44 6 %	 190000	 46000 11/2026	 11/2025
---	---	---	---	--	---	---	--	---	--

—	12/15/2023	Service	197371 km	00089 Niederlassung Nürnberg , Nürnberg	Automatic
---	------------	---------	-----------	--	-----------

 15000 11/2024		 15000 11/2024		 31000	 11/2023 ✓	 11/2023 ✓	 190000	 46000 11/2026	 11/2025
---	---	---	---	--	---	---	--	---	--

—	12/15/2023	Repair	197371 km	00089 Niederlassung Nürnberg BMW AG, Nürnberg	Job Job Job Job Job Job Job
---	------------	--------	-----------	---	---

—	Job
---	-----

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Befund: Haubendämpfer bis 08/24 Part I 0011322	Local	1
---	-------	---

—	Job
---	-----

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Standard scope of service Flat rate unit I 00 00 105	2 FRU
---	-------

—	Job
---	-----

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Brake fluid service Flat rate unit I 00 00 618	4 FRU
---	-------

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

BMW Kompakt-Check zum Schnellservice
Flat rate unit I AZ00 00 1

Local

1 FRU

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Achtung:
Part I IF00201

Local

1

Abholung nur bis 18 Uhr.
Part I IF00202

Local

1

Keine Barzahlung möglich.
Part I IF00203

Local






1

— 12/12/2023 Key

197351 km

00089






Remote KeyRead



— 11/14/2022 Key

180738 km

Key 0



— 11/02/2022 Key

180699 km

00089

Key 0

 -290 0.9 % 04/2023	 -290 04/2023	 -290 04/2023	 -290 04/2023	 45000 11/2023	 0 11/2023	 0 11/2023	 170000 11/2023	 -290 0.5 % 04/2023	 0 11/2023
--	---	---	---	--	--	--	--	--	--

— 11/02/2022 Service 180699 km 00089 Automatic
Niederlassung
Nürnberg ,
Nürnberg

 -290 ✓	 -290 ✓	 -290 ✓	 -290 ✓	 45000	 0	 0	 170000	 -290 ✓	 0
--	--	--	--	--	--	--	--	--	--

— 11/02/2022 Repair 180699 km 00089 Job
Niederlassung Job
Nürnberg Job
BMW AG, Job
Nürnberg Job
Job
Job
Job
Job
Job
Job
Job
Job
Job
Job
Job
Job

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words: Service Inclusive,00 11 53 06 00,Abgasrückführungskühler inklusive Abgas rückführungsventil ersetzen,AW Abgleich,

Performing additional work for pressure sensor functional check Flat rate unit I 00 72 939	3 FRU
Additional work: enter component identification of new exhaust-gas recirculation cooler in diagnostic system Flat rate unit I 00 72 940	1 FRU
Additional work: clean exhaust-gas recirculation pipe (do not use when replacing intake system) Flat rate unit I 00 72 941	2 FRU
Replace exhaust gas recirculation cooler, including exhaust gas recirculation valve Flat rate unit I 00 72 938	16 FRU
Exhaust gas cooler high temperature Part I 11 71 7 822 347	1
Acoustic cover front Part I 11 14 8 490 575	1
Pipe union	2

Part I 11 71 7 799 853

Vacuum hose black Part I 11 65 8 595 650	1
---	---

Connection piece Part I 11 65 7 803 012	1
--	---

AGR small parts set Part I 11 71 8 490 640	1
---	---

Holder Part I 61 13 1 369 832	1
----------------------------------	---

O-ring Part I 11 61 8 512 681	1
----------------------------------	---

Lubricant PF1 Part I 83 23 0 309 627	0
---	---

Hex bolt with washer Part I 07 11 9 905 750	1
--	---

Anti-freeze Part I 83 19 2 211 358	3
---------------------------------------	---

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Service consultation at the vehicle Flat rate unit I 00 52 050	0 FRU
---	-------

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Befund: - Scheinwerfer Einstellung nicht Part I 0011322	Local	1
--	-------	---

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Motorölservice - zusätzliche AW Flat rate unit I IM00 25 0	Local	2 FRU
---	-------	-------

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words: Energie Diagnose durchführen. Ruhrstromprüfung über Diagnose,durchführen. Laut Diagnose i.O. lt. Fehlerspeicher wird nur im ICM,Steuergerät Unterschpannung angezeigt. Testmodul für Unterspannung,durchführen. Laut Testmodul Fehlersuche am ICM Steuergerät. Fahrzeug auf,aktuelles Softwarestand programmieren.,Ruhestrom messung nach programierung erneut durchführen.,Eine Ruhestrom Messeung ohne Parkeins tellung und eine Messung mit,Parkeinstellung im Daschcam durchführen.i.O./lt. SB keine weitere,Massnahmen durchführen.,„Befundnummer:34 50 00 14 Steuergerät ICM Integrated Chassis Management,zeitweise Fehlfunktion,Ruhestromprüfung der Bordnetzbatte rie (nach Fahrzeugdiagose),-stark erhöhter Ruhestromverbrauch wenn die BMW, Dashcam angesteckt ist.,-Dascam kurz prüfen - (Einstellungen?),-nur kurze Fehl ersuche,,Energie Diagnose durchführen. Ruhrstromprüfung über Diagnose,durchführen. Laut Diagnose i.O. lt. Fehlerspeicher wird nur im ICM,Steuergerät Unterschpannung angezeigt. Testmodul für Unterspann ung,durchführen. Laut Testmodul Fehlersuche am ICM Steuergerät. Fahrzeug auf,aktuelles Softwarestand programmieren.,Ruhestrom messung nach programierung erneut durchführen.,Eine Ruhestrom Messeung ohne Parkeinstellung und eine Messung mit,Parkeinstellung im Daschcam durchführen.i.O./lt. SB keine weitere,Massnahmen durchführen.,„Ruhestromprüfung der Bordnetzbatte rie mit Parkeinstellung im Daschcam,Ru hestromprüfung der Bordnetzbatte rie.Ohne Parkeinstellung im Daschcam,

Desinfektionsroutine Flat rate unit I AZ00 88 9	Local	1 FRU
Performing vehicle test Flat rate unit I 00 00 556		3 FRU
Supporting the voltage of the vehicle electrical system/recharging the vehicle electrical system battery Flat rate unit I 61 21 528		1 FRU
Standby current measurement of vehicle battery Flat rate unit I 61 20 503		3 FRU
Work time without specification / vehicle electrical system Flat rate unit I 61 99 000		5 FRU
Program/encode control unit(s), includes deleting the fault memory Flat rate unit I 61 00 730		4 FRU
Standby current measurement of vehicle battery Flat rate unit I 61 20 503		3 FRU
Standby current measurement of vehicle battery Flat rate unit I 61 20 503		3 FRU
Carrying out vehicle battery "power reset" Flat rate unit I 61 20 908		2 FRU
initialize Tyre Pressure Control Flat rate unit I 36 11 503		1 FRU

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Standard scope of service	2 FRU
Flat rate unit I 00 00 105	

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Engine oil service	3 FRU
Flat rate unit I 00 00 610	

Ölzuschlag für Service Inklusive	Local	1
Part I 0000162		

BMW Engine Oil LL04 0W30	5
Part I 83 21 2 405 950	

Set oil-filter element	1
Part I 11 42 8 575 211	

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words: Keine Einstellarbeiten,

Vehicle check service	7 FRU
Flat rate unit I 00 00 624	

Clamping	1
Part I 72 11 8 469 012	

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Fuel filter service	5 FRU
Flat rate unit I 00 00 604	

Hose clamp	1
Part I 16 12 1 180 240	

Fuel filter cartridge	1
Part I 13 32 7 822 499	

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Service - air filter insert	1 FRU
Flat rate unit I 00 00 602	

Air filter element	1
--------------------	---

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Service - microfilter	3 FRU
Flat rate unit I 00 00 616	
Set, microfilter/activ. charcoal filter	1
Part I 64 11 9 272 642	

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Sommerräder abbauen / Winterräder	Local	6 FRU
Flat rate unit I IM36 00 1		

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Einlagerung Sommerräder	Local	1
Part I IF36000		

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Serviceberatung am Fahrzeug	Local	1
Part I IF52050		

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Fahrzeug-Außen-Wäsche (kostenlos)	Local	1
Part I 0011319		

— 05/10/2022 Key 167293 km Key 0


14000
04/2023


14000
321


14000
321


14000
321


60000
11/2023


531


150000


14000
04/2023


11/2023

—	05/10/2022	Repair	167293 km	00089 Niederlassung Nürnberg BMW AG, Nürnberg	Job Job Job Job Job
---	------------	--------	-----------	---	---------------------------------

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Befund: - Ad Blue Nachfüllmenge 12,5L 25 Part I 0011322	Local	1
--	-------	---

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Einlagerung Winterräder Part I IF36000	Local	1
---	-------	---

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

BMW Kompakt-Check zum Schnellservice Flat rate unit I AZ00 00 1	Local	2 FRU
--	-------	-------

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Winterräder abbauen / Sommerräder montie Flat rate unit I IM36 00 2	Local	6 FRU
--	-------	-------

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

—	02/28/2022	Key	161039 km	00089	Key 0				
									
20000	20000	20000	20000	60000			140000	20000	
04/2023	393	393	393		11/2023	603		04/2023	11/2023

—	02/01/2022	Key	159549 km	00089	Key 0
---	------------	-----	-----------	-------	-------



21000
04/2023



21000
420



21000
420



21000
420



60000



11/2023



630



140000



21000
04/2023



11/2023

—	02/01/2022	Repair	161039 km	00089 Niederlassung Nürnberg BMW AG, Nürnberg	Job Job Job Job Job Job
---	------------	--------	-----------	---	--

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words: Lackierung PF. 28.02, Wa. 01.03 -04.03,

Fahrzeugüberprüfung im Rahmen der Annahm	Local	0 FRU
Flat rate unit I 00 52 054		

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Zeitzuschlag für eine Hauptarbeit	Local	2 FRU
Flat rate unit I AZ41 99 0		

Stripping and refitting work for painting the front left or right door		5 FRU
Flat rate unit I 51 18 750		

Replacing front right side panel		13 FRU
Flat rate unit I 41 35 555		

Removing and installing front bumper panel		9 FRU
Flat rate unit I 51 11 656		

Replace bumper cover, front		6 FRU
Flat rate unit I 51 11 592		

Additional work with Park Distance Control		4 FRU
Flat rate unit I 66 20 610		

Removing and installing side view camera, left or right		1 FRU
Flat rate unit I 66 53 532		

Removing and installing side view camera, left or right		1 FRU
Flat rate unit I 66 53 532		

Setting Night Vision camera axially		2 FRU
Flat rate unit I 66 54 501		

Removing and installing right LED headlight Flat rate unit I 63 12 643		5 FRU
Removing and installing/replacing high-pressure nozzle of headlight cleaning system, right Flat rate unit I 61 67 623		2 FRU
Remove and install/replace left or right side sill trim panel Flat rate unit I 51 71 947		6 FRU
Removing and installing left or right front door Flat rate unit I 41 51 580		4 FRU
Performing vehicle test Flat rate unit I 00 00 556		2 FRU
Performing vehicle test Flat rate unit I 00 00 556		2 FRU
Verbringungskosten Part I 0009991	Local	1

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words: KV 41 AW i.O,

Blende Waschdüse rechts lackieren Flat rate unit I AZ99 99 0	Local	2 FRU
Zeitzuschlag für eine Hauptarbeit Flat rate unit I AZ99 99 0	Local	17 FRU
Painting bumper cover, front Flat rate unit I 99 68 535		14 FRU
Painting the side panel, left or right Flat rate unit I 99 35 521		8 FRU

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Trim cover, bumper, primed, front Part I 51 11 7 332 678	1
Set of mounted parts, bumper, front Part I 51 11 2 452 058	1
Covering primend right Part I 51 11 7 332 684	1
Side panel, front right Part I 41355A03262	1
Badge Part I 51 14 7 057 794	1
Ultrasonic sensor, Jatoba Part I 66 20 9 297 700	1

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Reinigungspaket Service	Local	1
Part I AZ00046		

— Job


Description:

Is interpreted as a repeat visit: No


Customer's own words:

Lackmaterial	Local	193
Part I 99 99 9 999 990		

11/02/2021	Key	156512 km	Key 0
------------	-----	-----------	-------



11/02/2021	Service	156512 km	00089 Niederlassung Nürnberg , Nürnberg	Automatic
------------	---------	-----------	--	-----------



11/02/2021	Repair	156512 km	00089 Niederlassung Nürnberg BMW AG, Nürnberg	Job Job Job Job Job
------------	--------	-----------	---	---------------------------------

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Brake fluid service	4 FRU
Flat rate unit I 00 00 618	

Brake fluid DOT4 LV, low viscosity	1
Part I 83 13 0 443 030	

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words: Service inkl.,

Standard scope of service

2 FRU

Flat rate unit I 00 00 105

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Überprüfung nach § 29 STVZO

Local

1

Part I 0012159

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Einlagerung Sommerräder: 10006212

Local

1

Part I IF36000

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Sommerräder abbauen / Winterräder

Local

6 FRU

Flat rate unit I IM36 00 1

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Reinigungspaket Service

Local

1

Part I AZ00046

—

05/26/2021 Repair

150229 km

00089

Job

Niederlassung

Job

Nürnberg

Job

BMW AG,

Job

Nürnberg

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words: #Federbruch hinten rechts,

Scheinwerfer einstellen Flat rate unit AZ63 00 0	Local	3 FRU
Removing and installing/replacing both coil springs, rear Flat rate unit 33 53 020		22 FRU
Rear coil spring Part 33 53 6 786 658		2
Spring pad lower Part 33 53 6 856 172		2
Spring pad upper Part 33 53 6 775 751		2
Auxiliary shock absorber Part 33 53 6 789 387		2
Guide support Part 33 50 6 863 301		2
Self-locking collar nut Part 07 11 9 905 374		6
Self-locking hex nut Part 32 21 6 769 539		2
Hex bolt with washer Part 07 11 9 907 031		2

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Desinfektionsroutine Flat rate unit AZ00 88 9	Local	1 FRU
--	-------	-------


— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

— 04/19/2021 Key 149445 km Key 0



— 04/19/2021 Service 149445 km 00089 Automatic
Niederlassung

Nürnberg ,
Nürnberg

 3900 ✓	 0	 3900 ✓	 0	 60000	 0	 120000	 35000	 0
--	--	--	--	--	--	---	---	--

— 04/19/2021 Repair 149445 km 00089
Niederlassung
Nürnberg
BMW AG,
Nürnberg Job
Job
Job
Job
Job

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Engine oil service Flat rate unit I 00 00 610	3 FRU
Ölzuschlag für Service inklusive Part I 0000162	Local 1
Set oil-filter element Part I 11 42 8 575 211	1
BMW Engine Oil LL04 0W30 Part I 83 21 2 405 950	5

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Service - microfilter Flat rate unit I 00 00 616	3 FRU
Set, microfilter/activ. charcoal filter Part I 64 11 9 272 642	1

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Standard scope of service Flat rate unit I 00 00 105	2 FRU
---	-------

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:






Windshield Washer Antifreeze
Part | 83 12 2 413 061

1

— 03/31/2021 Key

149374 km

Key 0



— 03/31/2021 Repair

149374 km

00089
Niederlassung
Nürnberg
BMW AG,
Nürnberg

Job
Job
Job

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

04. Sommerräder auslagern und
Flat rate unit | IM36 00 2

Local

6 FRU

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Einlagerung Winterräder
Part | IF36000

Local

1

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Desinfektionsroutine
Flat rate unit | AZ00 88 9

Local

1 FRU

— 10/24/2020 Key

146488 km

00089

Key 0



7000
04/2021



0



7000
188



0



60000



0
10/2021



120000



38000
04/2023



0
10/2021

—

10/24/2020 Repair

146488 km

00089
Niederlassung
Nürnberg
BMW AG,
Nürnberg

Job
Job

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Sommerräder abbauen / Winterräder
Flat rate unit I IM36 00 1

Local

6 FRU

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

BMW Kompakt-Check
Flat rate unit I AZ00 00 0

Local

1 FRU

—

10/01/2020 Repair

141200 km

00089
Niederlassung
Nürnberg
BMW AG,
Nürnberg

Job

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words: Vier Reifen mit Runflat ersetzen / Freigabe per Mail erhalten /,Festpreis 84928 EUR,

vier Reifen ersetzen mit Runflat (Reifen
Flat rate unit I AZ36 11 4

Local

24 FRU

Continental WinterContact TS 830 P SSR
Part I 85 45 2 549 413

1

Continental WinterContact TS 830 P SSR
Part I 85 45 2 549 413

1

Continental WinterContact TS 830 P SSR
Part I 85 45 2 549 413

1

Continental WinterContact TS 830 P SSR
Part I 85 45 2 549 413

1

Balance weight, zinc, w. adhesive foil
Part I 36 11 6 766 336

1

Balance weight, zinc, w. adhesive foil

Part I 36 11 6 766 338

1

Balance weight, zinc, w. adhesive foil

Part I 36 11 6 766 339

2

—

06/30/2020

Repair

146488 km

00089
Niederlassung
Nürnberg
BMW AG,
Nürnberg

Job

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Einlagerung Sommerräder

Part I 36000

Local

1

—


03/11/2020

Key

141200 km

00089

Key 0



—

03/11/2020

Repair

141200 km

00089
Niederlassung
Nürnberg
BMW AG,
Nürnberg

Job
Job
Job
Job
Job
Job
Job

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words: Störungssuche in der Radioanlage/Abdeckgitter Lautsprecher VL + VR mit,Gleitspray behandelt/Zierleitsten Türverkleidung VL + VR mit Gleitspray,behandelt/Abdeckgitter Center-Speaker mit Gleitspray,behandelt=>Beanstandung leicht verbessert kann nicht ganz abgestellt,werden da Klangeinstellung ziemlich basslastig ist.,Die Lautsprecher vorn rechts in der Türverkleidung prüfen"scheppern",bei Sprachdurchsagen (B5 aktuell),„Ggf. die Türverkleidung vorn rechts aus-einbauen.,Eine Probefahrt ist nicht möglich Tank ist leer.,

Troubleshooting in the radio

Flat rate unit I 65 10 009

3 FRU

Carrying out vehicle test

Flat rate unit I 00 00 006

4 FRU

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Reinigungspaket Service Part I 00046	Local	1
---	-------	---

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Shuttle-Service Part I 09072	Local	1
---------------------------------	-------	---

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Winterräder abbauen, Sommerräder Flat rate unit I IM36 00 2	Local	6 FRU
--	-------	-------

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Einlagerung Sommer-/Winterkompleträder Part I 36000	Local	1
--	-------	---

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Serviceberatung am Fahrzeug Part I 52050	Local	1
---	-------	---

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words: Label prüfen/Abgasrückführungskühler ers etzen und,Abgasrückführungsventil ummont ieren;
Abgasrückführungsrohr reinigen,=>Produktionsdatum 11.10.2016 =>AGR-Kühler muss ersetzt
werden,TA durchführen,

Check label/ replace exhaust-gas recirculation cooler and remount exhaust-gas recirculation valve; clean exhaust-gas recirculation pipe Flat rate unit I 00 68 741	26 FRU
--	--------

Additional work, perform pressure sensor function test Flat rate unit I 00 68 742	3 FRU
--	-------

exhaust cooler Part I 11 71 8 596 444	1
--	---

Set of small parts Part I 11 71 8 597 652	1
Pipe union Part I 11 71 7 799 853	2
O-ring Part I 11 61 8 583 456	1
Holder Part I 61 13 1 369 832	1
Anti-freeze Part I 83 19 2 211 358	3

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words: 3ncong,

Supporting the voltage of the vehicle electrical system/recharging the vehicle electrical system battery Flat rate unit I 61 21 528	1 FRU
--	-------

—	03/11/2020	Repair	141200 km	00089 Niederlassung Nürnberg BMW AG, Nürnberg	Job
---	------------	--------	-----------	---	-----

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

HandlingCharge GWL/WTY Part I 99 99 7 777 701	Local	1
--	-------	---

—	10/30/2019	Key	130653 km	00089	Key 0
---	------------	-----	-----------	-------	-------

								
22000	0	22000	0	5000	0	7000	50000	0
04/2021		548			10/2019		04/2023	10/2019

—	10/30/2019	Service	130653 km	00089 Niederlassung Nürnberg , Nürnberg	Automatic
---	------------	---------	-----------	--	-----------

								
22000	0	22000	0	5000	0	7000	50000	0
04/2021		04/2021			10/2019		04/2023	10/2019
				✓	✓	✓		

—	10/30/2019	Repair	130653 km	00089 Niederlassung Nürnberg BMW AG, Nürnberg	Job Job Job Job Job Job Job Job Job Job Job
---	------------	--------	-----------	---	---

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Reinigungspaket Service Part I 00046	Local	1
---	-------	---

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Removing and installing or replacing both gas pressure props for engine hood Flat rate unit I 51 23 766		1 FRU
--	--	-------

Gas spring front flap, active Part I 51 23 7 309 117		2
---	--	---

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Überprüfung nach § 29 STVZO Part I 0012159	Local	1
---	-------	---

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Standard scope of service Flat rate unit I 00 00 105		2 FRU
---	--	-------

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Brake fluid service Flat rate unit I 00 00 618	4 FRU
Brake fluid DOT4 LV, low viscosity Part I 83 13 0 443 030	1

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Service - front brakes Flat rate unit I 00 00 612	7 FRU
Repair kit, brake pads asbestos-free Part I 34 11 6 858 047	1
Brake pad wear sensor, front left Part I 34 35 6 791 958	1
Brake pad paste Part I 83 19 2 158 851	2
Brake cleaner, acetone-free Part I 83 19 2 413 695	1

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Rear brakes service Flat rate unit I 00 00 614	8 FRU
Repair kit, brake pads asbestos-free Part I 34 21 6 862 202	1
Brake pad wear sensor, rear Part I 34 35 6 791 962	1
Brake pad paste Part I 83 19 2 158 851	2
Brake cleaner, acetone-free Part I 83 19 2 413 695	1

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Removing and installing/replacing both front brake discs Flat rate unit I 34 11 613	3 FRU
Brake disc, lightweight, ventilated Part I 34 11 6 896 652	2
Inner hex bolt Part I 34 21 1 161 806	2

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Removing and installing/renewing both brake discs Flat rate unit I 34 21 932	2 FRU
Torx screw with washer Part I 34 10 6 864 424	4
Inner hex bolt Part I 34 21 1 161 806	2
Brake disc, lightweight, ventilated Part I 34 21 6 775 287	2

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Motorwäsche inkl. Versiegelung Part I 00204	Local	1
--	-------	---

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words: Auslagerung 13595968,

Sommerräder abbauen, Winterräder Flat rate unit I IM36 00 1	Local	6 FRU
--	-------	-------

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Einlagerung Sommer-/Winterkomplettäder Part I 36000	Local	1
--	-------	---

— 04/17/2019 Key

122332 km

00089

Key 0

 -80 01/2020	 -80 289	 -80 289	 -80 289	 11000	 0 10/2019	 7000	 -80 01/2020	 0 10/2019
---	---	---	---	--	---	---	--	---

— 04/17/2019 Service

122332 km

00089
Niederlassung
Nürnberg ,
Nürnberg

Automatic

									
-80	-80	-80	-80	11000	0	7000	-80	-80	0
01/2020	01/2020	01/2020	01/2020	01/2020	10/2019	10/2019	01/2020	01/2020	10/2019
✓	✓	✓	✓				✓		

[illegible]

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Windshield Washer Antifreeze	1
Part I 83 12 2 413 061	

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Reinigungspaket Service	Local	1
Part I 00046		

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Shuttle-Service	Local	1
Part I 09072		

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Diesel exhaust fluid AdBlue
Part I 83 19 2 288 328

145

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Standard scope of service
Flat rate unit I 00 00 105

2 FRU

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Service - microfilter
Flat rate unit I 00 00 616

3 FRU

Set, microfilter/activ. charcoal filter
Part I 64 11 9 272 642

1

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words: Lichter nicht verstellen,

Vehicle check service
Flat rate unit I 00 00 624

7 FRU

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Service - air filter insert
Flat rate unit I 00 00 602

1 FRU

Air filter element

1

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Fuel filter service Flat rate unit I 00 00 604	5 FRU
Fuel filter cartridge Part I 13 32 7 811 227	1
Hose clamp Part I 16 12 1 180 240	1

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Engine oil service Flat rate unit I 00 00 610	3 FRU
Ölzuschlag für Service Inklusive Part I 0000162	Local 1
Set oil-filter element Part I 11 42 8 575 211	1
BMW Engine Oil LL04 0W30 Part I 83 21 2 405 950	5

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Replacing flexible coupling for propeller shaft, rear Flat rate unit I 26 11 521	21 FRU
Universal joint Part I 26 11 7 610 061	1
Torx screw Part I 26 11 8 607 971	3
Hex bolt Part I 26 11 7 527 475	3

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Serviceberatung am Fahrzeug
Part I 52050

Local

1

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

kostenlose Fahrzeugoberwäsche
Part I 0011319

Local

1

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Betankung AdBlue
Flat rate unit I AZ16 00 0

Local

3 FRU

AdBlue Pauschale 3
Part I 16013

Local

1

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Befund:->Bremscheiben Tragbild HA schle
Part I 0011322

Local

1

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Winterräder abbauen, Sommerräder
Flat rate unit I IM36 00 2

Local

6 FRU

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Einlagerung Sommer-/Winterkompleträder
Part I 36000

Local

1

— 11/13/2018 Key

106765 km

Key 0

								
16000	16000	16000	16000	23000	0	6000	16000	0
01/2020	444	444	444		10/2019		01/2020	10/2019

—	11/13/2018	Repair	106768 km	00089	Job
				Niederlassung	Job
				Nürnberg	Job
				BMW AG,	Job
				Nürnberg	Job
					Job

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Serviceberatung am Fahrzeug Part I 52050	Local	1
---	-------	---

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words: Über Gutschein abrechnen Flüssigkeiten prüfen und ggf erg,

12-Punkte Fahrzeug Check Flat rate unit I AZ00 99 0	Local	10 FRU
--	-------	--------

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

kostenlose Fahrzeugoberwäsche Part I 0011319	Local	1
---	-------	---

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words: Auslagerungsnr. 12369268,

Sommerräder abbauen, Winterräder Flat rate unit I IM36 00 1	Local	6 FRU
--	-------	-------

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Einlagerung Sommer-/Winterkomplettäder Part I 36000	Local	1
--	-------	---

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

— 04/16/2018 Key 94486 km 00089 Key 0

								
28000	28000	28000	28000	34000	0	5000	28000	0
01/2020	655	655	655		10/2019		01/2020	10/2019

— 04/16/2018 Repair 94488 km 00089 Job
Niederlassung Job
Nürnberg Job
BMW AG, Job
Nürnberg Job

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Support lifting platform 1
Part I 51 71 7 123 311

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Serviceberatung am Fahrzeug Local 1
Part I 52050

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

kostenlose Fahrzeugoberwäsche Local 1
Part I 0011319

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Winterräder abbauen, Sommerräder auslage Local 6 FRU
Flat rate unit I IM36 00 2

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Einlagerung Sommer-/Winterkomplettreder
Part I 36000

Local

1

—	02/28/2018	Key	92913 km	00089	Key 0							
												
	29000	29000	29000	29000	36000	0	5000	29000		0		
	01/2020	701	701	701		10/2019		01/2020		10/2019		
—	01/26/2018	Key	91279 km	00089	Key 0							
												
	490	0	490	0	38000	0	5000	32000		0		
	01/2019		370			10/2019		01/2021		10/2019		
—	01/26/2018	Service	91279 km	22134	Automatic							
				Niederlassung Nürnberg Filiale Fischbach , Nürnberg								
												
	490	0	490	0	38000	0	5000	32000		0		
	01/2019		01/2019			10/2019		01/2021		10/2019		
	✓		✓									
—	01/26/2018	Repair	91286 km	22134	Job							
				Niederlassung Nürnberg Filiale Fischbach BMW AG, Nürnberg	Job Job Job Job Job Job Job Job Job							

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Motorölservice - zusätzliche AW
Flat rate unit I IM00 25 0

Local

2 FRU

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Windshield Washer Antifreeze	2
Part I 83 12 2 413 061	

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Fahrzeugüberprüfung im Rahmen der Annahm	Local	0 FRU
Flat rate unit I 00 52 054		

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Installing navigation map(s)	2 FRU
Flat rate unit I 65 90 600	

Enable code HU-H map EuropeNext Upd	1
Part I 65 90 2 406 583	

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Befund: Ad Blue Nachfüllmenge 11 Liter	Local	1
Part I 0011322		

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Standard scope of service	2 FRU	
Flat rate unit I 00 00 105		

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Service - microfilter 3 FRU
Flat rate unit I 00 00 616

Set, microfilter/activ. charcoal filter 1
Part I 64 11 9 272 642

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Engine oil service 3 FRU
Flat rate unit I 00 00 610

Ölzuschlag für Service Inklusive Local 1
Part I 0000162

Set oil-filter element 1
Part I 11 42 8 575 211

BMW Engine Oil LL04 0W30 5
Part I 83 21 2 405 950

— 10/04/2017 Key 78810 km 22134 Key 0

									
13000	0	13000	0	45000	0	5000	44000	0	0
01/2019		484			10/2017		01/2021		10/2017

— 10/04/2017 Service 78810 km 22134 Automatic

Niederlassung
Nürnberg
Filiale
Fischbach,
Nürnberg

									
13000		13000		45000	10/2017	5000	44000		10/2017
					✓				✓

— 09/20/2017 Repair 78810 km 22134 Job

Niederlassung Job
Nürnberg Job
Filiale Job
Fischbach Job
BMW AG, Job
Nürnberg Job
Job
Job
Job

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Retrofitting Advanced Car Eye camera, front and rear Flat rate unit I 72 66 168	18 FRU
--	--------

BMW Advanced Car Eye Part I 66 21 2 359 954	1
--	---

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Sommerräder abbauen, Winterräder auslage Flat rate unit I AZ36 00 2	Local	6 FRU
--	-------	-------

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Einlagerung Sommerräder 11684941 Part I 36001	Local	1
--	-------	---

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Standard scope of service Flat rate unit I 00 00 105	2 FRU
---	-------

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Brake fluid service Flat rate unit I 00 00 618	4 FRU
---	-------

Brake fluid DOT4 LV, low viscosity Part I 83 13 0 443 030	1
--	---

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Überprüfung nach § 29 STVZO mit Abgasunt Part I 0012159	Local	1
--	-------	---

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

kostenloser Lichttest 2017 Flat rate unit I NL 12 00 0	Local	1 FRU
---	-------	-------

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Fahrzeugüberprüfung im Rahmen der Annahm Flat rate unit I 00 52 054	Local	0 FRU
--	-------	-------

— 03/23/2017 Key 67364 km 00089 Key 0

 24000 01/2019	 0	 24000 679	 0	 60000	 0 10/2017	 11000	 60000 01/2021	 0 10/2017
---	--	---	--	--	---	--	--	---

— 03/23/2017 Repair 65361 km 00089 Niederlassung Nürnberg BMW AG, Nürnberg Job Job Job Job Job

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

BMW Kompakt-Check zum Radwechsel	Local	1 FRU
Flat rate unit I AZ00 00 0		

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Winterräder abbauen, Sommerräder auslage	Local	6 FRU
Flat rate unit I AZ36 00 3		

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Einlagerung Winterräder Einlagerungs-Nr.	Local	1
Part I 36001		

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

— Job


Description:

Is interpreted as a repeat visit: No

Customer's own words:

kostenlose Fahrzeugoberwäsche	Local	1
Part I 0011319		

—	02/13/2017	Key	65361 km	22134	Key 0
---	------------	-----	----------	-------	-------



—	02/13/2017	Repair	65361 km	22134	Job
				Niederlassung	Job
				Nürnberg	Job
				Filiale	Job
				Fischbach	Job
				BMW AG,	Job
				Nürnberg	Job

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Fahrzeugüberprüfung im Rahmen der Annahm Flat rate unit I 00 52 054	Local	0 FRU
--	-------	-------

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Checking and replacing the air conditioning condenser Flat rate unit I 00 64 293		17 FRU
---	--	--------

Condenser air conditioning Part I 64 50 9 391 489		1
--	--	---

Gasket ring Part I 64 50 8 375 741		1
---------------------------------------	--	---

Gasket ring Part I 64 50 8 374 959		1
---------------------------------------	--	---

Hex bolt Part I 07 14 7 029 829		2
------------------------------------	--	---

Refrigerant Part I 83 19 0 143 177		12
---------------------------------------	--	----

PAG oil Denso ND8 Part I 83 19 2 199 567		10
---	--	----

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Verkleidung Unterboden links ersetzen Flat rate unit I AZ41 99 0	Local	3 FRU
---	-------	-------

Removing and installing/replacing left or right door sill trim panel Flat rate unit I 51 71 447		8 FRU
--	--	-------

Remove and install/replace left or right side sill trim panel Flat rate unit I 51 71 947		6 FRU
---	--	-------

Painting left or right door sill trim panel Flat rate unit I 99 64 521		8 FRU
---	--	-------

Painting left or right door sill trim panel Flat rate unit I 99 64 021		23 FRU
---	--	--------

Door sill cover, primed left Part I 51 77 7 262 663		1
--	--	---

Underbody paneling, left Part I 51 75 7 207 267		1
--	--	---

Door sill cover, primed right Part I 51 77 7 262 664		1
---	--	---

Support lifting platform		1
--------------------------	--	---

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words: Tür mit Lackstift ausbessernSeitenwand HR polieren,

Delle an Tür VR drücken Flat rate unit I AZ09 95 4	Local	6 FRU
---	-------	-------

Stripping and refitting work for painting the front left or right door Flat rate unit I 51 18 750		5 FRU
--	--	-------

Painting the front door, left or right Flat rate unit I 99 51 558		34 FRU
--	--	--------

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

— Job


Description:

Is interpreted as a repeat visit: No


Customer's own words:

Lackmaterial Part I 99 99 9 999 990	Local	291
--	-------	-----

— 01/05/2017 Key 60801 km 22134 Key 0



— 01/05/2017 Service 60801 km 22134 Automatic
Niederlassung
Nürnberg
Filiale
Fischbach,
Nürnberg



— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Fuel filter service Flat rate unit I 00 00 604	5 FRU
Fuel filter cartridge Part I 13 32 7 811 227	1
Hose clamp Part I 16 12 1 180 240	1

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Service - microfilter Flat rate unit I 00 00 616	3 FRU
Set, microfilter/activ. charcoal filter Part I 64 11 9 272 642	1
Pollen filter housing cleaner Part I 83 19 2 180 509	0

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words: Scheibe VA soll 22,4mm ist 22,1mm,

Service - front brakes Flat rate unit I 00 00 612	7 FRU
Removing and installing/replacing both front brake discs Flat rate unit I 34 11 613	3 FRU
Repair kit, brake pads asbestos-free Part I 34 11 6 858 047	1
Brake pad wear sensor, front left Part I 34 35 6 791 958	1
Brake pad paste Part I 83 19 2 158 851	2
Clip Part I 34 11 6 798 879	2
Inner hex bolt Part I 34 21 1 161 806	2
Clip retainer Part I 34 35 6 787 325	1
Brake disc, lightweight, ventilated Part I 34 11 6 794 429	1

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Motorölservice - zusätzliche AW Flat rate unit I IM00 25 0	Local	2 FRU
---	-------	-------

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words: Kühlsystem auf Wasserdichtheit prüfen - Kühlmittel ergänzen -> kein,Verlust feststellbar,

Check the cooling system for watertightness with the special tool Flat rate unit I 17 00 509		2 FRU
---	--	-------

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Diesel exhaust fluid AdBlue Part I 83 19 2 288 328		90
---	--	----

Windshield Washer Antifreeze Part I 83 12 2 413 061		1
--	--	---

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words: Service Fahrzeug-Check Reifenluftdruck richtig stellen,

Vehicle check service
Flat rate unit I 00 00 624

7 FRU

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Fahrzeugüberprüfung im Rahmen der Annahm
Flat rate unit I 00 52 054

Local

0 FRU

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Nebelscheinwerfer einstellen
Flat rate unit I AZ63 00 0

Local

3 FRU

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Befund: Kühlmittel ergänzen -> kein Verl
Part I 0011322

Local









1

— 11/22/2016 Key

54562 km

00089

Key 0



5000

5000

5000

5000

5000

0

20000

5000

0

11/2017

373

373

373

10/2017

11/2017

10/2017

— 11/22/2016 Repair

54566 km

00089
Niederlassung
Nürnberg
BMW AG,
Nürnberg

Job
Job
Job
Job

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words: Abrechnung über GutscheinNr.: 815313026041,

12-Punkte Fahrzeug Check

Local

10 FRU

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Replacing exhaust-gas recirculation cooler 16 FRU
Flat rate unit | 00 64 199

Ersatzfahrzeug 1 Tag Local 1
Part | 0000160

exhaust cooler 1
Part | 11 71 8 596 444

Set of small parts 1
Part | 11 71 8 597 652

Pipe union 2
Part | 11 71 7 799 853

Oval head screw 2
Part | 35 21 7 685 343

Anti-freeze 4
Part | 83 19 2 211 358

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Fahrzeugüberprüfung im Rahmen der Annahm Local 0 FRU
Flat rate unit | 00 52 054

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

kostenlose Fahrzeugoberwäsche Local 1
Part | 0011319

— 11/10/2016 Key 53832 km 00089 Key 0


6000
11/2017


6000
384


6000
384


6000
384


5000
10/2017


0
10/2017


21000
11/2017


6000
11/2017


0
10/2017

— 10/12/2016 Repair 53221 km 22134 Job
Niederlassung Job
Nürnberg Job
Filiale Job
Fischbach

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Sommerräder abbauen, Winterräder auslage
Flat rate unit I AZ36 00 2

Local 6 FRU

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Fast service and service ticket with compact check or service
consultation
Flat rate unit I 00 52 051

0 FRU

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Einlagerung Sommerräder Einlagerungsnumm
Part I 36001

Local 1

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

— 08/04/2016 Key 50613 km 00089 Key 0

								
10000	10000	10000	10000	8000	0	25000	10000	0
11/2017	483	483	483		10/2017		11/2017	10/2017

— 08/04/2016 Repair 50613 km 00089 Job
Niederlassung Job
Nürnberg Job
BMW AG, Job
Nürnberg

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words: einen Reifen mit Runflat ab- und anbauen,(zum Ersetzen des Ventils),

einen Reifen mit Runflat ab- und anbauen
Flat rate unit I AZ36 11 1

Local

9 FRU

Screw-in valve RDC
Part I 36 14 6 792 829

1

Balance weight, zinc, w. adhesive foil
Part I 36 11 6 766 336

1

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Service consultation at the vehicle
Flat rate unit I 00 52 050

0 FRU

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Windshield Washer Antifreeze
Part I 83 12 2 298 528










1

— 04/06/2016 Key

45536 km

22134

Key 0



— 04/01/2016 Repair

45536 km

22134
Niederlassung
Nürnberg
Filiale
Fischbach
BMW AG,
Nürnberg

Job
Job
Job
Job

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Winterräder abbauen, Sommerräder auslage
Flat rate unit I AZ36 00 3

Local

6 FRU

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Fast service and service ticket with compact check or service
consultation
Flat rate unit I 00 52 051

0 FRU

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Einlagerung Winterräder Einlagerungsnumm
Part I 36001

Local

1

— Job

Description:

Is interpreted as a repeat visit: No








Customer's own words:

— 11/13/2015 Key

28667 km

22134

Key 0



-40
10/2016

0

-40
373

0

23000

0
10/2017

38000

27000
10/2018

0
10/2017

— 11/13/2015 Service

28667 km

22134

Manual

Niederlassung
Nürnberg,
Nürnberg



— 11/13/2015 Repair

28714 km

22134

Job

Niederlassung

Job

Nürnberg

Job

Filiale

Job

Fischbach

Job

BMW AG,

Job

Nürnberg

Job

Job

Job

Job

Job

Job

— Job

Description:**Is interpreted as a repeat visit:** No**Customer's own words:**

Engine oil service Flat rate unit I 00 00 610	3 FRU
--	-------

Set oil-filter element Part I 11 42 8 575 211	1
--	---

BMW Engine Oil LL04 5W30 Part I 83 21 2 405 948	5
--	---

— Job**Description:****Is interpreted as a repeat visit:** No**Customer's own words:**

Service - microfilter Flat rate unit I 00 00 616	3 FRU
---	-------

Set, microfilter/activ. charcoal filter Part I 64 11 9 272 642	1
---	---

Pollen filter housing cleaner Part I 83 19 2 180 509	0
---	---

— Job**Description:****Is interpreted as a repeat visit:** No**Customer's own words:**

Standard scope of service Flat rate unit I 00 00 105	2 FRU
---	-------

— Job**Description:****Is interpreted as a repeat visit:** No**Customer's own words:** technische Aktion00000000005 AW,

Program and code control units Flat rate unit I 00 62 227	10 FRU
--	--------

— Job**Description:****Is interpreted as a repeat visit:** No**Customer's own words:**

Premium Selection Durchsicht Flat rate unit I AZ00 01 0	Local	19 FRU
--	-------	--------

Supporting the voltage of the vehicle electrical system/recharging the vehicle electrical system battery Flat rate unit I 61 21 528	1 FRU
--	-------

Windshield Washer Antifreeze
Part I 83 12 2 298 528

2

Music adapter Apple iPod / iPhone
Part I 61 12 2 338 491

1

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words: Neue Winterräder vom Teiledienst montieren,Alu 18",Reifengarantie Continental Conti Winter Contact TS830P SSR 245 45 R18,RSC M+S Dot LM84 D2P5 3815,

Neue Winterräder vom Teiledienst montier
Flat rate unit I AZ36 02 0

Local

6 FRU

Wheel & tire, winter,light alloy RDC LC
Part I 36 11 2 412 374

1

Wheel & tire, winter,light alloy RDC LC
Part I 36 11 2 412 374

1

Wheel & tire, winter,light alloy RDC LC
Part I 36 11 2 412 374

1

Wheel & tire, winter,light alloy RDC LC
Part I 36 11 2 412 374

1

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Einlagerung Sommerräder 9453651
Part I 36001

Local

1

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Nachrüstung Service-Inclusive 10 Jahre/2
Part I 5100102

Local

1

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

BMW Key ring, 5-Series
Part I 80 27 2 287 779

1

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words: Fahrzeugüberprüfung im Rahmen der Annahme,Verkäufer H.Dienstl2 Schlüssel1 FFB-SH705636Standplatz außen vor U,

Vehicle check in frame of acceptance
Flat rate unit I 00 52 054

0 FRU

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Additional work, topping up AdBlue
Flat rate unit I 00 00 667

3 FRU

Diesel exhaust fluid AdBlue
Part I 83 19 2 288 328

550

—	10/28/2015	Repair	28561 km	22134	Job
				Niederlassung	Job
				Nürnberg	Job
				Filiale	
				Fischbach	
				BMW AG,	
				Nürnberg	

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Felge VL smart repair
Flat rate unit I AZ09 97 1

Local

10 FRU

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Delle Seitenwand HL drücken
Flat rate unit I AZ09 95 4

Local

6 FRU

Painting bumper cover, rear
Flat rate unit I 99 69 029

62 FRU

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

—	08/14/2015	Key	28653 km	25742	Key 0				
									
-30	0	-30	0	24000	0	38000	27000		0
10/2016		444			10/2017		10/2018		10/2017
—	06/26/2015	Key	23900 km	00027	Key 0				
									
6000	0	6000	0	28000	0	40000	35000		0
10/2016		493			10/2017		10/2018		10/2017
—	05/22/2015	Key	22988 km	00027	Key 0				
									
7000	0	7000	0	29000	0	41000	37000		0
10/2016		528			10/2017		10/2018		10/2017
—	05/12/2015	Key	22141 km	00027	Key 0				
									
7000	0	7000	0	29000	0	41000	37000		0
10/2016		538			10/2017		10/2018		10/2017
—	05/12/2015	Key	22140 km	00027	Key 0				
									
8000	0	8000	0	29000	0	41000	38000		0
10/2016		538			10/2017		10/2018		10/2017
—	05/12/2015	Repair	22140 km	00027	Job				
				Niederlassung	Job				
				Düsseldorf	Job				
				BMW AG,					
				Düsseldorf					

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words: SR bei Wareingang angel.WR zurück zum Wareneingang,

Depotservice Rädermontage
Flat rate unit I AZ36 00 2

Local

6 FRU

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words: AdBlue 3-4 l auffüllen,

Sichtkontrolle Flüssigkeiten nachfüllen Flat rate unit I AZ00 00 0	Local	2 FRU
Diesel exhaust fluid AdBlue Part I 83 19 2 289 602		40

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

kostenlose Fahrzeugoberwäsche Part I 0011319	Local	1
---	-------	---

— 05/11/2015 Key 22134 km 00027 Key 0

 8000 10/2016	 0	 8000 542	 0	 29000	 0 10/2017	 41000	 38000 10/2018	 0 10/2017
--	--	--	--	--	---	--	--	---