

Vehicle

BMW 318d, 110kW

WBA8H71080A727171



Development code	F31
Color	glacier-silber metallic
Actual integration level	F020-19-07-539
Start of warranty	May 9, 2018

▼ Technical Campaigns

There are no campaigns available.

▼ Special information

There are no campaigns available.

▼ Live Diagnosis

⚠ An error has occurred. Please try again later.

▼ Service contracts

No BSI contracts available

You can find additional service contract information and selection options in the DCSNet warranty vehicle enquiry.

▼ Information on faults, workshop/Service Consultation

No information on faults is available.

▼ Navigation map

Note: The installed map cannot be identified. One of the following maps could be installed in the vehicle.

Installed map	Enabling code (subscription)	Latest navigation map included in subscription	Latest navigation map subject to charge
Road Map EUROPE EVO 2018-1 (as of: Nov 7, 2022)	Release code valid for navigation maps with release date up to Dec 31, 2099 (SWID: 01200FFF).	Road Map EUROPE EVO 2025-2	-
Road Map EUROPE EVO 2018-1 (as of: Nov 7, 2022)	-	-	-

▾ Vehicle details

Vehicle type	Passenger car
Brand	BMW
Model	318d
Body	TOUR
Vehicle identification number (last 7 characters)	A727171
Vehicle identification number (17 characters)	WBA8H71080A727171
Development code	F31
Steering	LL
Engine	B47U
Engine number	52105316
Exhaust re-treatment	Euro 6 AD
Transmission	AUT
Transmission number	1595258W7N
Head unit serial number	HB2241J8253923
Drive	HECK
Integration level	F020-18-03-520
Production date	Apr 11, 2018
Production works	Muenchen
Delivery date	Apr 17, 2018
Delivering Retailers	ahg Autohandelsgesellschaft, Horb/Neckar, DE
National-market version	EUR
Paint code	A83
Upholstery code	CCL2
Model code	8H81
Base type	8H71
Lead type	8H81

▾ Optional equipment

Optional equipment fitted at the factory:

0164 Emissions standard EU6
01CA Selection of COP relevant vehicles
01CB CO2 package
0205 Automatic transmission
0216 Hydro steering-servotronic

Retrofitted optional equipment:


This vehicle has no retrofits.

0230 EU-specific additional contents
 0258 Tire with run-flat functionality
 02A6 BMW LA wheel, Double Spoke 392
 02PA Wheel bolt retainer
 02VB Tire pressure display
 02XE Sport leather steering wheel
 0302 Alarm system
 0320 Deleted, model lettering
 0322 Comfort Access
 03AT Roof rail, aluminum, satin finish
 0420 Sun protection glazing
 0423 Floor mats, velours
 0428 Warning triangle and first aid kit
 0430 Interior/outside mirror with auto dip
 0431 Interior mirror with automatic-dip
 0481 Sports seat
 0488 Lumbar support, driver and passenger
 0493 Storage compartment package
 0494 Seat heating driver/passenger
 04AE Armrest front, retractable
 04FU Fine wood 'Fineline' anthracite/accent
 0508 Park Distance Control (PDC)
 0521 Rain sensor
 0534 Automatic air conditioning
 0544 Cruise control with braking function
 0548 Kilometer-calibrated speedometer
 0563 Lights package
 05A1 LED Fog lights
 05A2 LED headlight
 05DA Passenger airbag deactivation
 05DC Rear-seat headrests, folding
 0609 Navigation system Professional
 0654 DAB tuner
 0676 HiFi speaker system
 0698 Area-Code 2 for DVD
 06AC Intelligent emergency SOS call
 06AE Teleservices
 06AK Connected Drive Services
 06AM Real-Time Traffic Information
 06AN Concierge Services
 06AP Remote Services
 06NW Phoning with wireless charging
 06WB Multifunctional instrument display
 06WD WLAN Hotspot
 07AC Sport Line
 07LD Modell Sport Line
 0801 German version
 0851 Language version German
 0879 On-board vehicle literature German
 08KA Oil service interval, 24 mos./30,000 km
 08R9 Refrigerant R1234yf
 09AA Outer skin protection
 09BM Navigation package, Connected Drive
 A090 90 AH AGM battery
 POLS Cloth cushion


▸ Software version control units

▾ Vehicle histories


	Date	Type	Vehicle mileage	Dealer	Overview
—	11/07/2022	Key	178573 km	00131	Key 0



28000
09/2024




28000
09/2024




60000



05/2023



26000



60000
09/2026



05/2023

—

11/07/2022 Repair

178573 km

00131
Autohaus Karl
+ Co. GmbH &
Co. KG, Mainz

Job
Job

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Replace exhaust-gas recirculation cooler, including exhaust-gas recirculation valve 25 FRU
Flat rate unit I 00 72 349

Performing additional work for pressure sensor functional check 3 FRU
Flat rate unit I 00 72 939

Additional work: enter component identification of new exhaust-gas recirculation cooler in diagnostic system 1 FRU
Flat rate unit I 00 72 940

Additional work: clean exhaust-gas recirculation pipe (do not use when replacing intake system) 2 FRU
Flat rate unit I 00 72 941

Exhaust gas cooler high temperature 1
Part I 11 71 7 822 347

Anti-freeze 3
Part I 83 19 2 218 348

AGR small parts set 1
Part I 11 71 8 490 640

Vacuum hose black 0.5
Part I 11 65 8 595 650

Pipe union 2
Part I 11 71 7 799 853

Holder 1
Part I 61 13 1 369 832

Connection piece 1
Part I 11 65 7 803 012

O-ring 1
Part I 11 61 8 512 681

Hex bolt 4
Part I 07 14 7 029 829

Acoustic cover front 1
Part I 11 14 8 490 577

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Ersatzfahrzeug FD-MZ 31 0 00115306001
Flat rate unit I 99 99 999

Local

1 FRU

— 09/29/2022 Key 175009 km 30639 Remote KeyRead

								
4400	4400	4400	4400	60000	31000	4400		\$
05/2023	05/2023	05/2023	05/2023			05/2023		05/2023

— 04/09/2022 Key 157779 km 30639 Key 0

								
22000	22000	22000	22000	80000	46000	22000		\$
05/2023	382	382	382			05/2023		05/2023

— 04/09/2022 Repair 157779 km 30639 Job
Cloppenburg
GmbH , Alzey

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Carrying out vehicle test 4 FRU
Flat rate unit I 00 00 006Supporting the voltage of the vehicle electrical system/recharging the
vehicle electrical system battery 1 FRU
Flat rate unit I 61 21 528Identifying cause of customer complaint without diagnostic system 3 FRU
Flat rate unit I 00 12 351Replacing oxygen sensor monitor 4 FRU
Flat rate unit I 13 62 664Oxygen sensor 1
Part I 13 62 8 573 155

— 02/21/2022 Key 153972 km 30639 Key 0

								
25000	25000	25000	25000	90000	50000	25000		\$
05/2023	430	430	430			05/2023		05/2023

— 11/24/2021 Key 149923 km Key 0

								
28000	28000	28000	28000	100000	05/2023	60000	28000	05/2023
05/2023	517	517	517				05/2023	

— 11/23/2021 Key 149832 km Key 0

								
28000	28000	28000	28000	100000	05/2023	60000	28000	05/2023
05/2023	518	518	518				05/2023	

— 11/19/2021 Repair 149500 km 00250 ahg Job
 Autohandelsgesellschaft Job
 mbH , Horb/Neckar Job
 Job

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

GW Auslieferung W.O.L.K.E inkl. eigene Aufbereitung	Local	21 FRU
Flat rate unit I 98 04 066		

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Statutory emission test		4 FRU
Flat rate unit I 00 00 440		

(Mandatory) general inspection		0 FRU
Flat rate unit I 00 12 559		

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

neuer Radsatz aufstecken	Local	4 FRU
Flat rate unit I 98 36 004		

gebr.WRads. VSp415 225/50R17 97H 1642695	Local	1
Part I VSFT3737		

Wheel bolt black		3
Part I 36 13 6 890 324		

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

AU-Siegel 00000000	Local	1 FRU
Flat rate unit I 99 99 999		
HU Intern 00000000	Local	1 FRU
Flat rate unit I 99 99 999		

— 11/15/2021 Key 149500 km Key 0

									
28000	28000	28000	28000	110000	05/2023	60000	28000		
05/2023	529	529	529				05/2023		05/2023

— 09/17/2021 Key 149391 km Key 0

									
28000	28000	28000	28000	110000	05/2023	70000	28000		
05/2023	584	584	584				05/2023		05/2023

— 06/10/2021 Key 149300 km Key 1

									
28000	28000	28000	28000	110000	0	70000	28000		
05/2023	729	729	729		05/2023		05/2023		05/2023

— 06/10/2021 Repair 149300 km 00250 ahg Job
Autohandelsgesellschaft Job
mbH , Horb/Neckar Job
Job

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Paket 5 Hereinnahmecheck GW Fahrzeugdurchsicht	Local	6 FRU
Flat rate unit I 00 00 074		

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Work time without specification/body equipment	14 FRU
Flat rate unit I 51 99 000	
Fitting/replacing foot mats	1 FRU
Flat rate unit I 51 47 970	
Floor mat velours driver side	1
Part I 51 47 7 332 091	

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Work time without specification/rear axle
Flat rate unit I 33 99 000

10 FRU

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Work time without specification/body equipment
Flat rate unit I 51 99 000

2 FRU

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Hereinnahmeaufbereitung Gebrauchtwagen - 00000000
Flat rate unit I 99 99 999

Local

1 FRU

— 05/25/2021 Key

148490 km

Key 0



— 05/25/2021 Service

148490 km

35658
Autohaus Fink
GmbH & Co.
KG, Kempten


Manual



— 05/03/2021 Key

146312 km

Key 0



— 02/04/2021 Key

140233 km

Key 0

								
10000		10000		1500	04/2021	80000	41000	
08/2022		537					1257	

— 02/04/2021 Service 140233 km 35658 Automatic
 Autohaus Fink GmbH&Co. KG , Kempten

								
10000	0	10000	0	1500	0	80000	41000	
				✓				

— 02/04/2021 Repair 140233 km 35658 Job
 Autohaus Fink GmbH & Co. KG , Kempten

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Removing and installing/replacing both front brake discs 3 FRU
 Flat rate unit I 34 11 613

Service Standardumfang
 Package I 0000105

Service Bremse vorn
 Package I 0000612

Beide Bremsscheiben vorn aus- und einbauen/ersetzen
 Package I 3411613

Package I MM01AUFTRAGSERTEIL*BM6X61 Local

Package I MM02DESINFEKTION*BM6X61 Local

Package I MM02FZG-WÄSCHEO.B*BM6X61 Local

— 02/01/2021 Key 139568 km Key 0

								
11000		11000		1800	04/2021	80000	42000	
08/2022		540					1260	

— 11/11/2020 Key 130908 km Key 0

								
22000	0	22000	0	7000	0	100000	50000	
08/2022		658			04/2021		1389	

—	11/09/2020	Key	130794 km	35658	Key 0		
 22000 08/2022	 0	 22000 659	 0	 7000	 0 04/2021	 100000	 50000 1390
—	08/24/2020	Key	121637 km	35658	Key 0		
 1300 12/2021	 1300 494	 1300 494	 1300 494	 7000	 0 04/2021	 110000	 1300 12/2021
—	08/24/2020	Service	121637 km	35658 Fink GmbH u. Co.KG, Kempten	Automatic		
 1300 12/2021 ✓	 1300 12/2021 ✓	 1300 12/2021 ✓	 1300 12/2021 ✓	 7000	 0 04/2021	 110000	 1300 12/2021 ✓
—	08/24/2020	Repair	121637 km	35658 Autohaus Fink GmbH & Co. KG , Kempten	Job: Service Fahrzeug-Check Job: Service Motoröl Job: Service Kraftstofffilter Job: Service Luftfiltereinsatz Job: Service Mikrofilter Job Job Job: Replace left and right wiper blade Job: Replacing the wiper blade for the rear wiper Job		

— Job: Service Fahrzeug-Check

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Service Fahrzeug-Check
Package I 000062418H810

Vehicle check service
Flat rate unit I 00 00 624

6

— Job: Service Motoröl

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Service Motoröl
Package I 000061018H810

Engine oil service	3
Flat rate unit I 00 00 610	
Set oil-filter element	1
Part I 11428575211	
BMW Engine Oil LL04 0W30	5
Part I 83212405950	

— Job: Service Kraftstofffilter

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Service Kraftstofffilter

Package I 000060418H810

Fuel filter service	3
Flat rate unit I 00 00 604	
Fuel filter cartridge	1
Part I 13328572522	

— Job: Service Luftfiltereinsatz

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Service Luftfiltereinsatz

Package I 000060218H810

Service - air filter insert	2
Flat rate unit I 00 00 602	
Air filter element	1
Part I 13718511668	

— Job: Service Mikrofilter

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Service Mikrofilter

Package I 000061618H810

Service - microfilter	2
Flat rate unit I 00 00 616	
Microfilter/activated Carbon container	1
Part I 64119237555	

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

!!! unknown BMW-Id ESTIMATE Service inklusive !!!

Local

0 FRU

Flat rate unit I -

Standard scope of service
Flat rate unit I 00 00 105

2 FRU

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Package I MM01AUFTRAGSERTEIL*BM8H81

Local

»Auftragserteilung mündlich /
Flat rate unit I 00 00 013

Local

0

— Job: Replace left and right wiper blade

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Replace left and right wiper blade
Package I 6161541

Replace left and right wiper blade
Flat rate unit I 61 61 541

1

Set of wiper blades
Part I 61612241375

1

— Job: Replacing the wiper blade for the rear wiper

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Replacing the wiper blade for the rear wiper
Package I 6162520

Replacing the wiper blade for the rear wiper
Flat rate unit I 61 62 520

1

Wiper blade
Part I 61627356763

1

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Package I MM02DESINFEKTION*BM8H81

Local

Fahrzeugdesinfektion
Flat rate unit I 00 00 096

Local

1

— 05/22/2020 Key

110397 km 35658

Key 0

								
13000	13000	13000	13000	7000		8000		13000
12/2021	549	549	549		04/2021			12/2021

— 05/22/2020 Service 110397 km 35658 Autohaus Fink GmbH & Co. KG, Kempten Manual

										
							✓			

— 12/02/2019 Key 91880 km 35658 Key 0

								
-500	0	-500	0	16000	0	12000	31000	
04/2021		514			04/2021		04/2023	

— 12/02/2019 Service 91880 km 35658 Fink GmbH u. Co.KG, Kempten Automatic

								
-500	0	-500	0	16000	0	12000	31000	
04/2021		04/2021		04/2021			04/2023	
✓		✓						

— 12/02/2019 Repair 91880 km 35658 Autohaus Fink GmbH & Co. KG , Kempten Job: Standard scope of service
Job: Engine oil service
Job: Service - microfilter

— Job: Standard scope of service

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Standard scope of service
Package I 0000105

Standard scope of service
Flat rate unit I 00 00 105

2

— Job: Engine oil service

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Engine oil service

Package I 0000610

Engine oil service	3
Flat rate unit I 00 00 610	
Set oil-filter element	1
Part I 11428575211	
BMW Engine Oil LL04 0W30	5
Part I 83212405950	

— Job: Service - microfilter

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Service - microfilter
Package I 0000616

Service - microfilter	2
Flat rate unit I 00 00 616	
Microfilter/activated Carbon container	1
Part I 64119237555	

— 11/26/2019 Key 90907 km 35658 Key 0

							
430	0	430	0	17000	0	13000	32000
04/2021		520			04/2021		04/2023

— 10/21/2019 Key 87899 km 01443 Key 0

							
3400	0	3400	0	21000	0	17000	34000
04/2021		556			04/2021		04/2023

— 10/21/2019 Repair 87899 km 01443 Job
Autohaus Reisacher GmbH , Memmingen Job

— Job

Description: Reisacher Standard-Check

Is interpreted as a repeat visit: No

Customer's own words:

!!! unknown BMW-Id 0099001 Standardcheck by Reisacher -kostenlos- Local !!! Flat rate unit I 00 99 001	2 FRU
Outside car wash Flat rate unit I 00 11 319	0 FRU
Service consultation at the vehicle	0 FRU

— Job

Description: 2. Scheinwerfer vorne links, wurde selbst eingebaut, bitte programmieren

Is interpreted as a repeat visit: No

Customer's own words:

Performing vehicle test 2 FRU
Flat rate unit I 00 00 556

Program/encode control unit(s), includes deleting the fault memory 4 FRU
Flat rate unit I 61 00 730

— 04/17/2019 Key 60371 km 35658 Key 0

-140	-140	-140	-140	43000	0	39000	-140
10/2020	563	563	563		04/2021		10/2020

— 04/17/2019 Service 60371 km 35658 Manual
Autohaus Fink
GmbH & Co.
KG, Kempten

✓	✓	✓	✓				✓		

— 03/12/2019 Repair 60371 km 35658 Job
Autohaus Fink
GmbH & Co.
KG, Kempten
Job
Job
Job
Job
Job
Job
Job
Job

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Continental SportContact 5 SSR 2
Part I 85 45 2 548 314

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

— Job

Description:

Is interpreted as a repeat visit: No









Customer's own words:

—

11/21/2018 Key

33979 km

Key 0



27000
10/2020

27000
709

27000
709

27000
709

70000

0
04/2021

70000

27000
10/2020

—

11/19/2018 Key

33351 km

Key 0

								
27000	27000	27000	27000	70000	0	70000	70000	27000
10/2020	712	712	712		04/2021			10/2020

— 11/19/2018 Repair 33351 km 35658 Autohaus Fink GmbH & Co. KG, Kempten Job Job

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Winterräder montieren Sommerräder waschen Local 5 FRU
Flat rate unit I 36 00 003

RDCi wheel & tire, winter, light alloy 4
Part I 36 11 2 464 242

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Rädereinlagerung einschl. 17" Local 4 FRU
Flat rate unit I 36 00 005

— 10/31/2018 Key 29265 km Key 0

								
1700	0	1700	0	70000	0	70000	70000	33000
04/2020		546			04/2021			04/2022

— 10/31/2018 Service 29265 km 35658 Autohaus Fink GmbH & Co. KG, Kempten Manual

										
✓		✓								

— 08/06/2018 Key 12998 km 35658 Key 0

								
18000	0	18000	0	60000	0	60000	60000	49000
04/2020		633			04/2021			04/2022

—	08/06/2018	Repair	12998 km	35658 Autohaus Fink GmbH & Co. KG , Kempten	Job Job
---	------------	--------	----------	--	------------

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Fahrzeugverbringung Flat rate unit I -	Local	12 FRU
---	-------	--------

Zeitzuschlag für eine Hauptarbeit Flat rate unit I -	Local	2 FRU
---	-------	-------

Performing vehicle test Flat rate unit I 00 00 556		8 FRU
---	--	-------

Removing and installing the exterior mirror on front left or right door Flat rate unit I 51 16 501		1 FRU
---	--	-------

Removing and installing or replacing cover on left or right outside mirror Flat rate unit I 51 16 541		1 FRU
--	--	-------

Removing and installing/replacing window recess finisher strip on front door, outer Flat rate unit I 51 21 800		2 FRU
---	--	-------

Removing and installing/replacing the window recess finisher strip on the inner front door Flat rate unit I 51 21 829		2 FRU
--	--	-------

Removing and installing or replacing cover on door handle, front left or right Flat rate unit I 51 41 517		1 FRU
--	--	-------

Kleinersatzteile Part I 9999	Local	1
---------------------------------	-------	---

LACKIERUNG Part I FT99999445445	Local	1
------------------------------------	-------	---

Mirror glas, heated, wide-angle, left Part I 51 16 7 285 005		1
---	--	---

Outside mirror cover cap, left, primed Part I 51 16 7 292 745		1
--	--	---

heated outside mirror, left Part I 51 16 7 345 673		1
---	--	---

Channel sealing,outside,door, front left Part I 51 33 7 258 295		1
--	--	---

Seal, outer left mirror triangle Part I 51 33 7 352 231		1
--	--	---


— Job

Description:


Is interpreted as a repeat visit: No

Customer's own words:


— 07/25/2018 Key 11230 km 35658 Key 0



— 07/19/2018 Key 10155 km 35658 Key 0



— 05/08/2018 Service 3 km 00250 AHG Autohandelsges. mbH, Horb/Neckar Manual



— 05/02/2018 Repair 0 km 00250 ahg Autohandelsgesellschaft mbH , Horb/Neckar Job

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Paket 1 Neuwagenaufbereitung Fahrzeugübergabe mit Aufber. tanken + Local Teleservice umst.
Flat rate unit I 00 00 060

40 FRU