

Vehicle

BMW 420d, 140kW

WBA4E91010G598190



Development code	F36
Color	imperial-blau brillant metallic
Actual integration level	F020-22-07-530
Start of warranty	September 21, 2016

▼ Technical Campaigns

There are no campaigns available.

▼ Special information

There are no campaigns available.

▼ Live Diagnosis

 There are no service solutions for Live Diagnosis.

▼ Service contracts

No BSI contracts available

You can find additional service contract information and selection options in the DCSNet warranty vehicle enquiry.

▼ Information on faults, workshop/Service Consultation

No information on faults is available.

▼ Navigation map

Note: The installed map cannot be identified. One of the following maps could be installed in the vehicle.

Installed map	Enabling code (subscription)	Latest navigation map included in subscription	Latest navigation map subject to charge
Road Map EUROPE EVO 2016-2 (as of: Sep 26, 2023)	-	-	-
Road Map EUROPE EVO 2016-2 (as of: Sep 26, 2023)	Release code valid for navigation maps with release date up to Dec 31, 2099 (SWID: 01200FFF).	Road Map EUROPE EVO 2025-2	-

▾ Vehicle details

Vehicle type	Passenger car
Brand	BMW
Model	420d
Body	COUPE
Vehicle identification number (last 7 characters)	G598190
Vehicle identification number (17 characters)	WBA4E91010G598190
Development code	F36
Steering	LL
Engine	B47O
Engine number	77749743
Exhaust re-treatment	EURO6;W;PI/CI; M, N1 I
Transmission	AUT
Transmission number	0255964WC7
Head unit serial number	HB2240G7985527
Drive	HECK
Integration level	F020-16-07-506
Production date	Sep 14, 2016
Production works	Dingolfing
Delivery date	Sep 15, 2016
Delivering Retailers	No information
National-market version	EUR
Paint code	A89
Upholstery code	LCSW
Model code	4E01
Base type	4E91
Lead type	4E01

▾ Optional equipment

Optional equipment fitted at the factory:

01CA Selection of COP relevant vehicles
01CB CO2 package
0230 EU-specific additional contents
02DX BMW LA wheel, Star Spoke 394
02TB Sport automatic transmission

Retrofitted optional equipment:

This vehicle has no retrofits.

02VB Tire pressure display
 0302 Alarm system
 0320 Deleted, model lettering
 03AG Reversing camera
 0423 Floor mats, velours
 0428 Warning triangle and first aid kit
 0431 Interior mirror with automatic-dip
 0481 Sports seat
 0488 Lumbar support, driver and passenger
 0493 Storage compartment package
 0494 Seat heating driver/passenger
 04AE Armrest front, retractable
 04CG Interior strips, "satin-silber" matt
 0502 Headlight cleaning system
 0508 Park Distance Control (PDC)
 0521 Rain sensor
 0522 Xenon Light
 0524 Adaptive Headlights
 0544 Cruise control with braking function
 0548 Kilometer-calibrated speedometer
 0575 Supplementary 12V sockets
 05AC High-beam assistant
 05DA Passenger airbag deactivation
 0609 Navigation system Professional
 0676 HiFi speaker system
 0698 Area-Code 2 for DVD
 06AC Intelligent emergency SOS call
 06AE Teleservices
 06AK Connected Drive Services
 06AM Real-Time Traffic Information
 06AN Concierge Services
 06AP Remote Services
 06NW Phoning with wireless charging
 06WA Instrument cluster, expanded equipment
 06WD WLAN Hotspot
 0710 M leather steering wheel
 07LC Modell Advantage
 07XP Navigation package, Connected Drive
 0801 German version
 0851 Language version German
 0879 On-board vehicle literature German
 08KA Oil service interval, 24 mos./30,000 km
 08R9 Refrigerant R1234yf
 08TH Road sign detection
 09AA Outer skin protection
 A090 90 AH AGM battery
 LEDE Leather trim

▾ Vehicle histories

	Date	Type	Vehicle mileage	Dealer	Overview
—	03/24/2026	Service	193789 km	OSS-60175044 macOIL GmbH, Frankfurt	Automatic
	 03/2028 ✓  03/2028	 03/2028	 03/2028   04/2026   03/2028	  03/2027 	
—	02/14/2025	Repair	179548 km	28454 ,	Job

Job

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

24-hour delivery service1 FRU

Flat rate unit I 00 99 310

— Job

Description:

Is interpreted as a repeat visit: No


Customer's own words:

Reinigung Standard im Wert von 19,00 EURO für unsere KundenLocal2 FRU


kostenlos

Flat rate unit I 01 00 001


—02/13/2025Key179548 km28454Key 0



—09/26/2023Key162190 km00319Key 0



—10/07/2022Key143864 km00319Key 0



—07/16/2020Repair102729 km23470 SpaettJob
GmbH & Co. Job
KG , FreisingJob
Job
Job
Job

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Vehicle check in frame of acceptance0 FRU

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Standard scope of service	2 FRU
Flat rate unit I 00 00 105	

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Service - front brakes	6 FRU
Flat rate unit I 00 00 612	

Repair kit, brake pads asbestos-free	1
Part I 34 10 6 859 181	

Brake pad wear sensor, front left	1
Part I 34 35 6 792 289	

Brake cleaner, acetone-free	1
Part I 83 19 2 413 695	

Brake pad paste	2
Part I 83 19 2 158 851	

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Removing and installing/replacing both front brake discs	3 FRU
Flat rate unit I 34 11 613	

Brake disc, ventilated	2
Part I 34 11 6 792 219	

Inner hex bolt	2
Part I 34 21 1 161 806	

Torx screw with washer	4
Part I 34 10 6 864 424	

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Replace left and right wiper blade	1 FRU
Flat rate unit I 61 61 541	

Set of wiper blades	1
Part I 61 61 2 349 870	

— Job

Description:


Is interpreted as a repeat visit: No

Customer's own words:


Endkontrolle durchgeführt	Local	0 FRU
Flat rate unit I 00 11 800		

SCHEIBENKLAR Ltr.	Local	3.5
Part I FT99 99 0 000 0		

— 07/03/2020 Key 102724 km 23470 Key 0



— 07/03/2020 Service 102724 km 23470 Spaett GmbH&Co. KG , Freising Automatic



— 07/03/2020 Repair 102729 km 23470 Spaett GmbH & Co. KG , Freising Job
Job
Job
Job
Job
Job

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Vehicle check in frame of acceptance	0 FRU
Flat rate unit I 00 52 054	

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Standard scope of service	2 FRU
---------------------------	-------

— Job

Description:**Is interpreted as a repeat visit:** No**Customer's own words:**

Service - front brakes	6 FRU
------------------------	-------

Flat rate unit I 00 00 612

Repair kit, brake pads asbestos-free	1
--------------------------------------	---

Part I 34 10 6 859 181

Brake pad wear sensor, front left	1
-----------------------------------	---

Part I 34 35 6 792 289

Brake cleaner, acetone-free	1
-----------------------------	---

Part I 83 19 2 413 695

Brake pad paste	2
-----------------	---

Part I 83 19 2 158 851

— Job

Description:**Is interpreted as a repeat visit:** No**Customer's own words:**

Removing and installing/replacing both front brake discs	3 FRU
--	-------

Flat rate unit I 34 11 613

Brake disc, ventilated	2
------------------------	---

Part I 34 11 6 792 219

Inner hex bolt	2
----------------	---

Part I 34 21 1 161 806

Torx screw with washer	4
------------------------	---

Part I 34 10 6 864 424

— Job

Description:**Is interpreted as a repeat visit:** No**Customer's own words:**

Replace left and right wiper blade	1 FRU
------------------------------------	-------

Flat rate unit I 61 61 541

Set of wiper blades	1
---------------------	---

Part I 61 61 2 349 870

— Job

Description:**Is interpreted as a repeat visit:** No**Customer's own words:**

Endkontrolle durchgeführt	Local	0 FRU
---------------------------	-------	-------

Flat rate unit I 00 11 800

—	07/03/2020	Repair	102729 km	23470 Spaett GmbH & Co. KG , Freising	Job Job Job Job Job Job	
---	------------	--------	-----------	---	--	--

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Vehicle check in frame of acceptance Flat rate unit I 00 52 054	0 FRU
--	-------

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Standard scope of service Flat rate unit I 00 00 105	-2 FRU
---	--------

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Service - front brakes Flat rate unit I 00 00 612	-6 FRU
--	--------

Repair kit, brake pads asbestos-free Part I 34 10 6 859 181	-1
--	----

Brake pad wear sensor, front left Part I 34 35 6 792 289	-1
---	----

Brake cleaner, acetone-free Part I 83 19 2 413 695	-1
---	----

Brake pad paste Part I 83 19 2 158 851	-2
---	----

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Removing and installing/replacing both front brake discs Flat rate unit I 34 11 613	-3 FRU
--	--------

Brake disc, ventilated	-2
------------------------	----

Inner hex bolt
Part I 34 21 1 161 806 -2

Torx screw with washer
Part I 34 10 6 864 424 -4

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Replace left and right wiper blade
Flat rate unit I 61 61 541 -1 FRU

Set of wiper blades
Part I 61 61 2 349 870 -1

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Endkontrolle durchgeführt
Flat rate unit I 00 11 800 Local 0 FRU

SCHEIBENKLAR Ltr.
Part I FT99 99 0 000 0 Local -3.5

— 02/03/2020 Key 92304 km 23470 Key 0

 29000 01/2022	 29000 688	 29000 688	 29000 688	 28000 10/2021	 26000 10/2021	 29000 01/2022	 29000 10/2021
---	---	---	---	---	---	---	--

— 01/09/2020 Key 91035 km 23470 Key 0

 -220 10/2020	 0 10/2020	 -220 296	 0 10/2021	 30000 10/2021	 28000 10/2021	 30000 10/2022	 0 10/2021
--	---	--	---	---	---	---	--

— 01/09/2020 Service 91035 km 23470 Spaett Automatic
GmbH&Co. KG , Freising

 -220 10/2020 ✓	 0 10/2020	 -220 10/2020 ✓	 0 10/2021	 30000 10/2021	 28000 10/2021	 30000 10/2022	 0 10/2021
---	---	---	---	---	---	---	--

— 01/09/2020 Repair 91035 km 23470 Spaett Job
GmbH & Co. KG , Freising Job
Job

	Job
	Job
	Job
	Job
	Job
	Job
	Job

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Vehicle check in frame of acceptance	0 FRU
Flat rate unit I 00 52 054	

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Standard scope of service	2 FRU
Flat rate unit I 00 00 105	

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Service - microfilter	2 FRU
Flat rate unit I 00 00 616	

Microfilter/activated Carbon container	1
Part I 64 11 9 237 555	

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Engine oil service	3 FRU
Flat rate unit I 00 00 610	

MOTOROEL LL04 5W - 30	Local	5
Part I FT99990000003		

Set oil-filter element	1
Part I 11 42 8 575 211	

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

—	11/01/2019	Repair	85723 km	26842 BMW Mobiler Service Einsatzleitzentrale , München	Job
---	------------	--------	----------	--	-----

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

—	11/01/2019	Repair	1 km	26842 BMW Mobiler Service Einsatzleitzentrale , München	Job
---	------------	--------	------	--	-----

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

—	10/02/2019	Key	83213 km	23470	Key 0			
								
8000	0	8000	0	36000	0	35000	39000	0
10/2020		395			-2 0.3 %		10/2022	-2 0.3 %

—	10/02/2019	Service	83213 km	23470 Spaett GmbH &C o. KG , Freising	Automatic			
								
8000	0	8000	0	36000	0	35000	39000	0
10/2020		10/2020			09/2019		10/2022	09/2019
					✓			✓

—	10/02/2019	Repair	83213 km	23470 Spaett GmbH & Co. KG , Freising	Job Job Job Job Job Job Job Job Job Job
---	------------	--------	----------	---------------------------------------	--

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Vehicle check in frame of acceptance Flat rate unit I 00 52 054	0 FRU
--	-------

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Standard scope of service Flat rate unit I 00 00 105	2 FRU
---	-------

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Brake fluid service	4 FRU
---------------------	-------

Flat rate unit I 00 00 618

BREMSFLUESSIGKEIT Ltr.
Part I FT9999000009

Local

1

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Hauptuntersuchung nach§29 inkl AU
Part I FT0000190

Local

1

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Replacing left fog light
Flat rate unit I 63 17 571

4 FRU

Fog lights, left
Part I 63 17 7 248 911

1

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Adjusting fog lights
Flat rate unit I 63 10 514

2 FRU

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Work time without specification/body equipment
Flat rate unit I 51 99 000

4 FRU

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Removing and installing/replacing Bowden cable for bonnet locks, front
Flat rate unit I 51 23 711

3 FRU

Bowden cable, hood, front
Part I 51 23 7 411 315

1

Pipe clip
Part I 17 12 7 609 160

2

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Endkontrolle durchgeführt
Flat rate unit I 00 11 800

Local

0 FRU

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

— 06/03/2019 Repair 77168 km 09031 Job
Niederlassung
München
Airportservice
BMW AG,
München-
Flughafen

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Fahrzeugüberprüfung im Rahmen der Annahm
Flat rate unit I 00 52 054

Local

0 FRU

Ersatzfahrzeug, 1 Tag, Kundenwunsch. 17.
Part I 0000158

Local

1

— 05/17/2019 Key 77168 km 09031 Key 0


14000
10/2020


0
09/2019


14000
533


0
09/2019


41000
09/2019


0
09/2019


41000
10/2022


43000
10/2022


0
09/2019

— 05/17/2019 Repair 77168 km 09031 Job
Niederlassung Job
München Job
Airportservice Job
BMW AG, Job
München- Job
Flughafen Job
Job

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words: It. Befund Kunde : OT PDC ohne/Fehlfunktion nach Befund und Freigabe,inst. Anfahrschaden Sensor HRA bei SB ersichtlich,Park Distance Control auf Funktion prüfen,Kabel instandsetzen,Befund: Fehlerspeic her ausgelesen hier PDC Sensor hinten Mitte rechts im,FS --> Leitungen und Steckverbindungen It. Testmodul geprüft hier war,die Sensorleitung des Sensors unterbrochen Leitung instandgesetzt,anschieße n FS gelöscht und PDC kontrolliert i.O,

Carrying out vehicle test Flat rate unit I 00 00 006	4 FRU
---	-------

Checking Park Distance Control for function Flat rate unit I 66 20 000	3 FRU
---	-------

Carrying out vehicle diagnosis, ABL Flat rate unit I 61 00 006	1 FRU
---	-------

Supporting the voltage of the vehicle electrical system/recharging the vehicle electrical system battery Flat rate unit I 61 21 528	1 FRU
--	-------

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words: It. befund Kunde: OT Kennzeichenhalter vorne gebrochen ersetzen bei SB,Anfahrschaden ersichtlich,

Kennzeichenhalter vorne ersetzen Flat rate unit I AZ51 99 0	Local	1 FRU
--	-------	-------

Kennzeichenunterlage Part I 99 99 0 000 252	Local	1
--	-------	---

Fillister head self-tapping screw Part I 51 18 1 835 719		4
---	--	---

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words: Befund: Fehlerspeicher ausgelesen dort war Heckklappenkontaktschalter,als Fehler abgelegt Fehler ist 54 mal abgelegt Testmodul abgearbeitet,It Testmodul leitungen zum Heckklappenschloss geprüft i.O,He cklappenschloss ist defekt und muss erneuert werden,DIACODE D5126_00000000_06_001,It. Befund Kunde: OT Öffnung Kofferraum mit Fernbedienung arbeitet,sporadisch nicht von 10 mal geht es 3 mal nicht me

ist nach längerer,Standzeit nach Befund und Freigabe inst,Heckklappenschloss ersetzen,

Troubleshooting in the electrical/electronic system	2 FRU
Flat rate unit I 61 00 009	

Removing and installing/replacing tailgate lock	4 FRU
Flat rate unit I 51 24 605	

Trunk lid lock	1
Part I 51 24 7 269 544	

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Endkontrolle	Local	1 FRU
Flat rate unit I AZ00 45 0		

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Füllstände prüfen und ergänzen	Local	1 FRU
Flat rate unit I AZ00 33 3		

Windshield Washer Antifreeze	2
Part I 83 12 2 413 061	

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Service-Reinigung	Local	1
Part I 11320		

—	11/28/2018	Repair	61376 km	23470 Spaett GmbH & Co. KG , Freising	Job Job Job Job Job Job Job Job Job Job
---	------------	--------	----------	---------------------------------------	--

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Vehicle check in frame of acceptance	0 FRU
--------------------------------------	-------

— Job

Description:**Is interpreted as a repeat visit:** No**Customer's own words:**

Standard scope of service	-2 FRU
Flat rate unit I 00 00 105	

— Job

Description:**Is interpreted as a repeat visit:** No**Customer's own words:**

Engine oil service	-3 FRU
Flat rate unit I 00 00 610	

MOTOROEL 0W-30 Ltr.	Local	-5
Part I FT99 99 0 000 0		

Set oil-filter element	-1
Part I 11 42 8 575 211	

— Job

Description:**Is interpreted as a repeat visit:** No**Customer's own words:**

Fuel filter service	-3 FRU
Flat rate unit I 00 00 604	

Fuel filter cartridge	-1
Part I 13 32 8 572 522	

— Job

Description:**Is interpreted as a repeat visit:** No**Customer's own words:**

Service - air filter insert	-2 FRU
Flat rate unit I 00 00 602	

Air filter element	-1
Part I 13 71 8 511 668	

— Job

Description:**Is interpreted as a repeat visit:** No**Customer's own words:**

Service - microfilter	-2 FRU
Flat rate unit I 00 00 616	

Microfilter/activated Carbon container
Part I 64 11 9 237 555

-1

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Rear brakes service -7 FRU
Flat rate unit I 00 00 614

Repair kit, brake pads asbestos-free -1
Part I 34 21 6 873 093

Brake pad wear sensor, rear -1
Part I 34 35 6 792 292

Brake pad paste -2
Part I 83 19 2 158 851

Brake cleaner, acetone-free -1
Part I 83 19 2 413 695

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Vehicle check service -6 FRU
Flat rate unit I 00 00 624

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Outside car wash and interior vehicle cleaning 0 FRU
Flat rate unit I 00 11 329

— Job

Description:

Is interpreted as a repeat visit: No










Customer's own words:

Endkontrolle durchgeführt Local 0 FRU
Flat rate unit I 00 11 800

— 10/22/2018 Key

61376 km

Key 0



— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Air filter element Part I 13 71 8 511 668	1
--	---

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Microfilter/activated Carbon container Part I 64 11 9 237 555	1
--	---

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Repair kit, brake pads asbestos-free Part I 34 21 6 873 093	1
--	---

Brake pad wear sensor, rear Part I 34 35 6 792 292	1
---	---

Brake pad paste Part I 83 19 2 158 851	2
---	---

Brake cleaner, acetone-free Part I 83 19 2 413 695	1
---	---

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

— Job

Description:
Is interpreted as a repeat visit: No
Customer's own words:

— Job

Description:
Is interpreted as a repeat visit: No
Customer's own words:

— Job

Description:
Is interpreted as a repeat visit: No
Customer's own words:

— Job

Description:
Is interpreted as a repeat visit: No
Customer's own words:

— Job

Description:
Is interpreted as a repeat visit: No
Customer's own words:

— Job

Description:
Is interpreted as a repeat visit: No
Customer's own words:

— Job

Description:
Is interpreted as a repeat visit: No
Customer's own words:

—	10/22/2018	Repair	61376 km	23470 Spaett GmbH & Co. KG , Freising	Job Job Job Job Job Job Job Job Job
---	------------	--------	----------	---------------------------------------	---

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Vehicle check in frame of acceptance
Flat rate unit I 00 52 054

0 FRU

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Standard scope of service
Flat rate unit I 00 00 105

2 FRU

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Engine oil service
Flat rate unit I 00 00 610

3 FRU

MOTOROEL 0W-30 Ltr.
Part I FT99 99 0 000 0

Local

5

Set oil-filter element
Part I 11 42 8 575 211

1

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Fuel filter service
Flat rate unit I 00 00 604

3 FRU

Fuel filter cartridge
Part I 13 32 8 572 522

1

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Service - air filter insert
Flat rate unit I 00 00 602

2 FRU

Air filter element
Part I 13 71 8 511 668

1

— Job

Description:**Is interpreted as a repeat visit:** No**Customer's own words:**

Service - microfilter Flat rate unit I 00 00 616	2 FRU
---	-------

Microfilter/activated Carbon container Part I 64 11 9 237 555	1
--	---

— Job**Description:****Is interpreted as a repeat visit:** No**Customer's own words:**

Rear brakes service Flat rate unit I 00 00 614	7 FRU
---	-------

Repair kit, brake pads asbestos-free Part I 34 21 6 873 093	1
--	---

Brake pad wear sensor, rear Part I 34 35 6 792 292	1
---	---

Brake pad paste Part I 83 19 2 158 851	2
---	---

Brake cleaner, acetone-free Part I 83 19 2 413 695	1
---	---

— Job**Description:****Is interpreted as a repeat visit:** No**Customer's own words:**

Vehicle check service Flat rate unit I 00 00 624	6 FRU
---	-------

— Job**Description:****Is interpreted as a repeat visit:** No**Customer's own words:**

Outside car wash and interior vehicle cleaning Flat rate unit I 00 11 329	0 FRU
--	-------

— Job**Description:****Is interpreted as a repeat visit:** No**Customer's own words:**

Endkontrolle durchgeführt Flat rate unit I 00 11 800	Local	0 FRU
---	-------	-------

—	08/24/2018	Repair	54702 km	23470 Spaett GmbH & Co. KG , Freising	Job Job Job Job Job
---	------------	--------	----------	---------------------------------------	---------------------------------

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Vehicle check in frame of acceptance Flat rate unit I 00 52 054	0 FRU
--	-------

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Standard scope of service Flat rate unit I 00 00 105	-2 FRU
---	--------

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Service - front brakes Flat rate unit I 00 00 612	-6 FRU
--	--------

Repair kit, brake pads asbestos-free Part I 34 10 6 859 181	-1
--	----

Brake pad wear sensor, front left Part I 34 35 6 792 289	-1
---	----

Brake pad paste Part I 83 19 2 158 851	-2
---	----

Brake cleaner, acetone-free Part I 83 19 2 413 695	-1
---	----

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Removing and installing/replacing both front brake discs Flat rate unit I 34 11 613	-3 FRU
--	--------

— Job

Description:
Is interpreted as a repeat visit: No
Customer's own words:

Endkontrolle durchgeführt
Flat rate unit I 00 11 800
Local
0 FRU

—	07/09/2018	Key	54700 km	23470	Key 0				
									
9000	9000	9000	9000	700	0	5000	9000		0
09/2019	448	448	448		09/2019		09/2019		09/2019

—	07/09/2018	Service	54700 km	23470 Spaett GmbH&Co. KG , Freising	Automatic				
									
9000	9000	9000	9000	700	0	5000	9000		0
09/2019	09/2019	09/2019	09/2019		09/2019		09/2019		09/2019
				✓					

—	07/09/2018	Repair	54702 km	23470 Spaett GmbH & Co. KG , Freising	Job Job Job Job Job Job	
---	------------	--------	----------	---------------------------------------	--	--

— Job

Description:
Is interpreted as a repeat visit: No
Customer's own words:

— Job

Description:
Is interpreted as a repeat visit: No
Customer's own words:

— Job

Description:
Is interpreted as a repeat visit: No
Customer's own words:

Repair kit, brake pads asbestos-free Part I 34 10 6 859 181	1
Brake pad wear sensor, front left Part I 34 35 6 792 289	1
Brake pad paste Part I 83 19 2 158 851	2

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

—	07/09/2018	Repair	54702 km	23470 Spaett GmbH & Co. KG , Freising	Job Job Job Job Job
---	------------	--------	----------	---	---------------------------------

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Vehicle check in frame of acceptance	0 FRU
Flat rate unit I 00 52 054	

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Standard scope of service	2 FRU
Flat rate unit I 00 00 105	

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Service - front brakes	6 FRU
Flat rate unit I 00 00 612	

Repair kit, brake pads asbestos-free	1
Part I 34 10 6 859 181	

Brake pad wear sensor, front left Part I 34 35 6 792 289	1
Brake pad paste Part I 83 19 2 158 851	2
Brake cleaner, acetone-free Part I 83 19 2 413 695	1

— Job

Description:
Is interpreted as a repeat visit: No
Customer's own words:

Removing and installing/replacing both front brake discs Flat rate unit I 34 11 613	3 FRU
--	-------

— Job

Description:
Is interpreted as a repeat visit: No
Customer's own words:

Endkontrolle durchgeführt Flat rate unit I 00 11 800	Local	0 FRU
---	-------	-------

—	04/10/2018	Repair	47884 km	26842 BMW Mobiler Service Einsatzleitzentrale , München	Job
---	------------	--------	----------	--	-----

— Job

Description:
Is interpreted as a repeat visit: No
Customer's own words:

—	03/23/2018	Key	47455 km	23470	Key 0
---	------------	-----	----------	-------	-------

								
16000	16000	16000	16000	17000	0	7000	16000	0
09/2019	556	556	556		09/2019		09/2019	09/2019

—	03/23/2018	Repair	47467 km	23470 Spaett GmbH & Co. KG , Freising	Job Job Job Job Job
---	------------	--------	----------	---	---------------------------------

— Job

Description:
Is interpreted as a repeat visit: No
Customer's own words:

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Endkontrolle durchgeführt
Flat rate unit I 00 11 800

Local

0 FRU

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

— Job

Description:

Is interpreted as a repeat visit: No


Customer's own words:

— 03/16/2018 Key


46551 km

23470


Key 0




17000
09/2019




17000
562



17000
562




17000
562




17000




0
09/2019



8000



17000
09/2019



0
09/2019

— 10/25/2017 Repair

32964 km

23470 Spaett
GmbH & Co.
KG , Freising

Job
Job
Job
Job
Job

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Service consultation at the vehicle with service ticket
Flat rate unit I 00 52 052

0 FRU

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Standard scope of service	-2 FRU
Flat rate unit I 00 00 105	

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Engine oil service	-10 FRU
Flat rate unit I 00 00 610	

MOTOROEL 0W-30 Ltr.	Local	-5
Part I FT99 99 0 000 0		

Set oil-filter element	-1
Part I 11 42 8 575 211	

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Service - microfilter	-2 FRU
Flat rate unit I 00 00 616	

Microfilter/activated Carbon container	-1
Part I 64 11 9 237 555	

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Replace left and right wiper blade	-1 FRU
Flat rate unit I 61 61 541	

Set of wiper blades	-1
Part I 61 61 2 349 870	

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Endkontrolle durchgeführt	Local	0 FRU
Flat rate unit I 00 11 800		

—	10/25/2017	Repair	32964 km	23470 Spaett GmbH & Co. KG , Freising	Job Job Job Job Job
---	------------	--------	----------	---------------------------------------	---------------------------------

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Service consultation at the vehicle with service ticket	0 FRU
Flat rate unit I 00 52 052	

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Standard scope of service	2 FRU
Flat rate unit I 00 00 105	

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Engine oil service	3 FRU
Flat rate unit I 00 00 610	

MOTOROEL 0W-30 Ltr.	Local	5
Part I FT99 99 0 000 0		

Set oil-filter element	1
Part I 11 42 8 575 211	

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Service - microfilter	2 FRU
Flat rate unit I 00 00 616	

Microfilter/activated Carbon container	1
Part I 64 11 9 237 555	

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Replace left and right wiper blade	1 FRU
Flat rate unit I 61 61 541	

Set of wiper blades	1
Part I 61 61 2 349 870	

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Endkontrolle durchgeführt
Flat rate unit I 00 11 800

Local

0 FRU

— 10/16/2017 Repair 34694 km 26842 BMW Mobiler Service Einsatzleitzentrale , München Job










— Job

Description:










Is interpreted as a repeat visit: No

Customer's own words:

— 09/21/2017 Key 32964 km 23470 Key 0



— 09/21/2017 Service 32964 km 23470 Spaett GmbH&Co. KG , Freising Automatic



— 09/21/2017 Repair 32964 km 23470 Spaett GmbH & Co. KG , Freising Job
Job
Job
Job
Job
Job
Job

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Service consultation at the vehicle with service ticket
Flat rate unit I 00 52 052

0 FRU

— Job

Description:**Is interpreted as a repeat visit:** No**Customer's own words:**

Standard scope of service	2 FRU
Flat rate unit I 00 00 105	

— Job**Description:****Is interpreted as a repeat visit:** No**Customer's own words:**

Engine oil service	10 FRU
Flat rate unit I 00 00 610	

MOTOROEL 0W-30 Ltr.	Local	5
Part I FT99990000003		

Set oil-filter element	1
Part I 11 42 8 575 211	

— Job**Description:****Is interpreted as a repeat visit:** No**Customer's own words:**

Service - microfilter	2 FRU
Flat rate unit I 00 00 616	

Microfilter/activated Carbon container	1
Part I 64 11 9 237 555	

— Job**Description:****Is interpreted as a repeat visit:** No**Customer's own words:**

Replace left and right wiper blade	1 FRU
Flat rate unit I 61 61 541	

Set of wiper blades	1
Part I 61 61 2 349 870	

— Job**Description:****Is interpreted as a repeat visit:** No**Customer's own words:**

Endkontrolle durchgeführt	Local	0 FRU
Flat rate unit I 00 11 800		

— Job**Description:**

Is interpreted as a repeat visit: No
Customer's own words:

— Job

Description:
Is interpreted as a repeat visit: No
Customer's own words:

—	09/20/2016	Repair	10 km	03399	Job
				Niederlassung	Job
				Mannheim	Job
				BMW AG,	Job
				Mannheim	

— Job

Description:
Is interpreted as a repeat visit: No
Customer's own words:

Free pre-delivery check	9 FRU
Flat rate unit I 00 00 009	
Installing navigation map(s)	2 FRU
Flat rate unit I 65 90 600	
Windshield Washer Antifreeze	1
Part I 83 12 2 409 031	

— Job

Description:
Is interpreted as a repeat visit: No
Customer's own words:

BMW warning vest, set of 2	1
Part I 82 26 2 288 693	

— Job

Description:
Is interpreted as a repeat visit: No
Customer's own words:

BMW Key ring 4-Series	1
Part I 80 27 2 354 146	

— Job

Description:
Is interpreted as a repeat visit: No
Customer's own words: