

Vehicle

BMW 320d, 140kW

WBA8H91020K662372



Development code	F31
Color	imperial-blau brillant metallic
Actual integration level	F020-22-07-530
Start of warranty	October 8, 2015

▼ Technical Campaigns

There are no campaigns available.

▼ Special information

There are no campaigns available.

▼ Live Diagnosis

 There are no service solutions for Live Diagnosis.

▼ Service contracts

No BSI contracts available

You can find additional service contract information and selection options in the DCSNet warranty vehicle enquiry.

▼ Information on faults, workshop/Service Consultation

No information on faults is available.

▼ Navigation map

Note: The installed map cannot be identified. One of the following maps could be installed in the vehicle.

Installed map	Enabling code (subscription)	Latest navigation map included in subscription	Latest navigation map subject to charge
Road Map EUROPE EVO 2015-4 (as of: Sep 27, 2024)	-	-	-
Road Map EUROPE EVO 2015-4 (as of: Sep 27, 2024)	Release code valid for navigation maps with release date up to Dec 31, 2099 (SWID: 00F10FFF).	Road Map EUROPE EVO 2026-1	-

▾ Vehicle details

Vehicle type	Passenger car
Brand	BMW
Model	320d
Body	TOUR
Vehicle identification number (last 7 characters)	K662372
Vehicle identification number (17 characters)	WBA8H91020K662372
Development code	F31
Steering	LL
Engine	B47O
Engine number	74089370
Exhaust re-treatment	EURO6;W;PI/CI; M, N1 I
Transmission	AUT
Transmission number	0132952ZEN
Head unit serial number	HB2140F7660551
Drive	HECK
Integration level	F020-15-07-505
Production date	Sep 5, 2015
Production works	Muenchen
Delivery date	Sep 15, 2015
Delivering Retailers	No information
National-market version	EUR
Paint code	A89
Upholstery code	BDAT
Model code	8H01
Base type	8H91
Lead type	8H01

▾ Optional equipment

Optional equipment fitted at the factory:

01CA Selection of COP relevant vehicles
01CB CO2 package
0205 Automatic transmission
0216 Hydro steering-servotronic
0230 EU-specific additional contents

Retrofitted optional equipment:

SHSZ Optional Equipment and Accessories auxiliary heating

0258 Tire with run-flat functionality
 02FH BMW LA wheel, V Spoke 390
 02VB Tire pressure display
 0320 Deleted, model lettering
 0322 Comfort access
 03AA Roof railing black
 0420 Sun protection glazing
 0423 Floor mats, velours
 0428 Warning triangle and first aid kit
 0430 Interior/outside mirror with auto dip
 0431 Interior mirror with automatic-dip
 0459 Seat adjuster, electric, with memory
 0488 Lumbar support, driver and passenger
 0493 Storage compartment package
 0494 Seat heating driver/passenger
 04AE Armrest front, retractable
 04CG Interior strips, "satin-silber" matt
 0508 Park Distance Control (PDC)
 0521 Rain sensor
 0534 Automatic air conditioning
 0544 Cruise control with braking function
 0548 Kilometer-calibrated speedometer
 0552 Adaptive LED headlight
 0563 Light package
 0575 Supplementary 12V sockets
 05A1 LED Fog lights
 05AC High-beam assistant
 05DA Passenger airbag deactivation
 05DC Rear-seat headrests, folding
 0609 Navigation system Professional
 0610 Head-up display
 0676 HiFi speaker system
 0698 Area-Code 2 for DVD
 06AC Intelligent emergency SOS call
 06AE Teleservices
 06AK Connected Drive Services
 06AM Real-Time Traffic Information
 06AN Concierge Services
 06AP Remote Services
 06NS Convenience phone, expanded Smartphone
 06WA Instrument cluster, expanded equipment
 07R7 Innovation package
 07XP Navigation package, Connected Drive
 0801 German version
 0851 Language version German
 0879 On-board vehicle literature German
 08KA Oil service interval, 24 mos./30,000 km
 08SM Car ident. number visible from outside
 08TH Road sign detection
 09AA Outer skin protection
 A090 90 AH AGM battery
 POLS Cloth cushion

▾ Vehicle histories

Date	Type	Vehicle mileage	Dealer	Overview
— 11/07/2025	Key	213766 km	35658	Key 0
 2700 -6 0.8 %	 2700 -6 0.8 %	 70000 09/2026	 37000 11/2027	 34000 11/2027

—	11/07/2025	Service	213766 km	35658 Autohaus Fink GmbH&Co. KG , Kempten	Automatic
---	------------	---------	-----------	--	-----------

								
2700	0	2700	0	70000	0	37000	34000	
✓		✓						

—	11/07/2025	Repair	213772 km	35658 ,	Job Job Job Job Job
---	------------	--------	-----------	---------	---------------------------------

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Standard scope of service Flat rate unit I 00 00 105	2 FRU
---	-------

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Engine oil service Flat rate unit I 00 00 610	3 FRU
Set oil-filter element Part I 11 42 8 575 211	1
Battery Part I 66 12 6 912 985	1
BMW Engine Oil LL04 0W30 Part I 83 21 2 405 950	5

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Service - microfilter Flat rate unit I 00 00 616	2 FRU
Microfilter/activated Carbon container Part I 64 11 9 237 555	1

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Fahrzeug-Oberwäsche Fußräume aussaugen (ohne Berechnung) Local 0 FRU
Flat rate unit I 99 11 111


— Job

Description: > Aktion/Nachlaß 5+ Lohn 20% / Teile 20% ist berücksichtigt


Is interpreted as a repeat visit: No

Customer's own words:

— 09/27/2024 Key 198629 km 35658 Key 0



— 09/27/2024 Service 198629 km 35658 Automatic
Autohaus Fink GmbH&Co. KG, Kempten



— 09/27/2024 Repair 198635 km 35658, Job
Job
Job

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Standard scope of service 2 FRU
Flat rate unit I 00 00 105

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Brake fluid service 6 FRU
Flat rate unit I 00 00 618

Brake fluid DOT4 LV, low viscosity 1
Part I 83 13 2 184 843

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Fahrzeug-Oberwäsche Fußräume aussaugen (ohne Berechnung) Local 0 FRU
Flat rate unit I 99 11 111

—	11/03/2023	Key	185457 km	35658	Key 0				
 -160 0.5 % 01/2024	 -160 01/2024	 -160 01/2024	 -160 01/2024	 70000	 70000	 70000	 -160 0.3 % 01/2024		
—	11/03/2023	Service	185457 km	35658 Autohaus Fink GmbH&Co. KG , Kempten	Automatic				
 -160 01/2024 ✓	 -160 01/2024 ✓	 -160 01/2024 ✓	 -160 01/2024 ✓	 70000	 70000	 70000	 -160 01/2024 ✓		
—	09/16/2022	Key	166174 km	35658	Key 0				
 20000 01/2024	 20000 01/2024	 20000 01/2024	 20000 01/2024	 31000	 -15 2.1 %	 16000	 20000 01/2024		
—	09/16/2022	Service	166174 km	35658 Autohaus Fink GmbH&Co. KG , Kempten	Automatic				
 20000 12/2023	 20000 12/2023	 20000 12/2023	 20000 12/2023	 31000	 09/2022 ✓	 16000	 20000 12/2023		
—	01/18/2022	Key	154656 km		Key 0				
 2500 -17 2.3 %		 2500 -17 2.3 %		 39000	 09/2022	 25000	 34000 703		
—	01/18/2022	Service	154656 km	35658 Autohaus Fink GmbH & Co. KG, Kempten	Manual				
 ✓		 ✓						 §	 §

—	12/14/2020	Key	138405 km		Key 1	
						
19000	0	19000	0	70000	0	48000
01/2022		413			09/2022	
						50000
						1143

—	12/14/2020	Repair	138405 km	35658	Job
				Autohaus Fink	Job
				GmbH & Co.	Job
				KG , Kempten	

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

APAS TC-1-0011890500	Local	18 FRU
Flat rate unit I -		
!!! unknown BMW-Id ESTIMATE Erst prüfen! !!!	Local	0 FRU
Flat rate unit I -		
!!! unknown BMW-Id ESTIMATE F1x F2x F3x G0x G1x G3x B47O B47T Local		0 FRU
B47U B47K AGR-Kühler prüfen ggf. ersetzen (erneute Prüfung) !!!		
Flat rate unit I -		

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Package I MM01AUFTRAGSERTEIL*BM8H01	Local	
»Auftragserteilung mündlich /	Local	0
Flat rate unit I 00 00 013		

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Package I MM02DESINFEKTION*BM8H01	Local	
Fahrzeugdesinfektion	Local	1
Flat rate unit I 00 00 096		

—	09/16/2020	Key	134464 km	35658	Key 0		
							
23000	0	23000	0	70000	0	60000	60000
01/2022		502			09/2020		1232

—	09/16/2020	Service	134464 km	35658 Fink GmbH u. Co.KG, Kempten	Automatic
---	------------	---------	-----------	-----------------------------------	-----------

							
23000 01/2022	0	23000 01/2022	0	70000	0 09/2020	60000	60000 01/2024
					✓		

—	09/16/2020	Repair	134464 km	35658 Autohaus Fink GmbH & Co. KG , Kempten	Job: Service Bremsflüssigkeit Job
---	------------	--------	-----------	---	-----------------------------------

— Job: Service Bremsflüssigkeit

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Service Bremsflüssigkeit
Package I 000061818H010

Brake fluid service Flat rate unit I 00 00 618	4
Brake fluid DOT4 LV, low viscosity Part I 83 13 2 184 843	1

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

!!! unknown BMW-Id ESTIMATE Standardumfang !!! Flat rate unit I -	Local	0 FRU
Standard scope of service Flat rate unit I 00 00 105		2 FRU

—	01/10/2020	Key	126161 km	35658	Key 0
---	------------	-----	-----------	-------	-------

							
60 04/2020	60 111	60 111	60 111	80000	0 09/2020	70000	60 04/2020

—	01/10/2020	Service	126161 km	35658 Fink GmbH u. Co.KG, Kempten	Automatic
---	------------	---------	-----------	-----------------------------------	-----------

							
60	60	60	60	80000	0	70000	60
04/2020	04/2020	04/2020	04/2020		09/2020		04/2020
✓	✓	✓	✓				✓

—	01/10/2020	Repair	126165 km	35658	Autohaus Fink GmbH & Co. KG , Kempten	Job Job Job Job Job Job
---	------------	--------	-----------	-------	---	--

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

—	10/30/2019	Key	124109 km	35658	Key 1		
							
2200	2200	2200	2200	80000	0	80000	2200
04/2020	182	182	182		09/2020		04/2020

—	10/30/2019	Repair	124113 km	35658	Job
				Autohaus Fink	Job
				GmbH & Co.	Job
				KG , Kempten	Job
					Job
					Job

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Kundenbeanstandung:	Local	0 FRU
Flat rate unit I -		

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Light test	2 FRU
Flat rate unit I 00 12 290	

Hypoid axle oil G1	1
Part I 83 22 2 295 532	

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

—	10/24/2019	Key	123940 km	35658	Key 0		
							
2300	2300	2300	2300	80000	0	80000	2300
04/2020	188	188	188		09/2020		04/2020
—	01/02/2019	Key	107474 km	31892	Key 1		
							
19000	19000	19000	19000	80000	0	100000	19000
04/2020	489	489	489		09/2020		04/2020
—	01/02/2019	Repair	107488 km	31892	Job		
				Autohaus	Job		
				Reisacher	Job		
				GmbH ,			
				Landsberg am			
				Lech			

— Job

Description: Grosse Auslieferungsdurchsicht (0099013)

Is interpreted as a repeat visit: No

Customer's own words:

!!! unknown BMW-Id 0099013 Große Auslieferung-vor Arbeitsbeginn	Local	16 FRU
Fahrzeug waschen (Kratzer,Dellen etc.) !!!		
Flat rate unit I 00 99 013		
Windshield Washer Antifreeze		2
Part I 83 12 2 409 031		

— Job

Description: HU und AU durchführen Dekra intern LL

Is interpreted as a repeat visit: No

Customer's own words:

Bereitstellen zur Hauptuntersuchung	Local	1 FRU
Flat rate unit I -		
Abgasmessung Diesel mit OBD 2 Jährig	Local	5 FRU
Flat rate unit I -		

— Job

Description: auf die vorhandenen Felgen lose Winterreifen drauf montieren, Sommerreifen entsorgen

Is interpreted as a repeat visit: No

Customer's own words:

Replacing four tires with run-flat technology Flat rate unit I 36 12 076	30 FRU
Replacing two tire with run-flat technology Flat rate unit I 36 12 055	17 FRU
Gebr. Winterradsatz 205/60R16 Alu mit RDC Part I GBWR5234	Local 1
Wheel electr. module RDCi w/ screw valve Part I 36 10 6 881 890	2

—	09/07/2018	Key	107394 km	Key 1			
							
19000	19000	19000	19000	1500	0	7000	19000
04/2020	603	603	603		09/2018		04/2020
—	09/07/2018	Service	107394 km	31892 Autohaus Reisacher GmbH, Landsberg am Lech	Automatic		
							
19000	19000	19000	19000	1500	09/2018	7000	19000
				✓	✓	✓	
—	08/31/2018	Repair	107395 km	31892 Autohaus Reisacher GmbH , Landsberg am Lech	Job Job Job Job		
—	Job						

Description: Service Bremse vo und hi.

Is interpreted as a repeat visit: No

Customer's own words:

Front brake/rear brake service Flat rate unit I 00 00 613	13 FRU
Standard scope of service Flat rate unit I 00 00 105	2 FRU
Removing and installing/replacing both front brake discs Flat rate unit I 34 11 613	3 FRU
Repair kit, brake pads asbestos-free Part I 34 10 6 859 181	1
Repair kit, brake pads asbestos-free Part I 34 21 6 873 093	1

Brake pad wear sensor, front left
Part I 34 35 6 792 289

1

Brake pad wear sensor, rear
Part I 34 35 6 792 292

1

Brake disc, ventilated
Part I 34 11 6 792 219

2

Inner hex bolt
Part I 34 21 1 161 806

2

— Job

Description: Stoßfänger vo und hi smarten

Is interpreted as a repeat visit: No

Customer's own words:

!!! unknown BMW-Id 9999120 Stoßfänger vorne links Smart-Repair !!! Local
Flat rate unit I 99 99 120

18 FRU

!!! unknown BMW-Id 9999120 Stoßfänger hinten rechts Smart-Repair !!! Local
Flat rate unit I 99 99 120

18 FRU

— Job

Description: Seitenteil hi re lackieren/Türe hi re polieren- falls nicht möglich RS SV

Is interpreted as a repeat visit: No

Customer's own words:

!!! unknown BMW-Id 9999125 Türe hinten rechts schleifen und polieren Local
!!!
Flat rate unit I 99 99 125

12 FRU

!!! unknown BMW-Id 9999120 Seitenteil hinten rechts Smart-Repair !!! Local
Flat rate unit I 99 99 120

18 FRU

— Job

Description: Service Bremsflüssigkeit

Is interpreted as a repeat visit: No

Customer's own words:

Brake fluid service
Flat rate unit I 00 00 618

4 FRU

Brake fluid DOT4 LV, low viscosity
Part I 83 13 2 184 843









1

— 08/30/2018 Key

107392 km

31892

Key 0



— 07/02/2018 Key

104176 km

31892

Key 0

							
23000	23000	23000	23000	3800	0	8000	23000
04/2020	668	668	668		09/2018		04/2020

—	07/02/2018	Repair	104182 km	31892	Job
				Autohaus	Job
				Reisacher	Job
				GmbH ,	
				Landsberg am	
				Lech	

— Job

Description: Reisacher Standard-Check

Is interpreted as a repeat visit: No

Customer's own words:

!!! unknown BMW-Id 0099001 Standardcheck by Reisacher -kostenlos- Local 2 FRU
!!!

Flat rate unit I 00 99 001

Outside car wash 0 FRU

Flat rate unit I 00 11 319

Service consultation at the vehicle with customer without service ticket 0 FRU

Flat rate unit I 00 52 053

— Job

Description: Motorlampe, Fahrzeug ruckel

Is interpreted as a repeat visit: No

Customer's own words:

Carrying out vehicle test 4 FRU
Flat rate unit I 00 00 006

Supporting the voltage of the vehicle electrical system/recharging the vehicle electrical system battery 1 FRU
Flat rate unit I 61 21 528

Carrying out vehicle diagnosis, ABL 2 FRU
Flat rate unit I 61 00 006

Replacing the exhaust-gas recirculation valve 7 FRU
Flat rate unit I 11 71 501

Program/encode control unit(s), includes deleting the fault memory 4 FRU
Flat rate unit I 61 00 730

EGR-valve 1
Part I 11 71 8 513 132

Gasket Steel 1
Part I 11 71 8 579 364

Oval head screw 2
Part I 35 21 7 685 343

Hose clamp 2
Part I 07 12 9 952 104

— Job

Description: Mobilität

Is interpreted as a repeat visit: No

Customer's own words:

—	06/26/2018	Key	103558 km	31892	Key 0			
								
23000	23000	23000	23000	4200	0	8000	23000	
04/2020	673	673	673		09/2018			04/2020
—	04/04/2018	Key	95258 km	31892	Key 0			
								
10	0	10	0	19000	0	8000	32000	
06/2019		452			09/2018			06/2021
—	04/04/2018	Service	95258 km	31892	Automatic			
				Autohaus Reisacher GmbH, Landsberg am Lech				
								
10		10		19000		8000	32000	
✓		✓			09/2018			
—	04/04/2018	Repair	95260 km	31892	Job			
				Autohaus Reisacher GmbH , Landsberg am Lech	Job Job Job Job			

— Job

Description: Reisacher Standard-Check

Is interpreted as a repeat visit: No

Customer's own words:

!!! unknown BMW-Id 0099001 Standardcheck by Reisacher -kostenlos- Local	2 FRU
!!!	
Flat rate unit I 00 99 001	
Outside car wash	0 FRU
Flat rate unit I 00 11 319	
Service consultation at the vehicle with customer without service ticket	0 FRU
Flat rate unit I 00 52 053	

— Job

Description: fällige Wartung durchführen

Is interpreted as a repeat visit: No

Customer's own words:

Standard scope of service Flat rate unit I 00 00 105		2 FRU
Engine oil service Flat rate unit I 00 00 610		3 FRU
Service - microfilter Flat rate unit I 00 00 616		2 FRU
Ölzusatzvergütung Part I ÖL ZUSATZ V	Local	1
Set oil-filter element Part I 11 42 8 575 211		1
BMW Engine Oil LL04 0W30 Part I 83 21 2 405 950		5
Microfilter/activated Carbon container Part I 64 11 9 237 555		1
Glass cleaner without antifreeze Part I 83 12 2 452 029		1

— Job

Description: Saison-Radwechsel

Is interpreted as a repeat visit: No

Customer's own words:

!!! unknown BMW-Id 0099022 Eingelagerte Sommerräder montieren inkl.wuchten Reinigung und Einlagerung der Winterräder !!! Flat rate unit I 00 99 022	Local	12 FRU
---	-------	--------

— Job

Description: Mobilität

Is interpreted as a repeat visit: No

Customer's own words:

—	01/09/2018	Key	88091 km	31892	Key 0		
							
8000	0	8000	0	28000	0	10000	39000
06/2019		537			09/2018		06/2021
—	01/09/2018	Repair	88100 km	31892	Job		
				Autohaus	Job		
				Reisacher	Job		
				GmbH ,			
				Landsberg am			
				Lech			

— Job

Description: Reisacher Standard-Check

Is interpreted as a repeat visit: No

Customer's own words:

!!! unknown BMW-Id 0099001 Standardcheck by Reisacher -kostenlos- Local !!! Flat rate unit I 00 99 001	2 FRU
--	-------

Outside car wash Flat rate unit I 00 11 319	0 FRU
--	-------

Service consultation at the vehicle with customer without service ticket Flat rate unit I 00 52 053	0 FRU
--	-------

— Job

Description: TA Steuergeräte progr.,ggf. AGR ers.

Is interpreted as a repeat visit: No

Customer's own words:

Operating test module and programming control unit Flat rate unit I 00 64 941	8 FRU
--	-------

— Job

Description: Mobilität

Is interpreted as a repeat visit: No

Customer's own words:

—	10/18/2017	Key	79174 km	31892	Key 0
---	------------	-----	----------	-------	-------

 17000 06/2019	 0	 17000 620	 0	 36000	 0 09/2018	 18000	 48000 06/2021
---	--	---	--	--	---	--	--

—	10/18/2017	Repair	79174 km	31892	Job Autohaus Reisacher GmbH , Landsberg am Lech
---	------------	--------	----------	-------	--

— Job

Description: Reisacher Standard-Check

Is interpreted as a repeat visit: No

Customer's own words:

!!! unknown BMW-Id 0099001 Standardcheck by Reisacher -kostenlos- Local !!! Flat rate unit I 00 99 001	2 FRU
--	-------

Outside car wash Flat rate unit I 00 11 319	0 FRU
--	-------

Key case, M Performance Part I 82 29 2 355 518	1
---	---

Set of wiper blades
Part I 61 61 2 241 375

1

Windshield Washer Antifreeze
Part I 83 12 2 409 031

2

Anti-freeze
Part I 83 19 2 211 358

1

— Job

Description: Lichttest

Is interpreted as a repeat visit: No

Customer's own words:

!!! unknown BMW-Id 6399010 Aktion Lichttest Oktober Plakette kleben Local
ja nein !!!
Flat rate unit I 63 99 010

1 FRU

— Job

Description: Saison-Radwechsel

Is interpreted as a repeat visit: No

Customer's own words:

!!! unknown BMW-Id 0099023 Eingelagerte Winterräder montieren Local
inkl.wuchten Reinigung und Einlagerung der Sommeräder !!!
Flat rate unit I 00 99 023

12 FRU

— 06/27/2017 Key

64309 km

31892

Key 0

 -1400 07/2018	 -1400 399	 -1400 399	 -1400 399	 46000	 0 09/2018	 29000	 -1400 07/2018
---	---	---	---	--	---	--	--

— 06/27/2017 Service

64309 km

31892

Manual

Autohaus
Reisacher
GmbH,
Landsberg am
Lech

 ✓	 ✓	 ✓	 ✓				 ✓		
--	--	--	--	---	---	---	---	---	---

— 06/26/2017 Repair

64318 km

31892

Job

Autohaus
Reisacher
GmbH,
Landsberg am
Lech

Job
Job

— Job

Description: Reisacher Standard-Check

Is interpreted as a repeat visit: No

Customer's own words:

!!! unknown BMW-Id 0099001 Standardcheck by Reisacher -kostenlos- Local !!! Flat rate unit I 00 99 001	2 FRU
Outside car wash Flat rate unit I 00 11 319	0 FRU
Service consultation at the vehicle with customer without service ticket Flat rate unit I 00 52 053	0 FRU

— Job

Description: fällige Wartung durchführen

Is interpreted as a repeat visit: No

Customer's own words:

Engine oil service Flat rate unit I 00 00 610	3 FRU
Standard scope of service Flat rate unit I 00 00 105	2 FRU
Vehicle check service Flat rate unit I 00 00 624	6 FRU
Service - air filter insert Flat rate unit I 00 00 602	2 FRU
Fuel filter service Flat rate unit I 00 00 604	3 FRU
Service - microfilter Flat rate unit I 00 00 616	2 FRU
Ölzusatzvergütung Part I ÖL ZUSATZ V	Local 1
Set oil-filter element Part I 11 42 8 575 211	1
BMW Engine Oil LL04 0W30 Part I 83 21 2 405 950	5
Air filter element Part I 13 71 8 511 668	1
Fuel filter cartridge Part I 13 32 8 572 522	1
Hose clamp Part I 07 12 9 952 104	2
Microfilter/activated Carbon container Part I 64 11 9 237 555	1
Glass cleaner without antifreeze Part I 83 12 2 361 702	2

— Job

Description: Ersatzfahrzeug

Is interpreted as a repeat visit: No

Customer's own words:

—	05/10/2017	Key	60256 km	31892	Key 0		
							
2600	2600	2600	2600	60000	0	34000	2600
07/2018	447	447	447		09/2018		07/2018

—	05/10/2017	Repair	60265 km	31892	Job
				Autohaus	Job
				Reisacher	Job
				GmbH ,	Job
				Landsberg am	
				Lech	

— Job

Description: Reisacher Standard-Check

Is interpreted as a repeat visit: No

Customer's own words:

!!! unknown BMW-Id 0099001 Standardcheck by Reisacher -kostenlos- Local	2 FRU
!!!	
Flat rate unit I 00 99 001	

Outside car wash	0 FRU
Flat rate unit I 00 11 319	

— Job

Description: Fehlermeldung Ausfall Kurvenlicht

Is interpreted as a repeat visit: No

Customer's own words:

Performing vehicle test	2 FRU
Flat rate unit I 00 00 556	

Supporting the voltage of the vehicle electrical system/recharging the vehicle electrical system battery	1 FRU
Flat rate unit I 61 21 528	

Carrying out vehicle diagnosis, ABL	1 FRU
Flat rate unit I 61 00 006	

Work time without specification/lights	0 FRU
Flat rate unit I 63 99 000	

Program/encode control unit(s), includes deleting the fault memory	4 FRU
Flat rate unit I 61 00 730	

— Job

Description: Saison-Radwechsel

Is interpreted as a repeat visit: No

Customer's own words:

!!! unknown BMW-Id 0099022 Eingelagerte Sommerräder montieren Local
inkl.wuchten Reinigung und Einlagerung der Winterräder !!!
Flat rate unit I 00 99 022

12 FRU

— Job

Description: Ersatzfahrzeug

Is interpreted as a repeat visit: No

Customer's own words:

— 04/27/2017 Key 58727 km 31892 Key 0

							
4200	4200	4200	4200	60000	0	35000	4200
07/2018	460	460	460		09/2018		07/2018

— 04/27/2017 Repair 58734 km 31892 Job
Autohaus Job
Reisacher Job
GmbH ,
Landsberg am
Lech

— Job

Description: Reisacher Standard-Check

Is interpreted as a repeat visit: No

Customer's own words:

!!! unknown BMW-Id 0099001 Standardcheck by Reisacher -kostenlos- Local
!!!
Flat rate unit I 00 99 001

2 FRU

Outside car wash
Flat rate unit I 00 11 319

0 FRU

— Job

Description: lt. Kd. Kühlwasserverlust

Is interpreted as a repeat visit: No

Customer's own words:

Check the cooling system for watertightness with the special tool
Flat rate unit I 17 00 009

4 FRU

Removing and installing or replacing EGR cooler
Flat rate unit I 11 71 600

23 FRU

Exhaust gas cooler high temperature
Part I 11 71 8 513 691

1

Gasket Steel
Part I 11 61 8 571 005

1

Pipe union
Part I 11 71 7 799 853

2

— Job

Description: Mobilität

Is interpreted as a repeat visit: No

Customer's own words:

—	04/05/2017	Key	56541 km	31892	Key 0		
							
7000	7000	7000	7000	60000	0	37000	7000
07/2018	482	482	482		09/2018		07/2018
—	10/19/2016	Key	40793 km	31892	Key 0		
							
23000	23000	23000	23000	70000	0	60000	23000
07/2018	650	650	650		09/2018		07/2018
—	10/18/2016	Repair	40793 km	31892	Job		
				Autohaus	Job		
				Reisacher			
				GmbH ,			
				Landsberg am			
				Lech			

— Job

Description: Reisacher Standard-Check

Is interpreted as a repeat visit: No

Customer's own words:

!!! unknown BMW-Id 0099001 Standardcheck by Reisacher -kostenlos- Local	2 FRU
!!! Flat rate unit I 00 99 001	
!!! unknown BMW-Id 6399010 Aktion Lichttest Oktober 2016 Plakette Local	1 FRU
kleben ja nein !!! Flat rate unit I 63 99 010	
Outside car wash	0 FRU
Flat rate unit I 00 11 319	
Windshield Washer Antifreeze	2
Part I 83 12 2 409 031	

— Job

Description: Saison-Radwechsel

Is interpreted as a repeat visit: No

Customer's own words:

!!! unknown BMW-Id 0099023 Eingelagerte Winterräder montieren
inkl.wuchten Reinigung und Einlagerung der Sommeräder !!!
Flat rate unit I 00 99 023

Local

12 FRU

—	07/25/2016	Key	31881 km	31892	Key 0			
								
-900	0	-900	0	80000	0	70000	31000	
09/2017		432			09/2018		09/2019	
—	07/25/2016	Service	31881 km	31892	Manual			
				Autohaus Reisacher GmbH, Landsberg am Lech				
								
✓		✓						
—	07/25/2016	Repair	31881 km	31892	Job			
				Autohaus Reisacher GmbH , Landsberg am Lech	Job			

— Job

Description: Reisacher Standard-Check

Is interpreted as a repeat visit: No

Customer's own words:

!!! unknown BMW-Id 0099001 Standardcheck by Reisacher -kostenlos- Local
!!!
Flat rate unit I 00 99 001

2 FRU

Outside car wash
Flat rate unit I 00 11 319

0 FRU

— Job

Description: fällige Wartung durchführen

Is interpreted as a repeat visit: No

Customer's own words:

Standard scope of service
Flat rate unit I 00 00 105

2 FRU

Engine oil service
Flat rate unit I 00 00 610

3 FRU

Service - microfilter
Flat rate unit I 00 00 616

2 FRU

Ölzusatzvergütung

Local

1

Part I ÖL ZUSATZ V

Set oil-filter element Part I 11 42 8 575 211	1
BMW Engine Oil LL04 0W30 Part I 83 21 2 405 950	5
Microfilter/activated Carbon container Part I 64 11 9 237 555	1
Glass cleaner without antifreeze Part I 83 12 2 361 702	2

—	05/30/2016	Key	26822 km	31892	Key 0		
							
4200	0	4200	0	80000	0	70000	36000
09/2017		487			09/2018		09/2019

—	05/13/2016	Key	24193 km	31892	Key 1		
							
7000	0	7000	0	80000	0	70000	38000
09/2017		505			09/2018		09/2019

—	05/13/2016	Repair	24193 km	31892	Job
				Autohaus	Job
				Reisacher	Job
				GmbH ,	Job
				Landsberg am	
				Lech	

— Job

Description: Reisacher Standard-Check

Is interpreted as a repeat visit: No

Customer's own words:

!!! unknown BMW-Id 0099001 Standardcheck by Reisacher -kostenlos- Local
!!!
Flat rate unit I 00 99 001

Outside car wash
Flat rate unit I 00 11 319

Glass cleaner without antifreeze
Part I 83 12 2 361 702

— Job

Description: Saison-Radwechsel

Is interpreted as a repeat visit: No

Customer's own words:

Storage fee, season including wheel cleaning
Flat rate unit I 00 99 020

— Job

Description: TA AGR-Ventil ers.

Is interpreted as a repeat visit: No

Customer's own words:

!!! unknown BMW-Id 0099500 Technische Aktion "AGR-Ventil" wird zu
einem späteren Zeitpunkt durchgeführt !!!
Flat rate unit I 00 99 500

Local

0 FRU

— Job

Description: Mobilität

Is interpreted as a repeat visit: No

Customer's own words:

—

05/13/2016 Repair

26828 km

31892
Autohaus
Reisacher
GmbH ,
Landsberg am
Lech

Job

Job

— Job

Description: Reisacher Standard-Check

Is interpreted as a repeat visit: No

Customer's own words:

!!! unknown BMW-Id 0099001 Standardcheck by Reisacher -kostenlos- Local	2 FRU
---	-------

!!!
Flat rate unit I 00 99 001

Outside car wash	0 FRU
------------------	-------

Flat rate unit I 00 11 319

Glass cleaner without antifreeze	2
----------------------------------	---

Part I 83 12 2 361 702

— Job

Description: TA AGR-Ventil ers.

Is interpreted as a repeat visit: No

Customer's own words:

Replace exhaust-gas recirculation valve	9 FRU
---	-------

Flat rate unit I 00 64 525

EGR-valve	1
-----------	---

Part I 11 71 8 594 492

Gasket Steel	1
--------------	---

Part I 11 71 8 579 364

Oval head screw	2
-----------------	---

Part I 35 21 7 685 343

Hose clamp	2
------------	---

Part I 07 12 9 952 104

—	09/09/2015	Repair	10 km	31892	Job
				Autohaus	Job
				Reisacher	Job
				GmbH ,	
				Landsberg am	
				Lech	

— Job

Description: Übergabedurchsicht

Is interpreted as a repeat visit: No

Customer's own words:

!!! unknown BMW-Id 8499001 Freischaltung Teleservice prüfen,ggf. aktivieren !!!	Local	3 FRU
---	-------	-------

Flat rate unit I 84 99 001

!!! unknown BMW-Id 6599010 Freischaltung von Navigationskarten mit Freischaltcode !!!	Local	3 FRU
---	-------	-------

Flat rate unit I 65 99 010

Free pre-delivery check	9 FRU
-------------------------	-------

Flat rate unit I 00 00 009

Enable code HU-H-2 map Europe Initial
Part I 65 90 2 365 635

1

Glass cleaner without antifreeze
Part I 83 12 2 361 702

2

— Job

Description: Standheizung einbauen Y-Kabel Iphone 6 einlegen

Is interpreted as a repeat visit: No

Customer's own words:

!!! unknown BMW-Id 6499500 Nachrüstung Standheizung !!!
Flat rate unit I 64 99 500

Local

108 FRU

!!! unknown BMW-Id 6199500 Nachrüstung Standheizung
programmieren/ codieren !!!
Flat rate unit I 61 99 500

Local

6 FRU

Install.kit, independent heater
Part I 64 50 2 359 944

1

Retrofit kit, remote cntrl,indep.heating
Part I 64 50 0 410 385

1

Media adapter
Part I 61 12 2 287 505

1

Hose clamp
Part I 64 21 8 367 179

1

— Job

Description: Winterräder montieren Sommerräder unter KD einlagern

Is interpreted as a repeat visit: No

Customer's own words:

!!! unknown BMW-Id 0099005 Kostenlose Einlagerung der
Sommerräder für eine Saison inkl.Reinigung,bei Kauf eines Radsatzes !!!
Flat rate unit I 00 99 005

Local

3 FRU

Detaching and attaching the front and rear wheels
Flat rate unit I 36 10 360

6 FRU

Gebr. Winterradsatz 205/60R16 Alu F30
Part I GBWR5088

Local

-1

RDCi wheel & tire, winter, steel
Part I 36 11 2 411 436

4

Wheel cover
Part I 36 13 6 791 806

4