

Vehicle

BMW 320d, 140kW

WBA8T31080G536869



Development code	F34
Color	mineral-grau metallic
Actual integration level	F020-25-07-520
Start of warranty	September 23, 2016

▼ Technical Campaigns

There are no campaigns available.

▼ Special information

There are no campaigns available.

▼ Live Diagnosis

 There are no service solutions for Live Diagnosis.

▼ Service contracts

No BSI contracts available

You can find additional service contract information and selection options in the DCSNet warranty vehicle enquiry.

▼ Information on faults, workshop/Service Consultation

No information on faults is available.

▼ Navigation map

Note: The installed map cannot be identified. One of the following maps could be installed in the vehicle.

Installed map	Enabling code (subscription)	Latest navigation map included in subscription	Latest navigation map subject to charge
Road Map EUROPE EVO 2016-2 (as of: Sep 2, 2025)	-	-	-
Road Map EUROPE EVO 2016-2 (as of: Sep 2, 2025)	Release code valid for navigation maps with release date up to Dec 31, 2099 (SWID: 01200FFF).	Road Map EUROPE EVO 2026-1	-

▾ Vehicle details

Vehicle type	Passenger car
Brand	BMW
Model	320d
Body	SAT
Vehicle identification number (last 7 characters)	G536869
Vehicle identification number (17 characters)	WBA8T31080G536869
Development code	F34
Steering	LL
Engine	B47O
Engine number	75039742
Exhaust re-treatment	EURO6;W;PI/CI; M, N1 I
Transmission	AUT
Transmission number	0552794WC7
Head unit serial number	HB2240G7985792
Drive	HECK
Integration level	F020-16-07-506
Production date	Sep 13, 2016
Production works	Dingolfing
Delivery date	Sep 14, 2016
Delivering Retailers	No information
National-market version	EUR
Paint code	B39
Upholstery code	BDAT
Model code	8T41
Base type	8T31
Lead type	8T41

▾ Optional equipment

Optional equipment fitted at the factory:

01CA Selection of COP relevant vehicles
01CB CO2 package
0205 Automatic transmission
0216 Hydro steering-servotronic
0230 EU-specific additional contents


Retrofitted optional equipment:

This vehicle has no retrofits.


0255 Sports leather steering wheel
0258 Tire with run-flat functionality
02L3 BMW LA wheel, V Spoke 395
02VB Tire pressure display
0302 Alarm system
0320 Deleted, model lettering
0321 Exterior parts in vehicle color
0322 Comfort access
03AG Reversing camera
0402 Electric panoramic roof
0420 Sun protection glazing
0423 Floor mats, velours
0428 Warning triangle and first aid kit
0430 Interior/outside mirror with auto dip
0431 Interior mirror with automatic-dip
0488 Lumbar support, driver and passenger
0493 Storage compartment package
0494 Seat heating driver/passenger
04AE Armrest front, retractable
04CG Interior strips, "satin-silber" matt
0508 Park Distance Control (PDC)
0521 Rain sensor
0534 Automatic air conditioning
0544 Cruise control with braking function
0548 Kilometer-calibrated speedometer
0552 Adaptive LED headlight
0563 Lights package
0575 Supplementary 12V sockets
05A1 LED Fog lights
05AC High-beam assistant
05AG Lane-change warning
05AS Driving Assistant
05DA Passenger airbag deactivation
0609 Navigation system Professional
0610 Head-up display
0676 HiFi speaker system
0698 Area-Code 2 for DVD
06AC Intelligent emergency SOS call
06AE Teleservices
06AK Connected Drive Services
06AM Real-Time Traffic Information
06AN Concierge Services
06AP Remote Services
06NW Phoning with wireless charging
06WA Instrument cluster, expanded equipment
06WD WLAN Hotspot
0760 High gloss shadow line
0775 Headlining anthracite
07LC Modell Advantage
07R7 Innovation package
0801 German version
0851 Language version German
0879 On-board vehicle literature German
08KA Oil service interval, 24 mos./30,000 km
08R9 Refrigerant R1234yf
08TF Active pedestrian protection
08TH Road sign detection
0925 Dummy-SALAPA
09AA Outer skin protection
09BM Navigation package, Connected Drive
A090 90 AH AGM battery
POLS Cloth cushion

▾ Vehicle histories

Date	Type	Vehicle mileage	Dealer	Overview
09/02/2025	Key	204363 km	03846	Key 0



09/02/2025	Service	204363 km	03846 Andreas Ehrl Potsdam, Potsdam	Automatic
------------	---------	-----------	-------------------------------------	-----------



09/02/2025	Repair	204373 km	03846 ,	Job
------------	--------	-----------	---------	-----

Job

Description: Hr. Gajewi, Hans-Ulrich vom 02.09.25 09:05 Uhr bis 03.09.25 15:12 Uhr

Is interpreted as a repeat visit: No

Customer's own words:

Mietwagen Klasse Mini	Local	2 FRU
Flat rate unit I 99 99 999		

09/02/2025	Repair	204373 km	03846 ,	Job: Annahme Job: Verbunddiag. 60 Mon. + Job: Service Bremsflüssigkeit Job: Service Standardumfang Job: Beide Gasdruckfedern für Job Job: AU&HU bei der Dekra Job: kostenfreie FZG wäsche Job Job
------------	--------	-----------	---------	---

Job: Annahme

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Annahme
Package I 0200123

Kennzeichenträger ersetzen nein	Local	0
Flat rate unit I 00 12 403		
Fehlende Flüssigkeiten ergänzen Ja	Local	1
Flat rate unit I 99 99 999		

Job: Verbunddiag. 60 Mon. +

Description: Beanstandung: aktueller Navistandort wird nicht gefunden

Is interpreted as a repeat visit: No

Customer's own words:

Verbunddiag. 60 Mon. +
Package I 0100114

Performing vehicle test Flat rate unit I 00 00 556	2
Supporting the voltage of the vehicle electrical system/recharging the vehicle electrical system battery Flat rate unit I 61 21 528	1
Determining cause of customer complaint with diagnostic system Flat rate unit I 00 12 350	9

— Job: Service Bremsflüssigkeit

Description: MKP 0000618 : BMW Service 5+, 20% Nachlass Nachlass

Is interpreted as a repeat visit: No

Customer's own words:

Service Bremsflüssigkeit
Package I 0000618

Brake fluid service Flat rate unit I 00 00 618	4
Brake fluid DOT4, low-viscosity EU Part I 83135A82511	1

— Job: Service Standardumfang

Description: MKP 0000105 : BMW Service 5+, 20% Nachlass Nachlass

Is interpreted as a repeat visit: No

Customer's own words:

Service Standardumfang
Package I 0000105

Standard scope of service Flat rate unit I 00 00 105	2
---	---

— Job: Beide Gasdruckfedern für

Description: Komm:-Haltbarkeit Dämpfer der Frontklappe abgelaufen Frontklappe abgelaufen MKP 512376618T410 :
BMW Service 5+, 20% Nachlass Nachlass

Is interpreted as a repeat visit: No

Customer's own words:

Beide Gasdruckfedern für
Package I 5123766

Removing and installing or replacing both gas pressure props for engine hood Flat rate unit I 51 23 766	1
Gas strut, hood Part I 51 23 7 239 233	2

— Job

Description: Komm:-bitte Navidaten aktualisieren

Is interpreted as a repeat visit: No

Customer's own words:

unknown fru: Software-Update für Straßen- k arte bei Abonnement Flat rate unit I 65 90 123	Local	2 FRU
---	-------	-------

— Job: AU&HU bei der Dekra

Description:

Is interpreted as a repeat visit: No

Customer's own words:

AU&HU bei der Dekra
Package I 0100113

Vorbereitung und Durchführung AU & HU bei der DEKRA #TÜV2 Flat rate unit I 00 12 990	Local	2
---	-------	---

Abgas-und Hauptuntersuchung bei der DEKRA (durchlaufender Flat rate unit I 99 99 999	Local	1
---	-------	---

— Job: kostenfreie FZG wäsche

Description:

Is interpreted as a repeat visit: No

Customer's own words:

kostenfreie FZG wäsche
Package I 0100113

Softtec-Wäsche ohne Berechnung Fahrgastraum aussaugen Türeinstiege reinigen Flat rate unit I 09 99 007	Local	0
--	-------	---

— Job

Description: Diagnose / Reparatur Navigationssystem Im Fehlerspeicher sind keine systemrelevanten Fehler im Navigationssystem abgelegt 1. Maßnahme: Fahrzeug neu programmieren und im Anschluss eine Funktionsprüfung durchführen

Is interpreted as a repeat visit: No

Customer's own words:

Program/encode control unit(s), includes deleting the fault memory Flat rate unit I 61 00 730		4 FRU
--	--	-------

Performing vehicle test Flat rate unit I 00 00 556		2 FRU
---	--	-------

— Job

Description: - Standlicht Scheinwerfer rechts mit Farbunterschied - Reifenluftdruck war 0,4 bar zu gering -> korrigiert auf Normalbeladung

Is interpreted as a repeat visit: No

Customer's own words:

Hinweise: Flat rate unit I 00 11 222	Local	0 FRU
---	-------	-------

—	07/16/2025	Key	201497 km	03846	Key 0						
											
	14000		14000		100000		8000	45000			
	08/2026		08/2026			09/2025	09/2025	08/2028		09/2025	
—	07/14/2025	Key	201293 km	07830	Key 0						
											
	15000		15000		100000		8000	46000			
	08/2026		08/2026			09/2025	09/2025	08/2028		09/2025	
—	07/09/2025	Key	200787 km	31253	Remote KeyRead						
											
	15000		15000		100000		8000	46000			
	08/2026		08/2026			09/2025	09/2025	08/2028		09/2025	
—	08/06/2024	Key	185372 km	31253	Key 0						
											
	-1300 4.2 %	-1300	-1300	-1300	100000		9000	-1300 2.1 %			
	04/2025	04/2025	04/2025	04/2025		09/2025	09/2025	04/2025		09/2025	
—	08/06/2024	Service	185372 km	31253	Automatic						
					Autohaus Ehrh GmbH Halle Zentrum/SV, Halle (Saale)						
											
	-1300	-1300	-1300	-1300	100000		9000	-1300			
	04/2025	04/2025	04/2025	04/2025		09/2025	09/2025	04/2025		09/2025	
	✓	✓	✓	✓				✓			
—	08/06/2024	Repair	185372 km	31253 ,	Job Job Job Job Job Job Job Job						

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Standard scope of service

2 FRU

— Job

Description:**Is interpreted as a repeat visit:** No**Customer's own words:**

Engine oil service	3 FRU
Flat rate unit I 00 00 610	

Set oil-filter element	1
Part I 11 42 8 575 211	

5W-30 Castrol EDGE Prof. Motoröl BMW LL-04	Local	5
Part I FT98 90 0 834 0		

— Job

Description:**Is interpreted as a repeat visit:** No**Customer's own words:**

Fuel filter service	3 FRU
Flat rate unit I 00 00 604	

Fuel filter cartridge	1
Part I 13 32 7 822 497	

— Job

Description:**Is interpreted as a repeat visit:** No**Customer's own words:**

Service - air filter insert	2 FRU
Flat rate unit I 00 00 602	

Air filter element	1
Part I 13 71 8 511 668	

— Job

Description:**Is interpreted as a repeat visit:** No**Customer's own words:**

Service - microfilter	2 FRU
Flat rate unit I 00 00 616	

Microfilter/activated Carbon container	1
Part I 64 11 9 237 555	

— Job

Description:**Is interpreted as a repeat visit:** No**Customer's own words:**

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Work time without specification / vehicle electrical system 2 FRU
Flat rate unit I 61 99 000

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Replacing the vehicle battery – including battery replacement registration 5 FRU
Flat rate unit I 61 21 517

Original BMW AGM-battery 1
Part I 61 21 6 806 755

— Job








Description:

Is interpreted as a repeat visit: No

Customer's own words:

Maschinelle Fahrzeugwäsche ohne Berechnung Local 2 FRU
Flat rate unit I 00 00 002

— 01/04/2024 Key 170646 km 31253 Key 0



— 01/04/2024 Repair 170656 km 31253 Autohaus Ehrl GmbH Halle Zentrum/SV , Halle (Saale) Job Job

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Replace left and right wiper blade 1 FRU
Flat rate unit I 61 61 541

Set of wiper blades 1
Part I 61615A43585

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Maschinelle Fahrzeugwäsche ohne Berechnung
Flat rate unit I 00 00 002

Local

2 FRU

Fahrzeug aussaugen ohne Berechnung
Flat rate unit I 01 00 004

Local








1 FRU

— 09/07/2023 Key

164010 km

31253

Key 0











— 09/07/2023 Service

164010 km

31253

Automatic

Autohaus Ehrl
GmbH Halle
Zentrum , Halle
(Saale)



— 09/07/2023 Repair

164015 km

31253

Job

Autohaus Ehrl
GmbH Halle
Zentrum , Halle
(Saale)

Job
Job
Job
Job
Job

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Standard scope of service
Flat rate unit I 00 00 105

2 FRU

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Service - front brakes
Flat rate unit I 00 00 612

6 FRU

Sicherheitsreiniger
Part I FT08 90 1 065 6

Local

1

Brake pad wear sensor, front left Part I 34 35 6 792 289	1
Repair kit, brake pads asbestos-free Part I 34 10 6 859 181	1
Brake pad paste Part I 83 23 0 140 233	2

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Brake fluid service Flat rate unit I 00 00 618	4 FRU
Brake fluid DOT4 LV, low viscosity Part I 83 13 2 184 842	1

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Presentation for emission inspection Flat rate unit I 00 00 527	5 FRU
VERBANDTASCHE Part I FT99 94 3 930 0	Local 1

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Maschinelle Fahrzeugwäsche ohn e Berechnung Flat rate unit I 00 00 002	Local 2 FRU
Fahrzeug aussaugen ohne Berech nung Flat rate unit I 01 00 004	Local 1 FRU

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

HU nach §29 StVZO §10 Abs .UstG Durchl.Pos Flat rate unit I 99 99 999	Local 1 FRU
--	-------------

 -1100 3.5 % 12/2023		 -1100 12/2023		 46000	 09/2023	 09/2023	 27000	 30000 12/2025	 09/2023
---	--	--	--	---	---	---	--	--	---

— 04/05/2023 Service 155667 km 31253 Automatic
Autohaus Ehrl
GmbH Halle
Zentrum , Halle
(Saale)

 -1100 12/2023 ✓		 -1100 12/2023 ✓		 46000	 09/2023	 09/2023	 27000	 30000 12/2025	 09/2023
--	---	--	---	--	--	--	---	---	--

— 04/05/2023 Repair 155670 km 31253 Job
Autohaus Ehrl Job
GmbH Halle Job
Zentrum , Halle Job
(Saale)

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Standard scope of service 2 FRU
Flat rate unit I 00 00 105

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Engine oil service 3 FRU
Flat rate unit I 00 00 610

5W-30 Castrol EDGE Prof. Motoröl BMW LL-04 Local 5
Part I FT98 90 0 834 0

Set oil-filter element 1
Part I 11 42 8 575 211

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Service - microfilter 2 FRU
Flat rate unit I 00 00 616

Microfilter/activated Carbon container 1
Part I 64 11 9 237 555

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Maschinelle Fahrzeugwäsche ohne Berechnung Flat rate unit I 00 00 002	Local	2 FRU
Fahrzeug aussaugen ohne Berechnung Flat rate unit I 01 00 004	Local	1 FRU

— 08/22/2022 Key 142186 km 03846 Key 0

									
13000		13000		60000			43000	44000	
12/2023		12/2023			09/2023	09/2023		12/2025	09/2023

— 08/19/2022 Key 142102 km 03846 Key 0

									
13000		13000		60000			43000	44000	
12/2023		12/2023			09/2023	09/2023		12/2025	09/2023

— 08/19/2022 Repair 142102 km 03846 Andreas Ehrl Potsdam GmbH & Co. KG, Potsdam Job

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Einen Reifen zum Sonderpreis ersetzen (Runflatausführung) Flat rate unit I 36 00 005	Local	7 FRU
Fahrzeugannahme durch Service- assistentin Flat rate unit I 01 00 002	Local	1 FRU
ZINKGEWICHT lt.§ 2005 Part I FT98 34 0 077 7	Local	2
Pirelli Cinturato P7 r-f Part I 85 45 2 593 501		1

— 07/22/2022 Key 139171 km 31253 Key 0

									
16000		16000		70000			50000	47000	
12/2023		489			09/2023	399		12/2025	09/2023

—	07/22/2022	Repair	139175 km	31253 Autohaus Ehrl GmbH Halle Zentrum , Halle (Saale)	Job
---	------------	--------	-----------	--	-----

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Fahrzeug aussaugen ohne Berechnung
Flat rate unit I 01 00 004

Local 1 FRU

Vehicle identification without vehicle test
Flat rate unit I 00 00 003

2 FRU

—	07/07/2022	Key	138194 km	31253	Remote KeyRead
---	------------	-----	-----------	-------	----------------

									
17000		17000		70000			60000	48000	
12/2023		504			09/2023	414		12/2025	09/2023

—	12/16/2021	Key	123974 km		Key 0
---	------------	-----	-----------	--	-------

									
1400	1400	1400	1400	80000			70000	1400	
07/2022	195	195	195		09/2023	615		07/2022	09/2023

—	12/16/2021	Service	123974 km	31253 Autohaus Ehrl GmbH Halle Zentrum , Halle (Saale)	Automatic
---	------------	---------	-----------	--	-----------

								
1400	1400	1400	1400	80000			70000	1400
06/2022	06/2022	06/2022	06/2022		08/2023		06/2022	08/2023
✓	✓	✓	✓				✓	

—	12/16/2021	Repair	123981 km	31253 Autohaus Ehrl GmbH Halle Zentrum , Halle (Saale)	Job Job Job Job Job Job
---	------------	--------	-----------	--	--

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Standard scope of service

2 FRU

Flat rate unit I 00 00 105

Engine oil service	3 FRU
Flat rate unit I 00 00 610	

5W-30 Castrol EDGE Prof. Motoröl BMW LL-04	Local	5
Part I FT98 90 0 834 0		

Set oil-filter element	1
Part I 11 42 8 575 211	

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Fuel filter service	3 FRU
Flat rate unit I 00 00 604	

Fuel filter cartridge	1
Part I 13 32 7 822 497	

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Service - air filter insert	2 FRU
Flat rate unit I 00 00 602	

Air filter element	1
Part I 13 71 8 511 668	

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Service - microfilter	2 FRU
Flat rate unit I 00 00 616	

Microfilter/activated Carbon container	1
Part I 64 11 9 237 555	

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Vehicle check service	6 FRU
Flat rate unit I 00 00 624	

Sicherung gelb	2
Part I 61 13 1 372 527	

Battery	1
Part I 61 31 9 217 643	

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Maschinelle Fahrzeugwäsche ohne Berechnung
Flat rate unit I 00 00 002

Local

2 FRU

Fahrzeug aussaugen ohne Berechnung
Flat rate unit I 01 00 004









Local

1 FRU

— 09/14/2021 Key

118038 km

Key 0












— 09/14/2021 Service

118038 km

31253
Autohaus Ehrl
GmbH Halle
Zentrum , Halle
(Saale)

Automatic



— 09/14/2021 Repair

118042 km

31253
Autohaus Ehrl
GmbH Halle
Zentrum , Halle
(Saale)

Job
Job
Job
Job
Job

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Standard scope of service
Flat rate unit I 00 00 105

2 FRU

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

§ emission test with on-board diagnosis
Flat rate unit I 00 00 128

4 FRU

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Brake fluid service	4 FRU
Flat rate unit I 00 00 618	

Brake fluid DOT4 LV, low viscosity	1
Part I 83 13 2 184 842	

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Fahrzeugwäsche ohne Berechnung	Local	2 FRU
Flat rate unit I 00 00 003		

Fahrzeug aussaugen ohne Berechnung	Local	1 FRU
Flat rate unit I 01 00 004		

— Job


Description:

Is interpreted as a repeat visit: No


Customer's own words:

HU nach §29 StVZO §10 Abs UStG Durchl. Pos 00000000	Local	1 FRU
Flat rate unit I 99 99 999		

07/09/2020	Key	94383 km	03846	Key 0
------------	-----	----------	-------	-------



07/09/2020	Service	94383 km	03846 Andreas Ehrl Potsdam GmbH&Co. KG , Potsdam	Automatic
------------	---------	----------	--	-----------



07/09/2020	Repair	94383 km	03846 Andreas Ehrl Potsdam GmbH & Co. KG , Potsdam	Job
------------	--------	----------	--	-----

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Fast service with compact check or service consultation at the vehicle	0 FRU
Flat rate unit I 00 52 055	

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Engine oil service	3 FRU
Flat rate unit I 00 00 610	

Standard scope of service	2 FRU
Flat rate unit I 00 00 105	

CASTROL Edge BMW LL04 Professional SAE 5W-30	Local	5
Part I FT91 70 0 000 5		

Set oil-filter element	1
Part I 11 42 8 575 211	

— Job

Description:


Is interpreted as a repeat visit: No

Customer's own words:

Service - microfilter	2 FRU
Flat rate unit I 00 00 616	

Microfilter/activated Carbon container	1
Part I 64 11 9 237 555	

—	11/29/2019	Key	82973 km	31253	Key 0
---	------------	-----	----------	-------	-------



—	11/29/2019	Repair	82973 km	31253	Job
Autohaus Ehrl GmbH Halle Zentrum , Halle (Saale)					

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Fahrzeug aussaugen ohne Berechnung	Local	1 FRU
Flat rate unit I 01 00 004		

Windshield Washer Antifreeze	1
------------------------------	---

—	10/15/2019	Repair	77439 km	28792	Job
				Niederlassung Leipzig Filiale Werk Leipzig BMW AG, Leipzig	

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Haftungsreduzierung Anmietung Ersatz- fa	Local	2
Part I 0000160		

—	09/18/2019	Key	77439 km	28792	Key 0
---	------------	-----	----------	-------	-------

 17000 02/2021	 0	 17000 529	 0	 3700	 0 09/2019	 7000	 48000 02/2023	 0 09/2019
---	--	---	--	---	---	---	--	---

—	09/18/2019	Service	77439 km	28792	Automatic
				Niederlassung Leipzig Filiale Werk Leipzig, Leipzig	

 17000		 17000		 3700	 09/2019	 7000	 48000	 09/2019
				✓	✓	✓		✓

—	09/18/2019	Repair	77439 km	28792	Job
				Niederlassung Leipzig Filiale Werk Leipzig BMW AG, Leipzig	Job Job Job Job Job Job Job Job Job Job

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Umweltplakette ausstellen	Local	1 FRU
Flat rate unit I NL51 01 1		
Replace windshield		24 FRU

Flat rate unit | 51 31 011

Additional work with rain/light sensor 3 FRU

Flat rate unit | 61 35 994

Adjusting head-up display 1 FRU

Flat rate unit | 62 30 517

Calibrate KAFAS camera 1 FRU

Flat rate unit | 66 51 526

Repair flat rate, window, cold, 1 hr. 1

Part | 83 19 2 289 285

Bump stop 11

Part | 51 31 7 288 462

Drip moulding, left 1

Part | 51 31 7 285 947

Drip molding, right 1

Part | 51 31 7 285 948

Sound insulation f apron 1

Part | 51 48 7 325 890

Cover, windshield, top 1

Part | 51 31 7 285 940

Windshield, green, rain sensor / HUD 1

Part | 51 31 7 285 939

Nylon cord 0

Part | 81 43 2 344 272

Adhesive tape 1

Part | 83 19 2 157 772

Paint activator, stick 1

Part | 83 19 2 154 458

Replacemt.small plates, low beam sensor 1

Part | 61 35 9 856 157

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Abgasuntersuchung mit OBD und Sonde Local 5 FRU

Flat rate unit | NL00 52 7

Überprüfung nach § 29 STVZO Local 1

Part | 0012159

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Vier Reifen mit Runflatausrüstung ersetzt Local 29 FRU

Flat rate unit | NL36 02 3

Pirelli Cinturato P7 K1 r-f Part I 85 45 2 593 672	4
Clip Part I 36 11 6 766 311	4
Balance weight, zinc Part I 36 11 6 766 315	1
Balance weight, zinc Part I 36 11 6 766 316	3
Balance weight, zinc, w. adhesive foil Part I 36 11 6 766 332	2
Balance weight, zinc, w. adhesive foil Part I 36 11 6 766 334	1
Balance weight, zinc, w. adhesive foil Part I 36 11 6 766 339	1
Balance weight, zinc, w. adhesive foil Part I 36 11 6 766 343	1
Safety cleanser 2.0 Part I 83 19 2 364 762	4

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words: Info: Die Bremsscheiben der VA sind unter dem Mindestmaß TH und müssen,lt. BMW Richtlinien ersetzt werden.,Mindestmaß 224mm / Istmaß 223mm,-----
-,Info: Die Bremsscheiben d
er HA sind über dem Mindestmaß TH und müssen,lt. BMW Richtlinien nicht ersetzt werden.,Mindestmaß 184mm / Istmaß 191mm,-----,Achtung!
Während der ersten 200km keine mutwi
lligen Gewaltbremsungen,vornehmen.,

Front brake/rear brake service Flat rate unit I 00 00 613	13 FRU
Repair kit, brake pads asbestos-free Part I 34 10 6 859 181	1
Brake pad wear sensor, front left Part I 34 35 6 792 289	1
Repair kit, brake pads asbestos-free Part I 34 21 6 873 093	1
Brake pad wear sensor, rear Part I 34 35 6 792 292	1
Safety cleanser 2.0 Part I 83 19 2 364 762	2
Brake pad paste Part I 83 19 2 158 851	4

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Standard scope of service	2 FRU
Flat rate unit I 00 00 105	

— Job**Description:****Is interpreted as a repeat visit:** No**Customer's own words:** ... nur wenn notwendig !,

Removing and installing/replacing both front brake discs	3 FRU
Flat rate unit I 34 11 613	

Brake disc, ventilated	2
Part I 34 11 6 792 219	

Inner hex bolt	2
Part I 34 21 1 161 806	

Torx screw with washer	4
Part I 34 10 6 864 424	

— Job**Description:****Is interpreted as a repeat visit:** No**Customer's own words:**

Replace left and right wiper blade	1 FRU
Flat rate unit I 61 61 541	

Set of wiper blades	1
Part I 61 61 2 241 375	

— Job**Description:****Is interpreted as a repeat visit:** No**Customer's own words:**

Brake fluid service	4 FRU
Flat rate unit I 00 00 618	

Brake fluid DOT4 LV, low viscosity	1
Part I 83 13 0 443 030	

Safety cleanser 2.0	4
Part I 83 19 2 364 762	

— Job**Description:****Is interpreted as a repeat visit:** No**Customer's own words:**

Fahrzeugüberprüfung im Rahmen der Annahm	Local	0 FRU
Flat rate unit I 00 52 054		

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Pflegepaket 1
Part I 0099521

Local

1

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Ersatzfahrzeug fremd 1 Tag (Abrech. SEW)
Part I 00161









Local

1

— 02/06/2019 Key

62625 km

Key 0










— 02/06/2019 Service

62625 km

28792
Niederlassung
Leipzig Filiale
Werk Leipzig,
Leipzig

Automatic



— 02/05/2019 Repair

62625 km

28792
Niederlassung
Leipzig Filiale
Werk Leipzig
BMW AG,
Leipzig

Job
Job
Job
Job
Job
Job
Job
Job
Job
Job

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Standard scope of service
Flat rate unit I 00 00 105

2 FRU

— Job

Description:**Is interpreted as a repeat visit:** No**Customer's own words:**

Engine oil service Flat rate unit I 00 00 610	3 FRU
Set oil-filter element Part I 11 42 8 575 211	1
BMW Engine Oil LL04 0W30 Part I 83 21 2 405 950	5
Safety cleanser 2.0 Part I 83 19 2 364 762	1

— Job**Description:****Is interpreted as a repeat visit:** No**Customer's own words:**

Service - air filter insert Flat rate unit I 00 00 602	2 FRU
Air filter element Part I 13 71 8 511 668	1

— Job**Description:****Is interpreted as a repeat visit:** No**Customer's own words:**

Fuel filter service Flat rate unit I 00 00 604	3 FRU
Fuel filter cartridge Part I 13 32 8 572 522	1
Safety cleanser 2.0 Part I 83 19 2 364 762	1

— Job**Description:****Is interpreted as a repeat visit:** No**Customer's own words:**

Pollenfiltergehäuse mit Spezialreiniger Flat rate unit I NL64 00 2	Local	1 FRU
Service - microfilter Flat rate unit I 00 00 616		2 FRU
Microfilter/activated Carbon container Part I 64 11 9 237 555		1
Vehicle interior filt..f.housing cleaner Part I 83 19 2 451 455		1

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words: Scheinwerfer einstellen (LI U RE -07%),Nebelscheinwerfer einstellen (RE -24%),

Scheinwerfer einstellen (LI U RE -0,7% Flat rate unit I NL63 00 2	Local	2 FRU
---	-------	-------

Nebelscheinwerfer einstellen (RE -2,4% Flat rate unit I NL63 00 2	Local	2 FRU
---	-------	-------

Vehicle check service Flat rate unit I 00 00 624		6 FRU
---	--	-------

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words: Abläufe Aggregaterraum gereinigt,

AZ without specification/maintenance Flat rate unit I 00 99 000		2 FRU
--	--	-------

kostenlose Fahrzeugoberwäsche Part I 0011319	Local	1
---	-------	---

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Fahrzeugüberprüfung im Rahmen der Annahm Flat rate unit I 00 52 054	Local	0 FRU
--	-------	-------

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Motorölservice - zusätzliche AW Flat rate unit I IM00 25 0	Local	2 FRU
---	-------	-------

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Ersatzfahrzeug fremd 1 Tag (Abrech. SEW) Part I 00161	Local	1
--	-------	---

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

—	08/20/2018	Key	50226 km	28792	Key 0
---	------------	-----	----------	-------	-------

								
13000	13000	13000	13000	45000	0	30000	13000	0
12/2019	498	498	498		09/2019		12/2019	09/2019

—	08/20/2018	Repair	50231 km	28792	Job
				Niederlassung	Job
				Leipzig Filiale	Job
				Werk Leipzig	Job
				BMW AG,	Job
				Leipzig	Job
					Job
					Job

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words: Füllstand Betriebsflüssigkeiten und Frostschutzgehalt prüfen/ergänzen; Frostschutzgehalt
Kühlwasser: -25°C,

Füllstand Betriebsflüssigkeiten und Fros	Local	1 FRU
Flat rate unit I NL00 50 0		
Windshield Washer Antifreeze		2
Part I 83 12 2 413 061		

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Ersatzfahrzeug fremd 1 Tag (Abrech. SEW)	Local	1
Part I 00161		

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Ersatzfahrzeug (24 Stunden) Haftungsredu	Local	1
Part I 0000160		

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Vehicle service - check before expiry of warranty
Flat rate unit I 00 00 102

5 FRU

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Performing vehicle test
Flat rate unit I 00 00 556

2 FRU

Supporting the voltage of the vehicle electrical system/recharging the
vehicle electrical system battery
Flat rate unit I 61 21 528

1 FRU

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Service consultation at the vehicle
Flat rate unit I 00 52 050

1 FRU


— Job

Description:


Is interpreted as a repeat visit: No

Customer's own words:

— 12/11/2017 Key 31577 km 28792 Key 0



— 12/11/2017 Service 31577 km 28792 Automatic
Niederlassung
Leipzig Filiale
Werk Leipzig,
Leipzig



— 12/06/2017 Repair 31577 km 28792 Job
Niederlassung Job
Leipzig Filiale Job

Werk Leipzig
BMW AG,
Leipzig

Job
Job
Job
Job
Job
Job
Job
Job
Job
Job

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Engine oil service Flat rate unit I 00 00 610	3 FRU
Set oil-filter element Part I 11 42 8 575 211	1
BMW Engine Oil LL04 0W30 Part I 83 21 2 405 950	5
Safety cleanser 2.0 Part I 83 19 2 364 762	1

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Pollenfiltergehäuse mit Spezialreiniger Flat rate unit I NL64 00 2	Local	1 FRU
Service - microfilter Flat rate unit I 00 00 616		2 FRU
Microfilter/activated Carbon container Part I 64 11 9 237 555		1
Vehicle interior filt..f.housing cleaner Part I 83 19 2 451 455		1

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Standard scope of service Flat rate unit I 00 00 105	2 FRU
---	-------

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words: *E TA Steuergeräte programmieren ggf. AGR-Ventil,ersetzen offen durchführen,Info: AGR-Ventil mit TM laut TA geprüft i.O > AGR-Ventil muss im laut TA,nicht ersetzt werden,

Operating test module and programming control unit	8 FRU
Flat rate unit I 00 64 941	

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words: Kennzeichenunterlagen hinten ersetzen,

Kennzeichenunterlagen hinten ersetzen	Local	1 FRU
Flat rate unit I NL36 00 4		

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words: Info,- verbaute Rad-Reifenkombination ist laut Herstellervorgaben nicht,zulässig > nach Absprache SB Einzelgutachten über Dekra erstellen lassen,

Vier Reifen mit Runflatausrüstung ersetzt	Local	29 FRU
Flat rate unit I NL36 02 3		

Pirelli W 240 Sottozero II r-f	4
Part I 85 45 2 593 804	

Balance weight, zinc, w. adhesive foil	1
Part I 36 11 6 766 326	

Balance weight, zinc, w. adhesive foil	1
Part I 36 11 6 766 334	

Balance weight, zinc, w. adhesive foil	1
Part I 36 11 6 766 336	

Balance weight, zinc, w. adhesive foil	1
Part I 36 11 6 766 338	

Balance weight, zinc, w. adhesive foil	1
Part I 36 11 6 766 342	

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Ersatzfahrzeug fremd 1 Tag (Abrech. SEW)	Local	1
Part I 00161		

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

kostenlose Fahrzeugoberwäsche	Local	1
Part I 0011319		

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Motorölservice - zusätzliche AW
Flat rate unit I IM00 25 0

Local

2 FRU

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Fahrzeugüberprüfung im Rahmen der Annahm
Flat rate unit I 00 52 054

Local

0 FRU

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Haftungsreduzierung Ersatzwagen
Part I 0000160

Local

1

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Änderungsabnahme §21 StVZO - Winterradsa
Part I 0012159

Local

1

— 09/15/2016 Repair 3 km 04543 Job
Niederlassung Job
Leipzig BMW
AG, Leipzig

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

Free pre-delivery check
Flat rate unit I 00 00 009

9 FRU

Commissioning of electromechanical steering gear (EPS) / initialization

1 FRU

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words: