

Thank you for ordering from us!

www.checkvin.eu

Vehicle

BMW 318D A, 110kW

WBA8H71010A036550



Development code F31
Color platin-silber metallic
Actual integration level F020-22-03-552
Start of warranty March 17, 2017

Delivery stop



There are Technical Campaigns for this vehicle.

Technical Campaigns

Status	Campaign number	Description	Reservation
Open	10011150700	Replacing the exhaust gas recirculation cooler (high temperature) Delivery stop Local campaign number: -	
Open	10011350700	Exhaust gas recirculation cooler customer notification Local campaign number: -	
Reserved	10032550300	Check the driver's airbag, replace if necessary (conversion SDI) Delivery stop Local campaign number: -	BuNo: 25508

VIN-based goodwill

Status	Campaign number	Description
Open	1SACC011056	Exhaust gas recirculation cooler Bx7 Local campaign number: -

Special information

There are no campaigns available.

Restrictions on the warranty

There are no restrictions on the warranty.

⚠ Market-specific restrictions are not currently displayed. Please check this in WDF/WXE via S-Gate.

Live Diagnosis

 There are no service solutions for Live Diagnosis.

Service contracts

No BSI contracts available

Information on faults, workshop/Service Consultation

No information on faults is available.

Navigation map

Installed map	Enabling code (subscription)	Latest navigation map included in subscription	Latest navigation map subject to charge
Road Map EUROPE Route 2016-2 (as of: Feb 21, 2023)	Release code valid for navigation maps with release date up to Jun 30, 2021 (SWID: 00B40059).	Road Map EUROPE WEST Route 2021-1	Road Map EUROPE EAST Route 2024

Vehicle details

Vehicle type	Passenger car
Brand	BMW
Model	318D A
Body	TOUR
Vehicle identification number (last 7 characters)	A036550
Vehicle identification number (17 characters)	WBA8H71010A036550
Development code	F31
Steering	LL
Engine	B47U
Engine number	53299905
Exhaust re-treatment	EURO6, W, PI/CI, M, N1 I
Transmission	AUT
Transmission number	0815161WC5
Head unit serial number	MM01DFH2556107
Drive	HECK
Integration level	F020-16-11-502
Production date	Feb 22, 2017
Production works	Muenchen
Delivery date	Feb 27, 2017

Delivering Retailers	Juma Leuven, Herent, BE
National-market version	EUR
Paint code	C08
Upholstery code	BDAT
Model code	8H81
Base type	8H71
Lead type	8H81

Optional equipment

Optional equipment fitted at the factory:

















































01CA Selection of COP relevant vehicles
01CB CO2 package
0205 Automatic transmission
0216 Hydro steering-servotronic
0230 EU-specific additional contents
0255 Sports leather steering wheel
02FH BMW LA wheel, V Spoke 390
02VB Tire pressure display
02VC Tire repair kit
03AA Roof railing black
03L8 Exterior parts, satin-gloss aluminum
0420 Sun protection glazing
0423 Floor mats, velours
0493 Storage compartment package
04AE Armrest front, retractable
04CG Interior strips, "satin-silber" matt
0508 Park Distance Control (PDC)
0521 Rain sensor
0544 Cruise control with braking function
0548 Kilometer-calibrated speedometer
0606 Navigation system Business
0698 Area-Code 2 for DVD
06AC Intelligent emergency SOS call
06AE Teleservices
06NH Hands-free with USB interface
06WA Instrument cluster, expanded equipment
07LC Modell Advantage
0843 Power reduction
0868 Language version Dutch
0886 On-board vehicle literature Dutch
08KA Oil service interval, 24 mos./30,000 km
08R9 Refrigerant R1234yf
08S3 Automatic locking when driving off
A090 90 AH AGM battery
POL5 Cloth cushion


Retrofitted optional equipment:

This vehicle has no retrofits.


Vehicle histories

	Date	Type	Vehicle mileage					Dealer	Overview
—	01/16/2024	Key	237247 km					05683	Key 0
	 1200 08/2025  1200 08/2025	 1200 08/2025	 1200 08/2025	 60000 08/2025	 -15 2.1 %	 60000 08/2025	 1200 08/2025		
—	01/16/2024	Key	237247 km					05683	Key 0


	 1200 08/2025	 1200 08/2025	 1200 08/2025	 1200 08/2025	 60000 08/2025	 -15 2.1 %	 60000	 1200 08/2025	
—	09/28/2023	Key		214814 km	05683	Key 0			
	 24000 08/2025	 24000 08/2025	 24000 08/2025	 24000 08/2025	 80000	 01/2024	 70000	 24000 08/2025	
—	08/16/2023	Key		207415 km		Key 0			
	 -2000 6.5 % 02/2025		 -2000 02/2025		 90000	 01/2024	 80000	 29000 02/2027	
—	08/16/2023	Service		207415 km	05683 De Mey Maldegem , Maldegem	Automatic			
	 -2000 02/2025 ✓		 -2000 02/2025 ✓		 90000	 01/2024	 80000	 29000 02/2027	
—	07/24/2023	Key		203559 km		Key 0			
	 1800 02/2025		 1800 02/2025		 90000	 01/2024	 90000	 33000 02/2027	
—	04/26/2023	Key		186130 km		Key 10			
	 20000 02/2025		 20000 02/2025		 100000	 01/2024	 100000	 60000 02/2027	
—	02/21/2023	Key		174387 km		Key 0			
	 -2700 8.7 % 01/2024	 -2700 01/2024	 -2700 01/2024	 -2700 01/2024	 90000	 01/2024	 110000	 -2700 4.4 % 01/2024	
—	02/21/2023	Service		174387 km	05683 De Mey Maldegem , Maldegem	Automatic			
	 -2700 01/2024 ✓	 -2700 01/2024 ✓	 -2700 01/2024 ✓	 -2700 01/2024 ✓	 90000	 01/2024	 110000	 -2700 01/2024 ✓	
—	02/10/2023	Key		172515 km		Key 0			



— 07/27/2022 Key 148886 km Key 1



— 07/27/2022 Service 148886 km 05655 Louyet Sint-Pieters-Leeuw , St. Pieters Leeuw Automatic



— 07/27/2022 Warranty 148886 km 05655 Job: G0x G3x B47O Program control units (DDE) Job

— Job: G0x G3x B47O Program control units (DDE)

Description: G0x G3x B47O Program control units (DDE)

Is interpreted as a repeat visit: No

Customer's own words:

Program control units 8 FRU
Flat rate unit I 00 71 940

G0x G3x B47O Program control units (DDE)
Defect I 00 13 51 03 00

— Job

Description:


Is interpreted as a repeat visit: No

Customer's own words:

Implement fault memory and pressure sensor functional check (in conjunction with one of the traffic reports mentioned above (program control units) 1 FRU
Flat rate unit I 00 72 677

Defect I 00 13 67 03 00

— 07/12/2022 Key 147002 km Remote KeyRead



— 01/17/2022 Key 140634 km Key 1

700 10/2022 700 254	20000 -46 6.3 % 38000 30000 974	—	01/17/2022	Service	140634 km	05742 Ginion Waterloo , Waterloo	Automatic
700 09/2022 ✓ 700 09/2022 ✓	20000 12/2021 ✓ 38000 30000 09/2024	—	12/11/2020	Key	116709 km		Key 1
25000 10/2022 25000 650	60000 12/2021 100000 60000 1370	—	12/10/2020	Key	116661 km		Key 1
25000 10/2022 25000 651	60000 12/2021 100000 60000 1371	—	10/08/2020	Key	111694 km		Key 1
1200 12/2021 1200 413 1200 413	1200 413 70000 12/2021 30000 1200 12/2021	—	10/08/2020	Service	111694 km	05659 Juma Leuven , Herent	Automatic
1200 11/2021 ✓ 1200 11/2021 ✓ 1200 11/2021 ✓	1200 11/2021 ✓ 70000 30000 1200 11/2021 ✓	—	01/30/2020	Key	88534 km		Key 1
26000 12/2021 26000 661 26000 661	26000 661 90000 12/2021 47000 26000 12/2021	—	01/30/2020	Service	88534 km	05659 Juma Leuven , Herent	Automatic
26000 11/2021 26000 11/2021 26000 11/2021	26000 11/2021 90000 47000 26000 11/2021						

— 01/30/2020 Warranty 88534 km 05659 Job: Interior trim/decorative trim/knee pads, center console/center armrest, front
Job: Control unit, steering column switch cluster (SZL) including coil spring cassette

— Job: Interior trim/decorative trim/knee pads, center console/center armrest, front

Description: Interior trim/decorative trim/knee pads, center console/center armrest, front

Is interpreted as a repeat visit: No

Customer's own words:

Removing and installing the center console trim 6 FRU
Flat rate unit I 51 16 160

Interior trim/decorative trim/knee pads, center console/center armrest, front
Defect I 51 16 42 68 00

Trim, center console, sliding cover, frt 1
Part I 51 16 9 323 675

— Job: Control unit, steering column switch cluster (SZL) including coil spring cassette

Description: Control unit, steering column switch cluster (SZL) including coil spring cassette

Is interpreted as a repeat visit: No

Customer's own words:

Replacing steering column switch cluster 6 FRU
Flat rate unit I 61 31 513

Carrying out vehicle test 2 FRU
Flat rate unit I 00 00 556

Supporting voltage of the vehicle electrical system/recharging vehicle battery 1 FRU
Flat rate unit I 61 21 528

Control unit, steering column switch cluster (SZL) including coil spring cassette
Defect I 61 12 55 02 00

Switch unit steering column 1
Part I 61 31 9 351 148

— 12/19/2019 Key 83843 km Key 1



— 12/19/2019 Warranty 83843 km 05659 Job: F1x F2x F3x F4x G0x G1x G3x B47 Check EGR radiator, replace if necessary
Job: Exhaust-gas recirculation valve

— Job: F1x F2x F3x F4x G0x G1x G3x B47 Check EGR radiator, replace if necessary

Description: F1x F2x F3x F4x G0x G1x G3x B47 Check EGR radiator, replace if necessary

Is interpreted as a repeat visit: No

Customer's own words:

Check label/ replace exhaust-gas recirculation cooler and remount exhaust-gas recirculation valve; clean exhaust-gas recirculation pipe 29 FRU

Flat rate unit | 00 68 741

F1x F2x F3x F4x G0x G1x G3x B47 Check EGR radiator, replace if necessary
Defect | 00 11 40 05 00

exhaust cooler 1
Part | 11 71 8 596 444

Set of small parts 1
Part | 11 71 8 597 652

Pipe union 2
Part | 11 71 7 799 853

— Job: Exhaust-gas recirculation valve

Description: Exhaust-gas recirculation valve**Is interpreted as a repeat visit:** No**Customer's own words:**

Replacing the exhaust-gas recirculation valve 4 FRU
Flat rate unit | 11 71 501

Exhaust-gas recirculation valve
Defect | 11 71 01 84 00


EGR-valve 1
Part | 11 71 8 594 492

Hose clamp 2
Part | 07 12 9 952 104


Oval head screw 2
Part | 35 21 7 685 343

Gasket Steel 1
Part | 11 71 8 579 364


— 03/07/2019 Key 52440 km 07538 Key 1



— 03/01/2019 Key 51397 km Key 1



— 03/01/2019 Service 51397 km 05659 Juma Automatic

Leuven ,
Herent

— 03/01/2019 Repair 51397 km 05659 Juma Job

Leuven ,
Herent

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

!!! unknown BMW-Id ESTIMATE Onderhoudshistorie door middel van Local 0 FRU
 ICOM naar het motorvoertuig overdragen !!!
 Flat rate unit | -

Service standaard omvang
 Package | 0000105

Standard scope of service 2
 Flat rate unit | 00 00 105

Service luchtfilterelement
 Package | 0000602

Service - air filter insert 2
 Flat rate unit | 00 00 602

Air filter element 1
 Part | 13718511668

Service brandstoffilter
 Package | 0000604

Fuel filter service 3
 Flat rate unit | 00 00 604

Fuel filter cartridge 1
 Part | 13328572522

Service motorolie
 Package | 0000610

Engine oil service 3
 Flat rate unit | 00 00 610

Set oil-filter element 1
 Part | 11428575211

BMW Engine Oil LL04 5W30 5
 Part | 83212405948

Service microfilter
 Package | 0000616

Service - microfilter 2
 Flat rate unit | 00 00 616

Microfilter/activated Carbon container 1
 Part | 64119237555


Service voertuig-check
 Package | 0000624

Vehicle check service 6
 Flat rate unit | 00 00 624

— 02/26/2019 Key

51125 km

Key 0




— 04/11/2018 Key

24752 km

Key 1



— 04/11/2018 Service 24752 km 05659 Juma Automatic
Leuven ,
Herent



— 04/11/2018 Repair 24752 km 05659 Juma Job
Leuven ,
Herent

— Job

Description:

Is interpreted as a repeat visit: No

Customer's own words:

!!! unknown BMW-Id ESTIMATE Onderhoudshistorie door middel van Local 0 FRU
ICOM naar het motorvoertuig overdragen !!!
Flat rate unit I -

Service standaard omvang
Package I 0000105

Standard scope of service 2
Flat rate unit I 00 00 105

Service motorolie
Package I 0000610

Engine oil service 3
Flat rate unit I 00 00 610

Set oil-filter element 1
Part I 11428575211

BMW Engine Oil LL04 5W30 5
Part I 83212405948

Service microfilter
Package I 0000616

Service - microfilter 2
Flat rate unit I 00 00 616

Microfilter/activated Carbon container 1
Part I 64119237555