

GENERAL INFO

File	8205644
License plate	1RXG115
VIN	WBA8H71010A036550
Dossier	2017 019 044 / 227461
Make / Model	BMW 318D Touring 100kW Aut.
Mileage	242420
1st inscription	18/04/2017
Start from	
Available from	15/01/2024


CHECK POINTS

Description	Number	Pres	Remark
Original license plate		Y	
Keys	2	Y	
Spare wheel			
Towbar (+keys)			
Certificate of conformity		Y	
Registration certificate Part 1		Y	
Repair kit		Y	
RunOnFlat			
Charging cable			

DAMAGES

Id	Damage	Dossier nbr	Acceptable damage
DAMAGE 224.106.181			
71	Side View Mirror Left // Plastic Repair	224.106.181	N
159	Rear Bonnet / Rear Window / Replace	224.106.181	N
193	Door Rear Right // Painting	224.106.181	N
210	Door Front Right // Smart Repair Small	224.106.181	N
421	Seat Front Right // Repair	224.106.181	N
860	Interior Cleaning // Small	224.106.181	N

If any missing items (keys, accessories, car documents, etc.) are invoiced you still can return them to Arval within five business days after reception of the inspection report. You may send this by registered letter to / return it on site (Arval Belgium NV/SA, Ikaroslaan 99, 1930 Zaventem) .

DAMAGE PICTURES



Damage within Renta-norm

OTHER DAMAGES



Side View Mirror Left // Plastic Repair: E - Scratch



Rear Bonnet / Rear Window / Replace: E - Scratch




Door Rear Right // Painting: AA - Scratch +Dent



Door Front Right // Smart Repair Small: AA - Scratch +Dent



Seat Front Right // Repair: E - Scratch



Interior Cleaning // Small: W - Stain