

Thank you for ordering from us!
www.checkvin.eu

Vehicle

BMW 420D A, 140KW

WBA4E9104GG285998



Development code F36
Colour glacier-silber metallic
Actual integration level F020-22-07-530
Start of warranty 13 August 2015

Delivery stop



Technical Campaigns are available.

Technical campaigns

Status	Campaign number	Description	Reservation
Open	10011150700	Replacing the exhaust gas recirculation cooler (high temperature) Delivery stop Local campaign number: -	
Open	10011350700	Exhaust gas recirculation cooler customer notification Local campaign number: -	
Open	10032420300	Replacing driver's airbag part II (SDI) Delivery stop Local campaign number: -	

Warranty extension/VIN-based goodwill

Status	Campaign number	Description
Open	1SACC011056	Exhaust gas recirculation cooler Bx7 Local campaign number: -

Special information

There are no Campaigns for this vehicle.

Restrictions on the warranty

There are no restrictions on the warranty.

⚠ Market-specific restrictions are not currently displayed. Please check this in WDF/WXE via S-Gate.

Live Diagnosis

 There are no service solutions for Live Diagnosis.

Service contracts

No BSI contracts

Information on faults workshop/Service Consultation

There is no information on faults.

Navigation map

Note: The installed map cannot be clearly identified. Presumably one of the following maps is present in the vehicle.

Installed map	Enabling code (subscription)	Latest navigation map included in subscription	Latest navigation map subject to charge
Road Map EUROPE EVO 2015-3+ (As of: 11 Apr 2023)	Enabling code valid for navigation maps with release date up to 31 Dec 2099 (SWID: 00F10FFF).	Road Map EUROPE EVO 2024-2	-
Road Map EUROPE EVO 2015-3+ (As of: 11 Apr 2023)	-	-	-

Vehicle details

Vehicle type	Passenger car
Brand	BMW
Model	420D A
Body	COUPE
Vehicle identification number (last 7 digits)	G285998
Vehicle identification number (17 digits)	WBA4E9104GG285998
Development code	F36
Steering	LL
Engine	B47O
Engine number	68609320
Exhaust re-treatment	EURO6, W, PI/CI, M, N1 I
Transmission	AUT
Transmission number	0021958ZEN
Head unit serial number	HB2140F7645744
Drive	HECK
Integration level, works	F020-15-07-503
Production date	17 Jul 2015

Production plant	Dingolfing
Delivery date	20 Jul 2015
Delivering retailer	No information
National-market version	EUR
Paint code	A83
Upholstery code	HAAT
Model code	4E01
Basic type	4E91
Lead type	4E01

Optional equipment

Optional equipment ex works:



















01CA Selection of COP-relevant vehicles
 01CB CO2 equipment
 0230 EU-specific additional contents
 0258 Tyres with runflat properties
 02PA Locking wheel bolt
 02PF BMW LA wheel, M star spoke 403
 02TB Sport automatic gearbox
 02VB Tyre pressure display
 0316 automatic trunk lid mechanism
 0337 M Sports package
 0423 Floor mats velours
 0428 Warning triangle and first aid kit
 0465 Through-loading system
 0481 Sports seat
 0493 Storage compartment package
 0494 Seat heating driver/passenger
 04AE Armrest front, retractable
 04WG Alum. Hexagon accent black high-gloss
 0502 Headlight cleaning system
 0508 Park Distance Control (PDC)
 0521 Rain sensor
 0522 Xenon Light
 0534 Automatic air conditioning
 0544 Cruise control with braking function
 0548 Kilometre speedo
 0563 Lights package
 0575 Additional 12V power socket
 05DA Passenger airbag deactivation
 0609 Navigation system Professional
 0610 Head-up display
 0698 Area-Code 2 for DVD
 06AC Intelligent emergency call
 06AE Teleservices
 06AK Connected Drive Services
 06AP Remote Services
 06NS Comfort telephony w/ enhanced Smartphone
 06S4 Language version Swedish
 06UH Traffic Information
 06WA Instrument panel with extended scope
 0704 M Sports suspension
 0710 M leather steering wheel
 0715 M Aerodynamics package
 0760 High gloss shadow line
 0775 Headlining anthracite
 07LF Modell M Sport
 0842 Cold-climate version
 0850 Dummy-SALAPA
 0885 On-board literature, Swedish
 08KA Oil service interval 24 mths / 30,000 km
 08SM Car ident. number visible from outside

Retrofitted optional equipment:

This vehicle has no retrofits.

08TG Thiefproofing device
0993 model year code in VIN
09AA Outer skin protection
A090 90 Ah AGM battery
POLS Cloth cushion

Vehicle histories

















	Date	Type	Vehicle mileage			Retailer	Overview
—	01/09/2023	Key	221157 Km			47681	Remote KeyRead
	 25000 05/2025	 25000 05/2025	 25000 05/2025	 25000 05/2025	 16000 09/2023	 70000 05/2025	 25000 05/2025
—	19/04/2023	Key	212606 Km				Remote KeyRead
	 7000 09/2023	 7000 09/2023	 7000 09/2023	 23000 09/2023	 1900 09/2025	 38000 09/2025	
—	19/10/2022	Key	202872 Km			47681	Key 1
	 18000 09/2023	 18000 09/2023	 18000 09/2023	 31000 09/2023	 5000 09/2025	 47000 09/2025	
—	17/10/2022	Key	202788 Km				Key 1
	 18000 09/2023	 18000 09/2023	 18000 09/2023	 31000 09/2023	 5000 09/2025	 47000 09/2025	
—	11/10/2022	Key	202459 Km			47681	Key 1
	 18000 09/2023	 18000 09/2023	 18000 09/2023	 32000 09/2023	 5000 09/2025	 47000 09/2025	
—	11/10/2022	Warranty	202459 Km			47681	Job Job: G0x G3x B47O Programming control units (DDE)
—	Job						
	Description:						
	Considered as a repeat visit	No					
	Customer's own words						
	Defect I 00 00 11 11 NE						
—	Job: G0x G3x B47O Programming control units (DDE)						
	Description:	G0x G3x B47O Programming control units (DDE)					
	Considered as a repeat visit	No					

Customer's own words

Program control units
Flat rate unit I 00 71 374

9 FRU

G0x G3x B47O Programming control units (DDE)
Defect I 00 13 51 03 00

- 18/06/2021 Key 184484 Km Key 1
- | | | | | | | | | |
|---|---|---|---|---|---|---|--|---|
|  |  |  |  |  |  |  |  |  |
| -13000 | -13000 | -13000 | -13000 | 60000 | 25000 | -13000 | -13000 | -13000 |
| 09/2022 | 433 | 433 | 433 | 09/2022 | | 09/2022 | | |
- 03/02/2020 Key 120506 Km 36331 Key 1
- | | | | | | | | | |
|---|---|---|---|---|---|---|--|---|
|  |  |  |  |  |  |  |  |  |
| 30000 | | 30000 | | 110000 | 10000 | 60000 | | |
| 01/2022 | | 688 | | 09/2020 | | 1408 | | |
- 29/01/2020 Key 119950 Km 36331 Key 1
- | | | | | | | | | |
|--|--|--|--|--|--|--|---|--|
|  |  |  |  |  |  |  |  |  |
| 30000 | | 30000 | | 110000 | 10000 | 60000 | | |
| 01/2022 | | 693 | | 09/2020 | | 1413 | | |
- 29/01/2020 Warranty 119969 Km 36331 Job: F1x F2x F3x F4x G0x G1x G3x B47 Check and if required replace exhaust-gas recirculation cooler

- Job: F1x F2x F3x F4x G0x G1x G3x B47 Check and if required replace exhaust-gas recirculation cooler

Description: F1x F2x F3x F4x G0x G1x G3x B47 Check and if required replace exhaust-gas recirculation cooler

Considered as a repeat visit No

Customer's own words

Check label/replace exhaust gas recirculation module and clean exhaust
gas recirculation pipe
Flat rate unit I 00 68 740 27 FRU

Performing additional work for pressure sensor function 3 FRU
Flat rate unit I 00 68 742

F1x F2x F3x F4x G0x G1x G3x B47 Check and if required replace
exhaust-gas recirculation cooler
Defect I 00 11 40 05 00

exhaust cooler 1
Part I 11 71 8 596 444

Gasket Steel 1
Part I 11 62 8 576 287





























Hose clamp 2
Part I 07 12 9 952 104

Gasket Steel 1
Part I 11 61 8 571 005

Gasket Steel 1
Part I 11 71 8 579 364

Pipe union 2
Part I 11 71 7 799 853

Torx bolt
Part I 11 71 2 249 909

—	10/01/2020	Service	118689 Km	OSS-60019731 Fosie Bilverkstad AB, Malmö	Manual
				    	 
—	30/01/2019	Key	87469 Km	24812	Key 1
				    	 
—	30/01/2019	Service	87469 Km	24812 Förenade Bil AB, Malmö Förenade Bil AB , Malmö	Automatic
				    	 
—	23/01/2019	Key	86766 Km		Key 1
				    	 
—	28/09/2018	Key	75594 Km		Key 1
				    	 
—	28/09/2018	Service	75594 Km	24812 Förenade Bil AB , Malmö	Automatic
				    	 
—	28/09/2018	Warranty	75549 Km	24812	Job: Exhaust gas recirculation valve (EGR)
—					Job: Exhaust gas recirculation valve (EGR)

Description: Exhaust gas recirculation valve (EGR)

Considered as a repeat visit No

Customer's own words

Performing vehicle test Flat rate unit 00 00 006	4 FRU
Supporting the voltage of the vehicle electrical system/recharging the vehicle electrical system battery Flat rate unit 61 21 528	1 FRU
Replacing exhaust gas recirculation valve Flat rate unit 11 71 501	7 FRU
Programming/encoding control unit(s) including deleting fault memories Flat rate unit 61 00 730	4 FRU
Exhaust gas recirculation valve (EGR) Defect 11 71 01 83 00	
EGR-valve Part 11 71 8 513 132	1
Hose clamp Part 16 12 1 176 918	2
Gasket Steel Part 11 71 8 579 364	1
Hex Bolt with washer Part 07 11 9 905 750	1
Oval head screw Part 35 21 7 685 343	2

— 28/09/2018 Warranty 75549 Km 24812 Job

— Job

Description:

Considered as a repeat visit No

Customer's own words

Brake fluid service Flat rate unit 00 00 618	0 FRU
Service - standard scope Flat rate unit 00 00 105	0 FRU
Defect 87 34 00 00 SE	

— 25/01/2018 Key 59127 Km 24812 Key 1

							
1500	1500	1500	1500	60000	40000	1500	1500
11/2018	276	276	276	07/2018		11/2018	

— 25/01/2018 Service 59127 Km 24812 Automatic
Förenade Bil AB, Malmö

							
1500	1500	1500	1500	60000	40000	1500	1500
10/2018	10/2018	10/2018	10/2018				
✓	✓	✓	✓				✓

— 25/01/2018 Warranty 59127 Km 24812 Job

Job
Job
Job
Job

— Job

Description:**Considered as a repeat visit** No**Customer's own words**

Engine oil service Flat rate unit I 00 00 610	0 FRU
--	-------

Service - standard scope Flat rate unit I 00 00 105	0 FRU
--	-------

Defect I 87 00 02 00 SE	
-------------------------	--

Set oil-filter element Part I 11 42 8 575 211	1
--	---

— Job

Description:**Considered as a repeat visit** No**Customer's own words**

Service, vehicle check Flat rate unit I 00 00 624	0 FRU
--	-------

Defect I 87 00 05 00 SE	
-------------------------	--

— Job

Description:**Considered as a repeat visit** No**Customer's own words**

Service - air filter element Flat rate unit I 00 00 602	0 FRU
--	-------

Defect I 87 13 01 00 SE	
-------------------------	--

Air filter element Part I 13 71 8 511 668	1
--	---

— Job

Description:**Considered as a repeat visit** No**Customer's own words**

Service fuel filter Flat rate unit I 00 00 604	0 FRU
---	-------

Defect I 87 13 02 00 SE	
-------------------------	--

Fuel filter cartridge Part I 13 32 8 572 522	1
---	---

— Job

Description:**Considered as a repeat visit** No**Customer's own words**

Microfilter service
Flat rate unit I 00 00 616

0 FRU

Defect I 87 64 01 00 SE

Microfilter/activated Carbon container
Part I 64 11 9 237 555

1

— 25/01/2018 Warranty 59127 Km 24812 Job
Job

— Job

Description:

Considered as a repeat visit No

Customer's own words

Defect I 00 00 11 11 SE

— Job

Description:

Considered as a repeat visit No

Customer's own words

Replacing the exhaust-gas recirculation cooler
Flat rate unit I 00 64 726

23 FRU

Defect I 00 11 36 04 00


exhaust cooler
Part I 11 71 8 596 444

1


Set of small parts
Part I 11 71 8 597 652

1

— 30/06/2017 Key 45380 Km 24812 Key 1



— 30/06/2017 Service 45380 Km 24812 Automatic
Förenade Bil AB, Malmö



— 30/06/2017 Warranty 45380 Km 24812 Job: F1x F2x F3x B47
programming control units and if necessary, replacing the EGR valve

— Job: F1x F2x F3x B47 programming control units and if necessary, replacing the EGR valve

Description: F1x F2x F3x B47 programming control units and if necessary, replacing the EGR valve

Considered as a repeat visit No


Customer's own words

Carrying out the ABL and programming the control units
Flat rate unit I 00 64 246

10 FRU

F1x F2x F3x B47 programming control units and if necessary, replacing
the EGR valve
Defect I 00 11 45 04 00

— 24/01/2017 Key 35909 Km 24812 Key 1



— 24/01/2017 Warranty 35909 Km 24812 Job: F1x F2x F3x F4x B47
Replacing the exhaust-gas recirculation valve

— Job: F1x F2x F3x F4x B47 Replacing the exhaust-gas recirculation valve

Description: F1x F2x F3x F4x B47 Replacing the exhaust-gas recirculation valve

Considered as a repeat visit No

Customer's own words

Replace exhaust-gas recirculation valve
Flat rate unit I 00 64 011

10 FRU

F1x F2x F3x F4x B47 Replacing the exhaust-gas recirculation valve
Defect I 00 11 15 04 00

EGR-valve
Part I 11 71 8 594 492

1

Gasket Steel
Part I 11 71 8 579 364

1


Oval head screw
Part I 35 21 7 685 343

2


Hose clamp
Part I 07 12 9 952 104

2

— 07/11/2016 Key 30830 Km 24812 Key 1



— 07/11/2016 Service 30830 Km 24812 Automatic
Förenade Bil
AB, Malmö



— 07/11/2016 Warranty 30830 Km 24812 Job
Job

— Job

Description:

Considered as a repeat visit No

Customer's own words

Engine oil service Flat rate unit I 00 00 610	0 FRU
--	-------

Service - standard scope Flat rate unit I 00 00 105	0 FRU
--	-------

Defect I 87 00 02 00 SE	
-------------------------	--

Set oil-filter element Part I 11 42 8 575 211	1
--	---

— Job

Description:

Considered as a repeat visit No

Customer's own words

Microfilter service Flat rate unit I 00 00 616	0 FRU
---	-------

Defect I 87 64 01 00 SE	
-------------------------	--

Microfilter/activated Carbon container Part I 64 11 9 237 555	1
--	---

Pollen-filter housing cleaner Part I 83 19 2 180 509	1
---	---