

BMW 3er 320d M Sport



VAT deductible (19%)


Stock number:	TE51794
Build year:	2016
First registration:	06/2016
Odometer reading:	231,101 km
Fuel type:	Diesel
Horsepower:	140 kW / 190 HP
Cylinder capacity:	1,995 ccm
Gear box:	Automatic
Inspection expires:	06/2025
Body type:	Combi
Total number of owners:	Not available
Keys:	2
Prior damage / Accident according to previous owner	Yes
Repair Cost	Unknown
Country of origin:	DE
Country of last registration:	-
Environmental class:	EURO 6
COC papers:	No
Seats:	5
Color:	White (Original)
Upholstery:	Alcantara (Original)
Door count:	5
CO2 Emissions:	119g/km



Car location

-



0:00 / 0:29





MAIN CAR DETAILS

CAR HIGHLIGHTS / ADDITIONAL PHOTOS



General



General



General

CAR EQUIPMENT

Some content has been automatically translated.

 Towbar	Trailer hitch (swiveling ball head)
 Heated seats	Front seat heating
 Sunroof	Panoramic roof (Transparent)
 Park Distance Control	Park-Distance-Control (PDC) front and rear
 Power steering	Power steering Servotronic
 Hands-free system	Bluetooth hands-free system with USB audio interface Bluetooth hands-free system with advanced smartphone integration
 Sport undercarriage	Sport suspension (M-Technic)
 Sport seats	Sports seats in front
 Navigation System	Business audio and navigation system ConnectedDrive navigation package Professional audio-navigation system
 Airbag	Disconnectable passenger airbag Driver side airbag / passenger side airbag Rear Cranial Airbag System Front head airbag system Side airbag rear Front side airbag
 AC System	Automatic dual-zone air conditioning with automatic air circulation control
 DPF / FAP	Particulate filter
 ESP	Dynamic Stability Control (DSC)
 Immobilizer	Immobilizer



Cruise Control

Cruise control, Active with Stop&Go function



On-board computer

External temperature indicator
On-board computer



Entertainment system

BMW Professional audio system (Radio/CD player MP3 compatible)
Instrument cluster (extended scope)



Theft alarm system / security alarm

Alarm system



ABS

Anti-lock Braking System (ABS)

CAR SERVICE DETAILS

Service book details:

Digital service book

Service appointment:

All

Last service on:

03/06/2024

Last service Mileage:

211,761 km



Drive belt change on:

-

Drive belt change Mileage:

-

Car service images 3 images available



TEST DRIVE INFORMATION

TEST DRIVE LOCATION: ON PUBLIC STREET < 80KM/H (LOWER SPEED)

NO SPECIFIC FINDINGS

CAR DATA ACCORDING TO IDENTIFICATION NUMBER (VIN)

Some content has been automatically translated.

-  Color monitor (6.5 """)
-  AUX-IN connection (AUX-IN)
-  Security system Active Protection
-  Storage package
-  Ambient lighting
-  Exhaust system (dual pipes) with chrome trim
-  Exterior finish: Shadow-Line high gloss
-  Check Control System
-  Anthracite headliner (BMW Individual)
-  Dynamic brake lights



PAINT THICKNESS NEW

Hood	112 µm
Roof	113 µm
Front fender left	125 µm
Front fender right	99 µm
Rear fender left	114 µm
Rear fender right	575 µm
Front door left	137 µm
Front door right	200 µm
Rear door left	100 µm
Rear door right	412 µm
Tailgate (Boot lid)	99 µm

CAR DAMAGE

DAMAGE AREAS

Sub-area images are merely displayed for orientation purposes and the damage summary reports the area's condition in detail. Please note that we take photos of all significant damages. Minor damage will be displayed below in the table without a corresponding image.



Deep scratch - down to primer

1/10



Deep scratch - down to primer

2/10



Paint damage

3/10



Paint damage

4/10



Professional repaint

5/10

No damage specific images



Professional repaint

6/10

No damage specific images



Deep scratch - down to primer

7/10



Paint damage

8/10



9/10



10/10

Damage and severity

FRONT BUMPER

6-10 SCRATCHES

Length: ≥20mm & <50mm Deep scratch - down to primer

HOOD

6-10 STONE CHIPS

Width: >3mm Paint damage

WINDSCREEN

3 STONE CHIPS

Width: ≤3mm Not in driver's eyeline

0

DAMAGE SUMMARY

The results of this car's evaluation are summarised in the DAMAGE SUMMARY table and visualised in the DAMAGE AREAS section below.

Damage / Part	Severity
1 REPAINT Rear right fender (1)	Thickness: ≥500µm , Professional repaint
1 REPAINT Rear right door (1)	Thickness: ≥250µm & <500µm , Professional repaint
1 REPAINT	Thickness: ≥125µm & <250µm , Professional repaint

Front right door (1)

10-14 Front bumper (6-10) Rear bumper (4)	Length: ≥20mm & <50mm , Deep scratch - down to primer
---	---


10-14 Hood (6-10) Roof (4)	Width: >3mm , Paint damage
--------------------------------------	----------------------------

3 STONE CHIPS Windscreen (3)	Width: ≤3mm , Not in driver's eyeline
--	---------------------------------------

2 WORN OUT Steering Wheel (1) Front door interior left (1)
--

MAIN WHEELS DETAILS

This section visualises the state of the car's tires, brake pad and disc condition. In the case that any rim-related damages are found on this car they will be displayed in the car damages section.



FRONT LEFT - (1/4)

Tire type

All season

DOT

0121

Profile depth (mm)

5

Tire condition

No issues found 

Rim type

Aluminium

Brake type

Disc brake

Brake pad thickness

≥ 3mm 

Brake disc condition

No issues found 

SECONDARY WHEELS DETAILS

FRONT LEFT - (1/4)

Tire type

Summer

DOT

0121

Profile depth (mm)

3

Tire condition

One-sided wear 

Rim type

Aluminium supplier