



BMW 4er 418d Gran Coupé





Stock number:	DK22019
Build year:	2014
First registration:	04/2015
Odometer reading:	243,477 km
Fuel type:	Diesel
Horsepower:	105 kW / 143 HP
Cylinder capacity:	1,995 ccm
Gear box:	Automatic
Inspection expires:	12/2025
Body type:	Coupé
Total number of owners:	4 (Including car dealers)
Keys:	2
Prior damage / Accident according to previous owner	No
Country of origin:	ES
Country of last registration:	ES
Environmental class:	EURO 6
COC papers:	No
Seats:	5
Color:	Gray (Original)
Upholstery:	Cloth (Original)
Door count:	4
CO2 Emissions:	124g/km




Car location

-



0:00 / 0:18







MAIN CAR DETAILS

CAR HIGHLIGHTS / ADDITIONAL PHOTOS




General



General



General




General



General



General



General



General



General



General




General



General



General



General



General



General



General



General



General

CAR EQUIPMENT

Some content has been automatically translated.

✓ Xenon lights	Bi-Xenon headlights
✓ Park Distance Control	Area view
✓ Power steering	Power steering Servotronic
✓ Hands-free system	Hands-free with USB interface Bluetooth hands-free device with expanded smartphone integration
✓ Sport undercarriage	Sport suspension (M-Technic)
✓ Sport seats	Sports seats in front
✓ Navigation System	Professional audio-navigation system
✓ Airbag	Disconnectable passenger airbag Driver side airbag / passenger side airbag Front side airbag Front head airbag system Rear Cranial Airbag System
✓ AC System	Automatic 2-zone climate control with automatic air recirculation control, expanded size
✓ DPF / FAP	Particulate filter
✓ Power windows	Electric windows front + rear
✓ ESP	Dynamic Stability Control (DSC) with expanded scope
✓ Immobilizer	Immobilizer
✓ On-board computer	Gear shift indicator On-board computer External temperature indicator



Entertainment system

BMW Professional audio system (Radio/CD player MP3 compatible)
BMW Professional audio system (Radio / DVD player compatible with MP3)
Instrument panel (enlarged size)



ABS

Anti-lock Braking System (ABS)

CAR SERVICE DETAILS

Service book details:

Not available

Service appointment:

Some

Last service on:

06/28/2024

Last service Mileage:

231,126 km


Drive belt change on:

-

Drive belt change Mileage:

-

Car service images 1 image



TECHNICAL INSPECTION


Date of latest technical inspection:

12/19/2023

Mileage at latest technical inspection:

233,903 km

Technical inspection images 1 image



TEST DRIVE INFORMATION

TEST DRIVE LOCATION: ON PUBLIC STREET < 80KM/H (LOWER SPEED)

NO SPECIFIC FINDINGS

CAR DATA ACCORDING TO IDENTIFICATION NUMBER (VIN)

Some content has been automatically translated.

-  Automatic headlight range control
-  Color monitor (6.5 """)
-  AUX-IN connection (AUX-IN)
-  Interior finish: Interior trim silver-satin, matte
-  Velvet Carpets
-  Front seats mechanically adjustable
-  Regenerative braking
-  Body: 4 doors
-  Check Control System
-  Automatic front and rear seat belts



PAINT THICKNESS NEW

Hood	160 µm
Roof	154 µm
Front fender left	165 µm
Front fender right	139 µm
Rear fender left	141 µm
Rear fender right	200 µm
Front door left	196 µm
Front door right	231 µm
Rear door left	216 µm
Rear door right	262 µm
Tailgate (Boot lid)	138 µm

CAR DAMAGE

DAMAGE AREAS

Sub-area images are merely displayed for orientation purposes and the damage summary reports the area's condition in detail. Please note that we take photos of all significant damages. Minor damage will be displayed below in the table without a corresponding image.



Deep scratch - down to primer

1/15



Deep scratch - down to primer

2/15



Deep scratch

3/15



Professional repaint

4/15

No damage specific images



Professional repaint

5/15

No damage specific images



Deep scratch - down to primer

6/15



Deep scratch - down to primer

7/15



Deep scratch - down to primer

8/15

No damage specific images



9/15



10/15



11/15



12/15



13/15



14/15



15/15

FRONT BUMPER

3 SCRATCHES

Length: ≥50mm & <100mm Deep scratch - down to primer


DAMAGE SUMMARY

The results of this car's evaluation are summarised in the DAMAGE SUMMARY table and visualised in the DAMAGE AREAS section below.

Damage / Part	Severity
1 CAR WRAPPING	
Rear right door window (1)	
1 REPAINT	
Rear right door (1)	Thickness: ≥250µm & <500µm , Professional repaint
3 REPAINT	
Rear left door (1) Rear right fender (1) Front right door (1)	Thickness: ≥125µm & <250µm , Professional repaint
7 SCRATCHES	
Front bumper (3) Rear bumper (4)	Length: ≥50mm & <100mm , Deep scratch - down to primer
4 SCRATCHES	
Front right rim (4)	Length: ≥25mm , Deep scratch
4 SCRATCHES	
Front left door (4)	Length: <20mm , Deep scratch - down to primer
7 WORN OUT	
Front door interior right (1) Center console (1) Center console (1) Door interior rear right (1) Door interior rear left (1) Front door interior left (1) Steering Wheel (1)	

MAIN WHEELS DETAILS [i](#)

This section visualises the state of the car's tires, brake pad and disc condition. In the case that any rim-related damages are found on this car they will be displayed in the car damages section.



FRONT LEFT - (1/4)

Tire type

Summer

DOT

3220

Profile depth (mm)

5

Tire condition

No issues found

Rim type

Aluminium

Brake type

Disc brake

Brake pad thickness

≥ 3mm

Brake disc condition

No issues found