

BMW 3er 320d Lounge





Stock number:	VR10946
Build year:	2016
First registration:	09/2016
Odometer reading:	240,302 km
Fuel type:	Diesel
Horsepower:	140 kW / 190 HP
Cylinder capacity:	1,995 ccm
Gear box:	Automatic
Inspection expires:	07/2025
Body type:	Combi
Total number of owners:	2
Keys:	2
Prior damage / Accident according to previous owner	Yes
Country of origin:	FR
Country of last registration:	-
Environmental class:	EURO 6
COC papers:	No
Seats:	5
Color:	Gray (Original)
Upholstery:	Leather (Original)
Door count:	5
CO2 Emissions:	119g/km



Car location

FR, Biarritz



0:00 / 0:19







MAIN CAR DETAILS

CAR HIGHLIGHTS / ADDITIONAL PHOTOS



General



General



General

CAR EQUIPMENT




Some content has been automatically translated.

 Heated seats	Front seat heating
 Park Distance Control	Rearview camera Park-Distance-Control (PDC) front and rear
 Power steering	Power steering Servotronic
 Hands-free system	Bluetooth hands-free with USB audio interface
 Navigation System	Professional audio-navigation system
 Airbag	Driver side airbag / passenger side airbag Disconnectable passenger airbag Side airbag rear Front side airbag Rear Cranial Airbag System Front head airbag system
 AC System	Automatic air conditioning
 DPF / FAP	Particulate filter
 ESP	Electronic Stability Program (ESP)
 Immobilizer	Immobilizer
 Cruise Control	Cruise control, Active with Stop&Go function
 On-board computer	External temperature indicator On-board computer
 Entertainment system	BMW Professional audio system (Radio/CD player MP3 compatible) Combiné d'instruments (fonctionnalité étendue)
 ABS	Anti-lock Braking System (ABS)

CAR SERVICE DETAILS

Service book details:	Digital service book
Service appointment:	Some
Last service on:	12/18/2019
Last service Mileage:	116,394 km
Drive belt change on:	-
Drive belt change Mileage:	-

Car service images 3 images available



TEST DRIVE INFORMATION

TEST DRIVE LOCATION: ON PUBLIC STREET < 80KM/H (LOWER SPEED)

NO SPECIFIC FINDINGS

CAR DATA ACCORDING TO IDENTIFICATION NUMBER (VIN)

Some content has been automatically translated.

-  Driver Assistance System: Front collision warning with brake function
-  Driving assistance system: lane departure warning system
-  Driving Assistance System: Driving Assistant
-  Color display (6.5 inches)
-  AUX-IN connection (AUX-IN)
-  Rear headrests foldable
-  Trunk cover / Blind
-  Body: 5-door
-  NOx storage catalyst (BMW Blue Performance)
-  Dynamic brake lights


PAINT THICKNESS NEW

Hood	109 µm
Roof	109 µm
Front fender left	112 µm
Front fender right	119 µm
Rear fender left	113 µm
Rear fender right	103 µm
Front door left	98 µm
Front door right	117 µm
Rear door left	104 µm
Rear door right	124 µm
Tailgate (Boot lid)	114 µm

CAR DAMAGE

DAMAGE AREAS

Sub-area images are merely displayed for orientation purposes and the damage summary reports the area's condition in detail. Please note that we take photos of all significant damages. Minor damage will be displayed below in the table without a corresponding image.



Deep scratch - down to primer

1/31

No damage specific images



Deep scratch - down to primer

2/31

No damage specific images



Deep scratch - down to primer

3/31

No damage specific images



Deep scratch

4/31



Deep scratch - down to primer

5/31

No damage specific images



Deep scratch

6/31



Deep scratch - down to primer

7/31

No damage specific images



Minimal not fitting parts, no grinding issues

8/31



Deep scratch - down to primer

9/31

No damage specific images



Deep scratch - down to primer

10/31

No damage specific images



Deep scratch

11/31



Deep scratch - down to primer

12/31

No damage specific images



Deep scratch

13/31



14/31



15/31



16/31



17/31



18/31



19/31



20/31



21/31



22/31



23/31



24/31



25/31



26/31



27/31



28/31



29/31



30/31



31/31

Damage and severity

FRONT LEFT FENDER

6-10 SCRATCHES

 **0**

Length: <20mm Deep scratch - down to primer

LEFT SIDE SKIRTS

11-15 SCRATCHES

 **0**

Length: <20mm Deep scratch - down to primer


DAMAGE SUMMARY

The results of this car's evaluation are summarised in the DAMAGE SUMMARY table and visualised in the DAMAGE AREAS section below.

Damage / Part	Severity
1 BODY GAP Rear bumper (1)	Minimal not fitting parts, no grinding issues
34-50 Front left rim (11-15) Rear left rim (11-15) Rear right rim (6-10) Front right rim (6-10)	Length: <25mm , Deep scratch
131-183 Front bumper (16-20) Hood (16-20) Left side skirts (11-15) Front left fender (6-10) Front left door (11-15) Rear left door (11-15) Rear left fender (6-10) Rear bumper (16-20) Tailgate (6-10) Rear right fender (6-10) Rear right door (6-10) Front right door (6-10) Right side skirts (6-10) Front right fender (3) Roof (5)	Length: <20mm , Deep scratch - down to primer
18 WORN OUT Steering Wheel (1) Driver seat (1) Driver seat (1) Front door interior left (1) Seat back left (1) Passenger seat (1) Door interior rear left (1) Floor covering (1) Headliner (1) Door interior rear right (1) Passenger seat (1) Passenger seat (1) Front door interior right (1) Floor covering (1) Dashboard (1) Dashboard (1) Dashboard (1) Headliner (1)	

MAIN WHEELS DETAILS ⓘ

This section visualises the state of the car’s tires, brake pad and disc condition. In the case that any rim-related damages are found on this car they will be displayed in the car damages section.



FRONT LEFT - (1/4)

Tire type
Summer

DOT
1723

Profile depth (mm)
4

Tire condition
No issues found ✓

Rim type
Aluminium

Brake type
Disc brake

Brake pad thickness
< 3mm ⚠

Brake disc condition
No issues found ✓