

Thank you for ordering from us!
www.checkvin.eu

Vehicle

BMW 320D XDR A, 140KW

WBA8J11070K631818



Development code F31
Colour mineral-weiss metallic
Actual integration level F020-22-07-530
Start of warranty 1 February 2017

Delivery stop



Technical Campaigns are available.

Technical campaigns

Status	Campaign number	Description	Reservation
Open	10032620300	Replacing driver's airbag part III (SDI)  Delivery stop Local campaign number: -	

Warranty extension/VIN-based goodwill

Status	Campaign number	Description
Open	1SACC011056	Exhaust gas recirculation cooler Bx7 Local campaign number: -

Special information

There are no Campaigns for this vehicle.

Restrictions on the warranty

There are no restrictions on the warranty.

⚠ Market-specific restrictions are not currently displayed. Please check this in WDF/WXE via S-Gate.

Live Diagnosis

 There are no service solutions for Live Diagnosis.

Service contracts

No BSI contracts

Information on faults workshop/Service Consultation

There is no information on faults.

Navigation map

Installed map	Enabling code (subscription)	Latest navigation map included in subscription	Latest navigation map subject to charge
Road Map EUROPE Route 2016-1 (As of: 25 Jul 2024)	Enabling code valid for navigation maps with release date up to 31 Dec 2025 (SWID: 00B4008F).	Road Map EUROPE EAST Route 2025	-

Vehicle details

Vehicle type	Passenger car
Brand	BMW
Model	320D XDR A
Body	TOUR
Vehicle identification number (last 7 digits)	K631818
Vehicle identification number (17 digits)	WBA8J11070K631818
Development code	F31
Steering	LL
Engine	B47O
Engine number	57149633
Exhaust re-treatment	EURO6, W, PI/CI, M, N1 I
Transmission	AUT
Transmission number	0130587ZN5
Head unit serial number	MM01DFG1631729
Drive	ALLR
Integration level, works	F020-16-03-504
Production date	27 May 2016
Production plant	Muenchen
Delivery date	28 May 2016
Delivering retailer	AUTOSTAR SPA, TRIESTE, IT
National-market version	EUR
Paint code	A96
Upholstery code	CBAT
Model code	8J21
Basic type	8J11
Lead type	8J21

Optional equipment

Optional equipment ex works:

01CA Selection of COP-relevant vehicles
 0230 Extra package, EU-specific
 024B BMW LA wheel, double spoke 397
 0258 Tyres with runflat properties
 02PA Locking wheel bolt
 02TB Sport automatic gearbox
 02VB Tyre pressure display
 02VL Variable sport steering
 03AA Roof railing black
 0420 Sun protection glazing
 0423 Floor mats velours
 0481 Sports seat
 0493 Storage compartment package
 04AE Armrest front, retractable
 04FT Alum. brushed lengthw. acc. black hi-gls
 0508 Park Distance Control (PDC)
 0521 Rain sensor
 0534 Automatic air conditioning
 0544 Cruise control with braking function
 0548 Kilometre speedo
 0563 Lights package
 05A2 LED headlight
 05DA Passenger airbag deactivation
 05DC Rear-seat headrests, folding
 0606 Navigation system Business
 0676 HiFi speaker system
 0698 Area-Code 2 for DVD
 06AC Intelligent emergency call
 06AE Teleservices
 06AK Connected Drive Services
 06NH Hands-free system with USB interface
 06UH Traffic Information
 06WA Instrument panel with extended scope
 0710 M leather steering wheel
 0760 High gloss shadow line
 0775 Headlining anthracite
 07AC Sport Line
 07LD Modell Sport Line
 0845 Acoustic fasten seat belt reminder
 0855 Language version, Italian
 0884 On-board literature Italian
 08KA Oil service interval 24 mths / 30,000 km
 0962 Deleted, licence plate support front
 09AA Outer skin protection
 A090 90 Ah AGM battery
 POLS Cloth cushion

Retrofitted optional equipment:

This vehicle has no retrofits.

Vehicle histories

	Date	Type	Vehicle mileage	Retailer	Overview
—	26/07/2024	Warranty	179752 Km	48435	Job: F1x F2x F3x G0x G1x G3x B47O B47K B47U B47T Replacing EGR cooler (high-temperature)
—	Job: F1x F2x F3x G0x G1x G3x B47O B47K B47U B47T Replacing EGR cooler (high-temperature)				
	Description: F1x F2x F3x G0x G1x G3x B47O B47K B47U B47T Replacing EGR cooler (high-temperature)				
	Considered as a repeat visit No				
	Customer's own words				
	Replace exhaust gas recirculation cooler, including exhaust gas recirculation valve				25 FRU
	Flat rate unit I 00 74 062				

Additional work: run function test for pressure sensor system Flat rate unit I 00 74 650	3 FRU
Additional work: enter component identification of new exhaust gas recirculation cooler in diagnostic system Flat rate unit I 00 74 651	1 FRU
Additional work cleaning the exhaust gas recirculation pipe Flat rate unit I 00 74 652	6 FRU
F1x F2x F3x G0x G1x G3x B47O B47K B47U B47T Replacing EGR cooler (high-temperature) Defect I 00 11 15 07 00	
Exhaust gas radiator high temperature Part I 11 71 7 822 347	1
Pipe union Part I 11 71 7 799 853	2
Acoustic cover front Part I 11 14 8 490 577	1
Connection piece Part I 11 65 7 803 012	1
Holder Part I 61 13 1 369 832	1
O-ring Part I 11 61 8 512 681	1
EGR small parts set Part I 11 71 8 490 640	1

—

26/07/2024

Warranty

179752 Km

48435

Job: E84 Fx Gx Bx7 Nx7 Customer notification exhaust gas recirculation cooler

— Job: E84 Fx Gx Bx7 Nx7 Customer notification exhaust gas recirculation cooler

Description: E84 Fx Gx Bx7 Nx7 Customer notification exhaust gas recirculation cooler

Considered as a repeat visit No

Customer's own words

Vehicle was already finished with another repair or technical campaign Flat rate unit I 00 74 759	1 FRU
E84 Fx Gx Bx7 Nx7 Customer notification exhaust gas recirculation cooler Defect I 00 11 35 07 00	

—

25/07/2024

Key

179752 Km

48435

Key 1



—

13/06/2024

Warranty

177747 Km

48435

Job: Fx Gx B37 B47 B57 N47 N57 Check coolant level (EGR)

— Job: Fx Gx B37 B47 B57 N47 N57 Check coolant level (EGR)

Description: Fx Gx B37 B47 B57 N47 N57 Check coolant level (EGR)

Considered as a repeat visit No

Customer's own words

Flat rate unit | 00 73 830


1 FRU

Flat rate unit | 00 73 827


4 FRU

Fx Gx B37 B47 B57 N47 N57 Check coolant level (EGR)
Defect | 11 71 90 08 00

— 12/06/2024 Key 177747 Km 48435 Key 1



— 12/06/2024 Service 177747 Km 48435 Automatic
AUTOTORINO
SPA , TRIESTE



— 26/05/2023 Warranty 150782 Km 48435 Job: Engine oil service

— Job: Engine oil service

Description: Engine oil service

Considered as a repeat visit No

Customer's own words

BMW engine oil service not including additional service
Flat rate unit | 00 00 252

4 FRU

Engine oil service
Defect | 87 00 02 00 00

Set oil-filter element
Part | 11 42 8 575 211

1

— 25/05/2023 Key 150782 Km Key 1



— 25/05/2023 Service 150782 Km 48435 Automatic
AUTOTORINO
SPA , TRIESTE



— 12/09/2022 Key 132038 Km Key 0



— 12/09/2022 Warranty 132038 Km 48435 Job: G0x G3x B47O Programming control units (DDE)

— Job: G0x G3x B47O Programming control units (DDE)

Description: G0x G3x B47O Programming control units (DDE)

Considered as a repeat visit No

Customer's own words


Program control units 9 FRU
Flat rate unit I 00 71 374

G0x G3x B47O Programming control units (DDE)
Defect I 00 13 51 03 00


— 02/09/2022 Key 130469 Km 48435 Remote KeyRead



— 11/04/2022 Key 111546 Km 48435 Key 0



— 11/04/2022 Service 111546 Km 48435 Automatic
AUTOTORINO
SPA
AUTOSTAR ,
TRIESTE



— 11/04/2022 Warranty 111546 Km 48435 Job: Engine oil service

— Job: Engine oil service

Description: Engine oil service

Considered as a repeat visit No


Customer's own words

BMW engine oil service not including additional service 4 FRU
Flat rate unit I 00 00 252

Engine oil service
Defect I 87 00 02 00 00

Set oil-filter element 1
Part I 11 42 8 575 211


— 14/01/2022 Key 105628 Km 48435 Key 0



— 31/05/2021 Key

93001 Km

Key 1




— 31/05/2021 Service

93001 Km

48435
AUTOTORINO
SPA
AUTOSTAR ,
TRIESTE

Automatic



— 31/05/2021 Warranty

93001 Km

48435

Job: Service - standard scope
Job: Service - brake fluid

— Job: Service - standard scope

Description: Service - standard scope

Considered as a repeat visit No

Customer's own words

Service - standard scope
Flat rate unit | 00 00 105

2 FRU

Service - standard scope
Defect | 87 00 06 00 00

— Job: Service - brake fluid

Description: Service - brake fluid

Considered as a repeat visit No

Customer's own words

Brake fluid service
Flat rate unit | 00 00 618

4 FRU

Service - brake fluid
Defect | 87 34 00 00 00Brake fluid
Part | 83 13 9 415 965


10

— 09/12/2020 Key

88068 Km

48435

Key 1



— 14/10/2020 Key

86436 Km

48435

Key 1



— 14/10/2020 Service

86436 Km

48435
AUTOTORINO
SPA
AUTOSTAR ,
TRIESTE

Automatic



— 14/10/2020 Warranty

86436 Km

48435

Job: Engine oil service
 Job: Service - standard scope
 Job: Washer fluid service
 Job: Service - micro filter/activated
 carbon filter

— Job: Engine oil service

Description: Engine oil service**Considered as a repeat visit** No**Customer's own words**

Engine oil service 3 FRU
 Flat rate unit I 00 00 610

Engine oil service
 Defect I 87 00 02 00 00

Set oil-filter element 1
 Part I 11 42 8 575 211

— Job: Service - standard scope

Description: Service - standard scope**Considered as a repeat visit** No**Customer's own words**

Service - standard scope 2 FRU
 Flat rate unit I 00 00 105

Service - standard scope
 Defect I 87 00 06 00 00

— Job: Washer fluid service

Description: Washer fluid service**Considered as a repeat visit** No**Customer's own words**

Washer fluid service
 Defect I 87 00 09 00 00

Windshield antifreeze 10
 Part I 83 19 0 413 112

— Job: Service - micro filter/activated carbon filter

Description: Service - micro filter/activated carbon filter

























Considered as a repeat visit No

Customer's own words

Microfilter service 2 FRU
Flat rate unit I 00 00 616

Service - micro filter/activated carbon filter
Defect I 87 64 01 00 00

Microfilter/activated Carbon container 1
Part I 64 11 9 237 555

—	16/01/2020	Key	67872 Km	48435	Key 1				
									
	19000		19000		-500		14000	49000	
	07/2021		525			05/2021		07/2023	
—	16/01/2020	Service	67872 Km	48435	Automatic				
					AUTOTORINO				
					SPA				
					AUTOSTAR ,				
					TRIESTE				
									
	19000		19000		-500		14000	49000	
	06/2021		06/2021		✓	04/2021		06/2023	
—	23/07/2019	Key	57056 Km	35911	Key 1				
									
	220	220	220	220	36000		23000	220	
	04/2020	248	248		05/2021			04/2020	
—	23/07/2019	Service	57056 Km	38233	Automatic				
					AUTOSTAR				
					SPA , TRIESTE				
									
	220	220	220	220	36000		23000	220	
	03/2020	03/2020	03/2020	03/2020	04/2021			03/2020	
	✓	✓	✓	✓				✓	
—	23/07/2019	Warranty	57056 Km	38233	Job: Oxygen monitor sensor				

— Job: Oxygen monitor sensor

Description: Oxygen monitor sensor

Considered as a repeat visit No

Customer's own words

Oxygen monitor sensor
Defect I 11 78 03 14 00

Oxygen sensor 1
Part I 13 62 8 589 104

—	23/07/2019	Warranty	57056 Km	38233	Job: Engine oil service Job: Service - vehicle check Job: Service - standard scope Job: Washer fluid service
---	------------	----------	----------	-------	---

Job: Service - air cleaner
 Job: Service - fuel filter
 Job: Service - micro filter/activated
 carbon filter

— Job: Engine oil service

Description: Engine oil service**Considered as a repeat visit** No**Customer's own words**

Engine oil service Flat rate unit I 00 00 610	3 FRU
--	-------

Engine oil service Defect I 87 00 02 00 00	
---	--

Set oil-filter element Part I 11 42 8 575 211	1
--	---

— Job: Service - vehicle check

Description: Service - vehicle check**Considered as a repeat visit** No**Customer's own words**

Service, vehicle check Flat rate unit I 00 00 624	6 FRU
--	-------

Service - vehicle check Defect I 87 00 05 00 00	
--	--

— Job: Service - standard scope

Description: Service - standard scope**Considered as a repeat visit** No**Customer's own words**

Service - standard scope Flat rate unit I 00 00 105	2 FRU
--	-------

Service - standard scope Defect I 87 00 06 00 00	
---	--

— Job: Washer fluid service

Description: Washer fluid service**Considered as a repeat visit** No**Customer's own words**

Washer fluid service Defect I 87 00 09 00 00	
---	--

Windshield antifreeze Part I 83 19 0 413 112	10
---	----

— Job: Service - air cleaner

Description: Service - air cleaner**Considered as a repeat visit** No**Customer's own words**

Service - air filter element Flat rate unit I 00 00 602	2 FRU
--	-------

Service - air cleaner	
-----------------------	--

Defect I 87 13 01 00 00

Air filter element
Part I 13 71 8 511 668

1

— Job: Service - fuel filter

Description: Service - fuel filter**Considered as a repeat visit** No**Customer's own words**Service fuel filter
Flat rate unit I 00 00 604

3 FRU

Service - fuel filter
Defect I 87 13 02 00 00Fuel filter cartridge
Part I 13 32 8 572 522

1

— Job: Service - micro filter/activated carbon filter

Description: Service - micro filter/activated carbon filter**Considered as a repeat visit** No**Customer's own words**Microfilter service
Flat rate unit I 00 00 616

2 FRU

Service - micro filter/activated carbon filter
Defect I 87 64 01 00 00Microfilter/activated Carbon container
Part I 64 11 9 237 555

1

— 28/06/2019 Warranty 54821 Km 38233 Job: F10 F11 F25 F26 F31 F34 F36 B47O Replacing exhaust-gas recirculation cooler

— Job: F10 F11 F25 F26 F31 F34 F36 B47O Replacing exhaust-gas recirculation cooler

Description: F10 F11 F25 F26 F31 F34 F36 B47O Replacing exhaust-gas recirculation cooler**Considered as a repeat visit** No**Customer's own words**Additional work of checking EGR cooler
Flat rate unit I 00 67 703

1 FRU

Replace exhaust-gas recirculation cooler and replace or remount
exhaust-gas recirculation valve; clean exhaust gas recirculation pipe
Flat rate unit I 00 66 955

28 FRU

F10 F11 F25 F26 F31 F34 F36 B47O Replacing exhaust-gas
recirculation cooler
Defect I 00 11 83 04 00Set of small parts
Part I 11 71 8 597 652

1

O-ring
Part I 11 61 8 512 681

1

exhaust cooler
Part I 11 71 8 596 444

1

— 28/06/2019 Warranty 54821 Km 38233 Job: Exhaust gas recirculation valve (EGR)

— Job: Exhaust gas recirculation valve (EGR)

Description: Exhaust gas recirculation valve (EGR)**Considered as a repeat visit** No**Customer's own words**Replacing exhaust gas recirculation valve
Flat rate unit I 11 71 501

4 FRU

Exhaust gas recirculation valve (EGR)
Defect I 11 71 01 83 00EGR-valve
Part I 11 71 8 513 132

1

— 28/06/2019 Warranty

54821 Km

38233

Job: Service - standard scope
Job: Service - brake fluid

— Job: Service - standard scope

Description: Service - standard scope**Considered as a repeat visit** No**Customer's own words**Service - standard scope
Flat rate unit I 00 00 105

2 FRU

Service - standard scope
Defect I 87 00 06 00 00

— Job: Service - brake fluid

Description: Service - brake fluid**Considered as a repeat visit** No**Customer's own words**Brake fluid service
Flat rate unit I 00 00 618

4 FRU

Service - brake fluid
Defect I 87 34 00 00 00Brake fluid
Part I 83 13 9 415 965







10

— 31/05/2019 Key

54821 Km

38233

Key 1









— 31/05/2019 Service

54821 Km

38233

AUTOSTAR
SPA , TRIESTE

Automatic




— 17/04/2018 Key

27160 Km

38233

Key 1



— 17/04/2018 Service 27160 Km 38233 AUTOSTAR SPA , TRIESTE Automatic



— 17/04/2018 Repair 13076 Km 38233 AUTOSTAR SPA , TRIESTE Job Job

— Job

Description:

Considered as a repeat visit No

Customer's own words

ISPA TC-1-0011450400 Local 12 FRU
Flat rate unit I -

— Job

Description:

Considered as a repeat visit No

Customer's own words

VR - SERVICE KM 30.000 Local 12 FRU
Flat rate unit I -

— 17/04/2018 Warranty 27160 Km 38233 Job: F1x F2x F3x B47 programming control units and if necessary, replacing the EGR valve

— Job: F1x F2x F3x B47 programming control units and if necessary, replacing the EGR valve

Description: F1x F2x F3x B47 programming control units and if necessary, replacing the EGR valve

Considered as a repeat visit No

Customer's own words

Carrying out the ABL and programming the control units 10 FRU
Flat rate unit I 00 64 246

F1x F2x F3x B47 programming control units and if necessary, replacing the EGR valve
Defect I 00 11 45 04 00

— 17/04/2018 Warranty 27160 Km 38233 Job: Engine oil service
Job: Service - standard scope
Job: Washer fluid service
Job: Service - micro filter/activated carbon filter

— Job: Engine oil service

Description: Engine oil service

Considered as a repeat visit No

Customer's own words

Engine oil service Flat rate unit I 00 00 610	3 FRU
--	-------

Engine oil service Defect I 87 00 02 00 00	
---	--

Set oil-filter element Part I 11 42 8 575 211	1
--	---

— Job: Service - standard scope

Description: Service - standard scope

Considered as a repeat visit No

Customer's own words

Service - standard scope Flat rate unit I 00 00 105	2 FRU
--	-------

Service - standard scope Defect I 87 00 06 00 00	
---	--

— Job: Washer fluid service

Description: Washer fluid service

Considered as a repeat visit No

Customer's own words

Washer fluid service Defect I 87 00 09 00 00	
---	--

Windshield antifreeze Part I 83 19 0 413 112	10
---	----

— Job: Service - micro filter/activated carbon filter

Description: Service - micro filter/activated carbon filter

Considered as a repeat visit No

Customer's own words

Microfilter service Flat rate unit I 00 00 616	2 FRU
---	-------

Service - micro filter/activated carbon filter Defect I 87 64 01 00 00	
---	--

Fine dust filt.invoice Service Inclusive Part I 64 11 2 458 688	1
--	---

11/10/2017	Warranty	13076 Km	38233	Job: Control panel of front heating and air conditioning system (incl. control unit)
------------	----------	----------	-------	--

— Job: Control panel of front heating and air conditioning system (incl. control unit)

Description: Control panel of front heating and air conditioning system (incl. control unit)

Considered as a repeat visit No

Customer's own words


Performing vehicle test Flat rate unit I 00 00 006	4 FRU
---	-------

Supporting the voltage of the vehicle electrical system/recharging the vehicle electrical system battery
Flat rate unit I 61 21 528

1 FRU

Control panel of front heating and air conditioning system (incl. control unit)
Defect I 64 11 64 02 00

— 03/10/2017 Key 13095 Km 38233 Key 1



— 02/10/2017 Key 13076 Km 35911 Key 1

