

Thank you for ordering from us!

www.checkvin.eu

Vehicle

BMW 318d, 110KW

WBA8T11070BA26646



Development code F34
Colour imperial-blau brillant metallic
Actual integration level F020-23-03-500
Start of warranty 25 January 2017

Delivery stop



Technical Campaigns are available.

Technical campaigns

Status	Campaign number	Description	Reservation
Reserved	10011150700	Replacing the exhaust gas recirculation cooler (high temperature) Delivery stop Local campaign number: -	BuNo: 22263
Reserved	10011350700	Exhaust gas recirculation cooler customer notification Local campaign number: -	BuNo: 22263
Reserved	10032550300	Check the driver's airbag, replace if necessary (conversion SDI) Delivery stop Local campaign number: -	BuNo: 22263

Warranty extension/VIN-based goodwill

Status	Campaign number	Description
Open	1SACC011056	Exhaust gas recirculation cooler Bx7 Local campaign number: -

Special information

There are no Campaigns for this vehicle.

Restrictions on the warranty

There are no restrictions on the warranty.

⚠ Market-specific restrictions are not currently displayed. Please check this in WDF/WXE via S-Gate.

Live Diagnosis

 There are no service solutions for Live Diagnosis.

Service contracts

No BSI contracts

Information on faults workshop/Service Consultation

There is no information on faults.

Navigation map

Installed map	Enabling code (subscription)	Latest navigation map included in subscription	Latest navigation map subject to charge
Road Map EUROPE Route 2016-2 (As of: 31 Mar 2025)	Enabling code valid for navigation maps with release date up to 31 Dec 2025 (SWID: 00B4008F).	Road Map EUROPE WEST Route 2025	-

Vehicle details

Vehicle type	Passenger car
Brand	BMW
Model	318d
Body	SAT
Vehicle identification number (last 7 digits)	BA26646
Vehicle identification number (17 digits)	WBA8T11070BA26646
Development code	F34
Steering	LL
Engine	B47U
Engine number	60359869
Exhaust re-treatment	EURO6, W, PI/CI, M, N1 I
Transmission	MECH
Transmission number	1217400CBJ
Head unit serial number	MM01DFH2769496
Drive	HECK
Integration level, works	F020-16-11-502
Production date	17 Jan 2017
Production plant	Dingolfing
Delivery date	19 Jan 2017

Delivering retailer	BYmyCAR, PARIS, FR
National-market version	EUR
Paint code	A89
Upholstery code	LCOM
Model code	8T11
Basic type	8T11
Lead type	8T11

Optional equipment

Optional equipment ex works:

- 01CA Selection of COP-relevant vehicles
- 01CB CO2 equipment
- 0216 Hydro steering-servotronic
- 0230 EU-specific additional contents
- 0255 Sports leather steering wheel
- 02DX BMW LA wheel, star spoke 394
- 02PA Locking wheel bolt
- 02VB Tyre pressure display
- 02VC Tyre repair set
- 03L8 Exterior equipment, aluminium, satinised
- 0423 Floor mats velours
- 0428 Warning triangle and first aid kit
- 0441 Smoker package
- 0493 Storage compartment package
- 04AE Armrest front, retractable
- 04CG Interior trim strips "satin-silber" matt
- 0508 Park Distance Control (PDC)
- 0521 Rain sensor
- 0544 Cruise control with braking function
- 0548 Kilometre speedo
- 0563 Lights package
- 05A1 LED Fog lights
- 05A2 LED headlight
- 05DA Passenger airbag deactivation
- 0606 Navigation system Business
- 0698 Area-Code 2 for DVD
- 06AC Intelligent emergency call
- 06AE Teleservices
- 06NH Hands-free system with USB interface
- 07LC Modell Advantage
- 0854 Language version, French
- 0881 On-board literature, French
- 08KA Oil service interval 24 mths / 30,000 km
- 08R9 Refrigerant R1234yf
- 08S3 Automatic locking during starting
- 08TF Active pedestrian protection
- A090 90 Ah AGM battery
- LEDE Leather equipment


Retrofitted optional equipment:

This vehicle has no retrofits.

Vehicle histories

Date		Type	Vehicle mileage			Retailer		Overview
— 31/03/2025		Key	138978 Km			22263		Key 0
								
210		210		33000	-30 4.1 %	-30 4.1 %	50000	210
10/2025		10/2025						10/2025

— 31/03/2025 Service 138978 Km 22263 Automatic
 LATITUDE
 AUTOMOBILES
 LORIENT ,
 LORIENT



— 03/05/2023 Warranty 96769 Km 22263 Job: F1x F2x F3x F4x G0x G1x G3x B47 Check and if required replace exhaust-gas recirculation cooler

— Job: F1x F2x F3x F4x G0x G1x G3x B47 Check and if required replace exhaust-gas recirculation cooler

Description: F1x F2x F3x F4x G0x G1x G3x B47 Check and if required replace exhaust-gas recirculation cooler

Considered as a repeat visit No

Customer's own words

Replace exhaust gas recirculation cooler using the pressure sensor system test and note production date of both exhaust gas recirculation coolers 26 FRU
 Flat rate unit I 00 70 526

Additional work cleaning the exhaust-gas recirculation pipe 1 FRU
 Flat rate unit I 00 70 527


F1x F2x F3x F4x G0x G1x G3x B47 Check and if required replace exhaust-gas recirculation cooler
 Defect I 00 11 40 05 00

Exhaust gas radiator high temperature 1
 Part I 11 71 7 822 347


Pipe union 2
 Part I 11 71 7 799 853

Set of small parts 1
 Part I 11 71 8 597 652

— 02/05/2023 Key 96769 Km Key 0



— 12/04/2023 Key 94394 Km Key 0



— 12/04/2023 Warranty 94394 Km 22263 Job: G0x G3x B47O Programming control units (DDE)
 Job: Fx Gx B37 B47 B57 N47 N57
 Check coolant level (EGR)

— Job: G0x G3x B47O Programming control units (DDE)

Description: G0x G3x B47O Programming control units (DDE)

Considered as a repeat visit No

Customer's own words

Program control units 8 FRU
Flat rate unit I 00 71 940

Additional work: check CCM Check Control message and coolant level 1 FRU
Flat rate unit I 00 73 677

G0x G3x B47O Programming control units (DDE)
Defect I 00 13 51 03 00

— Job: Fx Gx B37 B47 B57 N47 N57 Check coolant level (EGR)

Description: Fx Gx B37 B47 B57 N47 N57 Check coolant level (EGR)


Considered as a repeat visit No

Customer's own words

Flat rate unit I 00 73 827 4 FRU

Fx Gx B37 B47 B57 N47 N57 Check coolant level (EGR)
Defect I 11 71 90 08 00

— 15/02/2019 Key 33659 Km Key 1



— 15/02/2019 Service 33659 Km 32785 Automatic

NEUBAUER DIST.
LE
CHESNAY/PARLYII,
LE CHESNAY



— 15/02/2019 Repair 33659 Km 32785 Job: Service huile moteur
NEUBAUER Job: Service microfiltre
LE CHESNAY, Job: Service prestations standard
LE CHESNAY Job

— Job: Service huile moteur

Description:

Considered as a repeat visit No

Customer's own words

Service huile moteur
Package I 0000610

Engine oil service 10
Flat rate unit I 00 00 610

!!! unknown BMW-Id MOBIL Huile moteur mobil 5W30 longlife 04 Local 5
!!!
Part I MOBIL

Set oil-filter element 1
Part I 11428575211

— Job: Service microfiltre

Description:

Considered as a repeat visit	No
------------------------------	----

Customer's own words

Service microfiltre
Package I 0000616

Microfilter service	2
Flat rate unit I 00 00 616	

Microfilter/activated Carbon container	1
Part I 64119237555	

- Job: Service prestations standard

Description: CONTRAT ALPHABET

Considered as a repeat visit	No
------------------------------	----

Customer's own words

Service prestations standard
Package I 0000105

Service - standard scope	2
Flat rate unit I 00 00 105	

- Job

Description:

Considered as a repeat visit	No
------------------------------	----

Customer's own words

Remplacer balais essuies-glace AV	Local	1 FRU
Flat rate unit I -		