



BMW 4er 430i Gran Coupé M Sport

Stock number:	LB19725
Build year:	2016
First registration:	05/2016
Odometer reading:	200,671 km
Fuel type:	Petrol
Horsepower:	185 kW / 252 HP
Cylinder capacity:	1,998 ccm
Gear box:	Automatic
Inspection expires:	07/2025
Body type:	Sedan
Total number of owners:	2
Keys:	2
Prior damage / Accident according to previous owner	No
Country of origin:	BE
Country of last registration:	BE
Environmental class:	EURO 6b
COC papers:	Yes
Seats:	5
Color:	Black (Original)
Upholstery:	Leather (Original)
Door count:	4

Car location

-

MAIN CAR DETAILS

CAR HIGHLIGHTS / ADDITIONAL PHOTOS



General



General



General



General



General



General



General



General



General



General

TEST DRIVE INFORMATION

TEST DRIVE LOCATION: ON PUBLIC STREET < 80KM/H (LOWER SPEED)

NO SPECIFIC FINDINGS

--

DAMAGE SUMMARY

The results of this car's evaluation are summarised in the DAMAGE SUMMARY table and visualised in the DAMAGE AREAS section below.

Damage / Part	Severity
1 FADED Front bumper (1)	Diameter: <100mm
1 REPAINT Front right door (1)	Thickness: ≥125µm & <250µm , Professional repaint
2 SCRATCHES Front left door (1) Rear left door (1)	Length: ≥20mm & <50mm , Deep scratch - down to primer
4 SCRATCHES Front left fender (2) Front right fender (2)	Length: ≥20mm & <50mm , Surface scratch
8 SCRATCHES Front left rim (2) Rear left rim (2) Rear right rim (2) Front right rim (2)	Length: <25mm , Deep scratch
15 SCRATCHES Front left door (2) Rear left door (2) Rear bumper (3) Tailgate (2) Rear right fender (1) Rear right door (3) Front right door (2)	Length: <20mm , Surface scratch
8 SCRATCHES Front bumper (3) Rear bumper (2) Rear right fender (1) Rear right door (1) Front right door (1)	Length: <20mm , Deep scratch - down to primer
36-44 Front bumper (16-20) Hood (11-15) Front left fender (5) Right mirror housing (4)	Width: ≤3mm , Paint damage
4 STONE CHIPS Windscreen (4)	Width: ≤3mm , Not in driver's eyeline
2 RECONDITIONING NECESSARY Passenger seat (1) Steering Wheel (1)	
3 SCRATCHES Driver seat (1) Other seats (1) Floor covering (1)	Length: <50mm
1 WORN OUT Driver seat (1)	

CAR EQUIPMENT

Some content has been automatically translated.

✓ Xenon lights	Bi-Xenon headlights
✓ Heated seats	Front seat heating
✓ Seat settings	Front seats electrically adjustable, left with memory
✓ Sunroof	Electric sliding/tilting sunroof (glass)
✓ Park Distance Control	Park-Distance-Control (PDC) front and rear Rearview camera
✓ Power steering	Power steering Servotronic
✓ Hands-free system	Hands-free with USB interface
✓ Sport seats	Sports seats in front
✓ Navigation System	Professional audio-navigation system
✓ Airbag	Disconnectable passenger airbag Driver side airbag / passenger side airbag Rear Cranial Airbag System Front head airbag system Front side airbag
✓ AC System	Automatic dual-zone air conditioning with automatic air circulation control
✓ ESP	Dynamic Stability Control (DSC)
✓ Immobilizer	Immobilizer
✓ On-board computer	On-board computer



Entertainment system

BMW Professional audio system (Radio/CD player MP3 compatible)
Instrument cluster (extended scope)
HiFi Harman-Kardon speaker



Theft alarm system / security alarm

Alarm system



ABS

Anti-lock Braking System (ABS)

CAR SERVICE DETAILS

Service book details:

Not available

Service appointment:

-

Last service on:

-

Last service Mileage:

-

Drive belt change on:

-

Drive belt change Mileage:

-

TECHNICAL INSPECTION

Date of latest technical inspection:

06/10/2024

Mileage at latest technical inspection:

188,470 km

Technical inspection images 1 image

CAR DATA ACCORDING TO IDENTIFICATION NUMBER (VIN)

Some content has been automatically translated.

- ☒ Driving assistance system: lane departure warning system
- ☒ Automatic headlight range control
- ☒ Color monitor (6.5 """)
- ☒ AUX-IN connection (AUX-IN)
- ☒ Storage package
- ☒ Exhaust system (dual pipes) with chrome trim
- ☒ Exterior finish: Shadow-Line high gloss
- ☒ Anthracite headliner (BMW Individual)
- ☒ Dynamic brake lights
- ☒ First aid kit / First aid kit

