



BMW 3er 320d xDrive Sport Line


Stock number:	HK57304
Build year:	2016
First registration:	02/2016
Odometer reading:	217,586 km
Fuel type:	Diesel
Horsepower:	140 kW / 190 HP
Cylinder capacity:	1,995 ccm
Gear box:	Automatic
Inspection expires:	02/2025
Body type:	Combi
Total number of owners:	3
Keys:	2
Prior damage / Accident according to previous owner	Yes
Country of origin:	DE
Country of last registration:	-
Environmental class:	EURO 6
COC papers:	Yes
Seats:	5
Color:	Black (Original)
Upholstery:	Part leather (Original)
Door count:	5
CO2 Emissions:	129g/km

Car location

-

MAIN CAR DETAILS

CAR HIGHLIGHTS / ADDITIONAL PHOTOS



General



General



General

TEST DRIVE INFORMATION

TEST DRIVE LOCATION: IN BRANCH AREA, CAR DE-REGISTERED, TECHNICAL ADMISSION DUE

NO SPECIFIC FINDINGS

VEHICLE CONDITION

 1 area with sign of previous accident

 Repair status: Repaired

 Repaired by: Unknown


 Repair cost: Unknown

 Repair document not available

 6 damaged areas

 No indication of repainted panels


Exterior




Interior



Wheels



Underbody



Engine and drive system





Indications of accident



- One or more panels have different colour tones

 1

Damages

Panel	Damage	Severity	Description	Quantity	
<u>Front bumper</u>	Fracture	Length: $\geq 50\text{mm}$ & $< 100\text{mm}$ & Width: $\geq 5\text{mm}$	-	1	 1
<u>Hood</u>	Scratch	Length: $< 20\text{mm}$	Deep scratch - down to primer	11-15	 0

DAMAGE SUMMARY

The results of this car's evaluation are summarised in the DAMAGE SUMMARY table and visualised in the DAMAGE AREAS section below.

Damage / Part	Severity
2 DENTS Rear right door (2)	Width: $\geq 5\text{mm}$ & $< 20\text{mm}$, Paint damage
1 FRACTURE Front bumper (1)	Length: $\geq 50\text{mm}$ & $< 100\text{mm}$, Width: $\geq 5\text{mm}$
3 RUST Front left fender (1) Rear left fender (1) Roof (1)	Rusted
42-62 Hood (11-15) Left mirror housing (2) Front left door (6-10) Rear left door (6-10) Rear bumper (11-15) Tailgate (6-10)	Length: $< 20\text{mm}$, Deep scratch - down to primer
3 WORN OUT Passenger seat (1) Driver seat (1) Center console (1)	

CAR EQUIPMENT

Some content has been automatically translated.

✓ Towbar	Trailer hitch (swiveling ball head)
✓ Heated seats	Front seat heating
✓ Park Distance Control	Park-Distance-Control (PDC) front and rear
✓ Power steering	Power steering Servotronic
✓ Hands-free system	Bluetooth hands-free system with USB audio interface
✓ Sport seats	Sports seats in front
✓ Navigation System	Business audio and navigation system
✓ Airbag	Disconnectable passenger airbag Driver side airbag / passenger side airbag Rear Cranial Airbag System Front head airbag system Side airbag rear Front side airbag
✓ AC System	Automatic dual-zone air conditioning with automatic air circulation control
✓ DPF / FAP	Particulate filter
✓ ESP	Dynamic Stability Control (DSC)
✓ Immobilizer	Immobilizer
✓ All wheel drive	Drive type: xDrive (All-wheel drive)



On-board computer

External temperature indicator
On-board computer



Entertainment system

BMW Professional audio system (Radio/CD player MP3 compatible)
Instrument cluster (extended scope)



Theft alarm system / security alarm

Alarm system



ABS

Anti-lock Braking System (ABS)

CAR SERVICE DETAILS

Service book details:

Digital service book

Service appointment:

Some

Last service on:

07/31/2019

Last service Mileage:

217,586 km

Drive belt change on:

-

Drive belt change Mileage:

-

Car service images 1 image

CAR DATA ACCORDING TO IDENTIFICATION NUMBER (VIN)

Some content has been automatically translated.

-  Color monitor (6.5 """)
-  AUX-IN connection (AUX-IN)
-  Security system Active Protection
-  Storage package
-  Ambient lighting
-  Chrome exhaust tip, black
-  Check Control System
-  Dynamic brake lights
-  Entry sills with aluminum insert
-  Remote unlocking tailgate

