

Thank you for ordering from us!

www.checkvin.eu

Vehicle

BMW 318d, 110KW

WBA8C31090K804339



Development code
Colour
Actual integration level
Start of warranty

F30
mineral-grau metallic
F020-24-11-520
24 June 2016

Technical campaigns

There are no Campaigns for this vehicle.

Warranty extension/VIN-based goodwill

Status	Campaign number	Description
Open	1SACC011056	Exhaust gas recirculation cooler Bx7 Local campaign number: -

Special information

There are no Campaigns for this vehicle.

Restrictions on the warranty

There are no restrictions on the warranty.

⚠ Market-specific restrictions are not currently displayed. Please check this in WDF/WXE via S-Gate.

Live Diagnosis

 There are no service solutions for Live Diagnosis.

Service contracts

No BSI contracts

Information on faults workshop/Service Consultation

There is no information on faults.

Navigation map

Note: The installed map cannot be clearly identified. Presumably one of the following maps is present in the vehicle.

Installed map	Enabling code (subscription)	Latest navigation map included in subscription	Latest navigation map subject to charge
Road Map EUROPE EVO 2021-3 (As of: 12 Mar 2025)	Enabling code valid for navigation maps with release date up to 31 Dec 2099 (SWID: 00F10FFF).	Road Map EUROPE EVO 2025-1	-
Road Map EUROPE EVO 2021-3 (As of: 12 Mar 2025)	-	-	-

Vehicle details

Vehicle type	Passenger car
Brand	BMW
Model	318d
Body	LIM
Vehicle identification number (last 7 digits)	K804339
Vehicle identification number (17 digits)	WBA8C31090K804339
Development code	F30
Steering	LL
Engine	B47U
Engine number	52849653
Exhaust re-treatment	EURO6, W, PI/CI, M, N1 I
Transmission	MECH
Transmission number	1150230CBJ
Head unit serial number	HB2140G7872865
Drive	HECK
Integration level, works	F020-16-03-504
Production date	13 Jun 2016
Production plant	Muenchen
Delivery date	15 Jun 2016
Delivering retailer	Bortolin Hannut, Hannut, BE
National-market version	EUR
Paint code	B39
Upholstery code	HAAT
Model code	8C31
Basic type	8C31
Lead type	8C31

Optional equipment

Optional equipment ex works:

- 01CA Selection of COP-relevant vehicles
- 01CB CO2 equipment
- 0216 Hydro steering-servotronic
- 021C BMW LA wheel, M double spoke bicolor
- 0230 Extra package, EU-speciifc
- 0258 Tyres with runflat properties
- 02VB Tyre pressure display
- 02VF Adaptive M chassis
- 0302 Alarm system
- 0320 Deleted, model lettering
- 0337 M Sports package
- 0420 Sun protection glazing
- 0423 Floor mats velours
- 0430 Interior/outside mirror with auto dip
- 0431 Interior mirror with automatic-dip
- 0465 Through-loading system
- 0481 Sports seat
- 0493 Storage compartment package
- 04AE Armrest front, retractable
- 04WG Alum. Hexagon accent black high-gloss
- 0508 Park Distance Control (PDC)
- 0521 Rain sensor
- 0534 Automatic air conditioning
- 0544 Cruise control with braking function
- 0548 Kilometre speedo
- 0563 Light package
- 05A1 LED Fog lights
- 05A2 LED headlight
- 05AC High-beam assistant
- 05DC Rear-seat headrests, folding
- 0609 Navigation system Professional
- 0698 Area-Code 2 for DVD
- 06AC Intelligent emergency call
- 06AE Teleservices
- 06NH Hands-free system with USB interface
- 06WA Instrument panel with extended scope
- 0710 M leather steering wheel
- 0715 M Aerodynamics package
- 0760 High gloss shadow line
- 0775 Headlining anthracite
- 07LF Modell M Sport
- 0854 Language version, French
- 0881 On-board literature, French
- 08KA Oil service interval 24 mths / 30,000 km
- 08S3 Automatic locking during starting
- 08SM Car ident. number visible from outside
- 09AA Outer skin protection
- A090 90 Ah AGM battery
- POLS Cloth cushion

Retrofitted optional equipment:

This vehicle has no retrofits.

Vehicle histories

	Date	Type	Vehicle mileage	Retailer	Overview
—	12/03/2025	Key	233382 Km	31688	Key 0

— Job

Description:

Considered as a repeat visit No

Customer's own words

Replace exhaust gas recirculation cooler, including exhaust gas recirculation valve Flat rate unit I 00 74 062	25 FRU
---	--------

Additional work: run function test for pressure sensor system Flat rate unit I 00 74 650	3 FRU
---	-------

Additional work: enter component identification of new exhaust gas recirculation cooler in diagnostic system Flat rate unit I 00 74 651	1 FRU
--	-------

Additional work cleaning the exhaust gas recirculation pipe Flat rate unit I 00 74 652	6 FRU
---	-------

Exhaust gas radiator high temperature Part I 11 71 7 822 347	1
---	---

EGR small parts set Part I 11 71 8 490 640	1
---	---

Pipe union Part I 11 71 7 799 853	2
--------------------------------------	---

Holder Part I 61 13 1 369 832	1
----------------------------------	---

Connection piece Part I 11 65 7 803 012	1
--	---

O-ring Part I 11 61 8 512 681	1
----------------------------------	---

Hex Bolt Part I 07 14 7 029 829	4
------------------------------------	---

Acoustic cover front Part I 11 14 8 490 576	1
--	---

Pipe Part I 13 71 7 823 517	1
--------------------------------	---

Divers (huile,fluides, etc.) Part I 04	Local	1
---	-------	---

— Job

Description:

Considered as a repeat visit No

Customer's own words

Vehicle was already finished with another repair or technical campaign Flat rate unit I 00 74 759	1 FRU
--	-------

— Job

Description:

Considered as a repeat visit No

Customer's own words

Program control units	8 FRU
-----------------------	-------

Flat rate unit I 00 71 940

— Job

Description:

Considered as a repeat visit No

Customer's own words

unknown fru: Remplacer l'airbag conducteur Flat rate unit I 00 76 920	Local	3 FRU
--	-------	-------

Airbag module, driver's side Part I 32305A66F66		1
--	--	---

Divers (huile,fluides, etc.) Part I 04	Local	1
---	-------	---

— Job

Description:

Considered as a repeat visit No

Customer's own words

Accord Spécial Part I 08	Local	1
-----------------------------	-------	---

— Job

Description:

Considered as a repeat visit No

Customer's own words

—	12/03/2025	Warranty	233383 Km	31688	Job: F1x F2x F3x G0x G1x G3x B47O B47K B47U B47T Replacing EGR cooler (high-temperature) Job: E84 Fx Gx Bx7 Nx7 Customer notification exhaust gas recirculation cooler Job: G0x G3x B47O Programming control units (DDE) Job
---	------------	----------	-----------	-------	---

— Job: F1x F2x F3x G0x G1x G3x B47O B47K B47U B47T Replacing EGR cooler (high-temperature)

Description: F1x F2x F3x G0x G1x G3x B47O B47K B47U B47T Replacing EGR cooler (high-temperature)

Considered as a repeat visit No

Customer's own words

Replace exhaust gas recirculation cooler, including exhaust gas recirculation valve Flat rate unit I 00 74 062	25 FRU
---	--------

Additional work: run function test for pressure sensor system Flat rate unit I 00 74 650	3 FRU
---	-------

Additional work: enter component identification of new exhaust gas recirculation cooler in diagnostic system Flat rate unit I 00 74 651	1 FRU
--	-------

Additional work cleaning the exhaust gas recirculation pipe Flat rate unit I 00 74 652	6 FRU
---	-------

F1x F2x F3x G0x G1x G3x B47O B47K B47U B47T Replacing EGR cooler (high-temperature) Defect I 00 11 15 07 00	
--	--

Exhaust gas radiator high temperature Part I 11 71 7 822 347	1
EGR small parts set Part I 11 71 8 490 640	1
Pipe union Part I 11 71 7 799 853	2
Holder Part I 61 13 1 369 832	1
Connection piece Part I 11 65 7 803 012	1
O-ring Part I 11 61 8 512 681	1
Hex Bolt Part I 07 14 7 029 829	4
Acoustic cover front Part I 11 14 8 490 576	1
Pipe Part I 13 71 7 823 517	1

— Job: E84 Fx Gx Bx7 Nx7 Customer notification exhaust gas recirculation cooler

Description: E84 Fx Gx Bx7 Nx7 Customer notification exhaust gas recirculation cooler

Considered as a repeat visit No

Customer's own words

Vehicle was already finished with another repair or technical campaign Flat rate unit I 00 74 759	1 FRU
--	-------

E84 Fx Gx Bx7 Nx7 Customer notification exhaust gas recirculation cooler
Defect I 00 11 35 07 00

— Job: G0x G3x B47O Programming control units (DDE)

Description: G0x G3x B47O Programming control units (DDE)

Considered as a repeat visit No

Customer's own words

Program control units Flat rate unit I 00 71 940	8 FRU
---	-------

G0x G3x B47O Programming control units (DDE)
Defect I 00 13 51 03 00

— Job

Description:

Considered as a repeat visit No

Customer's own words

Defect I 87 00 05 00 QC

—	12/03/2025	Warranty	233383 Km	31688	Job: Fx Replace driver's airbag, part III (SDI)
---	------------	----------	-----------	-------	---

— Job: Fx Replace driver's airbag, part III (SDI)

Description: Fx Replace driver's airbag, part III (SDI)

Considered as a repeat visit No

Customer's own words

Replace driver's airbag
Flat rate unit I 00 76 920


3 FRU

Fx Replace driver's airbag, part III (SDI)
Defect I 00 32 62 03 00

Airbag module, driver's side
Part I 32305A66F66

1


— 03/03/2022 Key 181808 Km 31688 Key 0




— 03/03/2022 Key 181800 Km 31688 Key 0



— 20/05/2020 Key 146778 Km 10126 Key 0



— 10/02/2020 Key 145380 Km 10126 Key 0



— 13/01/2020 Key 142503 Km 10126 Key 1



— 13/01/2020 Service 142503 Km 10126 Bortolin Hannut, Hannut Automatic



— 20/08/2019 Warranty 125319 Km 10126 Job: F10 F11 F25 F26 F31 F34 F36 B47O Replacing exhaust-gas recirculation cooler

































— Job: F10 F11 F25 F26 F31 F34 F36 B47O Replacing exhaust-gas recirculation cooler

Description: F10 F11 F25 F26 F31 F34 F36 B47O Replacing exhaust-gas recirculation cooler

Considered as a repeat visit No

Customer's own words

Additional work of checking EGR cooler Flat rate unit I 00 67 703	1 FRU
Replace exhaust-gas recirculation cooler and replace or remount exhaust-gas recirculation valve; clean exhaust gas recirculation pipe Flat rate unit I 00 66 955	28 FRU
F10 F11 F25 F26 F31 F34 F36 B47O Replacing exhaust-gas recirculation cooler Defect I 00 11 83 04 00	
exhaust cooler Part I 11 71 8 596 444	1
Set of small parts Part I 11 71 8 597 652	1
Pipe union Part I 11 71 7 799 853	2
O-ring Part I 11 61 8 512 681	1

—	19/08/2019	Key	125319 Km	10126	Key 0		
							
25000		25000		43000	41000	60000	
07/2021		672		06/2021		07/2023	
—	29/07/2019	Key	122441 Km	10126	Key 1		
							
210	210	210	210	44000	43000	210	
02/2021	542	542	542	06/2021		02/2021	
—	29/07/2019	Service	122441 Km	10126 Bortolin Hannut, Hannut	Automatic		
							
210	210	210	210	44000	43000	210	
01/2021	01/2021	01/2021	01/2021	05/2021		01/2021	
✓	✓	✓	✓			✓	
—	28/06/2019	Key	119066 Km	10126	Key 1		
							
4700	4700	4700	4700	50000	49000	4700	
02/2021	573	573	573		-27 3.7 %	02/2021	
—	28/06/2019	Service	119066 Km	10126 Bortolin Hannut, Hannut	Automatic		
							
4700	4700	4700	4700	50000	49000	4700	
01/2021	01/2021	01/2021	01/2021	06/2019		01/2021	
				✓			
—	26/03/2019	Warranty	108538 Km	10126	Job: Intake manifold		

— Job: Intake manifold

Description: Intake manifold

Considered as a repeat visit No

Customer's own words

Performing vehicle test
Flat rate unit I 00 00 006 4 FRU

Removing and installing intake manifold
Flat rate unit I 11 61 550 21 FRU

Job time without allowance for / engine
Flat rate unit I 11 99 000 12 FRU

Intake manifold
Defect I 11 61 12 76 00

— 25/03/2019 Key 108538 Km 10126 Key 1

								
22000	22000	22000	22000	70000	70000	70000	22000	22000
02/2021	666	666	666		06/2019		02/2021	

— 04/03/2019 Key 105573 Km 10126 Key 1

								
26000	26000	26000	26000	9000	70000	26000	26000	26000
02/2021	687	687	687		06/2019		02/2021	

— 04/03/2019 Service 105573 Km 10126 Bortolin Automatic Hannut, Hannut

								
26000	26000	26000	26000	9000	0	70000	26000	26000
01/2021	01/2021	01/2021	01/2021	✓				

— 04/03/2019 Warranty 105573 Km 10126 Job

— Job

Description:

Considered as a repeat visit No

Customer's own words












































Visual inspection of EGR cooler output and checking cooler intake with CCM coolant level
Flat rate unit I 00 67 714 12 FRU

Defect I 00 11 10 05 00

— 11/02/2019 Key 102894 Km 10126 Key 1

								
1000		1000		10000	8000	28000		
09/2020		560			06/2019		09/2022	

—	11/02/2019	Service	102894 Km	10126 Bortolin Hannut , Hannut	Automatic		
 1000 01/1970 ✓	 0 01/1970	 1000 08/2020 ✓	 0 01/1970	 10000 01/1970	 0 01/1970	 8000 01/1970	 28000 01/1970
—	10/09/2018	Key	85742 Km		Key 1		
 -800 03/2020	 -800 531	 -800 531	 -800 531	 27000	 06/2019	 26000	 -800 03/2020
—	10/09/2018	Service	85742 Km	10126 Bortolin Hannut , Hannut	Automatic		
 -800 01/1970 ✓	 -800 02/2020 ✓	 -800 02/2020 ✓	 -800 02/2020 ✓	 27000 01/1970	 0 01/1970	 26000 01/1970	 -800 01/1970 ✓
—	09/07/2018	Key	78551 Km	10126	Key 1		
 9000 03/2020	 9000 592	 9000 592	 9000 592	 36000	 06/2019	 35000	 9000 03/2020
—	25/05/2018	Key	73903 Km	10126	Key 1		
 16000 03/2020	 16000 636	 16000 636	 16000 636	 43000	 06/2019	 43000	 16000 03/2020
—	14/03/2018	Key	63874 Km	10126	Key 1		
 -150 08/2019		 -150 497		 60000	 06/2019	 60000	 28000 08/2021
—	14/03/2018	Service	63874 Km	10126 Bortolin Hannut , Hannut	Automatic		
 -150 ✓		 -150 07/2019 ✓		 60000		 60000	 28000
—	05/03/2018	Key	63124 Km	10126	Key 1		

	 900 08/2019	 0	 900 506	 0	 60000 06/2019	 0	 60000 06/2019	 29000 08/2021	
—	23/11/2017	Key		51827 Km	10126		Key 1		
	 15000 08/2019	 0	 15000 645	 0	 6000 06/2019	 0	 5000	 44000 08/2021	
—	23/11/2017	Service		51827 Km	10126 Bortolin Hannut , Hannut		Automatic		
	 15000 08/2019	 0	 15000 08/2019	 0	 6000 06/2019	 0	 5000 06/2019	 44000 08/2021	
—	07/08/2017	Key		41519 Km	10126		Key 1		
	 -370 12/2018	 -370 510	 -370 510	 -370 510	 16000 06/2019	 0	 14000	 -370 12/2018	
—	07/08/2017	Service		41519 Km	10126 Delbrassinne Motors sa Delbrassinne , Hannut		Automatic		
	 -370 12/2018 ✓	 -370 12/2018 ✓	 -370 12/2018 ✓	 -370 12/2018 ✓	 16000 06/2019	 0	 14000	 -370 12/2018 ✓	
—	22/05/2017	Key		34810 Km	10126		Key 1		
	 8000 12/2018	 8000 587	 8000 587	 8000 587	 20000 06/2019	 0	 18000	 8000 12/2018	
—	22/12/2016	Key		20281 Km	10126		Key 1		
	 600 06/2018	 0	 600 555	 0	 34000 06/2019	 0	 33000	 28000 06/2020	
—	22/12/2016	Service		20281 Km	10126 Delbrassinne Motors sa Delbrassinne , Hannut		Automatic		

							
600		600		34000		33000	28000
06/2018		06/2018			06/2019		06/2020
✓		✓					