
Vehicle

BMW 520D XDR A, 140KW

WBA5E71050GK08216



Development code
Colour
Actual integration level
Start of warranty

F10
imperial-blau brillant metallic
F010-23-07-530
16 December 2014

Technical campaigns

There are no Campaigns for this vehicle.

Warranty extension/VIN-based goodwill

Status	Campaign number	Description
Open	1SACC011056	Exhaust gas recirculation cooler Bx7 Local campaign number: -

Special information

There are no Campaigns for this vehicle.

Restrictions on the warranty

There are no restrictions on the warranty.

⚠ Market-specific restrictions are not currently displayed. Please check this in WDF/WXE via S-Gate.

Live Diagnosis

 There are no service solutions for Live Diagnosis.

Service contracts

No BSI contracts

Information on faults workshop/Service Consultation

There is no information on faults.

Navigation map

Installed map	Enabling code (subscription)	Latest navigation map included in subscription	Latest navigation map subject to charge
Road Map EUROPE Route 2014-1 (As of: 27 Nov 2023)	Enabling code valid for navigation maps with release date up to 31 Dec 2025 (SWID: 00B4008F).	Road Map EUROPE WEST Route 2025	-

Vehicle details

Vehicle type	Passenger car
Brand	BMW
Model	520D XDR A
Body	LIM
Vehicle identification number (last 7 digits)	GK08216
Vehicle identification number (17 digits)	WBA5E71050GK08216
Development code	F10
Steering	LL
Engine	B47O
Engine number	91249048
Exhaust re-treatment	EURO6, W, PI/CI, M, N1 I
Transmission	AUT
Transmission number	0031287XAT
Head unit serial number	MM01DFE0369985
Drive	ALLR
Integration level, works	F010-14-07-505
Production date	16 Oct 2014
Production plant	Dingolfing
Delivery date	26 Nov 2014
Delivering retailer	BYmyCAR, PARIS, FR
National-market version	EUR
Paint code	A89
Upholstery code	LCSW
Model code	5E81
Basic type	5E71
Lead type	5E81

Optional equipment

Optional equipment ex works:


















01CA Selection of COP-relevant vehicles
 01CB CO2 equipment
 01CC Auto start/stop function
 01CD Brake Energy Regeneration
 0205 Automatic transmission
 0230 EU-specific additional contents
 0258 Tyres with runflat properties
 02PA Locking wheel bolt
 02V4 BMW LA wheel, M double spoke 613
 02VB Tyre pressure display
 0320 Deleted, model lettering
 0337 M Sports package
 0403 Glass roof, electrical
 0428 Warning triangle and first aid kit
 0430 Interior/outside mirror with auto dip
 0431 Interior mirror with automatic-dip
 0441 Smoker package
 0465 Through-loading system
 0481 Sports seat
 04B9 Interior trim strips,alum.finishgrinding
 04U2 Driving Experience Control incl. ECO PRO
 0502 Headlight cleaning system
 0508 Park Distance Control (PDC)
 0548 Kilometre speedo
 0552 Adaptive LED headlight
 05A1 LED Fog lights
 05AC High-beam assistant
 0606 Navigation system Business
 0698 Area-Code 2 for DVD
 06AC Intelligent emergency call
 06AE Teleservices
 0710 M leather steering wheel
 0715 M Aerodynamics package
 0760 High gloss shadow line
 0775 Headlining anthracite
 0854 Language version, French
 0881 On-board literature, French
 08KA Oil service interval 24 mths / 30,000 km
 08S3 Automatic locking during starting
 08TF Active pedestrian protection
 A105 105 Ah AGM battery
 LEDE Leather equipment

Retrofitted optional equipment:

This vehicle has no retrofits.

Vehicle histories

	Date	Type	Vehicle mileage	Retailer	Overview
—	26/06/2025	Service	142417 Km	OSS-60185608 HCG SPIDI GRUP S.R.L., BRASOV	Automatic

 -3000 11/2023 ✓		 -3000 11/2023 ✓		 5000	 01/2024	 01/2024	 19000	 28000 11/2025
—	16/11/2023	Key	128562 Km	05495	Key 0			
 -3000 9.7 % -12 1.6 %		 -3000 -12 1.6 %		 5000	 01/2024	 01/2024	 19000	 28000 11/2025
—	16/11/2023	Service	128562 Km	05495 BAYERN BY AUTOSPHERE BORDEAUX, BORDEAUX/MERIGNAC	Automatic			
 -3000 11/2023 ✓		 -3000 11/2023 ✓		 5000	 01/2024	 01/2024	 19000	 28000 11/2025
—	16/11/2023	Warranty	128562 Km	05495	Job: F1x F2x F3x G0x G1x G3x B47O B47K B47U B47T Replacing EGR cooler (high-temperature) Job: Fx Replace driver's airbag (SDI)			

— Job: F1x F2x F3x G0x G1x G3x B47O B47K B47U B47T Replacing EGR cooler (high-temperature)

Description: F1x F2x F3x G0x G1x G3x B47O B47K B47U B47T Replacing EGR cooler (high-temperature)

Considered as a repeat visit No

Customer's own words

Replace exhaust gas recirculation cooler, including exhaust gas recirculation valve Flat rate unit I 00 72 999	20 FRU
---	--------

Additional work: run function test for pressure sensor system Flat rate unit I 00 73 500	3 FRU
---	-------

Additional work: enter component identification of new exhaust gas recirculation cooler in diagnostic system Flat rate unit I 00 73 501	1 FRU
--	-------

F1x F2x F3x G0x G1x G3x B47O B47K B47U B47T Replacing EGR cooler (high-temperature) Defect I 00 11 60 06 00	
--	--

Exhaust gas radiator high temperature Part I 11 71 7 822 347	1
---	---

Acoustic cover front Part I 11 14 8 490 575	1
--	---

Vacuum hose black Part I 11 65 8 595 650	1
---	---

Pipe union Part I 11 71 7 799 853	2
--------------------------------------	---

EGR small parts set Part I 11 71 8 490 640	1
---	---

O-ring Part I 11 61 8 512 681	1
----------------------------------	---

Holder
Part I 61 13 1 369 832

— Job: Fx Replace driver's airbag (SDI)

Description: Fx Replace driver's airbag (SDI)

Considered as a repeat visit No

Customer's own words

Replace driver's airbag
Flat rate unit I 00 73 781

3 FRU


Fx Replace driver's airbag (SDI)
Defect I 00 32 39 03 00

Airbag module, driver's side
Part I 32305A66F66

1

—	25/10/2023	Key	127931 Km	05495	Key 0				
-2300 7.4 % 11/2023		-2300 11/2023		5000 01/2024	01/2024	20000 01/2024	29000 11/2025		
—	16/06/2022	Key	109571 Km	05495	Key 0				
22000 11/2023		22000 495		5000 01/2024	555	30000	50000 11/2025		
—	11/01/2022	Key	104006 Km		Key 0				
28000 11/2023		28000 650		5000	-730 99.9 %	-730 99.9 %	33000	-1600 -70 9.6 %	
—	11/01/2022	Service	104006 Km	05495 BAYERN BY AUTOSPHERE , BORDEAUX/MERIGNAC	Automatic				
28000 10/2023		28000 10/2023		5000	01/2020 ✓	33000	-1600 11/2021 ✓		
—	18/12/2021	Key	103561 Km		Key 0				
28000 11/2023		28000 673		5000	-707 96.8 %	-707 96.8 %	34000	-2100 -47 6.4 %	
—	27/08/2021	Key	100377 Km		Key 0				
-17000 -592 81 %	-17000 -592 81 %	-17000 -592 81 %	-17000 -592 81 %	7000	-592 81 %	37000	-17000 -592 81 %		

— 27/08/2021 Service 100377 Km 05495 BAYERN BY Automatic
AUTOSPHERE,
BORDEAUX/MERIGNAC



— 27/08/2021 Repair 100377 Km 05495 BAYERN BY Job
AUTOSPHERE
BORDEAUX,
BORDEAUX/MERIGNAC

— Job

Description:

Considered as a repeat visit No

Customer's own words un voyant orange uniquement

tableau de bord ne s'allume plus	Local	10 FRU
Flat rate unit I -		

Service prestations standard
Package I 0000105

Service - standard scope	2
Flat rate unit I 00 00 105	

Service cartouche de filtre à air
Package I 0000602

Service - air filter element	1
Flat rate unit I 00 00 602	

Air filter element	1
Part I 13718570043	

Entretien filtre à carburant
Package I 0000604

Service fuel filter	5
Flat rate unit I 00 00 604	

Hose clamp	1
Part I 16121180240	

Fuel filter cartridge	1
Part I 13327811227	

Service huile moteur
Package I 0000610

Engine oil service	3
Flat rate unit I 00 00 610	

BMW Engine Oil LL04 5W30	5
Part I 83212405948	

Set oil-filter element	1
Part I 11428575211	

Service microfiltre
Package I 0000616

Microfilter service	3
Flat rate unit I 00 00 616	

Set, microfilter/carbon canister	1
Part I 64119272642	

Service liquide de frein
Package I 0000618

Brake fluid service 4
Flat rate unit I 00 00 618

Brake fluid DOT4 LV, low viscosity 1
Part I 83132405977

Service contrôle véhicule
Package I 0000624

Service, vehicle check 7
Flat rate unit I 00 00 624

— 27/08/2021 Warranty 100377 Km 05495 Job: F1x F2x F3x F4x G0x G1x G3x B47 Check and if required replace exhaust-gas recirculation cooler

— Job: F1x F2x F3x F4x G0x G1x G3x B47 Check and if required replace exhaust-gas recirculation cooler

Description: F1x F2x F3x F4x G0x G1x G3x B47 Check and if required replace exhaust-gas recirculation cooler

Considered as a repeat visit No

Customer's own words

Replace exhaust gas recirculation cooler using the pressure sensor 26 FRU
system test and note production date of both exhaust gas recirculation coolers
Flat rate unit I 00 70 526


F1x F2x F3x F4x G0x G1x G3x B47 Check and if required replace exhaust-gas recirculation cooler
Defect I 00 11 40 05 00

exhaust cooler 1
Part I 11 71 8 596 444

Pipe union 2
Part I 11 71 7 799 853

Set of small parts 1
Part I 11 71 8 597 652

— 10/01/2018 Key 66691 Km 22319 Key 0



— 10/01/2018 Service 66691 Km 22319 CH. POZZI, PARIS Automatic



— 10/01/2018 Repair 66691 Km 22319 CH. POZZI, LEVALLOIS-PERRET
Job: Service huile moteur
Job: Service microfiltre
Job: Service prestations standard
Job: Service liquide de frein
Job

— Job: Service huile moteur

Description:

Considered as a repeat visit No

Customer's own words

Service huile moteur

Package I 0000610

Engine oil service	3
Flat rate unit I 00 00 610	

Set oil-filter element	1
Part I 11428575211	

BMW Engine Oil LL04 5W30	5
Part I 83212405948	

— Job: Service microfiltre

Description:

Considered as a repeat visit No

Customer's own words

Service microfiltre

Package I 0000616

Microfilter service	3
Flat rate unit I 00 00 616	

Set, microfilter/carbon canister	1
Part I 64119272642	

— Job: Service prestations standard

Description: CONTRAT TEMSYS

Considered as a repeat visit No

Customer's own words

Service prestations standard

Package I 0000105

Service - standard scope	2
Flat rate unit I 00 00 105	

— Job: Service liquide de frein

Description:

Considered as a repeat visit No

Customer's own words

Service liquide de frein

Package I 0000618

Brake fluid service	4
Flat rate unit I 00 00 618	

Brake fluid DOT4 LV, low viscosity	1
Part I 83132184843	

— Job

Description:

Considered as a repeat visit No

Customer's own words

Additional work, top up AdBlue	3 FRU
Flat rate unit I 00 00 667	

— Job

Description:

Considered as a repeat visit No

Customer's own words

Balais Essuie-glace AV
Flat rate unit | -

Local

2 FRU

— 27/12/2017 Key 65210 Km 43591 Key 0



— 11/08/2017 Key 57636 Km 43591 Key 0



— 26/05/2017 Key 53181 Km 43591 Key 0



— 26/05/2017 Warranty 53181 Km 43591 Job: F0x F1x N47 B47 Replace air conditioning condenser

— Job: F0x F1x N47 B47 Replace air conditioning condenser

Description: F0x F1x N47 B47 Replace air conditioning condenser

Considered as a repeat visit No

Customer's own words

Check and replace air conditioning capacitor
Flat rate unit | 00 64 293

17 FRU

F0x F1x N47 B47 Replace air conditioning condenser
Defect | 00 64 93 01 00Condenser, air conditioning
Part | 64 50 9 391 489

1

Gasket ring
Part | 64 50 8 375 741

1


Gasket ring
Part | 64 50 8 374 959

1


Hex Bolt
Part | 07 14 7 029 829

2

— 27/12/2016 Key 46279 Km 43591 Key 0



— 27/12/2016 Service 46279 Km 43591 S.D.A. Automatic
SPORT,
MONT DE
MARSAN



— 27/12/2016 Warranty 46279 Km 43591 Job

— Job

Description:

Considered as a repeat visit No

Customer's own words


Replacing the exhaust-gas recirculation cooler 16 FRU
Flat rate unit I 00 64 199

Defect I 00 11 36 04 00

exhaust cooler 1
Part I 11 71 8 596 444

Set of small parts 1
Part I 11 71 8 597 652

— 23/08/2016 Key 37609 Km 22319 Key 0



— 23/08/2016 Repair 37609 Km 22319 CH. Job
POZZI,
LEVALLOIS-
PERRET

— Job

Description: FUITE LIQUIDE DE REFROIDISSEMENT CLIENT A REMIS 10LITRES EN 1000KMS

Considered as a repeat visit No

Customer's own words

Effectuer un diagnostic mécanique (Forfait 180€ TTC) Local 24 FRU
Flat rate unit I -

— 23/08/2016 Warranty 37609 Km 22319 Job: EGR cooler (incl. bypass flap) /
exhaust cooler

— Job: EGR cooler (incl. bypass flap) / exhaust cooler

Description: EGR cooler (incl. bypass flap) / exhaust cooler

Considered as a repeat visit No

Customer's own words

Removing and installing or replacing EGR cooler 16 FRU
Flat rate unit I 11 71 100

Bleed the cooling system and check it for watertightness with the special tool
Flat rate unit I 17 00 539

4 FRU

EGR cooler (incl. bypass flap) / exhaust cooler
Defect I 11 71 06 48 00

Exhaust gas radiator high temperature
Part I 11 71 8 513 691

1


Gasket Steel
Part I 11 61 8 571 005

1

Pipe union
Part I 11 71 7 799 853

2

— 12/02/2016 Key 25586 Km 22319 Key 0



— 12/02/2016 Repair 25586 Km 22319 CH. POZZI, LEVALLOIS-PERRET Job

— Job

Description: pneu arriere

Considered as a repeat visit No


Customer's own words REMPL DES DEUX PNEUS AR

Changer pneu 2x
Flat rate unit I -

Local

12 FRU

— 21/12/2015 Key 21563 Km 22319 Key 0



— 21/12/2015 Repair 21563 Km 22319 CH. POZZI, LEVALLOIS-PERRET Job: Service gamme standard
Job: Service huile moteur
Job: Service microfiltre
Job

— Job: Service gamme standard

Description: + MISE A JOUR AD BLUE

Considered as a repeat visit No

Customer's own words

Service gamme standard
Package I 0000105

Service - standard scope
Flat rate unit I 00 00 105

2

— Job: Service huile moteur

Description:

Considered as a repeat visit No

Customer's own words

Service huile moteur

Package I 0000610

Engine oil service 3
Flat rate unit I 00 00 610

Set oil-filter element 1
Part I 11428575211

BMW Engine Oil LL04 5W30 5
Part I 83212405948

— Job: Service microfiltre

Description:

Considered as a repeat visit No

Customer's own words

Service microfiltre

Package I 0000616

Microfilter service 3
Flat rate unit I 00 00 616

Set, microfilter/carbon canister 1
Part I 64119272642

Pollen-filter housing cleaner 1
Part I 83192180509

— Job

Description:

Considered as a repeat visit No

Customer's own words


Balais Essuie-glace AV

Local

2 FRU

Flat rate unit I -

— 10/04/2015 Key 6327 Km 08311 Key 0



— 10/04/2015 Repair 6327 Km 08311 Job
NEUBAUER
BOULOGNE
BOULOGNE
BILLANCOURT
, BOULOGNE-
BILLANCOURT

— Job

Description: CLIENT ATTEND SUR PLACE

Considered as a repeat visit No

Customer's own words

Changer pneu 2x FORFAIT 60 € TTC

Local

9 FRU

Flat rate unit I -

— 29/12/2014 Key 1080 Km 09246 Key 0



28000

11/2016



48000



0

11/2017



49000



60000

11/2018