

Thank you for ordering from us!

www.checkvin.eu

Vehicle

BMW 318D A, 110KW

WBA8H71050A041928



Development code
Colour
Actual integration level
Start of warranty

F31
mineral-grau metallic
F020-23-03-500
16 October 2017

Technical campaigns

There are no Campaigns for this vehicle.

Warranty extension/VIN-based goodwill

Status	Campaign number	Description
Open	1SACC011056	Exhaust gas recirculation cooler Bx7 Local campaign number: -

Special information

There are no Campaigns for this vehicle.

Restrictions on the warranty

There are no restrictions on the warranty.

⚠ Market-specific restrictions are not currently displayed. Please check this in WDF/WXE via S-Gate.

Live Diagnosis

 There are no service solutions for Live Diagnosis.

Service contracts

No BSI contracts

Information on faults workshop/Service Consultation

There is no information on faults.

Navigation map

Note: The installed map cannot be clearly identified. Presumably one of the following maps is present in the vehicle.

Installed map	Enabling code (subscription)	Latest navigation map included in subscription	Latest navigation map subject to charge
Road Map EUROPE EVO 2021-3 (As of: 25 Mar 2024)	Enabling code valid for navigation maps with release date up to 31 Dec 2099 (SWID: 01200FFF).	Road Map EUROPE EVO 2025-1	-
Road Map EUROPE EVO 2021-3 (As of: 25 Mar 2024)	-	-	-

Vehicle details

Vehicle type	Passenger car
Brand	BMW
Model	318D A
Body	TOUR
Vehicle identification number (last 7 digits)	A041928
Vehicle identification number (17 digits)	WBA8H71050A041928
Development code	F31
Steering	LL
Engine	B47U
Engine number	62835123
Exhaust re-treatment	EURO6, W, PI/CI, M, N1 I
Transmission	AUT
Transmission number	1186760Z34
Head unit serial number	HB2240H8185589
Drive	HECK
Integration level, works	F020-17-07-507
Production date	29 Sept 2017
Production plant	Muenchen
Delivery date	12 Oct 2017
Delivering retailer	SIXT ASSET & FINANCE SAS, AVRIGNY, FR
National-market version	EUR
Paint code	B39
Upholstery code	LCL8
Model code	8H81
Basic type	8H71
Lead type	8H81

Optional equipment

Optional equipment ex works:

01CA Selection of COP-relevant vehicles
 01CB CO2 equipment
 0205 Automatic transmission
 0216 Hydro steering-servotronic
 0230 EU-specific additional contents
 0258 Tyres with runflat properties
 02PA Locking wheel bolt
 02PE BMW LA wheel, M star spoke 400
 02VB Tyre pressure display
 0302 Alarm system
 0320 Deleted, model lettering
 0337 M Sports package
 03AG Reversing camera
 03AT Roof rails aluminium satinated
 03L8 Exterior equipment, aluminium, satinised
 0402 Panorama glass roof
 0423 Floor mats velours
 0428 Warning triangle and first aid kit
 0430 Interior/outside mirror with auto dip
 0431 Interior mirror with automatic-dip
 0441 Smoker package
 0481 Sports seat
 0488 Lumbar support, driver and passenger
 0493 Storage compartment package
 0494 Seat heating driver/passenger
 04AE Armrest front, retractable
 04WF Alum. Hexagon accent blue matt
 0508 Park Distance Control (PDC)
 0521 Rain sensor
 0534 Automatic air conditioning
 0544 Cruise control with brake function
 0548 Kilometre speedo
 0563 Light package
 05A1 LED Fog lights
 05A2 LED headlight
 05DA Passenger airbag deactivation
 05DC Rear-seat headrests, folding
 0609 Navigation system Professional
 0698 Area-Code 2 for DVD
 06AC Intelligent emergency call
 06AE Teleservices
 06AK Connected Drive Services
 06AM Real-Time Traffic Information
 06AN Concierge Services
 06AP Remote Services
 06NW Telephony with wireless charging
 06UH Traffic Information
 06WB Multifunctional instrument display
 06WD WLAN Hotspot
 0704 M Sports suspension
 0710 M Leather steering wheel
 0715 M Aerodynamics package
 0775 Headlining anthracite
 07LF Modell M Sport
 07S9 Connected Drive Services Paket
 0854 Language version, French
 0881 On-board literature, French
 08KA Oil service interval 24 mths / 30,000 km
 08R9 Refrigerant R1234yf
 08S3 Automatic locking during starting
 08TH Road sign detection
 09AA Outer skin protection
 A090 90 Ah AGM battery
 LEDE Leather equipment

Retrofitted optional equipment:

03AC Trailer coupling

Vehicle histories

	Date	Type	Vehicle mileage			Retailer	Overview		
—	25/03/2024	Key	178756 Km			20406	Key 0		
	 16000 09/2025	 16000 09/2025	 16000 09/2025	 16000 09/2025	 7000	 03/2025	 8000	 16000 09/2025	 10/2024
—	25/03/2024	Warranty	178756 Km			20406	Job: F1x F2x F3x G0x G1x G3x B47O B47K B47U B47T Replacing EGR cooler (high-temperature) Job: E84 Fx Gx Bx7 Nx7 Customer notification exhaust gas recirculation cooler		
— Job: F1x F2x F3x G0x G1x G3x B47O B47K B47U B47T Replacing EGR cooler (high-temperature)									
Description: F1x F2x F3x G0x G1x G3x B47O B47K B47U B47T Replacing EGR cooler (high-temperature)									
Considered as a repeat visit No									
Customer's own words									
Replace exhaust gas recirculation cooler, including exhaust gas recirculation valve Flat rate unit I 00 74 062							25 FRU		
Additional work: run function test for pressure sensor system Flat rate unit I 00 74 650							3 FRU		
Additional work: enter component identification of new exhaust gas recirculation cooler in diagnostic system Flat rate unit I 00 74 651							1 FRU		
Additional work for replacing intake system Flat rate unit I 00 74 653							24 FRU		
F1x F2x F3x G0x G1x G3x B47O B47K B47U B47T Replacing EGR cooler (high-temperature) Defect I 00 11 15 07 00									
Exhaust gas radiator high temperature Part I 11 71 7 822 347							1		
EGR small parts set Part I 11 71 8 490 640							1		
Pipe union Part I 11 71 7 799 853							2		
Connection piece Part I 11 65 7 803 012							1		
O-ring Part I 11 61 8 512 681							1		
Hex Bolt Part I 07 14 7 029 829							4		
Acoustic cover front Part I 11 14 8 490 577							1		
Intake manifold AGR with flap control Part I 11 61 8 513 655							1		
Sensor, boost pressure Part I 13 62 8 637 896							1		
— Job: E84 Fx Gx Bx7 Nx7 Customer notification exhaust gas recirculation cooler									

Description: E84 Fx Gx Bx7 Nx7 Customer notification exhaust gas recirculation cooler

Considered as a repeat visit No

Customer's own words

Administrative effort 1 FRU
Flat rate unit I 00 74 758

E84 Fx Gx Bx7 Nx7 Customer notification exhaust gas recirculation cooler
Defect I 00 11 35 07 00

—

04/04/2023

Key

142900 Km

Key 0



13000

08/2024





13000

08/2024





7000

03/2025



8000

08/2026



44000



10/2023

—

04/04/2023

Warranty

142900 Km

03693

Job: G0x G3x B47O Programming control units (DDE)

— Job: G0x G3x B47O Programming control units (DDE)

Description: G0x G3x B47O Programming control units (DDE)

Considered as a repeat visit No

Customer's own words

Program control units 9 FRU
Flat rate unit I 00 71 374

G0x G3x B47O Programming control units (DDE)
Defect I 00 13 51 03 00

—

15/09/2021

Key

99320 Km

Key 0



24000

05/2023



24000

587



24000

587



24000

587



50000



46000

09/2022



24000

05/2023



10/2021

—

15/09/2021

Warranty

99378 Km

03633

Job: F1x F2x F3x G0x G1x G3x B47O B47T B47U B47K Check and, if required, replace EGR cooler

— Job: F1x F2x F3x G0x G1x G3x B47O B47T B47U B47K Check and, if required, replace EGR cooler

Description: F1x F2x F3x G0x G1x G3x B47O B47T B47U B47K Check and, if required, replace EGR cooler

Considered as a repeat visit No

Customer's own words

Visual insp. of EGR cooler outlet and inlet (OK), check CC message about coolant level (OK) and note the prod. date of the installed exhaust gas recirc. cooler 14 FRU
Flat rate unit I 00 70 005

F1x F2x F3x G0x G1x G3x B47O B47T B47U B47K Check and, if required, replace EGR cooler
Defect I 00 11 88 05 00

Gasket Steel 1
Part I 11 71 8 579 364

—

15/03/2019

Key





















29847 Km

03633

Key 0

<https://myair-b2d.bmwgroup.com/air/faces/xhtml/fahrzeug/FahrzeugSingleView.xhtml?vin=WBA8H71050A041928>

5/7

—	15/03/2019	Service		29847 Km	03633 Dusseldorp Alkmaar bv , Alkmaar	Automatic		
 900 09/2019	 	 900 166	 	 90000 10/2020	 	 90000	 32000 09/2021	 10/2021
—	05/03/2019	Key		29167 Km		Key 0		
 900 08/2019 ✓	 	 900 08/2019 ✓	 	 90000 09/2020	 	 90000	 32000 08/2021	 09/2021
—	05/03/2019	Service		29167 Km	03633 Dusseldorp Alkmaar bv , Alkmaar	Automatic		
 1600 09/2019	 	 1600 176	 	 90000 10/2020	 	 90000	 33000 09/2021	 10/2021
—	05/03/2019	Repair		29167 Km	03633 Dusseldorp Alkmaar B.V. , Alkmaar	Job		
 1600 08/2019 ✓	 	 1600 08/2019 ✓	 	 90000 09/2020	 	 90000	 33000 08/2021	 09/2021

— Job

Description:

Considered as a repeat visit No

Customer's own words

Service standaard omvang
Package I 0000105

Service - standard scope	2
Flat rate unit I 00 00 105	

Service motorolie
Package I 0000610

Engine oil service	3
Flat rate unit I 00 00 610	

BMW Genuine Oil LL-04 0W30	Local	5
Part I SLX		

Set oil-filter element	1
Part I 11428575211	

Service microfilter
Package I 0000616

Microfilter service	2
---------------------	---

Flat rate unit I 00 00 616

Microfilter/activated Carbon container
Part I 64119237555

1

—	24/10/2018	Key		17886 Km		Key 0			
									
	13000		13000		70000	70000	44000		
	09/2019		307			10/2020	09/2021		10/2021
—	12/07/2018	Key		17487 Km	31407	Key 0			
									
	13000		13000		70000	70000	44000		
	09/2019		410			10/2020	09/2021		10/2021
—	16/10/2017	Service		2 Km	04922 Walon France, Lauterbourg	Manual			
									
							0		
							10/2017		
							✓		