

Thank you for ordering from us!
www.checkvin.eu

Vehicle

BMW 520D A, 140KW

WBA5L31000D677049



Development code
Colour
Actual integration level
Start of warranty

F11
sophisto-grau brillant metallic
F010-22-11-510
5 August 2014

Technical campaigns

There are no Campaigns for this vehicle.

Warranty extension/VIN-based goodwill

Status	Campaign number	Description
Open	1SACC011056	Exhaust gas recirculation cooler Bx7 Local campaign number: -

Special information

There are no Campaigns for this vehicle.

Restrictions on the warranty

There are no restrictions on the warranty.

⚠ Market-specific restrictions are not currently displayed. Please check this in WDF/WXE via S-Gate.

Live Diagnosis

 There are no service solutions for Live Diagnosis.

Service contracts

No BSI contracts

Information on faults workshop/Service Consultation

There is no information on faults.

Navigation map

Installed map	Enabling code (subscription)	Latest navigation map included in subscription	Latest navigation map subject to charge
Road Map EUROPE Next 2014-2 (As of: 15 Jan 2025)	Enabling code valid for navigation maps with release date up to 31 Dec 2025 (SWID: 00A9008F).	Road Map EUROPE EAST Next 2025	-

Vehicle details

Vehicle type	Passenger car
Brand	BMW
Model	520D A
Body	TOUR
Vehicle identification number (last 7 digits)	D677049
Vehicle identification number (17 digits)	WBA5L31000D677049
Development code	F11
Steering	LL
Engine	B47O
Engine number	85398965
Exhaust re-treatment	EURO6, W, PI/CI, M, N1 I
Transmission	AUT
Transmission number	0004264XAB
Head unit serial number	HB2068E7917895
Drive	HECK
Integration level, works	F010-14-07-503
Production date	24 Jul 2014
Production plant	Dingolfing
Delivery date	18 Aug 2014
Delivering retailer	Fuhrpark, München, DE
National-market version	EUR
Paint code	A90
Upholstery code	LCOX
Model code	5L41
Basic type	5L31
Lead type	5L41

Optional equipment

Optional equipment ex works:

01CA Selection of COP-relevant vehicles
 01CB CO2 equipment
 01CC Auto start/stop function
 01CD Brake Energy Regeneration
 0205 Automatic transmission
 0230 Extra package, EU-specific
 0255 Sports leather steering wheel
 0258 Tyres with runflat properties
 02D3 BMW LA wheel, star spoke 365
 02VB Tyre pressure display
 0302 Alarm system
 0316 automatic trunk lid mechanism
 0320 Deleted, model lettering
 0322 Comfort access
 03AT Roof rails aluminium satinated
 0417 Roller sun visor, rear door
 0418 Luggage compartment package
 0423 Floor mats velours
 0428 Warning triangle and first aid kit
 0431 Interior mirror with automatic-dip
 0453 Climate-controlled seats, front
 0456 Comfort seat with memory
 0488 Lumbar support, driver and passenger
 0494 Seat heating driver/passenger
 04AT Interior trim finishers black high-gloss
 04U2 Driving experience switch incl. ECO PRO
 04UR Ambient interior light
 0502 Headlight cleaning system
 0508 Park Distance Control (PDC)
 0524 Adaptive Headlights
 0534 Automatic air conditioning
 0548 Kilometre speedo
 0575 Additional 12V sockets
 05A1 LED Fog lights
 05AC High-beam assistant
 05AL Active Protection
 0609 Navigation system Professional
 0610 Head-up display
 0688 Harman/Kardon surround sound system
 0698 Area-Code 2 for DVD
 06AC Intelligent emergency call
 06AE Teleservices
 06AK Connected Drive Services
 06AM Real-Time Traffic Information
 06AN Concierge Services
 06AP Remote Services
 06AR Internet
 06NS Comfort telephony w/ enhanced Smartphone
 06WB Multifunctional instrument display
 0761 Individual sunshade glazing
 0775 Headlining anthracite
 07RS Package Comfort
 07XP Navigation package Connected Drive
 0801 German version
 0851 Language version German
 0879 On-board literature, German
 08KA Oil service interval 24 mths / 30,000 km
 08TF Active pedestrian protection
 09AA Outer skin protection
 A105 105 Ah AGM battery
 LEDE Leather equipment

Retrofitted optional equipment:

0877 Omission of non-combined operation

Vehicle histories

	Date	Type	Vehicle mileage	Retailer	Overview
—	10/07/2025	Key	243020 Km	01554	Remote KeyRead

 23000 12/2026  23000 12/2026  23000 12/2026  23000 12/2026  80000  07/2027  07/2027  60000  23000 12/2026  09/2025	30/06/2025	Service	242715 Km	OSS-50022946 A.T.U Auto-Teile-Unger Handels GmbH & Co. KG, Weiden	Automatic
 23000 12/2026  23000 12/2026  23000 12/2026  23000 12/2026  80000  06/2025  06/2025  60000  23000 12/2026  09/2025  09/2025  09/2025	15/01/2025	Key	239759 Km	01554	Key 0
 28000 12/2026  28000 12/2026  28000 12/2026  28000 12/2026  80000  06/2025  06/2025  70000  28000 12/2026  09/2025	15/01/2025	Warranty	239766 Km	01554	Job: F1x F2x F3x G0x G1x G3x B47O B47K B47U B47T Replacing EGR cooler (high-temperature) Job: E84 Fx Gx Bx7 Nx7 Customer notification exhaust gas recirculation cooler Job: Fx Checking driver's airbag and replacing if necessary (SDI conversion)

— Job: F1x F2x F3x G0x G1x G3x B47O B47K B47U B47T Replacing EGR cooler (high-temperature)

Description: F1x F2x F3x G0x G1x G3x B47O B47K B47U B47T Replacing EGR cooler (high-temperature)

Considered as a repeat visit No

Customer's own words

Replace exhaust gas recirculation cooler, including exhaust gas recirculation valve Flat rate unit I 00 74 057	22 FRU
Additional work: run function test for pressure sensor system Flat rate unit I 00 74 636	3 FRU
Additional work: enter component identification of new exhaust gas recirculation cooler in diagnostic system Flat rate unit I 00 74 637	1 FRU
Additional work cleaning the exhaust gas recirculation pipe Flat rate unit I 00 74 638	6 FRU
F1x F2x F3x G0x G1x G3x B47O B47K B47U B47T Replacing EGR cooler (high-temperature) Defect I 00 11 13 07 00	
Exhaust gas radiator high temperature Part I 11 71 7 822 347	1
EGR small parts set Part I 11 71 8 490 640	1
Pipe union	2

Part I 11 71 7 799 853	
Holder Part I 61 13 1 369 832	1
Connection piece Part I 11 65 7 803 012	1
O-ring Part I 11 61 8 512 681	1
Hex Bolt Part I 07 14 7 029 829	2
Acoustic cover front Part I 11 14 8 490 575	1

— Job: E84 Fx Gx Bx7 Nx7 Customer notification exhaust gas recirculation cooler

Description: E84 Fx Gx Bx7 Nx7 Customer notification exhaust gas recirculation cooler

Considered as a repeat visit No

Customer's own words

Vehicle was already finished with another repair or technical campaign Flat rate unit I 00 74 759	1 FRU
E84 Fx Gx Bx7 Nx7 Customer notification exhaust gas recirculation cooler Defect I 00 11 35 07 00	

— Job: Fx Checking driver's airbag and replacing if necessary (SDI conversion)

Description: Fx Checking driver's airbag and replacing if necessary (SDI conversion)

Considered as a repeat visit No


Customer's own words

Check steering wheel (airbag module not affected) Flat rate unit I 00 76 854	1 FRU
Fx Checking driver's airbag and replacing if necessary (SDI conversion) Defect I 00 32 55 03 00	

— 19/12/2024 Service 239623 Km OSS-50022946 Manual
A.T.U Auto-Teile-Unger Handels GmbH & Co. KG, Weiden






— 26/11/2024 Key 239468 Km 01554 Remote KeyRead



— 05/01/2024 Service 226878 Km OSS-50022946 Manual
A.T.U Auto-Teile-Unger



12/09/2023 Key 226005 Km 01554 Key 0



12/09/2023 Repair 226006 Km 01554 Autohaus Rolf Horn GmbH, Düren Job Job

Job

Description:
Considered as a repeat visit No
Customer's own words

Fußraumreinigung Flat rate unit I 00 11 320	Local	1 FRU
Vehicle surface wash Flat rate unit I 00 11 319		3 FRU

Job

Description:
Considered as a repeat visit No
Customer's own words

HU / AU Abnahme Flat rate unit I 99 99 999	Local	1 FRU
---	-------	-------

12/09/2023 Warranty 226006 Km 01554 Job: Fx Gx B37 B47 B57 N47 N57 Check coolant level (EGR)

Job: Fx Gx B37 B47 B57 N47 N57 Check coolant level (EGR)

Description: Fx Gx B37 B47 B57 N47 N57 Check coolant level (EGR)
Considered as a repeat visit No
Customer's own words

Flat rate unit I 00 73 827	4 FRU
Fx Gx B37 B47 B57 N47 N57 Check coolant level (EGR) Defect I 11 71 90 08 00	

14/06/2023 Warranty 219670 Km 01554 Job: F1x F2x F3x B47O B47K B47U Programming control units (DDE)

Job: F1x F2x F3x B47O B47K B47U Programming control units (DDE)

Description: F1x F2x F3x B47O B47K B47U Programming control units (DDE)

Considered as a repeat visit No

Customer's own words

Program control units 8 FRU
Flat rate unit I 00 71 907

F1x F2x F3x B47O B47K B47U Programming control units (DDE)
Defect I 00 13 50 03 00

—

13/06/2023

Key

219663 Km

Key 0



19000

12/2024





19000

12/2024





140000



-73

10 %



-73

10 %



5000



45000

12/2026



-12

1.6 %

—

13/06/2023

Service

219663 Km

01554
Autohaus Rolf
Horn GmbH,
Düren

Automatic



19000

12/2024





19000

12/2024





140000



04/2023

✓



04/2023

✓



5000



45000

12/2026



06/2023

—

13/06/2023

Repair

219670 Km

01554
Autohaus Rolf
Horn GmbH,
Düren

Job
Job
Job
Job
Job

— Job

Description:

Considered as a repeat visit No

Customer's own words

Service - standard scope 2 FRU
Flat rate unit I 00 00 105

— Job

Description:

Considered as a repeat visit No

Customer's own words

Brake fluid service 4 FRU
Flat rate unit I 00 00 618

Sicherheitsreiniger 50ml 1
Part I VS99 99 0 000 7 Local

Brake fluid DOT4 LV, low viscosity 1
Part I 83 13 2 184 843

— Job

Description:

Considered as a repeat visit No

Customer's own words

Service, rear brakes 8 FRU
Flat rate unit I 00 00 614

<https://myair-b2d.bmwgroup.com/air/faces/xhtml/fahrzeug/FahrzeugSingleView.xhtml?vin=WBA5L31000D677049>

7/23

Repair kit, brake pads Part I 34 21 8 847 062	1
Brake-pad sensor, rear Part I 34 35 6 791 963	1
Brake-pad paste Part I 83 19 2 158 851	2

— Job

Description:

Considered as a repeat visit No

Customer's own words

Wichtiger Rechnungshinweis Flat rate unit I 00 00 020	Local	0 FRU
--	-------	-------

— Job

Description:

Considered as a repeat visit No

Customer's own words

Fußraumreinigung Flat rate unit I 00 11 320	Local	1 FRU
--	-------	-------

04/05/2023		Key		219071 Km		Remote KeyRead		
								
21000		21000		140000	-33 4.5 %	-33 4.5 %	5000	48000
12/2024		12/2024					12/2026	06/2023

13/12/2022		Key	215365 Km				Key 0	
								
1100	1100	1100	1100	140000			5000	1100
04/2023	04/2023	04/2023	04/2023		04/2023	04/2023		04/2023
								06/2023

15/06/2022		Key		207335 Km		01554		Key 0	
									
10000	10000	10000	10000	130000			5000	10000	
04/2023	286	286	286		04/2023	286		04/2023	06/2023

24/08/2021	Warranty	202288 Km	01554	Job: F1x F2x F3x G0x G1x G3x B47O B47T B47U B47K Check and, if required, replace EGR cooler (recheck)
------------	----------	-----------	-------	--

— Job: F1x F2x F3x G0x G1x G3x B47O B47T B47U B47K Check and, if required, replace EGR cooler (recheck)

Description: F1x F2x F3x G0x G1x G3x B47O B47T B47U B47K Check and, if required, replace EGR cooler (recheck)

Considered as a repeat visit No

Customer's own words

Vis. insp. of EGR cool. out. and EGR cool. inl. (not OK). Rep. ex. gas rec. cool. us. the press. sens. syst. test and note prod. date of both ex. gas rec. cool. Flat rate unit I 00 70 023	31 FRU
--	--------

Additional work cleaning the exhaust gas recirculation pipe 2 FRU
Flat rate unit I 00 70 536

F1x F2x F3x G0x G1x G3x B47O B47T B47U B47K Check and, if
required, replace EGR cooler (recheck)
Defect I 00 11 89 05 00

exhaust cooler 1
Part I 11 71 8 596 444

Set of small parts 1
Part I 11 71 8 597 652

Pipe union 2
Part I 11 71 7 799 853

O-ring 1
Part I 11 61 8 583 456

— 23/08/2021 Repair 202288 Km 01554 Job
Autohaus Rolf Job
Horn GmbH ,
Düren

— Job

Description:

Considered as a repeat visit No

Customer's own words

Fußraumreinigung (aussaugen) Local 1 FRU
Flat rate unit I 00 11 320

Vehicle surface wash 0 FRU
Flat rate unit I 00 11 319

— Job

Description:

Considered as a repeat visit No

Customer's own words

HU / AU Inkasso 00000000 Local 1 FRU
Flat rate unit I 99 99 999

— 01/07/2021 Key 196382 Km Key 0

								
23000	23000	23000	23000	130000	0	19000	23000	0
04/2023	667	667	667		04/2023		04/2023	06/2023

— 01/07/2021 Repair 196382 Km 01554 Job
Autohaus Rolf Job
Horn GmbH ,
Düren

— Job

Description:

Considered as a repeat visit No

Customer's own words

Performing vehicle test 4 FRU
Flat rate unit I 00 00 006

Vehicle diagnosis - carrying out the ABL
Flat rate unit | 61 00 006

2 FRU

— Job

Description:

Considered as a repeat visit No


Customer's own words

Wichtiger Rechnungshinweis
Flat rate unit | 00 00 020

Local

0 FRU

- 13/04/2021 Service 191538 Km OSS-50022946 A.T.U Auto-Teile-Unger Handels GmbH & Co. KG, Weiden Manual
- 23/04/2020 Warranty 189090 Km 26636 Job: F1x F2x F3x F4x G0x G1x G3x B47 Check and if required replace exhaust-gas recirculation cooler



- Job: F1x F2x F3x F4x G0x G1x G3x B47 Check and if required replace exhaust-gas recirculation cooler

Description: F1x F2x F3x F4x G0x G1x G3x B47 Check and if required replace exhaust-gas recirculation cooler

Considered as a repeat visit No






Customer's own words

Check exhaust-gas recirculation cooler production date (then no further repairs necessary)
Flat rate unit | 00 68 736









3 FRU

F1x F2x F3x F4x G0x G1x G3x B47 Check and if required replace exhaust-gas recirculation cooler
Defect | 00 11 40 05 00

- 16/04/2020 Key 189089 Km 26636 Key 0



- 18/06/2019 Key 163235 Km 26636 Key 0



- 18/06/2019 Service 163235 Km 26636 Procar Automobile GmbH&Co. KG, Köln Automatic

 -160 07/2020 ✓	 -160 07/2020 ✓	 -160 07/2020 ✓	 -160 07/2020 ✓	 90000 07/2020 ✓	 0 12/2019 ✓	 50000 07/2020 ✓	 -160 07/2020 ✓	 0 08/2019 ✓
--	--	--	--	---	---	---	---	---

— 27/02/2019 Key 153117 Km Key 0

 10000 07/2020	 10000 520	 10000 520	 10000 520	 3200 12/2019	 0 12/2019	 50000 07/2020	 10000 07/2020	 0 08/2019
---	---	---	---	--	---	---	--	---

— 27/02/2019 Service 153117 Km 26636 Procar Automobile GmbH&Co. KG , Köln Automatic

 10000 07/2020	 10000 07/2020	 10000 07/2020	 10000 07/2020	 3200 ✓	 0 12/2019	 50000 07/2020	 10000 07/2020	 0 08/2019
---	---	---	---	--	---	---	--	---

— 27/02/2019 Repair 153117 Km 26636 Procar Automobile GmbH & Co. KG , Köln Job Job Job Job

— Job

Description:

Considered as a repeat visit No

Customer's own words Soll bereits mitgemacht werden.

— Job

Description:

Considered as a repeat visit No

Customer's own words entladen nach einiger Zeit

— Job

Description:

Considered as a repeat visit No

Customer's own words FZ ruckelt.

— Job

Description:

Considered as a repeat visit No

Customer's own words

Package I 0000105

— 27/02/2019 Warranty 153117 Km 26636 Job: Exhaust gas recirculation valve (EGR)

— Job: Exhaust gas recirculation valve (EGR)

Description: Exhaust gas recirculation valve (EGR)

Considered as a repeat visit No

Customer's own words

Exhaust gas recirculation valve (EGR)
Defect I 11 71 01 83 00

Hose clamp
Part I 07 12 9 952 104

2

EGR-valve
Part I 11 71 8 513 132

1

Gasket Steel
Part I 11 71 8 579 364

1


Oval head screw
Part I 35 21 7 685 343

2


— 20/09/2018 Key 137320 Km Key 0

— 20/09/2018 Key 137320 Km Key 0

— 07/09/2018 Key 135742 Km 26636 Key 0



— 07/09/2018 Key 135712 Km Key 0




— 26/07/2018 Service 132112 Km 26636 Procar Automobile, Köln Manual




— 20/07/2018 Key 132097 Km 26636 Key 0

— 08/02/2018 Key 110921 Km 26636 Key 0



— 07/12/2017 Service 104617 Km 26636 Procar Automobile, Köln Automatic



—	07/12/2017	Repair	104617 Km	26636 Procar Automobile GmbH & Co. KG , Köln	Job: CBS: Standardumfang Job: CBS: Mikrofilter (ggf. weiter Zusatzarbe Job: CBS: Fahrzeug-Check Job: CBS: Luftfiltereinsatz Job: CBS: Kraftstofffilter Job: CBS: Bremsflüssigkeit Job: CBS: Motoröl Job Job Job
---	------------	--------	-----------	---	---

— Job: CBS: Standardumfang

Description:

Considered as a repeat visit No

Customer's own words

CBS: Standardumfang
Package I 0000105

Service - standard scope	2
Flat rate unit I 00 00 105	

— Job: CBS: Mikrofilter (ggf. weiter Zusatzarbe

Description:

Considered as a repeat visit No

Customer's own words

CBS: Mikrofilter (ggf. weiter Zusatzarbe
Package I 0000616

Microfilter service	3
Flat rate unit I 00 00 616	

Set, microfilter/carbon canister	1
Part I 64119272642	

Pollen-filter housing cleaner	1
Part I 83192180509	

— Job: CBS: Fahrzeug-Check

Description:

Considered as a repeat visit No

Customer's own words

CBS: Fahrzeug-Check
Package I 0000624

Service, vehicle check	7
Flat rate unit I 00 00 624	

SCHEIBENKLAR	Local	2
Part I F/99999999208		

— Job: CBS: Luftfiltereinsatz

Description:

Considered as a repeat visit No

Customer's own words

CBS: Luftfiltereinsatz
Package I 0000602

Service - air filter element	1
------------------------------	---

Flat rate unit | 00 00 602

Air filter element

Part | 13718570043

1

— Job: CBS: Kraftstofffilter

Description:

Considered as a repeat visit No

Customer's own words

CBS: Kraftstofffilter

Package | 0000604

Service fuel filter

Flat rate unit | 00 00 604

5

Fuel filter cartridge

Part | 13327811227

1

Hose clamp

Part | 07129952104

1

— Job: CBS: Bremsflüssigkeit

Description:

Considered as a repeat visit No

Customer's own words

CBS: Bremsflüssigkeit

Package | 0000618

Brake fluid service

Flat rate unit | 00 00 618

4

Brake fluid DOT4 LV, low viscosity

Part | 83132405977

1

— Job: CBS: Motoröl

Description:

Considered as a repeat visit No

Customer's own words

CBS: Motoröl

Package | 0000610

Engine oil service

Flat rate unit | 00 00 610

3

!!! unknown BMW-Id 9999999934 MOTORÖL LONGLIFE04 !!! Local

Part | 9999999934

5

Set oil-filter element

Part | 11428575211

1

Gasket ring

Part | 07119963151

1

— Job

Description:

Considered as a repeat visit No

Customer's own words

Check and replace air conditioning capacitor

Flat rate unit | 00 64 293

17 FRU

Condenser, air conditioning

1

Part I 64 50 9 391 489

Gasket ring

1

Part I 64 50 8 374 959

Gasket ring

1

Part I 64 50 8 375 741

Hex Bolt

2

Part I 07 14 7 029 829

Lubricant refrigeration compressor

0.1

Part I 81 22 9 407 724

Cooling agent

17

Part I 83 19 0 143 177

— Job

Description:**Considered as a repeat visit** No**Customer's own words**

!!! unknown BMW-Id ESTIMATE Bitte ers. !!!

Local

0 FRU

Flat rate unit I -

battery

2

Part I 61 31 9 217 643

— Job

Description:**Considered as a repeat visit** No**Customer's own words**

— 07/12/2017 Warranty

104622 Km

26636

Job: F0x F1x N47 B47 Replace air conditioning condenser

— Job: F0x F1x N47 B47 Replace air conditioning condenser

Description: F0x F1x N47 B47 Replace air conditioning condenser**Considered as a repeat visit** No**Customer's own words**

Check and replace air conditioning capacitor

17 FRU

Flat rate unit I 00 64 293

F0x F1x N47 B47 Replace air conditioning condenser

Defect I 00 64 93 01 00

Condenser, air conditioning

1

Part I 64 50 9 391 489

Gasket ring

1

Part I 64 50 8 374 959

Gasket ring

1

Part I 64 50 8 375 741

Hex Bolt

2

Part I 07 14 7 029 829

— 20/01/2017 Warranty

74740 Km

26636

Job

— Job

Description:

Considered as a repeat visit No

Customer's own words

Replacing the exhaust-gas recirculation cooler 16 FRU
Flat rate unit I 00 64 199

Defect I 00 11 36 04 00

exhaust cooler 1
Part I 11 71 8 596 444








Set of small parts 1
Part I 11 71 8 597 652

— 19/01/2017 Key

74737 Km

26636

Key 0











— 19/01/2017 Service

74737 Km

26636 Procar
Automobile,
Köln

Automatic



— 19/01/2017 Repair

74740 Km

26636 Procar
Automobile
GmbH & Co.
KG, Köln

Job: SB am Fzg. mit I-Pad und
Kunde
Job: CBS: Standardumfang
Job: CBS: Motoröl
Job: CBS: Mikrofilter (ggf. weiter
Zusatzarbe
Job: CBS: Bremse vorn
Job
Job: Procar Service-Check
Job: kostenlose Fahrzeugwäsche
Job

— Job: SB am Fzg. mit I-Pad und Kunde

Description:

Considered as a repeat visit No

Customer's own words

SB am Fzg. mit I-Pad und Kunde
Package I MM019999020

SB am Fzg. mit I-Pad und Kunde
Flat rate unit I -

Local

0

— Job: CBS: Standardumfang

Description:

Considered as a repeat visit No

Customer's own words

CBS: Standardumfang
Package I 0000105

Service - standard scope
Flat rate unit I 00 00 105

2

— Job: CBS: Motoröl

Description:**Considered as a repeat visit** No**Customer's own words**

CBS: Motoröl

Package I 0000610

Engine oil service	3
Flat rate unit I 00 00 610	

!!! unknown BMW-Id 9999999934 MOTORÖL LONGLIFE04 !!! Local	5
Part I 9999999934	

Set oil-filter element	1
Part I 11428575211	

Gasket ring	1
Part I 07119963151	

— Job: CBS: Mikrofilter (ggf. weiter Zusatzarbe

Description:**Considered as a repeat visit** No**Customer's own words**

CBS: Mikrofilter (ggf. weiter Zusatzarbe

Package I 0000616

Microfilter service	3
Flat rate unit I 00 00 616	

Set, microfilter/carbon canister	1
Part I 64119272642	

Pollen-filter housing cleaner	1
Part I 83192180509	

— Job: CBS: Bremse vorn

Description:**Considered as a repeat visit** No**Customer's own words**

CBS: Bremse vorn

Package I 0000612

Service, front brakes	7
Flat rate unit I 00 00 612	

Removing and installing or replacing both front brake discs	3
Flat rate unit I 34 11 613	

KERAMIKPASTE SPRAY Local	1
Part I F/99965105100	

!!! unknown BMW-Id 99990000005 BREMSSENREINIGER !!! Local	1
Part I 99990000005	

Repair kit, brake pads asbestos-free	1
Part I 34116858047	

Brake pad wear sensor, front left	1
Part I 34356791958	

Hex Bolt	4
Part I 34116772117	

Brake disc, lightweight, ventilated	2
-------------------------------------	---

Part I 34116794429

Inner hex bolt

2

Part I 34211161806

— Job

Description:**Considered as a repeat visit** No**Customer's own words**Replacing the exhaust-gas recirculation cooler
Flat rate unit I 00 64 199

16 FRU

exhaust cooler
Part I 11 71 8 596 444

1

Set of small parts
Part I 11 71 8 597 652

1

— Job: Procar Service-Check

Description:**Considered as a repeat visit** No**Customer's own words**Procar Service-Check
Package I MM019999290Procar Service-Check
Flat rate unit I -

Local

0

— Job: kostenlose Fahrzeugwäsche

Description:**Considered as a repeat visit** No**Customer's own words**kostenlose Fahrzeugwäsche
Package I MM020011329Vehicle surface wash and interior vehicle cleaning
Flat rate unit I 00 11 329

0

— Job

Description:**Considered as a repeat visit** No**Customer's own words**Costs for replacement vehicle
Flat rate unit I 00 00 160

0 FRU

— 22/04/2016 Warranty 52665 Km 26636 Job: Rear door outside door handle (including support/TAGE)

— Job: Rear door outside door handle (including support/TAGE)

Description: Rear door outside door handle (including support/TAGE)**Considered as a repeat visit** No**Customer's own words**Performing vehicle test
Flat rate unit I 00 00 006

4 FRU

Vehicle diagnosis - carrying out the ABL 6 FRU
Flat rate unit I 61 00 006

Supporting the voltage of the vehicle electrical system/recharging the vehicle electrical system battery 1 FRU
Flat rate unit I 61 21 528

Removing and installing/replacing outside door handle, rear left or right 1 FRU
Flat rate unit I 51 22 670

Rear door outside door handle (including support/TAGE)
Defect I 51 22 05 83 00

grab handle, paint finish, left 1
Part I 51 21 7 231 933

— 21/04/2016 Key 52655 Km 26636 Key 0

— 03/02/2016 Repair 45870 Km 26636 Procar Automobile GmbH & Co. KG, Köln Job Job Job

— Job

Description:

Considered as a repeat visit No

Customer's own words

Procar Service-Check Local 2 FRU
Flat rate unit I 99 99 290

SCHEIBENKLAR Local 2
Part I 99 99 9 999 208

— Job

Description:

Considered as a repeat visit No

Customer's own words

Service - standard scope 2 FRU
Flat rate unit I 00 00 105

Engine oil service 3 FRU
Flat rate unit I 00 00 610

Microfilter service 3 FRU
Flat rate unit I 00 00 616

Service - air filter element 1 FRU
Flat rate unit I 00 00 602

Service fuel filter 5 FRU
Flat rate unit I 00 00 604

Service, vehicle check 7 FRU
Flat rate unit I 00 00 624

MOTORÖL LONGLIFE04 Local 5
Part I 99 99 9 999 934

Set oil-filter element 1
Part I 11 42 8 575 211

Gasket ring 1
Part I 07 11 9 963 151

Set, microfilter/carbon canister 1

Part I 64 11 9 272 642

Fuel filter cartridge Part I 13 32 7 811 227	1
---	---

Hose clamp Part I 07 12 9 952 104	1
--------------------------------------	---

Air filter element Part I 13 71 8 570 043	1
--	---

— Job

Description:**Considered as a repeat visit** No**Customer's own words**

Bremse vorne messen und CBS Korrigieren Flat rate unit I 99 99 999	Local	1 FRU
---	-------	-------

—	03/02/2016	Warranty	45897 Km	26636	Job: EGR cooler (incl. bypass flap) / exhaust cooler
---	------------	----------	----------	-------	--

— Job: EGR cooler (incl. bypass flap) / exhaust cooler

Description: EGR cooler (incl. bypass flap) / exhaust cooler**Considered as a repeat visit** No**Customer's own words**

Performing vehicle test Flat rate unit I 00 00 556	3 FRU
---	-------

Vehicle diagnosis - carrying out the ABL Flat rate unit I 61 00 006	6 FRU
--	-------

Supporting the voltage of the vehicle electrical system/recharging the vehicle electrical system battery Flat rate unit I 61 21 528	1 FRU
--	-------

Check the cooling system for watertightness with the special tool Flat rate unit I 17 00 509	2 FRU
---	-------

Removing and installing or replacing EGR cooler Flat rate unit I 11 71 600	15 FRU
---	--------

TeileClearing, lump-sum fee Flat rate unit I 00 58 677	1 FRU
---	-------

EGR cooler (incl. bypass flap) / exhaust cooler Defect I 11 71 06 48 00	
--	--

Exhaust gas radiator high temperature Part I 11 71 8 513 691	1
---	---

Gasket Steel Part I 11 61 8 571 005	1
--	---

Torx-bolt with washer Part I 07 12 9 905 423	3
---	---

Anti-freeze Part I 83 19 2 211 358	3
---------------------------------------	---

Cable tie Part I 61 13 1 367 599	4
-------------------------------------	---

—	03/02/2016	Warranty	45897 Km	26636	Job: EGR cooler (incl. bypass flap) / exhaust cooler
---	------------	----------	----------	-------	--

— Job: EGR cooler (incl. bypass flap) / exhaust cooler

Description: EGR cooler (incl. bypass flap) / exhaust cooler

Considered as a repeat visit No

Customer's own words

EGR cooler (incl. bypass flap) / exhaust cooler
Defect | 11 71 06 48 00

—	02/02/2016	Key	45870 Km		26636		Key 0	
								
1700	1700	1700	1700	6000	0	25000	1700	0
05/2017	484	484	484		07/2017		05/2017	08/2017
—	10/08/2015	Key	29687 Km		26636		Key 0	
								
19000	19000	19000	19000	18000	0	35000	19000	0
05/2017	660	660	660		07/2017		05/2017	08/2017
—	10/08/2015	Repair	29687 Km		26636 Procar Automobile GmbH & Co. KG , Köln		Job	

— Job

Description:

Considered as a repeat visit No

Customer's own words

Haftpflichtschaden GVV Flat rate unit 99 99 999	Local	1 FRU
Schaden-Nr.: 2015.61.7.51960/SMZ Flat rate unit 99 99 999	Local	1 FRU
Fehlerspeicher nach Reparatur ausgelesen Flat rate unit 99 99 924	Local	4 FRU
Seitenwand vo.li. lackieren 14 AW Flat rate unit 99 99 999	Local	1 FRU
Türe vo.li. lackieren 34 AW Flat rate unit 99 99 999	Local	1 FRU
Türe hi.li. lackieren 8 AW Flat rate unit 99 99 999	Local	1 FRU
Zeitzuschlag für eine Hauptarbeit 22 AW Flat rate unit 99 99 999	Local	1 FRU
Fahrzeugverbringung zwecks Lackierung Flat rate unit 99 99 999	Local	1 FRU
Job time without allowance for / body equipment Flat rate unit 51 99 000		2 FRU
Removing and installing or replacing trim strip on front left or right side panel Flat rate unit 51 13 591		1 FRU
Removing and installing left or right front door trim panel		6 FRU

Removing and installing/replacing the sound insulation at the front left or right door	3 FRU
Flat rate unit I 51 48 560	

Job time without allowance for / body equipment	4 FRU
Flat rate unit I 51 99 000	

Channel cover,exterior,door, front left	1
Part I 51 33 7 182 275	

Clamp	1
Part I 07 14 7 229 342	

Sound insulating door front left	1
Part I 51 48 7 366 705	

—	18/05/2015	Repair	18322 Km	04709 Kaltenbach Automobile GmbH & Co. KG , Overath	Job Job Job Job Job
---	------------	--------	----------	---	---------------------------------

Customer's own words

Auslieferungsdurchsicht - GW -
Flat rate unit I 01 00 004

Local

5 FRU

— Job

Description:

Considered as a repeat visit No

Customer's own words

Service - standard scope Flat rate unit I 00 00 105	2 FRU
--	-------

— Job

Description:

Considered as a repeat visit No

Customer's own words

Engine oil service Flat rate unit I 00 00 610	3 FRU
--	-------

BMW Engine Oil LL04 5W30 Part I 83 21 2 405 948	5
--	---

Set oil-filter element Part I 11 42 8 575 211	1
--	---

— Job

Description:

Considered as a repeat visit No

Customer's own words

Microfilter service Flat rate unit I 00 00 616	3 FRU
---	-------

Set, microfilter/carbon canister Part I 64 11 9 272 642	1
--	---

— Job

Description:

Considered as a repeat visit No

Customer's own words

UMWELTPLAKETTE Part I FT0100010	Local	1
------------------------------------	-------	---

Glass cleaner without antifreeze Part I 83 12 0 029 485	1
--	---