

Thank you for ordering from us!
www.checkvin.eu

Vehicle

BMW 420i A, 135KW

WBA4D31020G767035



Development code
Colour
Actual integration level
Start of warranty

F36
alpinweiss 3
F020-20-07-540
15 October 2016

Technical campaigns

There are no Campaigns for this vehicle.

Warranty extension/VIN-based goodwill

There are no Campaigns for this vehicle.

Special information

There are no Campaigns for this vehicle.

Restrictions on the warranty

There are no restrictions on the warranty.

△ Market-specific restrictions are not currently displayed. Please check this in WDF/WXE via S-Gate.

Live Diagnosis

 There are no service solutions for Live Diagnosis.

Service contracts

No BSI contracts

Information on faults workshop/Service Consultation

There is no information on faults.

Navigation map

Note: The installed map cannot be clearly identified. Presumably one of the following maps is present in the vehicle.

Installed map	Enabling code (subscription)	Latest navigation map included in subscription	Latest navigation map subject to charge
Road Map EUROPE EVO 2018-4 (As of: 21 Sept 2020)	Enabling code valid for navigation maps with release date up to 31 Dec 2099 (SWID: 01200FFF).	Road Map EUROPE EVO 2025-1	-
Road Map EUROPE EVO 2018-4 (As of: 21 Sept 2020)	-	-	-

Vehicle details

Vehicle type	Passenger car
Brand	BMW
Model	420i A
Body	COUPE
Vehicle identification number (last 7 digits)	G767035
Vehicle identification number (17 digits)	WBA4D31020G767035
Development code	F36
Steering	LL
Engine	B48M
Engine number	17659728
Exhaust re-treatment	EURO6, W, PI/CI, M, N1 I
Transmission	AUT
Transmission number	0252160WDP
Head unit serial number	HB2240G7981976
Drive	HECK
Integration level, works	F020-16-07-505
Production date	30 Aug 2016
Production plant	Dingolfing
Delivery date	1 Sept 2016
Delivering retailer	Dusseldorf Zwolle B.V., Zwolle, NL
National-market version	EUR
Paint code	300
Upholstery code	LCSW
Model code	4D41
Basic type	4D31
Lead type	4D41

Optional equipment

Optional equipment ex works:

Retrofitted optional equipment:

01CA Selection of COP-relevant vehicles
01CB CO2 equipment
021C BMW LA wheel, M double spoke bicolor
0230 Extra package, EU-specific
0258 Tyres with runflat properties
02PA Locking wheel bolt
02TB Sport automatic gearbox
02VB Tyre pressure display
02VF Adaptive M chassis
02VL Variable sport steering
0302 Alarm system
0320 Deleted, model lettering
0322 Comfort access
0337 M Sports package
03AC Trailer coupling
03AG Reversing camera
0420 Sun protection glazing
0423 Floor mats velours
0430 Interior/outside mirror with auto dip
0431 Interior mirror with automatic-dip
0465 Through-loading system
0481 Sports seat
0493 Storage compartment package
0494 Seat heating driver/passenger
04AE Armrest front, retractable
04FT Alum. brushed lengthw. acc. black hi-gls
04NE Blow-by heater
0502 Headlight cleaning system
0508 Park Distance Control (PDC)
0521 Rain sensor
0522 Xenon Light
0534 Automatic air conditioning
0548 Kilometre speedo
0563 Light package
0575 Additional 12V sockets
05AC High-beam assistant
05AG Lane change warning
05AL Active Protection
05AS Driving Assistant
05DA Passenger airbag deactivation
05DF Active cruise control+stop&go function
05DL Surround View
05DP Park Assist
0609 Navigation system Professional
0610 Head-up display
0688 Harman/Kardon surround sound system
0698 Area-Code 2 for DVD
06AC Intelligent emergency call
06AE Teleservices
06AK Connected Drive Services
06AM Real-Time Traffic Information
06AP Remote Services
06NW Telephony with wireless charging
06WA Instrument panel with extended scope
06WD WLAN Hotspot
0710 M Leather steering wheel
0715 M Aerodynamics package
0760 High gloss shadow line
0775 Headlining anthracite
07LF Modell M Sport
0845 Acoustic fasten seat belt reminder
0868 Language version Dutch
0886 On-board literature, Dutch
08KA Oil service interval 24 mths / 30,000 km
08R9 Refrigerant R1234yf
08S2 Coding, alarm signal
08S3 Automatic locking during starting
08TH Road sign detection
09AA Outer skin protection
A090 90 Ah AGM battery
LEDE Leather equipment


This vehicle has no retrofits.

Vehicle histories

	Date	Type	Vehicle mileage	Retailer	Overview
—	03/03/2025	Key	175264 Km	03625	Key 0
					
	14000	14000	14000	14000	32000
	10/2025	10/2025	10/2025	10/2025	01/2026
—	03/03/2025	Warranty	175264 Km	03625	Job: Fx Replace driver's airbag, part III (SDI)
—	Job: Fx Replace driver's airbag, part III (SDI)				
	Description: Fx Replace driver's airbag, part III (SDI)				
	Considered as a repeat visit No				
	Customer's own words				
	Replace driver's airbag				3 FRU
	Flat rate unit I 00 76 920				
	Fx Replace driver's airbag, part III (SDI)				
	Defect I 00 32 62 03 00				
	Airbag module, driver's side				1
	Part I 32305A66F66				
—	30/09/2020	Key	116082 Km	03625	Key 0
					
	16000	16000	16000	16000	70000
	01/2022	456	456	456	10/2021
—	21/09/2020	Service	116076 Km	24212 Dusseldorp Zwolle (MINI) , Zwolle	Automatic
					
	17000	17000	17000	17000	13000
	12/2021	12/2021	12/2021	12/2021	09/2021
					✓
—	18/09/2020	Key	116076 Km	24212	Key 0
					
	17000	17000	17000	17000	13000
	01/2022	463	463	463	10/2021
—	06/07/2020	Warranty	112832 Km	03625	Job: Steering gear
—	Job: Steering gear				
	Description: Steering gear				
	Considered as a repeat visit No				
	Customer's own words				

Performing vehicle test Flat rate unit 00 00 006	4 FRU
Replacing electromechanical power steering (EPS) Flat rate unit 32 13 572	0 FRU
Start-up of electromechanical steering gear (EPS) / initialisation Flat rate unit 32 13 905	0 FRU
Kinematics Diagnosis System wheel alignment with ride height measurement without loading the vehicle Flat rate unit 32 00 595	0 FRU
Adjusting rear axle and front axle Flat rate unit 32 00 630	0 FRU
Supporting the voltage of the vehicle electrical system/recharging the vehicle electrical system battery Flat rate unit 61 21 528	1 FRU
Steering gear Defect 32 13 02 15 00	
RP Steering gear electric Part 32 10 6 889 106	1
Combination nut Part 33 30 6 787 062	2

—	26/06/2020	Key	112832 Km	03625	Key 0			
	 20000 01/2022	 20000 545	 20000 545	 20000 545	 14000	 10/2021	 21000	 20000 01/2022
—	03/03/2020	Key	107413 Km	03625	Key 0			
	 26000 01/2022	 26000 659	 26000 659	 26000 659	 16000	 10/2021	 21000	 26000 01/2022
—	07/01/2020	Key	102463 Km	03625	Key 0			
	 -1000 01/2021			 -1000 354	 6000	 10/2021	 8000	 32000 01/2023
—	07/01/2020	Service	102463 Km	03625 Dusseldorp Zwolle bv , Zwolle	Automatic			
	 -1000 12/2020 ✓			 -1000 12/2020 ✓	 6000 09/2021		 8000	 32000 12/2022
—	12/11/2019	Key	97163 Km	03625	Key 0			





— 08/10/2019 Key

92560 Km

03625

Key 0





— 08/10/2019 Service

92560 Km

03625
Dusseldorp
Zwolle bv ,
Zwolle

Automatic





— 28/05/2019 Key

79701 Km

03625

Key 0




— 20/04/2019 Key

76601 Km

03625

Key 0



— 06/03/2019 Warranty

73010 Km

03625

Job: Speakers

— Job: Speakers

Description: Speakers

Considered as a repeat visit No

Customer's own words

Performing vehicle test
Flat rate unit I 00 00 006

4 FRU



Speakers
Defect I 65 12 00 50 00MID-range loudspeaker
Part I 65 13 9 364 956

1

— 05/03/2019 Key

73010 Km

Key 0





— 29/01/2019 Key

69646 Km

03625

Key 0



— 29/01/2019 Warranty

68584 Km

03625

Job: Speakers

— Job: Speakers

Description: Speakers

Considered as a repeat visit No

Customer's own words

Speakers
Defect I 65 12 00 12 00

Tweeter
Part I 65 13 9 226 357

1



MID-range loudspeaker
Part I 65 13 9 364 956

1

— 15/01/2019 Key

68584 Km

Key 0





— 15/01/2019 Service

68584 Km

03625
Dusseldorp
Zwolle bv ,
Zwolle



Automatic



— 17/11/2018 Key

63867 Km

Key 0



— 19/09/2018 Warranty

58959 Km

03625

Job: Switch/button, multifunction steering wheel (MFL)

— Job: Switch/button, multifunction steering wheel (MFL)

Description: Switch/button, multifunction steering wheel (MFL)

Considered as a repeat visit No

Customer's own words

Removing and installing or replacing both switches, multifunction steering wheel
Flat rate unit I 61 31 721

3 FRU

Performing vehicle test
Flat rate unit I 00 00 006

4 FRU

Supporting the voltage of the vehicle electrical system/recharging the vehicle electrical system battery
Flat rate unit I 61 21 528

1 FRU

Performing vehicle test
Flat rate unit I 00 00 556

2 FRU

Switch/button, multifunction steering wheel (MFL)
Defect I 61 30 24 78 00

Switch, multifct.steering wheel, M-Sport
Part I 61 31 7 849 412

1

— 19/09/2018 Warranty 58959 Km 03625 Job: Switch/button, multifunction steering wheel (MFL)

— Job: Switch/button, multifunction steering wheel (MFL)

Description: Switch/button, multifunction steering wheel (MFL)

Considered as a repeat visit No

Customer's own words

Switch/button, multifunction steering wheel (MFL)
Defect I 61 30 24 78 00

Switch, multifct.steering wheel, M-Sport
Part I 61 31 7 849 412

1

— 19/09/2018 Warranty 58959 Km 03625 Job: Switch/button, multifunction steering wheel (MFL)

— Job: Switch/button, multifunction steering wheel (MFL)



Description: Switch/button, multifunction steering wheel (MFL)

Considered as a repeat visit No



Customer's own words

Switch/button, multifunction steering wheel (MFL)
Defect I 61 30 24 78 00



— 18/09/2018 Key 58959 Km Key 0




— 27/03/2018 Key 42614 Km 03625 Key 0




— 12/12/2017 Key 33970 Km 03625 Key 0




— 12/12/2017 Service 33970 Km 03625 Automatic
Dusseldorf

Zwolle bv ,
Zwolle


— 22/08/2017 Key




24865 Km 03625 Key 0




— 13/06/2017 Key




17679 Km 03625 Key 0




— 18/03/2017 Key



12230 Km 03625 Key 0



— 12/11/2016 Key



2331 Km 03625 Key 0

