

Thank you for ordering from us!

www.checkvin.eu

Vehicle

BMW 420D A, 140KW

WBA4E91060G592921



Development code
Colour
Actual integration level
Start of warranty

F36
frozen-bronze metallic
F020-22-11-510
18 March 2016

Technical campaigns

There are no Campaigns for this vehicle.

Warranty extension/VIN-based goodwill

Status	Campaign number	Description
Open	1SACC011056	Exhaust gas recirculation cooler Bx7 Local campaign number: -

Special information

There are no Campaigns for this vehicle.

Restrictions on the warranty

There are no restrictions on the warranty.

⚠ Market-specific restrictions are not currently displayed. Please check this in WDF/WXE via S-Gate.

Live Diagnosis

 There are no service solutions for Live Diagnosis.

Service contracts

No BSI contracts

Information on faults workshop/Service Consultation

There is no information on faults.

Navigation map

Note: The installed map cannot be clearly identified. Presumably one of the following maps is present in the vehicle.

Installed map	Enabling code (subscription)	Latest navigation map included in subscription	Latest navigation map subject to charge
Road Map EUROPE EVO 2022-2 (As of: 2 Jan 2025)	-	-	-
Road Map EUROPE EVO 2022-2 (As of: 2 Jan 2025)	Enabling code valid for navigation maps with release date up to 31 Dec 2099 (SWID: 00F10FFF).	Road Map EUROPE EVO 2025-1	-

Vehicle details

Vehicle type	Passenger car
Brand	BMW
Model	420D A
Body	COUPE
Vehicle identification number (last 7 digits)	G592921
Vehicle identification number (17 digits)	WBA4E91060G592921
Development code	F36
Steering	LL
Engine	B47O
Engine number	51679536
Exhaust re-treatment	EURO6, W, PI/CI, M, N1 I
Transmission	AUT
Transmission number	0324516ZRI
Head unit serial number	HB2140G7752712
Drive	HECK
Integration level, works	F020-15-11-505
Production date	18 Feb 2016
Production plant	Dingolfing
Delivery date	24 Feb 2016
Delivering retailer	NANNI NEMBER SRL, BRESCIA, IT
National-market version	EUR
Paint code	X11
Upholstery code	LCSW
Model code	4E01
Basic type	4E91
Lead type	4E01

Optional equipment

Optional equipment ex works:

01CA Selection of COP-relevant vehicles
01CB CO2 equipment
021C BMW LA wheel, M double spoke bicolor
0230 Extra package, EU-speciifc
0258 Tyres with runflat properties
02NH M Sport brake
02PA Locking wheel bolt
02TB Sport automatic gearbox
02VB Tyre pressure display
02VL Variable sport steering
0316 automatic trunk lid mechanism
0320 Deleted, model lettering
0337 M Sports package
03AG Reversing camera
0420 Sun protection glazing
0423 Floor mats velours
0430 Interior/outside mirror with auto dip
0431 Interior mirror with automatic-dip
0481 Sports seat
0488 Lumbar support, driver and passenger
0493 Storage compartment package
0494 Seat heating driver/passenger
04AE Armrest front, retractable
04WG Alum. Hexagon accent black high-gloss
0502 Headlight cleaning system
0508 Park Distance Control (PDC)
0521 Rain sensor
0522 Xenon Light
0534 Automatic air conditioning
0544 Cruise control with braking function
0548 Kilometre speedo
0563 Light package
0575 Additional 12V sockets
0609 Navigation system Professional
0676 HiFi speaker system
0698 Area-Code 2 for DVD
06AC Intelligent emergency call
06AE Teleservices
06NH Hands-free system with USB interface
06UH Traffic Information
06WA Instrument panel with extended scope
0704 M Sports suspension
0710 M Leather steering wheel
0715 M Aerodynamics package
0760 High gloss shadow line
0775 Headlining anthracite
07LF Modell M Sport
0845 Acoustic fasten seat belt reminder
0855 Language version, Italian
0884 On-board literature Italian
08KA Oil service interval 24 mths / 30,000 km
0962 Number-plate carrier, front, deletion
A090 90 Ah AGM battery
LEDE Leather equipment

Retrofitted optional equipment:

This vehicle has no retrofits.

Vehicle histories

Date		Type	Vehicle mileage			Retailer		Overview
— 02/01/2025		Key	200160 Km			34971		Key 0
								
16000		16000		40000	-32 4.4 %	49000	47000	
05/2026		05/2026				05/2028		05/2026

—	02/01/2025	Service	200160 Km	34971	Automatic			
				BONERA SPA DINAMICA , BRESCIA				
								
16000	16000	16000	40000	49000	47000			
05/2026	05/2026	05/2026		12/2024			05/2028	05/2026
			✓	✓	✓			
—	02/01/2025	Warranty	200160 Km	34971	Job: Fx Replace driver's airbag, part III (SDI)			

— Job: Fx Replace driver's airbag, part III (SDI)

Description: Fx Replace driver's airbag, part III (SDI)

Considered as a repeat visit No

Customer's own words

Replace driver's airbag	3 FRU
Flat rate unit I 00 76 920	
Fx Replace driver's airbag, part III (SDI)	
Defect I 00 32 62 03 00	
Airbag module, driver's side	1
Part I 32305A66F66	

—	20/05/2024	Warranty	185671 Km	34971	Job: F1x F2x F3x G0x G1x G3x B47O B47K B47U B47T Replacing EGR cooler (high-temperature)
---	------------	----------	-----------	-------	--

— Job: F1x F2x F3x G0x G1x G3x B47O B47K B47U B47T Replacing EGR cooler (high-temperature)

Description: F1x F2x F3x G0x G1x G3x B47O B47K B47U B47T Replacing EGR cooler (high-temperature)

Considered as a repeat visit No

Customer's own words

Replace exhaust gas recirculation cooler, including exhaust gas recirculation valve	23 FRU
Flat rate unit I 00 74 649	
Additional work: run function test for pressure sensor system	3 FRU
Flat rate unit I 00 74 650	
Additional work: enter component identification of new exhaust gas recirculation cooler in diagnostic system	1 FRU
Flat rate unit I 00 74 651	
Additional work cleaning the exhaust gas recirculation pipe	6 FRU
Flat rate unit I 00 74 652	
F1x F2x F3x G0x G1x G3x B47O B47K B47U B47T Replacing EGR cooler (high-temperature)	
Defect I 00 11 15 07 00	
Exhaust gas radiator high temperature	1
Part I 11 71 7 822 347	
EGR small parts set	1
Part I 11 71 8 490 640	
Pipe union	2
Part I 11 71 7 799 853	
Holder	1
Part I 61 13 1 369 832	

Connection piece Part I 11 65 7 803 012	1
O-ring Part I 11 61 8 512 681	1
Acoustic cover front Part I 11 14 8 490 577	1

16/05/2024	Key	185671 Km	34971	Key 0
 2800 06/2025  2800 06/2025  2800 06/2025  2800 06/2025  70000 06/2025  12/2024  80000  2800 06/2025  -15 2.1 %				
16/05/2024	Service	185671 Km	34971 BONERA SPA DINAMICA , BRESCIA	Automatic
 2800 06/2025 ✓  2800 06/2025 ✓  2800 06/2025 ✓  2800 06/2025 ✓  70000  12/2024  80000  2800 06/2025 ✓  05/2024 ✓				
19/06/2023	Key	157497 Km		Key 0
 -2700 8.7 % 05/2024  2800  -2700 05/2024  2800  90000  12/2024  90000  29000 05/2026  05/2024				
19/06/2023	Service	157497 Km	34971 BONERA SPA DINAMICA , BRESCIA	Automatic
 -2700 05/2024 ✓  2800  -2700 05/2024 ✓  2800  90000  12/2024  90000  29000 05/2026  05/2024				
19/06/2023	Warranty	157497 Km	34971	Job: Engine oil service
Job: Engine oil service				
Description: Engine oil service				
Considered as a repeat visit No				
Customer's own words				
BMW engine oil service not including additional service 4 FRU				
Flat rate unit I 00 00 252				
Engine oil service				
Defect I 87 00 02 00 00				
Set oil-filter element 1				
Part I 11 42 8 575 211				
19/06/2023	Warranty	157497 Km	34971	Job: Fx Gx B37 B47 B57 N47 N57
Check coolant level (EGR)				

— Job: Fx Gx B37 B47 B57 N47 N57 Check coolant level (EGR)

Description: Fx Gx B37 B47 B57 N47 N57 Check coolant level (EGR)

Considered as a repeat visit No

Customer's own words

Flat rate unit | 00 73 829

2 FRU


Fx Gx B37 B47 B57 N47 N57 Check coolant level (EGR)

Defect | 11 71 90 08 00

— 05/12/2022 Key

138888 Km

Key 0




— 05/12/2022 Service

138888 Km

34971
BONERA SPA
DINAMICA ,
BRESCIA

Automatic



— 05/12/2022 Warranty

138888 Km

34971

Job: G0x G3x B47O Programming control units (DDE)

— Job: G0x G3x B47O Programming control units (DDE)

Description: G0x G3x B47O Programming control units (DDE)

Considered as a repeat visit No

Customer's own words

Program control units

8 FRU

Flat rate unit | 00 71 940

G0x G3x B47O Programming control units (DDE)

Defect | 00 13 51 03 00

— 05/12/2022 Warranty

138888 Km

34971

Job

— Job

Description:

Considered as a repeat visit No

Customer's own words

Defect | 99 99 02 01 EM

— 01/06/2022 Warranty

123804 Km

34971

Job: Engine oil service

— Job: Engine oil service

Description: Engine oil service

Considered as a repeat visit No

Customer's own words

BMW engine oil service not including additional service
Flat rate unit I 00 00 252

4 FRU

Engine oil service
Defect I 87 00 02 00 00

Set oil-filter element
Part I 11 42 8 575 211

1

—	31/05/2022	Key	123804 Km	34971	Key 0			
	 260 02/2023	 260 240	 260 240	 260 240	 42000 02/2023	 50000 02/2023	 260 02/2023	 -90 12.3 %
—	31/05/2022	Service	123804 Km	34971	Automatic			
				BONERA SPA DINAMICA , BRESCIA				
	 260 01/2023 ✓	 260 01/2023 ✓	 260 01/2023 ✓	 260 01/2023 ✓	 42000 01/2023 ✓	 50000 01/2023 ✓	 260 01/2023 ✓	 03/2022 ✓
—	29/04/2022	Key	121275 Km	34971	Remote KeyRead			
	 2800 02/2023	 2800 272	 2800 272	 2800 272	 45000 02/2023	 60000 02/2023	 2800 02/2023	 -58 7.9 %
—	30/11/2021	Key	111183 Km		Key 0			
	 13000 02/2023	 13000 421	 13000 421	 13000 421	 60000 02/2023	 70000 02/2023	 13000 02/2023	 03/2022
—	24/02/2021	Key	93101 Km		Key 0			
	 -1700 -23 3.1 %		 -1700 -23 3.1 %		 70000 -23 3.1 %	 70000	 30000 02/2023	 03/2022
—	24/02/2021	Service	93101 Km	06098 NANNI MEMBER SRL , BRESCIA	Automatic			
	 -1700 02/2021 ✓		 -1700 02/2021 ✓		 70000 02/2021 ✓	 70000	 30000 01/2023	 02/2022
—	24/02/2021	Repair	93101 Km	06098 NANNI MEMBER SRL , BRESCIA	Job			
—	Job							

Description:**Considered as a repeat visit** No**Customer's own words**

Servizio entità dei lavori standard
Package I 0000105

Manutenzione olio motore
Package I 0000610

Manutenzione microfiltro
Package I 0000616

Manutenzione liquido freni
Package I 0000618

— 24/02/2021 Warranty 93101 Km 06098 Job: Engine oil service
Job: Service - standard scope
Job: Washer fluid service
Job: Service - brake fluid
Job: Service - micro filter/activated carbon filter

— Job: Engine oil service

Description: Engine oil service**Considered as a repeat visit** No**Customer's own words**

Engine oil service 3 FRU
Flat rate unit I 00 00 610

Engine oil service
Defect I 87 00 02 00 00

Set oil-filter element 1
Part I 11 42 8 575 211

— Job: Service - standard scope

Description: Service - standard scope**Considered as a repeat visit** No**Customer's own words**

Service - standard scope 2 FRU
Flat rate unit I 00 00 105

Service - standard scope
Defect I 87 00 06 00 00

— Job: Washer fluid service

Description: Washer fluid service**Considered as a repeat visit** No**Customer's own words**

Washer fluid service
Defect I 87 00 09 00 00

Windshield antifreeze 1
Part I 83 19 0 413 112

— Job: Service - brake fluid

Description: Service - brake fluid**Considered as a repeat visit** No

Customer's own words

Brake fluid service 4 FRU
Flat rate unit I 00 00 618

Service - brake fluid
Defect I 87 34 00 00 00

Brake fluid 10
Part I 83 13 9 415 965

— Job: Service - micro filter/activated carbon filter

Description: Service - micro filter/activated carbon filter

Considered as a repeat visit No

Customer's own words

Microfilter service 2 FRU
Flat rate unit I 00 00 616

Service - micro filter/activated carbon filter
Defect I 87 64 01 00 00


Microfilter/activated Carbon container 1
Part I 64 11 9 237 555

— 07/09/2020 Key

86688 Km

06098

Key 0



— 07/09/2020 Repair

86688 Km

06098 NANNI
MEMBER SRL
, BRESCIA

Job

— Job

Description:

Considered as a repeat visit No


Customer's own words

— 03/09/2019 Key

71654 Km

06098

Key 0



— 03/09/2019 Warranty

71654 Km

06098

Job: F10 F11 F25 F26 F31 F34
F36 B47O Replacing exhaust-gas
recirculation cooler

— Job: F10 F11 F25 F26 F31 F34 F36 B47O Replacing exhaust-gas recirculation cooler

Description: F10 F11 F25 F26 F31 F34 F36 B47O Replacing exhaust-gas recirculation cooler

Considered as a repeat visit No

Customer's own words

Replace exhaust-gas recirculation cooler and replace or remount
exhaust-gas recirculation valve; clean exhaust gas recirculation pipe 28 FRU
Flat rate unit I 00 66 955

Fetch and bring service zone
Flat rate unit I 00 99 200

0 FRU

F10 F11 F25 F26 F31 F34 F36 B47O Replacing exhaust-gas
recirculation cooler
Defect I 00 11 83 04 00

O-ring
Part I 11 61 8 512 681

1

Pipe union
Part I 11 71 7 799 853

2

exhaust cooler
Part I 11 71 8 596 444

1


Set of small parts
Part I 11 71 8 597 652

1

— 13/02/2019 Key

62082 Km

Key 0




— 13/02/2019 Service

62082 Km

06098 NANNI
MEMBER SRL
, BRESCIA

Automatic



— 13/02/2019 Repair

62082 Km

06098 NANNI
MEMBER SRL
, BRESCIA

Job

— Job

Description:

Considered as a repeat visit No

Customer's own words

!!! unknown BMW-Id ESTIMATE TC_ !!!
Flat rate unit I -

Local

58 FRU

Servizio entità dei lavori standard
Package I 0000105

Service - standard scope
Flat rate unit I 00 00 105

2

Assistenza cartuccia filtro aria
Package I 0000602

Service - air filter element
Flat rate unit I 00 00 602

2

Air filter element
Part I 13718511668

1

Servizio filtro carburante
Package I 0000604

Service fuel filter
Flat rate unit I 00 00 604

3

Fuel filter cartridge Part I 13328572522	1
---	---

Manutenzione olio motore
Package I 0000610

Engine oil service Flat rate unit I 00 00 610	3
--	---

OLIO ORIGINALE BMW 0W-30 LL04 Part I OIL0W30	Local	5
---	-------	---

Set oil-filter element Part I 11428575211	1
--	---

Manutenzione microfiltro
Package I 0000616

Microfilter service Flat rate unit I 00 00 616	2
---	---

Microfilter/activated Carbon container Part I 64119237555	1
--	---

Manutenzione liquido freni
Package I 0000618

Brake fluid service Flat rate unit I 00 00 618	4
---	---

Brake fluid DOT4 LV, low viscosity Part I 83132405976	1
--	---

Manutenzione Controllo veicolo
Package I 0000624

Service, vehicle check Flat rate unit I 00 00 624	6
--	---

—	13/02/2019	Warranty	62082 Km	06098	Job
---	------------	----------	----------	-------	-----

— Job

Description:

Considered as a repeat visit No

Customer's own words

Checking index exhaust-gas recirculation cooler (no further repairs necessary afterwards) Flat rate unit I 00 67 709	3 FRU
--	-------

Defect I 00 11 10 05 00

—	13/02/2019	Warranty	62082 Km	06098	Job: Engine oil service Job: Service - vehicle check Job: Service - standard scope Job: Washer fluid service Job: Service - air cleaner Job: Service - fuel filter Job: Service - brake fluid Job: Service - micro filter/activated carbon filter
---	------------	----------	----------	-------	---

— Job: Engine oil service

Description: Engine oil service

Considered as a repeat visit No

Customer's own words

Engine oil service Flat rate unit I 00 00 610	3 FRU
Engine oil service Defect I 87 00 02 00 00	
Set oil-filter element Part I 11 42 8 575 211	1
— Job: Service - vehicle check	
Description: Service - vehicle check	
Considered as a repeat visit No	
Customer's own words	
Service, vehicle check Flat rate unit I 00 00 624	6 FRU
Service - vehicle check Defect I 87 00 05 00 00	
— Job: Service - standard scope	
Description: Service - standard scope	
Considered as a repeat visit No	
Customer's own words	
Service - standard scope Flat rate unit I 00 00 105	2 FRU
Service - standard scope Defect I 87 00 06 00 00	
— Job: Washer fluid service	
Description: Washer fluid service	
Considered as a repeat visit No	
Customer's own words	
Washer fluid service Defect I 87 00 09 00 00	
Windshield antifreeze Part I 83 19 0 413 112	1
— Job: Service - air cleaner	
Description: Service - air cleaner	
Considered as a repeat visit No	
Customer's own words	
Service - air filter element Flat rate unit I 00 00 602	2 FRU
Service - air cleaner Defect I 87 13 01 00 00	
Air filter element Part I 13 71 8 511 668	1
— Job: Service - fuel filter	
Description: Service - fuel filter	
Considered as a repeat visit No	
Customer's own words	

Service fuel filter
Flat rate unit | 00 00 604 3 FRU

Service - fuel filter
Defect | 87 13 02 00 00

Hose clamp
Part | 07 12 9 952 104 1

Fuel filter cartridge
Part | 13 32 8 572 522 1

— Job: Service - brake fluid

Description: Service - brake fluid

Considered as a repeat visit No

Customer's own words

Brake fluid service
Flat rate unit | 00 00 618 4 FRU

Service - brake fluid
Defect | 87 34 00 00 00

Brake fluid
Part | 83 13 9 415 965 10

— Job: Service - micro filter/activated carbon filter

Description: Service - micro filter/activated carbon filter

Considered as a repeat visit No

Customer's own words

Microfilter service
Flat rate unit | 00 00 616 2 FRU

Service - micro filter/activated carbon filter
Defect | 87 64 01 00 00










Microfilter/activated Carbon container
Part | 64 11 9 237 555 1

— 29/03/2018 Key

41099 Km

06098

Key 0



— 29/03/2018 Repair

41099 Km

06098 NANNI
NUMBER SRL
, BRESCIA

Job
Job

— Job

Description:

Considered as a repeat visit No

Customer's own words

Controllo scadenza garanzia
Flat rate unit | - Local 6 FRU

— Job

Description:

Considered as a repeat visit No

Customer's own words

ISPA TC-1-0011450400
Flat rate unit I -

Local

9 FRU

- 29/03/2018 Warranty 41099 Km 06098 Job: F1x F2x F3x B47 programming control units and if necessary, replacing the EGR valve

- Job: F1x F2x F3x B47 programming control units and if necessary, replacing the EGR valve

Description: F1x F2x F3x B47 programming control units and if necessary, replacing the EGR valve

Considered as a repeat visit No

Customer's own words

Carrying out the ABL and programming the control units
Flat rate unit I 00 64 246

10 FRU

F1x F2x F3x B47 programming control units and if necessary, replacing the EGR valve
Defect I 00 11 45 04 00

- 29/03/2018 Warranty 41099 Km 06098 Job

- Job

Description:

Considered as a repeat visit No

Customer's own words

Service to check the vehicle prior to expiry of the warranty
Flat rate unit I 00 00 608

0 FRU

Defect I 99 99 01 13 00

BMW Natural Air starter kit
Part I 83 12 2 285 673

1

- 06/03/2018 Key 38954 Km 06098 Key 0

								
23000	23000	23000	23000	44000	0	49000	23000	0
10/2019	604	604	604		02/2019		10/2019	03/2020

- 06/03/2018 Repair 38954 Km 06098 NANNI MEMBER SRL , BRESCIA Job

- Job

Description:

Considered as a repeat visit No


Customer's own words 300 piu iva

Lavoro di carrozzeria
Flat rate unit I -

Local

1 FRU

- 24/10/2017 Key 31164 Km 06098 Key 0




— 24/10/2017 Service

31164 Km

06098 NANNI
NUMBER SRL,
BRESCIA

Automatic



— 24/10/2017 Repair

31164 Km

06098 NANNI
NUMBER SRL
, BRESCIAJob: Service - standard scope
Job: Microfilter service
Job: Engine oil service
Job
Job

— Job: Service - standard scope

Description:

Considered as a repeat visit No

Customer's own wordsService - standard scope
Package I 0000105Service - standard scope
Flat rate unit I 00 00 105

2

— Job: Microfilter service

Description:

Considered as a repeat visit No

Customer's own wordsMicrofilter service
Package I 0000616Microfilter service
Flat rate unit I 00 00 616

2

Microfilter/activated Carbon container
Part I 64119237555

1

Glass cleaner without antifreeze
Part I 83122452029

1

— Job: Engine oil service

Description:

Considered as a repeat visit No

Customer's own wordsEngine oil service
Package I 0000610Engine oil service
Flat rate unit I 00 00 610

3

!!! unknown BMW-Id OIL0W30 OLIO ORIGINALE BMW 0W-30 Local
LL04 !!!
Part I OIL0W30

5

Set oil-filter element
Part I 11428575211

1

— Job

Description:

Considered as a repeat visit No

Customer's own words

!!! unknown BMW-Id ESTIMATE !!!
Flat rate unit I -

Local

0 FRU

— Job

Description:

Considered as a repeat visit No

Customer's own words

!!! unknown BMW-Id ESTIMATE Tagliando 30.000 km !!!
Flat rate unit I -

Local

0 FRU

— 24/10/2017 Warranty 31164 Km 06098 Job: Engine oil service
Job: Service - standard scope
Job: Washer fluid service
Job: Service - micro filter/activated carbon filter

— Job: Engine oil service

Description: Engine oil service

Considered as a repeat visit No

Customer's own words

Engine oil service
Flat rate unit I 00 00 610

3 FRU

Engine oil service
Defect I 87 00 02 00 00

Set oil-filter element
Part I 11 42 8 575 211

1

— Job: Service - standard scope

Description: Service - standard scope

Considered as a repeat visit No

Customer's own words

Service - standard scope
Flat rate unit I 00 00 105

2 FRU

Service - standard scope
Defect I 87 00 06 00 00

— Job: Washer fluid service

Description: Washer fluid service

Considered as a repeat visit No

Customer's own words

Washer fluid service
Defect I 87 00 09 00 00

Windshield antifreeze
Part I 83 19 0 413 112

1

— Job: Service - micro filter/activated carbon filter

Description: Service - micro filter/activated carbon filter

Considered as a repeat visit No

Customer's own words

Microfilter service
Flat rate unit I 00 00 616

2 FRU

Service - micro filter/activated carbon filter
Defect I 87 64 01 00 00

Microfilter/activated Carbon container
Part I 64 11 9 237 555

1

— 31/08/2017 Warranty 27709 Km 06098 Job: Exhaust gas recirculation valve (EGR)

— Job: Exhaust gas recirculation valve (EGR)

Description: Exhaust gas recirculation valve (EGR)

Considered as a repeat visit No

Customer's own words

Performing vehicle test
Flat rate unit I 00 00 006

4 FRU

Replacing exhaust gas recirculation valve
Flat rate unit I 11 71 501

0 FRU

Exhaust gas recirculation valve (EGR)
Defect I 11 71 01 83 00

EGR-valve
Part I 11 71 8 513 132

1









Oval head screw
Part I 35 21 7 685 343

2

Gasket Steel
Part I 11 71 8 579 364

1

— 30/08/2017 Key 27709 Km 06098 Key 0



— 30/08/2017 Repair 27709 Km 06098 NANNI MEMBER SRL, BRESCIA Job

— Job

Description:

Considered as a repeat visit No

Customer's own words ADESSO E' SPENTA MOTORE NON RENDE IN MANIERA SALTUARIA

Spia gestione motore si accende
Flat rate unit | -

Local

12 FRU

— 14/04/2017 Key 20007 Km 06098 Key 0

									
11000	0	11000	0	60000	0	60000	42000		0
02/2018		320			02/2019		02/2020		03/2020

— 14/04/2017 Repair 20007 Km 06098 NANNI
Job MEMBER SRL , BRESCIA

— Job

Description:

Considered as a repeat visit No

Customer's own words ASPETTA.1 ORA.

Sostituzione ruote stoccate estive / invernali COMPLETE
Flat rate unit | -

Local

7 FRU

— 18/11/2016 Key 11242 Km 06098 Key 0

									
20000	0	20000	0	60000	0	60000	60000		0
02/2018		467			02/2019		02/2020		03/2020

— 18/11/2016 Repair 11242 Km 06098 NANNI
Job MEMBER SRL , BRESCIA

— Job

Description:

Considered as a repeat visit No

Customer's own words GOMME IN DEPOSITO

Sostituzione ruote stoccate estive / invernali COMPLETE
Flat rate unit | -

Local

7 FRU

— Job

Description:

Considered as a repeat visit No

Customer's own words

Controlli Livelli
Flat rate unit | -


Local

3 FRU

— 04/11/2016 Key 10547 Km 06098 Key 0

									
21000	0	21000	0	60000	0	60000	60000		0
02/2018		481			02/2019		02/2020		03/2020

— 04/10/2016 Key 9896 Km 06098 Key 0



— 04/10/2016 Repair 9896 Km 06098 NANNI MEMBER SRL , BRESCIA Job

— Job

Description:
Considered as a repeat visit No
Customer's own words

Lavoro di carrozzeria Local 1 FRU
Flat rate unit | -

— 17/03/2016 Key 5 Km 06098 Key 1

