

Thank you for ordering from us!
www.checkvin.eu

Vehicle

BMW 318D A, 110KW

WBA8H71010K657913



Development code
Colour
Actual integration level
Start of warranty

F31
black-sapphire metallic
F020-22-11-510
29 January 2016

Technical campaigns

There are no Campaigns for this vehicle.

Warranty extension/VIN-based goodwill

Status	Campaign number	Description
Open	1SACC011056	Exhaust gas recirculation cooler Bx7 Local campaign number: -

Special information

There are no Campaigns for this vehicle.

Restrictions on the warranty

There are no restrictions on the warranty.

⚠ Market-specific restrictions are not currently displayed. Please check this in WDF/WXE via S-Gate.

Live Diagnosis

 There are no service solutions for Live Diagnosis.

Service contracts

No BSI contracts

Information on faults workshop/Service Consultation

There is no information on faults.

Navigation map

Installed map	Enabling code (subscription)	Latest navigation map included in subscription	Latest navigation map subject to charge
Road Map EUROPE EAST Route 2021-1 (As of: 7 Aug 2024)	Enabling code valid for navigation maps with release date up to 31 Dec 2025 (SWID: 00B4008F).	Road Map EUROPE WEST Route 2025	-

Vehicle details

Vehicle type	Passenger car
Brand	BMW
Model	318D A
Body	TOUR
Vehicle identification number (last 7 digits)	K657913
Vehicle identification number (17 digits)	WBA8H71010K657913
Development code	F31
Steering	LL
Engine	B47U
Engine number	53479390
Exhaust re-treatment	EURO6, W, PI/CI, M, N1 I
Transmission	AUT
Transmission number	0136992ZEK
Head unit serial number	MM01DFF1289700
Drive	HECK
Integration level, works	F020-15-07-506
Production date	23 Sept 2015
Production plant	Muenchen
Delivery date	24 Sept 2015
Delivering retailer	BMW ITALIA RETAIL SRL - Flotte, ROMA, IT
National-market version	EUR
Paint code	475
Upholstery code	CCL1
Model code	8H81
Basic type	8H71
Lead type	8H81

Optional equipment

Optional equipment ex works:

- 01CA Selection of COP-relevant vehicles
- 01CB CO2 equipment
- 0205 Automatic transmission
- 0216 Hydro steering-servotronic
- 0230 Extra package, EU-speciifc
- 0258 Tyres with runflat properties
- 02A6 BMW LA wheel, double spoke 392
- 02PA Locking wheel bolt
- 02VB Tyre pressure display
- 02XE Leather sports steering wheel
- 0302 Alarm system
- 0423 Floor mats velours
- 0430 Interior/outside mirror with auto dip
- 0431 Interior mirror with automatic-dip
- 0481 Sports seat
- 0493 Storage compartment package
- 04AE Armrest front, retractable
- 04LU black high-gloss accent chrm. Perlglanz
- 0507 Park Distance Control (PDC), rear
- 0521 Rain sensor
- 0534 Automatic air conditioning
- 0544 Cruise control with brake function
- 0548 Kilometre speedo
- 0563 Light package
- 05A2 LED headlight
- 05DC Rear-seat headrests, folding
- 0606 Navigation system Business
- 0698 Area-Code 2 for DVD
- 06AC Intelligent emergency call
- 06AE Teleservices
- 06NH Hands-free system with USB interface
- 06UH Traffic Information
- 07AC Sport Line
- 07LD Modell Sport Line
- 0845 Acoustic fasten seat belt reminder
- 0855 Language version, Italian
- 0884 On-board literature Italian
- 08KA Oil service interval 24 mths / 30,000 km
- 0962 Deleted, licence plate support front
- 09AA Outer skin protection
- A090 90 Ah AGM battery
- POLS Cloth cushion

Retrofitted optional equipment:

This vehicle has no retrofits.

Vehicle histories

	Date	Type	Vehicle mileage	Retailer	Overview
—	07/08/2024	Key	216822 Km	07604	Key 0
	 19000 01/2026	 19000 01/2026	 90000 05/2025	 90000 01/2026	 01/2025
—	07/08/2024	Warranty	216822 Km	07604	Job: F1x F2x F3x G0x G1x G3x B47O B47K B47U B47T Replacing EGR cooler (high-temperature) Job: Fx Checking driver's airbag and replacing if necessary (SDI conversion)
—	Job: F1x F2x F3x G0x G1x G3x B47O B47K B47U B47T Replacing EGR cooler (high-temperature)				
	Description: F1x F2x F3x G0x G1x G3x B47O B47K B47U B47T Replacing EGR cooler (high-temperature)				
	Considered as a repeat visit No				
	Customer's own words				

Replace exhaust gas recirculation cooler, including exhaust gas recirculation valve
Flat rate unit I 00 74 062 25 FRU

Additional work: run function test for pressure sensor system
Flat rate unit I 00 74 650 3 FRU

Additional work: enter component identification of new exhaust gas recirculation cooler in diagnostic system
Flat rate unit I 00 74 651 1 FRU

Additional work cleaning the exhaust gas recirculation pipe
Flat rate unit I 00 74 652 6 FRU

F1x F2x F3x G0x G1x G3x B47O B47K B47U B47T Replacing EGR cooler (high-temperature)
Defect I 00 11 15 07 00

Exhaust gas radiator high temperature
Part I 11 71 7 822 347 1

EGR small parts set
Part I 11 71 8 490 640 1

Pipe union
Part I 11 71 7 799 853 2

Holder
Part I 61 13 1 369 832 1

Connection piece
Part I 11 65 7 803 012 1

O-ring
Part I 11 61 8 512 681 1

Acoustic cover front
Part I 11 14 8 490 577 1

— Job: Fx Checking driver's airbag and replacing if necessary (SDI conversion)

Description: Fx Checking driver's airbag and replacing if necessary (SDI conversion)

Considered as a repeat visit No

Customer's own words

Check steering wheel (airbag module not affected)
Flat rate unit I 00 76 854 1 FRU






Fx Checking driver's airbag and replacing if necessary (SDI conversion)
Defect I 00 32 55 03 00

— 23/04/2024 Key

210052 Km

07604

Key 0



— 23/04/2024 Warranty

210052 Km

07604

Job: Fx Gx B37 B47 B57 N47 N57
Check coolant level (EGR)

— Job: Fx Gx B37 B47 B57 N47 N57 Check coolant level (EGR)

Description: Fx Gx B37 B47 B57 N47 N57 Check coolant level (EGR)


Considered as a repeat visit No

Customer's own words

Flat rate unit I 00 73 827 4 FRU

Fx Gx B37 B47 B57 N47 N57 Check coolant level (EGR)
Defect I 11 71 90 08 00

— 08/02/2023 Key 179756 Km Key 0



— 08/02/2023 Warranty 179769 Km 07604 Job: G0x G3x B47O Programming control units (DDE)

— Job: G0x G3x B47O Programming control units (DDE)

Description: G0x G3x B47O Programming control units (DDE)

Considered as a repeat visit No


Customer's own words

Program control units 9 FRU
Flat rate unit I 00 71 374

Additional work: check CCM Check Control message and coolant level 1 FRU
Flat rate unit I 00 73 677

G0x G3x B47O Programming control units (DDE)
Defect I 00 13 51 03 00

— 24/11/2020 Key 112411 Km 40758 Key 0



— 24/11/2020 Warranty 112411 Km 40758 Job: Exhaust gas recirculation valve (EGR)

— Job: Exhaust gas recirculation valve (EGR)

Description: Exhaust gas recirculation valve (EGR)

Considered as a repeat visit No

Customer's own words

Performing vehicle test 4 FRU
Flat rate unit I 00 00 006

Supporting the voltage of the vehicle electrical system/recharging the vehicle electrical system battery 1 FRU
Flat rate unit I 61 21 528

Vehicle diagnosis - carrying out the ABL 1 FRU
Flat rate unit I 61 00 006

Replacing exhaust gas recirculation valve 7 FRU
Flat rate unit I 11 71 501

Exhaust gas recirculation valve (EGR)
Defect I 11 71 01 83 00

EGR-valve 1
Part I 11 71 8 513 132

Oval head screw 2
Part I 35 21 7 685 343

Gasket Steel
Part I 11 71 8 579 364

1


Hose clamp
Part I 07 12 9 952 104

2

— 07/10/2019 Key

80792 Km 07549

Key 0



— 07/10/2019 Warranty

80792 Km 07549

Job: F1x F2x F3x B47
programming control units and if
necessary, replacing the EGR valve
Job: F10 F11 F25 F26 F31 F34
F36 B47O Replacing exhaust-gas
recirculation cooler

— Job: F1x F2x F3x B47 programming control units and if necessary, replacing the EGR valve

Description: F1x F2x F3x B47 programming control units and if necessary, replacing the EGR valve**Considered as a repeat visit** No**Customer's own words**

Carrying out the ABL and programming the control units
Flat rate unit I 00 64 941

8 FRU

F1x F2x F3x B47 programming control units and if necessary, replacing
the EGR valve
Defect I 00 11 45 04 00

— Job: F10 F11 F25 F26 F31 F34 F36 B47O Replacing exhaust-gas recirculation cooler

Description: F10 F11 F25 F26 F31 F34 F36 B47O Replacing exhaust-gas recirculation cooler**Considered as a repeat visit** No**Customer's own words**

Additional work of checking EGR cooler
Flat rate unit I 00 67 703

1 FRU

Replace exhaust-gas recirculation cooler and replace or remount
exhaust-gas recirculation valve; clean exhaust gas recirculation pipe
Flat rate unit I 00 66 955

28 FRU

Perform additional work for pressure sensor system function
Flat rate unit I 00 67 695

3 FRU

F10 F11 F25 F26 F31 F34 F36 B47O Replacing exhaust-gas
recirculation cooler
Defect I 00 11 83 04 00

exhaust cooler
Part I 11 71 8 596 444

1

Set of small parts
Part I 11 71 8 597 652

1

Pipe union
Part I 11 71 7 799 853

2

O-ring
Part I 11 61 8 512 681

1

— 08/02/2016 Key

7 Km 36443

Key 0

