

Thank you for ordering from us!

www.checkvin.eu

Vehicle

BMW 320D A, 140KW

WBA8T31010G803608



Development code

Colour

Actual integration level

Start of warranty

F34

glacier-silber metallic

F020-22-11-510

26 September 2017

Technical campaigns

There are no Campaigns for this vehicle.

Warranty extension/VIN-based goodwill

Status	Campaign number	Description
Open	1SACC011056	Exhaust gas recirculation cooler Bx7 Local campaign number: -

Special information

There are no Campaigns for this vehicle.

Restrictions on the warranty

There are no restrictions on the warranty.

⚠ Market-specific restrictions are not currently displayed. Please check this in WDF/WXE via S-Gate.

Live Diagnosis

 There are no service solutions for Live Diagnosis.

Service contracts

No BSI contracts

Information on faults workshop/Service Consultation

There is no information on faults.

Navigation map

Note: The installed map cannot be clearly identified. Presumably one of the following maps is present in the vehicle.

Installed map	Enabling code (subscription)	Latest navigation map included in subscription	Latest navigation map subject to charge
Road Map EUROPE EVO 2017-2 (As of: 30 Jul 2024)	-	-	-
Road Map EUROPE EVO 2017-2 (As of: 30 Jul 2024)	Enabling code valid for navigation maps with release date up to 31 Dec 2099 (SWID: 01200FFF).	Road Map EUROPE EVO 2025-1	-

Vehicle details

Vehicle type	Passenger car
Brand	BMW
Model	320D A
Body	SAT
Vehicle identification number (last 7 digits)	G803608
Vehicle identification number (17 digits)	WBA8T31010G803608
Development code	F34
Steering	LL
Engine	B47O
Engine number	60325092
Exhaust re-treatment	EURO6, W, PI/CI, M, N1 I
Transmission	AUT
Transmission number	1232608Z35
Head unit serial number	HB2241H8180151
Drive	HECK
Integration level, works	F020-17-07-505
Production date	31 Aug 2017
Production plant	Dingolfing
Delivery date	1 Sept 2017
Delivering retailer	Ungeheuer Automobile GmbH, Karlsruhe, DE
National-market version	EUR
Paint code	A83
Upholstery code	HAAT
Model code	8T41
Basic type	8T31
Lead type	8T41

Optional equipment

Optional equipment ex works:

01CA Selection of COP-relevant vehicles
01CB CO2 equipment
0205 Automatic transmission
0216 Hydro steering-servotronic
0230 EU-specific additional contents
0258 Tyres with runflat properties
02PA Locking wheel bolt
02PE BMW LA wheel, M star spoke 400
02VB Tyre pressure display
0302 Alarm system
0320 Deleted, model lettering
0322 Comfort access system
0337 M Sports package
0420 Sun protection glazing
0423 Floor mats velours
0428 Warning triangle and first aid kit
0430 Interior/outside mirror with auto dip
0431 Interior mirror with automatic-dip
0441 Smoker package
0481 Sports seat
0488 Lumbar support, driver and passenger
0493 Storage compartment package
0494 Seat heating driver/passenger
04AE Armrest front, retractable
04FT Alum. brushed lengthw. acc. black hi-gls
0508 Park Distance Control (PDC)
0521 Rain sensor
0534 Automatic air conditioning
0544 Cruise control with brake function
0548 Kilometre speedo
0552 Adaptive LED headlight
0563 Lights package
0575 Additional 12V power socket
05A1 LED Fog lights
05AC High-beam assistant
05AS Driving Assistant
05DA Passenger airbag deactivation
0609 Navigation system Professional
0610 Head-up display
0654 DAB tuner
0698 Area-Code 2 for DVD
06AC Intelligent emergency call
06AE Teleservices
06AK Connected Drive Services
06AM Real-Time Traffic Information
06AN Concierge Services
06AP Remote Services
06NW Telephony with wireless charging
06WA Instrument panel with extended scope
06WD WLAN Hotspot
0704 M Sports suspension
0710 M Leather steering wheel
0715 M Aerodynamics package
0760 High gloss shadow line
0775 Headlining anthracite
07LF Modell M Sport
07R7 Innovation package
0801 German version
0851 Language version German
0879 On-board literature, German
08KA Oil service interval 24 mths / 30,000 km
08R9 Refrigerant R1234yf
08TF Active pedestrian protection
08TH Road sign detection
09AA Outer skin protection
09BM Navigation package Connected Drive
A090 90 Ah AGM battery
POLS Cloth cushion

Retrofitted optional equipment:

This vehicle has no retrofits.

Vehicle histories

	Date	Type	Vehicle mileage	Retailer	Overview
—	28/01/2025	Service	178139 Km	OSS-60153924 Autohaus Staufen GmbH, Geislingen an der Steige	Manual
—	30/07/2024	Key	166528 Km	00427	Key 0
—	30/07/2024	Warranty	166534 Km	00427	Job: F1x F2x F3x G0x G1x G3x B47O B47K B47U B47T Replacing EGR cooler (high-temperature) Job: E84 Fx Gx Bx7 Nx7 Customer notification exhaust gas recirculation cooler

— Job: F1x F2x F3x G0x G1x G3x B47O B47K B47U B47T Replacing EGR cooler (high-temperature)

Description: F1x F2x F3x G0x G1x G3x B47O B47K B47U B47T Replacing EGR cooler (high-temperature)

Considered as a repeat visit	No
------------------------------	----

Customer's own words

Replace exhaust gas recirculation cooler, including exhaust gas recirculation valve Flat rate unit 00 74 057	25 FRU
Additional work: run function test for pressure sensor system Flat rate unit 00 74 636	3 FRU
Additional work: enter component identification of new exhaust gas recirculation cooler in diagnostic system Flat rate unit 00 74 637	1 FRU
Additional work cleaning the exhaust gas recirculation pipe Flat rate unit 00 74 638	6 FRU
F1x F2x F3x G0x G1x G3x B47O B47K B47U B47T Replacing EGR cooler (high-temperature) Defect 00 11 13 07 00	
Exhaust gas radiator high temperature Part 11 71 7 822 347	1
EGR small parts set Part 11 71 8 490 640	1
Vacuum hose black Part 11 65 8 595 650	1
Pipe union Part 11 71 7 799 853	2
Holder	1

Connection piece
Part I 11 65 7 803 012

1

O-ring
Part I 11 61 8 512 681

1

Acoustic cover front
Part I 11 14 8 490 577

1

— Job: E84 Fx Gx Bx7 Nx7 Customer notification exhaust gas recirculation cooler

Description: E84 Fx Gx Bx7 Nx7 Customer notification exhaust gas recirculation cooler

Considered as a repeat visit No

Customer's own words

Administrative effort
Flat rate unit I 00 74 758

1 FRU

E84 Fx Gx Bx7 Nx7 Customer notification exhaust gas recirculation cooler
Defect I 00 11 35 07 00

— 29/07/2024 Key 166487 Km 00427 Remote KeyRead

 27000 07/2026	 27000 07/2026	 27000 07/2026	 70000	 01/2025	 01/2025	 60000	 27000 07/2026	 05/2025	 05/2025
---	---	---	--	--	--	--	--	--	--

— 09/07/2024 Service 165911 Km OSS-60153924 Autohaus Staufen GmbH, Geislingen an der Steige Manual

 ✓	 ✓	 ✓	 ✓	 ✓	 ✓	 ✓	 ✓	 ✓	 ✓	 ✓
--	--	--	--	--	--	--	---	--	--	--

— 28/02/2024 Key 162790 Km 00427 Remote KeyRead


 -800 2.9 % 08/2024	 -800 08/2024	 -800 08/2024	 -800 08/2024	 16000 01/2025	 01/2025	 5000 01/2025	 -800 1.4 % 08/2024	 05/2025	 05/2025
---	--	--	--	---	--	--	--	--	--

— 30/01/2024 Key 162193 Km 00427 Remote KeyRead


 -210 0.8 % 08/2024	 -210 08/2024	 -210 08/2024	 -210 08/2024	 16000 01/2025	 01/2025	 5000 01/2025	 -210 0.4 % 08/2024	 05/2025	 05/2025
---	--	--	--	---	--	--	--	--	--

— 25/05/2023 Key 152991 Km Remote KeyRead

 12000 08/2024	 12000 08/2024	 12000 08/2024	 12000 08/2024	 24000 01/2025	 01/2025	 14000 01/2025	 12000 08/2024	 05/2025	 05/2025
---	---	---	---	---	--	---	--	--	--



— 13/04/2021 Key 114703 Km Key 1



— 13/04/2021 Warranty 114708 Km 30317 Job: Switch/button, multifunction steering wheel (MFL)

— Job: Switch/button, multifunction steering wheel (MFL)

Description: Switch/button, multifunction steering wheel (MFL)

Considered as a repeat visit No


Customer's own words

Removing and installing or replacing both switches, multifunction steering wheel 0 FRU
Flat rate unit I 61 31 221


Switch/button, multifunction steering wheel (MFL)
Defect I 61 30 24 78 00

Switch, multifct.steering wheel, M-Sport 1
Part I 61 31 7 849 411

— 21/01/2021 Key 114599 Km Key 1




— 30/12/2020 Key 114588 Km 30315 Key 1



— 30/12/2020 Service 114588 Km 30315 Automatic

Ungeheuer
Automobile ,
Karlsruhe



— 30/12/2020 Repair 114588 Km 30315
Ungeheuer
Automobile
Job: Service Fahrzeug-Check
Job: Service Motoröl
Job: Service Kraftstofffilter
Job: Service Luftfiltereinsatz

— Job: Service Fahrzeug-Check

Description:

Considered as a repeat visit No

Customer's own words

Service Fahrzeug-Check
Package I 000062418T410

Service, vehicle check 6
Flat rate unit I 00 00 624

— Job: Service Motoröl

Description:

Considered as a repeat visit No

Customer's own words

Service Motoröl
Package I 000061018T410

Engine oil service 3
Flat rate unit I 00 00 610

!!! unknown BMW-Id FRE/99999100100 MOBIL 3000XE/1 5W30 Local 5
!!!
Part I FRE/99999100100

Set oil-filter element 1
Part I 11428575211

— Job: Service Kraftstofffilter

Description:

Considered as a repeat visit No

Customer's own words

Service Kraftstofffilter
Package I 000060418T410

Service fuel filter 3
Flat rate unit I 00 00 604

Fuel filter cartridge 1
Part I 13328572522

— Job: Service Luftfiltereinsatz

Description:

Considered as a repeat visit No

Customer's own words

Service Luftfiltereinsatz
Package I 000060218T410

Service - air filter element 2
Flat rate unit I 00 00 602

Air filter element 1
Part I 13718511668

— Job: Service Mikrofilter

Description:

Considered as a repeat visit No

Customer's own words

Service Mikrofilter

Package I 000061618T410

Microfilter service	2
Flat rate unit I 00 00 616	

Microfilter/activated Carbon container	1
Part I 64119237555	

— Job

Description:

Considered as a repeat visit No

Customer's own words

APAS TC-1-0011880500	Local	18 FRU
Flat rate unit I -		

!!! unknown BMW-Id ESTIMATE F1x F2x F3x G0x G1x G3x B47O B47T Local	0 FRU
B47U B47K AGR-Kühler prüfen ggf. ersetzen !!!	
Flat rate unit I -	

— Job

Description:

Considered as a repeat visit No

Customer's own words

aa Einlagerung Klein Mini/1er/2er/3er/4er/X1/Z4/i3	Local	1 FRU
Flat rate unit I -		

!!! unknown BMW-Id ESTIMATE Einlagerungsgebühr !!!	Local	0 FRU
Flat rate unit I -		

— Job

Description:

Considered as a repeat visit No

Customer's own words

!!! unknown BMW-Id ESTIMATE Standardumfang !!!	Local	0 FRU
Flat rate unit I -		

Service - standard scope	2 FRU
Flat rate unit I 00 00 105	

— Job

Description:

Considered as a repeat visit No

Customer's own words

CAREBMW	Local	0 FRU
Flat rate unit I 00 11 320		

Interior vehicle cleaning	1 FRU	
Flat rate unit I 00 11 315		

— Job

Description:**Considered as a repeat visit** No**Customer's own words**!!! unknown BMW-Id ESTIMATE !!!
Flat rate unit | -

Local

0 FRU

!!! unknown BMW-Id ESTIMATE !!!
Flat rate unit | -

Local

0 FRU

— 30/12/2020 Warranty 114594 Km 30315

Job: Engine oil service
Job: Service - vehicle check
Job: Service - standard scope
Job: Washer fluid service
Job: Service - air cleaner
Job: Service - fuel filter
Job: Service - micro filter/activated carbon filter

— Job: Engine oil service

Description: Engine oil service**Considered as a repeat visit** No**Customer's own words**Engine oil service
Flat rate unit | 00 00 610

3 FRU

Engine oil service
Defect | 87 00 02 00 00Set oil-filter element
Part | 11 42 8 575 211

1

— Job: Service - vehicle check

Description: Service - vehicle check**Considered as a repeat visit** No**Customer's own words**Service, vehicle check
Flat rate unit | 00 00 624

6 FRU

Service - vehicle check
Defect | 87 00 05 00 00

— Job: Service - standard scope

Description: Service - standard scope**Considered as a repeat visit** No**Customer's own words**Service - standard scope
Flat rate unit | 00 00 105

2 FRU

Service - standard scope
Defect | 87 00 06 00 00

— Job: Washer fluid service

Description: Washer fluid service**Considered as a repeat visit** No**Customer's own words**

Washer fluid service

Defect I 87 00 09 00 00

— Job: Service - air cleaner

Description: Service - air cleaner

Considered as a repeat visit No

Customer's own words

Service - air filter element Flat rate unit I 00 00 602	2 FRU
--	-------

Service - air cleaner
Defect I 87 13 01 00 00

Air filter element Part I 13 71 8 511 668	1
--	---

— Job: Service - fuel filter

Description: Service - fuel filter

Considered as a repeat visit No

Customer's own words

Service fuel filter Flat rate unit I 00 00 604	3 FRU
---	-------

Service - fuel filter
Defect I 87 13 02 00 00

Fuel filter cartridge Part I 13 32 8 572 522	1
---	---

— Job: Service - micro filter/activated carbon filter

Description: Service - micro filter/activated carbon filter

Considered as a repeat visit No

Customer's own words

Microfilter service Flat rate unit I 00 00 616	2 FRU
---	-------

Service - micro filter/activated carbon filter
Defect I 87 64 01 00 00

Microfilter/activated Carbon container Part I 64 11 9 237 555	1
--	---

—	30/12/2020	Warranty	114594 Km	30315	Job: F1x F2x F3x G0x G1x G3x B47O B47T B47U B47K Check and, if required, replace EGR cooler
---	------------	----------	-----------	-------	---

— Job: F1x F2x F3x G0x G1x G3x B47O B47T B47U B47K Check and, if required, replace EGR cooler

Description: F1x F2x F3x G0x G1x G3x B47O B47T B47U B47K Check and, if required, replace EGR cooler

Considered as a repeat visit No

Customer's own words

Visual insp. of EGR cooler outlet and inlet (OK), check CC message about coolant level (OK) and note the prod. date of the installed exhaust gas recirc. cooler Flat rate unit I 00 70 505	12 FRU
---	--------

F1x F2x F3x G0x G1x G3x B47O B47T B47U B47K Check and, if required, replace EGR cooler
Defect I 00 11 88 05 00

Oval head screw	2
-----------------	---

06/10/2020		Key	107490 Km					Key 1
								
8000	8000	8000	8000	27000	0	9000	8000	0
04/2022	571	571	571		-6 0.8 %		04/2022	-6 0.8 %

—	06/10/2020	Service	107490 Km	01554	Manual				
				Autohaus Rolf					
				Horn, Düren					
									
					✓			✓	✓

—	06/10/2020	Repair	107495 Km	01554 Autohaus Rolf Horn GmbH , Düren	Job Job Job
---	------------	--------	-----------	--	-------------------

— Job

Description:

Considered as a repeat visit No

Customer's own words

Auslagerung Sommerreifen ohne Berechnung Lagerort 954 Flat rate unit I 36 00 036	Local	0 FRU
Replacing four tyres with run-flat technology Flat rate unit I 36 12 076		30 FRU

— Job

Description:

Considered as a repeat visit No

Customer's own words

Fußraumreinigung (aussaugen) Flat rate unit I 00 11 320	Local	1 FRU
Vehicle surface wash Flat rate unit I 00 11 319		0 FRU
Light function test Flat rate unit I 00 12 290		0 FRU

— Job

Description:

Considered as a repeat visit No

Customer's own words

Kosten Leihfahrzeug (E) EU-AH 1800 00000000 Flat rate unit I 99 99 999	Local	1 FRU
---	-------	-------

—	06/10/2020	Repair	107495 Km	01554 Autohaus Rolf	Job Job
---	------------	--------	-----------	------------------------	------------

— Job

Description:

Considered as a repeat visit No

Customer's own words

Service - standard scope	2 FRU
Flat rate unit I 00 00 105	

— Job

Description:

Considered as a repeat visit No

Customer's own words

Brake fluid service	4 FRU
Flat rate unit I 00 00 618	

Brake fluid DOT4 LV, low viscosity	1
Part I 83 13 2 184 843	

— Job

Description:

Considered as a repeat visit No

Customer's own words

Fremdrechnung 00000000 87990100007	Local	1 FRU
Flat rate unit I 99 99 999		

—	06/10/2020	Warranty	107495 Km	01554	Job: Service - standard scope Job: Service - brake fluid Job: Service - legally required vehicle inspection/exhaust emission inspection
---	------------	----------	-----------	-------	---

— Job: Service - standard scope

Description: Service - standard scope

Considered as a repeat visit No

Customer's own words

Service - standard scope	2 FRU
Flat rate unit I 00 00 105	

Service - standard scope
Defect I 87 00 06 00 00

— Job: Service - brake fluid

Description: Service - brake fluid

Considered as a repeat visit No

Customer's own words

Brake fluid service	4 FRU
Flat rate unit I 00 00 618	

Service - brake fluid
Defect I 87 34 00 00 00

— Job: Service - legally required vehicle inspection/exhaust emission inspection

Description: Service - legally required vehicle inspection/exhaust emission inspection

Considered as a repeat visit No

Customer's own words

Service - legally required vehicle inspection/exhaust emission inspection
Defect I 87 99 01 00 00

—

02/04/2020

Key

84158 Km

00508

Key 1



700

10/2021





700

539





60000

09/2020



34000



28000

10/2023



09/2020

—

02/04/2020

Service

84158 Km

01554
Autohaus Rolf
Horn, Düren

Manual



✓





✓

















—

02/04/2020

Repair

84162 Km

01554
Autohaus Rolf
Horn GmbH,
Düren

Job
Job
Job

— Job

Description:

Considered as a repeat visit No

Customer's own words

Replacing four tyres with run-flat technology
Flat rate unit I 36 12 076
30 FRU

— Job

Description:

Considered as a repeat visit No

Customer's own words

Rädereinlagerung Lagernummer: 954 Einlagerungszeitraum: 6 Monate Local
Flat rate unit I 36 00 031
6 FRU

— Job

Description:

Considered as a repeat visit No

Customer's own words

Job time without allowance for / body equipment
Flat rate unit I 51 99 000
0 FRU

—

02/04/2020

Repair

84162 Km

01554
Autohaus Rolf
Horn GmbH,
Düren

Job
Job

— Job

Description:**Considered as a repeat visit** No**Customer's own words**

Service - standard scope	2 FRU
Flat rate unit I 00 00 105	

Engine oil service	3 FRU
Flat rate unit I 00 00 610	

BMW Engine Oil LL04 0W30	5
Part I 83 21 2 405 950	

Set oil-filter element	1
Part I 11 42 8 575 211	

— Job

Description:**Considered as a repeat visit** No**Customer's own words**

Microfilter service	2 FRU
Flat rate unit I 00 00 616	

Microfilter/activated Carbon container	1
Part I 64 11 9 237 555	

—	02/04/2020	Warranty	84162 Km	01554	Job: Engine oil service Job: Service - standard scope Job: Service - micro filter/activated carbon filter
---	------------	----------	----------	-------	---

— Job: Engine oil service

Description: Engine oil service**Considered as a repeat visit** No**Customer's own words**

Engine oil service	3 FRU
Flat rate unit I 00 00 610	

Engine oil service	
Defect I 87 00 02 00 00	

Set oil-filter element	1
Part I 11 42 8 575 211	

— Job: Service - standard scope

Description: Service - standard scope**Considered as a repeat visit** No**Customer's own words**

Service - standard scope	2 FRU
Flat rate unit I 00 00 105	

Service - standard scope	
Defect I 87 00 06 00 00	

— Job: Service - micro filter/activated carbon filter

Description: Service - micro filter/activated carbon filter**Considered as a repeat visit** No**Customer's own words**

Microfilter service
Flat rate unit | 00 00 616 2 FRU

Service - micro filter/activated carbon filter
Defect | 87 64 01 00 00

Microfilter/activated Carbon container 1
Part | 64 11 9 237 555

— 27/01/2020 Repair 63836 Km 01554 Job
Autohaus Rolf
Horn GmbH,
Düren

— Job

Description:

Considered as a repeat visit No

Customer's own words

Job time without allowance for / painting 6 FRU
Flat rate unit | 99 99 000

Flap, towing eye, primed 1
Part | 51 11 8 061 552

— 19/11/2019 Warranty 63836 Km 01554 Job: Service - standard scope
Job: Service - front brakes

— Job: Service - standard scope

Description: Service - standard scope

Considered as a repeat visit No

Customer's own words

Service - standard scope 2 FRU
Flat rate unit | 00 00 105

Service - standard scope
Defect | 87 00 06 00 00

— Job: Service - front brakes

Description: Service - front brakes

Considered as a repeat visit No

Customer's own words


Service, front brakes 6 FRU
Flat rate unit | 00 00 612

Service - front brakes
Defect | 87 34 11 01 00


Brake pad wear sensor, front left 1
Part | 34 35 6 792 289

Repair kit, brake pads asbestos-free 1
Part | 34 10 6 859 181

— 18/11/2019 Key 63811 Km 01554 Key 1



— 18/11/2019 Service 63811 Km 01554 Manual
Autohaus Rolf
Horn, Düren



— 18/11/2019 Repair 63836 Km 01554 Job
Autohaus Rolf
Horn GmbH, Job
Düren

— Job

Description:

Considered as a repeat visit No

Customer's own words

Fahrzeugoberwäsche Flat rate unit I 00 11 321	Local	0 FRU
Fußraumreinigung (aussaugen) Flat rate unit I 00 11 322	Local	0 FRU
Service consultation with customer at vehicle without service ticket Flat rate unit I 00 52 053		0 FRU

— Job

Description:

Considered as a repeat visit No

Customer's own words

Winterreifen montieren Flat rate unit I 36 00 020	Local	0 FRU
Replacing four tyres with run-flat technology Flat rate unit I 36 12 076		30 FRU

— Job

Description:

Considered as a repeat visit No

Customer's own words

Rädereinlagerung Lagernummer: Einlagerungszeitraum: 6 Monate Flat rate unit I 36 00 030	Local	6 FRU
--	-------	-------

— 18/11/2019 Repair 63836 Km 01554 Job
Autohaus Rolf
Horn GmbH, Job
Düren

— Job

Description:

Considered as a repeat visit No

Customer's own words

Service - standard scope Flat rate unit I 00 00 105		2 FRU
--	--	-------

— Job

Description:

Considered as a repeat visit No

Customer's own words

Service, front brakes Flat rate unit I 00 00 612	6 FRU
---	-------

Brake pad wear sensor, front left Part I 34 35 6 792 289	1
---	---

Repair kit, brake pads asbestos-free Part I 34 10 6 859 181	1
--	---

—	18/11/2019	Repair	63836 Km	01554 Autohaus Rolf Horn GmbH , Düren	Job
---	------------	--------	----------	--	-----

— Job

Description:

Considered as a repeat visit No

Customer's own words

Job time without allowance for / wheels Flat rate unit I 36 99 000	4 FRU
---	-------

Wheel electr. module RDCi w/ screw valve Part I 36 10 6 881 890	1
--	---

—	30/10/2019	Repair	35174 Km	30315 Ungeheuer Automobile GmbH , Karlsruhe	Job
---	------------	--------	----------	---	-----

— Job

Description:

Considered as a repeat visit No

Customer's own words

Versand der eingelagerten Winterräder Flat rate unit I 99 99 999	Local	1 FRU
---	-------	-------

an: Flat rate unit I 99 99 999	Local	1 FRU
-----------------------------------	-------	-------

AH Horn Flat rate unit I 99 99 999	Local	1 FRU
---------------------------------------	-------	-------

Bahnstr. 13-15 Flat rate unit I 99 99 999	Local	1 FRU
--	-------	-------

52355 Düren Flat rate unit I 99 99 999	Local	1 FRU
---	-------	-------

lt. Herrn Viktor Bergen. Flat rate unit I 99 99 999	Local	1 FRU
--	-------	-------

FRACHT / VERPACKUNG Part I 99 99 8 888 200	Local	100
---	-------	-----

—	08/10/2019	Key	56498 Km	01554	Key 1
---	------------	-----	----------	-------	-------

 490 11/2020	 490 419	 490 419	 490 419	 13000	 0 09/2020	 5000	 490 11/2020	 0 09/2020
--	--	--	--	---	--	--	---	--

— 08/10/2019 Service 56498 Km 01554 Manual
Autohaus Rolf
Horn, Düren

 ✓	 ✓	 ✓	 ✓			 ✓	 ✓		
--	--	--	--	---	---	--	---	---	---

— 08/10/2019 Repair 56504 Km 01554 Job
Autohaus Rolf
Horn GmbH ,
Düren Job
Job
Job
Job
Job
Job
Job

— Job

Description:

Considered as a repeat visit No

Customer's own words

Service - standard scope 2 FRU
Flat rate unit I 00 00 105

— Job

Description:

Considered as a repeat visit No

Customer's own words

Engine oil service 3 FRU
Flat rate unit I 00 00 610

Set oil-filter element 1
Part I 11 42 8 575 211

BMW Engine Oil LL04 0W30 5
Part I 83 21 2 405 950

— Job

Description:

Considered as a repeat visit No

Customer's own words

Microfilter service 2 FRU
Flat rate unit I 00 00 616

Microfilter/activated Carbon container 1
Part I 64 11 9 237 555

— Job

Description:

Considered as a repeat visit No

Customer's own words

Service fuel filter Flat rate unit I 00 00 604	3 FRU
Fuel filter cartridge Part I 13 32 8 572 522	1
Clamping bracket Part I 13 32 7 789 220	1

— Job

Description:

Considered as a repeat visit No

Customer's own words

Service - air filter element Flat rate unit I 00 00 602	2 FRU
Air filter element Part I 13 71 8 511 668	1

— Job

Description:

Considered as a repeat visit No

Customer's own words

Service, vehicle check Flat rate unit I 00 00 624	6 FRU
--	-------

— Job

Description:

Considered as a repeat visit No

Customer's own words

Replace left and right wiper blade Flat rate unit I 61 61 041	2 FRU
Set of wiper blades Part I 61 61 2 241 375	1

— Job

Description:

Considered as a repeat visit No

Customer's own words

Service, rear brakes Flat rate unit I 00 00 614	7 FRU
Repair kit, brake pads asbestos-free Part I 34 21 6 873 093	1
Brake-pad sensor, rear Part I 34 35 6 792 292	1

—	08/10/2019	Warranty	56504 Km	01554	Job: Service - standard scope Job: Engine oil service Job: Service - micro filter/activated carbon filter Job: Service - fuel filter Job: Service - air cleaner Job: Service - vehicle check Job: Service - front wiper blade Job: Service - rear brakes
---	------------	----------	----------	-------	---

— Job: Service - standard scope

Description: Service - standard scope

Considered as a repeat visit No

Customer's own words

Service - standard scope	2 FRU
Flat rate unit I 00 00 105	

Service - standard scope
Defect I 87 00 06 00 00

— Job: Engine oil service

Description: Engine oil service

Considered as a repeat visit No

Customer's own words

Engine oil service	3 FRU
Flat rate unit I 00 00 610	

Engine oil service
Defect I 87 00 02 00 00

Set oil-filter element	1
Part I 11 42 8 575 211	

— Job: Service - micro filter/activated carbon filter

Description: Service - micro filter/activated carbon filter

Considered as a repeat visit No

Customer's own words

Microfilter service	2 FRU
Flat rate unit I 00 00 616	

Service - micro filter/activated carbon filter
Defect I 87 64 01 00 00

Microfilter/activated Carbon container	1
Part I 64 11 9 237 555	

— Job: Service - fuel filter

Description: Service - fuel filter

Considered as a repeat visit No

Customer's own words

Service fuel filter	3 FRU
Flat rate unit I 00 00 604	

Service - fuel filter
Defect I 87 13 02 00 00

Fuel filter cartridge	1
Part I 13 32 8 572 522	

Clamping bracket	1
Part I 13 32 7 789 220	

— Job: Service - air cleaner

Description: Service - air cleaner

Considered as a repeat visit No

Customer's own words

Service - air filter element
Flat rate unit | 00 00 602

2 FRU

Service - air cleaner
Defect | 87 13 01 00 00

Air filter element
Part | 13 71 8 511 668

1

— Job: Service - vehicle check

Description: Service - vehicle check

Considered as a repeat visit No

Customer's own words

Service, vehicle check
Flat rate unit | 00 00 624

6 FRU

Service - vehicle check
Defect | 87 00 05 00 00

— Job: Service - front wiper blade

Description: Service - front wiper blade

Considered as a repeat visit No

Customer's own words

Replace left and right wiper blade
Flat rate unit | 61 61 041

0 FRU

Replace left and right wiper blade
Flat rate unit | 61 61 541

1 FRU

Service - front wiper blade
Defect | 87 61 61 00 00

Set of wiper blades
Part | 61 61 2 241 375

1

— Job: Service - rear brakes

Description: Service - rear brakes

Considered as a repeat visit No

Customer's own words

Service, rear brakes
Flat rate unit | 00 00 614

7 FRU

Service - rear brakes
Defect | 87 34 21 01 00

Repair kit, brake pads asbestos-free
Part | 34 21 6 873 093

1

Brake-pad sensor, rear
Part | 34 35 6 792 292







1

— 06/05/2019 Key

35170 Km

30315

Key 1



— 06/05/2019 Repair

35170 Km

30315
Ungeheuer
Automobile

Job
Job

— Job

Description:

Considered as a repeat visit No

Customer's own words

(Annual) vehicle inspection within framework of DGUV Regulation 70	0 FRU
Flat rate unit I 00 12 170	

— Job

Description:

Considered as a repeat visit No

Customer's own words

Package I MM04RW1KLEIN	Local	
!!! unknown BMW-Id 0000360 Montage eingelagerter Räder !!!	Local	8
Flat rate unit I 00 00 360		
!!! unknown BMW-Id 0000368 Räder reinigen !!!	Local	2
Flat rate unit I 00 00 368		
Einlagerung Radsatz	Local	1
Part I 99998888809		

—	06/05/2019	Repair	35174 Km	30315	Job
				Ungeheuer	Job
				Automobile	Job
				GmbH ,	
				Karlsruhe	

— Job

Description:

Considered as a repeat visit No

Customer's own words

Montage eingelagerter Reifen	Local	2 FRU
Flat rate unit I 00 00 360		
SR reinigen und WR einlagern	Local	0 FRU
Flat rate unit I 00 00 363		
Einlagerung Reifen	Local	1
Part I 99 99 8 888 809		

— Job

Description:

Considered as a repeat visit No

Customer's own words

Jährliche Prüfung im Rahmen der UVV BGV D29 im Verbund	Local	0 FRU
Flat rate unit I 00 12 570		

— Job

Description:

Considered as a repeat visit No

Customer's own words

Fahrzeug vorne aussaugen
Flat rate unit I 00 11 315

Local

0 FRU

Kostenlose Wagen-Oberwäsche
Flat rate unit I 00 11 320










Local

0 FRU

— 08/11/2018 Key

26569 Km

Key 1












— 08/11/2018 Service

26569 Km

30315
Ungeheuer
Automobile ,
Karlsruhe

Automatic



— 08/11/2018 Repair

26569 Km

30315
Ungeheuer
Automobile
GmbH ,
Karlsruhe

Job: Service - standard scope
Job: Engine oil service
Job: Microfilter service
Job
Job
Job
Job
Job
Job

— Job: Service - standard scope

Description:

Considered as a repeat visit No

Customer's own words

Service - standard scope
Package I 0000105

Service - standard scope
Flat rate unit I 00 00 105

2

— Job: Engine oil service

Description:

Considered as a repeat visit No

Customer's own words

Engine oil service
Package I 0000610

Engine oil service
Flat rate unit I 00 00 610

3

!!! unknown BMW-Id FRE/99999100100 MOBIL S 3000XE 5W30 Local
!!!
Part I FRE/99999100100

5

Set oil-filter element
Part I 11428575211

1

— Job: Microfilter service

Description:

Considered as a repeat visit No

Customer's own words

Microfilter service
Package I 0000616

Microfilter service	2
Flat rate unit I 00 00 616	

Microfilter/activated Carbon container	1
Part I 64119237555	

— Job

Description:

Considered as a repeat visit No

Customer's own words

CAREBMW	Local	0 FRU
Flat rate unit I -		

— Job

Description:

Considered as a repeat visit No

Customer's own words

Package I MM0400003602	Local
------------------------	-------

!!! unknown BMW-Id 0000360 Montage eingelagerter Räder !!!	Local	0
Flat rate unit I 00 00 360		

Einlagerung Radsatz	Local	1
Part I 99998888809		

— Job

Description:

Considered as a repeat visit No

Customer's own words

Interior vehicle cleaning	0 FRU
Flat rate unit I 00 11 315	

— Job

Description:

Considered as a repeat visit No

Customer's own words

Vehicle surface wash	0 FRU
Flat rate unit I 00 11 319	

— Job

Description:

Considered as a repeat visit No

Customer's own words

CAREBMW	Local	0 FRU
Flat rate unit I 00 99 310		

— Job

Description:

Considered as a repeat visit No

Customer's own words

CAREBMW	Local	0 FRU
Flat rate unit I 00 52 050		

— Job

Description:

Considered as a repeat visit No

Customer's own words

!!! unknown BMW-Id ESTIMATE !!!	Local	0 FRU
Flat rate unit I -		

!!! unknown BMW-Id ESTIMATE !!!	Local	0 FRU
Flat rate unit I -		

—	08/11/2018	Repair	26572 Km	30315 Ungeheuer Automobile GmbH , Karlsruhe	Job
---	------------	--------	----------	---	-----

— Job

Description:

Considered as a repeat visit No

Customer's own words

Replacing four tyres with run-flat technology		2 FRU
Flat rate unit I 36 12 576		

Einlagerung Radsatz	Local	1
Part I 99 99 8 888 809		

—	08/11/2018	Warranty	26572 Km	30315	Job: Service - standard scope Job: Engine oil service Job: Service - micro filter/activated carbon filter Job: Washer fluid service
---	------------	----------	----------	-------	---

— Job: Service - standard scope

Description: Service - standard scope

Considered as a repeat visit No

Customer's own words

Service - standard scope		2 FRU
Flat rate unit I 00 00 105		

Service - standard scope		
Defect I 87 00 06 00 00		

— Job: Engine oil service

Description: Engine oil service

Considered as a repeat visit No

Customer's own words

Engine oil service		3 FRU
Flat rate unit I 00 00 610		

Engine oil service
Defect I 87 00 02 00 00

Set oil-filter element
Part I 11 42 8 575 211

1

— Job: Service - micro filter/activated carbon filter

Description: Service - micro filter/activated carbon filter

Considered as a repeat visit No

Customer's own words

Microfilter service
Flat rate unit I 00 00 616

2 FRU

Service - micro filter/activated carbon filter
Defect I 87 64 01 00 00

Microfilter/activated Carbon container
Part I 64 11 9 237 555

1

— Job: Washer fluid service

Description: Washer fluid service

Considered as a repeat visit No

Customer's own words









Washer fluid service
Defect I 87 00 09 00 00

— 16/04/2018 Key

14369 Km

30315

Key 1










— 23/10/2017 Key

2558 Km

30315

Key 0



— 04/10/2017 Repair

2566 Km

30315
Ungeheuer
Automobile
GmbH ,
Karlsruhe

Job
Job
Job

— Job

Description:

Considered as a repeat visit No

Customer's own words

Vier Reifen mit Runflatausführung ersetzen
Flat rate unit I 36 12 076

Local

3 FRU

Räder reinigen
Flat rate unit I 00 00 363

Local

0 FRU

ZINK AUSWUCHTGEWICHT
Part I 99 01 8 000 020

Local

8

Einlagerung Sommerreifen Part I 99 99 8 888 809	Local	1
Michelin Pilot Alpin PA4 Part I 85 45 2 591 523		2
Michelin Pilot Alpin PA4 Part I 85 45 2 549 204		2

— Job

Description:

Considered as a repeat visit No

Customer's own words

Licht-Test Flat rate unit I 00 12 290	Local	0 FRU
--	-------	-------

— Job

Description:

Considered as a repeat visit No

Customer's own words

Kostenbeteiligung an Reifen durch Flat rate unit I 99 99 999	Local	1 FRU
---	-------	-------

Großkundenabteilung Flat rate unit I 99 99 999	Local	1 FRU
---	-------	-------

— 04/10/2017 Repair 2566 Km 30315 Ungeheuer Automobile GmbH, Karlsruhe Job

— Job

Description:

Considered as a repeat visit No

Customer's own words

Kostenbeteiligung an Reifen Flat rate unit I 99 99 999	Local	1 FRU
---	-------	-------

durch Großkundenabt. It. Flat rate unit I 99 99 999	Local	1 FRU
--	-------	-------

Herr Rohrmeier Flat rate unit I 99 99 999	Local	1 FRU
--	-------	-------

— 11/09/2017 Service 2 Km 30315 Ungeheuer Automobile GmbH, Karlsruhe Manual



— 07/09/2017 Repair 3 Km 30315 Ungeheuer Automobile Job
Job
Job

— Job

Description:
Considered as a repeat visit No
Customer's own words

Free pre-delivery check	0 FRU
Flat rate unit I 00 00 009	

— Job

Description:
Considered as a repeat visit No
Customer's own words

WARNWESTE GELB	Local	1
Part I FRE/F9035086053		
Scheibenklar	Local	1
Part I BMW/83122409031		

— Job

Description:
Considered as a repeat visit No
Customer's own words

Installing navigation map(s)	0 FRU
Flat rate unit I 65 90 600	

— Job

Description:
Considered as a repeat visit No
Customer's own words